

## **Declaration of Equality**

We: Werner Turck GmbH & Co.KG Goethestr. 7, 58 553 Halver

declare for the following products the design identity except the listed differences:

Device designation	ld-No.	Differences
TB-M18-H1147	7030001	
TB-M18-H1147/C41	7030588	Customer-specific firmware version
TB-M18-H1147/C42	100003695	Customer-specific firmware version
TB-M18-H1147/C53	7030729	3 RS485 (R1=2.7K, R2=150Ω, R3=2.7k)
		communication resistors not assembled
TB-EM18WD-H1147-EX	7030381	Stainless steel housing instead of brass
		housing
TB-EM18WD-H1147-EX/C53	100036841	Stainless steel housing instead of brass
		housing + 3 RS485 (R1=2.7K, R2=150Ω, R3=2.7k)
		communication resistors not assembled

The devices match in the following documents:

- Block diagram
- Schematic
- Parts placement Drawing
- PCB Layout
- Internal and external photos
- Parts List (except of see table)

Halver, 25.01.2022

Dr. Matthias Linde, Head of Approvals

Place and date of issue

Name, function and signature