



Qty  
**1** Type  
**TB-EM18WD-H1147-Ex**




Ident-No. **7030381**



10...30 VDC



IP69K



1822H

Warning: Hazardous voltage can cause electrical shock and burns. Disconnect power before proceeding with any work on this equipment.  
Made in Germany  
Hans Turck GmbH & Co. KG | Witzlebenstraße 7  
45472 Mülheim an der Ruhr | Germany | www.turck.com

**FCC/IC Digital Device Limitations**

M/N: **TB-EM18WD-H1147-EX**  
FCC ID **YQ7-TBM18W**  
IC: **8821A-TBM18W**  
MVN: **TB2863/3**

This device complies with Industry Canada licence-exempt RSS standard(s) and part 15 of the FCC Rules. Operation is subject to the following two conditions:  
(1) this device may not cause interference, and  
(2) this device must accept any interference, including interference that may cause undesired operation of the device.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes :  
(1) l'appareil ne doit pas produire de brouillage, et  
(2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.


This radio equipment is in compliance with Directive 2014/53/EU. The full text of the EU declaration of conformity is available at:

Dieser Funkanlagentyp entspricht der Richtlinie 2014/53/EU. Der vollständige Text der EU-Konformitätserklärung ist verfügbar unter:


Qty **1** Type **TB-EM18WD-H1147-Ex/C53**



Ident-No. **100036841**



10...30 VDC



IP69K



1922H

Warning: Hazardous voltage can cause electrical shock and burns. Disconnect power before proceeding with any work on this equipment.  
 Made in Germany  
 Hans Turck GmbH & Co. KG | Witzlebenstraße 7  
 45472 Mülheim an der Ruhr | Germany | www.turck.com

**FCC/IC Digital Device Limitations**

M/N: **TB-EM18WD-H1147-EX/C53**  
 FCC ID **YQ7-TBM18W**  
 IC: **8821A-TBM18W**  
 HVIN: **TB2863/3**

This device complies with Industry Canada licence-exempt RSS standard(s) and part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause interference, and
- (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes :

- (1) l'appareil ne doit pas produire de brouillage, et
- (2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

This radio equipment is in compliance with Directive 2014/53/EU. The full text of the EU declaration of conformity is available at:


Dieser Funkanlagentyp entspricht der Richtlinie 2014/53/EU. Der vollständige Text der EU-Konformitätserklärung ist verfügbar unter:

Qty  
**1**

Type  
**TB-M18-H1147**



Ident-No. **7030001**



IP67



1622H

Warning: Hazardous voltage can cause electrical shock and burns. Disconnect power before proceeding with any work on this equipment.  
Made in Germany  
Hans Turck GmbH & Co. KG | Witzlebenstraße 7  
45472 Mülheim an der Ruhr | Germany | [www.turck.com](http://www.turck.com)

**FCC/IC Digital Device Limitations**

M/N: **TB-M18-H1147**  
FCC ID **YQ7-TBM18W**  
IC: **8821A-TBM18W**  
MVN: **TB2863/3**

This device complies with Industry Canada licence-exempt RSS standard(s) and part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause interference, and
- (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes :

- (1) l'appareil ne doit pas produire de brouillage, et
- (2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.


This radio equipment is in compliance with Directive 2014/53/EU. The full text of the EU declaration of conformity is available at:

Dieser Funkanlagentyp entspricht der Richtlinie 2014/53/EU. Der vollständige Text der EU-Konformitätserklärung ist verfügbar unter:

Qty  
**1** | Type  
**TB-M18-H1147/C41**



Ident-No. **7030588**



IP67



1622H

Warning: Hazardous voltage can cause electrical shock and burns. Disconnect power before proceeding with any work on this equipment.  
 Made in Germany  
 Hans Turck GmbH & Co. KG | Witzlebenstraße 7  
 45472 Mülheim an der Ruhr | Germany | www.turck.com

**FCC/IC Digital Device Limitations**

M/N: **TB-M18-H1147/C41**  
 FCC ID **YQ7-TBM18W**  
 IC: **8821A-TBM18W**  
 HVIN: **TB2863/3**

This device complies with Industry Canada licence-exempt RSS standard(s) and part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause interference, and
- (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes :

- (1) l'appareil ne doit pas produire de brouillage, et
- (2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.


This radio equipment is in compliance with Directive 2014/53/EU. The full text of the EU declaration of conformity is available at:

Dieser Funkanlagentyp entspricht der Richtlinie 2014/53/EU. Der vollständige Text der EU-Konformitätserklärung ist verfügbar unter:

Qty **1** Type **TB-M18-H1147/C42**



Ident-No. **100003695** **FW-V1.85**



IP67



1622H

Warning: Hazardous voltage can cause electrical shock and burns. Disconnect power before proceeding with any work on this equipment.  
 Made in Germany  
 Hans Turck GmbH & Co. KG | Witzlebenstraße 7  
 45472 Mülheim an der Ruhr | Germany | www.turck.com

**FCC/IC Digital Device Limitations**

M/N: **TB-M18-H1147/C42**  
 FCC ID **YQ7-TBM18W**  
 IC: **8821A-TBM18W**  
 HVIN: **TB2863/3**

This device complies with Industry Canada licence-exempt RSS standard(s) and part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause interference, and
- (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes :

- (1) l'appareil ne doit pas produire de brouillage, et
- (2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

This radio equipment is in compliance with Directive 2014/53/EU. The full text of the EU declaration of conformity is available at:


Dieser Funkanlagentyp entspricht der Richtlinie 2014/53/EU. Der vollständige Text der EU-Konformitätserklärung ist verfügbar unter:

Qty  
**1**

Type  
**TB-M18-H1147/C53**



Ident-No. **7030729**



IP67



1622H

Warning: Hazardous voltage can cause electrical shock and burns. Disconnect power before proceeding with any work on this equipment.  
Made in Germany  
Hans Turck GmbH & Co. KG | Witzlebenstraße 7  
45472 Mülheim an der Ruhr | Germany | [www.turck.com](http://www.turck.com)

**FCC/IC Digital Device Limitations**

M/N: **TB-M18-H1147/C53**  
FCC ID **YQ7-TBM18W**  
IC: **8821A-TBM18W**  
MVN: **TB2863/3**

This device complies with Industry Canada licence-exempt RSS standard(s) and part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause interference, and
- (2) this device must accept any interference, including interference that may cause undesired operation of the device.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes :

- (1) l'appareil ne doit pas produire de brouillage, et
- (2) l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

This radio equipment is in compliance with Directive 2014/53/EU. The full text of the EU declaration of conformity is available at:

Dieser Funkanlagentyp entspricht der Richtlinie 2014/53/EU. Der vollständige Text der EU-Konformitätserklärung ist verfügbar unter: