

SORIN CRM S.r.l Via Crescentino 13040 Saluggia (VC) Italy

September, 13th 2013

To:

Federal Communications Commission

7435 Oakland Mills Road Columbia, MD 21046-1609

Re:

Labeling for FCC ID: YSGVR124

(Model: VR124)

To whom it may Concern,

The equipment is implanted in the human body therefore the label with FCC ID is not feasible. Pursuant to sections 47 CFR 2.926 (e), we are proposing two following alternative methods:

- 1. The FCC ID and the statements required are in the User Manual (page 22)
- 2. The FCC ID appears on the package label which is affixed to the shipping box

Sincerely,

Olivier Varomme

Regulatory affairs Engineer

SORIN CRM

Parc d'affaires NOVEOS

4, Avenue Réaumur

92140 CLAMART Cedex