

SORIN CRM S.r.l
Via Crescentino
13040 Saluggia (VC)
Italy

May 31st, 2012

To: Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046-1609

Re: Labeling for FCC ID: YSGVR9250
(Model: VR 9250)

To whom it may Concern,

The equipment is implanted in the human body therefore the label with FCC ID is not feasible. Pursuant to sections 47 CFR 2.926 (e), we are proposing two following alternative methods:

1. The FCC ID and the statements required are in the User Manual (page 27)
2. The FCC ID appears on the package label which is affixed to the shipping box

Sincerely,



Cécile de Jeso
Regulatory affairs Engineer

SORIN CRM
Parc d'affaires NOVEOS
4, Avenue Réaumur
92140 CLAMART Cedex