

# 8. SETUP PHOTO







UL VERIFICATION SERVICES INC. 47173 BENICIA STREET, FREMONT, CA 94538, USA This report shall not be reproduced except in full, without the written approval of . UL Verification Services Inc. FORM NO: CCSUP4701I FAX: (510) 661-0888 Inc.

Page 18 of 27







Page 19 of 27




## **CONFIGURATION 1 STANDBY MODE**





Page 20 of 27






Page 21 of 27






Page 22 of 27


#### **CONFIGURATION 2 OPERATING MODE (COIL 2)**







UL VERIFICATION SERVICES INC. 47173 BENICIA STREET, FREMONT, CA 94538, USA This report shall not be reproduced except in full, without the written approval of . UL Verification Services Inc. FORM NO: CCSUP4701I FAX: (510) 661-0888 Inc.

Page 23 of 27







Page 24 of 27




## **CONFIGURATION 3 OPERATING MODE (Coil 1)**





Page 25 of 27





Page 26 of 27





## **END OF REPORT**

Page 27 of 27