Phonetone Technology (Shenzhen) Co., Ltd.

Oct 12, 2018

Subject: Tuning and Adjustment of Signal booster, FCC ID: YYOANCP65

There are no external tuning adjustments, the amplifier is factory set not exceed maximum gains, power levels, and downlink dependent region (RSSI) set points as provided in the test results.

Yours sincerely,

Guangwei Zhang

Guangnei Zhang