

LG Innotek Co., Ltd.

#978-1, Jangduk-dong, Gwangsan-gu, Gwangju, 506-731, Korea

Date: June 11, 2012

Description of change

FCC ID: YZP-TWFMB005D IC: 7414C-TWFMB005D

We inform that module of above FCC ID, IC has minor change of hardware.

Change Items : Remove RF Connector for test purpose and replace the RF connector with 0 ohm resistor. (There is no other change except RF connector removal and add 0 ohm resistor.)

Sincerely,

Deok-su Oh

Senior Research Engineer