


The location of the Bluetooth earphone is too small and can not mark the FCC ID number. During production, the FCC ID number should be mark at the bottom of the charging box and user manual. If the charging case is lost or damaged, the Bluetooth earphone cannot be charging and Use.



silk-screen to the bottom of the charging box



silk-screen color

PANTONE 425 U