



Plot on Configuration VHT20 / 5320 MHz / Average / Port 3 / 9GHz~18GHz




Date: 6.APR.2018 22:19:49

Plot on Configuration VHT20 / 5320 MHz / Average / Port 4 / 9GHz~18GHz




Date: 6.APR.2018 22:29:59

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 6.APR.2018 22:06:11

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 6.APR.2018 22:17:16

Plot on Configuration VHT20 / 5320 MHz / Average / Port 3 / 9GHz~18GHz




Date: 6.APR.2018 22:20:48

Plot on Configuration VHT20 / 5320 MHz / Average / Port 4 / 9GHz~18GHz




Date: 6.APR.2018 22:31:47

Plot on Configuration VHT40 / 5270 MHz / Average / Port 1 / 9GHz~18GHz




Date: 6 APR 2018 22:42:45

Plot on Configuration VHT40 / 5270 MHz / Average / Port 2 / 9GHz~18GHz




Date: 6 APR 2018 22:52:42

Plot on Configuration VHT40 / 5270 MHz / Average / Port 3 / 9GHz~18GHz




Date: 6 APR 2018 22:56:15

Plot on Configuration VHT40 / 5270 MHz / Average / Port 4 / 9GHz~18GHz




Date: 6 APR 2018 23:06:14

Plot on Configuration VHT40 / 5270 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 6.APR.2018 22:43:35

Plot on Configuration VHT40 / 5270 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 6.APR.2018 22:54:04

Plot on Configuration VHT40 / 5270 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 6.APR.2018 22:57:02

Plot on Configuration VHT40 / 5270 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 6.APR.2018 23:07:13

Plot on Configuration VHT40 / 5310 MHz / Average / Port 1 / 9GHz~18GHz




Date: 6.APR.2018 23:19:11

Plot on Configuration VHT40 / 5310 MHz / Average / Port 2 / 9GHz~18GHz




Date: 6.APR.2018 23:29:15

Plot on Configuration VHT40 / 5310 MHz / Average / Port 3 / 9GHz~18GHz




Date: 6 APR 2018 23:38:00

Plot on Configuration VHT40 / 5310 MHz / Average / Port 4 / 9GHz~18GHz




Date: 6 APR 2018 23:51:26

Plot on Configuration VHT40 / 5310 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 6 APR 2018 23:20:18

Plot on Configuration VHT40 / 5310 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 6 APR 2018 23:30:03

Plot on Configuration VHT40 / 5310 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 6.APR.2018 23:39:05

Plot on Configuration VHT40 / 5310 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 6.APR.2018 23:53:21

Plot on Configuration VHT80 / 5290 MHz / Average / Port 1 / 9GHz~18GHz




Date: 6.APR.2018 23:56:13

Plot on Configuration VHT80 / 5290 MHz / Average / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 00:07:29

Plot on Configuration VHT80 / 5290 MHz / Average / Port 3 / 9GHz~18GHz



Date: 7.APR.2018 00:10:14


Plot on Configuration VHT80 / 5290 MHz / Average / Port 4 / 9GHz~18GHz



Date: 7.APR.2018 00:21:00




Plot on Configuration VHT80 / 5290 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 6.APR.2018 23:57:22

Plot on Configuration VHT80 / 5290 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 00:08:10

Plot on Configuration VHT80 / 5290 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 00:11:20

Plot on Configuration VHT80 / 5290 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 00:22:29

Plot on Configuration VHT20 / 5500 MHz / Average / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 00:46:00

Plot on Configuration VHT20 / 5500 MHz / Average / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 00:56:09

Plot on Configuration VHT20 / 5500 MHz / Average / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 00:59:33

Plot on Configuration VHT20 / 5500 MHz / Average / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 01:12:03

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 00:46:59

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 00:57:12

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 01:01:08

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 01:13:04

Plot on Configuration VHT20 / 5580 MHz / Average / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 01:15:48

Plot on Configuration VHT20 / 5580 MHz / Average / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 01:26:33

Plot on Configuration VHT20 / 5580 MHz / Average / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 01:40:03

Plot on Configuration VHT20 / 5580 MHz / Average / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 01:55:52

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 01:16:28

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 01:27:16

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 01:41:22

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 01:57:11

Plot on Configuration VHT20 / 5700 MHz / Average / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 01:59:48

Plot on Configuration VHT20 / 5700 MHz / Average / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 02:09:43

Plot on Configuration VHT20 / 5700 MHz / Average / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 02:13:23

Plot on Configuration VHT20 / 5700 MHz / Average / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 02:27:21

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 02:00:38

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 02:10:32

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 02:14:16

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 02:28:02

Plot on Configuration VHT20 / 5720 MHz / Average / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 02:30.11

Plot on Configuration VHT20 / 5720 MHz / Average / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 02:41.01

Plot on Configuration VHT20 / 5720 MHz / Average / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 02:43:54

Plot on Configuration VHT20 / 5720 MHz / Average / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 02:52:53

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 02:31:26

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 02:41:43

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 02:44:56

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 02:53:40

Plot on Configuration VHT40 / 5510 MHz / Average / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 19:24:26

Plot on Configuration VHT40 / 5510 MHz / Average / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 19:43:46

Plot on Configuration VHT40 / 5510 MHz / Average / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 19:48:21

Plot on Configuration VHT40 / 5510 MHz / Average / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 20:10:48

Plot on Configuration VHT40 / 5510 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 19:25:15

Plot on Configuration VHT40 / 5510 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 19:44:26

Plot on Configuration VHT40 / 5510 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 19:49:14

Plot on Configuration VHT40 / 5510 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 20:07:56

Plot on Configuration VHT40 / 5550 MHz / Average / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 20:17:29

Plot on Configuration VHT40 / 5550 MHz / Average / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 20:30:04

Plot on Configuration VHT40 / 5550 MHz / Average / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 20:34:15

Plot on Configuration VHT40 / 5550 MHz / Average / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 20:46:10

Plot on Configuration VHT40 / 5550 MHz / Peak / Port 1 / 9GHz~18GHz



Date: 7.APR.2018 20:18:32


Plot on Configuration VHT40 / 5550 MHz / Peak / Port 2 / 9GHz~18GHz



Date: 7.APR.2018 20:31:36




Plot on Configuration VHT40 / 5550 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 20:35:04

Plot on Configuration VHT40 / 5550 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 20:47:33

Plot on Configuration VHT40 / 5670 MHz / Average / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 21:05:53

Plot on Configuration VHT40 / 5670 MHz / Average / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 21:22:05

Plot on Configuration VHT40 / 5670 MHz / Average / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 21:26:07

Plot on Configuration VHT40 / 5670 MHz / Average / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 21:41:38

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 21:07:39

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 21:23:15

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 21:27:13

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 21:42:51

Plot on Configuration VHT40 / 5710 MHz / Average / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 21:54:39

Plot on Configuration VHT40 / 5710 MHz / Average / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 22:12:47

Plot on Configuration VHT40 / 5710 MHz / Average / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 22:18:39

Plot on Configuration VHT40 / 5710 MHz / Average / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 22:35:17

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 21:56:24

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 22:14:06

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 22:20:26

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 22:38:22

Plot on Configuration VHT80 / 5530 MHz / Average / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 22:47:11

Plot on Configuration VHT80 / 5530 MHz / Average / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 23:05:02

Plot on Configuration VHT80 / 5530 MHz / Average / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 23:10:44

Plot on Configuration VHT80 / 5530 MHz / Average / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 23:30:48

Plot on Configuration VHT80 / 5530 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 22:48:23

Plot on Configuration VHT80 / 5530 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 7.APR.2018 23:07:44

Plot on Configuration VHT80 / 5530 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 7.APR.2018 23:12:14

Plot on Configuration VHT80 / 5530 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 7.APR.2018 23:31:58

Plot on Configuration VHT80 / 5610 MHz / Average / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 23:44:44

Plot on Configuration VHT80 / 5610 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8.APR.2018 00:00:51

Plot on Configuration VHT80 / 5610 MHz / Average / Port 3 / 9GHz~18GHz




Date: 8.APR.2018 00:05:17

Plot on Configuration VHT80 / 5610 MHz / Average / Port 4 / 9GHz~18GHz




Date: 8.APR.2018 00:18:14

Plot on Configuration VHT80 / 5610 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 7.APR.2018 23:46:06

Plot on Configuration VHT80 / 5610 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8.APR.2018 00:02:00

Plot on Configuration VHT80 / 5610 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 8.APR.2018 00:06:31

Plot on Configuration VHT80 / 5610 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 8.APR.2018 00:19:21

Plot on Configuration VHT80 / 5690 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8.APR.2018 00:24:47

Plot on Configuration VHT80 / 5690 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8.APR.2018 00:37:57

Plot on Configuration VHT80 / 5690 MHz / Average / Port 3 / 9GHz~18GHz




Date: 8.APR.2018 00:42:38

Plot on Configuration VHT80 / 5690 MHz / Average / Port 4 / 9GHz~18GHz




Date: 8.APR.2018 00:58:05

Plot on Configuration VHT80 / 5690 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8.APR.2018 00:26:05

Plot on Configuration VHT80 / 5690 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8.APR.2018 00:39:59

Plot on Configuration VHT80 / 5690 MHz / Peak / Port 3 / 9GHz~18GHz




Date: 8.APR.2018 00:43:48

Plot on Configuration VHT80 / 5690 MHz / Peak / Port 4 / 9GHz~18GHz




Date: 8.APR.2018 00:59:43

Plot on Configuration VHT20 / 5260 MHz / Average / Port 1 / 18GHz~40GHz




Date: 6.APR.2018 21:07:40

Plot on Configuration VHT20 / 5260 MHz / Average / Port 2 / 18GHz~40GHz




Date: 6.APR.2018 21:11:39

Plot on Configuration VHT20 / 5260 MHz / Average / Port 3 / 18GHz~40GHz



Date: 6.APR.2018 21:22:02


Plot on Configuration VHT20 / 5260 MHz / Average / Port 4 / 18GHz~40GHz



Date: 6.APR.2018 21:26:29




Plot on Configuration VHT20 / 5260 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 6 APR 2018 21:08:39

Plot on Configuration VHT20 / 5260 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 6 APR 2018 21:15:48

Plot on Configuration VHT20 / 5260 MHz / Peak / Port 3 / 18GHz~40GHz




Date: 6.APR.2018 21:23:51

Plot on Configuration VHT20 / 5260 MHz / Peak / Port 4 / 18GHz~40GHz




Date: 6.APR.2018 21:27:23

Plot on Configuration VHT20 / 5300 MHz / Average / Port 1 / 18GHz~40GHz




Date: 6.APR.2018 21:36:47

Plot on Configuration VHT20 / 5300 MHz / Average / Port 2 / 18GHz~40GHz




Date: 6.APR.2018 21:40:19

Plot on Configuration VHT20 / 5300 MHz / Average / Port 3 / 18GHz~40GHz




Date: 6.APR.2018 21:50:27

Plot on Configuration VHT20 / 5300 MHz / Average / Port 4 / 18GHz~40GHz




Date: 6.APR.2018 21:57:26

Plot on Configuration VHT20 / 5300 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 6.APR.2018 21:37:43

Plot on Configuration VHT20 / 5300 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 6.APR.2018 21:42:13

Plot on Configuration VHT20 / 5300 MHz / Peak / Port 3 / 18GHz~40GHz




Date: 6.APR.2018 21:51:26

Plot on Configuration VHT20 / 5300 MHz / Peak / Port 4 / 18GHz~40GHz




Date: 6.APR.2018 22:08:37

Plot on Configuration VHT20 / 5320 MHz / Average / Port 1 / 18GHz~40GHz




Date: 6.APR.2018 22:12:09

Plot on Configuration VHT20 / 5320 MHz / Average / Port 2 / 18GHz~40GHz




Date: 6.APR.2018 22:22:47

Plot on Configuration VHT20 / 5320 MHz / Average / Port 3 / 18GHz~40GHz




Date: 6.APR.2018 22:27:34

Plot on Configuration VHT20 / 5320 MHz / Average / Port 4 / 18GHz~40GHz




Date: 6.APR.2018 22:09:21

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 6 APR 2018 22:09:21

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 6 APR 2018 22:13:33

Plot on Configuration VHT20 / 5320 MHz / Peak / Port 3 / 18GHz~40GHz



Date: 6 APR 2018 22:23:45


Plot on Configuration VHT20 / 5320 MHz / Peak / Port 4 / 18GHz~40GHz



Date: 6 APR 2018 22:28:17




Plot on Configuration VHT40 / 5270 MHz / Average / Port 1 / 18GHz~40GHz



Date: 6 APR 2018 22:46:27


Plot on Configuration VHT40 / 5270 MHz / Average / Port 2 / 18GHz~40GHz



Date: 6 APR 2018 22:49:45




Plot on Configuration VHT40 / 5270 MHz / Average / Port 3 / 18GHz~40GHz



Date: 6 APR 2018 22:59:03


Plot on Configuration VHT40 / 5270 MHz / Average / Port 4 / 18GHz~40GHz



Date: 6 APR 2018 23:02:37




Plot on Configuration VHT40 / 5270 MHz / Peak / Port 1 / 18GHz~40GHz



Date: 6 APR 2018 22:47:10

Plot on Configuration VHT40 / 5270 MHz / Peak / Port 2 / 18GHz~40GHz



Date: 6 APR 2018 22:50:50