




Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 1GHz~3GHz




Date: 16.OCT.2017 22:32:18

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 1GHz~3GHz




Date: 16.OCT.2017 23:11:53


Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 17.OCT.2017 18:53:38

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 17.OCT.2017 19:52:24

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 1GHz~3GHz




Date: 16.OCT.2017 23:34:54

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 1GHz~3GHz




Date: 16.OCT.2017 23:58:31

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 16.OCT.2017 23:35:08

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 16.OCT.2017 23:57:32

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 1GHz~3GHz




Date: 17.OCT.2017 00:00:22

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 1GHz~3GHz




Date: 17.OCT.2017 01:04:52

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 17.OCT.2017 00:00:35

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 17.OCT.2017 01:04:36


Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 17.OCT.2017 01:11:51

Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 17.OCT.2017 01:27:02

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 1GHz~3GHz




Date: 17.OCT.2017 20:12:01

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 1GHz~3GHz




Date: 17.OCT.2017 20:37:51

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 17.OCT.2017 20:20:16

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 17.OCT.2017 20:38:49

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 1GHz~3GHz




Date: 12.OCT.2017 17:39:26

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 1GHz~3GHz




Date: 12.OCT.2017 19:37:19

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 12.OCT.2017 17:41:18

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 12.OCT.2017 19:37:00

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 1GHz~3GHz




Date: 12.OCT.2017 19:39:44

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 1GHz~3GHz




Date: 12.OCT.2017 20:04:02

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 12.OCT.2017 19:40:11

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 12.OCT.2017 20:03:20


Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 12.OCT.2017 20:07:44

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 12.OCT.2017 20:31:53

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 1GHz~3GHz




Date: 13.OCT.2017 01:22:22

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 1GHz~3GHz




Date: 13.OCT.2017 01:17:51

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 13.OCT.2017 01:21:46

Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 13.OCT.2017 01:18:15

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 1 / 1GHz~3GHz




Date: 12.OCT.2017 21:24:25

Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 2 / 1GHz~3GHz




Date: 12.OCT.2017 21:38:49

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 12.OCT.2017 21:24:45

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 12.OCT.2017 21:38:32


Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 1GHz~3GHz




Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 1GHz~3GHz



Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 1GHz~3GHz




Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 1GHz~3GHz




Date: 12.OCT.2017 21:54:36

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 1GHz~3GHz




Date: 12.OCT.2017 22:05:45

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 12.OCT.2017 21:55:04

Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 12.OCT.2017 22:05:28

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 1GHz~3GHz




Date: 13.OCT.2017 01:20:21

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 1GHz~3GHz




Date: 13.OCT.2017 01:19:42

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 1GHz~3GHz




Date: 13.OCT.2017 01:21:05

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 1GHz~3GHz




Date: 13.OCT.2017 01:19:16

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 3GHz~6GHz




Date: 20.OCT.2017 14:33:51

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 3GHz~6GHz




Date: 16.OCT.2017 22:52:19

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 16.OCT.2017 22:46:04

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 16.OCT.2017 22:50:38

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 3GHz~6GHz




Date: 16.OCT.2017 22:44:31

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 3GHz~6GHz




Date: 16.OCT.2017 23:09:28


Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 3GHz~6GHz




Date: 16.OCT.2017 23:18:56

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 3GHz~6GHz




Date: 16.OCT.2017 23:31:10

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 16.OCT.2017 23:20:09

Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 16.OCT.2017 23:30:34


Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 17.OCT.2017 19:06:46

Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 17.OCT.2017 19:56:02


Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 16.OCT.2017 23:37:33

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 3GHz~6GHz



Date: 16.OCT.2017 23:55:39

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 3GHz~6GHz




Date: 17.OCT.2017 00:01:36

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 3GHz~6GHz




Date: 17.OCT.2017 01:08:03

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 17.OCT.2017 00:01:55

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 17.OCT.2017 01:05:45

Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 1 / 3GHz~6GHz




Date: 20.OCT.2017 14:03:16

Plot on Configuration QPSK, 80M / 5310 MHz / Average / Port 2 / 3GHz~6GHz




Date: 20.OCT.2017 14:15:12


Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 1 / 3GHz~6GHz



Plot on Configuration QPSK, 80M / 5310 MHz / Peak / Port 2 / 3GHz~6GHz




Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 3GHz~6GHz




Date: 17.OCT.2017 20:22:28

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 3GHz~6GHz




Date: 17.OCT.2017 20:40:57

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 17.OCT.2017 20:23:32

Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 17.OCT.2017 20:42:12

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 3GHz~6GHz




Date: 12.OCT.2017 17:48:54

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 19:35:59

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 3GHz~6GHz



Date: 12.OCT.2017 17:54:48

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 12.OCT.2017 19:35:37

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 3GHz~6GHz



Date: 12.OCT.2017 19:43:44

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 3GHz~6GHz



Date: 12.OCT.2017 20:00:05