



## Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:16:08

## Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:16:33

## Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:16:48

## Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:17:16

## Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:16:58

## Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:17:26

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:17:45

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:18:26

## Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:17:56

## Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:18:37


Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 9GHz~18GHz




## Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 21:10:31

## Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 21:26:37

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 9GHz~18GHz






## Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:19:07

## Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:19:48

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:20:44

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:21:14

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 3.OCT.2017 17:20:55

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 3.OCT.2017 17:21:24

## Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 21:41:32

## Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 21:59:17

## Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 17.OCT.2017 21:42:18

## Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 17.OCT.2017 22:00:15

## Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 00:47:27

## Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 00:50:32


Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 9GHz~18GHz




## Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 9GHz~18GHz



Date: 8.OCT.2017 00:53:08


## Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 9GHz~18GHz



Date: 8.OCT.2017 00:56:31




Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 00:53:55

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 00:57:29

## Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 00:59:31

## Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:02:23

## Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 01:00:28

## Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:03:18

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 10:58:23

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 11:32:33

## Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 10:57:19

## Plot on Configuration QPSK, 20M / 5720 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 11:32:00

## Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 01:06:29

## Plot on Configuration QPSK, 80M / 5510 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:08:16

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 01:07:14

Plot on Configuration QPSK, 80M / 5510 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:09:23

## Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 1 / 9GHz~18GHz



Date: 8.OCT.2017 01:10:20


## Plot on Configuration QPSK, 80M / 5610 MHz / Average / Port 2 / 9GHz~18GHz



Date: 8.OCT.2017 01:11:57




Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 01:10:58

Plot on Configuration QPSK, 80M / 5610 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:12:47

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 1 / 9GHz~18GHz




Date: 8.OCT.2017 01:16:00

Plot on Configuration QPSK, 80M / 5650 MHz / Average / Port 2 / 9GHz~18GHz




Date: 8.OCT.2017 01:17:49


Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 1 / 9GHz~18GHz



Plot on Configuration QPSK, 80M / 5650 MHz / Peak / Port 2 / 9GHz~18GHz




Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 11:50:35

Plot on Configuration QPSK, 80M / 5720 MHz / Average / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 11:46:34

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 1 / 9GHz~18GHz




Date: 13.OCT.2017 11:50:13

Plot on Configuration QPSK, 80M / 5720 MHz / Peak / Port 2 / 9GHz~18GHz




Date: 13.OCT.2017 11:46:49

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:23:11

Plot on Configuration QPSK, 20M / 5260 MHz / Average / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:23:54

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:23:23

Plot on Configuration QPSK, 20M / 5260 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:24:08

Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 1 / 18GHz~40GHz




Plot on Configuration QPSK, 20M / 5300 MHz / Average / Port 2 / 18GHz~40GHz






## Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:24:55

## Plot on Configuration QPSK, 20M / 5300 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:25:37

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:26:11

Plot on Configuration QPSK, 20M / 5320 MHz / Average / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:26:52


Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 1 / 18GHz~40GHz



Plot on Configuration QPSK, 20M / 5320 MHz / Peak / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 1 / 18GHz~40GHz




Date: 17.OCT.2017 21:11:58

Plot on Configuration QPSK, 20M / 5250 MHz / Average / Port 2 / 18GHz~40GHz




Date: 17.OCT.2017 21:28:01

## Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 17.OCT.2017 21:12:59

## Plot on Configuration QPSK, 20M / 5250 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 17.OCT.2017 21:29:17

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:27:43

Plot on Configuration QPSK, 80M / 5290 MHz / Average / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:28:32

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:27:57

Plot on Configuration QPSK, 80M / 5290 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:28:45

Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 1 / 18GHz~40GHz



Date: 3.OCT.2017 17:29:21


Plot on Configuration QPSK, 80M / 5300 MHz / Average / Port 2 / 18GHz~40GHz



Date: 3.OCT.2017 17:30:07




Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 3.OCT.2017 17:29:33

Plot on Configuration QPSK, 80M / 5300 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 3.OCT.2017 17:30:18

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 1 / 18GHz~40GHz




Date: 17.OCT.2017 21:43:51

Plot on Configuration QPSK, 80M / 5250 MHz / Average / Port 2 / 18GHz~40GHz




Date: 17.OCT.2017 22:02:19


Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 1 / 18GHz~40GHz



Plot on Configuration QPSK, 80M / 5250 MHz / Peak / Port 2 / 18GHz~40GHz




Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 1 / 18GHz~40GHz




Date: 8.OCT.2017 01:22:10

Plot on Configuration QPSK, 20M / 5500 MHz / Average / Port 2 / 18GHz~40GHz




Date: 8.OCT.2017 01:24:24

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 8.OCT.2017 01:23:02

Plot on Configuration QPSK, 20M / 5500 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 8.OCT.2017 01:24:58

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 1 / 18GHz~40GHz




Date: 8.OCT.2017 01:26:45

Plot on Configuration QPSK, 20M / 5580 MHz / Average / Port 2 / 18GHz~40GHz




Date: 8.OCT.2017 01:28:46

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 8.OCT.2017 01:27:35

Plot on Configuration QPSK, 20M / 5580 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 8.OCT.2017 01:29:54

Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 1 / 18GHz~40GHz



Date: 8.OCT.2017 01:31:18


Plot on Configuration QPSK, 20M / 5650 MHz / Average / Port 2 / 18GHz~40GHz



Date: 8.OCT.2017 01:33:29




Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 1 / 18GHz~40GHz




Date: 8.OCT.2017 01:32:07

Plot on Configuration QPSK, 20M / 5650 MHz / Peak / Port 2 / 18GHz~40GHz




Date: 8.OCT.2017 01:34:19

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 1 / 18GHz~40GHz



Date: 13.OCT.2017 11:28:41

Plot on Configuration QPSK, 20M / 5720 MHz / Average / Port 2 / 18GHz~40GHz



Date: 13.OCT.2017 11:30:50