

## Buddi Colorado product range FCC warning statement

The Colorado product range includes three devices which has in-built wireless technology and its own FCCID. The following FCC warning statement is printed out on a paper/label and put into the Smart TAG, Smart Beacon and RF Beacon box during packaging.

## **FCC** warning statement

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference, and
- (2) This device must accept any interference received, including interference that may cause undesired operation.

This equipment complies with FCC radiation exposure limits set forth for an uncontrolled environment. End users must follow the specific operating instructions for satisfying RF exposure compliance. This transmitter must not be co-located or operating in conjunction with any other antenna or transmitter.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment

buddi ltd 343 05 01 1

In addition to this printed warning the same text included in the user manual of the Colorado system.

Tel: 0800 978 8800 www.buddi.co.uk Co. Reg. No. 05308826



## **FCC Warning Statement**

Operation is subject to the following two conditions:

(1) This device may not cause harmful interference, and

(2) This device must accept any interference received, including interference that may cause undesired operation.

This device complies with Part 15 of the FCC Rules.

This equipment complies with FCC radiation exposure limits set forth for an uncontrolled environment. End users must follow the specific operating instructions for satisfying RF exposure compliance. This transmitter must not be co-located or operating in conjunction with any other antenna or transmitter.

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment

buddi ltd 343 05 01 1

Figure 1: Picture of a printed FCC warning