




SGS-CSTC Standards Technical Services Co., Ltd.
Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 25 of 59

BAND41_15MHz_QPSK_41515_75RB#0




Date: 22.OCT.2018 09:16:05

BAND41_15MHz_64QAM_39765_75RB#0



Date: 22.OCT.2018 09:09:32

BAND41_15MHz_64QAM_40640_75RB#0



Date: 22.OCT.2018 09:13:31




SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch


Report No.: ZR/2018/A000801

Page: 26 of 59


BAND41_15MHz_64QAM_41515_75RB#0



BAND41_15MHz_16QAM_39765_75RB#0



BAND41_15MHz_16QAM_40640_75RB#0






SGS-CSTC Standards Technical Services Co., Ltd.
Shenzhen Branch


Report No.: ZR/2018/A000801

Page: 27 of 59


BAND41_15MHz_16QAM_41515_75RB#0



BAND41_20MHz_QPSK_39790_100RB#0



BAND41_20MHz_QPSK_40640_100RB#0






SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch


Report No.: ZR/2018/A000801

Page: 28 of 59


BAND41_20MHz_QPSK_41490_100RB#0



BAND41_20MHz_64QAM_39790_100RB#0



BAND41_20MHz_64QAM_40640_100RB#0






SGS-CSTC Standards Technical Services Co., Ltd.
Shenzhen Branch


Report No.: ZR/2018/A000801

Page: 29 of 59


BAND41_20MHz_64QAM_41490_100RB#0



BAND41_20MHz_16QAM_39790_100RB#0



BAND41_20MHz_16QAM_40640_100RB#0






SGS-CSTC Standards Technical Services Co., Ltd.
Shenzhen Branch

Report No.: ZR/2018/A000801

Page: 30 of 59


BAND41_20MHz_16QAM_41490_100RB#0





5. Band Edge Compliance

5.1. Test Plots






SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 32 of 59

BAND 41_5MHz_QPSK_41565_1RB#24




Date: 22.OCT.2018 09:51:29

BAND 41_5MHz_QPSK_41565_25RB#0



Date: 22.OCT.2018 09:49:24

BAND 41_5MHz_16QAM_39715_1RB#0



Date: 22.OCT.2018 10:13:55




SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 33 of 59

BAND 41_5MHz_16QAM_39715_25RB#0




Date: 22.OCT.2018 10:12:05

BAND 41_5MHz_16QAM_41565_1RB#24



Date: 22.OCT.2018 09:51:15

BAND 41_5MHz_16QAM_41565_25RB#0



Date: 22.OCT.2018 09:49:37




SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch


Report No.: ZR/2018/A000801

Page: 34 of 59


BAND 41_5MHz_64QAM_39715_1RB#0



BAND 41_5MHz_64QAM_39715_25RB#0



BAND 41_5MHz_64QAM_41565_1RB#24






SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 35 of 59

BAND 41_5MHz_64QAM_41565_25RB#0




Date: 22.OCT.2018 09:49:52

BAND 41_10MHz_QPSK_39740_1RB#0



Date: 22.OCT.2018 10:20:06

BAND 41_10MHz_QPSK_39740_50RB#0



Date: 22.OCT.2018 10:18:42




SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 36 of 59

BAND 41_10MHz_QPSK_41540_1RB#49




Date: 22.OCT.2018 09:47:32

BAND 41_10MHz_QPSK_41540_50RB#0



Date: 22.OCT.2018 09:45:51

BAND 41_10MHz_16QAM_39740_1RB#0



Date: 22.OCT.2018 10:19:41




SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 37 of 59

BAND 41_10MHz_16QAM_39740_50RB#0




Date: 22.OCT.2018 10:18:52

BAND 41_10MHz_16QAM_41540_1RB#49



Date: 22.OCT.2018 09:47:14

BAND 41_10MHz_16QAM_41540_50RB#0



Date: 22.OCT.2018 09:46:18




SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 38 of 59

BAND 41_10MHz_64QAM_39740_1RB#0




Date: 22.OCT.2018 10:19:24

BAND 41_10MHz_64QAM_39740_50RB#0



Date: 22.OCT.2018 10:19:07

BAND 41_10MHz_64QAM_41540_1RB#49



Date: 22.OCT.2018 09:46:55




SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 39 of 59

BAND 41_10MHz_64QAM_41540_50RB#0




Date: 22.OCT.2018 09:46:37

BAND 41_15MHz_QPSK_39765_1RB#0



Date: 22.OCT.2018 10:24:19

BAND 41_15MHz_QPSK_39765_75RB#0



Date: 22.OCT.2018 10:22:35




SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch

Report No.: ZR/2018/A000801


Page: 40 of 59

BAND 41_15MHz_QPSK_41515_1RB#74




Date: 22.OCT.2018 09:43:39

BAND 41_15MHz_QPSK_41515_75RB#0



Date: 22.OCT.2018 09:42:15

BAND 41_15MHz_16QAM_39765_1RB#0



Date: 22.OCT.2018 10:24:00




SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch


Report No.: ZR/2018/A000801

Page: 41 of 59


BAND 41_15MHz_16QAM_39765_75RB#0



BAND 41_15MHz_16QAM_41515_1RB#74



BAND 41_15MHz_16QAM_41515_75RB#0






SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch


Report No.: ZR/2018/A000801

Page: 42 of 59


BAND 41_15MHz_64QAM_39765_1RB#0



BAND 41_15MHz_64QAM_39765_75RB#0



BAND 41_15MHz_64QAM_41515_1RB#74






SGS-CSTC Standards Technical Services Co., Ltd. Shenzhen Branch


Report No.: ZR/2018/A000801

Page: 43 of 59

BAND 41_15MHz_64QAM_41515_75RB#0



BAND 41_20MHz_QPSK_39790_1RB#0



BAND 41_20MHz_QPSK_39790_100RB#0

