

## 8. SETUP PHOTOS


### 8.1. RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)




Page 108 of 114



#### 8.2. RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)





Page 109 of 114




Page 110 of 114


# 8.3. RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION







Page 111 of 114





Page 112 of 114





Page 113 of 114

# END OF REPORT

 Page 114 of 114

 UL VERIFICATION SERVICES INC.
 FORM NO: CCSUP4701J

 47173 BENICIA STREET, FREMONT, CA 94538, USA
 TEL: (510) 771-1000
 FAX: (510) 661-0888

 This report shall not be reproduced except in full, without the written approval of UL Verification Services Inc.