

9. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




TEL: (510) 771-1000 FAX: (510) 661-0888


RADIATED RF MEASUREMENT SETUP



TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.



RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION




TEL: (510) 771-1000






TEL: (510) 771-1000 FA

POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





END OF REPORT