
# 10. SETUP PHOTOS


### ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



Page 43 of 47

## RADIATED RF MEASUREMENT SETUP






Page 44 of 47


#### RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION





Page 45 of 47


UL CCS FORM NO: CCSUP4701H 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.




UL CCS FORM NO: CCSUP4701H 47173 BENICIA STREET, FREMONT, CA 94538, USA TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.

Page 46 of 47

#### POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP





# **END OF REPORT**

Page 47 of 47