




5.3. SETUP PHOTOS



RADIATED MEASUREMENT SETUP (BELOW 1 GHz)





RADIATED MEASUREMENT SETUP (BELOW 1 GHz)



RADIATED MEASUREMENT SETUP (ABOVE 1 GHz)



RADIATED MEASUREMENT SETUP (ABOVE 1 GHz)




POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP



LINE CONDUCTED FRONT PHOTO (PS-USB ADAPTER)



LINE CONDUCTED BACK PHOTO (PS-USB ADAPTER)



POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP



END OF REPORT