

9. SETUP PHOTOS


ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP




RADIATED RF MEASUREMENT SETUP




TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.



RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION








POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP



TEL: (510) 771-1000 This report shall not be reproduced except in full, without the written approval of UL CCS.



END OF REPORT