

A TYPOGRAPHICAL ERROR WAS FOUND IN
SHEET 18 OF EXHIBIT 06 – “TEST REPORT”

PLEASE REPLACE WITH THE ATTACHED SHEET

EXHIBIT 6I – Transient Frequency Behavior (Note: Measurement made at 155.025 MHz)




Figure 6I-1: 5 Watts, 12.5 KHz Key-Up Attack Time




Figure 6I-2: 5 Watts, 12.5 KHz De-Key Decay Time