

January 27, 2014

Office of Engineering and Technology
Laboratory Division
Equipment Authorization Branch
7435 Oakland Mills Road
Columbia, MD 21046

Att: Tim Harrington

Subject: Response to Correspondence Number 45092 for Certification of Transmitter with
FCC ID: AZ489FT3829, EA449420, Jan 10, 2014.

Dear Mr. Harrington,

Please see below for our response:

Q1) Further clarification is requested as follows.

80.203(b)(1) [along with 80.169(a)] and 80.203(b)(3) require that programming of authorized channels must be performed only by a person holding a First Class Radiotelegraph Operator's Certificate, Second Class Radiotelegraph Operator's Certificate, Radiotelegraph Operator License, or General Radiotelephone Operator License.

Response:

The following will be added to the FPP (Front Panel Programming) manual:

When the device is being operated on frequencies licensed under Part 80 of the FCC rules, pursuant to 47 CFR 80.169(a), 80.203(b)(1) and 80.203(b)(3) the programming of authorized channels must only be performed by a person holding one or more of the following qualifications:

First Class Radiotelegraph Operator's Certificate,
Second Class Radiotelegraph Operator's Certificate,
Radiotelegraph Operator License, or
General Radiotelephone Operator License.

If you require any additional information, please contact me at (954) 723-5422 (Phone).

Sincerely,



Kim Uong
Manager, Regulatory Compliance
Email: Kim.Uong@motorolasolutions.com



FCC ID: AZ489FT3829