

American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

July 21, 2003

RE: FCC ID: O6YUTS-801FSU

Attention: Kathy Grzovic

I have a few comments on this Application.

1. The manual does not appear to have the 20cm separation caution. Please include this 20cm separation caution statement in the manual for mobile devices.

Response: Please refer to the revised manual uploaded with this response.

2. Please note that the band edge PLOT 8-2 appears to be failing at 1895MHz. This may be due to the span used. Please note that at 1895MHz the band edge appears closer to -11dBm than -13dBm. Please provide a plot that clearly shows compliance to the 1895MHz band edge.

Response: The measurement performed with the spectrum analyzer was showing passing values for the block edge. By doing the same plots with a narrower span, we were able to show that all the signals at and after the block edge are compliant with the -13 dBm limit. Please see the revised report uploaded with this response.

3. Please note that the band edge PLOT 8-4 appears to be failing at 1910MHz. This may be due to the span used. Please note that at 1910MHz the band edge appears closer to -12dBm than -13dBm. Please provide a plot that clearly shows compliance to the 1910MHz band edge.

Response: The measurement performed with the spectrum analyzer was showing passing values for the block edge. By doing the same plots with a narrower span, we were able to show that all the signals at and after the block edge are compliant with the -13 dBm limit. Please see the revised report uploaded with this response.

Dennis Ward
mailto:dward@AmericanTCB.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the sender.