



Annex A of test report F082568E02
EUT: cB-0901-0302AP inside RBEPA
Manufacturer: connectBlue AB



82568_2.jpg

RBEPA, test set-up fully anechoic chamber


Annex A of test report F082568E02
EUT: cB-0901-0302AP inside RBEPA
Manufacturer: connectBlue AB



82568_4.jpg

RBEPA, test set-up fully anechoic chamber

Annex A of test report F082568E02
EUT: cB-0901-0302AP inside RBEPA
Manufacturer: connectBlue AB



82568_1.jpg

RBEPA, test set-up fully anechoic chamber

Annex A of test report F082568E02
EUT: cB-0901-0302AP inside RBEPA
Manufacturer: connectBlue AB



82568_3.jpg

RBEPA, test set-up fully anechoic chamber


Annex A of test report F082568E02
EUT: cB-0901-0302AP inside RBEPA
Manufacturer: connectBlue AB



82568_11.jpg

RBEPA, test set-up open area test-site

Annex A of test report F082568E02
EUT: cB-0901-0302AP inside RBEPA
Manufacturer: connectBlue AB



82568_12.jpg

RBEPA, test set-up conducted emission measurement