

FCC ID: TJA-RES-1001

D.L.S. ELECTRONIC SYSTEMS, INC.
1250 Peterson Drive
Wheeling, Illinois 60090

LIST MODIFICATIONS

FOR THE

Classroom Response System - Renaissance Responder

MODEL NUMBER: RES-1001

1. Capacitor C34 (large electrolytic) was added at the battery signal. C34 is located directly above the -battery connector on rev 7.
2. Pads and traces for non-stuff components C28, C29, C31, C32, L6, L7, and U5 were removed from the artwork. All of these components were located to the right of U4 near the top of the PCB on rev 5.
- 3.
- 4.
- 5.