



1776 K STREET NW
WASHINGTON, DC 20006
PHONE 202.719.7000
FAX 202.719.7049

7925 JONES BRANCH DRIVE
McLEAN, VA 22102
PHONE 703.905.2800
FAX 703.905.2820

www.wileyrein.com

February 17, 2011

Jennifer D. Hindin
202.719.4975
jhindin@wileyrein.com

Marlene H. Dortch
Secretary
Federal Communications Commission
445 12th Street SW
Washington, D.C. 20554

Re: Application of PanAmSat Licensee Corp. to Modify Authorization for
Galaxy 11 (call sign S2253), File No. SAT-MOD-20101102-00229

Dear Ms. Dortch:

Intelsat License LLC¹ (“Intelsat”), by counsel, herein supplements the above-referenced pending modification application seeking authority for Galaxy 11 (call sign S2253) to relocate to, and operate at, 304.5° E.L. (55.5° W.L).² Specifically, Intelsat notifies the Commission that the Galaxy 11 satellite has two helium tanks with a volume of 68.579 liters each. The helium in those two tanks that was used during orbit raising was permanently isolated from the propulsion system by firing a pyrotechnic valve at beginning of on-orbit life such that the residual gas (about 5%) cannot be vented at end of life.

Please contact the undersigned with any questions.

Sincerely,

/s/ Jennifer D. Hindin

Jennifer D. Hindin
Counsel to Intelsat License LLC

cc: Robert Nelson, Karl Kensinger, Kathryn Medley, Stephen Duall

¹ The licenses previously held by PanAmSat Licensee Corp. recently have been assigned to Intelsat License LLC. See Letter from Jennifer Hindin to Marlene H. Dortch, Notification of Consummation of *Pro Forma* Assignment and Transfer of Control and Name Change, File Nos. SES-ASG-20101203-01501, SES-ASG-20101206-01502, SES-T/C-20101203-01503, SES-ASG-20101203-01504, SES-ASG-20101206-01512, SAT-ASG-20101203-00251, SAT-ASG-20101203-00252, SAT-T/C-20101203-00253, SAT-T/C-20101203-00254, and 0004520968 (filed Jan. 18, 2011).

² See *PanAmSat Licensee Corp. Application to Modify Authorization for Galaxy 11*, File No. SAT-MOD-20101102-00229 (filed Nov. 2, 2010).