

March 14, 2013

Ms. Marlene H. Dortch
Secretary
Federal Communications Commission
445 12th Street, S.W.
Washington, DC 20554



Re: Supplement to Application for Authority to Modify Galaxy 11 License
Call Sign S2253; File No.: SAT-MOD-20121018-00184

Dear Ms. Dortch:

Intelsat License LLC ("Intelsat"), pursuant to Section 1.65 of the Commission's rules,¹ hereby supplements its above referenced pending application to redeploy the Galaxy 11 satellite (call sign S2253) from 55.5° W.L. to 44.8° W.L.

As the Commission is aware, on February 1, 2013 Intelsat 27, which was to replace Galaxy 11 at 55.5° W.L., failed to launch successfully and was lost.² As a result of this launch failure, Intelsat plans to delay the redeployment of Galaxy 11 to 44.8° W.L. until the second half of 2015, when Galaxy 11 is expected to be replaced by a new satellite – Intelsat 27R. With the exception of the timing of the redeployment, all other information in the pending application remains the same.

Please contact the undersigned should you have any questions.

Sincerely,

A handwritten signature in blue ink, appearing to read "Susan H. Crandall".

Susan H. Crandall
Assistant General Counsel
Intelsat Corporation

Cc: Bob Nelson
Stephen Duall
Jay Whaley
Cindy Spiers

¹ 47 U.S.C. §1.65.

² See Letter from Jennifer D. Hindin, Counsel for Intelsat License LLC, to Ms. Marlene H. Dortch, FCC, File No. SAT-LOA-20110610-00105 (Mar. 1, 2013).