

```
[FormatInfo]
format_ver=1
[GeoMain]
ntc_id=9000021
adm=USA
sat_name=USABSS-21
long_nom=-101.0000
n_diag=1
[COHeader]
beam_id=BB10
emi_rcp=E
polar_disc=X
reason=B
n_bore=1
n_cont=8
[B1]
gain=0.00
p=-120.2120;44.6490
[C1]
gain=-10.00
n_point=103
P1=-127.5000;48.7140
P2=-127.3720;49.0000
P3=-127.0840;49.5000
P4=-127.0000;49.6180
P5=-126.6940;50.0000
P6=-126.5000;50.2040
P7=-126.1700;50.5000
P8=-126.0000;50.6330
P9=-125.5000;50.9460
P10=-125.3860;51.0000
P11=-125.0000;51.1670
P12=-124.5000;51.3180
P13=-124.0000;51.4090
P14=-123.5000;51.4440
P15=-123.0000;51.4280
P16=-122.5000;51.3700
P17=-122.0000;51.2740
P18=-121.5000;51.1460
P19=-121.0420;51.0000
P20=-121.0000;50.9860
P21=-120.5000;50.7880
P22=-120.0000;50.5660
P23=-119.8700;50.5000
P24=-119.5000;50.3110
P25=-119.0000;50.0350
P26=-118.9420;50.0000
P27=-118.5000;49.7210
P28=-118.1670;49.5000
P29=-118.0000;49.3830
P30=-117.5000;49.0150
P31=-117.4810;49.0000
P32=-117.0000;48.6050
P33=-116.8770;48.5000
P34=-116.5000;48.1490
P35=-116.3460;48.0000
P36=-116.0000;47.6340
```

P37=-115.8770;47.5000
P38=-115.5000;47.0470
P39=-115.4620;47.0000
P40=-115.1090;46.5000
P41=-115.0000;46.3190
P42=-114.8130;46.0000
P43=-114.5740;45.5000
P44=-114.5000;45.2990
P45=-114.3930;45.0000
P46=-114.2750;44.5000
P47=-114.2160;44.0000
P48=-114.2140;43.5000
P49=-114.2710;43.0000
P50=-114.3940;42.5000
P51=-114.5000;42.2040
P52=-114.5790;42.0000
P53=-114.8350;41.5000
P54=-115.0000;41.2430
P55=-115.1780;41.0000
P56=-115.5000;40.6210
P57=-115.6260;40.5000
P58=-116.0000;40.1970
P59=-116.2990;40.0000
P60=-116.5000;39.8860
P61=-117.0000;39.6850
P62=-117.5000;39.5550
P63=-117.8940;39.5000
P64=-118.0000;39.4870
P65=-118.5000;39.4790
P66=-118.7810;39.5000
P67=-119.0000;39.5180
P68=-119.5000;39.5990
P69=-120.0000;39.7140
P70=-120.5000;39.8560
P71=-120.9460;40.0000
P72=-121.0000;40.0200
P73=-121.5000;40.2280
P74=-122.0000;40.4480
P75=-122.1120;40.5000
P76=-122.5000;40.7060
P77=-123.0000;40.9760
P78=-123.0420;41.0000
P79=-123.5000;41.2900
P80=-123.8290;41.5000
P81=-124.0000;41.6230
P82=-124.5000;41.9830
P83=-124.5230;42.0000
P84=-125.0000;42.3960
P85=-125.1260;42.5000
P86=-125.5000;42.8490
P87=-125.6640;43.0000
P88=-126.0000;43.3560
P89=-126.1390;43.5000
P90=-126.5000;43.9330
P91=-126.5570;44.0000
P92=-126.9170;44.5000
P93=-127.0000;44.6400

P94=-127.2180;45.0000
P95=-127.4570;45.5000
P96=-127.5000;45.6210
P97=-127.6370;46.0000
P98=-127.7550;46.5000
P99=-127.8130;47.0000
P100=-127.8070;47.5000
P101=-127.7310;48.0000
P102=-127.5900;48.5000
P103=-127.5000;48.7140
[C2]
gain=-20.00
n_point=181
P1=-132.5000;48.8880
P2=-132.4580;49.0000
P3=-132.1300;49.5000
P4=-132.0000;49.6350
P5=-131.6520;50.0000
P6=-131.5000;50.1280
P7=-131.1030;50.5000
P8=-131.0000;50.5850
P9=-130.5780;51.0000
P10=-130.5000;51.0780
P11=-130.1280;51.5000
P12=-130.0000;51.6720
P13=-129.7660;52.0000
P14=-129.5000;52.4750
P15=-129.4850;52.5000
P16=-129.2720;53.0000
P17=-129.0970;53.5000
P18=-129.0000;53.8390
P19=-128.9430;54.0000
P20=-128.8030;54.5000
P21=-128.6500;55.0000
P22=-128.5000;55.3670
P23=-128.4270;55.5000
P24=-128.0000;55.9870
P25=-127.9810;56.0000
P26=-127.5000;56.2720
P27=-127.0000;56.4240
P28=-126.5000;56.4770
P29=-126.0000;56.4680
P30=-125.5000;56.4110
P31=-125.0000;56.3120
P32=-124.5000;56.1720
P33=-124.0000;56.0040
P34=-123.9900;56.0000
P35=-123.5000;55.7800
P36=-123.0000;55.5190
P37=-122.9690;55.5000
P38=-122.5000;55.2110
P39=-122.2060;55.0000
P40=-122.0000;54.8620
P41=-121.5440;54.5000
P42=-121.5000;54.4670
P43=-121.0000;54.0310
P44=-120.9700;54.0000

P45=-120.5000;53.5910
P46=-120.4140;53.5000
P47=-120.0000;53.1560
P48=-119.8430;53.0000
P49=-119.5000;52.7080
P50=-119.2910;52.5000
P51=-119.0000;52.2710
P52=-118.6880;52.0000
P53=-118.5000;51.8530
P54=-118.0740;51.5000
P55=-118.0000;51.4440
P56=-117.5000;51.0510
P57=-117.4350;51.0000
P58=-117.0000;50.6490
P59=-116.7970;50.5000
P60=-116.5000;50.2700
P61=-116.1020;50.0000
P62=-116.0000;49.9220
P63=-115.5000;49.5850
P64=-115.3350;49.5000
P65=-115.0000;49.2940
P66=-114.5000;49.0870
P67=-114.0780;49.0000
P68=-114.0000;48.9780
P69=-113.5000;48.9920
P70=-113.4150;49.0000
P71=-113.0000;49.0400
P72=-112.5580;49.0000
P73=-112.5000;48.9940
P74=-112.0000;48.7940
P75=-111.5420;48.5000
P76=-111.5000;48.4730
P77=-111.0000;48.0190
P78=-110.9830;48.0000
P79=-110.5590;47.5000
P80=-110.5000;47.4280
P81=-110.2180;47.0000
P82=-110.0000;46.6540
P83=-109.9200;46.5000
P84=-109.6890;46.0000
P85=-109.5000;45.5310
P86=-109.4900;45.5000
P87=-109.3680;45.0000
P88=-109.2810;44.5000
P89=-109.2360;44.0000
P90=-109.2380;43.5000
P91=-109.2890;43.0000
P92=-109.4010;42.5000
P93=-109.5000;42.2030
P94=-109.5970;42.0000
P95=-109.9060;41.5000
P96=-110.0000;41.3770
P97=-110.5000;41.0530
P98=-111.0000;41.0280
P99=-111.5000;41.2030
P100=-112.0000;41.3790
P101=-112.5000;41.3610

P102=-113.0000;41.0440
P103=-113.0370;41.0000
P104=-113.5000;40.5360
P105=-113.5280;40.5000
P106=-113.9350;40.0000
P107=-114.0000;39.9020
P108=-114.3120;39.5000
P109=-114.5000;39.1930
P110=-114.6630;39.0000
P111=-114.9520;38.5000
P112=-115.0000;38.3380
P113=-115.1850;38.0000
P114=-115.1890;37.5000
P115=-115.0000;37.1280
P116=-114.9210;37.0000
P117=-114.9210;36.5000
P118=-115.0000;36.4210
P119=-115.5000;36.0640
P120=-115.6630;36.0000
P121=-116.0000;35.9360
P122=-116.5000;35.9320
P123=-116.9460;36.0000
P124=-117.0000;36.0160
P125=-117.5000;36.3050
P126=-117.7260;36.5000
P127=-118.0000;36.7980
P128=-118.1400;37.0000
P129=-118.5000;37.2350
P130=-118.8330;37.5000
P131=-119.0000;37.5600
P132=-119.5000;37.7820
P133=-119.9420;38.0000
P134=-120.0000;38.0200
P135=-120.5000;38.2190
P136=-121.0000;38.4200
P137=-121.1900;38.5000
P138=-121.5000;38.6290
P139=-122.0000;38.8340
P140=-122.4350;39.0000
P141=-122.5000;39.0290
P142=-123.0000;39.2500
P143=-123.5000;39.4550
P144=-123.6160;39.5000
P145=-124.0000;39.6820
P146=-124.5000;39.9070
P147=-124.7150;40.0000
P148=-125.0000;40.1460
P149=-125.5000;40.3920
P150=-125.7280;40.5000
P151=-126.0000;40.6500
P152=-126.5000;40.9180
P153=-126.6580;41.0000
P154=-127.0000;41.2050
P155=-127.5000;41.4960
P156=-127.5060;41.5000
P157=-128.0000;41.8260
P158=-128.2690;42.0000

P159=-128.5000;42.1710
P160=-128.9510;42.5000
P161=-129.0000;42.5400
P162=-129.5000;42.9510
P163=-129.5600;43.0000
P164=-130.0000;43.4020
P165=-130.1070;43.5000
P166=-130.5000;43.9000
P167=-130.5980;44.0000
P168=-131.0000;44.4500
P169=-131.0440;44.5000
P170=-131.4360;45.0000
P171=-131.5000;45.0950
P172=-131.7710;45.5000
P173=-132.0000;45.8900
P174=-132.0640;46.0000
P175=-132.3030;46.5000
P176=-132.4900;47.0000
P177=-132.5000;47.0400
P178=-132.6160;47.5000
P179=-132.6740;48.0000
P180=-132.6290;48.5000
P181=-132.5000;48.8880
[C3]
gain=-30.00
n_point=359
P1=-136.0000;50.6720
P2=-135.8140;51.0000
P3=-135.5000;51.3800
P4=-135.3730;51.5000
P5=-135.0000;51.7390
P6=-134.5000;51.9770
P7=-134.4410;52.0000
P8=-134.0000;52.1350
P9=-133.5000;52.2820
P10=-133.0000;52.4760
P11=-132.9550;52.5000
P12=-132.5000;52.8640
P13=-132.3920;53.0000
P14=-132.3210;53.5000
P15=-132.5000;53.9830
P16=-132.5060;54.0000
P17=-132.7790;54.5000
P18=-133.0000;54.8520
P19=-133.1020;55.0000
P20=-133.4240;55.5000
P21=-133.5000;55.6670
P22=-133.6590;56.0000
P23=-133.7980;56.5000
P24=-133.8590;57.0000
P25=-133.7170;57.5000
P26=-133.5000;57.9950
P27=-133.4980;58.0000
P28=-133.2970;58.5000
P29=-133.0530;59.0000
P30=-133.0000;59.1470
P31=-132.8380;59.5000

P32=-132.6440;60.0000
P33=-132.5000;60.2790
P34=-132.2910;60.5000
P35=-132.1920;61.0000
P36=-132.0000;61.1920
P37=-131.5000;61.3490
P38=-131.0000;61.3690
P39=-130.5000;61.3060
P40=-130.0000;61.1800
P41=-129.5000;61.0200
P42=-129.4510;61.0000
P43=-129.0000;60.9000
P44=-128.5000;60.7690
P45=-128.0000;60.6250
P46=-127.5950;60.5000
P47=-127.5000;60.4720
P48=-127.0000;60.3060
P49=-126.5000;60.1240
P50=-126.1900;60.0000
P51=-126.0000;59.9340
P52=-125.5000;59.7430
P53=-125.0000;59.5460
P54=-124.8930;59.5000
P55=-124.5000;59.3300
P56=-124.0000;59.1120
P57=-123.7530;59.0000
P58=-123.5000;58.8780
P59=-123.0000;58.6270
P60=-122.7540;58.5000
P61=-122.5000;58.3620
P62=-122.0000;58.0900
P63=-121.8370;58.0000
P64=-121.5000;57.7930
P65=-121.0170;57.5000
P66=-121.0000;57.4880
P67=-120.5000;57.1310
P68=-120.3100;57.0000
P69=-120.0000;56.7540
P70=-119.6620;56.5000
P71=-119.5000;56.3530
P72=-119.1180;56.0000
P73=-119.0000;55.8730
P74=-118.6480;55.5000
P75=-118.5000;55.3000
P76=-118.2710;55.0000
P77=-118.0250;54.5000
P78=-118.0000;54.3080
P79=-117.9600;54.0000
P80=-117.9540;53.5000
P81=-117.8710;53.0000
P82=-117.6790;52.5000
P83=-117.5000;52.3020
P84=-117.2720;52.0000
P85=-117.0000;51.7380
P86=-116.6890;51.5000
P87=-116.5000;51.3520
P88=-116.0000;51.1230

P89=-115.5000;51.2780
P90=-115.3290;51.5000
P91=-115.2050;52.0000
P92=-115.1210;52.5000
P93=-115.0000;52.6850
P94=-114.5000;52.8390
P95=-114.0000;52.7600
P96=-113.5000;52.5800
P97=-113.3470;52.5000
P98=-113.0000;52.3080
P99=-112.5200;52.0000
P100=-112.5000;51.9870
P101=-112.0000;51.6010
P102=-111.8820;51.5000
P103=-111.5000;51.1820
P104=-111.2940;51.0000
P105=-111.0000;50.7300
P106=-110.7600;50.5000
P107=-110.5000;50.2320
P108=-110.2830;50.0000
P109=-110.0000;49.6870
P110=-109.8160;49.5000
P111=-109.5000;49.1310
P112=-109.3560;49.0000
P113=-109.0000;48.5690
P114=-108.9040;48.5000
P115=-108.5000;48.0350
P116=-108.3500;48.0000
P117=-108.0000;47.8260
P118=-107.9060;48.0000
P119=-107.8000;48.5000
P120=-107.7890;49.0000
P121=-107.8270;49.5000
P122=-107.9080;50.0000
P123=-107.9890;50.5000
P124=-108.0000;50.5760
P125=-108.0420;51.0000
P126=-108.0760;51.5000
P127=-108.0170;52.0000
P128=-108.0000;52.0300
P129=-107.8130;52.0000
P130=-107.5000;51.9660
P131=-107.0000;51.5720
P132=-106.9400;51.5000
P133=-106.5000;51.0410
P134=-106.4720;51.0000
P135=-106.1070;50.5000
P136=-106.0000;50.3750
P137=-105.7760;50.0000
P138=-105.5000;49.6010
P139=-105.4480;49.5000
P140=-105.1870;49.0000
P141=-105.0000;48.6700
P142=-104.9290;48.5000
P143=-104.7260;48.0000
P144=-104.5080;47.5000
P145=-104.5000;47.4800

P146=-104.3640;47.0000
P147=-104.2230;46.5000
P148=-104.0940;46.0000
P149=-104.0000;45.5820
P150=-103.9870;45.5000
P151=-103.9250;45.0000
P152=-103.8830;44.5000
P153=-103.8630;44.0000
P154=-103.8660;43.5000
P155=-103.8910;43.0000
P156=-103.9370;42.5000
P157=-104.0000;42.0200
P158=-104.0040;42.0000
P159=-104.1220;41.5000
P160=-104.2560;41.0000
P161=-104.4010;40.5000
P162=-104.5000;40.1730
P163=-104.5780;40.0000
P164=-104.8030;39.5000
P165=-104.9960;39.0000
P166=-105.0000;38.9910
P167=-105.2650;38.5000
P168=-105.4860;38.0000
P169=-105.5000;37.9700
P170=-105.7900;37.5000
P171=-106.0000;37.0770
P172=-106.0490;37.0000
P173=-106.3650;36.5000
P174=-106.5000;36.2700
P175=-106.6950;36.0000
P176=-107.0000;35.5360
P177=-107.0290;35.5000
P178=-107.4520;35.0000
P179=-107.5000;34.9450
P180=-107.9330;34.5000
P181=-108.0000;34.4370
P182=-108.5000;34.0370
P183=-108.5530;34.0000
P184=-109.0000;33.6890
P185=-109.2960;33.5000
P186=-109.5000;33.3830
P187=-110.0000;33.0760
P188=-110.1300;33.0000
P189=-110.5000;32.8580
P190=-111.0000;32.5580
P191=-111.0690;32.5000
P192=-111.5000;32.3060
P193=-111.8550;32.0000
P194=-112.0000;31.9350
P195=-112.5000;31.6950
P196=-112.8150;31.5000
P197=-113.0000;31.4380
P198=-113.5000;31.2880
P199=-114.0000;31.1440
P200=-114.5000;31.0320
P201=-114.7880;31.0000
P202=-115.0000;30.9900

P203=-115.3260;31.0000
P204=-115.5000;31.0160
P205=-116.0000;31.1650
P206=-116.5000;31.4120
P207=-116.6430;31.5000
P208=-116.5000;31.6070
P209=-116.0000;31.9560
P210=-115.9380;32.0000
P211=-115.5000;32.0780
P212=-115.0000;32.1680
P213=-114.5000;32.2640
P214=-114.0000;32.3650
P215=-113.5000;32.4910
P216=-113.4660;32.5000
P217=-113.0000;32.5610
P218=-112.5000;32.6450
P219=-112.0000;32.7770
P220=-111.6260;33.0000
P221=-111.5000;33.0440
P222=-111.0000;33.3000
P223=-110.8070;33.5000
P224=-110.5000;33.7800
P225=-110.3280;34.0000
P226=-110.0000;34.4770
P227=-109.9870;34.5000
P228=-109.6160;35.0000
P229=-109.5000;35.1710
P230=-109.2470;35.5000
P231=-109.0000;35.8830
P232=-108.9140;36.0000
P233=-108.5500;36.5000
P234=-108.5000;36.5660
P235=-108.1490;37.0000
P236=-108.0000;37.2420
P237=-107.8030;37.5000
P238=-107.5100;38.0000
P239=-107.5000;38.0210
P240=-107.2160;38.5000
P241=-107.0530;39.0000
P242=-107.0000;39.2370
P243=-106.9050;39.5000
P244=-106.8080;40.0000
P245=-106.7860;40.5000
P246=-106.8310;41.0000
P247=-106.9500;41.5000
P248=-107.0000;41.6570
P249=-107.5000;41.7550
P250=-107.6210;41.5000
P251=-108.0000;41.0100
P252=-108.0050;41.0000
P253=-108.3000;40.5000
P254=-108.5000;40.2100
P255=-108.6400;40.0000
P256=-108.9780;39.5000
P257=-109.0000;39.4720
P258=-109.4110;39.0000
P259=-109.5000;38.8910

P260=-109.8680;38.5000
P261=-110.0000;38.3520
P262=-110.3650;38.0000
P263=-110.5000;37.8330
P264=-110.7750;37.5000
P265=-111.0000;37.1420
P266=-111.0950;37.0000
P267=-111.4200;36.5000
P268=-111.5000;36.3920
P269=-111.8230;36.0000
P270=-112.0000;35.8180
P271=-112.3070;35.5000
P272=-112.5000;35.3290
P273=-112.9010;35.0000
P274=-113.0000;34.9410
P275=-113.5000;34.6580
P276=-113.8080;34.5000
P277=-114.0000;34.4200
P278=-114.5000;34.2520
P279=-115.0000;34.1220
P280=-115.5000;34.0280
P281=-115.7920;34.0000
P282=-116.0000;33.9860
P283=-116.5000;33.9820
P284=-116.9460;34.0000
P285=-117.0000;34.0030
P286=-117.5000;34.0710
P287=-118.0000;34.1650
P288=-118.5000;34.2770
P289=-119.0000;34.4000
P290=-119.4070;34.5000
P291=-119.5000;34.5370
P292=-120.0000;34.7430
P293=-120.5000;34.9450
P294=-120.6360;35.0000
P295=-121.0000;35.2240
P296=-121.4520;35.5000
P297=-121.5000;35.5500
P298=-121.9240;36.0000
P299=-122.0000;36.3050
P300=-122.0490;36.5000
P301=-122.0000;36.6080
P302=-121.8540;37.0000
P303=-121.8330;37.5000
P304=-122.0000;37.6420
P305=-122.3710;38.0000
P306=-122.5000;38.0660
P307=-123.0000;38.3110
P308=-123.5000;38.4990
P309=-123.5020;38.5000
P310=-124.0000;38.6900
P311=-124.5000;38.8430
P312=-125.0000;38.9680
P313=-125.1430;39.0000
P314=-125.5000;39.1220
P315=-126.0000;39.2880
P316=-126.5000;39.4460

P317=-126.6740;39.5000
P318=-127.0000;39.6350
P319=-127.5000;39.8370
P320=-127.9230;40.0000
P321=-128.0000;40.0370
P322=-128.5000;40.2740
P323=-128.9960;40.5000
P324=-129.0000;40.5020
P325=-129.5000;40.7680
P326=-129.9390;41.0000
P327=-130.0000;41.0370
P328=-130.5000;41.3340
P329=-130.7780;41.5000
P330=-131.0000;41.6500
P331=-131.5000;41.9910
P332=-131.5140;42.0000
P333=-132.0000;42.3630
P334=-132.1840;42.5000
P335=-132.5000;42.7670
P336=-132.7800;43.0000
P337=-133.0000;43.2070
P338=-133.3160;43.5000
P339=-133.5000;43.6890
P340=-133.8160;44.0000
P341=-134.0000;44.2120
P342=-134.2620;44.5000
P343=-134.5000;44.8130
P344=-134.6500;45.0000
P345=-134.9860;45.5000
P346=-135.0000;45.5230
P347=-135.3120;46.0000
P348=-135.5000;46.3680
P349=-135.5740;46.5000
P350=-135.7980;47.0000
P351=-135.9720;47.5000
P352=-136.0000;47.5890
P353=-136.1300;48.0000
P354=-136.2410;48.5000
P355=-136.2960;49.0000
P356=-136.2940;49.5000
P357=-136.2310;50.0000
P358=-136.0830;50.5000
P359=-136.0000;50.6720
[C4]
gain=-30.00
n_point=185
P1=-160.3920;72.4460
P2=-160.0000;72.3780
P3=-159.5000;72.2930
P4=-159.0000;72.2110
P5=-158.5000;72.1260
P6=-158.0000;72.0390
P7=-157.7510;72.0000
P8=-157.5000;71.9550
P9=-157.0000;71.8680
P10=-156.5000;71.7820
P11=-156.0000;71.6960

P12=-155.5000;71.6050
P13=-155.0000;71.5180
P14=-154.8870;71.5000
P15=-154.5000;71.4310
P16=-154.0000;71.3430
P17=-153.5000;71.2500
P18=-153.0000;71.1580
P19=-152.5000;71.0680
P20=-152.1050;71.0000
P21=-152.0000;70.9810
P22=-151.5000;70.8820
P23=-151.0000;70.7860
P24=-150.5000;70.6940
P25=-150.0000;70.5980
P26=-149.5000;70.5000
P27=-149.4990;70.5000
P28=-149.0000;70.4010
P29=-148.5000;70.3030
P30=-148.0000;70.1990
P31=-147.5000;70.0980
P32=-147.0040;70.0000
P33=-147.0000;69.9990
P34=-146.5000;69.8880
P35=-146.0000;69.7820
P36=-145.5000;69.6760
P37=-145.0000;69.5640
P38=-144.7070;69.5000
P39=-144.5000;69.4540
P40=-144.0000;69.3400
P41=-143.5000;69.2220
P42=-143.0000;69.1090
P43=-142.5460;69.0000
P44=-142.5000;68.9870
P45=-142.0000;68.8580
P46=-141.5000;68.7380
P47=-141.0000;68.6190
P48=-140.5160;68.5000
P49=-140.5000;68.4950
P50=-140.0000;68.3300
P51=-139.5000;68.1850
P52=-139.0000;68.0450
P53=-138.8260;68.0000
P54=-138.5000;67.8940
P55=-138.0000;67.7250
P56=-137.5000;67.5570
P57=-137.3360;67.5000
P58=-137.0000;67.3820
P59=-136.5000;67.2060
P60=-136.0000;67.0240
P61=-135.9330;67.0000
P62=-135.5000;66.8290
P63=-135.0000;66.6410
P64=-134.6060;66.5000
P65=-134.5000;66.4430
P66=-134.0000;66.1610
P67=-133.6900;66.0000
P68=-133.5000;65.8930

P69=-133.0000;65.6040
P70=-132.8260;65.5000
P71=-132.5000;65.2530
P72=-132.1420;65.0000
P73=-132.0000;64.8180
P74=-131.7620;64.5000
P75=-131.5000;64.0800
P76=-131.4490;64.0000
P77=-131.4730;63.5000
P78=-131.5000;63.2650
P79=-131.5360;63.0000
P80=-131.8600;62.5000
P81=-132.0000;62.2160
P82=-132.2860;62.0000
P83=-132.5000;61.9610
P84=-133.0000;61.9940
P85=-133.0510;62.0000
P86=-133.5000;62.0750
P87=-134.0000;62.1690
P88=-134.5000;62.2480
P89=-135.0000;62.3100
P90=-135.5000;62.3660
P91=-136.0000;62.4150
P92=-136.5000;62.4640
P93=-136.9670;62.5000
P94=-137.0000;62.5030
P95=-137.5000;62.5540
P96=-138.0000;62.5850
P97=-138.5000;62.6060
P98=-139.0000;62.6150
P99=-139.5000;62.6110
P100=-140.0000;62.5940
P101=-140.5000;62.5500
P102=-140.8820;62.5000
P103=-141.0000;62.4850
P104=-141.5000;62.3980
P105=-142.0000;62.2750
P106=-142.5000;62.1300
P107=-142.7850;62.0000
P108=-143.0000;61.8080
P109=-143.3310;61.5000
P110=-143.4160;61.0000
P111=-143.5000;60.6130
P112=-143.5250;60.5000
P113=-143.5000;60.2500
P114=-143.4730;60.0000
P115=-143.4140;59.5000
P116=-143.4640;59.0000
P117=-143.5000;58.9220
P118=-143.8400;58.5000
P119=-144.0000;58.4240
P120=-144.5000;58.4060
P121=-145.0000;58.4490
P122=-145.2620;58.5000
P123=-145.5000;58.5510
P124=-146.0000;58.7130
P125=-146.5000;58.8710

P126=-146.8010;59.0000
P127=-147.0000;59.1000
P128=-147.5000;59.3110
P129=-147.8940;59.5000
P130=-148.0000;59.5520
P131=-148.5000;59.7750
P132=-148.9510;60.0000
P133=-149.0000;60.0270
P134=-149.5000;60.2860
P135=-149.9450;60.5000
P136=-150.0000;60.5270
P137=-150.5000;60.7820
P138=-150.9920;61.0000
P139=-151.0000;61.0040
P140=-151.5000;61.2910
P141=-151.9830;61.5000
P142=-152.0000;61.5080
P143=-152.5000;61.7650
P144=-152.9900;62.0000
P145=-153.0000;62.0050
P146=-153.5000;62.2420
P147=-154.0000;62.4700
P148=-154.0740;62.5000
P149=-154.5000;62.7160
P150=-155.0000;62.9360
P151=-155.1360;63.0000
P152=-155.5000;63.1670
P153=-156.0000;63.3750
P154=-156.3390;63.5000
P155=-156.5000;63.5780
P156=-157.0000;63.7980
P157=-157.4900;64.0000
P158=-157.5000;64.0040
P159=-158.0000;64.2020
P160=-158.5000;64.3790
P161=-158.8510;64.5000
P162=-159.0000;64.5530
P163=-159.5000;64.7360
P164=-160.0000;64.8930
P165=-160.3950;65.0000
P166=-160.5000;65.0330
P167=-161.0000;65.1970
P168=-161.5000;65.3520
P169=-162.0000;65.4930
P170=-162.0270;65.5000
P171=-162.5000;65.6260
P172=-163.0000;65.7490
P173=-163.5000;65.8700
P174=-164.0000;65.9900
P175=-164.0420;66.0000
P176=-164.5000;66.1060
P177=-165.0000;66.2130
P178=-165.5000;66.3120
P179=-166.0000;66.4070
P180=-166.5000;66.4940
P181=-166.5310;66.5000
P182=-167.0000;66.5930

P183=-167.5000;66.6780
P184=-168.0000;66.7580
P185=-168.0850;66.7710
[C5]
gain=-2.00
n_point=93
P1=-123.0000;46.9370
P2=-122.9550;47.0000
P3=-122.8033;47.1237
P4=-122.6517;47.2473
P5=-122.5000;47.3710
P6=-122.2230;47.5000
P7=-122.0000;47.5730
P8=-121.7500;47.6065
P9=-121.5000;47.6400
P10=-121.2500;47.6310
P11=-121.0000;47.6220
P12=-120.7500;47.5780
P13=-120.5000;47.5340
P14=-120.3880;47.5000
P15=-120.1940;47.4320
P16=-120.0000;47.3640
P17=-119.7500;47.2460
P18=-119.5000;47.1280
P19=-119.2820;47.0000
P20=-119.1410;46.9085
P21=-119.0000;46.8170
P22=-118.7945;46.6585
P23=-118.5890;46.5000
P24=-118.5000;46.4210
P25=-118.3620;46.2807
P26=-118.2240;46.1403
P27=-118.0860;46.0000
P28=-118.0000;45.8890
P29=-117.8700;45.6945
P30=-117.7400;45.5000
P31=-117.6600;45.3510
P32=-117.5800;45.2020
P33=-117.5000;45.0530
P34=-117.4760;45.0000
P35=-117.4257;44.8333
P36=-117.3753;44.6667
P37=-117.3250;44.5000
P38=-117.3110;44.3333
P39=-117.2970;44.1667
P40=-117.2830;44.0000
P41=-117.3050;43.8333
P42=-117.3270;43.6667
P43=-117.3490;43.5000
P44=-117.4245;43.3100
P45=-117.5000;43.1200
P46=-117.5680;43.0000
P47=-117.7120;42.8573
P48=-117.8560;42.7147
P49=-118.0000;42.5720
P50=-118.1160;42.5000
P51=-118.3080;42.4190

P52=-118.5000;42.3380
P53=-118.7500;42.2925
P54=-119.0000;42.2470
P55=-119.2500;42.2525
P56=-119.5000;42.2580
P57=-119.7500;42.3020
P58=-120.0000;42.3460
P59=-120.2500;42.4220
P60=-120.5000;42.4980
P61=-120.5050;42.5000
P62=-120.7525;42.6225
P63=-121.0000;42.7450
P64=-121.2180;42.8725
P65=-121.4360;43.0000
P66=-121.5000;43.0450
P67=-121.6667;43.1763
P68=-121.8333;43.3077
P69=-122.0000;43.4390
P70=-122.0700;43.5000
P71=-122.2133;43.6547
P72=-122.3567;43.8093
P73=-122.5000;43.9640
P74=-122.5310;44.0000
P75=-122.6463;44.1667
P76=-122.7617;44.3333
P77=-122.8770;44.5000
P78=-122.9385;44.6205
P79=-123.0000;44.7410
P80=-123.0620;44.8705
P81=-123.1240;45.0000
P82=-123.1720;45.1667
P83=-123.2200;45.3333
P84=-123.2680;45.5000
P85=-123.2823;45.6667
P86=-123.2967;45.8333
P87=-123.3110;46.0000
P88=-123.2810;46.1667
P89=-123.2510;46.3333
P90=-123.2210;46.5000
P91=-123.1473;46.6457
P92=-123.0737;46.7913
P93=-123.0000;46.9370
[C6]
gain=-4.00
n_point=102
P1=-124.5000;47.5200
P2=-124.3375;47.7600
P3=-124.1750;48.0000
P4=-124.0000;48.1760
P5=-123.7825;48.3380
P6=-123.5650;48.5000
P7=-123.5000;48.5370
P8=-123.2500;48.6345
P9=-123.0000;48.7320
P10=-122.7500;48.7855
P11=-122.5000;48.8390
P12=-122.2500;48.8560

P13=-122.0000;48.8730
P14=-121.7500;48.8580
P15=-121.5000;48.8430
P16=-121.2500;48.8010
P17=-121.0000;48.7590
P18=-120.7500;48.6940
P19=-120.5000;48.6290
P20=-120.1260;48.5000
P21=-120.0000;48.4530
P22=-119.7500;48.3355
P23=-119.5000;48.2180
P24=-119.2995;48.1090
P25=-119.0990;48.0000
P26=-119.0000;47.9430
P27=-118.7500;47.7760
P28=-118.5000;47.6090
P29=-118.3550;47.5000
P30=-118.1775;47.3525
P31=-118.0000;47.2050
P32=-117.7760;47.0000
P33=-117.6380;46.8580
P34=-117.5000;46.7160
P35=-117.3130;46.5000
P36=-117.1565;46.2990
P37=-117.0000;46.0980
P38=-116.9320;46.0000
P39=-116.7850;45.7500
P40=-116.6380;45.5000
P41=-116.5000;45.1950
P42=-116.4220;45.0000
P43=-116.3510;44.7500
P44=-116.2800;44.5000
P45=-116.2420;44.2500
P46=-116.2040;44.0000
P47=-116.2115;43.7500
P48=-116.2190;43.5000
P49=-116.2685;43.2500
P50=-116.3180;43.0000
P51=-116.4090;42.7690
P52=-116.5000;42.5380
P53=-116.5190;42.5000
P54=-116.7130;42.2500
P55=-116.9070;42.0000
P56=-117.0000;41.9100
P57=-117.2500;41.7350
P58=-117.5000;41.5600
P59=-117.6320;41.5000
P60=-118.0000;41.3690
P61=-118.2500;41.3205
P62=-118.5000;41.2720
P63=-118.7500;41.2625
P64=-119.0000;41.2530
P65=-119.2500;41.2745
P66=-119.5000;41.2960
P67=-119.7500;41.3455
P68=-120.0000;41.3950
P69=-120.3660;41.5000

P70=-120.5000;41.5440
P71=-120.7500;41.6490
P72=-121.0000;41.7540
P73=-121.2500;41.8735
P74=-121.5000;41.9930
P75=-121.5120;42.0000
P76=-121.7560;42.1530
P77=-122.0000;42.3060
P78=-122.2900;42.5000
P79=-122.5000;42.6650
P80=-122.7025;42.8325
P81=-122.9050;43.0000
P82=-123.0000;43.0900
P83=-123.2040;43.2950
P84=-123.4080;43.5000
P85=-123.5000;43.6080
P86=-123.6605;43.8040
P87=-123.8210;44.0000
P88=-124.0000;44.2650
P89=-124.1520;44.5000
P90=-124.2845;44.7500
P91=-124.4170;45.0000
P92=-124.5000;45.2260
P93=-124.5970;45.5000
P94=-124.6530;45.7500
P95=-124.7090;46.0000
P96=-124.7225;46.2500
P97=-124.7360;46.5000
P98=-124.7075;46.7500
P99=-124.6790;47.0000
P100=-124.5950;47.2500
P101=-124.5110;47.5000
P102=-124.5000;47.5200
[C7]
gain=-6.00
n_point=111
P1=-125.5000;48.2720
P2=-125.3640;48.5000
P3=-125.1820;48.7145
P4=-125.0000;48.9290
P5=-124.9250;49.0000
P6=-124.7125;49.1595
P7=-124.5000;49.3190
P8=-124.1710;49.5000
P9=-124.0000;49.5750
P10=-123.5000;49.7270
P11=-123.0000;49.8120
P12=-122.5000;49.8370
P13=-122.0000;49.8090
P14=-121.5000;49.7360
P15=-121.0000;49.6220
P16=-120.5920;49.5000
P17=-120.5000;49.4710
P18=-120.0000;49.2710
P19=-119.7500;49.1570
P20=-119.5000;49.0430
P21=-119.4180;49.0000

P22=-119.0000;48.7680
P23=-118.7785;48.6340
P24=-118.5570;48.5000
P25=-118.5000;48.4630
P26=-118.2500;48.2785
P27=-118.0000;48.0940
P28=-117.8820;48.0000
P29=-117.6910;47.8370
P30=-117.5000;47.6740
P31=-117.3120;47.5000
P32=-117.0000;47.1850
P33=-116.8300;47.0000
P34=-116.6650;46.7960
P35=-116.5000;46.5920
P36=-116.4310;46.5000
P37=-116.2670;46.2500
P38=-116.1030;46.0000
P39=-116.0000;45.8170
P40=-115.8370;45.5000
P41=-115.7370;45.2500
P42=-115.6370;45.0000
P43=-115.5685;44.7570
P44=-115.5000;44.5140
P45=-115.4970;44.5000
P46=-115.4610;44.2500
P47=-115.4250;44.0000
P48=-115.4205;43.7500
P49=-115.4160;43.5000
P50=-115.4495;43.2500
P51=-115.4830;43.0000
P52=-115.5000;42.9340
P53=-115.5670;42.7170
P54=-115.6340;42.5000
P55=-115.7570;42.2500
P56=-115.8800;42.0000
P57=-116.0000;41.8220
P58=-116.2630;41.5000
P59=-116.5000;41.2740
P60=-116.8770;41.0000
P61=-117.0000;40.9280
P62=-117.2500;40.8215
P63=-117.5000;40.7150
P64=-117.7500;40.6505
P65=-118.0000;40.5860
P66=-118.5000;40.5320
P67=-119.0000;40.5400
P68=-119.5000;40.6040
P69=-119.7500;40.6585
P70=-120.0000;40.7130
P71=-120.2500;40.7860
P72=-120.5000;40.8590
P73=-120.9050;41.0000
P74=-121.0000;41.0380
P75=-121.2500;41.1555
P76=-121.5000;41.2730
P77=-121.7265;41.3865
P78=-121.9530;41.5000

P79=-122.0000;41.5270
P80=-122.2500;41.6835
P81=-122.5000;41.8400
P82=-122.7450;42.0000
P83=-123.0000;42.1890
P84=-123.2025;42.3445
P85=-123.4050;42.5000
P86=-123.5000;42.5830
P87=-123.7320;42.7915
P88=-123.9640;43.0000
P89=-124.0000;43.0380
P90=-124.2165;43.2690
P91=-124.4330;43.5000
P92=-124.5000;43.5820
P93=-124.6680;43.7910
P94=-124.8360;44.0000
P95=-125.0000;44.2440
P96=-125.1690;44.5000
P97=-125.3070;44.7500
P98=-125.4450;45.0000
P99=-125.5000;45.1350
P100=-125.6470;45.5000
P101=-125.7195;45.7500
P102=-125.7920;46.0000
P103=-125.8290;46.2500
P104=-125.8660;46.5000
P105=-125.8700;46.7500
P106=-125.8740;47.0000
P107=-125.8370;47.2500
P108=-125.8000;47.5000
P109=-125.7185;47.7500
P110=-125.6370;48.0000
P111=-125.5000;48.2720
[C8]
gain=-30.00
n_point=71
P1=-113.5000;39.0720
P2=-113.5100;39.0360
P3=-113.5200;39.0000
P4=-113.5000;38.9620
P5=-113.4500;38.9299
P6=-113.4000;38.8978
P7=-113.3500;38.8657
P8=-113.3000;38.8336
P9=-113.2500;38.8015
P10=-113.2000;38.7694
P11=-113.1500;38.7373
P12=-113.1000;38.7052
P13=-113.0500;38.6731
P14=-113.0000;38.6410
P15=-112.9444;38.6679
P16=-112.8889;38.6948
P17=-112.8333;38.7217
P18=-112.7778;38.7486
P19=-112.7222;38.7754
P20=-112.6667;38.8023
P21=-112.6111;38.8292

P22=-112.5556;38.8561
P23=-112.5000;38.8830
P24=-112.4650;38.9220
P25=-112.4300;38.9610
P26=-112.3950;39.0000
P27=-112.3852;39.0500
P28=-112.3754;39.1000
P29=-112.3656;39.1500
P30=-112.3558;39.2000
P31=-112.3460;39.2500
P32=-112.3362;39.3000
P33=-112.3264;39.3500
P34=-112.3166;39.4000
P35=-112.3068;39.4500
P36=-112.2970;39.5000
P37=-112.3260;39.5401
P38=-112.3550;39.5803
P39=-112.3840;39.6204
P40=-112.4130;39.6606
P41=-112.4420;39.7007
P42=-112.4710;39.7409
P43=-112.5000;39.7810
P44=-112.5625;39.7997
P45=-112.6250;39.8185
P46=-112.6875;39.8372
P47=-112.7500;39.8560
P48=-112.8125;39.8748
P49=-112.8750;39.8935
P50=-112.9375;39.9123
P51=-113.0000;39.9310
P52=-113.0391;39.8918
P53=-113.0782;39.8526
P54=-113.1173;39.8135
P55=-113.1564;39.7743
P56=-113.1955;39.7351
P57=-113.2346;39.6959
P58=-113.2736;39.6567
P59=-113.3127;39.6175
P60=-113.3518;39.5784
P61=-113.3909;39.5392
P62=-113.4300;39.5000
P63=-113.4378;39.4524
P64=-113.4456;39.4049
P65=-113.4533;39.3573
P66=-113.4611;39.3098
P67=-113.4689;39.2622
P68=-113.4767;39.2147
P69=-113.4844;39.1671
P70=-113.4922;39.1196
P71=-113.5000;39.0720