

```
[FormatInfo]
format_ver=1
[GeoMain]
ntc_id=910100000
adm=USA
sat_name=USABSS-21
long_nom=-101.0000
n_diag=1
[COHeader]
beam_id=BB22
emi_rcp=E
polar_disc=C
reason=B
n_bore=1
n_cont=20
[B1]
gain=0.00
p=-84.1720;33.9810
[C1]
gain=-30.00
n_point=153
P1=-74.5000 ;40.7860
P2=-74.4080 ;40.5000
P3=-74.2920 ;40.0000
P4=-74.1980 ;39.5000
P5=-74.1050 ;39.0000
P6=-74.0740 ;38.5000
P7=-74.0160 ;38.0000
P8=-74.0570 ;37.5000
P9=-74.0610 ;37.0000
P10=-74.1630 ;36.5000
P11=-74.2170 ;36.0000
P12=-74.3560 ;35.5000
P13=-74.4390 ;35.0000
P14=-74.5000 ;34.7530
P15=-74.5980 ;34.5000
P16=-74.7900 ;34.0000
P17=-74.9480 ;33.5000
P18=-75.0000 ;33.3690
P19=-75.2210 ;33.0000
P20=-75.4400 ;32.5000
P21=-75.5000 ;32.3720
P22=-75.7430 ;32.0000
P23=-76.0000 ;31.5280
P24=-76.0200 ;31.5000
P25=-76.3980 ;31.0000
P26=-76.5000 ;30.8370
P27=-76.7760 ;30.5000
P28=-77.0000 ;30.1990
P29=-77.1770 ;30.0000
P30=-77.5000 ;29.6280
P31=-77.6220 ;29.5000
P32=-78.0000 ;29.1430
P33=-78.1490 ;29.0000
P34=-78.5000 ;28.6930
P35=-78.7140 ;28.5000
P36=-79.0000 ;28.2650
```

P37=-79.3050 ;28.0000
P38=-79.5000 ;27.8740
P39=-79.9660 ;27.5000
P40=-80.0000 ;27.4800
P41=-80.5000 ;27.1580
P42=-80.7170 ;27.0000
P43=-81.0000 ;26.8640
P44=-81.4970 ;26.5000
P45=-81.5000 ;26.4990
P46=-82.0000 ;26.2900
P47=-82.4930 ;26.0000
P48=-82.5000 ;25.9980
P49=-83.0000 ;25.8220
P50=-83.5000 ;25.6070
P51=-83.7720 ;25.5000
P52=-84.0000 ;25.4590
P53=-84.5000 ;25.3740
P54=-85.0000 ;25.2910
P55=-85.5000 ;25.2300
P56=-86.0000 ;25.2040
P57=-86.5000 ;25.2120
P58=-87.0000 ;25.2590
P59=-87.5000 ;25.3310
P60=-88.0000 ;25.4160
P61=-88.4080 ;25.5000
P62=-88.5000 ;25.5330
P63=-89.0000 ;25.7570
P64=-89.5000 ;25.9550
P65=-89.6130 ;26.0000
P66=-90.0000 ;26.2610
P67=-90.3460 ;26.5000
P68=-90.5000 ;26.6270
P69=-90.9500 ;27.0000
P70=-91.0000 ;27.0520
P71=-91.3760 ;27.5000
P72=-91.5000 ;27.6470
P73=-91.7270 ;28.0000
P74=-92.0000 ;28.3930
P75=-92.0520 ;28.5000
P76=-92.3040 ;29.0000
P77=-92.5000 ;29.3540
P78=-92.5550 ;29.5000
P79=-92.7300 ;30.0000
P80=-92.9270 ;30.5000
P81=-93.0000 ;30.7160
P82=-93.0540 ;31.0000
P83=-93.1500 ;31.5000
P84=-93.2120 ;32.0000
P85=-93.2530 ;32.5000
P86=-93.2670 ;33.0000
P87=-93.2440 ;33.5000
P88=-93.1940 ;34.0000
P89=-93.1200 ;34.5000
P90=-93.0300 ;35.0000
P91=-93.0000 ;35.1540
P92=-92.8780 ;35.5000
P93=-92.6920 ;36.0000

P94=-92.5200 ;36.5000
P95=-92.5000 ;36.5610
P96=-92.2520 ;37.0000
P97=-92.0130 ;37.5000
P98=-92.0000 ;37.5300
P99=-91.6830 ;38.0000
P100=-91.5000 ;38.3200
P101=-91.3680 ;38.5000
P102=-91.0130 ;39.0000
P103=-91.0000 ;39.0190
P104=-90.5750 ;39.5000
P105=-90.5000 ;39.5880
P106=-90.1110 ;40.0000
P107=-90.0000 ;40.1170
P108=-89.6120 ;40.5000
P109=-89.5000 ;40.6050
P110=-89.0720 ;41.0000
P111=-89.0000 ;41.0590
P112=-88.5000 ;41.4820
P113=-88.4770 ;41.5000
P114=-88.0000 ;41.8240
P115=-87.7620 ;42.0000
P116=-87.5000 ;42.1550
P117=-87.0000 ;42.4990
P118=-86.9990 ;42.5000
P119=-86.5000 ;42.7410
P120=-86.0550 ;43.0000
P121=-86.0000 ;43.0220
P122=-85.5000 ;43.2200
P123=-85.0000 ;43.4490
P124=-84.8770 ;43.5000
P125=-84.5000 ;43.6040
P126=-84.0000 ;43.7500
P127=-83.5000 ;43.8960
P128=-83.1020 ;44.0000
P129=-83.0000 ;44.0150
P130=-82.5000 ;44.0770
P131=-82.0000 ;44.1270
P132=-81.5000 ;44.1610
P133=-81.0000 ;44.1750
P134=-80.5000 ;44.1680
P135=-80.0000 ;44.1410
P136=-79.5000 ;44.0950
P137=-79.0000 ;44.0350
P138=-78.7450 ;44.0000
P139=-78.5000 ;43.9390
P140=-78.0000 ;43.7910
P141=-77.5000 ;43.6330
P142=-77.0690 ;43.5000
P143=-77.0000 ;43.4670
P144=-76.5000 ;43.1830
P145=-76.1960 ;43.0000
P146=-76.0000 ;42.8440
P147=-75.6040 ;42.5000
P148=-75.5000 ;42.3930
P149=-75.1850 ;42.0000
P150=-75.0000 ;41.7560

P151=-74.8420 ;41.5000
P152=-74.6060 ;41.0000
P153=-74.5000 ;40.7860
[C2]
gain=-40.00
n_point=689
P1=-53.5000 ;56.0340
P2=-53.6880 ;56.5000
P3=-53.9540 ;57.0000
P4=-54.0000 ;57.0450
P5=-54.5000 ;57.4440
P6=-54.5630 ;57.5000
P7=-55.0000 ;57.7840
P8=-55.3650 ;58.0000
P9=-55.5000 ;58.0750
P10=-56.0000 ;58.3390
P11=-56.3080 ;58.5000
P12=-56.5000 ;58.6070
P13=-57.0000 ;58.8530
P14=-57.2720 ;59.0000
P15=-57.5000 ;59.1730
P16=-58.0000 ;59.4220
P17=-58.1410 ;59.5000
P18=-58.5000 ;59.8460
P19=-58.7160 ;60.0000
P20=-59.0000 ;60.1520
P21=-59.5000 ;60.4020
P22=-59.7180 ;60.5000
P23=-60.0000 ;60.6040
P24=-60.5000 ;60.7630
P25=-61.0000 ;60.8930
P26=-61.5000 ;60.9940
P27=-61.5350 ;61.0000
P28=-62.0000 ;61.0750
P29=-62.5000 ;61.1340
P30=-63.0000 ;61.1710
P31=-63.5000 ;61.1930
P32=-64.0000 ;61.1970
P33=-64.5000 ;61.1860
P34=-65.0000 ;61.1600
P35=-65.5000 ;61.1070
P36=-66.0000 ;61.0640
P37=-66.5000 ;61.0340
P38=-66.8930 ;61.0000
P39=-67.0000 ;60.9950
P40=-67.5000 ;60.9670
P41=-68.0000 ;60.9270
P42=-68.5000 ;60.8770
P43=-69.0000 ;60.8140
P44=-69.5000 ;60.7320
P45=-70.0000 ;60.6290
P46=-70.5000 ;60.5010
P47=-70.5030 ;60.5000
P48=-71.0000 ;60.4460
P49=-71.5000 ;60.3890
P50=-72.0000 ;60.3210
P51=-72.5000 ;60.2380

P52=-73.0000 ;60.1370
P53=-73.5000 ;60.0180
P54=-73.5690 ;60.0000
P55=-74.0000 ;59.9210
P56=-74.5000 ;59.8220
P57=-75.0000 ;59.7160
P58=-75.5000 ;59.6030
P59=-75.9290 ;59.5000
P60=-76.0000 ;59.4900
P61=-76.5000 ;59.4110
P62=-77.0000 ;59.3100
P63=-77.5000 ;59.1860
P64=-78.0000 ;59.0370
P65=-78.1170 ;59.0000
P66=-78.5000 ;58.9280
P67=-79.0000 ;58.8250
P68=-79.5000 ;58.7150
P69=-80.0000 ;58.5870
P70=-80.3060 ;58.5000
P71=-80.5000 ;58.4620
P72=-81.0000 ;58.3490
P73=-81.5000 ;58.2050
P74=-82.0000 ;58.0260
P75=-82.0710 ;58.0000
P76=-82.5000 ;57.9030
P77=-83.0000 ;57.7720
P78=-83.5000 ;57.6080
P79=-83.7900 ;57.5000
P80=-84.0000 ;57.4450
P81=-84.5000 ;57.2840
P82=-85.0000 ;57.0680
P83=-85.1430 ;57.0000
P84=-85.5000 ;56.8800
P85=-86.0000 ;56.6750
P86=-86.3520 ;56.5000
P87=-86.5000 ;56.4530
P88=-87.0000 ;56.2610
P89=-87.4900 ;56.0000
P90=-87.5000 ;55.9960
P91=-88.0000 ;55.7740
P92=-88.4380 ;55.5000
P93=-88.5000 ;55.4730
P94=-89.0000 ;55.2370
P95=-89.3920 ;55.0000
P96=-89.5000 ;54.9530
P97=-90.0000 ;54.6860
P98=-90.2760 ;54.5000
P99=-90.5000 ;54.3780
P100=-91.0000 ;54.0200
P101=-91.0270 ;54.0000
P102=-91.5000 ;53.6740
P103=-91.7130 ;53.5000
P104=-92.0000 ;53.3100
P105=-92.3810 ;53.0000
P106=-92.5000 ;52.9150
P107=-92.9830 ;52.5000
P108=-93.0000 ;52.4890

P109=-93.5000 ;52.0960
P110=-93.6070 ;52.0000
P111=-94.0000 ;51.6780
P112=-94.1910 ;51.5000
P113=-94.5000 ;51.2170
P114=-94.7220 ;51.0000
P115=-95.0000 ;50.7470
P116=-95.2530 ;50.5000
P117=-95.5000 ;50.2560
P118=-95.7500 ;50.0000
P119=-96.0000 ;49.7310
P120=-96.2150 ;49.5000
P121=-96.5000 ;49.1730
P122=-96.6550 ;49.0000
P123=-97.0000 ;48.5800
P124=-97.0690 ;48.5000
P125=-97.4740 ;48.0000
P126=-97.5000 ;47.9640
P127=-97.8840 ;47.5000
P128=-98.0000 ;47.3290
P129=-98.2590 ;47.0000
P130=-98.5000 ;46.6230
P131=-98.5930 ;46.5000
P132=-98.9400 ;46.0000
P133=-99.0000 ;45.8930
P134=-99.2860 ;45.5000
P135=-99.5000 ;45.0930
P136=-99.5630 ;45.0000
P137=-99.8810 ;44.5000
P138=-100.0000;44.2280
P139=-100.1430;44.0000
P140=-100.4130;43.5000
P141=-100.5000;43.2600
P142=-100.6560;43.0000
P143=-100.9000;42.5000
P144=-101.0000;42.1600
P145=-101.0860;42.0000
P146=-101.3230;41.5000
P147=-101.4860;41.0000
P148=-101.5000;40.9510
P149=-101.7190;40.5000
P150=-101.8940;40.0000
P151=-102.0000;39.5050
P152=-102.0020;39.5000
P153=-102.1790;39.0000
P154=-102.3150;38.5000
P155=-102.4170;38.0000
P156=-102.4850;37.5000
P157=-102.5000;37.3250
P158=-102.5740;37.0000
P159=-102.6520;36.5000
P160=-102.7090;36.0000
P161=-102.7460;35.5000
P162=-102.7580;35.0000
P163=-102.7420;34.5000
P164=-102.7040;34.0000
P165=-102.6530;33.5000

P166=-102.5840;33.0000
P167=-102.5000;32.5830
P168=-102.4930;32.5000
P169=-102.4350;32.0000
P170=-102.3620;31.5000
P171=-102.2760;31.0000
P172=-102.1680;30.5000
P173=-102.0270;30.0000
P174=-102.0000;29.9110
P175=-101.9560;29.5000
P176=-101.8870;29.0000
P177=-101.7830;28.5000
P178=-101.6330;28.0000
P179=-101.5000;27.6420
P180=-101.4750;27.5000
P181=-101.3590;27.0000
P182=-101.1760;26.5000
P183=-101.0000;26.1530
P184=-100.9610;26.0000
P185=-100.7780;25.5000
P186=-100.5000;25.0540
P187=-100.4770;25.0000
P188=-100.2090;24.5000
P189=-100.0000;24.2320
P190=-99.8730 ;24.0000
P191=-99.5000 ;23.5460
P192=-99.4720 ;23.5000
P193=-99.0860 ;23.0000
P194=-99.0000 ;22.9010
P195=-98.6920 ;22.5000
P196=-98.5000 ;22.2910
P197=-98.2790 ;22.0000
P198=-98.0000 ;21.6780
P199=-97.8780 ;21.5000
P200=-97.5000 ;21.0910
P201=-97.4110 ;21.0000
P202=-97.0000 ;20.5720
P203=-96.9360 ;20.5000
P204=-96.5000 ;20.0670
P205=-96.4210 ;20.0000
P206=-96.0000 ;19.6260
P207=-95.7840 ;19.5000
P208=-95.5000 ;19.2720
P209=-95.0130 ;19.0000
P210=-95.0000 ;18.9910
P211=-94.5000 ;18.6450
P212=-94.0750 ;18.5000
P213=-94.0000 ;18.4550
P214=-93.5000 ;18.1710
P215=-93.0000 ;18.0090
P216=-92.9640 ;18.0000
P217=-92.5000 ;17.7360
P218=-92.0000 ;17.5510
P219=-91.8260 ;17.5000
P220=-91.5000 ;17.3260
P221=-91.0000 ;17.1270
P222=-90.5000 ;17.0220

P223=-90.3580 ;17.0000
P224=-90.0000 ;16.8650
P225=-89.5000 ;16.7450
P226=-89.0000 ;16.6770
P227=-88.5000 ;16.6460
P228=-88.0000 ;16.6420
P229=-87.5000 ;16.6620
P230=-87.0000 ;16.7070
P231=-86.5000 ;16.7730
P232=-86.0000 ;16.8690
P233=-85.5000 ;16.9980
P234=-85.4920 ;17.0000
P235=-85.0000 ;17.0630
P236=-84.5000 ;17.1440
P237=-84.0000 ;17.2550
P238=-83.5000 ;17.4060
P239=-83.2280 ;17.5000
P240=-83.0000 ;17.5500
P241=-82.5000 ;17.6390
P242=-82.0000 ;17.7640
P243=-81.5000 ;17.9510
P244=-81.3870 ;18.0000
P245=-81.0000 ;18.1250
P246=-80.5000 ;18.2970
P247=-80.0880 ;18.5000
P248=-80.0000 ;18.5680
P249=-79.5000 ;18.7660
P250=-79.0000 ;18.9970
P251=-78.9950 ;19.0000
P252=-78.5000 ;19.2780
P253=-78.0530 ;19.5000
P254=-78.0000 ;19.6360
P255=-77.5000 ;19.8750
P256=-77.2550 ;20.0000
P257=-77.5000 ;20.1750
P258=-78.0000 ;20.0610
P259=-78.1380 ;20.0000
P260=-78.5000 ;19.7740
P261=-79.0000 ;19.6580
P262=-79.4230 ;19.5000
P263=-79.5000 ;19.4380
P264=-80.0000 ;19.2690
P265=-80.5000 ;19.1630
P266=-81.0000 ;19.0110
P267=-81.0330 ;19.0000
P268=-81.5000 ;18.8850
P269=-82.0000 ;18.7910
P270=-82.5000 ;18.6670
P271=-83.0000 ;18.5180
P272=-83.0580 ;18.5000
P273=-83.5000 ;18.4120
P274=-84.0000 ;18.3440
P275=-84.5000 ;18.2640
P276=-85.0000 ;18.1520
P277=-85.5000 ;18.0220
P278=-85.5940 ;18.0000
P279=-86.0000 ;17.9620

P280=-86.5000 ;17.9230
P281=-87.0000 ;17.8880
P282=-87.5000 ;17.8650
P283=-88.0000 ;17.8640
P284=-88.5000 ;17.8900
P285=-89.0000 ;17.9340
P286=-89.5000 ;17.9800
P287=-89.6410 ;18.0000
P288=-90.0000 ;18.1220
P289=-90.5000 ;18.2980
P290=-91.0000 ;18.4460
P291=-91.2050 ;18.5000
P292=-91.5000 ;18.6420
P293=-92.0000 ;18.8630
P294=-92.5000 ;18.9910
P295=-92.5230 ;19.0000
P296=-93.0000 ;19.2660
P297=-93.5000 ;19.4570
P298=-93.6340 ;19.5000
P299=-94.0000 ;19.7290
P300=-94.5000 ;19.9860
P301=-94.5250 ;20.0000
P302=-95.0000 ;20.3660
P303=-95.2350 ;20.5000
P304=-95.5000 ;20.7250
P305=-95.8080 ;21.0000
P306=-96.0000 ;21.1860
P307=-96.3050 ;21.5000
P308=-96.5000 ;21.7060
P309=-96.7710 ;22.0000
P310=-97.0000 ;22.2620
P311=-97.1640 ;22.5000
P312=-97.5000 ;22.8820
P313=-97.5850 ;23.0000
P314=-98.0000 ;23.4950
P315=-98.0040 ;23.5000
P316=-98.3680 ;24.0000
P317=-98.5000 ;24.1640
P318=-98.6980 ;24.5000
P319=-99.0000 ;24.8930
P320=-99.0600 ;25.0000
P321=-99.3420 ;25.5000
P322=-99.5000 ;25.7460
P323=-99.6090 ;26.0000
P324=-99.8640 ;26.5000
P325=-100.0000;26.7640
P326=-100.0580;27.0000
P327=-100.1860;27.5000
P328=-100.3560;28.0000
P329=-100.5000;28.4300
P330=-100.5130;28.5000
P331=-100.5920;29.0000
P332=-100.6620;29.5000
P333=-100.7460;30.0000
P334=-100.8370;30.5000
P335=-100.9220;31.0000
P336=-101.0000;31.4910

P337=-101.0010;31.5000
P338=-101.0260;32.0000
P339=-101.0550;32.5000
P340=-101.0830;33.0000
P341=-101.1050;33.5000
P342=-101.1220;34.0000
P343=-101.1350;34.5000
P344=-101.1350;35.0000
P345=-101.1200;35.5000
P346=-101.0920;36.0000
P347=-101.0570;36.5000
P348=-101.0210;37.0000
P349=-101.0000;37.2800
P350=-100.9550;37.5000
P351=-100.8300;38.0000
P352=-100.6960;38.5000
P353=-100.5850;39.0000
P354=-100.5000;39.4400
P355=-100.4790;39.5000
P356=-100.2780;40.0000
P357=-100.1010;40.5000
P358=-100.0000;40.8450
P359=-99.9270 ;41.0000
P360=-99.6800 ;41.5000
P361=-99.5070 ;42.0000
P362=-99.5000 ;42.0180
P363=-99.2170 ;42.5000
P364=-99.0140 ;43.0000
P365=-99.0000 ;43.0290
P366=-98.6900 ;43.5000
P367=-98.5000 ;43.9440
P368=-98.4620 ;44.0000
P369=-98.1150 ;44.5000
P370=-98.0000 ;44.7250
P371=-97.7990 ;45.0000
P372=-97.5000 ;45.4750
P373=-97.4810 ;45.5000
P374=-97.0860 ;46.0000
P375=-97.0000 ;46.1250
P376=-96.6870 ;46.5000
P377=-96.5000 ;46.7490
P378=-96.2820 ;47.0000
P379=-96.0000 ;47.3440
P380=-95.8570 ;47.5000
P381=-95.5000 ;47.9020
P382=-95.4060 ;48.0000
P383=-95.0000 ;48.4260
P384=-94.9250 ;48.5000
P385=-94.5000 ;48.9210
P386=-94.4180 ;49.0000
P387=-94.0000 ;49.3920
P388=-93.8840 ;49.5000
P389=-93.5000 ;49.8210
P390=-93.3000 ;50.0000
P391=-93.0000 ;50.2410
P392=-92.6940 ;50.5000
P393=-92.5000 ;50.6420

P394=-92.0440 ;51.0000
P395=-92.0000 ;51.0270
P396=-91.5000 ;51.3530
P397=-91.2910 ;51.5000
P398=-91.0000 ;51.6720
P399=-90.5320 ;52.0000
P400=-90.5000 ;52.0170
P401=-90.0000 ;52.2990
P402=-89.6920 ;52.5000
P403=-89.5000 ;52.5990
P404=-89.0000 ;52.9050
P405=-88.8450 ;53.0000
P406=-88.5000 ;53.1640
P407=-88.0000 ;53.4360
P408=-87.8790 ;53.5000
P409=-87.5000 ;53.6400
P410=-87.0000 ;53.8650
P411=-86.7180 ;54.0000
P412=-86.5000 ;54.0710
P413=-86.0000 ;54.2660
P414=-85.5060 ;54.5000
P415=-85.5000 ;54.5020
P416=-85.0000 ;54.6670
P417=-84.5000 ;54.8530
P418=-84.1260 ;55.0000
P419=-84.0000 ;55.0300
P420=-83.5000 ;55.1580
P421=-83.0000 ;55.3120
P422=-82.5000 ;55.4890
P423=-82.4680 ;55.5000
P424=-82.0000 ;55.6140
P425=-81.5000 ;55.7690
P426=-81.0000 ;55.9530
P427=-80.8750 ;56.0000
P428=-80.5000 ;56.0860
P429=-80.0000 ;56.2050
P430=-79.5000 ;56.3370
P431=-79.0000 ;56.4830
P432=-78.9420 ;56.5000
P433=-78.5000 ;56.5810
P434=-78.0000 ;56.6970
P435=-77.5000 ;56.8350
P436=-77.0000 ;56.9930
P437=-76.9780 ;57.0000
P438=-76.5000 ;57.0910
P439=-76.0000 ;57.1910
P440=-75.5000 ;57.2860
P441=-75.0000 ;57.3860
P442=-74.5000 ;57.4900
P443=-74.4510 ;57.5000
P444=-74.0000 ;57.5540
P445=-73.5000 ;57.6300
P446=-73.0000 ;57.7190
P447=-72.5000 ;57.8130
P448=-72.0000 ;57.8760
P449=-71.5000 ;57.9300
P450=-71.0000 ;57.9710

P451=-70.5000 ;57.9950
P452=-70.2730 ;58.0000
P453=-70.0000 ;58.0030
P454=-69.5000 ;58.0030
P455=-69.3820 ;58.0000
P456=-69.0000 ;57.9830
P457=-68.5000 ;57.9470
P458=-68.0000 ;57.9000
P459=-67.5000 ;57.8330
P460=-67.0000 ;57.7470
P461=-66.5000 ;57.6520
P462=-66.0000 ;57.5280
P463=-65.9010 ;57.5000
P464=-65.5000 ;57.3640
P465=-65.0000 ;57.1980
P466=-64.5000 ;57.0160
P467=-64.4560 ;57.0000
P468=-64.0000 ;56.8110
P469=-63.5000 ;56.6110
P470=-63.2390 ;56.5000
P471=-63.0000 ;56.3840
P472=-62.5000 ;56.1640
P473=-62.1340 ;56.0000
P474=-62.0000 ;55.9280
P475=-61.5000 ;55.6720
P476=-61.1250 ;55.5000
P477=-61.0000 ;55.4280
P478=-60.5000 ;55.0970
P479=-60.3470 ;55.0000
P480=-60.0000 ;54.7390
P481=-59.7090 ;54.5000
P482=-59.5000 ;54.2570
P483=-59.2890 ;54.0000
P484=-59.0000 ;53.5480
P485=-58.9750 ;53.5000
P486=-58.7730 ;53.0000
P487=-58.6680 ;52.5000
P488=-58.6410 ;52.0000
P489=-58.6690 ;51.5000
P490=-58.7240 ;51.0000
P491=-58.7980 ;50.5000
P492=-58.8940 ;50.0000
P493=-58.9900 ;49.5000
P494=-59.0000 ;49.4490
P495=-59.1090 ;49.0000
P496=-59.2140 ;48.5000
P497=-59.2940 ;48.0000
P498=-59.3440 ;47.5000
P499=-59.3880 ;47.0000
P500=-59.4230 ;46.5000
P501=-59.4810 ;46.0000
P502=-59.5000 ;45.8230
P503=-59.5550 ;45.5000
P504=-59.6400 ;45.0000
P505=-59.7250 ;44.5000
P506=-59.8070 ;44.0000
P507=-59.9110 ;43.5000

P508=-60.0000 ;43.0630
P509=-60.0170 ;43.0000
P510=-60.1960 ;42.5000
P511=-60.3440 ;42.0000
P512=-60.5000 ;41.5530
P513=-60.5210 ;41.5000
P514=-60.6910 ;41.0000
P515=-60.8960 ;40.5000
P516=-61.0000 ;40.2720
P517=-61.1220 ;40.0000
P518=-61.2920 ;39.5000
P519=-61.5000 ;39.0750
P520=-61.5330 ;39.0000
P521=-61.7380 ;38.5000
P522=-62.0000 ;38.0660
P523=-62.0340 ;38.0000
P524=-62.2440 ;37.5000
P525=-62.5000 ;37.0240
P526=-62.5120 ;37.0000
P527=-62.7600 ;36.5000
P528=-63.0000 ;36.1180
P529=-63.0680 ;36.0000
P530=-63.3100 ;35.5000
P531=-63.5000 ;35.2180
P532=-63.6200 ;35.0000
P533=-63.9120 ;34.5000
P534=-64.0000 ;34.3640
P535=-64.2170 ;34.0000
P536=-64.5000 ;33.5540
P537=-64.5350 ;33.5000
P538=-64.8660 ;33.0000
P539=-65.0000 ;32.8050
P540=-65.2000 ;32.5000
P541=-65.5000 ;32.0710
P542=-65.5530 ;32.0000
P543=-65.8810 ;31.5000
P544=-66.0000 ;31.3610
P545=-66.2870 ;31.0000
P546=-66.5000 ;30.6940
P547=-66.6460 ;30.5000
P548=-67.0000 ;30.0430
P549=-67.0360 ;30.0000
P550=-67.4110 ;29.5000
P551=-67.5000 ;29.3810
P552=-67.8200 ;29.0000
P553=-68.0000 ;28.8090
P554=-68.2670 ;28.5000
P555=-68.5000 ;28.2080
P556=-68.6780 ;28.0000
P557=-69.0000 ;27.6270
P558=-69.1140 ;27.5000
P559=-69.5000 ;27.0740
P560=-69.5690 ;27.0000
P561=-70.0000 ;26.5300
P562=-70.0290 ;26.5000
P563=-70.4850 ;26.0000
P564=-70.5000 ;25.9820

P565=-70.9660 ;25.5000
P566=-71.0000 ;25.4650
P567=-71.4800 ;25.0000
P568=-71.5000 ;24.9800
P569=-72.0000 ;24.5080
P570=-72.0090 ;24.5000
P571=-72.5000 ;24.0420
P572=-72.5460 ;24.0000
P573=-73.0000 ;23.5910
P574=-73.1010 ;23.5000
P575=-73.5000 ;23.1160
P576=-73.6390 ;23.0000
P577=-74.0000 ;22.6780
P578=-74.2260 ;22.5000
P579=-74.0000 ;22.1860
P580=-73.5000 ;22.4630
P581=-73.4550 ;22.5000
P582=-73.0000 ;22.8540
P583=-72.8210 ;23.0000
P584=-72.5000 ;23.2540
P585=-72.2140 ;23.5000
P586=-72.0000 ;23.7000
P587=-71.6510 ;24.0000
P588=-71.5000 ;24.1360
P589=-71.0930 ;24.5000
P590=-71.0000 ;24.5920
P591=-70.5460 ;25.0000
P592=-70.5000 ;25.0440
P593=-70.0040 ;25.5000
P594=-70.0000 ;25.5030
P595=-69.5000 ;25.9930
P596=-69.4930 ;26.0000
P597=-69.0000 ;26.4970
P598=-68.9970 ;26.5000
P599=-68.5310 ;27.0000
P600=-68.5000 ;27.0340
P601=-68.0470 ;27.5000
P602=-68.0000 ;27.5420
P603=-67.5680 ;28.0000
P604=-67.5000 ;28.0720
P605=-67.1180 ;28.5000
P606=-67.0000 ;28.6360
P607=-66.6550 ;29.0000
P608=-66.5000 ;29.1670
P609=-66.1960 ;29.5000
P610=-66.0000 ;29.7490
P611=-65.7810 ;30.0000
P612=-65.5000 ;30.3450
P613=-65.3610 ;30.5000
P614=-65.0000 ;30.9970
P615=-64.9970 ;31.0000
P616=-64.5840 ;31.5000
P617=-64.5000 ;31.6290
P618=-64.2180 ;32.0000
P619=-64.0000 ;32.3310
P620=-63.8720 ;32.5000
P621=-63.5650 ;33.0000

P622=-63.5000 ;33.1010
P623=-63.2460 ;33.5000
P624=-63.0000 ;33.9360
P625=-62.9560 ;34.0000
P626=-62.7050 ;34.5000
P627=-62.5000 ;34.8980
P628=-62.4440 ;35.0000
P629=-62.2060 ;35.5000
P630=-62.0000 ;35.9420
P631=-61.9710 ;36.0000
P632=-61.7260 ;36.5000
P633=-61.5000 ;36.9670
P634=-61.4820 ;37.0000
P635=-61.2880 ;37.5000
P636=-61.0350 ;38.0000
P637=-61.0000 ;38.0490
P638=-60.7570 ;38.5000
P639=-60.5000 ;38.9700
P640=-60.4830 ;39.0000
P641=-60.2530 ;39.5000
P642=-60.0000 ;39.9350
P643=-59.9650 ;40.0000
P644=-59.6890 ;40.5000
P645=-59.5000 ;40.8160
P646=-59.3910 ;41.0000
P647=-59.1040 ;41.5000
P648=-59.0000 ;41.6730
P649=-58.7910 ;42.0000
P650=-58.5220 ;42.5000
P651=-58.5000 ;42.5390
P652=-58.2200 ;43.0000
P653=-58.0000 ;43.4340
P654=-57.9590 ;43.5000
P655=-57.6650 ;44.0000
P656=-57.5000 ;44.3500
P657=-57.4090 ;44.5000
P658=-57.1520 ;45.0000
P659=-57.0000 ;45.4040
P660=-56.9510 ;45.5000
P661=-56.7290 ;46.0000
P662=-56.5470 ;46.5000
P663=-56.5000 ;46.6450
P664=-56.3440 ;47.0000
P665=-56.1560 ;47.5000
P666=-56.0040 ;48.0000
P667=-56.0000 ;48.0150
P668=-55.8230 ;48.5000
P669=-55.6600 ;49.0000
P670=-55.5080 ;49.5000
P671=-55.5000 ;49.5250
P672=-55.3120 ;50.0000
P673=-55.1300 ;50.5000
P674=-55.0000 ;50.8990
P675=-54.9560 ;51.0000
P676=-54.7470 ;51.5000
P677=-54.5330 ;52.0000
P678=-54.5000 ;52.0780

P679=-54.2510 ;52.5000
P680=-54.0000 ;53.0000
P681=-54.0000 ;53.0010
P682=-53.7890 ;53.5000
P683=-53.6540 ;54.0000
P684=-53.5300 ;54.5000
P685=-53.5000 ;54.6640
P686=-53.4140 ;55.0000
P687=-53.3900 ;55.5000
P688=-53.4850 ;56.0000
P689=-53.5000 ;56.0340

[C3]

gain=-40.00

n_point=469

P1=-66.0000 ;45.9980
P2=-66.0010 ;46.0000
P3=-66.1300 ;46.5000
P4=-66.3550 ;47.0000
P5=-66.5000 ;47.2160
P6=-66.6940 ;47.5000
P7=-67.0000 ;47.9200
P8=-67.0440 ;48.0000
P9=-67.3550 ;48.5000
P10=-67.5000 ;48.6800
P11=-67.7850 ;49.0000
P12=-68.0000 ;49.2710
P13=-68.1350 ;49.5000
P14=-68.5000 ;49.9080
P15=-68.6140 ;50.0000
P16=-69.0000 ;50.3330
P17=-69.2020 ;50.5000
P18=-69.5000 ;50.7340
P19=-69.9970 ;51.0000
P20=-70.0000 ;51.0020
P21=-70.5000 ;51.2790
P22=-71.0000 ;51.4350
P23=-71.2940 ;51.5000
P24=-71.5000 ;51.5700
P25=-72.0000 ;51.7170
P26=-72.5000 ;51.7560
P27=-73.0000 ;51.7980
P28=-73.5000 ;51.8480
P29=-74.0000 ;51.8730
P30=-74.5000 ;51.8990
P31=-75.0000 ;51.9140
P32=-75.5000 ;51.9200
P33=-76.0000 ;51.9200
P34=-76.5000 ;51.9140
P35=-77.0000 ;51.9000
P36=-77.5000 ;51.8770
P37=-78.0000 ;51.8410
P38=-78.5000 ;51.7890
P39=-79.0000 ;51.7190
P40=-79.5000 ;51.6300
P41=-80.0000 ;51.5180
P42=-80.0760 ;51.5000
P43=-80.5000 ;51.4470

P44=-81.0000 ;51.3730
P45=-81.5000 ;51.2820
P46=-82.0000 ;51.1730
P47=-82.5000 ;51.0340
P48=-82.6090 ;51.0000
P49=-83.0000 ;50.9580
P50=-83.5000 ;50.8530
P51=-84.0000 ;50.6930
P52=-84.4480 ;50.5000
P53=-84.5000 ;50.4870
P54=-85.0000 ;50.3920
P55=-85.5000 ;50.1700
P56=-85.8130 ;50.0000
P57=-86.0000 ;49.9210
P58=-86.5000 ;49.7470
P59=-86.8900 ;49.5000
P60=-87.0000 ;49.4580
P61=-87.5000 ;49.2170
P62=-87.8390 ;49.0000
P63=-88.0000 ;48.9520
P64=-88.5000 ;48.6760
P65=-88.7520 ;48.5000
P66=-89.0000 ;48.3960
P67=-89.5000 ;48.0100
P68=-89.5130 ;48.0000
P69=-90.0000 ;47.7210
P70=-90.2710 ;47.5000
P71=-90.5000 ;47.3680
P72=-90.9280 ;47.0000
P73=-91.0000 ;46.9590
P74=-91.5000 ;46.5140
P75=-91.5160 ;46.5000
P76=-92.0000 ;46.1110
P77=-92.1200 ;46.0000
P78=-92.5000 ;45.6610
P79=-92.6650 ;45.5000
P80=-93.0000 ;45.1660
P81=-93.1620 ;45.0000
P82=-93.5000 ;44.6290
P83=-93.6200 ;44.5000
P84=-94.0000 ;44.0490
P85=-94.0440 ;44.0000
P86=-94.4770 ;43.5000
P87=-94.5000 ;43.4640
P88=-94.9060 ;43.0000
P89=-95.0000 ;42.8440
P90=-95.2820 ;42.5000
P91=-95.5000 ;42.1170
P92=-95.5890 ;42.0000
P93=-95.9350 ;41.5000
P94=-96.0000 ;41.3560
P95=-96.2590 ;41.0000
P96=-96.4930 ;40.5000
P97=-96.5000 ;40.4860
P98=-96.8460 ;40.0000
P99=-97.0000 ;39.5040
P100=-97.0030 ;39.5000

P101=-97.3150 ;39.0000
P102=-97.4480 ;38.5000
P103=-97.5000 ;38.3470
P104=-97.6820 ;38.0000
P105=-97.8630 ;37.5000
P106=-97.9380 ;37.0000
P107=-98.0000 ;36.7640
P108=-98.1070 ;36.5000
P109=-98.2740 ;36.0000
P110=-98.3580 ;35.5000
P111=-98.3810 ;35.0000
P112=-98.4020 ;34.5000
P113=-98.4240 ;34.0000
P114=-98.4360 ;33.5000
P115=-98.4390 ;33.0000
P116=-98.4350 ;32.5000
P117=-98.4010 ;32.0000
P118=-98.3230 ;31.5000
P119=-98.2090 ;31.0000
P120=-98.0460 ;30.5000
P121=-98.0000 ;30.3760
P122=-97.9070 ;30.0000
P123=-97.8470 ;29.5000
P124=-97.7320 ;29.0000
P125=-97.5080 ;28.5000
P126=-97.5000 ;28.4830
P127=-97.3580 ;28.0000
P128=-97.2190 ;27.5000
P129=-97.0000 ;27.0900
P130=-96.9660 ;27.0000
P131=-96.7850 ;26.5000
P132=-96.5000 ;26.0820
P133=-96.4450 ;26.0000
P134=-96.2150 ;25.5000
P135=-96.0000 ;25.2280
P136=-95.8380 ;25.0000
P137=-95.5000 ;24.6110
P138=-95.4210 ;24.5000
P139=-95.0000 ;24.0850
P140=-94.9010 ;24.0000
P141=-94.5000 ;23.6170
P142=-94.3580 ;23.5000
P143=-94.0000 ;23.1890
P144=-93.7280 ;23.0000
P145=-93.5000 ;22.8020
P146=-93.1120 ;22.5000
P147=-93.0000 ;22.4080
P148=-92.5000 ;22.0830
P149=-92.3850 ;22.0000
P150=-92.0000 ;21.6990
P151=-91.5790 ;21.5000
P152=-91.5000 ;21.4440
P153=-91.0000 ;21.1720
P154=-90.5000 ;21.0050
P155=-90.4850 ;21.0000
P156=-90.0000 ;20.7630
P157=-89.5000 ;20.6520

P158=-89.0000 ;20.6420
P159=-88.5000 ;20.6130
P160=-88.0000 ;20.5770
P161=-87.5000 ;20.5580
P162=-87.0000 ;20.5600
P163=-86.5000 ;20.5800
P164=-86.0000 ;20.6160
P165=-85.5000 ;20.6590
P166=-85.0000 ;20.7060
P167=-84.5000 ;20.7580
P168=-84.0000 ;20.8620
P169=-83.6150 ;21.0000
P170=-83.5000 ;21.0550
P171=-83.0000 ;21.1510
P172=-82.5000 ;21.2730
P173=-82.0370 ;21.5000
P174=-82.0000 ;21.5290
P175=-81.5000 ;21.7140
P176=-81.0000 ;21.9330
P177=-80.8890 ;22.0000
P178=-80.5000 ;22.2280
P179=-80.0000 ;22.4240
P180=-79.8840 ;22.5000
P181=-79.5000 ;22.7440
P182=-79.0760 ;23.0000
P183=-79.0000 ;23.1960
P184=-78.5000 ;23.3900
P185=-78.3350 ;23.5000
P186=-78.5000 ;23.6780
P187=-79.0000 ;23.5680
P188=-79.1120 ;23.5000
P189=-79.5000 ;23.2540
P190=-80.0000 ;23.0530
P191=-80.0890 ;23.0000
P192=-80.5000 ;22.7450
P193=-81.0000 ;22.5930
P194=-81.1940 ;22.5000
P195=-81.5000 ;22.3300
P196=-82.0000 ;22.2450
P197=-82.5000 ;22.0500
P198=-82.6220 ;22.0000
P199=-83.0000 ;21.8640
P200=-83.5000 ;21.7620
P201=-84.0000 ;21.6650
P202=-84.5000 ;21.5520
P203=-84.7020 ;21.5000
P204=-85.0000 ;21.4050
P205=-85.5000 ;21.3430
P206=-86.0000 ;21.3200
P207=-86.5000 ;21.3090
P208=-87.0000 ;21.3020
P209=-87.5000 ;21.2970
P210=-88.0000 ;21.2940
P211=-88.5000 ;21.3050
P212=-89.0000 ;21.3620
P213=-89.5000 ;21.4920
P214=-89.5140 ;21.5000

P215=-90.0000 ;21.7220
P216=-90.5000 ;21.9010
P217=-90.7730 ;22.0000
P218=-91.0000 ;22.1400
P219=-91.5000 ;22.3880
P220=-91.6700 ;22.5000
P221=-92.0000 ;22.7450
P222=-92.4620 ;23.0000
P223=-92.5000 ;23.0310
P224=-93.0000 ;23.4380
P225=-93.0690 ;23.5000
P226=-93.5000 ;23.8610
P227=-93.6790 ;24.0000
P228=-94.0000 ;24.3010
P229=-94.2420 ;24.5000
P230=-94.5000 ;24.7560
P231=-94.7280 ;25.0000
P232=-95.0000 ;25.3060
P233=-95.1520 ;25.5000
P234=-95.5000 ;25.9320
P235=-95.5580 ;26.0000
P236=-95.7880 ;26.5000
P237=-96.0000 ;26.8370
P238=-96.0760 ;27.0000
P239=-96.2730 ;27.5000
P240=-96.5000 ;27.9960
P241=-96.5030 ;28.0000
P242=-96.6200 ;28.5000
P243=-96.7730 ;29.0000
P244=-96.9640 ;29.5000
P245=-97.0000 ;29.6170
P246=-97.0990 ;30.0000
P247=-97.1270 ;30.5000
P248=-97.1790 ;31.0000
P249=-97.2830 ;31.5000
P250=-97.3750 ;32.0000
P251=-97.4540 ;32.5000
P252=-97.5000 ;32.9260
P253=-97.5050 ;33.0000
P254=-97.5090 ;33.5000
P255=-97.5000 ;33.6370
P256=-97.4710 ;34.0000
P257=-97.4060 ;34.5000
P258=-97.3140 ;35.0000
P259=-97.2130 ;35.5000
P260=-97.1690 ;36.0000
P261=-97.1140 ;36.5000
P262=-97.0000 ;36.8580
P263=-96.9410 ;37.0000
P264=-96.7430 ;37.5000
P265=-96.6440 ;38.0000
P266=-96.5000 ;38.3550
P267=-96.4200 ;38.5000
P268=-96.1850 ;39.0000
P269=-96.0020 ;39.5000
P270=-96.0000 ;39.5040
P271=-95.6760 ;40.0000

P272=-95.5000 ;40.4010
P273=-95.4340 ;40.5000
P274=-95.0910 ;41.0000
P275=-95.0000 ;41.1730
P276=-94.7480 ;41.5000
P277=-94.5000 ;41.9100
P278=-94.4280 ;42.0000
P279=-94.0540 ;42.5000
P280=-94.0000 ;42.5570
P281=-93.6060 ;43.0000
P282=-93.5000 ;43.1100
P283=-93.1320 ;43.5000
P284=-93.0000 ;43.6580
P285=-92.6670 ;44.0000
P286=-92.5000 ;44.1790
P287=-92.1750 ;44.5000
P288=-92.0000 ;44.6660
P289=-91.6500 ;45.0000
P290=-91.5000 ;45.1200
P291=-91.0860 ;45.5000
P292=-91.0000 ;45.5660
P293=-90.5070 ;46.0000
P294=-90.5000 ;46.0090
P295=-90.0000 ;46.3270
P296=-89.7780 ;46.5000
P297=-89.5000 ;46.6480
P298=-89.0510 ;47.0000
P299=-89.0000 ;47.0420
P300=-88.5000 ;47.3100
P301=-88.2240 ;47.5000
P302=-88.0000 ;47.6140
P303=-87.5000 ;47.8730
P304=-87.2960 ;48.0000
P305=-87.0000 ;48.1420
P306=-86.5000 ;48.3950
P307=-86.3120 ;48.5000
P308=-86.0000 ;48.5980
P309=-85.5000 ;48.8030
P310=-85.0740 ;49.0000
P311=-85.0000 ;49.0110
P312=-84.5000 ;49.1270
P313=-84.0000 ;49.2910
P314=-83.5000 ;49.4750
P315=-83.4250 ;49.5000
P316=-83.0000 ;49.5520
P317=-82.5000 ;49.6180
P318=-82.0000 ;49.7590
P319=-81.5000 ;49.8950
P320=-81.1020 ;50.0000
P321=-81.0000 ;50.0250
P322=-80.5000 ;50.1140
P323=-80.0000 ;50.1870
P324=-79.5000 ;50.2560
P325=-79.0000 ;50.3300
P326=-78.5000 ;50.3900
P327=-78.0000 ;50.4370
P328=-77.5000 ;50.4710

P329=-77.0000 ;50.4930
P330=-76.6350 ;50.5000
P331=-76.5000 ;50.5010
P332=-76.2370 ;50.5000
P333=-76.0000 ;50.4980
P334=-75.5000 ;50.4750
P335=-75.0000 ;50.4320
P336=-74.5000 ;50.3670
P337=-74.0000 ;50.2770
P338=-73.5000 ;50.1760
P339=-73.0000 ;50.0910
P340=-72.5350 ;50.0000
P341=-72.5000 ;49.9860
P342=-72.0000 ;49.7130
P343=-71.5000 ;49.5560
P344=-71.3970 ;49.5000
P345=-71.0000 ;49.2220
P346=-70.7040 ;49.0000
P347=-70.5000 ;48.8210
P348=-70.0970 ;48.5000
P349=-70.0000 ;48.4070
P350=-69.6380 ;48.0000
P351=-69.5000 ;47.8420
P352=-69.1890 ;47.5000
P353=-69.0000 ;47.2850
P354=-68.7780 ;47.0000
P355=-68.5000 ;46.6310
P356=-68.4260 ;46.5000
P357=-68.1360 ;46.0000
P358=-68.0000 ;45.7910
P359=-67.8630 ;45.5000
P360=-67.6990 ;45.0000
P361=-67.5360 ;44.5000
P362=-67.5000 ;44.3920
P363=-67.4210 ;44.0000
P364=-67.4150 ;43.5000
P365=-67.3880 ;43.0000
P366=-67.4000 ;42.5000
P367=-67.4360 ;42.0000
P368=-67.5000 ;41.5390
P369=-67.5100 ;41.5000
P370=-67.6040 ;41.0000
P371=-67.6840 ;40.5000
P372=-67.8200 ;40.0000
P373=-67.8550 ;39.5000
P374=-67.9500 ;39.0000
P375=-68.0000 ;38.8120
P376=-68.0860 ;38.5000
P377=-68.1650 ;38.0000
P378=-68.2440 ;37.5000
P379=-68.3020 ;37.0000
P380=-68.5000 ;36.5670
P381=-68.5220 ;36.5000
P382=-68.5690 ;36.0000
P383=-68.7620 ;35.5000
P384=-68.7370 ;35.0000
P385=-69.0000 ;34.9080

P386=-69.1620 ;34.5000
P387=-69.1970 ;34.0000
P388=-69.5000 ;33.8160
P389=-69.6530 ;33.5000
P390=-69.7770 ;33.0000
P391=-70.0000 ;32.8930
P392=-70.2350 ;32.5000
P393=-70.5000 ;32.0390
P394=-70.5250 ;32.0000
P395=-70.8280 ;31.5000
P396=-71.0000 ;31.3210
P397=-71.2140 ;31.0000
P398=-71.5000 ;30.6390
P399=-71.6110 ;30.5000
P400=-71.9990 ;30.0000
P401=-72.0000 ;29.9990
P402=-72.3490 ;29.5000
P403=-72.5000 ;29.2990
P404=-72.7380 ;29.0000
P405=-73.0000 ;28.7220
P406=-73.1970 ;28.5000
P407=-73.5000 ;28.1800
P408=-73.6660 ;28.0000
P409=-74.0000 ;27.6550
P410=-74.1450 ;27.5000
P411=-74.5000 ;27.0990
P412=-74.5980 ;27.0000
P413=-74.5000 ;26.6400
P414=-74.0000 ;26.9940
P415=-73.9930 ;27.0000
P416=-73.5000 ;27.4830
P417=-73.4840 ;27.5000
P418=-73.0360 ;28.0000
P419=-73.0000 ;28.0310
P420=-72.5920 ;28.5000
P421=-72.5000 ;28.5820
P422=-72.1400 ;29.0000
P423=-72.0000 ;29.1010
P424=-71.6630 ;29.5000
P425=-71.5000 ;29.6970
P426=-71.2550 ;30.0000
P427=-71.0000 ;30.3420
P428=-70.8680 ;30.5000
P429=-70.5250 ;31.0000
P430=-70.5000 ;31.0230
P431=-70.2240 ;31.5000
P432=-70.0000 ;31.8180
P433=-69.8660 ;32.0000
P434=-69.6210 ;32.5000
P435=-69.5000 ;32.7430
P436=-69.3760 ;33.0000
P437=-69.1210 ;33.5000
P438=-69.0000 ;33.7270
P439=-68.9110 ;34.0000
P440=-68.6840 ;34.5000
P441=-68.5000 ;34.8700
P442=-68.4550 ;35.0000

P443=-68.2230 ;35.5000
P444=-68.0720 ;36.0000
P445=-68.0000 ;36.0350
P446=-67.8540 ;36.5000
P447=-67.6960 ;37.0000
P448=-67.5000 ;37.4530
P449=-67.4830 ;37.5000
P450=-67.2750 ;38.0000
P451=-67.1540 ;38.5000
P452=-67.0000 ;38.9470
P453=-66.9810 ;39.0000
P454=-66.7830 ;39.5000
P455=-66.6280 ;40.0000
P456=-66.5150 ;40.5000
P457=-66.5000 ;40.5630
P458=-66.3690 ;41.0000
P459=-66.1580 ;41.5000
P460=-66.1040 ;42.0000
P461=-66.0240 ;42.5000
P462=-66.0000 ;42.6650
P463=-65.8750 ;43.0000
P464=-65.7360 ;43.5000
P465=-65.7260 ;44.0000
P466=-65.7240 ;44.5000
P467=-65.7160 ;45.0000
P468=-65.7850 ;45.5000
P469=-66.0000 ;45.9980

[C4]

gain=-40.00

n_point=215

P1=-73.0000 ;41.0390
P2=-73.0780 ;41.5000
P3=-73.2880 ;42.0000
P4=-73.5000 ;42.3730
P5=-73.5730 ;42.5000
P6=-73.7640 ;43.0000
P7=-74.0000 ;43.2990
P8=-74.2200 ;43.5000
P9=-74.5000 ;43.7460
P10=-74.9190 ;44.0000
P11=-75.0000 ;44.0570
P12=-75.5000 ;44.3780
P13=-75.7400 ;44.5000
P14=-76.0000 ;44.6550
P15=-76.5000 ;44.9000
P16=-77.0000 ;44.9920
P17=-77.0100 ;45.0000
P18=-77.5000 ;45.2590
P19=-78.0000 ;45.3650
P20=-78.5000 ;45.2840
P21=-79.0000 ;45.2550
P22=-79.5000 ;45.4400
P23=-79.6010 ;45.5000
P24=-80.0000 ;45.5560
P25=-80.5000 ;45.5860
P26=-81.0000 ;45.5670
P27=-81.4600 ;45.5000

P28=-81.5000 ;45.4940
P29=-82.0000 ;45.3960
P30=-82.5000 ;45.2950
P31=-83.0000 ;45.1830
P32=-83.5000 ;45.0560
P33=-83.6840 ;45.0000
P34=-84.0000 ;44.9220
P35=-84.5000 ;44.8730
P36=-85.0000 ;44.6590
P37=-85.2880 ;44.5000
P38=-85.5000 ;44.3940
P39=-86.0000 ;44.2930
P40=-86.4260 ;44.0000
P41=-86.5000 ;43.9100
P42=-87.0000 ;43.7810
P43=-87.3680 ;43.5000
P44=-87.5000 ;43.3980
P45=-88.0000 ;43.1050
P46=-88.1300 ;43.0000
P47=-88.5000 ;42.8140
P48=-88.8630 ;42.5000
P49=-89.0000 ;42.4300
P50=-89.4730 ;42.0000
P51=-89.5000 ;41.9480
P52=-90.0000 ;41.5190
P53=-90.0200 ;41.5000
P54=-90.5000 ;41.1040
P55=-90.6030 ;41.0000
P56=-91.0000 ;40.6640
P57=-91.1570 ;40.5000
P58=-91.4710 ;40.0000
P59=-91.5000 ;39.9430
P60=-91.7870 ;39.5000
P61=-92.0000 ;39.3690
P62=-92.3090 ;39.0000
P63=-92.5000 ;38.6090
P64=-92.5850 ;38.5000
P65=-92.8020 ;38.0000
P66=-93.0000 ;37.7580
P67=-93.1750 ;37.5000
P68=-93.2790 ;37.0000
P69=-93.5000 ;36.7840
P70=-93.6860 ;36.5000
P71=-93.7690 ;36.0000
P72=-93.7510 ;35.5000
P73=-94.0000 ;35.2580
P74=-94.1140 ;35.0000
P75=-94.2880 ;34.5000
P76=-94.3600 ;34.0000
P77=-94.3800 ;33.5000
P78=-94.3510 ;33.0000
P79=-94.2580 ;32.5000
P80=-94.1460 ;32.0000
P81=-94.1680 ;31.5000
P82=-94.1350 ;31.0000
P83=-94.0000 ;30.7120
P84=-93.8270 ;30.5000

P85=-93.6810 ;30.0000
P86=-93.5750 ;29.5000
P87=-93.5000 ;29.3600
P88=-93.2860 ;29.0000
P89=-93.0650 ;28.5000
P90=-93.0000 ;28.3950
P91=-92.8470 ;28.5000
P92=-92.8060 ;29.0000
P93=-93.0000 ;29.3270
P94=-93.3220 ;29.5000
P95=-93.3370 ;30.0000
P96=-93.3460 ;30.5000
P97=-93.5000 ;30.8430
P98=-93.6950 ;31.0000
P99=-93.7890 ;31.5000
P100=-93.8520 ;32.0000
P101=-93.7690 ;32.5000
P102=-93.6830 ;33.0000
P103=-93.6400 ;33.5000
P104=-93.6340 ;34.0000
P105=-93.6460 ;34.5000
P106=-93.6410 ;35.0000
P107=-93.5000 ;35.1470
P108=-93.3950 ;35.5000
P109=-93.2390 ;36.0000
P110=-93.0320 ;36.5000
P111=-93.0000 ;36.5330
P112=-92.8050 ;37.0000
P113=-92.5920 ;37.5000
P114=-92.5000 ;37.5680
P115=-92.2610 ;38.0000
P116=-92.0000 ;38.4290
P117=-91.9470 ;38.5000
P118=-91.5840 ;39.0000
P119=-91.5000 ;39.1490
P120=-91.2510 ;39.5000
P121=-91.0000 ;39.6620
P122=-90.6850 ;40.0000
P123=-90.5000 ;40.1830
P124=-90.1890 ;40.5000
P125=-90.0000 ;40.7080
P126=-89.7000 ;41.0000
P127=-89.5000 ;41.1720
P128=-89.1470 ;41.5000
P129=-89.0000 ;41.5860
P130=-88.5450 ;42.0000
P131=-88.5000 ;42.0940
P132=-88.0000 ;42.3970
P133=-87.8660 ;42.5000
P134=-87.5000 ;42.6810
P135=-87.0770 ;43.0000
P136=-87.0000 ;43.1010
P137=-86.5000 ;43.2640
P138=-86.1400 ;43.5000
P139=-86.0000 ;43.6180
P140=-85.5000 ;43.7240
P141=-85.0230 ;44.0000

P142=-85.0000 ;44.0570
P143=-84.5000 ;44.1320
P144=-84.0000 ;44.2370
P145=-83.5000 ;44.4340
P146=-83.2960 ;44.5000
P147=-83.0000 ;44.6960
P148=-82.5000 ;44.7150
P149=-82.0000 ;44.7110
P150=-81.5000 ;44.7120
P151=-81.0000 ;44.7300
P152=-80.5000 ;44.7690
P153=-80.0000 ;44.8220
P154=-79.5000 ;44.8650
P155=-79.0000 ;44.8260
P156=-78.5000 ;44.5280
P157=-78.4580 ;44.5000
P158=-78.0000 ;44.3760
P159=-77.5000 ;44.4310
P160=-77.0000 ;44.1270
P161=-76.5000 ;44.0190
P162=-76.4710 ;44.0000
P163=-76.0000 ;43.6540
P164=-75.7660 ;43.5000
P165=-75.5000 ;43.2760
P166=-75.1250 ;43.0000
P167=-75.0000 ;42.8750
P168=-74.7610 ;42.5000
P169=-74.5000 ;42.1550
P170=-74.3280 ;42.0000
P171=-74.0850 ;41.5000
P172=-74.0000 ;41.3070
P173=-73.8950 ;41.0000
P174=-73.6430 ;40.5000
P175=-73.6950 ;40.0000
P176=-73.5450 ;39.5000
P177=-73.5000 ;39.2240
P178=-73.4680 ;39.0000
P179=-73.5000 ;38.5190
P180=-73.5010 ;38.5000
P181=-73.5000 ;38.4940
P182=-73.3850 ;38.0000
P183=-73.5000 ;37.7380
P184=-73.5800 ;37.5000
P185=-73.5000 ;37.0830
P186=-73.4540 ;37.0000
P187=-73.5000 ;36.9740
P188=-73.7220 ;36.5000
P189=-73.6770 ;36.0000
P190=-73.6210 ;35.5000
P191=-73.8080 ;35.0000
P192=-74.0000 ;34.7600
P193=-74.1150 ;34.5000
P194=-74.3230 ;34.0000
P195=-74.3670 ;33.5000
P196=-74.0000 ;33.3570
P197=-73.8970 ;33.5000
P198=-73.6870 ;34.0000

P199=-73.6030 ;34.5000
P200=-73.5000 ;34.5750
P201=-73.3330 ;35.0000
P202=-73.3970 ;35.5000
P203=-73.2180 ;36.0000
P204=-73.0000 ;36.4700
P205=-72.9880 ;36.5000
P206=-72.8410 ;37.0000
P207=-72.9010 ;37.5000
P208=-72.7390 ;38.0000
P209=-72.8630 ;38.5000
P210=-72.6850 ;39.0000
P211=-72.8100 ;39.5000
P212=-72.8090 ;40.0000
P213=-72.8890 ;40.5000
P214=-72.9840 ;41.0000
P215=-73.0000 ;41.0390

[C5]

gain=-50.00

n_point=535

P1=-77.0400 ;80.3260
P2=-77.5000 ;80.1420
P3=-77.8250 ;80.0000
P4=-78.0000 ;79.9430
P5=-78.5000 ;79.7710
P6=-79.0000 ;79.5300
P7=-79.0710 ;79.5000
P8=-79.5000 ;79.3620
P9=-80.0000 ;79.1250
P10=-80.2860 ;79.0000
P11=-80.5000 ;78.9280
P12=-81.0000 ;78.6990
P13=-81.4330 ;78.5000
P14=-81.5000 ;78.4760
P15=-82.0000 ;78.2500
P16=-82.5000 ;78.0070
P17=-82.5140 ;78.0000
P18=-83.0000 ;77.7730
P19=-83.5000 ;77.5160
P20=-83.5300 ;77.5000
P21=-84.0000 ;77.2650
P22=-84.4780 ;77.0000
P23=-84.5000 ;76.9890
P24=-85.0000 ;76.7320
P25=-85.3670 ;76.5000
P26=-85.5000 ;76.4490
P27=-86.0000 ;76.2860
P28=-86.5000 ;76.0640
P29=-86.6210 ;76.0000
P30=-87.0000 ;75.8460
P31=-87.5000 ;75.5900
P32=-87.6520 ;75.5000
P33=-88.0000 ;75.3190
P34=-88.4960 ;75.0000
P35=-88.5000 ;74.9980
P36=-89.0000 ;74.7300
P37=-89.3640 ;74.5000

P38=-89.5000 ;74.4200
P39=-90.0000 ;74.0820
P40=-90.1130 ;74.0000
P41=-90.5000 ;73.7200
P42=-90.7960 ;73.5000
P43=-91.0000 ;73.4050
P44=-91.5000 ;73.1440
P45=-91.7040 ;73.0000
P46=-92.0000 ;72.8390
P47=-92.4550 ;72.5000
P48=-92.5000 ;72.4640
P49=-93.0000 ;72.1210
P50=-93.1500 ;72.0000
P51=-93.5000 ;71.7140
P52=-93.7340 ;71.5000
P53=-94.0000 ;71.3050
P54=-94.4150 ;71.0000
P55=-94.5000 ;70.9560
P56=-95.0000 ;70.6080
P57=-95.1410 ;70.5000
P58=-95.5000 ;70.1540
P59=-95.6720 ;70.0000
P60=-96.0000 ;69.6840
P61=-96.1670 ;69.5000
P62=-96.5000 ;69.2880
P63=-96.9140 ;69.0000
P64=-97.0000 ;68.9340
P65=-97.4150 ;68.5000
P66=-97.5000 ;68.3930
P67=-97.8910 ;68.0000
P68=-98.0000 ;67.9490
P69=-98.5000 ;67.5080
P70=-98.5100 ;67.5000
P71=-99.0000 ;67.0230
P72=-99.0200 ;67.0000
P73=-99.4970 ;66.5000
P74=-99.5000 ;66.4980
P75=-99.9850 ;66.0000
P76=-100.0000;65.9790
P77=-100.3600;65.5000
P78=-100.5000;65.3730
P79=-100.8320;65.0000
P80=-101.0000;64.6530
P81=-101.1070;64.5000
P82=-101.5000;64.0940
P83=-101.5800;64.0000
P84=-101.8920;63.5000
P85=-102.0000;63.3750
P86=-102.3220;63.0000
P87=-102.5000;62.6560
P88=-102.6010;62.5000
P89=-103.0000;62.0100
P90=-103.0080;62.0000
P91=-103.3370;61.5000
P92=-103.5000;61.2950
P93=-103.7600;61.0000
P94=-104.0000;60.5620

P95=-104.0410;60.5000
P96=-104.3860;60.0000
P97=-104.5000;59.7720
P98=-104.6670;59.5000
P99=-104.9130;59.0000
P100=-105.0000;58.8350
P101=-105.2120;58.5000
P102=-105.4720;58.0000
P103=-105.5000;57.9330
P104=-105.7330;57.5000
P105=-106.0000;57.0080
P106=-106.0050;57.0000
P107=-106.3560;56.5000
P108=-106.5000;56.1270
P109=-106.5750;56.0000
P110=-106.8700;55.5000
P111=-107.0000;55.1620
P112=-107.0980;55.0000
P113=-107.2910;54.5000
P114=-107.4900;54.0000
P115=-107.5000;53.9810
P116=-107.7340;53.5000
P117=-107.9330;53.0000
P118=-108.0000;52.7950
P119=-108.1660;52.5000
P120=-108.3490;52.0000
P121=-108.5000;51.6190
P122=-108.5600;51.5000
P123=-108.7630;51.0000
P124=-108.8750;50.5000
P125=-109.0000;50.0920
P126=-109.0420;50.0000
P127=-109.2910;49.5000
P128=-109.3680;49.0000
P129=-109.5000;48.5790
P130=-109.5290;48.5000
P131=-109.6770;48.0000
P132=-109.8640;47.5000
P133=-109.9520;47.0000
P134=-110.0000;46.8130
P135=-110.0990;46.5000
P136=-110.1780;46.0000
P137=-110.3380;45.5000
P138=-110.4030;45.0000
P139=-110.4810;44.5000
P140=-110.5000;44.3180
P141=-110.5430;44.0000
P142=-110.6760;43.5000
P143=-110.7700;43.0000
P144=-110.8180;42.5000
P145=-110.8130;42.0000
P146=-110.8920;41.5000
P147=-110.9240;41.0000
P148=-110.9090;40.5000
P149=-110.8610;40.0000
P150=-110.8780;39.5000
P151=-110.8960;39.0000

P152=-110.8800;38.5000
P153=-110.8360;38.0000
P154=-110.7690;37.5000
P155=-110.6770;37.0000
P156=-110.5950;36.5000
P157=-110.5130;36.0000
P158=-110.5000;35.9400
P159=-110.4590;35.5000
P160=-110.4050;35.0000
P161=-110.3410;34.5000
P162=-110.2720;34.0000
P163=-110.1990;33.5000
P164=-110.1040;33.0000
P165=-110.0310;32.5000
P166=-110.0000;32.3000
P167=-109.9680;32.0000
P168=-109.9230;31.5000
P169=-109.8730;31.0000
P170=-109.8230;30.5000
P171=-109.7580;30.0000
P172=-109.6560;29.5000
P173=-109.5000;29.0580
P174=-109.4580;29.0000
P175=-109.3140;28.5000
P176=-109.2630;28.0000
P177=-109.1600;27.5000
P178=-109.0000;27.1650
P179=-108.8950;27.0000
P180=-108.7970;26.5000
P181=-108.6110;26.0000
P182=-108.5000;25.7980
P183=-108.3880;25.5000
P184=-108.1800;25.0000
P185=-108.0000;24.7110
P186=-107.8840;24.5000
P187=-107.6840;24.0000
P188=-107.5000;23.7080
P189=-107.3690;23.5000
P190=-107.2080;23.0000
P191=-107.0000;22.6810
P192=-106.8930;22.5000
P193=-106.6410;22.0000
P194=-106.5000;21.7920
P195=-106.3360;21.5000
P196=-106.1170;21.0000
P197=-106.0000;20.8380
P198=-105.8070;20.5000
P199=-105.5000;20.0900
P200=-105.4110;20.0000
P201=-105.1520;19.5000
P202=-105.0000;19.3080
P203=-104.7900;19.0000
P204=-104.5000;18.6580
P205=-104.3930;18.5000
P206=-104.0000;18.0630
P207=-103.9130;18.0000
P208=-103.5260;17.5000

P209=-103.5000;17.4720
P210=-103.0610;17.0000
P211=-103.0000;16.9370
P212=-102.6060;16.5000
P213=-102.5000;16.3930
P214=-102.1180;16.0000
P215=-102.0000;15.8840
P216=-101.5260;15.5000
P217=-101.5000;15.4750
P218=-101.0000;15.0370
P219=-100.9690;15.0000
P220=-100.5000;14.5860
P221=-100.3850;14.5000
P222=-100.0000;14.1820
P223=-99.7360 ;14.0000
P224=-99.5000 ;13.8040
P225=-99.0000 ;13.5240
P226=-98.9820 ;13.5000
P227=-98.5000 ;13.1420
P228=-98.2480 ;13.0000
P229=-98.0000 ;12.8150
P230=-97.5000 ;12.6540
P231=-97.3220 ;12.5000
P232=-97.0000 ;12.2690
P233=-96.5000 ;12.1170
P234=-96.2800 ;12.0000
P235=-96.0000 ;11.8250
P236=-95.5000 ;11.5720
P237=-95.2170 ;11.5000
P238=-95.0000 ;11.3670
P239=-94.5000 ;11.2280
P240=-94.0000 ;11.0790
P241=-93.7710 ;11.0000
P242=-93.5000 ;10.8740
P243=-93.0000 ;10.7020
P244=-92.5000 ;10.7060
P245=-92.0000 ;10.6550
P246=-91.5000 ;10.5500
P247=-91.3320 ;10.5000
P248=-91.0000 ;10.4210
P249=-90.5000 ;10.3260
P250=-90.0000 ;10.2520
P251=-89.5000 ;10.1980
P252=-89.0000 ;10.1730
P253=-88.5000 ;10.1750
P254=-88.0000 ;10.1890
P255=-87.5000 ;10.2070
P256=-87.0000 ;10.2260
P257=-86.5000 ;10.2440
P258=-86.0000 ;10.2640
P259=-85.5000 ;10.2880
P260=-85.0000 ;10.3330
P261=-84.5000 ;10.4200
P262=-84.1920 ;10.5000
P263=-84.5000 ;10.7130
P264=-85.0000 ;10.7520
P265=-85.5000 ;10.7530

P266=-86.0000 ;10.7480
P267=-86.5000 ;10.7520
P268=-87.0000 ;10.7640
P269=-87.5000 ;10.7880
P270=-88.0000 ;10.8210
P271=-88.5000 ;10.8580
P272=-89.0000 ;10.8870
P273=-89.5000 ;10.9060
P274=-90.0000 ;10.9380
P275=-90.2750 ;11.0000
P276=-90.5000 ;11.0390
P277=-91.0000 ;11.1430
P278=-91.5000 ;11.2350
P279=-92.0000 ;11.2430
P280=-92.5000 ;11.2910
P281=-93.0000 ;11.4140
P282=-93.1890 ;11.5000
P283=-93.5000 ;11.6340
P284=-94.0000 ;11.8220
P285=-94.5000 ;11.8410
P286=-94.7320 ;12.0000
P287=-95.0000 ;12.1520
P288=-95.5000 ;12.4140
P289=-95.8080 ;12.5000
P290=-96.0000 ;12.6260
P291=-96.5000 ;12.8320
P292=-96.8250 ;13.0000
P293=-97.0000 ;13.1180
P294=-97.5000 ;13.3030
P295=-97.7800 ;13.5000
P296=-98.0000 ;13.6610
P297=-98.5000 ;13.9110
P298=-98.6120 ;14.0000
P299=-99.0000 ;14.2970
P300=-99.2930 ;14.5000
P301=-99.5000 ;14.6700
P302=-100.0000;14.9600
P303=-100.0290;15.0000
P304=-100.5000;15.4090
P305=-100.6080;15.5000
P306=-101.0000;15.8650
P307=-101.1690;16.0000
P308=-101.5000;16.3140
P309=-101.6810;16.5000
P310=-102.0000;16.8210
P311=-102.1800;17.0000
P312=-102.5000;17.3340
P313=-102.6580;17.5000
P314=-103.0000;17.8600
P315=-103.1420;18.0000
P316=-103.5000;18.4290
P317=-103.5510;18.5000
P318=-103.9700;19.0000
P319=-104.0000;19.0340
P320=-104.2940;19.5000
P321=-104.5000;19.7570
P322=-104.6900;20.0000

P323=-105.0000;20.4440
P324=-105.0560;20.5000
P325=-105.2830;21.0000
P326=-105.5000;21.3030
P327=-105.6560;21.5000
P328=-105.8510;22.0000
P329=-106.0000;22.2310
P330=-106.1400;22.5000
P331=-106.3910;23.0000
P332=-106.5000;23.1780
P333=-106.6760;23.5000
P334=-106.8650;24.0000
P335=-107.0000;24.2220
P336=-107.1450;24.5000
P337=-107.3260;25.0000
P338=-107.5000;25.2960
P339=-107.6030;25.5000
P340=-107.7800;26.0000
P341=-108.0000;26.4100
P342=-108.0660;26.5000
P343=-108.2280;27.0000
P344=-108.3600;27.5000
P345=-108.5000;27.8380
P346=-108.5950;28.0000
P347=-108.7140;28.5000
P348=-108.7860;29.0000
P349=-108.8700;29.5000
P350=-109.0000;29.9820
P351=-109.0070;30.0000
P352=-109.0850;30.5000
P353=-109.1140;31.0000
P354=-109.1350;31.5000
P355=-109.1650;32.0000
P356=-109.2010;32.5000
P357=-109.2450;33.0000
P358=-109.3080;33.5000
P359=-109.3790;34.0000
P360=-109.4700;34.5000
P361=-109.5000;34.6950
P362=-109.5320;35.0000
P363=-109.5470;35.5000
P364=-109.5640;36.0000
P365=-109.5920;36.5000
P366=-109.6230;37.0000
P367=-109.6710;37.5000
P368=-109.7270;38.0000
P369=-109.7790;38.5000
P370=-109.7860;39.0000
P371=-109.7740;39.5000
P372=-109.7620;40.0000
P373=-109.7720;40.5000
P374=-109.8230;41.0000
P375=-109.7820;41.5000
P376=-109.7050;42.0000
P377=-109.6570;42.5000
P378=-109.6830;43.0000
P379=-109.5940;43.5000

P380=-109.5390;44.0000
P381=-109.5000;44.2300
P382=-109.4200;44.5000
P383=-109.3260;45.0000
P384=-109.2330;45.5000
P385=-109.1030;46.0000
P386=-109.0270;46.5000
P387=-109.0000;46.5770
P388=-108.8470;47.0000
P389=-108.7610;47.5000
P390=-108.5970;48.0000
P391=-108.5000;48.3510
P392=-108.4310;48.5000
P393=-108.2660;49.0000
P394=-108.1270;49.5000
P395=-108.0000;49.9540
P396=-107.9830;50.0000
P397=-107.7360;50.5000
P398=-107.5600;51.0000
P399=-107.5000;51.1510
P400=-107.3000;51.5000
P401=-107.1670;52.0000
P402=-107.0000;52.3780
P403=-106.9400;52.5000
P404=-106.6720;53.0000
P405=-106.5000;53.4780
P406=-106.4870;53.5000
P407=-106.1850;54.0000
P408=-106.0000;54.4400
P409=-105.9620;54.5000
P410=-105.6990;55.0000
P411=-105.5000;55.3820
P412=-105.4270;55.5000
P413=-105.1500;56.0000
P414=-105.0000;56.2480
P415=-104.8090;56.5000
P416=-104.5270;57.0000
P417=-104.5000;57.0450
P418=-104.2180;57.5000
P419=-104.0000;57.8430
P420=-103.8810;58.0000
P421=-103.5840;58.5000
P422=-103.5000;58.6390
P423=-103.2760;59.0000
P424=-103.0000;59.4020
P425=-102.9220;59.5000
P426=-102.5880;60.0000
P427=-102.5000;60.0990
P428=-102.2010;60.5000
P429=-102.0000;60.7300
P430=-101.7510;61.0000
P431=-101.5000;61.4590
P432=-101.4670;61.5000
P433=-101.0000;61.9300
P434=-100.9240;62.0000
P435=-100.5160;62.5000
P436=-100.5000;62.5170

P437=-100.0140;63.0000
P438=-100.0000;63.0190
P439=-99.6020 ;63.5000
P440=-99.5000 ;63.5970
P441=-99.0610 ;64.0000
P442=-99.0000 ;64.0730
P443=-98.6090 ;64.5000
P444=-98.5000 ;64.5810
P445=-98.0590 ;65.0000
P446=-98.0000 ;65.0800
P447=-97.5760 ;65.5000
P448=-97.5000 ;65.5430
P449=-97.0000 ;65.9240
P450=-96.8950 ;66.0000
P451=-96.5000 ;66.3310
P452=-96.3110 ;66.5000
P453=-96.0000 ;66.6950
P454=-95.5820 ;67.0000
P455=-95.5000 ;67.0530
P456=-95.0000 ;67.4590
P457=-94.9430 ;67.5000
P458=-94.5000 ;67.8570
P459=-94.3290 ;68.0000
P460=-94.0000 ;68.1660
P461=-93.5000 ;68.4600
P462=-93.4400 ;68.5000
P463=-93.0000 ;68.8390
P464=-92.7590 ;69.0000
P465=-92.5000 ;69.1860
P466=-92.1090 ;69.5000
P467=-92.0000 ;69.5550
P468=-91.5000 ;69.7840
P469=-91.1290 ;70.0000
P470=-91.0000 ;70.0680
P471=-90.5000 ;70.3950
P472=-90.3240 ;70.5000
P473=-90.0000 ;70.7090
P474=-89.5570 ;71.0000
P475=-89.5000 ;71.0330
P476=-89.0000 ;71.3200
P477=-88.7040 ;71.5000
P478=-88.5000 ;71.5700
P479=-88.0000 ;71.7620
P480=-87.5640 ;72.0000
P481=-87.5000 ;72.0320
P482=-87.0000 ;72.2940
P483=-86.5960 ;72.5000
P484=-86.5000 ;72.5470
P485=-86.0000 ;72.8080
P486=-85.6710 ;73.0000
P487=-85.5000 ;73.0940
P488=-85.0000 ;73.3700
P489=-84.7570 ;73.5000
P490=-84.5000 ;73.5820
P491=-84.0000 ;73.7700
P492=-83.5490 ;74.0000
P493=-83.5000 ;74.0160

P494=-83.0000 ;74.1790
P495=-82.5000 ;74.3910
P496=-82.2290 ;74.5000
P497=-82.0000 ;74.5800
P498=-81.5000 ;74.7790
P499=-81.0080 ;75.0000
P500=-81.0000 ;75.0030
P501=-80.5000 ;75.2010
P502=-80.0000 ;75.4310
P503=-79.8430 ;75.5000
P504=-79.5000 ;75.6230
P505=-79.0000 ;75.8490
P506=-78.6330 ;76.0000
P507=-78.5000 ;76.0440
P508=-78.0000 ;76.2460
P509=-77.5000 ;76.4480
P510=-77.3760 ;76.5000
P511=-77.0000 ;76.6440
P512=-76.5000 ;76.8330
P513=-76.0960 ;77.0000
P514=-76.0000 ;77.0360
P515=-75.5000 ;77.2140
P516=-75.0000 ;77.4000
P517=-74.7670 ;77.5000
P518=-74.5000 ;77.5950
P519=-74.0000 ;77.7510
P520=-73.5000 ;77.9460
P521=-73.3560 ;78.0000
P522=-73.0000 ;78.1020
P523=-72.5000 ;78.2630
P524=-72.0000 ;78.4570
P525=-71.8700 ;78.5000
P526=-71.5000 ;78.5840
P527=-71.0000 ;78.7130
P528=-70.5000 ;78.9010
P529=-70.2170 ;79.0000
P530=-70.0000 ;79.0520
P531=-69.5000 ;79.1590
P532=-69.0000 ;79.2950
P533=-68.5000 ;79.4840
P534=-68.4490 ;79.5000
P535=-68.4410 ;79.5020
[C6]
gain=-50.00
n_point=127
P1=-166.4073;68.7029
P2=-164.9353;68.4628
P3=-163.4690;68.1962
P4=-162.0084;67.9032
P5=-160.5533;67.5838
P6=-159.1039;67.2380
P7=-157.6608;66.8643
P8=-156.2281;66.4548
P9=-154.8064;66.0082
P10=-153.3976;65.5258
P11=-152.0022;65.0075
P12=-150.6258;64.4404

P13=-149.2714;63.8188
P14=-147.9466;63.1383
P15=-146.6538;62.3983
P16=-145.3897;61.6100
P17=-144.1533;60.7783
P18=-142.9462;59.9055
P19=-141.7695;58.9914
P20=-140.6395;58.0213
P21=-139.5605;56.9924
P22=-138.5176;55.9276
P23=-137.5101;54.8302
P24=-136.5298;53.7074
P25=-135.5641;52.5712
P26=-134.6509;51.3951
P27=-133.7549;50.2040
P28=-132.8788;48.9984
P29=-132.0702;47.7486
P30=-131.3280;46.4551
P31=-130.6690;45.1210
P32=-130.0962;43.7485
P33=-129.5994;42.3452
P34=-129.1534;40.9266
P35=-128.7103;39.5046
P36=-128.2775;38.0804
P37=-127.8172;36.6643
P38=-127.3260;35.2588
P39=-126.8071;33.8629
P40=-126.2667;32.4749
P41=-125.7209;31.0903
P42=-125.1796;29.7048
P43=-124.6367;28.3205
P44=-124.0759;26.9408
P45=-123.4784;25.5773
P46=-122.8450;24.2301
P47=-122.1895;22.8942
P48=-121.5290;21.5622
P49=-120.8668;20.2317
P50=-120.1841;18.9124
P51=-119.4429;17.6230
P52=-118.6318;16.3738
P53=-117.7778;15.1539
P54=-116.9220;13.9357
P55=-116.0780;12.7097
P56=-115.1860;11.5166
P57=-114.2312;10.3734
P58=-113.2223;9.2778
P59=-112.1860;8.2066
P60=-111.1510;7.1337
P61=-110.0623;6.1173
P62=-108.9067;5.1769
P63=-107.7067;4.2952
P64=-106.4874;3.4421
P65=-105.2540;2.6079
P66=-103.9697;1.8559
P67=-102.6301;1.2123
P68=-101.2754;0.5971
P69=-99.9117 ;0.0083

P70=-98.5154 ; -0.5017
P71=-97.0800 ; -0.8896
P72=-95.6235 ; -1.1915
P73=-94.1634 ; -1.4842
P74=-92.7022 ; -1.7707
P75=-91.2351 ; -2.0188
P76=-89.7451 ; -2.0588
P77=-88.2554 ; -2.0341
P78=-86.7650 ; -2.0023
P79=-85.2751 ; -1.9666
P80=-83.7873 ; -1.8867
P81=-82.3091 ; -1.6910
P82=-80.8468 ; -1.4236
P83=-79.4146 ; -1.0194
P84=-77.9933 ; -0.5860
P85=-76.5805 ; -0.1254
P86=-75.1981 ; 0.4185
P87=-73.8497 ; 1.0438
P88=-72.5164 ; 1.7023
P89=-71.1539 ; 2.2975
P90=-69.7399 ; 2.7631
P91=-68.3038 ; 3.1582
P92=-66.8890 ; 3.6128
P93=-65.5075 ; 4.1702
P94=-64.1501 ; 4.7800
P95=-62.8131 ; 5.4352
P96=-61.4875 ; 6.1125
P97=-60.2061 ; 6.8686
P98=-58.9426 ; 7.6571
P99=-57.6936 ; 8.4681
P100=-56.4695 ; 9.3181
P101=-55.2343 ; 10.1513
P102=-53.9969 ; 10.9820
P103=-52.7633 ; 11.8177
P104=-51.5181 ; 12.6364
P105=-50.2709 ; 13.4522
P106=-49.0231 ; 14.2670
P107=-47.7709 ; 15.0751
P108=-46.5190 ; 15.8832
P109=-45.2638 ; 16.6864
P110=-44.0044 ; 17.4813
P111=-42.7352 ; 18.2603
P112=-41.4643 ; 19.0375
P113=-40.1901 ; 19.8092
P114=-38.8990 ; 20.5517
P115=-37.6220 ; 21.3188
P116=-36.3214 ; 22.0450
P117=-34.9998 ; 22.7305
P118=-33.6654 ; 23.3916
P119=-32.3078 ; 24.0058
P120=-30.9174 ; 24.5412
P121=-29.5012 ; 25.0007
P122=-28.0702 ; 25.4115
P123=-26.6226 ; 25.7635
P124=-25.1626 ; 26.0631
P125=-23.6922 ; 26.3057
P126=-22.2135 ; 26.4903

P127=-20.7283 ;26.6191
[C7]
gain=-50.00
n_point=147
P1=-111.6158;81.1563
P2=-110.5872;80.2029
P3=-109.7851;79.0913
P4=-109.2270;77.8299
P5=-109.0214;76.4719
P6=-109.0813;75.0833
P7=-109.2728;73.7310
P8=-109.5596;72.3916
P9=-109.8630;71.0487
P10=-110.1219;69.6930
P11=-110.3702;68.3334
P12=-110.6529;66.9805
P13=-111.0129;65.6446
P14=-111.3560;64.3048
P15=-111.6848;62.9619
P16=-112.0232;61.6215
P17=-112.3624;60.2839
P18=-112.6791;58.9419
P19=-112.9609;57.5903
P20=-113.2758;56.2462
P21=-113.5610;54.8952
P22=-113.7977;53.5342
P23=-114.0275;52.1762
P24=-114.2387;50.8141
P25=-114.4198;49.4450
P26=-114.5525;48.0702
P27=-114.6195;46.6899
P28=-114.6299;45.3055
P29=-114.6152;43.9209
P30=-114.5392;42.5408
P31=-114.3915;41.1669
P32=-114.1913;39.7986
P33=-114.0064;38.4275
P34=-113.8415;37.0538
P35=-113.6774;35.6815
P36=-113.5554;34.3033
P37=-113.4157;32.9269
P38=-113.1807;31.5627
P39=-112.9475;30.1987
P40=-112.6477;28.8518
P41=-112.2141;27.5385
P42=-111.7283;26.2466
P43=-111.1984;24.9720
P44=-110.6345;23.7095
P45=-110.0658;22.4502
P46=-109.4444;21.2160
P47=-108.7612;20.0145
P48=-108.0212;18.8496
P49=-107.2225;17.7223
P50=-106.3738;16.6299
P51=-105.4804;15.5724
P52=-104.5396;14.5585
P53=-103.5286;13.6133

P54=-102.4843;12.7046
P55=-101.3940;11.8560
P56=-100.2475;11.0856
P57=-99.0543 ;10.3874
P58=-97.8262 ;9.7524
P59=-96.5655 ;9.1899
P60=-95.2704 ;8.7204
P61=-93.9527 ;8.3101
P62=-92.6109 ;7.9936
P63=-91.2415 ;7.8237
P64=-89.8648 ;7.7134
P65=-88.4833 ;7.6390
P66=-87.0902 ;7.6094
P67=-85.7158 ;7.6323
P68=-84.3474 ;7.7202
P69=-82.9255 ;7.8993
P70=-81.6205 ;8.1869
P71=-80.3857 ;8.5937
P72=-78.7568 ;9.0977
P73=-78.3031 ;8.9558
P74=-79.1575 ;8.3083
P75=-80.5492 ;7.7454
P76=-81.8827 ;7.3459
P77=-83.1787 ;7.0847
P78=-84.5814 ;6.9129
P79=-85.9600 ;6.8076
P80=-87.3323 ;6.7555
P81=-88.7242 ;6.7590
P82=-90.1034 ;6.8627
P83=-91.4752 ;7.0221
P84=-92.8438 ;7.2112
P85=-94.1904 ;7.5086
P86=-95.5099 ;7.9083
P87=-96.7978 ;8.3998
P88=-98.0468 ;8.9711
P89=-99.2699 ;9.6024
P90=-100.4669;10.2878
P91=-101.6244;11.0361
P92=-102.7259;11.8643
P93=-103.7536;12.7902
P94=-104.7554;13.7462
P95=-105.7353;14.7226
P96=-106.6778;15.7366
P97=-107.5500;16.8104
P98=-108.3673;17.9264
P99=-109.1362;19.0762
P100=-109.8524;20.2583
P101=-110.5097;21.4705
P102=-111.1240;22.7049
P103=-111.7125;23.9538
P104=-112.2642;25.2201
P105=-112.7817;26.5000
P106=-113.2591;27.7935
P107=-113.6641;29.1111
P108=-113.9766;30.4552
P109=-114.2155;31.8176
P110=-114.4246;33.1832

P111=-114.6390;34.5486
P112=-114.8619;35.9127
P113=-115.0940;37.2751
P114=-115.3504;38.6342
P115=-115.6168;39.9922
P116=-115.8480;41.3553
P117=-115.9703;42.7330
P118=-116.0384;44.1147
P119=-116.0577;45.4963
P120=-116.0055;46.8787
P121=-115.9370;48.2615
P122=-115.8451;49.6416
P123=-115.6891;51.0138
P124=-115.5045;52.3827
P125=-115.3153;53.7515
P126=-115.1464;55.1237
P127=-114.9186;56.4869
P128=-114.6567;57.8436
P129=-114.4711;59.2087
P130=-114.2729;60.5745
P131=-114.0568;61.9402
P132=-113.8494;63.3079
P133=-113.6991;64.6821
P134=-113.5909;66.0601
P135=-113.4767;67.4354
P136=-113.4533;68.8174
P137=-113.5328;70.2006
P138=-113.6951;71.5730
P139=-113.9318;72.9284
P140=-114.2863;74.2581
P141=-114.7996;75.5496
P142=-115.4655;76.7543
P143=-116.3306;77.8120
P144=-117.4126;78.6896
P145=-118.5609;79.4675
P146=-119.7576;80.1554
P147=-120.9933;80.7491

[C8]

gain=-50.00

n_point=85

P1=-22.9941 ;43.3716
P2=-24.4745 ;43.1334
P3=-25.9563 ;42.9054
P4=-27.4282 ;42.6321
P5=-28.8851 ;42.2836
P6=-30.3314 ;41.8987
P7=-31.7599 ;41.4450
P8=-33.1750 ;40.9478
P9=-34.5681 ;40.3908
P10=-35.9547 ;39.8281
P11=-37.3048 ;39.2034
P12=-38.6361 ;38.5386
P13=-39.9488 ;37.8453
P14=-41.2573 ;37.1398
P15=-42.5426 ;36.3728
P16=-43.8186 ;35.6005
P17=-45.0625 ;34.7610

P18=-46.3075 ;33.9244
P19=-47.5321 ;33.0561
P20=-48.7269 ;32.1490
P21=-49.8734 ;31.1802
P22=-51.0134 ;30.2042
P23=-52.0808 ;29.1490
P24=-53.1244 ;28.0704
P25=-54.1486 ;26.9733
P26=-55.1722 ;25.8773
P27=-56.2197 ;24.8041
P28=-57.2987 ;23.7616
P29=-58.3970 ;22.7384
P30=-59.5110 ;21.7330
P31=-60.6358 ;20.7395
P32=-61.7914 ;19.7818
P33=-62.9484 ;18.8258
P34=-64.1212 ;17.8894
P35=-65.3175 ;16.9836
P36=-66.5219 ;16.0891
P37=-67.7455 ;15.2218
P38=-69.0051 ;14.4083
P39=-70.3042 ;13.6536
P40=-71.6149 ;12.9478
P41=-72.9766 ;12.2773
P42=-74.2429 ;11.5089
P43=-75.3676 ;10.6541
P44=-74.4820 ;10.7117
P45=-73.1039 ;11.2767
P46=-71.7199 ;11.9185
P47=-70.4049 ;12.6046
P48=-69.1111 ;13.3719
P49=-67.8681 ;14.2101
P50=-66.6468 ;15.0807
P51=-65.4496 ;15.9857
P52=-64.2608 ;16.9011
P53=-63.0810 ;17.8280
P54=-61.9038 ;18.7589
P55=-60.7417 ;19.7080
P56=-59.5645 ;20.6391
P57=-58.4317 ;21.6232
P58=-57.2647 ;22.5674
P59=-56.1263 ;23.5455
P60=-54.9961 ;24.5331
P61=-53.8767 ;25.5328
P62=-52.7477 ;26.5215
P63=-51.6570 ;27.5529
P64=-50.5567 ;28.5739
P65=-49.4543 ;29.5927
P66=-48.3504 ;30.6094
P67=-47.1941 ;31.5665
P68=-46.0342 ;32.5185
P69=-44.8071 ;33.3818
P70=-43.5872 ;34.2447
P71=-42.3245 ;35.0421
P72=-41.0497 ;35.8263
P73=-39.7374 ;36.5474
P74=-38.4021 ;37.2288

P75=-37.0503 ;37.8765
P76=-35.6792 ;38.4806
P77=-34.2930 ;39.0384
P78=-32.8892 ;39.5445
P79=-31.4667 ;39.9981
P80=-30.0374 ;40.4330
P81=-28.5901 ;40.7971
P82=-27.1278 ;41.1086
P83=-25.6663 ;41.4357
P84=-24.1803 ;41.6164
P85=-22.6885 ;41.7821
[C9]
gain=-40.00
n_point=110
P1=-40.6301 ;72.2086
P2=-42.3381 ;71.9318
P3=-44.0464 ;71.6575
P4=-45.7551 ;71.3858
P5=-47.4642 ;71.1167
P6=-49.1736 ;70.8493
P7=-50.8824 ;70.5782
P8=-52.5905 ;70.3022
P9=-54.2972 ;70.0185
P10=-56.0020 ;69.7235
P11=-57.7047 ;69.4171
P12=-59.4055 ;69.0999
P13=-61.1045 ;68.7718
P14=-62.7992 ;68.4244
P15=-64.4876 ;68.0512
P16=-66.1696 ;67.6511
P17=-67.8449 ;67.2211
P18=-69.5136 ;66.7620
P19=-71.1762 ;66.2844
P20=-72.8321 ;65.7881
P21=-74.4775 ;65.2543
P22=-76.1138 ;64.6919
P23=-77.7438 ;64.1154
P24=-79.3681 ;63.5207
P25=-80.9909 ;62.9213
P26=-82.6133 ;62.3222
P27=-84.2311 ;61.7125
P28=-85.8396 ;61.0785
P29=-87.4270 ;60.3948
P30=-88.9801 ;59.6341
P31=-90.5061 ;58.8197
P32=-92.0018 ;57.9508
P33=-93.4579 ;57.0172
P34=-94.8609 ;56.0058
P35=-96.1758 ;54.8830
P36=-97.4235 ;53.6845
P37=-98.6078 ;52.4239
P38=-99.7067 ;51.0874
P39=-100.7100 ;49.6797
P40=-101.6162 ;48.2068
P41=-102.4519 ;46.6938
P42=-103.1783 ;45.1248
P43=-103.7890 ;43.5091

P44=-104.2965;41.8544
P45=-104.6213;40.1599
P46=-104.8254;38.4417
P47=-104.8908;36.7136
P48=-104.8170;34.9854
P49=-104.7323;33.2571
P50=-104.6310;31.5305
P51=-104.4799;29.8075
P52=-104.1431;28.1114
P53=-103.6088;26.4709
P54=-102.8641;24.9132
P55=-102.0139;23.4076
P56=-101.1380;21.9174
P57=-100.1362;20.5086
P58=-98.9439 ;19.2576
P59=-97.6152 ;18.1519
P60=-96.2204 ;17.1297
P61=-94.7518 ;16.2226
P62=-93.1567 ;15.5657
P63=-91.4854 ;15.1264
P64=-89.7820 ;14.8392
P65=-88.0697 ;14.5884
P66=-86.3449 ;14.5748
P67=-84.6323 ;14.8380
P68=-82.9409 ;15.1851
P69=-81.2516 ;15.5512
P70=-79.5723 ;15.9648
P71=-77.9141 ;16.4531
P72=-76.3192 ;17.1199
P73=-74.8029 ;17.9525
P74=-73.3679 ;18.9169
P75=-71.9834 ;19.9542
P76=-70.6461 ;21.0515
P77=-69.3329 ;22.1773
P78=-68.0699 ;23.3595
P79=-66.8209 ;24.5566
P80=-65.6019 ;25.7845
P81=-64.4062 ;27.0350
P82=-63.2575 ;28.3279
P83=-62.1540 ;29.6597
P84=-61.0888 ;31.0221
P85=-60.0395 ;32.3973
P86=-58.9873 ;33.7706
P87=-57.9020 ;35.1178
P88=-56.7945 ;36.4471
P89=-55.6769 ;37.7677
P90=-54.5385 ;39.0706
P91=-53.3977 ;40.3713
P92=-52.2490 ;41.6655
P93=-51.1651 ;43.0129
P94=-50.1388 ;44.4060
P95=-49.2323 ;45.8787
P96=-48.3792 ;47.3835
P97=-47.4961 ;48.8690
P98=-46.4251 ;50.2283
P99=-45.2348 ;51.4814
P100=-43.9532 ;52.6419

P101=-42.5640 ;53.6701
P102=-41.1231 ;54.6275
P103=-39.6514 ;55.5348
P104=-38.1429 ;56.3777
P105=-36.5898 ;57.1353
P106=-34.9931 ;57.7930
P107=-33.3595 ;58.3570
P108=-31.6963 ;58.8295
P109=-30.0089 ;59.1988
P110=-28.2976 ;59.4642

[C10]

gain=-2.00

n_point=84

P1=-82.5000 ;35.1460
P2=-82.4220 ;35.0000
P3=-82.3952 ;34.8750
P4=-82.3685 ;34.7500
P5=-82.3418 ;34.6250
P6=-82.3150 ;34.5000
P7=-82.3290 ;34.3333
P8=-82.3430 ;34.1667
P9=-82.3570 ;34.0000
P10=-82.4047 ;33.8450
P11=-82.4523 ;33.6900
P12=-82.5000 ;33.5350
P13=-82.5130 ;33.5000
P14=-82.5910 ;33.3750
P15=-82.6690 ;33.2500
P16=-82.7470 ;33.1250
P17=-82.8250 ;33.0000
P18=-82.9125 ;32.8935
P19=-83.0000 ;32.7870
P20=-83.0980 ;32.6913
P21=-83.1960 ;32.5957
P22=-83.2940 ;32.5000
P23=-83.3970 ;32.4230
P24=-83.5000 ;32.3460
P25=-83.6667 ;32.2563
P26=-83.8333 ;32.1667
P27=-84.0000 ;32.0770
P28=-84.1250 ;32.0385
P29=-84.2500 ;32.0000
P30=-84.3750 ;31.9695
P31=-84.5000 ;31.9390
P32=-84.6667 ;31.9350
P33=-84.8333 ;31.9310
P34=-85.0000 ;31.9270
P35=-85.1430 ;31.9635
P36=-85.2860 ;32.0000
P37=-85.3930 ;32.0420
P38=-85.5000 ;32.0840
P39=-85.6250 ;32.1872
P40=-85.7500 ;32.2905
P41=-85.8750 ;32.3937
P42=-86.0000 ;32.4970
P43=-86.0020 ;32.5000
P44=-86.0502 ;32.6250

P45=-86.0985 ;32.7500
P46=-86.1468 ;32.8750
P47=-86.1950 ;33.0000
P48=-86.2123 ;33.1667
P49=-86.2297 ;33.3333
P50=-86.2470 ;33.5000
P51=-86.2160 ;33.6667
P52=-86.1850 ;33.8333
P53=-86.1540 ;34.0000
P54=-86.1027 ;34.1250
P55=-86.0513 ;34.2500
P56=-86.0000 ;34.3750
P57=-85.9340 ;34.5000
P58=-85.8405 ;34.6250
P59=-85.7470 ;34.7500
P60=-85.6535 ;34.8750
P61=-85.5600 ;35.0000
P62=-85.5000 ;35.0620
P63=-85.3750 ;35.1628
P64=-85.2500 ;35.2635
P65=-85.1250 ;35.3643
P66=-85.0000 ;35.4650
P67=-84.9370 ;35.5000
P68=-84.7913 ;35.5633
P69=-84.6457 ;35.6267
P70=-84.5000 ;35.6900
P71=-84.3333 ;35.7283
P72=-84.1667 ;35.7667
P73=-84.0000 ;35.8050
P74=-83.8333 ;35.8030
P75=-83.6667 ;35.8010
P76=-83.5000 ;35.7990
P77=-83.3333 ;35.7473
P78=-83.1667 ;35.6957
P79=-83.0000 ;35.6440
P80=-82.8965 ;35.5720
P81=-82.7930 ;35.5000
P82=-82.6953 ;35.3820
P83=-82.5977 ;35.2640
P84=-82.5000 ;35.1460
[C11]
gain=-4.00
n_point=93
P1=-81.5000 ;34.5380
P2=-81.4990 ;34.5000
P3=-81.5000 ;34.4910
P4=-81.5283 ;34.3273
P5=-81.5567 ;34.1637
P6=-81.5850 ;34.0000
P7=-81.6453 ;33.8333
P8=-81.7057 ;33.6667
P9=-81.7660 ;33.5000
P10=-81.8440 ;33.3383
P11=-81.9220 ;33.1767
P12=-82.0000 ;33.0150
P13=-82.0090 ;33.0000
P14=-82.1320 ;32.8333

P15=-82.2550 ;32.6667
P16=-82.3780 ;32.5000
P17=-82.5000 ;32.3650
P18=-82.6280 ;32.2433
P19=-82.7560 ;32.1217
P20=-82.8840 ;32.0000
P21=-83.0000 ;31.9070
P22=-83.1667 ;31.7960
P23=-83.3333 ;31.6850
P24=-83.5000 ;31.5740
P25=-83.6460 ;31.5000
P26=-83.8230 ;31.4250
P27=-84.0000 ;31.3500
P28=-84.2500 ;31.2850
P29=-84.5000 ;31.2200
P30=-84.7500 ;31.2010
P31=-85.0000 ;31.1820
P32=-85.2500 ;31.2140
P33=-85.5000 ;31.2460
P34=-85.7500 ;31.3415
P35=-86.0000 ;31.4370
P36=-86.1030 ;31.5000
P37=-86.2353 ;31.6123
P38=-86.3677 ;31.7247
P39=-86.5000 ;31.8370
P40=-86.6300 ;32.0000
P41=-86.7150 ;32.1667
P42=-86.8000 ;32.3333
P43=-86.8850 ;32.5000
P44=-86.9233 ;32.6590
P45=-86.9617 ;32.8180
P46=-87.0000 ;32.9770
P47=-87.0040 ;33.0000
P48=-87.0047 ;33.1667
P49=-87.0053 ;33.3333
P50=-87.0060 ;33.5000
P51=-87.0000 ;33.5320
P52=-86.9667 ;33.6880
P53=-86.9333 ;33.8440
P54=-86.9000 ;34.0000
P55=-86.8363 ;34.1667
P56=-86.7727 ;34.3333
P57=-86.7090 ;34.5000
P58=-86.6045 ;34.7005
P59=-86.5000 ;34.9010
P60=-86.4370 ;35.0000
P61=-86.3023 ;35.1667
P62=-86.1677 ;35.3333
P63=-86.0330 ;35.5000
P64=-86.0000 ;35.5330
P65=-85.8333 ;35.6730
P66=-85.6667 ;35.8130
P67=-85.5000 ;35.9530
P68=-85.4300 ;36.0000
P69=-85.2150 ;36.1230
P70=-85.0000 ;36.2460
P71=-84.7500 ;36.3550

P72=-84.5000 ;36.4640
P73=-84.3690 ;36.5000
P74=-84.1845 ;36.5430
P75=-84.0000 ;36.5860
P76=-83.7500 ;36.6055
P77=-83.5000 ;36.6250
P78=-83.2500 ;36.5980
P79=-83.0000 ;36.5710
P80=-82.7630 ;36.5000
P81=-82.5000 ;36.3960
P82=-82.3333 ;36.2777
P83=-82.1667 ;36.1593
P84=-82.0000 ;36.0410
P85=-81.9620 ;36.0000
P86=-81.8620 ;35.8333
P87=-81.7620 ;35.6667
P88=-81.6620 ;35.5000
P89=-81.6150 ;35.3333
P90=-81.5680 ;35.1667
P91=-81.5210 ;35.0000
P92=-81.5105 ;34.7690
P93=-81.5000 ;34.5380
[C12]
gain=-6.00
n_point=91
P1=-81.0000 ;35.5740
P2=-80.9790 ;35.5000
P3=-80.9490 ;35.2500
P4=-80.9190 ;35.0000
P5=-80.9245 ;34.7500
P6=-80.9300 ;34.5000
P7=-80.9650 ;34.3250
P8=-81.0000 ;34.1500
P9=-81.0350 ;34.0000
P10=-81.1260 ;33.7500
P11=-81.2170 ;33.5000
P12=-81.3320 ;33.2500
P13=-81.4470 ;33.0000
P14=-81.5000 ;32.9120
P15=-81.6405 ;32.7060
P16=-81.7810 ;32.5000
P17=-81.8905 ;32.3620
P18=-82.0000 ;32.2240
P19=-82.2050 ;32.0000
P20=-82.3525 ;31.8580
P21=-82.5000 ;31.7160
P22=-82.6305 ;31.6080
P23=-82.7610 ;31.5000
P24=-83.0000 ;31.3310
P25=-83.2500 ;31.1805
P26=-83.5000 ;31.0300
P27=-83.5650 ;31.0000
P28=-83.7825 ;30.9180
P29=-84.0000 ;30.8360
P30=-84.2500 ;30.7715
P31=-84.5000 ;30.7070
P32=-84.7500 ;30.6810

P33=-85.0000 ;30.6550
P34=-85.2500 ;30.6715
P35=-85.5000 ;30.6880
P36=-85.7500 ;30.7510
P37=-86.0000 ;30.8140
P38=-86.2020 ;30.9070
P39=-86.4040 ;31.0000
P40=-86.5000 ;31.0590
P41=-86.6623 ;31.2060
P42=-86.8247 ;31.3530
P43=-86.9870 ;31.5000
P44=-87.0000 ;31.5160
P45=-87.1495 ;31.7580
P46=-87.2990 ;32.0000
P47=-87.3885 ;32.2500
P48=-87.4780 ;32.5000
P49=-87.5000 ;32.6370
P50=-87.5225 ;32.8185
P51=-87.5450 ;33.0000
P52=-87.5415 ;33.2500
P53=-87.5380 ;33.5000
P54=-87.5000 ;33.7280
P55=-87.4440 ;34.0000
P56=-87.3530 ;34.2500
P57=-87.2620 ;34.5000
P58=-87.1450 ;34.7500
P59=-87.0280 ;35.0000
P60=-87.0000 ;35.0460
P61=-86.8375 ;35.2730
P62=-86.6750 ;35.5000
P63=-86.5000 ;35.7080
P64=-86.3560 ;35.8540
P65=-86.2120 ;36.0000
P66=-86.0000 ;36.1880
P67=-85.7945 ;36.3440
P68=-85.5890 ;36.5000
P69=-85.5000 ;36.5590
P70=-85.2500 ;36.6925
P71=-85.0000 ;36.8260
P72=-84.7935 ;36.9130
P73=-84.5870 ;37.0000
P74=-84.5000 ;37.0320
P75=-84.2500 ;37.0910
P76=-84.0000 ;37.1500
P77=-83.7500 ;37.1780
P78=-83.5000 ;37.2060
P79=-83.2500 ;37.1990
P80=-83.0000 ;37.1920
P81=-82.7500 ;37.1420
P82=-82.5000 ;37.0920
P83=-82.2560 ;37.0000
P84=-82.0000 ;36.8750
P85=-81.7510 ;36.6875
P86=-81.5020 ;36.5000
P87=-81.5000 ;36.4980
P88=-81.3315 ;36.2490
P89=-81.1630 ;36.0000

P90=-81.0815 ;35.7870
P91=-81.0000 ;35.5740
[C13]
gain=-10.00
n_point=104
P1=-80.5000 ;36.8030
P2=-80.3300 ;36.5000
P3=-80.2440 ;36.2500
P4=-80.1580 ;36.0000
P5=-80.1150 ;35.7500
P6=-80.0720 ;35.5000
P7=-80.0680 ;35.2500
P8=-80.0640 ;35.0000
P9=-80.0970 ;34.7500
P10=-80.1300 ;34.5000
P11=-80.1905 ;34.2500
P12=-80.2510 ;34.0000
P13=-80.3360 ;33.7500
P14=-80.4210 ;33.5000
P15=-80.5000 ;33.3150
P16=-80.6590 ;33.0000
P17=-80.8045 ;32.7500
P18=-80.9500 ;32.5000
P19=-81.0000 ;32.4240
P20=-81.1605 ;32.2120
P21=-81.3210 ;32.0000
P22=-81.5000 ;31.7830
P23=-81.6315 ;31.6415
P24=-81.7630 ;31.5000
P25=-82.0000 ;31.2770
P26=-82.1620 ;31.1385
P27=-82.3240 ;31.0000
P28=-82.5000 ;30.8700
P29=-82.7500 ;30.7030
P30=-83.0000 ;30.5360
P31=-83.0640 ;30.5000
P32=-83.2820 ;30.3960
P33=-83.5000 ;30.2920
P34=-83.7500 ;30.1930
P35=-84.0000 ;30.0940
P36=-84.3410 ;30.0000
P37=-84.5000 ;29.9660
P38=-84.7500 ;29.9370
P39=-85.0000 ;29.9080
P40=-85.2500 ;29.9100
P41=-85.5000 ;29.9120
P42=-85.7500 ;29.9455
P43=-86.0000 ;29.9790
P44=-86.0770 ;30.0000
P45=-86.2885 ;30.0755
P46=-86.5000 ;30.1510
P47=-86.7500 ;30.2815
P48=-87.0000 ;30.4120
P49=-87.1250 ;30.5000
P50=-87.3125 ;30.6715
P51=-87.5000 ;30.8430
P52=-87.6380 ;31.0000

P53=-87.8035 ;31.2500
P54=-87.9690 ;31.5000
P55=-88.0000 ;31.5650
P56=-88.0810 ;31.7825
P57=-88.1620 ;32.0000
P58=-88.2170 ;32.2500
P59=-88.2720 ;32.5000
P60=-88.2915 ;32.7500
P61=-88.3110 ;33.0000
P62=-88.2975 ;33.2500
P63=-88.2840 ;33.5000
P64=-88.2375 ;33.7500
P65=-88.1910 ;34.0000
P66=-88.1215 ;34.2500
P67=-88.0520 ;34.5000
P68=-88.0000 ;34.6410
P69=-87.9190 ;34.8205
P70=-87.8380 ;35.0000
P71=-87.6980 ;35.2500
P72=-87.5580 ;35.5000
P73=-87.5000 ;35.5900
P74=-87.3430 ;35.7950
P75=-87.1860 ;36.0000
P76=-87.0000 ;36.2210
P77=-86.7290 ;36.5000
P78=-86.5000 ;36.7120
P79=-86.3230 ;36.8560
P80=-86.1460 ;37.0000
P81=-86.0000 ;37.1030
P82=-85.7500 ;37.2585
P83=-85.5000 ;37.4140
P84=-85.3390 ;37.5000
P85=-85.0000 ;37.6510
P86=-84.7500 ;37.7435
P87=-84.5000 ;37.8360
P88=-84.2500 ;37.9075
P89=-84.0000 ;37.9790
P90=-83.8780 ;38.0000
P91=-83.5000 ;38.0530
P92=-83.2500 ;38.0620
P93=-83.0000 ;38.0710
P94=-82.7500 ;38.0535
P95=-82.5000 ;38.0360
P96=-82.3080 ;38.0000
P97=-82.0000 ;37.9220
P98=-81.7500 ;37.8150
P99=-81.5000 ;37.7080
P100=-81.1630 ;37.5000
P101=-81.0000 ;37.3740
P102=-80.8200 ;37.1870
P103=-80.6400 ;37.0000
P104=-80.5000 ;36.8030
[C14]
gain=-20.00
n_point=118
P1=-79.0000 ;36.8190
P2=-78.9410 ;36.5000

P3=-78.9100 ;36.2500
P4=-78.8790 ;36.0000
P5=-78.8825 ;35.7500
P6=-78.8860 ;35.5000
P7=-78.9010 ;35.2500
P8=-78.9160 ;35.0000
P9=-78.9540 ;34.7500
P10=-78.9920 ;34.5000
P11=-79.0000 ;34.4720
P12=-79.0845 ;34.2360
P13=-79.1690 ;34.0000
P14=-79.2585 ;33.7500
P15=-79.3480 ;33.5000
P16=-79.5000 ;33.0950
P17=-79.5470 ;33.0000
P18=-79.6995 ;32.7500
P19=-79.8520 ;32.5000
P20=-80.0000 ;32.2500
P21=-80.1790 ;32.0000
P22=-80.3395 ;31.7675
P23=-80.5000 ;31.5350
P24=-80.5290 ;31.5000
P25=-80.7535 ;31.2500
P26=-80.9780 ;31.0000
P27=-81.0000 ;30.9780
P28=-81.2485 ;30.7390
P29=-81.4970 ;30.5000
P30=-81.5000 ;30.4970
P31=-81.7500 ;30.3035
P32=-82.0000 ;30.1100
P33=-82.1440 ;30.0000
P34=-82.5000 ;29.8060
P35=-82.7365 ;29.6530
P36=-82.9730 ;29.5000
P37=-83.0000 ;29.4900
P38=-83.2500 ;29.3970
P39=-83.5000 ;29.3040
P40=-83.7500 ;29.2075
P41=-84.0000 ;29.1110
P42=-84.3580 ;29.0000
P43=-84.5000 ;28.9730
P44=-85.0000 ;28.9150
P45=-85.5000 ;28.8940
P46=-86.0000 ;28.9200
P47=-86.5000 ;28.9940
P48=-86.5230 ;29.0000
P49=-86.7615 ;29.0875
P50=-87.0000 ;29.1750
P51=-87.2500 ;29.2870
P52=-87.5000 ;29.3990
P53=-87.6710 ;29.5000
P54=-88.0000 ;29.7640
P55=-88.2540 ;30.0000
P56=-88.5000 ;30.2670
P57=-88.6620 ;30.5000
P58=-88.8170 ;30.7500
P59=-88.9720 ;31.0000

P60=-89.0000 ;31.0570
P61=-89.0680 ;31.2785
P62=-89.1360 ;31.5000
P63=-89.1990 ;31.7500
P64=-89.2620 ;32.0000
P65=-89.3020 ;32.2500
P66=-89.3420 ;32.5000
P67=-89.3475 ;32.7500
P68=-89.3530 ;33.0000
P69=-89.3275 ;33.2500
P70=-89.3020 ;33.5000
P71=-89.2550 ;33.7500
P72=-89.2080 ;34.0000
P73=-89.1480 ;34.2500
P74=-89.0880 ;34.5000
P75=-89.0000 ;34.8320
P76=-88.9290 ;35.0000
P77=-88.8010 ;35.2500
P78=-88.6730 ;35.5000
P79=-88.5000 ;35.8530
P80=-88.4040 ;36.0000
P81=-88.2300 ;36.2500
P82=-88.0560 ;36.5000
P83=-88.0000 ;36.5780
P84=-87.8150 ;36.7890
P85=-87.6300 ;37.0000
P86=-87.5000 ;37.1310
P87=-87.3035 ;37.3155
P88=-87.1070 ;37.5000
P89=-87.0000 ;37.5850
P90=-86.7500 ;37.7865
P91=-86.5000 ;37.9880
P92=-86.4840 ;38.0000
P93=-86.2420 ;38.1385
P94=-86.0000 ;38.2770
P95=-85.6340 ;38.5000
P96=-85.5000 ;38.5570
P97=-85.0000 ;38.7680
P98=-84.5000 ;38.9770
P99=-84.4300 ;39.0000
P100=-84.0000 ;39.0890
P101=-83.5000 ;39.1740
P102=-83.0000 ;39.2240
P103=-82.5000 ;39.2300
P104=-82.0000 ;39.1890
P105=-81.5000 ;39.0990
P106=-81.1100 ;39.0000
P107=-81.0000 ;38.9580
P108=-80.7500 ;38.8305
P109=-80.5000 ;38.7030
P110=-80.1500 ;38.5000
P111=-80.0000 ;38.3720
P112=-79.8185 ;38.1860
P113=-79.6370 ;38.0000
P114=-79.5000 ;37.8210
P115=-79.3250 ;37.5000
P116=-79.1900 ;37.2500

P117=-79.0550 ;37.0000
P118=-79.0000 ;36.8190
[C15]
gain=-30.00
n_point=146
P1=-78.0000 ;38.2340
P2=-78.1380 ;38.5000
P3=-78.3190 ;38.7170
P4=-78.5000 ;38.9340
P5=-78.5420 ;39.0000
P6=-78.7710 ;39.2310
P7=-79.0000 ;39.4620
P8=-79.0780 ;39.5000
P9=-79.5000 ;39.8220
P10=-79.8670 ;40.0000
P11=-80.0000 ;40.0810
P12=-80.5000 ;40.2460
P13=-81.0000 ;40.2760
P14=-81.5000 ;40.3870
P15=-82.0000 ;40.4360
P16=-82.5000 ;40.4330
P17=-83.0000 ;40.4080
P18=-83.5000 ;40.3810
P19=-84.0000 ;40.3090
P20=-84.5000 ;40.1590
P21=-84.8280 ;40.0000
P22=-85.0000 ;39.9550
P23=-85.5000 ;39.7930
P24=-86.0000 ;39.5320
P25=-86.0450 ;39.5000
P26=-86.5000 ;39.2540
P27=-86.8870 ;39.0000
P28=-87.0000 ;38.9290
P29=-87.2500 ;38.7775
P30=-87.5000 ;38.6260
P31=-87.6390 ;38.5000
P32=-88.0000 ;38.1940
P33=-88.1950 ;38.0000
P34=-88.5000 ;37.6420
P35=-88.6310 ;37.5000
P36=-88.7840 ;37.2500
P37=-88.9370 ;37.0000
P38=-89.0000 ;36.9590
P39=-89.1775 ;36.7295
P40=-89.3550 ;36.5000
P41=-89.5000 ;36.2420
P42=-89.6780 ;36.0000
P43=-89.7715 ;35.7500
P44=-89.8650 ;35.5000
P45=-90.0000 ;35.1140
P46=-90.0630 ;35.0000
P47=-90.1760 ;34.7500
P48=-90.2890 ;34.5000
P49=-90.3365 ;34.2500
P50=-90.3840 ;34.0000
P51=-90.3855 ;33.7500
P52=-90.3870 ;33.5000

P53=-90.3695 ;33.2500
P54=-90.3520 ;33.0000
P55=-90.3395 ;32.7500
P56=-90.3270 ;32.5000
P57=-90.3435 ;32.2500
P58=-90.3600 ;32.0000
P59=-90.3170 ;31.7500
P60=-90.2740 ;31.5000
P61=-90.1655 ;31.2500
P62=-90.0570 ;31.0000
P63=-90.0000 ;30.8850
P64=-89.8150 ;31.0000
P65=-89.7745 ;31.2500
P66=-89.7340 ;31.5000
P67=-89.7455 ;31.7500
P68=-89.7570 ;32.0000
P69=-89.8120 ;32.2500
P70=-89.8670 ;32.5000
P71=-89.8435 ;32.7500
P72=-89.8200 ;33.0000
P73=-89.7670 ;33.2500
P74=-89.7140 ;33.5000
P75=-89.6815 ;33.7500
P76=-89.6490 ;34.0000
P77=-89.6340 ;34.2500
P78=-89.6190 ;34.5000
P79=-89.5000 ;34.6940
P80=-89.3640 ;35.0000
P81=-89.2765 ;35.2500
P82=-89.1890 ;35.5000
P83=-89.0000 ;35.8650
P84=-88.9130 ;36.0000
P85=-88.7725 ;36.2500
P86=-88.6320 ;36.5000
P87=-88.5000 ;36.6850
P88=-88.2540 ;37.0000
P89=-88.0000 ;37.2450
P90=-87.7460 ;37.5000
P91=-87.5000 ;37.7010
P92=-87.1620 ;38.0000
P93=-87.0000 ;38.1660
P94=-86.7500 ;38.3310
P95=-86.5000 ;38.4960
P96=-86.4950 ;38.5000
P97=-86.0000 ;38.6750
P98=-85.7820 ;38.8375
P99=-85.5640 ;39.0000
P100=-85.5000 ;39.1250
P101=-85.0000 ;39.1710
P102=-84.5000 ;39.4320
P103=-84.3300 ;39.5000
P104=-84.0000 ;39.6560
P105=-83.5000 ;39.6830
P106=-83.0000 ;39.7110
P107=-82.5000 ;39.7350
P108=-82.0000 ;39.7440
P109=-81.5000 ;39.7500

P110=-81.0000 ;39.6590
P111=-80.8210 ;39.5000
P112=-80.5000 ;39.3690
P113=-80.0000 ;39.1490
P114=-79.8320 ;39.0000
P115=-79.5000 ;38.7480
P116=-79.3890 ;38.5000
P117=-79.1945 ;38.2750
P118=-79.0000 ;38.0500
P119=-78.9290 ;38.0000
P120=-78.8110 ;37.7500
P121=-78.6930 ;37.5000
P122=-78.5000 ;37.1160
P123=-78.3830 ;37.0000
P124=-78.3380 ;36.7500
P125=-78.2930 ;36.5000
P126=-78.2350 ;36.2500
P127=-78.1770 ;36.0000
P128=-78.1595 ;35.7500
P129=-78.1420 ;35.5000
P130=-78.1505 ;35.2500
P131=-78.1590 ;35.0000
P132=-78.0000 ;34.7130
P133=-77.8810 ;35.0000
P134=-77.8725 ;35.2500
P135=-77.8640 ;35.5000
P136=-77.8175 ;35.7500
P137=-77.7710 ;36.0000
P138=-77.7295 ;36.2500
P139=-77.6880 ;36.5000
P140=-77.6965 ;36.7500
P141=-77.7050 ;37.0000
P142=-77.7175 ;37.2500
P143=-77.7300 ;37.5000
P144=-77.7855 ;37.7500
P145=-77.8410 ;38.0000
P146=-78.0000 ;38.2340
[C16]
gain=-30.00
n_point=78
P1=-81.5000 ;29.8430
P2=-81.6250 ;29.7862
P3=-81.7500 ;29.7295
P4=-81.8750 ;29.6727
P5=-82.0000 ;29.6160
P6=-82.0870 ;29.5580
P7=-82.1740 ;29.5000
P8=-82.2827 ;29.4293
P9=-82.3913 ;29.3587
P10=-82.5000 ;29.2880
P11=-82.6250 ;29.2473
P12=-82.7500 ;29.2065
P13=-82.8750 ;29.1657
P14=-83.0000 ;29.1250
P15=-83.1020 ;29.0625
P16=-83.2040 ;29.0000
P17=-83.3520 ;28.9405

P18=-83.5000 ;28.8810
P19=-83.6250 ;28.8335
P20=-83.7500 ;28.7860
P21=-83.8750 ;28.7385
P22=-84.0000 ;28.6910
P23=-84.1250 ;28.6465
P24=-84.2500 ;28.6020
P25=-84.3750 ;28.5575
P26=-84.5000 ;28.5130
P27=-84.5550 ;28.5000
P28=-84.6663 ;28.4298
P29=-84.7775 ;28.3595
P30=-84.8887 ;28.2892
P31=-85.0000 ;28.2190
P32=-85.1667 ;28.1950
P33=-85.3333 ;28.1710
P34=-85.5000 ;28.1470
P35=-85.6667 ;28.1100
P36=-85.8333 ;28.0730
P37=-86.0000 ;28.0360
P38=-86.0680 ;28.0000
P39=-86.0000 ;27.9840
P40=-85.8333 ;27.9607
P41=-85.6667 ;27.9373
P42=-85.5000 ;27.9140
P43=-85.3333 ;27.9070
P44=-85.1667 ;27.9000
P45=-85.0000 ;27.8930
P46=-84.8333 ;27.9157
P47=-84.6667 ;27.9383
P48=-84.5000 ;27.9610
P49=-84.3820 ;28.0000
P50=-84.2547 ;28.0440
P51=-84.1273 ;28.0880
P52=-84.0000 ;28.1320
P53=-83.8333 ;28.1237
P54=-83.6667 ;28.1153
P55=-83.5000 ;28.1070
P56=-83.3750 ;28.1815
P57=-83.2500 ;28.2560
P58=-83.1250 ;28.3305
P59=-83.0000 ;28.4050
P60=-82.9310 ;28.4525
P61=-82.8620 ;28.5000
P62=-82.7413 ;28.5610
P63=-82.6207 ;28.6220
P64=-82.5000 ;28.6830
P65=-82.3835 ;28.7623
P66=-82.2670 ;28.8415
P67=-82.1505 ;28.9207
P68=-82.0340 ;29.0000
P69=-82.0000 ;29.0780
P70=-81.8750 ;29.1457
P71=-81.7500 ;29.2135
P72=-81.6250 ;29.2813
P73=-81.5000 ;29.3490
P74=-81.4140 ;29.4245

P75=-81.3280 ;29.5000
P76=-81.3853 ;29.6143
P77=-81.4427 ;29.7287
P78=-81.5000 ;29.8430
[C17]
gain=-40.00
n_point=71
P1=-81.0000 ;26.2420
P2=-81.0625 ;26.2237
P3=-81.1250 ;26.2055
P4=-81.1875 ;26.1873
P5=-81.2500 ;26.1690
P6=-81.3125 ;26.1508
P7=-81.3750 ;26.1325
P8=-81.4375 ;26.1143
P9=-81.5000 ;26.0960
P10=-81.5493 ;26.0640
P11=-81.5987 ;26.0320
P12=-81.6480 ;26.0000
P13=-81.7067 ;25.9647
P14=-81.7653 ;25.9293
P15=-81.8240 ;25.8940
P16=-81.8827 ;25.8587
P17=-81.9413 ;25.8233
P18=-82.0000 ;25.7880
P19=-82.0625 ;25.7635
P20=-82.1250 ;25.7390
P21=-82.1875 ;25.7145
P22=-82.2500 ;25.6900
P23=-82.3125 ;25.6655
P24=-82.3750 ;25.6410
P25=-82.4375 ;25.6165
P26=-82.5000 ;25.5920
P27=-82.5517 ;25.5613
P28=-82.6033 ;25.5307
P29=-82.6550 ;25.5000
P30=-82.6162 ;25.4478
P31=-82.5775 ;25.3955
P32=-82.5387 ;25.3433
P33=-82.5000 ;25.2910
P34=-82.4375 ;25.2857
P35=-82.3750 ;25.2805
P36=-82.3125 ;25.2752
P37=-82.2500 ;25.2700
P38=-82.1875 ;25.2647
P39=-82.1250 ;25.2595
P40=-82.0625 ;25.2542
P41=-82.0000 ;25.2490
P42=-81.9520 ;25.2849
P43=-81.9040 ;25.3207
P44=-81.8560 ;25.3566
P45=-81.8080 ;25.3924
P46=-81.7600 ;25.4283
P47=-81.7120 ;25.4641
P48=-81.6640 ;25.5000
P49=-81.6367 ;25.5510
P50=-81.6093 ;25.6020

P51=-81.5820 ;25.6530
P52=-81.5547 ;25.7040
P53=-81.5273 ;25.7550
P54=-81.5000 ;25.8060
P55=-81.4375 ;25.8135
P56=-81.3750 ;25.8210
P57=-81.3125 ;25.8285
P58=-81.2500 ;25.8360
P59=-81.1875 ;25.8435
P60=-81.1250 ;25.8510
P61=-81.0625 ;25.8585
P62=-81.0000 ;25.8660
P63=-80.9557 ;25.8995
P64=-80.9115 ;25.9330
P65=-80.8673 ;25.9665
P66=-80.8230 ;26.0000
P67=-80.8584 ;26.0484
P68=-80.8938 ;26.0968
P69=-80.9292 ;26.1452
P70=-80.9646 ;26.1936
P71=-81.0000 ;26.2420
[C18]
gain=-50.00
n_point=192
P1=-46.1594 ;74.7910
P2=-46.1685 ;74.7894
P3=-47.9723 ;74.4540
P4=-49.7745 ;74.1102
P5=-51.5749 ;73.7579
P6=-53.3732 ;73.3948
P7=-55.1647 ;73.0024
P8=-56.9505 ;72.5854
P9=-58.7375 ;72.1735
P10=-60.5203 ;71.7431
P11=-62.2817 ;71.2196
P12=-64.0433 ;70.7054
P13=-65.8406 ;70.3706
P14=-67.6323 ;70.0211
P15=-69.3912 ;69.5298
P16=-71.1358 ;68.9726
P17=-72.8791 ;68.4025
P18=-74.6319 ;67.8685
P19=-76.3907 ;67.3623
P20=-78.1234 ;66.7758
P21=-79.8389 ;66.1390
P22=-81.5548 ;65.5106
P23=-83.2587 ;64.8423
P24=-84.9532 ;64.1514
P25=-86.6388 ;63.4470
P26=-88.3002 ;62.6749
P27=-89.9472 ;61.8717
P28=-91.5315 ;60.9566
P29=-93.0491 ;59.9348
P30=-94.5102 ;58.8347
P31=-95.2060 ;58.2405
P32=-95.9019 ;57.6463
P33=-96.5664 ;57.0164

P34=-97.2309 ;56.3865
P35=-97.8818 ;55.7406
P36=-98.5327 ;55.0947
P37=-99.1211 ;54.3912
P38=-99.7095 ;53.6878
P39=-100.2543;52.9518
P40=-100.7991;52.2159
P41=-101.3136;51.4559
P42=-101.8282;50.6960
P43=-102.3071;49.9180
P44=-102.7860;49.1399
P45=-103.1947;48.3188
P46=-103.6035;47.4977
P47=-104.0008;46.6735
P48=-104.3982;45.8492
P49=-104.7234;44.9899
P50=-105.0487;44.1307
P51=-105.3196;43.2601
P52=-105.5905;42.3895
P53=-105.7995;41.4998
P54=-106.0085;40.6101
P55=-106.1394;39.7095
P56=-106.2703;38.8090
P57=-106.3034;37.8963
P58=-106.3365;36.9836
P59=-106.3303;36.0629
P60=-106.3240;35.1423
P61=-106.2076;34.2380
P62=-106.0911;33.3337
P63=-105.9116;32.4364
P64=-105.7320;31.5391
P65=-105.6384;30.6350
P66=-105.5449;29.7308
P67=-105.3418;28.8615
P68=-105.1387;27.9921
P69=-104.9147;27.1218
P70=-104.6907;26.2516
P71=-104.2832;25.4315
P72=-103.8757;24.6113
P73=-103.4269;23.8168
P74=-102.9781;23.0222
P75=-102.4952;22.2543
P76=-102.0123;21.4865
P77=-101.4820;20.7483
P78=-100.9517;20.0101
P79=-100.3390;19.3306
P80=-99.7264 ;18.6512
P81=-99.0229 ;18.0627
P82=-98.3194 ;17.4742
P83=-97.5924 ;16.9237
P84=-96.8654 ;16.3731
P85=-96.0927 ;15.9061
P86=-95.3200 ;15.4391
P87=-94.4906 ;15.0666
P88=-93.6613 ;14.6942
P89=-92.7948 ;14.4548
P90=-91.9284 ;14.2154

P91=-91.0094 ;14.0286
P92=-90.0905 ;13.8418
P93=-89.2466 ;13.8165
P94=-88.4028 ;13.7912
P95=-87.3632 ;13.8454
P96=-86.3237 ;13.8995
P97=-85.3316 ;14.0092
P98=-86.0672 ;14.0441
P99=-86.8028 ;14.0791
P100=-87.8061 ;14.0952
P101=-88.8095 ;14.1113
P102=-89.6713 ;14.2580
P103=-90.5331 ;14.4046
P104=-91.4340 ;14.5926
P105=-92.3349 ;14.7806
P106=-93.1661 ;15.0523
P107=-93.9972 ;15.3240
P108=-94.8094 ;15.7451
P109=-95.6217 ;16.1661
P110=-96.3717 ;16.6797
P111=-97.1216 ;17.1933
P112=-97.8466 ;17.7485
P113=-98.5716 ;18.3036
P114=-99.2380 ;18.9327
P115=-99.9044 ;19.5618
P116=-100.4959;20.2558
P117=-101.0875;20.9497
P118=-101.5846;21.7094
P119=-102.0818;22.4690
P120=-102.5450;23.2549
P121=-103.0083;24.0407
P122=-103.4348;24.8395
P123=-103.8613;25.6383
P124=-104.1815;26.4914
P125=-104.5016;27.3444
P126=-104.7410;28.2180
P127=-104.9803;29.0917
P128=-105.1247;29.9966
P129=-105.2691;30.9016
P130=-105.3287;31.8145
P131=-105.3883;32.7274
P132=-105.4664;33.6422
P133=-105.5444;34.5571
P134=-105.5823;35.4732
P135=-105.6201;36.3893
P136=-105.6188;37.3059
P137=-105.6174;38.2226
P138=-105.4779;39.1273
P139=-105.3384;40.0319
P140=-105.1626;40.9245
P141=-104.9868;41.8171
P142=-104.7307;42.6955
P143=-104.4747;43.5739
P144=-104.1604;44.4338
P145=-103.8461;45.2937
P146=-103.4616;46.1193
P147=-103.0770;46.9448

P148=-102.6482;47.7528
P149=-102.2194;48.5609
P150=-101.7522;49.3491
P151=-101.2850;50.1372
P152=-100.7582;50.8883
P153=-100.2314;51.6393
P154=-99.6548 ;52.3523
P155=-99.0782 ;53.0654
P156=-98.4656 ;53.7487
P157=-97.8530 ;54.4320
P158=-97.1995 ;55.0748
P159=-96.5460 ;55.7175
P160=-95.8533 ;56.3172
P161=-95.1606 ;56.9169
P162=-94.4365 ;57.4753
P163=-93.7123 ;58.0336
P164=-92.1993 ;59.0648
P165=-90.6581 ;60.0451
P166=-89.0357 ;60.8859
P167=-87.3746 ;61.6478
P168=-85.6894 ;62.3619
P169=-83.9875 ;63.0365
P170=-82.2760 ;63.6830
P171=-80.5658 ;64.3387
P172=-78.8507 ;64.9752
P173=-77.1272 ;65.5837
P174=-75.3994 ;66.2046
P175=-73.6614 ;66.7729
P176=-71.9093 ;67.2516
P177=-70.1510 ;67.7374
P178=-68.3912 ;68.2512
P179=-66.6445 ;68.8191
P180=-64.8928 ;69.3610
P181=-63.0938 ;69.6969
P182=-61.2803 ;69.9747
P183=-59.4852 ;70.3418
P184=-57.6973 ;70.7476
P185=-55.9063 ;71.1451
P186=-54.1123 ;71.5295
P187=-52.3153 ;71.8993
P188=-50.5156 ;72.2559
P189=-48.7132 ;72.6005
P190=-46.9092 ;72.9359
P191=-45.1038 ;73.2630
P192=-43.3058 ;73.5804
[C19]
gain=-8.00
n_point=98
P1=-83.7697 ;37.5945
P2=-84.0040 ;37.5477
P3=-84.2382 ;37.5008
P4=-84.3880 ;37.4613
P5=-84.6026 ;37.3863
P6=-84.8172 ;37.3113
P7=-85.1304 ;37.1780
P8=-85.4464 ;36.9992
P9=-85.7624 ;36.8203

P10=-85.8916 ;36.7289
P11=-86.0131 ;36.6363
P12=-86.2798 ;36.4039
P13=-86.5465 ;36.1714
P14=-86.6837 ;36.0253
P15=-86.8210 ;35.8793
P16=-86.9304 ;35.7417
P17=-87.0398 ;35.6042
P18=-87.1007 ;35.5223
P19=-87.2190 ;35.3567
P20=-87.3269 ;35.1587
P21=-87.4348 ;34.9607
P22=-87.5427 ;34.7626
P23=-87.6392 ;34.5484
P24=-87.6960 ;34.3770
P25=-87.7529 ;34.2055
P26=-87.7984 ;34.0365
P27=-87.8439 ;33.8674
P28=-87.8776 ;33.6726
P29=-87.9113 ;33.4777
P30=-87.9194 ;33.2808
P31=-87.9274 ;33.0839
P32=-87.9165 ;32.9107
P33=-87.9055 ;32.7375
P34=-87.8784 ;32.5656
P35=-87.8514 ;32.3938
P36=-87.7999 ;32.1913
P37=-87.7106 ;31.9589
P38=-87.6214 ;31.7266
P39=-87.4551 ;31.4675
P40=-87.3428 ;31.2924
P41=-87.1370 ;31.0886
P42=-86.9312 ;30.8849
P43=-86.7269 ;30.7495
P44=-86.5226 ;30.6140
P45=-86.2030 ;30.4646
P46=-85.8710 ;30.3858
P47=-85.5391 ;30.3071
P48=-85.3501 ;30.2900
P49=-85.1679 ;30.2838
P50=-84.8011 ;30.3177
P51=-84.4342 ;30.3515
P52=-84.1269 ;30.4303
P53=-83.8428 ;30.5330
P54=-83.5586 ;30.6358
P55=-83.3596 ;30.7364
P56=-83.1606 ;30.8370
P57=-82.9989 ;30.9395
P58=-82.8371 ;31.0421
P59=-82.7812 ;31.0804
P60=-82.5804 ;31.2416
P61=-82.3796 ;31.4028
P62=-82.1788 ;31.5640
P63=-82.0116 ;31.7403
P64=-81.8443 ;31.9166
P65=-81.6771 ;32.0928
P66=-81.5860 ;32.2059

P67=-81.4158 ;32.4331
P68=-81.2580 ;32.6779
P69=-81.1002 ;32.9227
P70=-80.9949 ;33.1251
P71=-80.9123 ;33.3017
P72=-80.8297 ;33.4784
P73=-80.7254 ;33.7666
P74=-80.6641 ;33.9698
P75=-80.6027 ;34.1730
P76=-80.5600 ;34.4016
P77=-80.5172 ;34.6303
P78=-80.5043 ;34.7868
P79=-80.5032 ;35.0131
P80=-80.5022 ;35.2394
P81=-80.5392 ;35.5457
P82=-80.6140 ;35.7884
P83=-80.6888 ;36.0311
P84=-80.7637 ;36.2737
P85=-80.7852 ;36.3088
P86=-80.9417 ;36.5130
P87=-81.0982 ;36.7171
P88=-81.2547 ;36.9212
P89=-81.5497 ;37.1271
P90=-81.8448 ;37.3329
P91=-81.9555 ;37.3833
P92=-82.2448 ;37.5020
P93=-82.6148 ;37.5637
P94=-82.9848 ;37.6254
P95=-83.0759 ;37.6301
P96=-83.1635 ;37.6330
P97=-83.4666 ;37.6138
P98=-83.7697 ;37.5945
[C20]
gain=-15.00
n_point=107
P1=-83.1677 ;38.6372
P2=-83.5932 ;38.5811
P3=-84.0188 ;38.5249
P4=-84.2224 ;38.4760
P5=-84.4987 ;38.3850
P6=-84.7749 ;38.2940
P7=-84.9437 ;38.2269
P8=-85.2719 ;38.0794
P9=-85.6001 ;37.9319
P10=-85.7673 ;37.8321
P11=-85.9641 ;37.7144
P12=-86.2331 ;37.5308
P13=-86.5020 ;37.3472
P14=-86.7637 ;37.1220
P15=-87.0254 ;36.8968
P16=-87.1465 ;36.7805
P17=-87.2313 ;36.6944
P18=-87.4081 ;36.4956
P19=-87.5849 ;36.2967
P20=-87.7072 ;36.1310
P21=-87.8758 ;35.8892
P22=-88.0443 ;35.6475

P23=-88.1746 ;35.3976
P24=-88.2975 ;35.1307
P25=-88.4204 ;34.8637
P26=-88.5433 ;34.5968
P27=-88.5630 ;34.5284
P28=-88.6330 ;34.2232
P29=-88.7030 ;33.9180
P30=-88.7730 ;33.6128
P31=-88.7901 ;33.5126
P32=-88.8032 ;33.4033
P33=-88.8010 ;33.0865
P34=-88.7987 ;32.7697
P35=-88.7964 ;32.4528
P36=-88.7918 ;32.4151
P37=-88.7821 ;32.3364
P38=-88.6871 ;31.9542
P39=-88.5920 ;31.5720
P40=-88.5116 ;31.3370
P41=-88.3693 ;31.0990
P42=-88.2269 ;30.8610
P43=-87.9933 ;30.5851
P44=-87.7596 ;30.3091
P45=-87.7160 ;30.2688
P46=-87.6680 ;30.2245
P47=-87.3579 ;30.0133
P48=-87.0477 ;29.8020
P49=-86.8362 ;29.7084
P50=-86.6246 ;29.6148
P51=-86.2033 ;29.4773
P52=-85.8400 ;29.4258
P53=-85.4473 ;29.4021
P54=-85.0301 ;29.4103
P55=-84.7134 ;29.4429
P56=-84.4735 ;29.4878
P57=-84.2335 ;29.5326
P58=-84.0156 ;29.6063
P59=-83.7976 ;29.6800
P60=-83.3988 ;29.8485
P61=-83.0001 ;30.0170
P62=-82.8626 ;30.0974
P63=-82.5644 ;30.2869
P64=-82.2661 ;30.4763
P65=-81.9471 ;30.7394
P66=-81.6281 ;31.0026
P67=-81.5693 ;31.0585
P68=-81.3051 ;31.3371
P69=-81.0410 ;31.6157
P70=-80.8787 ;31.8256
P71=-80.7165 ;32.0354
P72=-80.5275 ;32.3013
P73=-80.3798 ;32.5491
P74=-80.2322 ;32.7969
P75=-80.0845 ;33.0447
P76=-80.0653 ;33.0788
P77=-79.9538 ;33.3674
P78=-79.8423 ;33.6560
P79=-79.7308 ;33.9446

P80=-79.6769 ;34.1124
P81=-79.6131 ;34.3210
P82=-79.5570 ;34.6420
P83=-79.5009 ;34.9631
P84=-79.4838 ;35.1706
P85=-79.4797 ;35.3354
P86=-79.5047 ;35.7103
P87=-79.5296 ;36.0852
P88=-79.5480 ;36.2107
P89=-79.5545 ;36.2479
P90=-79.5704 ;36.3227
P91=-79.6907 ;36.6389
P92=-79.8110 ;36.9551
P93=-79.9259 ;37.1547
P94=-80.0408 ;37.3543
P95=-80.2387 ;37.5940
P96=-80.4637 ;37.8256
P97=-80.6598 ;37.9683
P98=-80.8558 ;38.1110
P99=-81.1893 ;38.2741
P100=-81.5227 ;38.4371
P101=-81.6295 ;38.4720
P102=-81.6899 ;38.4901
P103=-82.0104 ;38.5636
P104=-82.4372 ;38.6043
P105=-82.8640 ;38.6450
P106=-82.9210 ;38.6437
P107=-83.1677 ;38.6372