

```
[FormatInfo]
format_ver=1
[GeoMain]
ntc_id=910100000
adm=USA
sat_name=USABSS-21
long_nom=-101.0000
n_diag=1
[COHeader]
beam_id=BB24
emi_rcp=E
polar_disc=C
reason=B
n_bore=1
n_cont=24
[B1]
gain=0.00
p=-89.9320;34.5820
[C1]
gain=-40.00
n_point=333
P1=-67.0000 ;54.3340
P2=-66.9350 ;54.0000
P3=-66.8770 ;53.5000
P4=-66.8130 ;53.0000
P5=-66.7360 ;52.5000
P6=-66.6830 ;52.0000
P7=-66.7050 ;51.5000
P8=-66.7400 ;51.0000
P9=-66.7590 ;50.5000
P10=-66.7540 ;50.0000
P11=-66.7600 ;49.5000
P12=-66.7690 ;49.0000
P13=-66.7710 ;48.5000
P14=-66.7700 ;48.0000
P15=-66.8020 ;47.5000
P16=-66.8590 ;47.0000
P17=-66.9060 ;46.5000
P18=-66.9480 ;46.0000
P19=-67.0000 ;45.6220
P20=-67.0220 ;45.5000
P21=-67.1760 ;45.0000
P22=-67.3090 ;44.5000
P23=-67.4220 ;44.0000
P24=-67.5000 ;43.7430
P25=-67.5950 ;43.5000
P26=-67.7980 ;43.0000
P27=-67.9410 ;42.5000
P28=-68.0000 ;42.3460
P29=-68.1500 ;42.0000
P30=-68.3770 ;41.5000
P31=-68.5000 ;41.1190
P32=-68.5550 ;41.0000
P33=-68.7850 ;40.5000
P34=-68.9740 ;40.0000
P35=-69.0000 ;39.9250
P36=-69.1910 ;39.5000
```

P37=-69.4230 ;39.0000
P38=-69.5000 ;38.7440
P39=-69.6280 ;38.5000
P40=-69.8230 ;38.0000
P41=-69.9930 ;37.5000
P42=-70.0000 ;37.4760
P43=-70.1920 ;37.0000
P44=-70.4380 ;36.5000
P45=-70.5000 ;36.1160
P46=-70.5470 ;36.0000
P47=-70.8420 ;35.5000
P48=-70.9580 ;35.0000
P49=-71.0000 ;34.9130
P50=-71.2550 ;34.5000
P51=-71.4180 ;34.0000
P52=-71.5000 ;33.8240
P53=-71.7030 ;33.5000
P54=-71.9190 ;33.0000
P55=-72.0000 ;32.8260
P56=-72.2100 ;32.5000
P57=-72.4600 ;32.0000
P58=-72.5000 ;31.8840
P59=-72.7440 ;31.5000
P60=-73.0000 ;31.0480
P61=-73.0340 ;31.0000
P62=-73.4000 ;30.5000
P63=-73.5000 ;30.2660
P64=-73.6910 ;30.0000
P65=-74.0000 ;29.5230
P66=-74.0170 ;29.5000
P67=-74.4560 ;29.0000
P68=-74.5000 ;28.8830
P69=-74.8200 ;28.5000
P70=-75.0000 ;28.2180
P71=-75.1860 ;28.0000
P72=-75.5000 ;27.5490
P73=-75.5420 ;27.5000
P74=-75.9670 ;27.0000
P75=-76.0000 ;26.9610
P76=-76.4240 ;26.5000
P77=-76.5000 ;26.4350
P78=-76.9160 ;26.0000
P79=-77.0000 ;25.8920
P80=-77.3900 ;25.5000
P81=-77.5000 ;25.4030
P82=-77.9050 ;25.0000
P83=-78.0000 ;24.8900
P84=-78.4150 ;24.5000
P85=-78.5000 ;24.4250
P86=-78.9540 ;24.0000
P87=-79.0000 ;23.9750
P88=-79.5000 ;23.5490
P89=-79.5570 ;23.5000
P90=-80.0000 ;23.1690
P91=-80.2010 ;23.0000
P92=-80.5000 ;22.8160
P93=-80.8840 ;22.5000

P94=-81.0000 ;22.4110
P95=-81.5000 ;22.0220
P96=-81.5300 ;22.0000
P97=-82.0000 ;21.7420
P98=-82.3350 ;21.5000
P99=-82.5000 ;21.4060
P100=-83.0000 ;21.0950
P101=-83.1490 ;21.0000
P102=-83.5000 ;20.8500
P103=-84.0000 ;20.5610
P104=-84.1090 ;20.5000
P105=-84.5000 ;20.3520
P106=-85.0000 ;20.1140
P107=-85.2390 ;20.0000
P108=-85.5000 ;19.9350
P109=-86.0000 ;19.7780
P110=-86.5000 ;19.5870
P111=-86.7230 ;19.5000
P112=-87.0000 ;19.4400
P113=-87.5000 ;19.3180
P114=-88.0000 ;19.1690
P115=-88.4820 ;19.0000
P116=-88.5000 ;18.9980
P117=-89.0000 ;18.9310
P118=-89.5000 ;18.8340
P119=-90.0000 ;18.7230
P120=-90.5000 ;18.6030
P121=-90.9500 ;18.5000
P122=-91.0000 ;18.4950
P123=-91.5000 ;18.4570
P124=-92.0000 ;18.4250
P125=-92.5000 ;18.4120
P126=-93.0000 ;18.4230
P127=-93.5000 ;18.4550
P128=-93.9890 ;18.5000
P129=-94.0000 ;18.5020
P130=-94.5000 ;18.6460
P131=-95.0000 ;18.7950
P132=-95.5000 ;18.9320
P133=-95.8330 ;19.0000
P134=-96.0000 ;19.0690
P135=-96.5000 ;19.2710
P136=-97.0000 ;19.4290
P137=-97.3190 ;19.5000
P138=-97.5000 ;19.5820
P139=-98.0000 ;19.8100
P140=-98.5000 ;19.9860
P141=-98.5390 ;20.0000
P142=-99.0000 ;20.2720
P143=-99.5000 ;20.4820
P144=-99.5330 ;20.5000
P145=-100.0000;20.8400
P146=-100.2560;21.0000
P147=-100.5000;21.2000
P148=-100.8950;21.5000
P149=-101.0000;21.5920
P150=-101.4510;22.0000

P151=-101.5000;22.0510
P152=-101.8980;22.5000
P153=-102.0000;22.6060
P154=-102.3690;23.0000
P155=-102.5000;23.1430
P156=-102.7820;23.5000
P157=-103.0000;23.7480
P158=-103.2120;24.0000
P159=-103.5000;24.3280
P160=-103.6390;24.5000
P161=-104.0000;24.9440
P162=-104.0470;25.0000
P163=-104.4070;25.5000
P164=-104.5000;25.6210
P165=-104.7320;26.0000
P166=-105.0000;26.4140
P167=-105.0610;26.5000
P168=-105.3100;27.0000
P169=-105.5000;27.3380
P170=-105.6040;27.5000
P171=-105.7740;28.0000
P172=-105.9600;28.5000
P173=-106.0000;28.5970
P174=-106.1420;29.0000
P175=-106.2630;29.5000
P176=-106.3990;30.0000
P177=-106.5000;30.3410
P178=-106.5450;30.5000
P179=-106.6410;31.0000
P180=-106.7300;31.5000
P181=-106.8260;32.0000
P182=-106.9310;32.5000
P183=-107.0000;32.8230
P184=-107.0320;33.0000
P185=-107.1020;33.5000
P186=-107.1640;34.0000
P187=-107.2230;34.5000
P188=-107.2780;35.0000
P189=-107.3280;35.5000
P190=-107.3750;36.0000
P191=-107.4090;36.5000
P192=-107.4150;37.0000
P193=-107.4090;37.5000
P194=-107.3910;38.0000
P195=-107.3630;38.5000
P196=-107.3230;39.0000
P197=-107.2700;39.5000
P198=-107.2020;40.0000
P199=-107.1200;40.5000
P200=-107.0430;41.0000
P201=-107.0000;41.2640
P202=-106.9370;41.5000
P203=-106.7970;42.0000
P204=-106.6650;42.5000
P205=-106.5320;43.0000
P206=-106.5000;43.1270
P207=-106.3490;43.5000

P208=-106.1640;44.0000
P209=-106.0240;44.5000
P210=-106.0000;44.5790
P211=-105.8000;45.0000
P212=-105.5750;45.5000
P213=-105.5000;45.7000
P214=-105.3350;46.0000
P215=-105.0920;46.5000
P216=-105.0000;46.7310
P217=-104.8420;47.0000
P218=-104.5780;47.5000
P219=-104.5000;47.6690
P220=-104.2690;48.0000
P221=-104.0000;48.4640
P222=-103.9740;48.5000
P223=-103.6150;49.0000
P224=-103.5000;49.1940
P225=-103.2700;49.5000
P226=-103.0000;49.9140
P227=-102.9320;50.0000
P228=-102.5400;50.5000
P229=-102.5000;50.5610
P230=-102.1200;51.0000
P231=-102.0000;51.1620
P232=-101.6910;51.5000
P233=-101.5000;51.7120
P234=-101.2160;52.0000
P235=-101.0000;52.2270
P236=-100.7210;52.5000
P237=-100.5000;52.7160
P238=-100.1970;53.0000
P239=-100.0000;53.1800
P240=-99.6430 ;53.5000
P241=-99.5000 ;53.6300
P242=-99.0720 ;54.0000
P243=-99.0000 ;54.0500
P244=-98.5000 ;54.3970
P245=-98.3530 ;54.5000
P246=-98.0000 ;54.7200
P247=-97.5920 ;55.0000
P248=-97.5000 ;55.0570
P249=-97.0000 ;55.3690
P250=-96.7950 ;55.5000
P251=-96.5000 ;55.6750
P252=-96.0000 ;55.9870
P253=-95.9780 ;56.0000
P254=-95.5000 ;56.2090
P255=-95.0000 ;56.4570
P256=-94.9120 ;56.5000
P257=-94.5000 ;56.6650
P258=-94.0000 ;56.8920
P259=-93.7670 ;57.0000
P260=-93.5000 ;57.1090
P261=-93.0000 ;57.3150
P262=-92.5700 ;57.5000
P263=-92.5000 ;57.5200
P264=-92.0000 ;57.6710

P265=-91.5000 ;57.8440
P266=-91.0890 ;58.0000
P267=-91.0000 ;58.0280
P268=-90.5000 ;58.1850
P269=-90.0000 ;58.3660
P270=-89.6590 ;58.5000
P271=-89.5000 ;58.5460
P272=-89.0000 ;58.6950
P273=-88.5000 ;58.8570
P274=-88.0820 ;59.0000
P275=-88.0000 ;59.0210
P276=-87.5000 ;59.1570
P277=-87.0000 ;59.3100
P278=-86.5000 ;59.4810
P279=-86.4430 ;59.5000
P280=-86.0000 ;59.6160
P281=-85.5000 ;59.7520
P282=-85.0000 ;59.8920
P283=-84.6210 ;60.0000
P284=-84.5000 ;60.0240
P285=-84.0000 ;60.1250
P286=-83.5000 ;60.2370
P287=-83.0000 ;60.3600
P288=-82.5000 ;60.4870
P289=-82.4440 ;60.5000
P290=-82.0000 ;60.5720
P291=-81.5000 ;60.6510
P292=-81.0000 ;60.7240
P293=-80.5000 ;60.7880
P294=-80.0000 ;60.8430
P295=-79.5000 ;60.8860
P296=-79.0000 ;60.9210
P297=-78.5000 ;60.9440
P298=-78.0000 ;60.9490
P299=-77.5000 ;60.9340
P300=-77.0000 ;60.9020
P301=-76.5000 ;60.8490
P302=-76.0000 ;60.7670
P303=-75.5000 ;60.6650
P304=-75.0000 ;60.5210
P305=-74.9410 ;60.5000
P306=-74.5000 ;60.3360
P307=-74.0000 ;60.1280
P308=-73.7370 ;60.0000
P309=-73.5000 ;59.8690
P310=-73.0000 ;59.6120
P311=-72.7920 ;59.5000
P312=-72.5000 ;59.2810
P313=-72.0920 ;59.0000
P314=-72.0000 ;58.9420
P315=-71.5000 ;58.5970
P316=-71.3540 ;58.5000
P317=-71.0000 ;58.2880
P318=-70.5210 ;58.0000
P319=-70.5000 ;57.9870
P320=-70.0000 ;57.6920
P321=-69.6670 ;57.5000

P322=-69.5000 ;57.3640
P323=-69.0330 ;57.0000
P324=-69.0000 ;56.9760
P325=-68.5000 ;56.5490
P326=-68.4560 ;56.5000
P327=-68.0000 ;56.0540
P328=-67.9470 ;56.0000
P329=-67.5070 ;55.5000
P330=-67.5000 ;55.4900
P331=-67.2290 ;55.0000
P332=-67.0480 ;54.5000
P333=-67.0000 ;54.3340

[C2]

gain=-50.00

n_point=471

P1=-149.9520;76.4760
P2=-149.5000;76.3990
P3=-149.0000;76.3190
P4=-148.5000;76.2120
P5=-148.0000;76.0740
P6=-147.7860;76.0000
P7=-147.5000;75.9460
P8=-147.0000;75.8490
P9=-146.5000;75.7440
P10=-146.0000;75.5920
P11=-145.7710;75.5000
P12=-145.5000;75.4400
P13=-145.0000;75.3210
P14=-144.5000;75.2030
P15=-144.0000;75.0260
P16=-143.9430;75.0000
P17=-143.5000;74.8730
P18=-143.0000;74.7330
P19=-142.5000;74.5760
P20=-142.3210;74.5000
P21=-142.0000;74.4100
P22=-141.5000;74.2200
P23=-141.0000;74.0510
P24=-140.8820;74.0000
P25=-140.5000;73.8810
P26=-140.0000;73.6480
P27=-139.6180;73.5000
P28=-139.5000;73.4680
P29=-139.0000;73.2620
P30=-138.5180;73.0000
P31=-138.5000;72.9920
P32=-138.0000;72.8060
P33=-137.5580;72.5000
P34=-137.5000;72.4670
P35=-137.0000;72.2820
P36=-136.5680;72.0000
P37=-136.5000;71.9620
P38=-136.0000;71.7270
P39=-135.6100;71.5000
P40=-135.5000;71.4360
P41=-135.0000;71.1360
P42=-134.7780;71.0000

P43=-134.5000;70.8230
P44=-134.0680;70.5000
P45=-134.0000;70.4610
P46=-133.5000;70.0860
P47=-133.3970;70.0000
P48=-133.0000;69.7560
P49=-132.7050;69.5000
P50=-132.5000;69.3050
P51=-132.0990;69.0000
P52=-132.0000;68.9140
P53=-131.6210;68.5000
P54=-131.5000;68.4020
P55=-131.1160;68.0000
P56=-131.0000;67.8530
P57=-130.6390;67.5000
P58=-130.5000;67.2390
P59=-130.3340;67.0000
P60=-130.0000;66.6800
P61=-129.8560;66.5000
P62=-129.5910;66.0000
P63=-129.5000;65.8920
P64=-129.2220;65.5000
P65=-129.0000;65.1310
P66=-128.9170;65.0000
P67=-128.6460;64.5000
P68=-128.5000;64.2030
P69=-128.3880;64.0000
P70=-128.0950;63.5000
P71=-128.0000;63.2730
P72=-127.8500;63.0000
P73=-127.6130;62.5000
P74=-127.5000;62.2150
P75=-127.3820;62.0000
P76=-127.1730;61.5000
P77=-127.0320;61.0000
P78=-127.0000;60.9030
P79=-126.8370;60.5000
P80=-126.6490;60.0000
P81=-126.5000;59.5790
P82=-126.4610;59.5000
P83=-126.3110;59.0000
P84=-126.1930;58.5000
P85=-126.0450;58.0000
P86=-126.0000;57.8210
P87=-125.9070;57.5000
P88=-125.8590;57.0000
P89=-125.6810;56.5000
P90=-125.5790;56.0000
P91=-125.5060;55.5000
P92=-125.5000;55.4790
P93=-125.3010;55.0000
P94=-125.2150;54.5000
P95=-125.1200;54.0000
P96=-125.0580;53.5000
P97=-125.0200;53.0000
P98=-125.0000;52.9060
P99=-124.8650;52.5000

P100=-124.7640;52.0000
P101=-124.6510;51.5000
P102=-124.5600;51.0000
P103=-124.5140;50.5000
P104=-124.5000;50.4250
P105=-124.3770;50.0000
P106=-124.3190;49.5000
P107=-124.1920;49.0000
P108=-124.1110;48.5000
P109=-124.0010;48.0000
P110=-124.0000;47.9960
P111=-123.8600;47.5000
P112=-123.7560;47.0000
P113=-123.6680;46.5000
P114=-123.5650;46.0000
P115=-123.5000;45.7280
P116=-123.4220;45.5000
P117=-123.2800;45.0000
P118=-123.1630;44.5000
P119=-123.0430;44.0000
P120=-123.0000;43.8110
P121=-122.9040;43.5000
P122=-122.7420;43.0000
P123=-122.6410;42.5000
P124=-122.5000;42.0720
P125=-122.4700;42.0000
P126=-122.3270;41.5000
P127=-122.1800;41.0000
P128=-122.0550;40.5000
P129=-122.0000;40.2690
P130=-121.9120;40.0000
P131=-121.7370;39.5000
P132=-121.6330;39.0000
P133=-121.5290;38.5000
P134=-121.5000;38.4280
P135=-121.3630;38.0000
P136=-121.2660;37.5000
P137=-121.1740;37.0000
P138=-121.0480;36.5000
P139=-121.0000;36.2700
P140=-120.9390;36.0000
P141=-120.8140;35.5000
P142=-120.6960;35.0000
P143=-120.6400;34.5000
P144=-120.5000;34.0030
P145=-120.4990;34.0000
P146=-120.3550;33.5000
P147=-120.2390;33.0000
P148=-120.2290;32.5000
P149=-120.0550;32.0000
P150=-120.0000;31.9670
P151=-119.8610;31.5000
P152=-119.7290;31.0000
P153=-119.6630;30.5000
P154=-119.5000;30.3030
P155=-119.4110;30.0000
P156=-119.3110;29.5000

P157=-119.0000;29.0320
P158=-118.9860;29.0000
P159=-118.8010;28.5000
P160=-118.6060;28.0000
P161=-118.5000;27.9210
P162=-118.2960;27.5000
P163=-118.1440;27.0000
P164=-118.0000;26.8620
P165=-117.8100;26.5000
P166=-117.6440;26.0000
P167=-117.5000;25.8540
P168=-117.3060;25.5000
P169=-117.1340;25.0000
P170=-117.0000;24.8700
P171=-116.7940;24.5000
P172=-116.5890;24.0000
P173=-116.5000;23.9330
P174=-116.2450;23.5000
P175=-116.0000;23.0120
P176=-115.9930;23.0000
P177=-115.7210;22.5000
P178=-115.5000;22.1400
P179=-115.4090;22.0000
P180=-115.1910;21.5000
P181=-115.0000;21.2760
P182=-114.8250;21.0000
P183=-114.5000;20.5280
P184=-114.4790;20.5000
P185=-114.1620;20.0000
P186=-114.0000;19.8090
P187=-113.7790;19.5000
P188=-113.5000;19.1120
P189=-113.4110;19.0000
P190=-113.0790;18.5000
P191=-113.0000;18.4450
P192=-112.6520;18.0000
P193=-112.5000;17.7950
P194=-112.2540;17.5000
P195=-112.0000;17.2310
P196=-111.7910;17.0000
P197=-111.5000;16.6650
P198=-111.3490;16.5000
P199=-111.0000;16.1250
P200=-110.8790;16.0000
P201=-110.5000;15.5980
P202=-110.4000;15.5000
P203=-110.0000;15.1300
P204=-109.8690;15.0000
P205=-109.5000;14.6490
P206=-109.3390;14.5000
P207=-109.0000;14.1970
P208=-108.7880;14.0000
P209=-108.5000;13.7820
P210=-108.1880;13.5000
P211=-108.0000;13.3350
P212=-107.5980;13.0000
P213=-107.5000;12.9140

P214=-107.0000;12.5350
P215=-106.9560;12.5000
P216=-106.5000;12.2090
P217=-106.2310;12.0000
P218=-106.0000;11.8540
P219=-105.5000;11.5250
P220=-105.4640;11.5000
P221=-105.0000;11.2800
P222=-104.5790;11.0000
P223=-104.5000;10.9530
P224=-104.0000;10.7210
P225=-103.6560;10.5000
P226=-103.5000;10.4270
P227=-103.0000;10.2230
P228=-102.6280;10.0000
P229=-102.5000;9.9310
P230=-102.0000;9.7940
P231=-101.5000;9.5120
P232=-101.4750;9.5000
P233=-101.0000;9.3570
P234=-100.5000;9.2100
P235=-100.0500;9.0000
P236=-100.0000;8.9860
P237=-99.5000 ;8.8890
P238=-99.0000 ;8.7410
P239=-98.5000 ;8.5670
P240=-98.3040 ;8.5000
P241=-98.0000 ;8.4470
P242=-97.5000 ;8.4090
P243=-97.0000 ;8.3210
P244=-96.5000 ;8.2190
P245=-96.0000 ;8.1190
P246=-95.5000 ;8.0270
P247=-95.3220 ;8.0000
P248=-95.0000 ;7.9690
P249=-94.5000 ;7.9410
P250=-94.0000 ;7.9300
P251=-93.5000 ;7.9260
P252=-93.0000 ;7.9260
P253=-92.5000 ;7.9280
P254=-92.0000 ;7.9310
P255=-91.5000 ;7.9330
P256=-91.0000 ;7.9360
P257=-90.5000 ;7.9420
P258=-90.0000 ;7.9500
P259=-89.5000 ;7.9660
P260=-89.0640 ;8.0000
P261=-89.0000 ;8.0090
P262=-88.5000 ;8.1040
P263=-88.0000 ;8.2120
P264=-87.5000 ;8.3360
P265=-87.0000 ;8.4460
P266=-86.6220 ;8.5000
P267=-86.5000 ;8.5490
P268=-86.0000 ;8.7940
P269=-85.5000 ;8.9100
P270=-85.1830 ;9.0000

P271=-85.0000 ;9.0910
P272=-84.5000 ;9.3230
P273=-84.0000 ;9.4070
P274=-83.7640 ;9.5000
P275=-83.5000 ;9.6250
P276=-83.0000 ;9.7940
P277=-82.5000 ;9.8790
P278=-82.1530 ;10.0000
P279=-82.0000 ;10.0570
P280=-81.5000 ;10.1950
P281=-81.0000 ;10.3010
P282=-80.5000 ;10.4690
P283=-80.4550 ;10.5000
P284=-80.0000 ;10.6480
P285=-79.5000 ;10.7830
P286=-79.0000 ;10.9640
P287=-78.9510 ;11.0000
P288=-78.5000 ;11.2070
P289=-78.0000 ;11.4080
P290=-77.7870 ;11.5000
P291=-77.5000 ;11.6590
P292=-77.0000 ;11.9030
P293=-76.8090 ;12.0000
P294=-76.5000 ;12.1970
P295=-76.0000 ;12.4550
P296=-75.9210 ;12.5000
P297=-75.5000 ;12.8170
P298=-75.1640 ;13.0000
P299=-75.0000 ;13.1200
P300=-74.5000 ;13.4610
P301=-74.4470 ;13.5000
P302=-74.0000 ;13.8750
P303=-73.7590 ;14.0000
P304=-73.5000 ;14.2080
P305=-73.0000 ;14.4970
P306=-72.9960 ;14.5000
P307=-72.5000 ;14.8870
P308=-72.3830 ;15.0000
P309=-72.0000 ;15.3370
P310=-71.7770 ;15.5000
P311=-71.5000 ;15.7380
P312=-71.0790 ;16.0000
P313=-71.0000 ;16.0680
P314=-70.5000 ;16.4740
P315=-70.4570 ;16.5000
P316=-70.0000 ;16.8910
P317=-69.8820 ;17.0000
P318=-69.5000 ;17.3450
P319=-69.3470 ;17.5000
P320=-69.0000 ;17.8280
P321=-68.7730 ;18.0000
P322=-68.5000 ;18.2550
P323=-68.2770 ;18.5000
P324=-68.0000 ;18.7670
P325=-67.6780 ;19.0000
P326=-67.5000 ;19.1670
P327=-67.1100 ;19.5000

P328=-67.0000 ;19.6070
P329=-66.6010 ;20.0000
P330=-66.5000 ;20.0970
P331=-66.0660 ;20.5000
P332=-66.0000 ;20.5640
P333=-65.5490 ;21.0000
P334=-65.5000 ;21.0460
P335=-65.0000 ;21.4880
P336=-64.9860 ;21.5000
P337=-64.5000 ;21.9320
P338=-64.4520 ;22.0000
P339=-64.0000 ;22.4520
P340=-63.9550 ;22.5000
P341=-63.5000 ;22.9580
P342=-63.4370 ;23.0000
P343=-63.0000 ;23.4210
P344=-62.9290 ;23.5000
P345=-62.5000 ;23.9340
P346=-62.4560 ;24.0000
P347=-62.0000 ;24.4840
P348=-61.9710 ;24.5000
P349=-61.5000 ;24.9480
P350=-61.4710 ;25.0000
P351=-61.0450 ;25.5000
P352=-61.0000 ;25.5470
P353=-60.5320 ;26.0000
P354=-60.5000 ;26.0360
P355=-60.1540 ;26.5000
P356=-60.0000 ;26.6620
P357=-59.6680 ;27.0000
P358=-59.5000 ;27.1950
P359=-59.2830 ;27.5000
P360=-59.0000 ;27.8040
P361=-58.8280 ;28.0000
P362=-58.5000 ;28.3680
P363=-58.3590 ;28.5000
P364=-58.0000 ;28.9140
P365=-57.9440 ;29.0000
P366=-57.5000 ;29.4730
P367=-57.4830 ;29.5000
P368=-57.1080 ;30.0000
P369=-57.0000 ;30.1180
P370=-56.6910 ;30.5000
P371=-56.5000 ;30.7000
P372=-56.2160 ;31.0000
P373=-56.0000 ;31.2260
P374=-55.7330 ;31.5000
P375=-55.5000 ;31.7610
P376=-55.2730 ;32.0000
P377=-55.0000 ;32.2890
P378=-54.8160 ;32.5000
P379=-54.5000 ;32.8170
P380=-54.3330 ;33.0000
P381=-54.0000 ;33.3260
P382=-53.8250 ;33.5000
P383=-53.5000 ;33.8150
P384=-53.3040 ;34.0000

P385=-53.0000 ;34.2920
P386=-52.7740 ;34.5000
P387=-52.5000 ;34.7580
P388=-52.2270 ;35.0000
P389=-52.0000 ;35.2090
P390=-51.6570 ;35.5000
P391=-51.5000 ;35.6420
P392=-51.0640 ;36.0000
P393=-51.0000 ;36.0570
P394=-50.5000 ;36.4540
P395=-50.4500 ;36.5000
P396=-50.0000 ;36.8590
P397=-49.8490 ;37.0000
P398=-49.5000 ;37.2810
P399=-49.2390 ;37.5000
P400=-49.0000 ;37.6880
P401=-48.5910 ;38.0000
P402=-48.5000 ;38.0750
P403=-48.0000 ;38.4170
P404=-47.9040 ;38.5000
P405=-47.5000 ;38.7850
P406=-47.2300 ;39.0000
P407=-47.0000 ;39.1660
P408=-46.5380 ;39.5000
P409=-46.5000 ;39.5310
P410=-46.0000 ;39.8560
P411=-45.8310 ;40.0000
P412=-45.5000 ;40.2210
P413=-45.0950 ;40.5000
P414=-45.0000 ;40.5740
P415=-44.5000 ;40.8520
P416=-44.3190 ;41.0000
P417=-44.0000 ;41.2080
P418=-43.5050 ;41.5000
P419=-43.5000 ;41.5040
P420=-43.0000 ;41.7960
P421=-42.6490 ;42.0000
P422=-42.5000 ;42.1140
P423=-42.0000 ;42.3580
P424=-41.7510 ;42.5000
P425=-41.5000 ;42.6790
P426=-41.0000 ;42.8990
P427=-40.7990 ;43.0000
P428=-40.5000 ;43.1990
P429=-40.0000 ;43.4230
P430=-39.7950 ;43.5000
P431=-39.5000 ;43.6670
P432=-39.0000 ;43.9190
P433=-38.7560 ;44.0000
P434=-38.5000 ;44.1060
P435=-38.0000 ;44.3570
P436=-37.7320 ;44.5000
P437=-37.5000 ;44.5950
P438=-37.0000 ;44.7320
P439=-36.6010 ;45.0000
P440=-36.5000 ;45.0470
P441=-36.0000 ;45.1810

P442=-35.5000 ;45.3150
P443=-35.2960 ;45.5000
P444=-35.0000 ;45.6280
P445=-34.5000 ;45.7460
P446=-34.0000 ;45.8460
P447=-33.8310 ;46.0000
P448=-33.5000 ;46.1300
P449=-33.0000 ;46.3040
P450=-32.5000 ;46.3290
P451=-32.1270 ;46.5000
P452=-32.0000 ;46.5350
P453=-31.5000 ;46.7100
P454=-31.0000 ;46.8910
P455=-30.5000 ;46.9150
P456=-30.2680 ;47.0000
P457=-30.0000 ;47.0360
P458=-29.5000 ;47.1690
P459=-29.0000 ;47.3830
P460=-28.7240 ;47.5000
P461=-28.5000 ;47.5420
P462=-28.0000 ;47.5300
P463=-27.5000 ;47.5410
P464=-27.0000 ;47.5980
P465=-26.5000 ;47.7450
P466=-26.0650 ;48.0000
P467=-26.0000 ;48.0120
P468=-25.5000 ;48.0880
P469=-25.0000 ;48.0730
P470=-24.5000 ;48.0540
P471=-24.2820 ;48.0520

[C3]

gain=-50.00

n_point=147

P1=-82.5000 ;13.3390
P2=-83.0000 ;13.3000
P3=-83.5000 ;13.2050
P4=-83.9540 ;13.0000
P5=-84.0000 ;12.9590
P6=-84.5000 ;12.8140
P7=-85.0000 ;12.6960
P8=-85.3750 ;12.5000
P9=-85.5000 ;12.4410
P10=-86.0000 ;12.2860
P11=-86.5000 ;12.1270
P12=-86.7440 ;12.0000
P13=-87.0000 ;11.9130
P14=-87.5000 ;11.8420
P15=-88.0000 ;11.6320
P16=-88.3370 ;11.5000
P17=-88.5000 ;11.4460
P18=-89.0000 ;11.3440
P19=-89.5000 ;11.3340
P20=-90.0000 ;11.3900
P21=-90.5000 ;11.3050
P22=-91.0000 ;11.2720
P23=-91.5000 ;11.2710
P24=-92.0000 ;11.2940

P25=-92.5000 ;11.3320
P26=-93.0000 ;11.3420
P27=-93.5000 ;11.3270
P28=-94.0000 ;11.3270
P29=-94.5000 ;11.3440
P30=-95.0000 ;11.3780
P31=-95.5000 ;11.4290
P32=-96.0000 ;11.4820
P33=-96.1100 ;11.5000
P34=-96.5000 ;11.5920
P35=-97.0000 ;11.7270
P36=-97.5000 ;11.8450
P37=-98.0000 ;11.8590
P38=-98.4850 ;12.0000
P39=-98.5000 ;12.0060
P40=-99.0000 ;12.2490
P41=-99.5000 ;12.3990
P42=-99.8190 ;12.5000
P43=-100.0000;12.5980
P44=-100.5000;12.7980
P45=-101.0000;12.9900
P46=-101.0120;13.0000
P47=-101.5000;13.2770
P48=-102.0000;13.4340
P49=-102.0630;13.5000
P50=-102.5000;13.7790
P51=-103.0000;13.9610
P52=-103.0270;14.0000
P53=-103.5000;14.3190
P54=-103.8120;14.5000
P55=-104.0000;14.6370
P56=-104.5000;14.8960
P57=-104.6010;15.0000
P58=-105.0000;15.3020
P59=-105.2470;15.5000
P60=-105.5000;15.7150
P61=-105.8470;16.0000
P62=-106.0000;16.1320
P63=-106.4290;16.5000
P64=-106.5000;16.5670
P65=-107.0000;16.9730
P66=-107.0210;17.0000
P67=-107.5000;17.4660
P68=-107.5530;17.5000
P69=-108.0000;17.9490
P70=-108.0430;18.0000
P71=-108.5000;18.4630
P72=-108.7020;18.0000
P73=-108.5000;17.7810
P74=-108.1970;17.5000
P75=-108.0000;17.2960
P76=-107.7640;17.0000
P77=-107.5000;16.7430
P78=-107.2220;16.5000
P79=-107.0000;16.2800
P80=-106.6920;16.0000
P81=-106.5000;15.8260

P82=-106.1450;15.5000
P83=-106.0000;15.3690
P84=-105.5190;15.0000
P85=-105.5000;14.9830
P86=-105.0000;14.6140
P87=-104.8820;14.5000
P88=-104.5000;14.2120
P89=-104.2100;14.0000
P90=-104.0000;13.8320
P91=-103.5000;13.5800
P92=-103.3910;13.5000
P93=-103.0000;13.2390
P94=-102.5400;13.0000
P95=-102.5000;12.9720
P96=-102.0000;12.6930
P97=-101.5420;12.5000
P98=-101.5000;12.4740
P99=-101.0000;12.1680
P100=-100.5000;12.0500
P101=-100.4300;12.0000
P102=-100.0000;11.7640
P103=-99.5000 ;11.5820
P104=-99.2230 ;11.5000
P105=-99.0000 ;11.3850
P106=-98.5000 ;11.2100
P107=-98.0000 ;11.1250
P108=-97.5000 ;11.0080
P109=-97.4720 ;11.0000
P110=-97.0000 ;10.8390
P111=-96.5000 ;10.7110
P112=-96.0000 ;10.6280
P113=-95.5000 ;10.6220
P114=-95.0000 ;10.6220
P115=-94.5000 ;10.6000
P116=-94.0000 ;10.5580
P117=-93.5000 ;10.5020
P118=-93.4790 ;10.5000
P119=-93.0000 ;10.4330
P120=-92.5000 ;10.3760
P121=-92.0000 ;10.3370
P122=-91.5000 ;10.3200
P123=-91.0000 ;10.3300
P124=-90.5000 ;10.3700
P125=-90.0000 ;10.4500
P126=-89.7920 ;10.5000
P127=-89.5000 ;10.5470
P128=-89.0000 ;10.6330
P129=-88.5000 ;10.6500
P130=-88.0000 ;10.7550
P131=-87.5190 ;11.0000
P132=-87.5000 ;11.0100
P133=-87.0000 ;11.1120
P134=-86.5000 ;11.2830
P135=-86.0720 ;11.5000
P136=-86.0000 ;11.5510
P137=-85.5000 ;11.6440
P138=-85.0000 ;11.8500

P139=-84.7200 ;12.0000
P140=-84.5000 ;12.1250
P141=-84.0000 ;12.2670
P142=-83.5000 ;12.4890
P143=-83.4790 ;12.5000
P144=-83.0000 ;12.7060
P145=-82.5000 ;12.9020
P146=-82.3030 ;13.0000
P147=-82.5000 ;13.3390

[C4]

gain=-50.00

n_point=123

P1=-81.0000 ;17.7580
P2=-81.5000 ;17.6190
P3=-81.7030 ;17.5000
P4=-82.0000 ;17.2720
P5=-82.5000 ;17.2140
P6=-82.8640 ;17.0000
P7=-83.0000 ;16.8880
P8=-83.5000 ;16.7320
P9=-84.0000 ;16.5430
P10=-84.0830 ;16.5000
P11=-84.5000 ;16.3580
P12=-85.0000 ;16.2220
P13=-85.4140 ;16.0000
P14=-85.5000 ;15.9270
P15=-86.0000 ;15.7690
P16=-86.5000 ;15.7090
P17=-86.9410 ;15.5000
P18=-87.0000 ;15.4350
P19=-87.5000 ;15.3760
P20=-88.0000 ;15.2190
P21=-88.4740 ;15.0000
P22=-88.5000 ;14.9750
P23=-89.0000 ;14.7810
P24=-89.5000 ;14.7660
P25=-90.0000 ;14.8020
P26=-90.5000 ;14.6700
P27=-91.0000 ;14.5520
P28=-91.3810 ;14.5000
P29=-91.5000 ;14.4680
P30=-92.0000 ;14.4500
P31=-92.5000 ;14.4850
P32=-92.5590 ;14.5000
P33=-93.0000 ;14.5640
P34=-93.5000 ;14.6740
P35=-94.0000 ;14.7810
P36=-94.5000 ;14.7650
P37=-95.0000 ;14.7850
P38=-95.5000 ;14.8800
P39=-95.9380 ;15.0000
P40=-96.0000 ;15.0180
P41=-96.5000 ;15.1900
P42=-97.0000 ;15.3060
P43=-97.5000 ;15.2820
P44=-98.0000 ;15.3760
P45=-98.1130 ;15.5000

P46=-98.5000 ;15.6520
P47=-99.0000 ;15.8390
P48=-99.3790 ;16.0000
P49=-99.5000 ;16.0700
P50=-100.0000;16.2310
P51=-100.3790;16.5000
P52=-100.5000;16.5840
P53=-101.0000;16.7600
P54=-101.2460;17.0000
P55=-101.5000;17.1890
P56=-101.9810;17.5000
P57=-102.0000;17.5150
P58=-102.5000;17.7330
P59=-102.7230;18.0000
P60=-103.0000;18.2120
P61=-103.3660;18.0000
P62=-103.0000;17.7250
P63=-102.7320;17.5000
P64=-102.5000;17.3270
P65=-102.1100;17.0000
P66=-102.0000;16.9090
P67=-101.5000;16.6820
P68=-101.3230;16.5000
P69=-101.0000;16.2810
P70=-100.6000;16.0000
P71=-100.5000;15.9260
P72=-100.0000;15.7450
P73=-99.6010 ;15.5000
P74=-99.5000 ;15.4360
P75=-99.0000 ;15.1710
P76=-98.5000 ;15.1230
P77=-98.3650 ;15.0000
P78=-98.0000 ;14.8540
P79=-97.5000 ;14.7430
P80=-97.0000 ;14.6200
P81=-96.5000 ;14.5310
P82=-96.4620 ;14.5000
P83=-96.0000 ;14.3250
P84=-95.5000 ;14.2260
P85=-95.0000 ;14.2240
P86=-94.5000 ;14.1520
P87=-94.0000 ;14.0400
P88=-93.8290 ;14.0000
P89=-93.5000 ;13.9150
P90=-93.0000 ;13.8220
P91=-92.5000 ;13.7700
P92=-92.0000 ;13.7600
P93=-91.5000 ;13.7930
P94=-91.0000 ;13.8710
P95=-90.5000 ;13.9970
P96=-90.4890 ;14.0000
P97=-90.0000 ;14.0860
P98=-89.5000 ;14.1990
P99=-89.0000 ;14.2830
P100=-88.5000 ;14.2840
P101=-88.1090 ;14.5000
P102=-88.0000 ;14.6140

P103=-87.5000 ;14.6260
P104=-87.0000 ;14.7960
P105=-86.5730 ;15.0000
P106=-86.5000 ;15.0660
P107=-86.0000 ;15.2090
P108=-85.5000 ;15.2440
P109=-85.0000 ;15.4780
P110=-84.9570 ;15.5000
P111=-84.5000 ;15.6360
P112=-84.0000 ;15.8300
P113=-83.6990 ;16.0000
P114=-83.5000 ;16.1480
P115=-83.0000 ;16.2260
P116=-82.5600 ;16.5000
P117=-82.5000 ;16.5750
P118=-82.0000 ;16.7910
P119=-81.6510 ;17.0000
P120=-81.5000 ;17.2150
P121=-81.0000 ;17.3290
P122=-80.7640 ;17.5000
P123=-81.0000 ;17.7580

[C5]

gain=-2.00

n_point=82

P1=-88.0000 ;35.5970
P2=-87.9760 ;35.5000
P3=-87.9693 ;35.3333
P4=-87.9627 ;35.1667
P5=-87.9560 ;35.0000
P6=-87.9780 ;34.8785
P7=-88.0000 ;34.7570
P8=-88.0300 ;34.6285
P9=-88.0600 ;34.5000
P10=-88.1135 ;34.3750
P11=-88.1670 ;34.2500
P12=-88.2205 ;34.1250
P13=-88.2740 ;34.0000
P14=-88.3493 ;33.8750
P15=-88.4247 ;33.7500
P16=-88.5000 ;33.6250
P17=-88.5980 ;33.5000
P18=-88.7320 ;33.3737
P19=-88.8660 ;33.2473
P20=-89.0000 ;33.1210
P21=-89.0930 ;33.0605
P22=-89.1860 ;33.0000
P23=-89.3430 ;32.9180
P24=-89.5000 ;32.8360
P25=-89.6667 ;32.7960
P26=-89.8333 ;32.7560
P27=-90.0000 ;32.7160
P28=-90.1667 ;32.7223
P29=-90.3333 ;32.7287
P30=-90.5000 ;32.7350
P31=-90.6667 ;32.7990
P32=-90.8333 ;32.8630
P33=-91.0000 ;32.9270

P34=-91.1000 ;33.0000
P35=-91.2000 ;33.1063
P36=-91.3000 ;33.2125
P37=-91.4000 ;33.3187
P38=-91.5000 ;33.4250
P39=-91.5460 ;33.5000
P40=-91.6027 ;33.6667
P41=-91.6593 ;33.8333
P42=-91.7160 ;34.0000
P43=-91.7343 ;34.1667
P44=-91.7527 ;34.3333
P45=-91.7710 ;34.5000
P46=-91.7500 ;34.6667
P47=-91.7290 ;34.8333
P48=-91.7080 ;35.0000
P49=-91.6523 ;35.1667
P50=-91.5967 ;35.3333
P51=-91.5410 ;35.5000
P52=-91.5000 ;35.5790
P53=-91.4050 ;35.7193
P54=-91.3100 ;35.8597
P55=-91.2150 ;36.0000
P56=-91.1075 ;36.1200
P57=-91.0000 ;36.2400
P58=-90.8937 ;36.3267
P59=-90.7873 ;36.4133
P60=-90.6810 ;36.5000
P61=-90.5905 ;36.5575
P62=-90.5000 ;36.6150
P63=-90.3333 ;36.6810
P64=-90.1667 ;36.7470
P65=-90.0000 ;36.8130
P66=-89.8333 ;36.8347
P67=-89.6667 ;36.8563
P68=-89.5000 ;36.8780
P69=-89.3333 ;36.8457
P70=-89.1667 ;36.8133
P71=-89.0000 ;36.7810
P72=-88.8333 ;36.6930
P73=-88.6667 ;36.6050
P74=-88.5000 ;36.5170
P75=-88.4820 ;36.5000
P76=-88.3980 ;36.3750
P77=-88.3140 ;36.2500
P78=-88.2300 ;36.1250
P79=-88.1460 ;36.0000
P80=-88.0973 ;35.8657
P81=-88.0487 ;35.7313
P82=-88.0000 ;35.5970
[C6]
gain=-4.00
n_point=97
P1=-87.5000 ;36.6550
P2=-87.4210 ;36.5000
P3=-87.3687 ;36.3333
P4=-87.3163 ;36.1667
P5=-87.2640 ;36.0000

P6=-87.2433 ;35.8333
P7=-87.2227 ;35.6667
P8=-87.2020 ;35.5000
P9=-87.2090 ;35.3333
P10=-87.2160 ;35.1667
P11=-87.2230 ;35.0000
P12=-87.2560 ;34.8333
P13=-87.2890 ;34.6667
P14=-87.3220 ;34.5000
P15=-87.3747 ;34.3333
P16=-87.4273 ;34.1667
P17=-87.4800 ;34.0000
P18=-87.5000 ;33.9560
P19=-87.5837 ;33.8040
P20=-87.6673 ;33.6520
P21=-87.7510 ;33.5000
P22=-87.8755 ;33.3165
P23=-88.0000 ;33.1330
P24=-88.1120 ;33.0000
P25=-88.2413 ;32.8700
P26=-88.3707 ;32.7400
P27=-88.5000 ;32.6100
P28=-88.6410 ;32.5000
P29=-88.8205 ;32.3815
P30=-89.0000 ;32.2630
P31=-89.1667 ;32.1827
P32=-89.3333 ;32.1023
P33=-89.5000 ;32.0220
P34=-89.5850 ;32.0000
P35=-89.7925 ;31.9560
P36=-90.0000 ;31.9120
P37=-90.2500 ;31.9110
P38=-90.5000 ;31.9100
P39=-90.7375 ;31.9550
P40=-90.9750 ;32.0000
P41=-91.0000 ;32.0060
P42=-91.1667 ;32.0997
P43=-91.3333 ;32.1933
P44=-91.5000 ;32.2870
P45=-91.6300 ;32.3935
P46=-91.7600 ;32.5000
P47=-91.8800 ;32.6305
P48=-92.0000 ;32.7610
P49=-92.0785 ;32.8805
P50=-92.1570 ;33.0000
P51=-92.2310 ;33.1667
P52=-92.3050 ;33.3333
P53=-92.3790 ;33.5000
P54=-92.4395 ;33.7350
P55=-92.5000 ;33.9700
P56=-92.5060 ;34.0000
P57=-92.5137 ;34.1667
P58=-92.5213 ;34.3333
P59=-92.5290 ;34.5000
P60=-92.5145 ;34.6295
P61=-92.5000 ;34.7590
P62=-92.4830 ;34.8795

P63=-92.4660 ;35.0000
P64=-92.4160 ;35.1667
P65=-92.3660 ;35.3333
P66=-92.3160 ;35.5000
P67=-92.2430 ;35.6667
P68=-92.1700 ;35.8333
P69=-92.0970 ;36.0000
P70=-92.0000 ;36.1680
P71=-91.8830 ;36.3340
P72=-91.7660 ;36.5000
P73=-91.6330 ;36.6495
P74=-91.5000 ;36.7990
P75=-91.3875 ;36.8995
P76=-91.2750 ;37.0000
P77=-91.1375 ;37.1050
P78=-91.0000 ;37.2100
P79=-90.8333 ;37.3053
P80=-90.6667 ;37.4007
P81=-90.5000 ;37.4960
P82=-90.4900 ;37.5000
P83=-90.2450 ;37.5765
P84=-90.0000 ;37.6530
P85=-89.7500 ;37.6895
P86=-89.5000 ;37.7260
P87=-89.2500 ;37.7135
P88=-89.0000 ;37.7010
P89=-88.7500 ;37.6315
P90=-88.5000 ;37.5620
P91=-88.3760 ;37.5000
P92=-88.1880 ;37.3805
P93=-88.0000 ;37.2610
P94=-87.8680 ;37.1305
P95=-87.7360 ;37.0000
P96=-87.6180 ;36.8275
P97=-87.5000 ;36.6550
[C7]
gain=-6.00
n_point=90
P1=-87.0000 ;37.0790
P2=-86.9560 ;37.0000
P3=-86.8640 ;36.7500
P4=-86.7720 ;36.5000
P5=-86.7220 ;36.2500
P6=-86.6720 ;36.0000
P7=-86.6560 ;35.7500
P8=-86.6400 ;35.5000
P9=-86.6610 ;35.2500
P10=-86.6820 ;35.0000
P11=-86.7355 ;34.7500
P12=-86.7890 ;34.5000
P13=-86.8675 ;34.2500
P14=-86.9460 ;34.0000
P15=-87.0000 ;33.8700
P16=-87.0905 ;33.6850
P17=-87.1810 ;33.5000
P18=-87.3310 ;33.2500
P19=-87.4810 ;33.0000

P20=-87.5000 ;32.9730
P21=-87.6975 ;32.7365
P22=-87.8950 ;32.5000
P23=-88.0000 ;32.3890
P24=-88.2185 ;32.1945
P25=-88.4370 ;32.0000
P26=-88.5000 ;31.9530
P27=-88.7500 ;31.8065
P28=-89.0000 ;31.6600
P29=-89.1880 ;31.5800
P30=-89.3760 ;31.5000
P31=-89.5000 ;31.4560
P32=-89.7500 ;31.4040
P33=-90.0000 ;31.3520
P34=-90.2500 ;31.3445
P35=-90.5000 ;31.3370
P36=-90.7500 ;31.3735
P37=-91.0000 ;31.4100
P38=-91.2720 ;31.5000
P39=-91.5000 ;31.5970
P40=-91.7500 ;31.7605
P41=-92.0000 ;31.9240
P42=-92.0850 ;32.0000
P43=-92.2233 ;32.1587
P44=-92.3617 ;32.3173
P45=-92.5000 ;32.4760
P46=-92.5170 ;32.5000
P47=-92.6505 ;32.7500
P48=-92.7840 ;33.0000
P49=-92.8705 ;33.2500
P50=-92.9570 ;33.5000
P51=-93.0000 ;33.7330
P52=-93.0390 ;34.0000
P53=-93.0465 ;34.2500
P54=-93.0540 ;34.5000
P55=-93.0290 ;34.7500
P56=-93.0040 ;35.0000
P57=-93.0000 ;35.0190
P58=-92.9370 ;35.2595
P59=-92.8740 ;35.5000
P60=-92.7790 ;35.7500
P61=-92.6840 ;36.0000
P62=-92.5920 ;36.1855
P63=-92.5000 ;36.3710
P64=-92.4230 ;36.5000
P65=-92.2365 ;36.7500
P66=-92.0500 ;37.0000
P67=-92.0000 ;37.0580
P68=-91.7700 ;37.2790
P69=-91.5400 ;37.5000
P70=-91.5000 ;37.5340
P71=-91.2500 ;37.7040
P72=-91.0000 ;37.8740
P73=-90.7650 ;38.0000
P74=-90.5000 ;38.1230
P75=-90.2500 ;38.2005
P76=-90.0000 ;38.2780

P77=-89.7500 ;38.3165
P78=-89.5000 ;38.3550
P79=-89.2500 ;38.3540
P80=-89.0000 ;38.3530
P81=-88.7500 ;38.3065
P82=-88.5000 ;38.2600
P83=-88.2500 ;38.1605
P84=-88.0000 ;38.0610
P85=-87.8970 ;38.0000
P86=-87.6985 ;37.8535
P87=-87.5000 ;37.7070
P88=-87.3030 ;37.5000
P89=-87.1515 ;37.2895
P90=-87.0000 ;37.0790

[C8]

gain=-10.00
n_point=109
P1=-86.0000 ;37.0320
P2=-85.9910 ;37.0000
P3=-85.9425 ;36.7500
P4=-85.8940 ;36.5000
P5=-85.8710 ;36.2500
P6=-85.8480 ;36.0000
P7=-85.8530 ;35.7500
P8=-85.8580 ;35.5000
P9=-85.8870 ;35.2500
P10=-85.9160 ;35.0000
P11=-85.9580 ;34.7795
P12=-86.0000 ;34.5590
P13=-86.0140 ;34.5000
P14=-86.0980 ;34.2500
P15=-86.1820 ;34.0000
P16=-86.2840 ;33.7500
P17=-86.3860 ;33.5000
P18=-86.5000 ;33.2630
P19=-86.6540 ;33.0000
P20=-86.8105 ;32.7500
P21=-86.9670 ;32.5000
P22=-87.0000 ;32.4540
P23=-87.1885 ;32.2270
P24=-87.3770 ;32.0000
P25=-87.5000 ;31.8670
P26=-87.7005 ;31.6835
P27=-87.9010 ;31.5000
P28=-88.0000 ;31.4170
P29=-88.2500 ;31.2430
P30=-88.5000 ;31.0690
P31=-88.6220 ;31.0000
P32=-88.8110 ;30.9085
P33=-89.0000 ;30.8170
P34=-89.2500 ;30.7245
P35=-89.5000 ;30.6320
P36=-89.7500 ;30.5770
P37=-90.0000 ;30.5220
P38=-90.3160 ;30.5000
P39=-90.5000 ;30.4900
P40=-90.6070 ;30.5000

P41=-91.0000 ;30.5490
P42=-91.2500 ;30.6205
P43=-91.5000 ;30.6920
P44=-91.7500 ;30.8070
P45=-92.0000 ;30.9220
P46=-92.1280 ;31.0000
P47=-92.3140 ;31.1360
P48=-92.5000 ;31.2720
P49=-92.7420 ;31.5000
P50=-92.8710 ;31.6475
P51=-93.0000 ;31.7950
P52=-93.1450 ;32.0000
P53=-93.2885 ;32.2500
P54=-93.4320 ;32.5000
P55=-93.5000 ;32.6530
P56=-93.6250 ;33.0000
P57=-93.6840 ;33.2500
P58=-93.7430 ;33.5000
P59=-93.7740 ;33.7500
P60=-93.8050 ;34.0000
P61=-93.8090 ;34.2500
P62=-93.8130 ;34.5000
P63=-93.7870 ;34.7500
P64=-93.7610 ;35.0000
P65=-93.7100 ;35.2500
P66=-93.6590 ;35.5000
P67=-93.5875 ;35.7500
P68=-93.5160 ;36.0000
P69=-93.5000 ;36.0430
P70=-93.3945 ;36.2715
P71=-93.2890 ;36.5000
P72=-93.1525 ;36.7500
P73=-93.0160 ;37.0000
P74=-93.0000 ;37.0240
P75=-92.8205 ;37.2620
P76=-92.6410 ;37.5000
P77=-92.5000 ;37.6680
P78=-92.3375 ;37.8340
P79=-92.1750 ;38.0000
P80=-92.0000 ;38.1610
P81=-91.7820 ;38.3305
P82=-91.5640 ;38.5000
P83=-91.5000 ;38.5440
P84=-91.2500 ;38.6830
P85=-91.0000 ;38.8220
P86=-90.6120 ;39.0000
P87=-90.5000 ;39.0440
P88=-90.2500 ;39.1140
P89=-90.0000 ;39.1840
P90=-89.7500 ;39.2270
P91=-89.5000 ;39.2700
P92=-89.2500 ;39.2800
P93=-89.0000 ;39.2900
P94=-88.7500 ;39.2660
P95=-88.5000 ;39.2420
P96=-88.2500 ;39.1840
P97=-88.0000 ;39.1260

P98=-87.6820 ;39.0000
P99=-87.5000 ;38.9090
P100=-87.2500 ;38.7395
P101=-87.0000 ;38.5700
P102=-86.9210 ;38.5000
P103=-86.7105 ;38.2675
P104=-86.5000 ;38.0350
P105=-86.4760 ;38.0000
P106=-86.3310 ;37.7500
P107=-86.1860 ;37.5000
P108=-86.0930 ;37.2660
P109=-86.0000 ;37.0320
[C9]
gain=-20.00
n_point=120
P1=-85.0000 ;37.9230
P2=-84.8980 ;37.5000
P3=-84.8610 ;37.2500
P4=-84.8240 ;37.0000
P5=-84.8075 ;36.7500
P6=-84.7910 ;36.5000
P7=-84.7870 ;36.2500
P8=-84.7830 ;36.0000
P9=-84.8095 ;35.7500
P10=-84.8360 ;35.5000
P11=-84.8755 ;35.2500
P12=-84.9150 ;35.0000
P13=-84.9545 ;34.7500
P14=-84.9940 ;34.5000
P15=-85.0000 ;34.4680
P16=-85.0830 ;34.2340
P17=-85.1660 ;34.0000
P18=-85.2630 ;33.7500
P19=-85.3600 ;33.5000
P20=-85.5000 ;33.0890
P21=-85.5460 ;33.0000
P22=-85.6985 ;32.7500
P23=-85.8510 ;32.5000
P24=-86.0000 ;32.2130
P25=-86.1520 ;32.0000
P26=-86.3220 ;31.7500
P27=-86.4920 ;31.5000
P28=-86.5000 ;31.4890
P29=-86.7210 ;31.2445
P30=-86.9420 ;31.0000
P31=-87.0000 ;30.9370
P32=-87.2385 ;30.7185
P33=-87.4770 ;30.5000
P34=-87.5000 ;30.4810
P35=-87.7500 ;30.3060
P36=-88.0000 ;30.1310
P37=-88.2060 ;30.0000
P38=-88.5000 ;29.8420
P39=-88.7500 ;29.7290
P40=-89.0000 ;29.6160
P41=-89.3300 ;29.5000
P42=-89.5000 ;29.4580

P43=-90.0000 ;29.3850
P44=-90.5000 ;29.3660
P45=-91.0000 ;29.3970
P46=-91.5000 ;29.4780
P47=-91.5990 ;29.5000
P48=-92.0000 ;29.6530
P49=-92.2500 ;29.7740
P50=-92.5000 ;29.8950
P51=-92.7000 ;30.0000
P52=-93.0000 ;30.2100
P53=-93.3740 ;30.5000
P54=-93.5000 ;30.6210
P55=-93.6765 ;30.8105
P56=-93.8530 ;31.0000
P57=-94.0000 ;31.1900
P58=-94.2190 ;31.5000
P59=-94.3580 ;31.7500
P60=-94.4970 ;32.0000
P61=-94.5000 ;32.0070
P62=-94.6055 ;32.2535
P63=-94.7110 ;32.5000
P64=-94.7745 ;32.7500
P65=-94.8380 ;33.0000
P66=-94.8785 ;33.2500
P67=-94.9190 ;33.5000
P68=-94.9395 ;33.7500
P69=-94.9600 ;34.0000
P70=-94.9590 ;34.2500
P71=-94.9580 ;34.5000
P72=-94.9290 ;34.7500
P73=-94.9000 ;35.0000
P74=-94.8520 ;35.2500
P75=-94.8040 ;35.5000
P76=-94.7380 ;35.7500
P77=-94.6720 ;36.0000
P78=-94.5860 ;36.2435
P79=-94.5000 ;36.4870
P80=-94.4950 ;36.5000
P81=-94.3695 ;36.7500
P82=-94.2440 ;37.0000
P83=-94.1220 ;37.2395
P84=-94.0000 ;37.4790
P85=-93.9860 ;37.5000
P86=-93.8090 ;37.7500
P87=-93.6320 ;38.0000
P88=-93.5000 ;38.1880
P89=-93.2300 ;38.5000
P90=-93.0000 ;38.7490
P91=-92.7340 ;39.0000
P92=-92.5000 ;39.1950
P93=-92.1160 ;39.5000
P94=-92.0000 ;39.5780
P95=-91.7500 ;39.7335
P96=-91.5000 ;39.8890
P97=-91.3010 ;40.0000
P98=-91.0000 ;40.1360
P99=-90.5000 ;40.3360

P100=-90.0020 ;40.5000
P101=-90.0000 ;40.5010
P102=-89.5000 ;40.5810
P103=-89.0000 ;40.6190
P104=-88.5000 ;40.6120
P105=-88.0000 ;40.5530
P106=-87.7710 ;40.5000
P107=-87.5000 ;40.4190
P108=-87.0000 ;40.2120
P109=-86.5890 ;40.0000
P110=-86.5000 ;39.9420
P111=-86.2500 ;39.7420
P112=-86.0000 ;39.5420
P113=-85.9570 ;39.5000
P114=-85.7540 ;39.2500
P115=-85.5510 ;39.0000
P116=-85.5000 ;38.9290
P117=-85.2670 ;38.5000
P118=-85.1480 ;38.2500
P119=-85.0290 ;38.0000
P120=-85.0000 ;37.9230
[C10]
gain=-30.00
n_point=79
P1=-91.0000 ;41.1350
P2=-91.1667 ;41.1257
P3=-91.3333 ;41.1163
P4=-91.5000 ;41.1070
P5=-91.6400 ;41.0535
P6=-91.7800 ;41.0000
P7=-91.8900 ;40.9465
P8=-92.0000 ;40.8930
P9=-92.1667 ;40.8297
P10=-92.3333 ;40.7663
P11=-92.5000 ;40.7030
P12=-92.5943 ;40.6353
P13=-92.6887 ;40.5677
P14=-92.7830 ;40.5000
P15=-92.8915 ;40.4275
P16=-93.0000 ;40.3550
P17=-93.1080 ;40.2663
P18=-93.2160 ;40.1775
P19=-93.3240 ;40.0887
P20=-93.4320 ;40.0000
P21=-93.5000 ;39.9400
P22=-93.6020 ;39.8300
P23=-93.7040 ;39.7200
P24=-93.8060 ;39.6100
P25=-93.9080 ;39.5000
P26=-94.0000 ;39.3840
P27=-94.0713 ;39.2880
P28=-94.1425 ;39.1920
P29=-94.2137 ;39.0960
P30=-94.2850 ;39.0000
P31=-94.3567 ;38.8733
P32=-94.4283 ;38.7467
P33=-94.5000 ;38.6200

P34=-94.5810 ;38.5000
P35=-94.5945 ;38.3750
P36=-94.6080 ;38.2500
P37=-94.6215 ;38.1250
P38=-94.6350 ;38.0000
P39=-94.5675 ;37.9255
P40=-94.5000 ;37.8510
P41=-94.4555 ;37.9255
P42=-94.4110 ;38.0000
P43=-94.3083 ;38.0912
P44=-94.2055 ;38.1825
P45=-94.1028 ;38.2738
P46=-94.0000 ;38.3650
P47=-93.9470 ;38.4325
P48=-93.8940 ;38.5000
P49=-93.7955 ;38.6053
P50=-93.6970 ;38.7105
P51=-93.5985 ;38.8158
P52=-93.5000 ;38.9210
P53=-93.4240 ;39.0000
P54=-93.3180 ;39.1023
P55=-93.2120 ;39.2045
P56=-93.1060 ;39.3067
P57=-93.0000 ;39.4090
P58=-92.8990 ;39.5000
P59=-92.7993 ;39.5838
P60=-92.6995 ;39.6675
P61=-92.5997 ;39.7513
P62=-92.5000 ;39.8350
P63=-92.3945 ;39.9175
P64=-92.2890 ;40.0000
P65=-92.1927 ;40.0990
P66=-92.0963 ;40.1980
P67=-92.0000 ;40.2970
P68=-91.8797 ;40.3647
P69=-91.7593 ;40.4323
P70=-91.6390 ;40.5000
P71=-91.5695 ;40.6315
P72=-91.5000 ;40.7630
P73=-91.3333 ;40.8203
P74=-91.1667 ;40.8777
P75=-91.0000 ;40.9350
P76=-90.8975 ;40.9675
P77=-90.7950 ;41.0000
P78=-90.8975 ;41.0675
P79=-91.0000 ;41.1350
[C11]
gain=-30.00
n_point=83
P1=-84.0000 ;38.9360
P2=-84.0770 ;39.0000
P3=-84.1710 ;39.2500
P4=-84.2650 ;39.5000
P5=-84.3825 ;39.6555
P6=-84.5000 ;39.8110
P7=-84.6400 ;40.0000
P8=-84.8200 ;40.2110

P9=-85.0000 ;40.4220
P10=-85.1310 ;40.5000
P11=-85.3155 ;40.6440
P12=-85.5000 ;40.7880
P13=-85.6910 ;40.8940
P14=-85.8820 ;41.0000
P15=-86.0000 ;41.0690
P16=-86.2500 ;41.0365
P17=-86.5000 ;41.0040
P18=-86.5050 ;41.0000
P19=-86.5000 ;40.9980
P20=-86.3333 ;40.8390
P21=-86.1667 ;40.6800
P22=-86.0000 ;40.5210
P23=-85.9950 ;40.5000
P24=-85.8530 ;40.3333
P25=-85.7110 ;40.1667
P26=-85.5690 ;40.0000
P27=-85.5000 ;39.9330
P28=-85.3285 ;39.7165
P29=-85.1570 ;39.5000
P30=-85.0785 ;39.3665
P31=-85.0000 ;39.2330
P32=-84.8580 ;39.0000
P33=-84.7730 ;38.7500
P34=-84.6880 ;38.5000
P35=-84.6155 ;38.2500
P36=-84.5430 ;38.0000
P37=-84.5000 ;37.9070
P38=-84.4545 ;37.7035
P39=-84.4090 ;37.5000
P40=-84.3115 ;37.2500
P41=-84.2140 ;37.0000
P42=-84.2605 ;36.7500
P43=-84.3070 ;36.5000
P44=-84.3315 ;36.2500
P45=-84.3560 ;36.0000
P46=-84.3140 ;35.7500
P47=-84.2720 ;35.5000
P48=-84.3120 ;35.2500
P49=-84.3520 ;35.0000
P50=-84.5000 ;34.9240
P51=-84.5640 ;34.7120
P52=-84.6280 ;34.5000
P53=-84.6835 ;34.2500
P54=-84.7390 ;34.0000
P55=-84.7540 ;33.7500
P56=-84.7690 ;33.5000
P57=-84.6345 ;33.3145
P58=-84.5000 ;33.1290
P59=-84.3950 ;33.3145
P60=-84.2900 ;33.5000
P61=-84.2260 ;33.7500
P62=-84.1620 ;34.0000
P63=-84.1200 ;34.2500
P64=-84.0780 ;34.5000
P65=-84.0000 ;34.6510

P66=-83.9540 ;34.8255
P67=-83.9080 ;35.0000
P68=-83.8355 ;35.2500
P69=-83.7630 ;35.5000
P70=-83.6870 ;35.7500
P71=-83.6110 ;36.0000
P72=-83.6320 ;36.2500
P73=-83.6530 ;36.5000
P74=-83.6885 ;36.7500
P75=-83.7240 ;37.0000
P76=-83.6535 ;37.2500
P77=-83.5830 ;37.5000
P78=-83.6770 ;37.7500
P79=-83.7710 ;38.0000
P80=-83.7410 ;38.2500
P81=-83.7110 ;38.5000
P82=-83.8555 ;38.7180
P83=-84.0000 ;38.9360
[C12]
gain=-30.00
n_point=157
P1=-80.0000 ;39.1840
P2=-79.9780 ;39.0000
P3=-79.9620 ;38.5000
P4=-79.9490 ;38.0000
P5=-79.9550 ;37.5000
P6=-79.9890 ;37.0000
P7=-80.0000 ;36.7700
P8=-80.0250 ;36.5000
P9=-80.1680 ;36.0000
P10=-80.2850 ;35.5000
P11=-80.3920 ;35.0000
P12=-80.5000 ;34.6210
P13=-80.5500 ;34.5000
P14=-80.7710 ;34.0000
P15=-80.9440 ;33.5000
P16=-81.0000 ;33.3540
P17=-81.1940 ;33.0000
P18=-81.4360 ;32.5000
P19=-81.5000 ;32.3700
P20=-81.7470 ;32.0000
P21=-82.0000 ;31.5040
P22=-82.0030 ;31.5000
P23=-82.3730 ;31.0000
P24=-82.5000 ;30.7950
P25=-82.7360 ;30.5000
P26=-83.0000 ;30.1260
P27=-83.1080 ;30.0000
P28=-83.5000 ;29.5390
P29=-83.5370 ;29.5000
P30=-84.0000 ;29.0150
P31=-84.0160 ;29.0000
P32=-84.5000 ;28.5520
P33=-84.5590 ;28.5000
P34=-85.0000 ;28.1600
P35=-85.2080 ;28.0000
P36=-85.5000 ;27.7960

P37=-85.9120 ;27.5000
P38=-86.0000 ;27.4520
P39=-86.5000 ;27.1790
P40=-86.8080 ;27.0000
P41=-87.0000 ;26.9170
P42=-87.5000 ;26.7050
P43=-87.9360 ;26.5000
P44=-88.0000 ;26.4810
P45=-88.5000 ;26.3530
P46=-89.0000 ;26.2150
P47=-89.5000 ;26.0890
P48=-89.9160 ;26.0000
P49=-90.0000 ;25.9920
P50=-90.5000 ;25.9590
P51=-91.0000 ;25.9430
P52=-91.5000 ;25.9470
P53=-92.0000 ;25.9650
P54=-92.5000 ;25.9990
P55=-92.5140 ;26.0000
P56=-93.0000 ;26.1060
P57=-93.5000 ;26.2450
P58=-94.0000 ;26.3980
P59=-94.3290 ;26.5000
P60=-94.5000 ;26.5790
P61=-95.0000 ;26.8560
P62=-95.2940 ;27.0000
P63=-95.5000 ;27.1460
P64=-95.9630 ;27.5000
P65=-96.0000 ;27.5320
P66=-96.5000 ;27.9970
P67=-96.5030 ;28.0000
P68=-96.9120 ;28.5000
P69=-97.0000 ;28.6030
P70=-97.2710 ;29.0000
P71=-97.5000 ;29.3410
P72=-97.5960 ;29.5000
P73=-97.8770 ;30.0000
P74=-98.0000 ;30.2250
P75=-98.1330 ;30.5000
P76=-98.3220 ;31.0000
P77=-98.5000 ;31.4370
P78=-98.5280 ;31.5000
P79=-98.6750 ;32.0000
P80=-98.7840 ;32.5000
P81=-98.8710 ;33.0000
P82=-98.9340 ;33.5000
P83=-98.9710 ;34.0000
P84=-98.9750 ;34.5000
P85=-98.9440 ;35.0000
P86=-98.8850 ;35.5000
P87=-98.8010 ;36.0000
P88=-98.6940 ;36.5000
P89=-98.5770 ;37.0000
P90=-98.5000 ;37.2910
P91=-98.4200 ;37.5000
P92=-98.2220 ;38.0000
P93=-98.0420 ;38.5000

P94=-98.0000 ;38.6030
P95=-97.7700 ;39.0000
P96=-97.5330 ;39.5000
P97=-97.5000 ;39.5700
P98=-97.2080 ;40.0000
P99=-97.0000 ;40.3530
P100=-96.8910 ;40.5000
P101=-96.5360 ;41.0000
P102=-96.5000 ;41.0490
P103=-96.1110 ;41.5000
P104=-96.0000 ;41.6340
P105=-95.6590 ;42.0000
P106=-95.5000 ;42.1710
P107=-95.1700 ;42.5000
P108=-95.0000 ;42.6610
P109=-94.6320 ;43.0000
P110=-94.5000 ;43.1100
P111=-94.0390 ;43.5000
P112=-94.0000 ;43.5280
P113=-93.5000 ;43.8720
P114=-93.3170 ;44.0000
P115=-93.0000 ;44.1820
P116=-92.5040 ;44.5000
P117=-92.5000 ;44.5020
P118=-92.0000 ;44.7270
P119=-91.5000 ;44.9840
P120=-91.4640 ;45.0000
P121=-91.0000 ;45.1530
P122=-90.5000 ;45.3260
P123=-90.0000 ;45.4930
P124=-89.9730 ;45.5000
P125=-89.5000 ;45.5860
P126=-89.0000 ;45.6650
P127=-88.5000 ;45.7260
P128=-88.0000 ;45.7650
P129=-87.5000 ;45.7800
P130=-87.0000 ;45.7680
P131=-86.5000 ;45.7340
P132=-86.0000 ;45.6780
P133=-85.5000 ;45.6040
P134=-85.0000 ;45.5160
P135=-84.9290 ;45.5000
P136=-84.5000 ;45.3610
P137=-84.0000 ;45.1710
P138=-83.5680 ;45.0000
P139=-83.5000 ;44.9650
P140=-83.0000 ;44.6680
P141=-82.7370 ;44.5000
P142=-82.5000 ;44.3210
P143=-82.1020 ;44.0000
P144=-82.0000 ;43.9020
P145=-81.6580 ;43.5000
P146=-81.5000 ;43.3150
P147=-81.2790 ;43.0000
P148=-81.0000 ;42.5470
P149=-80.9800 ;42.5000
P150=-80.7440 ;42.0000

P151=-80.5330 ;41.5000
P152=-80.5000 ;41.4250
P153=-80.3820 ;41.0000
P154=-80.2810 ;40.5000
P155=-80.1350 ;40.0000
P156=-80.0660 ;39.5000
P157=-80.0000 ;39.1840
[C13]
gain=-40.00
n_point=96
P1=-89.5000 ;46.6330
P2=-89.7500 ;46.6420
P3=-90.0000 ;46.6510
P4=-90.2500 ;46.6505
P5=-90.5000 ;46.6500
P6=-90.7500 ;46.6110
P7=-91.0000 ;46.5720
P8=-91.1680 ;46.5000
P9=-91.3340 ;46.3735
P10=-91.5000 ;46.2470
P11=-91.7500 ;46.2000
P12=-92.0000 ;46.1530
P13=-92.3560 ;46.0000
P14=-92.5000 ;45.8920
P15=-92.7500 ;45.7775
P16=-93.0000 ;45.6630
P17=-93.2800 ;45.5000
P18=-93.5000 ;45.3480
P19=-93.7500 ;45.2225
P20=-94.0000 ;45.0970
P21=-94.1200 ;45.0000
P22=-94.3100 ;44.8395
P23=-94.5000 ;44.6790
P24=-94.7210 ;44.5000
P25=-95.0000 ;44.2880
P26=-95.1670 ;44.1440
P27=-95.3340 ;44.0000
P28=-95.5000 ;43.8820
P29=-95.6965 ;43.6910
P30=-95.8930 ;43.5000
P31=-96.0000 ;43.4080
P32=-96.1840 ;43.2040
P33=-96.3680 ;43.0000
P34=-96.5000 ;42.8480
P35=-96.6550 ;42.6740
P36=-96.8100 ;42.5000
P37=-97.0000 ;42.2470
P38=-97.2120 ;42.0000
P39=-97.3560 ;41.7540
P40=-97.5000 ;41.5080
P41=-97.5060 ;41.5000
P42=-97.6800 ;41.2500
P43=-97.8540 ;41.0000
P44=-98.0000 ;40.7200
P45=-98.1500 ;40.5000
P46=-98.1765 ;40.2500
P47=-98.2030 ;40.0000

P48=-98.0000 ;39.8200
P49=-97.9010 ;40.0000
P50=-97.7750 ;40.2500
P51=-97.6490 ;40.5000
P52=-97.5000 ;40.5600
P53=-97.3345 ;40.7800
P54=-97.1690 ;41.0000
P55=-97.0000 ;41.2360
P56=-96.7750 ;41.5000
P57=-96.6375 ;41.6780
P58=-96.5000 ;41.8560
P59=-96.3700 ;42.0000
P60=-96.1850 ;42.1910
P61=-96.0000 ;42.3820
P62=-95.8860 ;42.5000
P63=-95.6930 ;42.7000
P64=-95.5000 ;42.9000
P65=-95.3980 ;43.0000
P66=-95.1990 ;43.2065
P67=-95.0000 ;43.4130
P68=-94.9030 ;43.5000
P69=-94.7015 ;43.6765
P70=-94.5000 ;43.8530
P71=-94.3190 ;44.0000
P72=-94.1595 ;44.1160
P73=-94.0000 ;44.2320
P74=-93.8130 ;44.3660
P75=-93.6260 ;44.5000
P76=-93.5000 ;44.6480
P77=-93.2500 ;44.7675
P78=-93.0000 ;44.8870
P79=-92.8280 ;45.0000
P80=-92.6640 ;45.1410
P81=-92.5000 ;45.2820
P82=-92.2500 ;45.3590
P83=-92.0000 ;45.4360
P84=-91.8800 ;45.5000
P85=-91.6900 ;45.6635
P86=-91.5000 ;45.8270
P87=-91.2500 ;45.8750
P88=-91.0000 ;45.9230
P89=-90.7450 ;46.0000
P90=-90.5000 ;46.1930
P91=-90.2500 ;46.2890
P92=-90.0000 ;46.3850
P93=-89.7500 ;46.4275
P94=-89.5000 ;46.4700
P95=-89.2550 ;46.5000
P96=-89.5000 ;46.6330
[C14]
gain=-40.00
n_point=66
P1=-86.5000 ;47.0580
P2=-86.6000 ;47.0638
P3=-86.7000 ;47.0696
P4=-86.8000 ;47.0754
P5=-86.9000 ;47.0812

P6=-87.0000 ;47.0870
P7=-87.1000 ;47.0888
P8=-87.2000 ;47.0906
P9=-87.3000 ;47.0924
P10=-87.4000 ;47.0942
P11=-87.5000 ;47.0960
P12=-87.6000 ;47.0948
P13=-87.7000 ;47.0936
P14=-87.8000 ;47.0924
P15=-87.9000 ;47.0912
P16=-88.0000 ;47.0900
P17=-88.1000 ;47.0852
P18=-88.2000 ;47.0804
P19=-88.3000 ;47.0756
P20=-88.4000 ;47.0708
P21=-88.5000 ;47.0660
P22=-88.6000 ;47.0558
P23=-88.7000 ;47.0456
P24=-88.8000 ;47.0354
P25=-88.9000 ;47.0252
P26=-89.0000 ;47.0150
P27=-89.0800 ;47.0000
P28=-89.0533 ;46.9440
P29=-89.0267 ;46.8880
P30=-89.0000 ;46.8320
P31=-88.9000 ;46.8206
P32=-88.8000 ;46.8092
P33=-88.7000 ;46.7978
P34=-88.6000 ;46.7864
P35=-88.5000 ;46.7750
P36=-88.4000 ;46.7780
P37=-88.3000 ;46.7810
P38=-88.2000 ;46.7840
P39=-88.1000 ;46.7870
P40=-88.0000 ;46.7900
P41=-87.9000 ;46.7928
P42=-87.8000 ;46.7956
P43=-87.7000 ;46.7984
P44=-87.6000 ;46.8012
P45=-87.5000 ;46.8040
P46=-87.4000 ;46.8068
P47=-87.3000 ;46.8096
P48=-87.2000 ;46.8124
P49=-87.1000 ;46.8152
P50=-87.0000 ;46.8180
P51=-86.9000 ;46.8240
P52=-86.8000 ;46.8300
P53=-86.7000 ;46.8360
P54=-86.6000 ;46.8420
P55=-86.5000 ;46.8480
P56=-86.4175 ;46.8733
P57=-86.3350 ;46.8987
P58=-86.2525 ;46.9240
P59=-86.1700 ;46.9493
P60=-86.0875 ;46.9747
P61=-86.0050 ;47.0000
P62=-86.1040 ;47.0116

P63=-86.2030 ;47.0232
P64=-86.3020 ;47.0348
P65=-86.4010 ;47.0464
P66=-86.5000 ;47.0580
[C15]
gain=-40.00
n_point=93
P1=-79.5000 ;42.3010
P2=-79.6700 ;42.5000
P3=-79.7450 ;42.7500
P4=-79.8200 ;43.0000
P5=-79.9100 ;43.2310
P6=-80.0000 ;43.4620
P7=-80.0570 ;43.5000
P8=-80.1510 ;43.6667
P9=-80.2450 ;43.8333
P10=-80.3390 ;44.0000
P11=-80.4195 ;44.1245
P12=-80.5000 ;44.2490
P13=-80.6140 ;44.3745
P14=-80.7280 ;44.5000
P15=-80.8640 ;44.6790
P16=-81.0000 ;44.8580
P17=-81.1380 ;45.0000
P18=-81.3190 ;45.1295
P19=-81.5000 ;45.2590
P20=-81.6600 ;45.3795
P21=-81.8200 ;45.5000
P22=-82.0000 ;45.6120
P23=-82.2500 ;45.7185
P24=-82.5000 ;45.8250
P25=-82.6540 ;46.0000
P26=-82.8270 ;46.0860
P27=-83.0000 ;46.1720
P28=-83.2500 ;46.2340
P29=-83.5000 ;46.2960
P30=-83.6585 ;46.3980
P31=-83.8170 ;46.5000
P32=-84.0000 ;46.5720
P33=-84.2500 ;46.6310
P34=-84.5000 ;46.6900
P35=-84.7500 ;46.7015
P36=-85.0000 ;46.7130
P37=-85.2500 ;46.6585
P38=-85.5000 ;46.6040
P39=-85.6160 ;46.5000
P40=-85.5000 ;46.4770
P41=-85.2500 ;46.4205
P42=-85.0000 ;46.3640
P43=-84.7500 ;46.3240
P44=-84.5000 ;46.2840
P45=-84.2500 ;46.2345
P46=-84.0000 ;46.1850
P47=-83.9060 ;46.0000
P48=-83.7030 ;45.9220
P49=-83.5000 ;45.8440
P50=-83.2500 ;45.7825

P51=-83.0000 ;45.7210
P52=-82.8780 ;45.6105
P53=-82.7560 ;45.5000
P54=-82.5000 ;45.3670
P55=-82.2785 ;45.1835
P56=-82.0570 ;45.0000
P57=-82.0000 ;44.9530
P58=-81.8333 ;44.8100
P59=-81.6667 ;44.6670
P60=-81.5000 ;44.5240
P61=-81.4750 ;44.5000
P62=-81.3277 ;44.3333
P63=-81.1803 ;44.1667
P64=-81.0330 ;44.0000
P65=-81.0000 ;43.9540
P66=-80.8135 ;43.7270
P67=-80.6270 ;43.5000
P68=-80.5000 ;43.2640
P69=-80.3950 ;43.1320
P70=-80.2900 ;43.0000
P71=-80.2450 ;42.7500
P72=-80.2000 ;42.5000
P73=-80.1000 ;42.2745
P74=-80.0000 ;42.0490
P75=-79.9390 ;42.0000
P76=-79.8205 ;41.7500
P77=-79.7020 ;41.5000
P78=-79.6780 ;41.2500
P79=-79.6540 ;41.0000
P80=-79.6220 ;40.7500
P81=-79.5900 ;40.5000
P82=-79.5450 ;40.2925
P83=-79.5000 ;40.0850
P84=-79.4090 ;40.2925
P85=-79.3180 ;40.5000
P86=-79.3025 ;40.7500
P87=-79.2870 ;41.0000
P88=-79.3315 ;41.2500
P89=-79.3760 ;41.5000
P90=-79.3695 ;41.7500
P91=-79.3630 ;42.0000
P92=-79.4315 ;42.1505
P93=-79.5000 ;42.3010
[C16]
gain=-40.00
n_point=479
P1=-73.0000 ;46.7760
P2=-73.0660 ;47.0000
P3=-73.2800 ;47.5000
P4=-73.5000 ;47.9580
P5=-73.5200 ;48.0000
P6=-73.7920 ;48.5000
P7=-74.0000 ;48.8330
P8=-74.0930 ;49.0000
P9=-74.3940 ;49.5000
P10=-74.5000 ;49.6410
P11=-74.7450 ;50.0000

P12=-75.0000 ;50.3790
P13=-75.0860 ;50.5000
P14=-75.4660 ;51.0000
P15=-75.5000 ;51.0470
P16=-75.8210 ;51.5000
P17=-76.0000 ;51.7070
P18=-76.2820 ;52.0000
P19=-76.5000 ;52.2200
P20=-76.8150 ;52.5000
P21=-77.0000 ;52.6540
P22=-77.5000 ;52.9750
P23=-77.5450 ;53.0000
P24=-78.0000 ;53.2910
P25=-78.5000 ;53.4740
P26=-78.5840 ;53.5000
P27=-79.0000 ;53.6800
P28=-79.5000 ;53.8250
P29=-80.0000 ;53.9150
P30=-80.5000 ;53.9660
P31=-80.8780 ;54.0000
P32=-81.0000 ;54.0190
P33=-81.5000 ;54.0790
P34=-82.0000 ;54.1150
P35=-82.5000 ;54.1350
P36=-83.0000 ;54.1410
P37=-83.5000 ;54.1400
P38=-84.0000 ;54.1310
P39=-84.5000 ;54.1100
P40=-85.0000 ;54.0800
P41=-85.5000 ;54.0380
P42=-85.8730 ;54.0000
P43=-86.0000 ;53.9910
P44=-86.5000 ;53.9540
P45=-87.0000 ;53.9120
P46=-87.5000 ;53.8600
P47=-88.0000 ;53.7910
P48=-88.5000 ;53.6990
P49=-89.0000 ;53.5810
P50=-89.2860 ;53.5000
P51=-89.5000 ;53.4630
P52=-90.0000 ;53.3630
P53=-90.5000 ;53.2350
P54=-91.0000 ;53.0700
P55=-91.1850 ;53.0000
P56=-91.5000 ;52.9290
P57=-92.0000 ;52.7730
P58=-92.5000 ;52.5480
P59=-92.5940 ;52.5000
P60=-93.0000 ;52.3660
P61=-93.5000 ;52.1230
P62=-93.7080 ;52.0000
P63=-94.0000 ;51.8710
P64=-94.5000 ;51.5800
P65=-94.6170 ;51.5000
P66=-95.0000 ;51.2860
P67=-95.3860 ;51.0000
P68=-95.5000 ;50.9440

P69=-96.0000 ;50.6150
P70=-96.1480 ;50.5000
P71=-96.5000 ;50.2810
P72=-96.8370 ;50.0000
P73=-97.0000 ;49.8930
P74=-97.4440 ;49.5000
P75=-97.5000 ;49.4610
P76=-97.9940 ;49.0000
P77=-98.0000 ;48.9940
P78=-98.5000 ;48.5190
P79=-98.5190 ;48.5000
P80=-98.9970 ;48.0000
P81=-99.0000 ;47.9960
P82=-99.4500 ;47.5000
P83=-99.5000 ;47.4410
P84=-99.8770 ;47.0000
P85=-100.0000;46.8410
P86=-100.2780;46.5000
P87=-100.5000;46.1730
P88=-100.6370;46.0000
P89=-100.9680;45.5000
P90=-101.0000;45.4460
P91=-101.3420;45.0000
P92=-101.5000;44.6870
P93=-101.6290;44.5000
P94=-101.9100;44.0000
P95=-102.0000;43.8180
P96=-102.2030;43.5000
P97=-102.4010;43.0000
P98=-102.5000;42.7710
P99=-102.6450;42.5000
P100=-102.8360;42.0000
P101=-102.9970;41.5000
P102=-103.0000;41.4930
P103=-103.2340;41.0000
P104=-103.3760;40.5000
P105=-103.4970;40.0000
P106=-103.5000;39.9910
P107=-103.6370;39.5000
P108=-103.7150;39.0000
P109=-103.7880;38.5000
P110=-103.8620;38.0000
P111=-103.9220;37.5000
P112=-103.9810;37.0000
P113=-104.0000;36.7980
P114=-104.0170;36.5000
P115=-104.0220;36.0000
P116=-104.0040;35.5000
P117=-104.0000;35.4450
P118=-103.8420;35.0000
P119=-103.7350;34.5000
P120=-103.6880;34.0000
P121=-103.6570;33.5000
P122=-103.6220;33.0000
P123=-103.5660;32.5000
P124=-103.5000;32.1600
P125=-103.3800;32.5000

P126=-103.3760;33.0000
P127=-103.3940;33.5000
P128=-103.4160;34.0000
P129=-103.4350;34.5000
P130=-103.4420;35.0000
P131=-103.4290;35.5000
P132=-103.3940;36.0000
P133=-103.3450;36.5000
P134=-103.2940;37.0000
P135=-103.2370;37.5000
P136=-103.1760;38.0000
P137=-103.0660;38.5000
P138=-103.0000;38.6350
P139=-102.8990;39.0000
P140=-102.7880;39.5000
P141=-102.6580;40.0000
P142=-102.5000;40.3720
P143=-102.4410;40.5000
P144=-102.2020;41.0000
P145=-102.0240;41.5000
P146=-102.0000;41.5480
P147=-101.7490;42.0000
P148=-101.5440;42.5000
P149=-101.5000;42.5750
P150=-101.2510;43.0000
P151=-101.0000;43.4900
P152=-100.9930;43.5000
P153=-100.6530;44.0000
P154=-100.5000;44.2600
P155=-100.3160;44.5000
P156=-100.0000;44.9960
P157=-99.9970 ;45.0000
P158=-99.5620 ;45.5000
P159=-99.5000 ;45.5890
P160=-99.1280 ;46.0000
P161=-99.0000 ;46.1610
P162=-98.6800 ;46.5000
P163=-98.5000 ;46.7030
P164=-98.2070 ;47.0000
P165=-98.0000 ;47.2070
P166=-97.6970 ;47.5000
P167=-97.5000 ;47.6730
P168=-97.1440 ;48.0000
P169=-97.0000 ;48.1310
P170=-96.5710 ;48.5000
P171=-96.5000 ;48.5620
P172=-96.0000 ;48.9280
P173=-95.9040 ;49.0000
P174=-95.5000 ;49.2530
P175=-95.1590 ;49.5000
P176=-95.0000 ;49.6040
P177=-94.5000 ;49.9030
P178=-94.3480 ;50.0000
P179=-94.0000 ;50.1850
P180=-93.5000 ;50.4720
P181=-93.4500 ;50.5000
P182=-93.0000 ;50.6770

P183=-92.5000 ;50.9120
P184=-92.3060 ;51.0000
P185=-92.0000 ;51.0870
P186=-91.5000 ;51.2450
P187=-91.0000 ;51.4260
P188=-90.7860 ;51.5000
P189=-90.5000 ;51.5650
P190=-90.0000 ;51.6720
P191=-89.5000 ;51.7930
P192=-89.0000 ;51.9220
P193=-88.6900 ;52.0000
P194=-88.5000 ;52.0410
P195=-88.0000 ;52.1250
P196=-87.5000 ;52.1990
P197=-87.0000 ;52.2720
P198=-86.5000 ;52.3480
P199=-86.0000 ;52.4270
P200=-85.5290 ;52.5000
P201=-85.5000 ;52.5020
P202=-85.0000 ;52.5280
P203=-84.5000 ;52.5450
P204=-84.0000 ;52.5550
P205=-83.5000 ;52.5570
P206=-83.0000 ;52.5500
P207=-82.5000 ;52.5320
P208=-82.0600 ;52.5000
P209=-82.0000 ;52.4930
P210=-81.5000 ;52.4150
P211=-81.0000 ;52.3160
P212=-80.5000 ;52.2020
P213=-80.0000 ;52.0720
P214=-79.7890 ;52.0000
P215=-79.5000 ;51.8750
P216=-79.0000 ;51.6470
P217=-78.7290 ;51.5000
P218=-78.5000 ;51.3440
P219=-78.0110 ;51.0000
P220=-78.0000 ;50.9910
P221=-77.5000 ;50.5520
P222=-77.4510 ;50.5000
P223=-77.0000 ;50.0180
P224=-76.9840 ;50.0000
P225=-76.5490 ;49.5000
P226=-76.5000 ;49.4410
P227=-76.1800 ;49.0000
P228=-76.0000 ;48.7910
P229=-75.7800 ;48.5000
P230=-75.5000 ;48.1090
P231=-75.4350 ;48.0000
P232=-75.0850 ;47.5000
P233=-75.0000 ;47.3690
P234=-74.8270 ;47.0000
P235=-74.5480 ;46.5000
P236=-74.5000 ;46.4100
P237=-74.3500 ;46.0000
P238=-74.2090 ;45.5000
P239=-74.0210 ;45.0000

P240=-74.0000 ;44.8460
P241=-73.9580 ;44.5000
P242=-73.8860 ;44.0000
P243=-73.8730 ;43.5000
P244=-73.8470 ;43.0000
P245=-73.8890 ;42.5000
P246=-73.9150 ;42.0000
P247=-73.9590 ;41.5000
P248=-74.0000 ;41.3530
P249=-74.0850 ;41.0000
P250=-74.1150 ;40.5000
P251=-74.2550 ;40.0000
P252=-74.2890 ;39.5000
P253=-74.4300 ;39.0000
P254=-74.5000 ;38.7560
P255=-74.5520 ;38.5000
P256=-74.7270 ;38.0000
P257=-74.7750 ;37.5000
P258=-74.9490 ;37.0000
P259=-75.0000 ;36.8750
P260=-75.0960 ;36.5000
P261=-75.2770 ;36.0000
P262=-75.4080 ;35.5000
P263=-75.5000 ;35.2900
P264=-75.6440 ;35.0000
P265=-75.8410 ;34.5000
P266=-75.9600 ;34.0000
P267=-76.0000 ;33.9500
P268=-76.2630 ;33.5000
P269=-76.4330 ;33.0000
P270=-76.5000 ;32.8130
P271=-76.6670 ;32.5000
P272=-76.8920 ;32.0000
P273=-77.0000 ;31.9200
P274=-77.2910 ;31.5000
P275=-77.4820 ;31.0000
P276=-77.5000 ;30.9710
P277=-77.8020 ;30.5000
P278=-78.0000 ;30.2500
P279=-78.1980 ;30.0000
P280=-78.5000 ;29.5650
P281=-78.5540 ;29.5000
P282=-78.9070 ;29.0000
P283=-79.0000 ;28.8940
P284=-79.3390 ;28.5000
P285=-79.5000 ;28.3360
P286=-79.8070 ;28.0000
P287=-80.0000 ;27.7530
P288=-80.2450 ;27.5000
P289=-80.5000 ;27.2420
P290=-80.7400 ;27.0000
P291=-81.0000 ;26.7180
P292=-81.2250 ;26.5000
P293=-81.5000 ;26.2380
P294=-81.7610 ;26.0000
P295=-82.0000 ;25.7920
P296=-82.3290 ;25.5000

P297=-82.5000 ;25.3630
P298=-82.9480 ;25.0000
P299=-83.0000 ;24.9590
P300=-83.5000 ;24.5880
P301=-83.6120 ;24.5000
P302=-84.0000 ;24.2630
P303=-84.3730 ;24.0000
P304=-84.5000 ;23.9290
P305=-85.0000 ;23.6380
P306=-85.2160 ;23.5000
P307=-85.5000 ;23.3690
P308=-86.0000 ;23.1630
P309=-86.3090 ;23.0000
P310=-86.5000 ;22.9390
P311=-87.0000 ;22.7900
P312=-87.5000 ;22.5970
P313=-87.7760 ;22.5000
P314=-88.0000 ;22.4490
P315=-88.5000 ;22.3890
P316=-89.0000 ;22.3400
P317=-89.5000 ;22.2370
P318=-90.0000 ;22.1390
P319=-90.5000 ;22.0420
P320=-90.7460 ;22.0000
P321=-91.0000 ;21.9800
P322=-91.5000 ;21.9620
P323=-92.0000 ;21.9540
P324=-92.5000 ;21.9490
P325=-93.0000 ;21.9430
P326=-93.5000 ;21.9460
P327=-94.0000 ;21.9970
P328=-94.0120 ;22.0000
P329=-94.5000 ;22.1530
P330=-95.0000 ;22.3050
P331=-95.5000 ;22.4630
P332=-95.5960 ;22.5000
P333=-96.0000 ;22.7370
P334=-96.5000 ;22.9310
P335=-96.6000 ;23.0000
P336=-97.0000 ;23.2950
P337=-97.3570 ;23.5000
P338=-97.5000 ;23.6060
P339=-98.0000 ;23.9140
P340=-98.0960 ;24.0000
P341=-98.5000 ;24.3270
P342=-98.7580 ;24.5000
P343=-99.0000 ;24.7020
P344=-99.3560 ;25.0000
P345=-99.5000 ;25.1330
P346=-99.9020 ;25.5000
P347=-100.0000;25.5970
P348=-100.3890;26.0000
P349=-100.5000;26.1320
P350=-100.8210;26.5000
P351=-101.0000;26.7520
P352=-101.3100;27.0000
P353=-101.4660;27.5000

P354=-101.5000;27.5620
P355=-101.6650;27.5000
P356=-101.6260;27.0000
P357=-101.5000;26.7410
P358=-101.3200;26.5000
P359=-101.0980;26.0000
P360=-101.0000;25.8750
P361=-100.7180;25.5000
P362=-100.5000;25.2370
P363=-100.3070;25.0000
P364=-100.0000;24.6860
P365=-99.8390 ;24.5000
P366=-99.5000 ;24.1760
P367=-99.2980 ;24.0000
P368=-99.0000 ;23.7330
P369=-98.7270 ;23.5000
P370=-98.5000 ;23.3070
P371=-98.0560 ;23.0000
P372=-98.0000 ;22.9510
P373=-97.5000 ;22.5670
P374=-97.4130 ;22.5000
P375=-97.0000 ;22.1740
P376=-96.6040 ;22.0000
P377=-96.5000 ;21.9190
P378=-96.0000 ;21.5970
P379=-95.6940 ;21.5000
P380=-95.5000 ;21.3880
P381=-95.0000 ;21.1550
P382=-94.5000 ;21.0880
P383=-94.0000 ;21.0390
P384=-93.5700 ;21.0000
P385=-93.5000 ;20.9880
P386=-93.0000 ;20.9370
P387=-92.5000 ;20.9220
P388=-92.0000 ;20.9300
P389=-91.5000 ;20.9550
P390=-91.0000 ;20.9980
P391=-90.9820 ;21.0000
P392=-90.5000 ;21.0220
P393=-90.0000 ;21.0530
P394=-89.5000 ;21.0890
P395=-89.0000 ;21.1290
P396=-88.5000 ;21.2120
P397=-88.0000 ;21.3530
P398=-87.6160 ;21.5000
P399=-87.5000 ;21.5200
P400=-87.0000 ;21.6150
P401=-86.5000 ;21.8000
P402=-86.1390 ;22.0000
P403=-86.0000 ;22.0480
P404=-85.5000 ;22.2670
P405=-85.1640 ;22.5000
P406=-85.0000 ;22.5780
P407=-84.5000 ;22.8520
P408=-84.3030 ;23.0000
P409=-84.0000 ;23.1730
P410=-83.6110 ;23.5000

P411=-83.5000 ;23.5860
P412=-83.0000 ;23.9660
P413=-82.9620 ;24.0000
P414=-82.5000 ;24.3520
P415=-82.3430 ;24.5000
P416=-82.0000 ;24.7700
P417=-81.7580 ;25.0000
P418=-81.5000 ;25.2310
P419=-81.2280 ;25.5000
P420=-81.0000 ;25.7290
P421=-80.7230 ;26.0000
P422=-80.5000 ;26.2150
P423=-80.2190 ;26.5000
P424=-80.0000 ;26.7190
P425=-79.7320 ;27.0000
P426=-79.5000 ;27.2470
P427=-79.2640 ;27.5000
P428=-79.0000 ;27.8370
P429=-78.8550 ;28.0000
P430=-78.5000 ;28.4500
P431=-78.4560 ;28.5000
P432=-78.0790 ;29.0000
P433=-78.0000 ;29.1090
P434=-77.6960 ;29.5000
P435=-77.5000 ;29.7300
P436=-77.2780 ;30.0000
P437=-77.0000 ;30.4850
P438=-76.9880 ;30.5000
P439=-76.6200 ;31.0000
P440=-76.5000 ;31.3320
P441=-76.3880 ;31.5000
P442=-76.1570 ;32.0000
P443=-76.0000 ;32.1830
P444=-75.7800 ;32.5000
P445=-75.5820 ;33.0000
P446=-75.5000 ;33.2420
P447=-75.3480 ;33.5000
P448=-75.1360 ;34.0000
P449=-75.0080 ;34.5000
P450=-75.0000 ;34.5170
P451=-74.7560 ;35.0000
P452=-74.5950 ;35.5000
P453=-74.5000 ;35.8530
P454=-74.4390 ;36.0000
P455=-74.2440 ;36.5000
P456=-74.1900 ;37.0000
P457=-74.0090 ;37.5000
P458=-74.0000 ;37.5250
P459=-73.8940 ;38.0000
P460=-73.7330 ;38.5000
P461=-73.6730 ;39.0000
P462=-73.5280 ;39.5000
P463=-73.5000 ;39.5960
P464=-73.4260 ;40.0000
P465=-73.2630 ;40.5000
P466=-73.2310 ;41.0000
P467=-73.1010 ;41.5000

P468=-73.0000 ;41.9860
P469=-72.9960 ;42.0000
P470=-72.9220 ;42.5000
P471=-72.8040 ;43.0000
P472=-72.7800 ;43.5000
P473=-72.7050 ;44.0000
P474=-72.7090 ;44.5000
P475=-72.7120 ;45.0000
P476=-72.7230 ;45.5000
P477=-72.8070 ;46.0000
P478=-72.9120 ;46.5000
P479=-73.0000 ;46.7760

[C17]

gain=-50.00

n_point=74

P1=-78.0000 ;24.0850
P2=-78.0640 ;24.0425
P3=-78.1280 ;24.0000
P4=-78.2210 ;23.9220
P5=-78.3140 ;23.8440
P6=-78.4070 ;23.7660
P7=-78.5000 ;23.6880
P8=-78.6250 ;23.6855
P9=-78.7500 ;23.6830
P10=-78.8750 ;23.6805
P11=-79.0000 ;23.6780
P12=-79.0647 ;23.6187
P13=-79.1293 ;23.5593
P14=-79.1940 ;23.5000
P15=-79.2960 ;23.4317
P16=-79.3980 ;23.3633
P17=-79.5000 ;23.2950
P18=-79.5793 ;23.2213
P19=-79.6585 ;23.1475
P20=-79.7378 ;23.0737
P21=-79.8170 ;23.0000
P22=-79.8780 ;22.9193
P23=-79.9390 ;22.8387
P24=-80.0000 ;22.7580
P25=-80.0807 ;22.6935
P26=-80.1615 ;22.6290
P27=-80.2422 ;22.5645
P28=-80.3230 ;22.5000
P29=-80.3820 ;22.4260
P30=-80.4410 ;22.3520
P31=-80.5000 ;22.2780
P32=-80.5875 ;22.2085
P33=-80.6750 ;22.1390
P34=-80.7625 ;22.0695
P35=-80.8500 ;22.0000
P36=-80.7625 ;21.9503
P37=-80.6750 ;21.9005
P38=-80.5875 ;21.8507
P39=-80.5000 ;21.8010
P40=-80.4280 ;21.8673
P41=-80.3560 ;21.9337
P42=-80.2840 ;22.0000

P43=-80.2130 ;22.0592
P44=-80.1420 ;22.1185
P45=-80.0710 ;22.1778
P46=-80.0000 ;22.2370
P47=-79.9250 ;22.3027
P48=-79.8500 ;22.3685
P49=-79.7750 ;22.4343
P50=-79.7000 ;22.5000
P51=-79.6333 ;22.5487
P52=-79.5667 ;22.5973
P53=-79.5000 ;22.6460
P54=-79.4196 ;22.7168
P55=-79.3392 ;22.7876
P56=-79.2588 ;22.8584
P57=-79.1784 ;22.9292
P58=-79.0980 ;23.0000
P59=-79.0490 ;23.0895
P60=-79.0000 ;23.1790
P61=-78.9000 ;23.2350
P62=-78.8000 ;23.2910
P63=-78.7000 ;23.3470
P64=-78.6000 ;23.4030
P65=-78.5000 ;23.4590
P66=-78.4570 ;23.5000
P67=-78.3808 ;23.5792
P68=-78.3047 ;23.6583
P69=-78.2285 ;23.7375
P70=-78.1523 ;23.8167
P71=-78.0762 ;23.8958
P72=-78.0000 ;23.9750
P73=-77.9740 ;24.0000
P74=-78.0000 ;24.0850
[C18]
gain=-50.00
n_point=85
P1=-84.5000 ;19.7150
P2=-84.7500 ;19.6940
P3=-85.0000 ;19.6730
P4=-85.1650 ;19.5865
P5=-85.3300 ;19.5000
P6=-85.4150 ;19.4055
P7=-85.5000 ;19.3110
P8=-85.7500 ;19.3320
P9=-86.0000 ;19.3530
P10=-86.1667 ;19.2707
P11=-86.3333 ;19.1883
P12=-86.5000 ;19.1060
P13=-86.7230 ;19.0000
P14=-86.8615 ;18.9370
P15=-87.0000 ;18.8740
P16=-87.1667 ;18.8117
P17=-87.3333 ;18.7493
P18=-87.5000 ;18.6870
P19=-87.7500 ;18.6815
P20=-88.0000 ;18.6760
P21=-88.2500 ;18.6760
P22=-88.5000 ;18.6760

P23=-88.7000 ;18.5880
P24=-88.9000 ;18.5000
P25=-88.9500 ;18.2855
P26=-89.0000 ;18.0710
P27=-89.1667 ;18.1377
P28=-89.3333 ;18.2043
P29=-89.5000 ;18.2710
P30=-89.6667 ;18.2967
P31=-89.8333 ;18.3223
P32=-90.0000 ;18.3480
P33=-90.1667 ;18.3107
P34=-90.3333 ;18.2733
P35=-90.5000 ;18.2360
P36=-90.6667 ;18.1903
P37=-90.8333 ;18.1447
P38=-91.0000 ;18.0990
P39=-91.2185 ;18.0495
P40=-91.4370 ;18.0000
P41=-91.2185 ;17.9015
P42=-91.0000 ;17.8030
P43=-90.8333 ;17.7720
P44=-90.6667 ;17.7410
P45=-90.5000 ;17.7100
P46=-90.2500 ;17.6815
P47=-90.0000 ;17.6530
P48=-89.8333 ;17.7010
P49=-89.6667 ;17.7490
P50=-89.5000 ;17.7970
P51=-89.3333 ;17.8610
P52=-89.1667 ;17.9250
P53=-89.0000 ;17.9890
P54=-88.9670 ;18.0000
P55=-88.8113 ;18.0610
P56=-88.6557 ;18.1220
P57=-88.5000 ;18.1830
P58=-88.3333 ;18.2137
P59=-88.1667 ;18.2443
P60=-88.0000 ;18.2750
P61=-87.7500 ;18.3035
P62=-87.5000 ;18.3320
P63=-87.3333 ;18.3023
P64=-87.1667 ;18.2727
P65=-87.0000 ;18.2430
P66=-86.8557 ;18.3287
P67=-86.7113 ;18.4143
P68=-86.5670 ;18.5000
P69=-86.5000 ;18.6810
P70=-86.2500 ;18.6520
P71=-86.0000 ;18.6230
P72=-85.8333 ;18.6917
P73=-85.6667 ;18.7603
P74=-85.5000 ;18.8290
P75=-85.3595 ;18.9145
P76=-85.2190 ;19.0000
P77=-85.1095 ;19.0995
P78=-85.0000 ;19.1990
P79=-84.8333 ;19.2383

P80=-84.6667 ;19.2777
P81=-84.5000 ;19.3170
P82=-84.3260 ;19.4085
P83=-84.1520 ;19.5000
P84=-84.3260 ;19.6075
P85=-84.5000 ;19.7150
[C19]
gain=-50.00
n_point=203
P1=-73.5000 ;63.0500
P2=-74.0000 ;63.1140
P3=-74.5000 ;63.1460
P4=-75.0000 ;63.1400
P5=-75.5000 ;63.1240
P6=-76.0000 ;63.0950
P7=-76.5000 ;63.0620
P8=-77.0000 ;63.0300
P9=-77.4720 ;63.0000
P10=-77.5000 ;62.9980
P11=-78.0000 ;62.9680
P12=-78.5000 ;62.9370
P13=-79.0000 ;62.9060
P14=-79.5000 ;62.8730
P15=-80.0000 ;62.8340
P16=-80.5000 ;62.7850
P17=-81.0000 ;62.7250
P18=-81.5000 ;62.6340
P19=-82.0000 ;62.5230
P20=-82.0920 ;62.5000
P21=-82.5000 ;62.3530
P22=-83.0000 ;62.2050
P23=-83.5000 ;62.0650
P24=-83.7290 ;62.0000
P25=-84.0000 ;61.6910
P26=-84.5000 ;61.6450
P27=-85.0000 ;61.6510
P28=-85.5000 ;61.6430
P29=-86.0000 ;61.5980
P30=-86.4180 ;61.5000
P31=-86.5000 ;61.4830
P32=-87.0000 ;61.3460
P33=-87.5000 ;61.1710
P34=-87.9280 ;61.0000
P35=-88.0000 ;60.8930
P36=-88.5000 ;60.7020
P37=-89.0000 ;60.6620
P38=-89.5000 ;60.6060
P39=-89.8540 ;60.5000
P40=-90.0000 ;60.4640
P41=-90.5000 ;60.2980
P42=-91.0000 ;60.0720
P43=-91.1570 ;60.0000
P44=-91.5000 ;59.7990
P45=-92.0000 ;59.7080
P46=-92.5000 ;59.5980
P47=-92.7260 ;59.5000
P48=-93.0000 ;59.3460

P49=-93.5000 ;59.0910
P50=-93.6810 ;59.0000
P51=-94.0000 ;58.8660
P52=-94.5000 ;58.7580
P53=-94.9990 ;58.5000
P54=-95.0000 ;58.4980
P55=-95.5000 ;58.1640
P56=-95.9010 ;58.0000
P57=-96.0000 ;57.9740
P58=-96.5000 ;57.7340
P59=-96.8030 ;57.5000
P60=-97.0000 ;57.3530
P61=-97.5000 ;57.1130
P62=-97.6700 ;57.0000
P63=-98.0000 ;56.7240
P64=-98.3320 ;56.5000
P65=-98.5000 ;56.4160
P66=-98.9660 ;56.0000
P67=-99.0000 ;55.9510
P68=-99.5000 ;55.6810
P69=-99.7050 ;55.5000
P70=-100.0000;55.2150
P71=-100.2470;55.0000
P72=-100.5000;54.6750
P73=-100.6900;54.5000
P74=-101.0000;54.3310
P75=-101.2950;54.0000
P76=-101.5000;53.8400
P77=-101.8370;53.5000
P78=-102.0000;53.3540
P79=-102.3360;53.0000
P80=-102.5000;52.8260
P81=-102.8010;52.5000
P82=-103.0000;52.1530
P83=-103.1320;52.0000
P84=-103.4510;51.5000
P85=-103.5000;51.4340
P86=-103.8690;51.0000
P87=-104.0000;50.8090
P88=-104.2680;50.5000
P89=-104.5000;50.0390
P90=-104.5310;50.0000
P91=-104.7130;49.5000
P92=-104.8990;49.0000
P93=-105.0000;48.9310
P94=-105.2220;48.5000
P95=-105.5000;48.1520
P96=-105.6030;48.0000
P97=-105.7810;47.5000
P98=-106.0000;47.0060
P99=-106.0030;47.0000
P100=-106.1100;46.5000
P101=-106.2880;46.0000
P102=-106.0000;45.8390
P103=-105.9060;46.0000
P104=-105.8840;46.5000
P105=-105.9730;47.0000

P106=-105.5000;47.0710
P107=-105.2490;47.5000
P108=-105.0000;47.8380
P109=-104.8960;48.0000
P110=-104.7140;48.5000
P111=-104.5000;48.7710
P112=-104.3610;49.0000
P113=-104.0000;49.4480
P114=-103.9610;49.5000
P115=-103.6000;50.0000
P116=-103.5000;50.0940
P117=-103.1930;50.5000
P118=-103.0000;50.7450
P119=-102.7910;51.0000
P120=-102.5000;51.3850
P121=-102.3990;51.5000
P122=-102.0010;52.0000
P123=-102.0000;52.0010
P124=-101.5810;52.5000
P125=-101.5000;52.6480
P126=-101.1850;53.0000
P127=-101.0000;53.2670
P128=-100.7730;53.5000
P129=-100.5000;53.7070
P130=-100.1990;54.0000
P131=-100.0000;54.1560
P132=-99.5500 ;54.5000
P133=-99.5000 ;54.5770
P134=-99.0000 ;54.9830
P135=-98.9770 ;55.0000
P136=-98.5000 ;55.3970
P137=-98.3510 ;55.5000
P138=-98.0000 ;55.6620
P139=-97.5890 ;56.0000
P140=-97.5000 ;56.1390
P141=-97.0000 ;56.3260
P142=-96.7360 ;56.5000
P143=-96.5000 ;56.7880
P144=-96.0000 ;56.9740
P145=-95.9490 ;57.0000
P146=-95.5000 ;57.1890
P147=-95.0040 ;57.5000
P148=-95.0000 ;57.5070
P149=-94.5000 ;57.7410
P150=-94.0000 ;57.8780
P151=-93.7300 ;58.0000
P152=-93.5000 ;58.1990
P153=-93.0000 ;58.4240
P154=-92.7540 ;58.5000
P155=-92.5000 ;58.5570
P156=-92.0000 ;58.6650
P157=-91.5000 ;58.8520
P158=-91.1550 ;59.0000
P159=-91.0000 ;59.1710
P160=-90.5000 ;59.3450
P161=-90.0000 ;59.3950
P162=-89.5930 ;59.5000

P163=-89.5000 ;59.5190
P164=-89.0000 ;59.6550
P165=-88.5000 ;59.8480
P166=-88.1310 ;60.0000
P167=-88.0000 ;60.1760
P168=-87.5000 ;60.3460
P169=-87.0000 ;60.3800
P170=-86.5000 ;60.4240
P171=-86.1640 ;60.5000
P172=-86.0000 ;60.5290
P173=-85.5000 ;60.6530
P174=-85.0000 ;60.8040
P175=-84.5000 ;60.9750
P176=-84.4230 ;61.0000
P177=-84.0000 ;61.3970
P178=-83.5000 ;61.4930
P179=-83.4420 ;61.5000
P180=-83.0000 ;61.5770
P181=-82.5000 ;61.5990
P182=-82.0000 ;61.6250
P183=-81.5000 ;61.6620
P184=-81.0000 ;61.7130
P185=-80.5000 ;61.7730
P186=-80.0000 ;61.8420
P187=-79.5000 ;61.9120
P188=-79.0000 ;61.9790
P189=-78.8310 ;62.0000
P190=-78.5000 ;62.0600
P191=-78.0000 ;62.1110
P192=-77.5000 ;62.1400
P193=-77.0000 ;62.1670
P194=-76.5000 ;62.1950
P195=-76.0000 ;62.2200
P196=-75.5000 ;62.2500
P197=-75.0000 ;62.2810
P198=-74.5000 ;62.3330
P199=-74.0000 ;62.4220
P200=-73.7930 ;62.5000
P201=-73.5000 ;62.7570
P202=-73.2670 ;63.0000
P203=-73.5000 ;63.0500
[C20]
gain=-50.00
n_point=340
P1=-69.8959 ;79.8378
P2=-70.3110 ;79.7130
P3=-70.5000 ;79.6550
P4=-70.9280 ;79.5000
P5=-71.0000 ;79.4800
P6=-71.5000 ;79.3570
P7=-72.0000 ;79.2030
P8=-72.5000 ;79.0100
P9=-72.5310 ;79.0000
P10=-73.0000 ;78.8800
P11=-73.5000 ;78.7160
P12=-74.0000 ;78.5220
P13=-74.0630 ;78.5000

P14=-74.5000 ;78.3720
P15=-75.0000 ;78.1910
P16=-75.5000 ;78.0030
P17=-75.5080 ;78.0000
P18=-76.0000 ;77.8330
P19=-76.5000 ;77.6620
P20=-76.9690 ;77.5000
P21=-77.0000 ;77.4890
P22=-77.5000 ;77.3040
P23=-78.0000 ;77.1610
P24=-78.5000 ;77.0330
P25=-78.6020 ;77.0000
P26=-79.0000 ;76.8680
P27=-79.5000 ;76.7360
P28=-80.0000 ;76.5880
P29=-80.2470 ;76.5000
P30=-80.5000 ;76.4230
P31=-81.0000 ;76.2590
P32=-81.5000 ;76.0760
P33=-81.6890 ;76.0000
P34=-82.0000 ;75.8940
P35=-82.5000 ;75.7130
P36=-83.0000 ;75.5040
P37=-83.0090 ;75.5000
P38=-83.5000 ;75.3150
P39=-84.0000 ;75.0960
P40=-84.1940 ;75.0000
P41=-84.5000 ;74.8670
P42=-85.0000 ;74.6350
P43=-85.2770 ;74.5000
P44=-85.5000 ;74.4030
P45=-86.0000 ;74.1630
P46=-86.3110 ;74.0000
P47=-86.5000 ;73.9070
P48=-87.0000 ;73.6610
P49=-87.2890 ;73.5000
P50=-87.5000 ;73.4210
P51=-88.0000 ;73.2720
P52=-88.5000 ;73.1050
P53=-88.7760 ;73.0000
P54=-89.0000 ;72.9240
P55=-89.5000 ;72.7320
P56=-89.9610 ;72.5000
P57=-90.0000 ;72.4820
P58=-90.5000 ;72.2260
P59=-90.9210 ;72.0000
P60=-91.0000 ;71.9570
P61=-91.5000 ;71.6720
P62=-91.7720 ;71.5000
P63=-92.0000 ;71.3860
P64=-92.5000 ;71.1750
P65=-92.8550 ;71.0000
P66=-93.0000 ;70.9490
P67=-93.5000 ;70.7640
P68=-94.0000 ;70.5080
P69=-94.0150 ;70.5000
P70=-94.5000 ;70.2200

P71=-94.8680 ;70.0000
P72=-95.0000 ;69.9180
P73=-95.5000 ;69.5430
P74=-95.5630 ;69.5000
P75=-96.0000 ;69.3520
P76=-96.5000 ;69.1590
P77=-96.8390 ;69.0000
P78=-97.0000 ;68.9210
P79=-97.5000 ;68.5970
P80=-97.6600 ;68.5000
P81=-98.0000 ;68.2750
P82=-98.3430 ;68.0000
P83=-98.5000 ;67.9360
P84=-99.0000 ;67.7360
P85=-99.4410 ;67.5000
P86=-99.5000 ;67.4630
P87=-100.0000;67.1000
P88=-100.1320;67.0000
P89=-100.5000;66.7460
P90=-100.8400;66.5000
P91=-101.0000;66.4120
P92=-101.5000;66.0420
P93=-101.5510;66.0000
P94=-102.0000;65.5230
P95=-102.0210;65.5000
P96=-102.5000;65.1510
P97=-102.6800;65.0000
P98=-103.0000;64.5950
P99=-103.0780;64.5000
P100=-103.5000;64.1790
P101=-103.6880;64.0000
P102=-104.0000;63.5490
P103=-104.0360;63.5000
P104=-104.5000;63.1050
P105=-104.6060;63.0000
P106=-104.9330;62.5000
P107=-105.0000;62.4480
P108=-105.4890;62.0000
P109=-105.5000;61.9770
P110=-105.8360;61.5000
P111=-106.0000;61.3460
P112=-106.3310;61.0000
P113=-106.5000;60.7490
P114=-106.6850;60.5000
P115=-107.0000;60.0170
P116=-107.0110;60.0000
P117=-107.3900;59.5000
P118=-107.5000;59.1990
P119=-107.6010;59.0000
P120=-107.9260;58.5000
P121=-108.0000;58.3810
P122=-108.2930;58.0000
P123=-108.4830;57.5000
P124=-108.5000;57.4760
P125=-108.8690;57.0000
P126=-109.0000;56.7250
P127=-109.1650;56.5000

P128=-109.3530;56.0000
P129=-109.5000;55.5720
P130=-109.5350;55.5000
P131=-109.7860;55.0000
P132=-109.9630;54.5000
P133=-110.0000;54.4180
P134=-110.1760;54.0000
P135=-110.3400;53.5000
P136=-110.5000;53.1310
P137=-110.5560;53.0000
P138=-110.8350;52.5000
P139=-110.9750;52.0000
P140=-111.0000;51.9130
P141=-111.1200;51.5000
P142=-111.2710;51.0000
P143=-111.4470;50.5000
P144=-111.5000;50.3670
P145=-111.6790;50.0000
P146=-111.6980;49.5000
P147=-111.8680;49.0000
P148=-112.0000;48.5690
P149=-112.0290;48.5000
P150=-112.1290;48.0000
P151=-112.2140;47.5000
P152=-112.3310;47.0000
P153=-112.3980;46.5000
P154=-112.4850;46.0000
P155=-112.5000;45.9860
P156=-112.6160;45.5000
P157=-112.6830;45.0000
P158=-112.6360;44.5000
P159=-112.7150;44.0000
P160=-112.7830;43.5000
P161=-112.6440;43.0000
P162=-112.6720;42.5000
P163=-112.7370;42.0000
P164=-112.5030;41.5000
P165=-112.5000;41.4970
P166=-112.5000;41.5000
P167=-112.4270;42.0000
P168=-112.4370;42.5000
P169=-112.4450;43.0000
P170=-112.3070;43.5000
P171=-112.3060;44.0000
P172=-112.3330;44.5000
P173=-112.1960;45.0000
P174=-112.0000;45.3530
P175=-111.9530;45.5000
P176=-111.8860;46.0000
P177=-111.8390;46.5000
P178=-111.6890;47.0000
P179=-111.5000;47.4910
P180=-111.4960;47.5000
P181=-111.3940;48.0000
P182=-111.2580;48.5000
P183=-111.0840;49.0000
P184=-111.0000;49.2390

P185=-110.8950;49.5000
P186=-110.7730;50.0000
P187=-110.5750;50.5000
P188=-110.5000;50.6880
P189=-110.3370;51.0000
P190=-110.2060;51.5000
P191=-110.0000;51.8440
P192=-109.9150;52.0000
P193=-109.7200;52.5000
P194=-109.5400;53.0000
P195=-109.5000;53.0800
P196=-109.2630;53.5000
P197=-109.0660;54.0000
P198=-109.0000;54.1130
P199=-108.8120;54.5000
P200=-108.5490;55.0000
P201=-108.5000;55.0830
P202=-108.2590;55.5000
P203=-108.0220;56.0000
P204=-108.0000;56.0330
P205=-107.6120;56.5000
P206=-107.5000;56.7300
P207=-107.2880;57.0000
P208=-107.0360;57.5000
P209=-107.0000;57.5650
P210=-106.6380;58.0000
P211=-106.5000;58.2450
P212=-106.3070;58.5000
P213=-106.0000;58.9920
P214=-105.9950;59.0000
P215=-105.5760;59.5000
P216=-105.5000;59.6060
P217=-105.1850;60.0000
P218=-105.0000;60.1680
P219=-104.7240;60.5000
P220=-104.5000;60.7260
P221=-104.2060;61.0000
P222=-104.0000;61.2900
P223=-103.8160;61.5000
P224=-103.5000;61.7230
P225=-103.1430;62.0000
P226=-103.0000;62.1820
P227=-102.6650;62.5000
P228=-102.5000;62.6160
P229=-102.0000;62.9790
P230=-101.9740;63.0000
P231=-101.5000;63.4390
P232=-101.4270;63.5000
P233=-101.0000;63.8000
P234=-100.7220;64.0000
P235=-100.5000;64.2000
P236=-100.1340;64.5000
P237=-100.0000;64.5690
P238=-99.5000 ;64.8860
P239=-99.3140 ;65.0000
P240=-99.0000 ;65.2380
P241=-98.6780 ;65.5000

P242=-98.5000 ;65.5850
P243=-98.0000 ;65.8060
P244=-97.6130 ;66.0000
P245=-97.5000 ;66.0650
P246=-97.0000 ;66.4060
P247=-96.8440 ;66.5000
P248=-96.5000 ;66.6740
P249=-96.0000 ;66.8680
P250=-95.7420 ;67.0000
P251=-95.5000 ;67.1010
P252=-95.0000 ;67.3450
P253=-94.7100 ;67.5000
P254=-94.5000 ;67.6240
P255=-94.0000 ;67.9370
P256=-93.8970 ;68.0000
P257=-93.5000 ;68.1590
P258=-93.0000 ;68.3140
P259=-92.6060 ;68.5000
P260=-92.5000 ;68.5470
P261=-92.0000 ;68.7890
P262=-91.5970 ;69.0000
P263=-91.5000 ;69.0530
P264=-91.0000 ;69.3560
P265=-90.7490 ;69.5000
P266=-90.5000 ;69.6210
P267=-90.0000 ;69.8050
P268=-89.5000 ;69.9940
P269=-89.4880 ;70.0000
P270=-89.0000 ;70.1870
P271=-88.5000 ;70.4330
P272=-88.3540 ;70.5000
P273=-88.0000 ;70.6610
P274=-87.5000 ;70.9190
P275=-87.3480 ;71.0000
P276=-87.0000 ;71.1870
P277=-86.5000 ;71.4640
P278=-86.4320 ;71.5000
P279=-86.0000 ;71.6880
P280=-85.5000 ;71.8280
P281=-85.0000 ;71.9870
P282=-84.9680 ;72.0000
P283=-84.5000 ;72.1520
P284=-84.0000 ;72.3330
P285=-83.5880 ;72.5000
P286=-83.5000 ;72.5340
P287=-83.0000 ;72.7240
P288=-82.5000 ;72.9380
P289=-82.3660 ;73.0000
P290=-82.0000 ;73.1550
P291=-81.5000 ;73.3730
P292=-81.2120 ;73.5000
P293=-81.0000 ;73.5840
P294=-80.5000 ;73.7990
P295=-80.0400 ;74.0000
P296=-80.0000 ;74.0210
P297=-79.5000 ;74.2420
P298=-79.0000 ;74.4230

P299=-78.8020 ;74.5000
P300=-78.5000 ;74.6220
P301=-78.0000 ;74.7730
P302=-77.5000 ;74.9020
P303=-77.0710 ;75.0000
P304=-77.0000 ;75.0210
P305=-76.5000 ;75.1640
P306=-76.0000 ;75.2920
P307=-75.5000 ;75.4120
P308=-75.2250 ;75.5000
P309=-75.0000 ;75.5770
P310=-74.5000 ;75.7120
P311=-74.0000 ;75.8670
P312=-73.6110 ;76.0000
P313=-73.5000 ;76.0330
P314=-73.0000 ;76.1780
P315=-72.5000 ;76.3290
P316=-72.0280 ;76.5000
P317=-72.0000 ;76.5080
P318=-71.5000 ;76.6360
P319=-71.0000 ;76.7870
P320=-70.5000 ;76.9520
P321=-70.3460 ;77.0000
P322=-70.0000 ;77.0870
P323=-69.5000 ;77.2330
P324=-69.0000 ;77.3840
P325=-68.6140 ;77.5000
P326=-68.5000 ;77.5280
P327=-68.0000 ;77.6620
P328=-67.5000 ;77.8040
P329=-67.0000 ;77.9430
P330=-66.8110 ;78.0000
P331=-66.5000 ;78.0760
P332=-66.0000 ;78.2110
P333=-65.5000 ;78.3350
P334=-65.0000 ;78.4740
P335=-64.9140 ;78.5000
P336=-64.5000 ;78.5980
P337=-64.0000 ;78.7210
P338=-63.5000 ;78.8380
P339=-63.4980 ;78.8380
P340=-62.2801 ;78.8355
[C21]
gain=-50.00
n_point=240
P1=-118.1616;80.9028
P2=-117.8910;80.7650
P3=-117.5000;80.5580
P4=-117.4050;80.5000
P5=-117.0000;80.2490
P6=-116.6120;80.0000
P7=-116.5000;79.9170
P8=-116.0000;79.5420
P9=-115.9460;79.5000
P10=-115.5000;79.0970
P11=-115.3940;79.0000
P12=-115.0000;78.5560

P13=-114.9500;78.5000
P14=-114.6140;78.0000
P15=-114.5000;77.7930
P16=-114.3510;77.5000
P17=-114.1440;77.0000
P18=-114.0560;76.5000
P19=-114.0380;76.0000
P20=-114.0000;75.8810
P21=-113.8690;75.5000
P22=-113.7490;75.0000
P23=-113.7200;74.5000
P24=-113.7820;74.0000
P25=-114.0000;73.5460
P26=-114.0250;73.5000
P27=-114.0180;73.0000
P28=-114.0000;72.8490
P29=-113.9450;72.5000
P30=-114.0000;72.1010
P31=-114.0140;72.0000
P32=-114.2600;71.5000
P33=-114.2160;71.0000
P34=-114.2040;70.5000
P35=-114.3240;70.0000
P36=-114.4540;69.5000
P37=-114.3890;69.0000
P38=-114.5000;68.6340
P39=-114.5370;68.5000
P40=-114.6140;68.0000
P41=-114.6390;67.5000
P42=-114.7980;67.0000
P43=-114.8480;66.5000
P44=-115.0000;66.1380
P45=-115.0470;66.0000
P46=-115.0730;65.5000
P47=-115.1900;65.0000
P48=-115.3020;64.5000
P49=-115.3610;64.0000
P50=-115.4880;63.5000
P51=-115.5000;63.4610
P52=-115.5980;63.0000
P53=-115.6630;62.5000
P54=-115.7900;62.0000
P55=-115.9090;61.5000
P56=-116.0000;61.1780
P57=-116.0380;61.0000
P58=-116.1040;60.5000
P59=-116.1900;60.0000
P60=-116.2500;59.5000
P61=-116.2920;59.0000
P62=-116.4050;58.5000
P63=-116.4470;58.0000
P64=-116.5000;57.8550
P65=-116.5850;57.5000
P66=-116.7000;57.0000
P67=-116.7710;56.5000
P68=-116.8640;56.0000
P69=-116.8750;55.5000

P70=-117.0000;55.0640
P71=-117.0140;55.0000
P72=-117.0520;54.5000
P73=-117.0920;54.0000
P74=-117.1520;53.5000
P75=-117.2430;53.0000
P76=-117.2930;52.5000
P77=-117.3700;52.0000
P78=-117.3740;51.5000
P79=-117.4740;51.0000
P80=-117.4650;50.5000
P81=-117.5000;50.3080
P82=-117.5510;50.0000
P83=-117.5960;49.5000
P84=-117.6340;49.0000
P85=-117.6420;48.5000
P86=-117.6960;48.0000
P87=-117.6620;47.5000
P88=-117.7310;47.0000
P89=-117.6990;46.5000
P90=-117.6940;46.0000
P91=-117.7410;45.5000
P92=-117.6820;45.0000
P93=-117.7090;44.5000
P94=-117.6910;44.0000
P95=-117.6200;43.5000
P96=-117.6170;43.0000
P97=-117.5120;42.5000
P98=-117.5000;42.4470
P99=-117.4510;42.0000
P100=-117.4110;41.5000
P101=-117.3080;41.0000
P102=-117.2120;40.5000
P103=-117.2080;40.0000
P104=-117.1110;39.5000
P105=-117.0000;39.2460
P106=-116.9450;39.0000
P107=-116.8660;38.5000
P108=-116.8140;38.0000
P109=-116.7130;37.5000
P110=-116.6100;37.0000
P111=-116.5000;36.5290
P112=-116.4950;36.5000
P113=-116.4040;36.0000
P114=-116.3050;35.5000
P115=-116.2120;35.0000
P116=-116.2470;34.5000
P117=-116.5000;34.0200
P118=-116.6380;34.5000
P119=-116.7590;35.0000
P120=-116.7600;35.5000
P121=-116.8960;36.0000
P122=-117.0000;36.0800
P123=-117.1320;36.5000
P124=-117.2520;37.0000
P125=-117.2720;37.5000
P126=-117.3830;38.0000

P127=-117.5000;38.1760
P128=-117.6010;38.5000
P129=-117.7160;39.0000
P130=-117.7380;39.5000
P131=-117.8480;40.0000
P132=-117.9810;40.5000
P133=-118.0000;40.5830
P134=-118.0780;41.0000
P135=-118.1980;41.5000
P136=-118.2830;42.0000
P137=-118.2790;42.5000
P138=-118.3650;43.0000
P139=-118.4320;43.5000
P140=-118.5000;43.9350
P141=-118.5120;44.0000
P142=-118.5770;44.5000
P143=-118.5740;45.0000
P144=-118.6450;45.5000
P145=-118.6520;46.0000
P146=-118.6680;46.5000
P147=-118.7060;47.0000
P148=-118.6640;47.5000
P149=-118.7080;48.0000
P150=-118.6760;48.5000
P151=-118.6780;49.0000
P152=-118.6760;49.5000
P153=-118.6220;50.0000
P154=-118.6440;50.5000
P155=-118.5540;51.0000
P156=-118.5940;51.5000
P157=-118.5000;51.9590
P158=-118.4950;52.0000
P159=-118.5000;52.1760
P160=-118.5170;52.5000
P161=-118.5000;52.6340
P162=-118.4650;53.0000
P163=-118.4410;53.5000
P164=-118.3910;54.0000
P165=-118.3460;54.5000
P166=-118.3540;55.0000
P167=-118.3290;55.5000
P168=-118.2890;56.0000
P169=-118.2550;56.5000
P170=-118.1910;57.0000
P171=-118.1890;57.5000
P172=-118.0140;58.0000
P173=-118.0810;58.5000
P174=-118.0000;58.8320
P175=-117.9750;59.0000
P176=-117.9720;59.5000
P177=-117.9640;60.0000
P178=-117.9700;60.5000
P179=-117.9340;61.0000
P180=-117.9170;61.5000
P181=-117.8520;62.0000
P182=-117.8320;62.5000
P183=-117.7580;63.0000

P184=-117.7890;63.5000
P185=-117.6710;64.0000
P186=-117.7960;64.5000
P187=-117.6630;65.0000
P188=-117.8240;65.5000
P189=-117.7460;66.0000
P190=-117.8310;66.5000
P191=-117.8360;67.0000
P192=-117.8070;67.5000
P193=-117.8650;68.0000
P194=-117.8470;68.5000
P195=-117.9150;69.0000
P196=-118.0000;69.3190
P197=-118.0700;69.5000
P198=-118.0220;70.0000
P199=-118.2190;70.5000
P200=-118.3890;71.0000
P201=-118.4780;71.5000
P202=-118.5000;71.6030
P203=-118.5930;72.0000
P204=-118.8610;72.5000
P205=-119.0000;72.8220
P206=-119.0950;73.0000
P207=-119.2760;73.5000
P208=-119.4280;74.0000
P209=-119.5000;74.1060
P210=-119.8100;74.5000
P211=-120.0000;74.7740
P212=-120.1820;75.0000
P213=-120.5000;75.4470
P214=-120.5430;75.5000
P215=-121.0000;75.9340
P216=-121.0580;76.0000
P217=-121.5000;76.4610
P218=-121.5360;76.5000
P219=-121.9500;77.0000
P220=-122.0000;77.0340
P221=-122.5000;77.4850
P222=-122.5180;77.5000
P223=-123.0000;77.7740
P224=-123.3420;78.0000
P225=-123.5000;78.0790
P226=-124.0000;78.3460
P227=-124.2560;78.5000
P228=-124.5000;78.6090
P229=-125.0000;78.8360
P230=-125.2870;79.0000
P231=-125.5000;79.0910
P232=-126.0000;79.2700
P233=-126.4560;79.5000
P234=-126.5000;79.5180
P235=-127.0000;79.6740
P236=-127.5000;79.8510
P237=-127.8210;80.0000
P238=-128.0000;80.0620
P239=-128.0380;80.0720
P240=-128.5067;80.1934

[C22]

gain=-30.00

n_point=78

P1=-105.0000;31.2570
P2=-104.9520;31.1285
P3=-104.9040;31.0000
P4=-104.8030;30.8940
P5=-104.7020;30.7880
P6=-104.6010;30.6820
P7=-104.5000;30.5760
P8=-104.4780;30.5000
P9=-104.4358;30.3750
P10=-104.3935;30.2500
P11=-104.3513;30.1250
P12=-104.3090;30.0000
P13=-104.2365;29.8750
P14=-104.1640;29.7500
P15=-104.0915;29.6250
P16=-104.0190;29.5000
P17=-104.0000;29.4730
P18=-103.9713;29.3547
P19=-103.9425;29.2365
P20=-103.9137;29.1182
P21=-103.8850;29.0000
P22=-103.8482;28.8750
P23=-103.8115;28.7500
P24=-103.7747;28.6250
P25=-103.7380;28.5000
P26=-103.6785;28.3863
P27=-103.6190;28.2725
P28=-103.5595;28.1587
P29=-103.5000;28.0450
P30=-103.4880;28.0000
P31=-103.4637;27.8750
P32=-103.4395;27.7500
P33=-103.4153;27.6250
P34=-103.3910;27.5000
P35=-103.3852;27.3750
P36=-103.3795;27.2500
P37=-103.3737;27.1250
P38=-103.3680;27.0000
P39=-103.4340;26.9310
P40=-103.5000;26.8620
P41=-103.5465;26.9310
P42=-103.5930;27.0000
P43=-103.6947;27.1068
P44=-103.7965;27.2135
P45=-103.8982;27.3203
P46=-104.0000;27.4270
P47=-104.0390;27.5000
P48=-104.0995;27.6250
P49=-104.1600;27.7500
P50=-104.2205;27.8750
P51=-104.2810;28.0000
P52=-104.3540;28.1127
P53=-104.4270;28.2253
P54=-104.5000;28.3380

P55=-104.5250;28.4190
P56=-104.5500;28.5000
P57=-104.5860;28.6250
P58=-104.6220;28.7500
P59=-104.6580;28.8750
P60=-104.6940;29.0000
P61=-104.7307;29.1250
P62=-104.7675;29.2500
P63=-104.8043;29.3750
P64=-104.8410;29.5000
P65=-104.8940;29.6433
P66=-104.9470;29.7867
P67=-105.0000;29.9300
P68=-105.0110;30.0000
P69=-105.0200;30.1250
P70=-105.0290;30.2500
P71=-105.0380;30.3750
P72=-105.0470;30.5000
P73=-105.0450;30.6250
P74=-105.0430;30.7500
P75=-105.0410;30.8750
P76=-105.0390;31.0000
P77=-105.0195;31.1285
P78=-105.0000;31.2570
[C23]
gain=-8.00
n_point=99
P1=-91.6149 ;37.9474
P2=-91.8275 ;37.7741
P3=-92.0585 ;37.5515
P4=-92.2356 ;37.3550
P5=-92.4127 ;37.1584
P6=-92.6134 ;36.8913
P7=-92.7498 ;36.6670
P8=-92.8863 ;36.4428
P9=-93.0228 ;36.1695
P10=-93.0944 ;35.9948
P11=-93.1659 ;35.8201
P12=-93.2332 ;35.6148
P13=-93.2882 ;35.3589
P14=-93.3432 ;35.1029
P15=-93.3981 ;34.8470
P16=-93.4091 ;34.7402
P17=-93.4195 ;34.6395
P18=-93.4126 ;34.3654
P19=-93.4057 ;34.0912
P20=-93.3989 ;33.8171
P21=-93.3770 ;33.6529
P22=-93.3267 ;33.4002
P23=-93.2580 ;33.1787
P24=-93.1893 ;32.9571
P25=-93.0964 ;32.7574
P26=-93.0035 ;32.5576
P27=-92.9114 ;32.3942
P28=-92.8193 ;32.2309
P29=-92.6515 ;32.0295
P30=-92.4838 ;31.8281

P31=-92.2931 ;31.6354
P32=-92.0372 ;31.4477
P33=-91.8141 ;31.3169
P34=-91.5911 ;31.1861
P35=-91.3207 ;31.0734
P36=-91.0683 ;31.0127
P37=-90.8158 ;30.9520
P38=-90.6540 ;30.9303
P39=-90.3876 ;30.9298
P40=-90.1212 ;30.9292
P41=-89.9082 ;30.9652
P42=-89.6953 ;31.0011
P43=-89.3612 ;31.1146
P44=-89.0271 ;31.2281
P45=-88.8780 ;31.2966
P46=-88.8397 ;31.3169
P47=-88.7821 ;31.3473
P48=-88.5659 ;31.4920
P49=-88.3498 ;31.6366
P50=-88.1336 ;31.7813
P51=-87.9416 ;31.9686
P52=-87.7496 ;32.1559
P53=-87.5576 ;32.3432
P54=-87.5259 ;32.3814
P55=-87.4743 ;32.4434
P56=-87.3290 ;32.6456
P57=-87.1838 ;32.8477
P58=-87.0386 ;33.0499
P59=-86.9273 ;33.2408
P60=-86.8160 ;33.4316
P61=-86.7237 ;33.6336
P62=-86.6314 ;33.8356
P63=-86.5733 ;33.9941
P64=-86.5152 ;34.1527
P65=-86.4597 ;34.3232
P66=-86.4042 ;34.4938
P67=-86.3491 ;34.7563
P68=-86.3084 ;35.0334
P69=-86.2677 ;35.3105
P70=-86.2501 ;35.5671
P71=-86.2536 ;35.8739
P72=-86.2721 ;36.0692
P73=-86.2906 ;36.2646
P74=-86.3277 ;36.4588
P75=-86.3647 ;36.6531
P76=-86.4364 ;36.8653
P77=-86.5080 ;37.0775
P78=-86.6382 ;37.3018
P79=-86.7683 ;37.5260
P80=-86.8985 ;37.7503
P81=-87.1373 ;37.9877
P82=-87.3760 ;38.2252
P83=-87.4991 ;38.3119
P84=-87.7921 ;38.4681
P85=-88.0850 ;38.6243
P86=-88.3156 ;38.7054
P87=-88.6117 ;38.7428

P88=-88.9079 ;38.7801
P89=-89.2040 ;38.8175
P90=-89.3567 ;38.8143
P91=-89.5436 ;38.8031
P92=-89.9068 ;38.7265
P93=-90.2700 ;38.6499
P94=-90.4775 ;38.5750
P95=-90.6849 ;38.5002
P96=-90.9031 ;38.3894
P97=-91.1213 ;38.2786
P98=-91.3681 ;38.1130
P99=-91.6149 ;37.9474
[C24]
gain=-15.00
n_point=108
P1=-91.7767 ;39.0387
P2=-91.8591 ;38.9800
P3=-91.9378 ;38.9197
P4=-92.2308 ;38.6745
P5=-92.5238 ;38.4294
P6=-92.7343 ;38.2080
P7=-92.9447 ;37.9867
P8=-93.0976 ;37.8031
P9=-93.3430 ;37.4672
P10=-93.4625 ;37.2825
P11=-93.5821 ;37.0977
P12=-93.6760 ;36.9192
P13=-93.7749 ;36.7218
P14=-93.8738 ;36.5243
P15=-93.9765 ;36.3127
P16=-94.0572 ;36.0778
P17=-94.1379 ;35.8429
P18=-94.1924 ;35.6307
P19=-94.2469 ;35.4184
P20=-94.3009 ;35.1512
P21=-94.3569 ;34.7610
P22=-94.3858 ;34.4053
P23=-94.3837 ;34.0482
P24=-94.3529 ;33.6741
P25=-94.3112 ;33.4138
P26=-94.2695 ;33.1535
P27=-94.2595 ;33.1128
P28=-94.1819 ;32.8476
P29=-94.1044 ;32.5823
P30=-93.9894 ;32.2994
P31=-93.8463 ;32.0439
P32=-93.7031 ;31.7884
P33=-93.5816 ;31.6026
P34=-93.4941 ;31.4832
P35=-93.2780 ;31.2416
P36=-93.0620 ;31.0001
P37=-92.8112 ;30.8003
P38=-92.5604 ;30.6005
P39=-92.4222 ;30.5020
P40=-92.1664 ;30.3659
P41=-91.9003 ;30.2470
P42=-91.6341 ;30.1282

P43=-91.3916 ;30.0490
P44=-90.9962 ;29.9719
P45=-90.6293 ;29.9343
P46=-90.1977 ;29.9407
P47=-89.8407 ;29.9796
P48=-89.4542 ;30.0853
P49=-89.0677 ;30.1911
P50=-88.9713 ;30.2312
P51=-88.8818 ;30.2685
P52=-88.5309 ;30.4576
P53=-88.1800 ;30.6467
P54=-87.9370 ;30.8215
P55=-87.6939 ;30.9963
P56=-87.5172 ;31.1555
P57=-87.3666 ;31.2933
P58=-87.1514 ;31.5213
P59=-86.9361 ;31.7492
P60=-86.7058 ;32.0465
P61=-86.5003 ;32.3379
P62=-86.4355 ;32.4339
P63=-86.2952 ;32.6772
P64=-86.1459 ;32.9311
P65=-85.9966 ;33.1849
P66=-85.9093 ;33.3909
P67=-85.7841 ;33.7214
P68=-85.6591 ;34.0468
P69=-85.5890 ;34.2491
P70=-85.5190 ;34.4515
P71=-85.4721 ;34.7034
P72=-85.4253 ;34.9552
P73=-85.4153 ;35.0133
P74=-85.3811 ;35.2678
P75=-85.3469 ;35.5224
P76=-85.3339 ;35.7590
P77=-85.3209 ;35.9956
P78=-85.3210 ;36.1414
P79=-85.3359 ;36.3719
P80=-85.3508 ;36.6024
P81=-85.3895 ;36.9090
P82=-85.4762 ;37.2667
P83=-85.5630 ;37.6243
P84=-85.5940 ;37.6961
P85=-85.6247 ;37.7655
P86=-85.7979 ;38.0939
P87=-85.9712 ;38.4222
P88=-86.1282 ;38.6169
P89=-86.2851 ;38.8116
P90=-86.4819 ;39.0291
P91=-86.7064 ;39.2057
P92=-86.9393 ;39.3594
P93=-87.1723 ;39.5131
P94=-87.4155 ;39.6208
P95=-87.6588 ;39.7285
P96=-87.9271 ;39.8127
P97=-88.0775 ;39.8515
P98=-88.6000 ;39.8981
P99=-89.1224 ;39.9446

P100=-89.2215 ;39.9386
P101=-89.3484 ;39.9310
P102=-89.7741 ;39.8539
P103=-90.1998 ;39.7767
P104=-90.5629 ;39.6605
P105=-90.8273 ;39.5471
P106=-91.0916 ;39.4338
P107=-91.4342 ;39.2362
P108=-91.7767 ;39.0387