

```
[FormatInfo]
format_ver=1
[GeoMain]
ntc_id=910100000
adm=USA
sat_name=USABSS-21
long_nom=-101.0000
n_diag=1
[COHeader]
beam_id=CB13
emi_rcp=E
polar_disc=C
reason=B
n_bore=1
n_cont=26
[B1]
gain=0.00
p=-83.0300;40.9340
[C1]
gain=-40.00
n_point=421
P1=-49.7890 ;75.8100
P2=-50.0000 ;75.7700
P3=-50.5000 ;75.6740
P4=-51.0000 ;75.5800
P5=-51.4440 ;75.5000
P6=-51.5000 ;75.4870
P7=-52.0000 ;75.3760
P8=-52.5000 ;75.2730
P9=-53.0000 ;75.1670
P10=-53.5000 ;75.0660
P11=-53.8400 ;75.0000
P12=-54.0000 ;74.9610
P13=-54.5000 ;74.8460
P14=-55.0000 ;74.7300
P15=-55.5000 ;74.6180
P16=-56.0000 ;74.5130
P17=-56.0670 ;74.5000
P18=-56.5000 ;74.3920
P19=-57.0000 ;74.2640
P20=-57.5000 ;74.1430
P21=-58.0000 ;74.0320
P22=-58.1470 ;74.0000
P23=-58.5000 ;73.9060
P24=-59.0000 ;73.7670
P25=-59.5000 ;73.6420
P26=-60.0000 ;73.5280
P27=-60.1100 ;73.5000
P28=-60.5000 ;73.3810
P29=-61.0000 ;73.2420
P30=-61.5000 ;73.1180
P31=-61.9400 ;73.0000
P32=-62.0000 ;72.9800
P33=-62.5000 ;72.8270
P34=-63.0000 ;72.6930
P35=-63.5000 ;72.5520
P36=-63.6940 ;72.5000
```

P37=-64.0000 ;72.3950
P38=-64.5000 ;72.2330
P39=-65.0000 ;72.0860
P40=-65.3270 ;72.0000
P41=-65.5000 ;71.9410
P42=-66.0000 ;71.7550
P43=-66.5000 ;71.6000
P44=-66.8110 ;71.5000
P45=-67.0000 ;71.4270
P46=-67.5000 ;71.2500
P47=-68.0000 ;71.0830
P48=-68.2520 ;71.0000
P49=-68.5000 ;70.9070
P50=-69.0000 ;70.7260
P51=-69.5000 ;70.5560
P52=-69.6680 ;70.5000
P53=-70.0000 ;70.3720
P54=-70.5000 ;70.1900
P55=-71.0000 ;70.0180
P56=-71.0500 ;70.0000
P57=-71.5000 ;69.8100
P58=-72.0000 ;69.6150
P59=-72.3330 ;69.5000
P60=-72.5000 ;69.4280
P61=-73.0000 ;69.2040
P62=-73.5000 ;69.0100
P63=-73.5230 ;69.0000
P64=-74.0000 ;68.7880
P65=-74.5000 ;68.5800
P66=-74.7060 ;68.5000
P67=-75.0000 ;68.3710
P68=-75.5000 ;68.1600
P69=-75.8900 ;68.0000
P70=-76.0000 ;67.9400
P71=-76.5000 ;67.6900
P72=-76.9200 ;67.5000
P73=-77.0000 ;67.4590
P74=-77.5000 ;67.2020
P75=-77.9300 ;67.0000
P76=-78.0000 ;66.9640
P77=-78.5000 ;66.7150
P78=-78.9670 ;66.5000
P79=-79.0000 ;66.4800
P80=-79.5000 ;66.1780
P81=-79.8220 ;66.0000
P82=-80.0000 ;65.8940
P83=-80.5000 ;65.6090
P84=-80.6960 ;65.5000
P85=-81.0000 ;65.3140
P86=-81.5000 ;65.0280
P87=-81.5480 ;65.0000
P88=-82.0000 ;64.6980
P89=-82.3250 ;64.5000
P90=-82.5000 ;64.3890
P91=-83.0000 ;64.0770
P92=-83.1260 ;64.0000
P93=-83.5000 ;63.7330

P94=-83.8620 ;63.5000
P95=-84.0000 ;63.4100
P96=-84.5000 ;63.0810
P97=-84.6280 ;63.0000
P98=-85.0000 ;62.7350
P99=-85.3440 ;62.5000
P100=-85.5000 ;62.3960
P101=-86.0000 ;62.0620
P102=-86.0910 ;62.0000
P103=-86.5000 ;61.6990
P104=-86.7690 ;61.5000
P105=-87.0000 ;61.3250
P106=-87.4620 ;61.0000
P107=-87.5000 ;60.9680
P108=-88.0000 ;60.5380
P109=-88.0470 ;60.5000
P110=-88.5000 ;60.1300
P111=-88.6520 ;60.0000
P112=-89.0000 ;59.6600
P113=-89.1750 ;59.5000
P114=-89.5000 ;59.2000
P115=-89.7080 ;59.0000
P116=-90.0000 ;58.7110
P117=-90.2210 ;58.5000
P118=-90.5000 ;58.2310
P119=-90.7320 ;58.0000
P120=-91.0000 ;57.7300
P121=-91.2310 ;57.5000
P122=-91.5000 ;57.2310
P123=-91.7270 ;57.0000
P124=-92.0000 ;56.7080
P125=-92.1890 ;56.5000
P126=-92.5000 ;56.1510
P127=-92.6380 ;56.0000
P128=-93.0000 ;55.5800
P129=-93.0690 ;55.5000
P130=-93.4720 ;55.0000
P131=-93.5000 ;54.9640
P132=-93.8650 ;54.5000
P133=-94.0000 ;54.3290
P134=-94.2610 ;54.0000
P135=-94.5000 ;53.6830
P136=-94.6430 ;53.5000
P137=-94.9870 ;53.0000
P138=-95.0000 ;52.9810
P139=-95.3190 ;52.5000
P140=-95.5000 ;52.2150
P141=-95.6490 ;52.0000
P142=-95.9630 ;51.5000
P143=-96.0000 ;51.4420
P144=-96.3000 ;51.0000
P145=-96.5000 ;50.6680
P146=-96.6210 ;50.5000
P147=-96.9040 ;50.0000
P148=-97.0000 ;49.8080
P149=-97.1900 ;49.5000
P150=-97.4230 ;49.0000

P151=-97.5000 ;48.8290
P152=-97.6940 ;48.5000
P153=-97.9270 ;48.0000
P154=-98.0000 ;47.8350
P155=-98.2090 ;47.5000
P156=-98.4230 ;47.0000
P157=-98.5000 ;46.7750
P158=-98.6580 ;46.5000
P159=-98.8390 ;46.0000
P160=-98.9790 ;45.5000
P161=-99.0000 ;45.4300
P162=-99.2170 ;45.0000
P163=-99.3930 ;44.5000
P164=-99.5000 ;44.0800
P165=-99.5450 ;44.0000
P166=-99.7100 ;43.5000
P167=-99.7950 ;43.0000
P168=-99.8710 ;42.5000
P169=-99.9550 ;42.0000
P170=-100.0000;41.6970
P171=-100.0490;41.5000
P172=-100.1060;41.0000
P173=-100.1000;40.5000
P174=-100.0830;40.0000
P175=-100.0770;39.5000
P176=-100.0630;39.0000
P177=-100.0090;38.5000
P178=-100.0000;38.4570
P179=-99.9140 ;38.0000
P180=-99.8030 ;37.5000
P181=-99.7020 ;37.0000
P182=-99.6040 ;36.5000
P183=-99.5000 ;36.0490
P184=-99.4810 ;36.0000
P185=-99.2450 ;35.5000
P186=-99.0710 ;35.0000
P187=-99.0000 ;34.6160
P188=-98.5000 ;34.7640
P189=-98.4610 ;35.0000
P190=-98.0000 ;35.4360
P191=-97.5000 ;35.0700
P192=-97.4660 ;35.0000
P193=-97.2000 ;34.5000
P194=-97.0000 ;34.2090
P195=-96.9090 ;34.0000
P196=-96.6790 ;33.5000
P197=-96.5000 ;33.1350
P198=-96.4380 ;33.0000
P199=-96.2050 ;32.5000
P200=-96.0080 ;32.0000
P201=-96.0000 ;31.9820
P202=-95.7670 ;31.5000
P203=-95.5490 ;31.0000
P204=-95.5000 ;30.8890
P205=-95.2790 ;30.5000
P206=-95.0480 ;30.0000
P207=-95.0000 ;29.8900

P208=-94.7470 ;29.5000
P209=-94.5000 ;29.0550
P210=-94.4630 ;29.0000
P211=-94.0830 ;28.5000
P212=-94.0000 ;28.3710
P213=-93.6980 ;28.0000
P214=-93.5000 ;27.7710
P215=-93.2310 ;27.5000
P216=-93.0000 ;27.2890
P217=-92.6910 ;27.0000
P218=-92.5000 ;26.8630
P219=-92.0120 ;26.5000
P220=-92.0000 ;26.4930
P221=-91.5000 ;26.2280
P222=-91.1290 ;26.0000
P223=-91.0000 ;25.9410
P224=-90.5000 ;25.7930
P225=-90.0000 ;25.6430
P226=-89.5030 ;25.5000
P227=-89.5000 ;25.4990
P228=-89.0000 ;25.4440
P229=-88.5000 ;25.4140
P230=-88.0000 ;25.4120
P231=-87.5000 ;25.4320
P232=-87.0000 ;25.4760
P233=-86.8090 ;25.5000
P234=-86.5000 ;25.5700
P235=-86.0000 ;25.7110
P236=-85.5000 ;25.8460
P237=-85.0000 ;25.9510
P238=-84.7950 ;26.0000
P239=-84.5000 ;26.1320
P240=-84.0000 ;26.3230
P241=-83.5000 ;26.4600
P242=-83.4190 ;26.5000
P243=-83.0000 ;26.7500
P244=-82.5000 ;26.9680
P245=-82.4370 ;27.0000
P246=-82.0000 ;27.2810
P247=-81.5760 ;27.5000
P248=-81.5000 ;27.5560
P249=-81.0000 ;27.8730
P250=-80.8020 ;28.0000
P251=-80.5000 ;28.2300
P252=-80.0760 ;28.5000
P253=-80.0000 ;28.5610
P254=-79.5000 ;28.8940
P255=-79.3570 ;29.0000
P256=-79.0000 ;29.2790
P257=-78.7050 ;29.5000
P258=-78.5000 ;29.6690
P259=-78.0710 ;30.0000
P260=-78.0000 ;30.0600
P261=-77.5000 ;30.4640
P262=-77.4630 ;30.5000
P263=-77.0000 ;30.9020
P264=-76.8990 ;31.0000

P265=-76.5000 ;31.3640
P266=-76.3610 ;31.5000
P267=-76.0000 ;31.8480
P268=-75.8550 ;32.0000
P269=-75.5000 ;32.3620
P270=-75.3760 ;32.5000
P271=-75.0000 ;32.8970
P272=-74.9000 ;33.0000
P273=-74.5000 ;33.4250
P274=-74.4260 ;33.5000
P275=-74.0000 ;33.9610
P276=-73.9650 ;34.0000
P277=-73.5380 ;34.5000
P278=-73.5000 ;34.5420
P279=-73.0960 ;35.0000
P280=-73.0000 ;35.1090
P281=-72.6590 ;35.5000
P282=-72.5000 ;35.6840
P283=-72.2200 ;36.0000
P284=-72.0000 ;36.2420
P285=-71.7610 ;36.5000
P286=-71.5000 ;36.8090
P287=-71.3320 ;37.0000
P288=-71.0000 ;37.3710
P289=-70.8730 ;37.5000
P290=-70.5000 ;37.9350
P291=-70.4410 ;38.0000
P292=-70.0000 ;38.4880
P293=-69.9880 ;38.5000
P294=-69.5610 ;39.0000
P295=-69.5000 ;39.0650
P296=-69.1110 ;39.5000
P297=-69.0000 ;39.6310
P298=-68.6760 ;40.0000
P299=-68.5000 ;40.1990
P300=-68.2400 ;40.5000
P301=-68.0000 ;40.7740
P302=-67.7930 ;41.0000
P303=-67.5000 ;41.3510
P304=-67.3700 ;41.5000
P305=-67.0000 ;41.9410
P306=-66.9520 ;42.0000
P307=-66.5310 ;42.5000
P308=-66.5000 ;42.5380
P309=-66.1300 ;43.0000
P310=-66.0000 ;43.1570
P311=-65.7260 ;43.5000
P312=-65.5000 ;43.7700
P313=-65.3160 ;44.0000
P314=-65.0000 ;44.3750
P315=-64.9000 ;44.5000
P316=-64.5000 ;44.9870
P317=-64.4900 ;45.0000
P318=-64.1000 ;45.5000
P319=-64.0000 ;45.6220
P320=-63.7030 ;46.0000
P321=-63.5000 ;46.2470

P322=-63.2980 ;46.5000
P323=-63.0000 ;46.8610
P324=-62.8870 ;47.0000
P325=-62.5000 ;47.4610
P326=-62.4670 ;47.5000
P327=-62.0450 ;48.0000
P328=-62.0000 ;48.0510
P329=-61.6150 ;48.5000
P330=-61.5000 ;48.6310
P331=-61.1780 ;49.0000
P332=-61.0000 ;49.2030
P333=-60.7350 ;49.5000
P334=-60.5000 ;49.7640
P335=-60.2860 ;50.0000
P336=-60.0000 ;50.3100
P337=-59.8270 ;50.5000
P338=-59.5000 ;50.8370
P339=-59.3480 ;51.0000
P340=-59.0000 ;51.3570
P341=-58.8580 ;51.5000
P342=-58.5000 ;51.8720
P343=-58.3660 ;52.0000
P344=-58.0000 ;52.3650
P345=-57.8570 ;52.5000
P346=-57.5000 ;52.8400
P347=-57.3380 ;53.0000
P348=-57.0000 ;53.3360
P349=-56.8250 ;53.5000
P350=-56.5000 ;53.8270
P351=-56.3100 ;54.0000
P352=-56.0000 ;54.2840
P353=-55.7730 ;54.5000
P354=-55.5000 ;54.7520
P355=-55.2140 ;55.0000
P356=-55.0000 ;55.1960
P357=-54.6450 ;55.5000
P358=-54.5000 ;55.6230
P359=-54.0610 ;56.0000
P360=-54.0000 ;56.0550
P361=-53.5000 ;56.4440
P362=-53.4320 ;56.5000
P363=-53.0000 ;56.8960
P364=-52.8700 ;57.0000
P365=-52.5000 ;57.2930
P366=-52.2510 ;57.5000
P367=-52.0000 ;57.7200
P368=-51.6370 ;58.0000
P369=-51.5000 ;58.1130
P370=-51.0400 ;58.5000
P371=-51.0000 ;58.5330
P372=-50.5000 ;58.9010
P373=-50.3610 ;59.0000
P374=-50.0000 ;59.2810
P375=-49.7230 ;59.5000
P376=-49.5000 ;59.6770
P377=-49.0000 ;59.9810
P378=-48.9720 ;60.0000

P379=-48.5000 ;60.3560
P380=-48.2930 ;60.5000
P381=-48.0000 ;60.7170
P382=-47.5000 ;60.9910
P383=-47.4850 ;61.0000
P384=-47.0000 ;61.3400
P385=-46.7500 ;61.5000
P386=-46.5000 ;61.6810
P387=-46.0000 ;61.9480
P388=-45.9040 ;62.0000
P389=-45.5000 ;62.2310
P390=-45.0700 ;62.5000
P391=-45.0000 ;62.5500
P392=-44.5000 ;62.8270
P393=-44.0380 ;63.0000
P394=-44.0000 ;63.0190
P395=-43.5000 ;63.2900
P396=-43.1430 ;63.5000
P397=-43.0000 ;63.5820
P398=-42.5000 ;63.7900
P399=-42.0000 ;63.9520
P400=-41.8650 ;64.0000
P401=-41.5000 ;64.1910
P402=-41.0000 ;64.4230
P403=-40.7980 ;64.5000
P404=-40.5000 ;64.6260
P405=-40.0000 ;64.7980
P406=-39.5000 ;64.9470
P407=-39.3130 ;65.0000
P408=-39.0000 ;65.1010
P409=-38.5000 ;65.2670
P410=-38.0000 ;65.3930
P411=-37.5530 ;65.5000
P412=-37.5000 ;65.5240
P413=-37.0000 ;65.6980
P414=-36.5000 ;65.8200
P415=-36.0000 ;65.9150
P416=-35.5150 ;66.0000
P417=-35.5000 ;66.0040
P418=-35.0000 ;66.1160
P419=-34.5000 ;66.2360
P420=-34.0000 ;66.3450
P421=-33.5670 ;66.4110
[C2]
gain=-2.00
n_point=88
P1=-81.5000 ;42.6820
P2=-81.4250 ;42.5910
P3=-81.3500 ;42.5000
P4=-81.3058 ;42.3750
P5=-81.2615 ;42.2500
P6=-81.2172 ;42.1250
P7=-81.1730 ;42.0000
P8=-81.1800 ;41.8750
P9=-81.1870 ;41.7500
P10=-81.1940 ;41.6250
P11=-81.2010 ;41.5000

P12=-81.2372 ;41.3750
P13=-81.2735 ;41.2500
P14=-81.3098 ;41.1250
P15=-81.3460 ;41.0000
P16=-81.3973 ;40.8870
P17=-81.4487 ;40.7740
P18=-81.5000 ;40.6610
P19=-81.5435 ;40.5805
P20=-81.5870 ;40.5000
P21=-81.6795 ;40.3750
P22=-81.7720 ;40.2500
P23=-81.8645 ;40.1250
P24=-81.9570 ;40.0000
P25=-82.0000 ;39.9510
P26=-82.1182 ;39.8382
P27=-82.2365 ;39.7255
P28=-82.3547 ;39.6128
P29=-82.4730 ;39.5000
P30=-82.5000 ;39.4780
P31=-82.6250 ;39.3997
P32=-82.7500 ;39.3215
P33=-82.8750 ;39.2433
P34=-83.0000 ;39.1650
P35=-83.1253 ;39.1100
P36=-83.2507 ;39.0550
P37=-83.3760 ;39.0000
P38=-83.5000 ;38.9550
P39=-83.6667 ;38.9357
P40=-83.8333 ;38.9163
P41=-84.0000 ;38.8970
P42=-84.1440 ;38.9313
P43=-84.2880 ;38.9657
P44=-84.4320 ;39.0000
P45=-84.5000 ;39.0300
P46=-84.5953 ;39.1475
P47=-84.6905 ;39.2650
P48=-84.7857 ;39.3825
P49=-84.8810 ;39.5000
P50=-84.9207 ;39.6593
P51=-84.9603 ;39.8187
P52=-85.0000 ;39.9780
P53=-85.0030 ;40.0000
P54=-85.0000 ;40.0270
P55=-84.9753 ;40.1847
P56=-84.9507 ;40.3423
P57=-84.9260 ;40.5000
P58=-84.8828 ;40.6250
P59=-84.8395 ;40.7500
P60=-84.7962 ;40.8750
P61=-84.7530 ;41.0000
P62=-84.6930 ;41.1250
P63=-84.6330 ;41.2500
P64=-84.5730 ;41.3750
P65=-84.5130 ;41.5000
P66=-84.5000 ;41.5190
P67=-84.4022 ;41.6393
P68=-84.3045 ;41.7595

P69=-84.2067 ;41.8797
P70=-84.1090 ;42.0000
P71=-84.0000 ;42.1160
P72=-83.8843 ;42.2120
P73=-83.7685 ;42.3080
P74=-83.6527 ;42.4040
P75=-83.5370 ;42.5000
P76=-83.5000 ;42.5270
P77=-83.3333 ;42.6123
P78=-83.1667 ;42.6977
P79=-83.0000 ;42.7830
P80=-82.8333 ;42.8317
P81=-82.6667 ;42.8803
P82=-82.5000 ;42.9290
P83=-82.3333 ;42.9283
P84=-82.1667 ;42.9277
P85=-82.0000 ;42.9270
P86=-81.8333 ;42.8453
P87=-81.6667 ;42.7637
P88=-81.5000 ;42.6820
[C3]
gain=-4.00
n_point=87
P1=-80.5000 ;43.0740
P2=-80.4630 ;43.0000
P3=-80.4270 ;42.8333
P4=-80.3910 ;42.6667
P5=-80.3550 ;42.5000
P6=-80.3553 ;42.3333
P7=-80.3557 ;42.1667
P8=-80.3560 ;42.0000
P9=-80.3900 ;41.8333
P10=-80.4240 ;41.6667
P11=-80.4580 ;41.5000
P12=-80.5000 ;41.3750
P13=-80.5720 ;41.1875
P14=-80.6440 ;41.0000
P15=-80.7303 ;40.8333
P16=-80.8167 ;40.6667
P17=-80.9030 ;40.5000
P18=-81.0000 ;40.3460
P19=-81.1225 ;40.1730
P20=-81.2450 ;40.0000
P21=-81.3725 ;39.8385
P22=-81.5000 ;39.6770
P23=-81.6590 ;39.5000
P24=-81.8295 ;39.3325
P25=-82.0000 ;39.1650
P26=-82.1940 ;39.0000
P27=-82.3470 ;38.8890
P28=-82.5000 ;38.7780
P29=-82.7185 ;38.6390
P30=-82.9370 ;38.5000
P31=-83.0000 ;38.4660
P32=-83.2500 ;38.3700
P33=-83.5000 ;38.2740
P34=-83.7500 ;38.2190

P35=-84.0000 ;38.1640
P36=-84.2500 ;38.1675
P37=-84.5000 ;38.1710
P38=-84.7500 ;38.2530
P39=-85.0000 ;38.3350
P40=-85.1110 ;38.4175
P41=-85.2220 ;38.5000
P42=-85.3610 ;38.6770
P43=-85.5000 ;38.8540
P44=-85.5750 ;39.0000
P45=-85.6153 ;39.1667
P46=-85.6557 ;39.3333
P47=-85.6960 ;39.5000
P48=-85.6950 ;39.6667
P49=-85.6940 ;39.8333
P50=-85.6930 ;40.0000
P51=-85.6667 ;40.1667
P52=-85.6403 ;40.3333
P53=-85.6140 ;40.5000
P54=-85.5570 ;40.7095
P55=-85.5000 ;40.9190
P56=-85.4730 ;41.0000
P57=-85.3913 ;41.1667
P58=-85.3097 ;41.3333
P59=-85.2280 ;41.5000
P60=-85.1140 ;41.7005
P61=-85.0000 ;41.9010
P62=-84.9320 ;42.0000
P63=-84.8027 ;42.1667
P64=-84.6733 ;42.3333
P65=-84.5440 ;42.5000
P66=-84.5000 ;42.5500
P67=-84.3437 ;42.7000
P68=-84.1873 ;42.8500
P69=-84.0310 ;43.0000
P70=-84.0000 ;43.0260
P71=-83.8333 ;43.1407
P72=-83.6667 ;43.2553
P73=-83.5000 ;43.3700
P74=-83.2570 ;43.5000
P75=-83.0000 ;43.6220
P76=-82.7500 ;43.6985
P77=-82.5000 ;43.7750
P78=-82.2500 ;43.8100
P79=-82.0000 ;43.8450
P80=-81.7500 ;43.8250
P81=-81.5000 ;43.8050
P82=-81.2500 ;43.7075
P83=-81.0000 ;43.6100
P84=-80.8520 ;43.5000
P85=-80.7347 ;43.3580
P86=-80.6173 ;43.2160
P87=-80.5000 ;43.0740
[C4]
gain=-6.00
n_point=92
P1=-80.0000 ;43.7090

P2=-79.8850 ;43.5000
P3=-79.8210 ;43.2500
P4=-79.7570 ;43.0000
P5=-79.7450 ;42.7500
P6=-79.7330 ;42.5000
P7=-79.7675 ;42.2500
P8=-79.8020 ;42.0000
P9=-79.8675 ;41.7500
P10=-79.9330 ;41.5000
P11=-80.0000 ;41.3220
P12=-80.0670 ;41.1610
P13=-80.1340 ;41.0000
P14=-80.2675 ;40.7500
P15=-80.4010 ;40.5000
P16=-80.5000 ;40.3350
P17=-80.6125 ;40.1675
P18=-80.7250 ;40.0000
P19=-80.8625 ;39.8125
P20=-81.0000 ;39.6250
P21=-81.1020 ;39.5000
P22=-81.3010 ;39.2875
P23=-81.5000 ;39.0750
P24=-81.5760 ;39.0000
P25=-81.7880 ;38.8170
P26=-82.0000 ;38.6340
P27=-82.1750 ;38.5000
P28=-82.3375 ;38.3890
P29=-82.5000 ;38.2780
P30=-82.7315 ;38.1390
P31=-82.9630 ;38.0000
P32=-83.0000 ;37.9810
P33=-83.2500 ;37.8845
P34=-83.5000 ;37.7880
P35=-83.7500 ;37.7215
P36=-84.0000 ;37.6550
P37=-84.2500 ;37.6325
P38=-84.5000 ;37.6100
P39=-84.7500 ;37.6485
P40=-85.0000 ;37.6870
P41=-85.2500 ;37.7980
P42=-85.5000 ;37.9090
P43=-85.6140 ;38.0000
P44=-85.7427 ;38.1613
P45=-85.8713 ;38.3227
P46=-86.0000 ;38.4840
P47=-86.0090 ;38.5000
P48=-86.0920 ;38.7500
P49=-86.1750 ;39.0000
P50=-86.2020 ;39.2500
P51=-86.2290 ;39.5000
P52=-86.2165 ;39.7500
P53=-86.2040 ;40.0000
P54=-86.1620 ;40.2500
P55=-86.1200 ;40.5000
P56=-86.0600 ;40.7175
P57=-86.0000 ;40.9350
P58=-85.9780 ;41.0000

P59=-85.8700 ;41.2500
P60=-85.7620 ;41.5000
P61=-85.6390 ;41.7500
P62=-85.5160 ;42.0000
P63=-85.5000 ;42.0280
P64=-85.3425 ;42.2640
P65=-85.1850 ;42.5000
P66=-85.0925 ;42.6240
P67=-85.0000 ;42.7480
P68=-84.8900 ;42.8740
P69=-84.7800 ;43.0000
P70=-84.6400 ;43.1460
P71=-84.5000 ;43.2920
P72=-84.2580 ;43.5000
P73=-84.0000 ;43.7090
P74=-83.7770 ;43.8545
P75=-83.5540 ;44.0000
P76=-83.5000 ;44.0330
P77=-83.2500 ;44.1495
P78=-83.0000 ;44.2660
P79=-82.7500 ;44.3475
P80=-82.5000 ;44.4290
P81=-82.3035 ;44.4645
P82=-82.1070 ;44.5000
P83=-82.0000 ;44.5180
P84=-81.7500 ;44.5215
P85=-81.5000 ;44.5250
P86=-81.3320 ;44.5000
P87=-81.0000 ;44.4380
P88=-80.7500 ;44.3240
P89=-80.5000 ;44.2100
P90=-80.2380 ;44.0000
P91=-80.1190 ;43.8545
P92=-80.0000 ;43.7090

[C5]

gain=-10.00
n_point=106
P1=-79.0000 ;44.2560
P2=-78.9070 ;44.0000
P3=-78.8580 ;43.7500
P4=-78.8090 ;43.5000
P5=-78.8110 ;43.2500
P6=-78.8130 ;43.0000
P7=-78.8390 ;42.7500
P8=-78.8650 ;42.5000
P9=-78.9260 ;42.2500
P10=-78.9870 ;42.0000
P11=-79.0000 ;41.9580
P12=-79.0825 ;41.7290
P13=-79.1650 ;41.5000
P14=-79.2780 ;41.2500
P15=-79.3910 ;41.0000
P16=-79.5000 ;40.7830
P17=-79.6600 ;40.5000
P18=-79.8085 ;40.2500
P19=-79.9570 ;40.0000
P20=-80.0000 ;39.9390

P21=-80.1695 ;39.7195
P22=-80.3390 ;39.5000
P23=-80.5000 ;39.3000
P24=-80.6325 ;39.1500
P25=-80.7650 ;39.0000
P26=-81.0000 ;38.7510
P27=-81.2570 ;38.5000
P28=-81.5000 ;38.2880
P29=-81.6755 ;38.1440
P30=-81.8510 ;38.0000
P31=-82.0000 ;37.8960
P32=-82.2500 ;37.7315
P33=-82.5000 ;37.5670
P34=-82.6170 ;37.5000
P35=-83.0000 ;37.3160
P36=-83.2500 ;37.2110
P37=-83.5000 ;37.1060
P38=-83.8350 ;37.0000
P39=-84.0000 ;36.9580
P40=-84.2500 ;36.9225
P41=-84.5000 ;36.8870
P42=-84.7500 ;36.8845
P43=-85.0000 ;36.8820
P44=-85.2500 ;36.9230
P45=-85.5000 ;36.9640
P46=-85.6050 ;37.0000
P47=-85.8025 ;37.0970
P48=-86.0000 ;37.1940
P49=-86.1885 ;37.3470
P50=-86.3770 ;37.5000
P51=-86.5000 ;37.6510
P52=-86.6045 ;37.8255
P53=-86.7090 ;38.0000
P54=-86.8030 ;38.2500
P55=-86.8970 ;38.5000
P56=-86.9415 ;38.7500
P57=-86.9860 ;39.0000
P58=-87.0000 ;39.3440
P59=-87.0050 ;39.5000
P60=-87.0000 ;39.5670
P61=-86.9800 ;39.7835
P62=-86.9600 ;40.0000
P63=-86.9100 ;40.2500
P64=-86.8600 ;40.5000
P65=-86.7945 ;40.7500
P66=-86.7290 ;41.0000
P67=-86.6510 ;41.2500
P68=-86.5730 ;41.5000
P69=-86.5000 ;41.6990
P70=-86.3690 ;42.0000
P71=-86.2455 ;42.2500
P72=-86.1220 ;42.5000
P73=-86.0000 ;42.7270
P74=-85.8270 ;43.0000
P75=-85.6635 ;43.2410
P76=-85.5000 ;43.4820
P77=-85.4860 ;43.5000

P78=-85.2740 ;43.7500
P79=-85.0620 ;44.0000
P80=-85.0000 ;44.0680
P81=-84.7645 ;44.2840
P82=-84.5290 ;44.5000
P83=-84.5000 ;44.5250
P84=-84.2500 ;44.7040
P85=-84.0000 ;44.8830
P86=-83.7930 ;45.0000
P87=-83.5000 ;45.1600
P88=-83.2500 ;45.2615
P89=-83.0000 ;45.3630
P90=-82.7560 ;45.4315
P91=-82.5120 ;45.5000
P92=-82.5000 ;45.5030
P93=-82.2500 ;45.5425
P94=-82.0000 ;45.5820
P95=-81.5000 ;45.6010
P96=-81.0000 ;45.5640
P97=-80.6720 ;45.5000
P98=-80.5000 ;45.4610
P99=-80.2500 ;45.3605
P100=-80.0000 ;45.2600
P101=-79.7920 ;45.1300
P102=-79.5840 ;45.0000
P103=-79.5000 ;44.9330
P104=-79.3115 ;44.7165
P105=-79.1230 ;44.5000
P106=-79.0000 ;44.2560
[C6]
gain=-20.00
n_point=126
P1=-77.5000 ;45.4170
P2=-77.3420 ;45.0000
P3=-77.3040 ;44.7500
P4=-77.2660 ;44.5000
P5=-77.2730 ;44.2500
P6=-77.2800 ;44.0000
P7=-77.3145 ;43.7500
P8=-77.3490 ;43.5000
P9=-77.4035 ;43.2500
P10=-77.4580 ;43.0000
P11=-77.5000 ;42.8700
P12=-77.6270 ;42.5000
P13=-77.7230 ;42.2500
P14=-77.8190 ;42.0000
P15=-78.0000 ;41.5450
P16=-78.0210 ;41.5000
P17=-78.1585 ;41.2500
P18=-78.2960 ;41.0000
P19=-78.5000 ;40.5650
P20=-78.5380 ;40.5000
P21=-78.7110 ;40.2500
P22=-78.8840 ;40.0000
P23=-79.0000 ;39.8050
P24=-79.2230 ;39.5000
P25=-79.5000 ;39.1110

P26=-79.5900 ;39.0000
P27=-79.7950 ;38.7665
P28=-80.0000 ;38.5330
P29=-80.0300 ;38.5000
P30=-80.2650 ;38.2710
P31=-80.5000 ;38.0420
P32=-80.5450 ;38.0000
P33=-80.7725 ;37.8115
P34=-81.0000 ;37.6230
P35=-81.1490 ;37.5000
P36=-81.5000 ;37.2610
P37=-81.8570 ;37.0000
P38=-82.0000 ;36.9250
P39=-82.2500 ;36.7815
P40=-82.5000 ;36.6380
P41=-82.7440 ;36.5000
P42=-83.0000 ;36.4040
P43=-83.5000 ;36.2020
P44=-84.0000 ;36.0100
P45=-84.0380 ;36.0000
P46=-84.5000 ;35.9280
P47=-85.0000 ;35.8840
P48=-85.5000 ;35.8900
P49=-86.0000 ;35.9540
P50=-86.1880 ;36.0000
P51=-86.5000 ;36.1310
P52=-86.7500 ;36.2720
P53=-87.0000 ;36.4130
P54=-87.1160 ;36.5000
P55=-87.3080 ;36.7035
P56=-87.5000 ;36.9070
P57=-87.5710 ;37.0000
P58=-87.6895 ;37.2500
P59=-87.8080 ;37.5000
P60=-87.8930 ;37.7500
P61=-87.9780 ;38.0000
P62=-88.0000 ;38.1000
P63=-88.0610 ;38.5000
P64=-88.0815 ;38.7500
P65=-88.1020 ;39.0000
P66=-88.1020 ;39.2500
P67=-88.1020 ;39.5000
P68=-88.0945 ;39.7500
P69=-88.0870 ;40.0000
P70=-88.0745 ;40.2500
P71=-88.0620 ;40.5000
P72=-88.0425 ;40.7500
P73=-88.0230 ;41.0000
P74=-88.0000 ;41.2490
P75=-87.9780 ;41.5000
P76=-87.9540 ;41.7500
P77=-87.9300 ;42.0000
P78=-87.8970 ;42.2500
P79=-87.8640 ;42.5000
P80=-87.8190 ;42.7500
P81=-87.7740 ;43.0000
P82=-87.6995 ;43.2500

P83=-87.6250 ;43.5000
P84=-87.5000 ;43.8080
P85=-87.4220 ;44.0000
P86=-87.2945 ;44.2500
P87=-87.1670 ;44.5000
P88=-87.0000 ;44.7720
P89=-86.8550 ;45.0000
P90=-86.6775 ;45.2415
P91=-86.5000 ;45.4830
P92=-86.4870 ;45.5000
P93=-86.2675 ;45.7500
P94=-86.0480 ;46.0000
P95=-86.0000 ;46.0500
P96=-85.7685 ;46.2750
P97=-85.5370 ;46.5000
P98=-85.5000 ;46.5330
P99=-85.2500 ;46.7360
P100=-85.0000 ;46.9390
P101=-84.9170 ;47.0000
P102=-84.5000 ;47.2780
P103=-84.1230 ;47.5000
P104=-84.0000 ;47.5680
P105=-83.5000 ;47.7970
P106=-83.0000 ;47.9820
P107=-82.9210 ;48.0000
P108=-82.5000 ;48.0920
P109=-82.0000 ;48.1310
P110=-81.5000 ;48.0730
P111=-81.2980 ;48.0000
P112=-81.0000 ;47.8970
P113=-80.5000 ;47.6210
P114=-80.3390 ;47.5000
P115=-80.0000 ;47.3120
P116=-79.5000 ;47.0120
P117=-79.4820 ;47.0000
P118=-79.0000 ;46.7280
P119=-78.5880 ;46.5000
P120=-78.5000 ;46.4400
P121=-78.2500 ;46.2490
P122=-78.0000 ;46.0580
P123=-77.9290 ;46.0000
P124=-77.7335 ;45.7500
P125=-77.5380 ;45.5000
P126=-77.5000 ;45.4170
[C7]
gain=-30.00
n_point=91
P1=-85.0000 ;35.1310
P2=-85.1667 ;35.1490
P3=-85.3333 ;35.1670
P4=-85.5000 ;35.1850
P5=-85.6667 ;35.2100
P6=-85.8333 ;35.2350
P7=-86.0000 ;35.2600
P8=-86.1170 ;35.3800
P9=-86.2340 ;35.5000
P10=-86.3670 ;35.5470

P11=-86.5000 ;35.5940
P12=-86.6667 ;35.6623
P13=-86.8333 ;35.7307
P14=-87.0000 ;35.7990
P15=-87.1605 ;35.8995
P16=-87.3210 ;36.0000
P17=-87.4105 ;36.0740
P18=-87.5000 ;36.1480
P19=-87.6030 ;36.2653
P20=-87.7060 ;36.3827
P21=-87.8090 ;36.5000
P22=-87.9045 ;36.6110
P23=-88.0000 ;36.7220
P24=-88.1135 ;36.8610
P25=-88.2270 ;37.0000
P26=-88.2660 ;37.1667
P27=-88.3050 ;37.3333
P28=-88.3440 ;37.5000
P29=-88.3960 ;37.6297
P30=-88.4480 ;37.7593
P31=-88.5000 ;37.8890
P32=-88.5660 ;38.0000
P33=-88.6237 ;38.1667
P34=-88.6813 ;38.3333
P35=-88.7390 ;38.5000
P36=-88.7987 ;38.6667
P37=-88.8583 ;38.8333
P38=-88.9180 ;39.0000
P39=-88.9590 ;39.1310
P40=-89.0000 ;39.2620
P41=-89.0700 ;39.1310
P42=-89.1400 ;39.0000
P43=-89.2177 ;38.8333
P44=-89.2953 ;38.6667
P45=-89.3730 ;38.5000
P46=-89.3953 ;38.3333
P47=-89.4177 ;38.1667
P48=-89.4400 ;38.0000
P49=-89.4290 ;37.8333
P50=-89.4180 ;37.6667
P51=-89.4070 ;37.5000
P52=-89.3930 ;37.3333
P53=-89.3790 ;37.1667
P54=-89.3650 ;37.0000
P55=-89.2940 ;36.8333
P56=-89.2230 ;36.6667
P57=-89.1520 ;36.5000
P58=-89.0760 ;36.4050
P59=-89.0000 ;36.3100
P60=-88.9380 ;36.1550
P61=-88.8760 ;36.0000
P62=-88.7507 ;35.8783
P63=-88.6253 ;35.7567
P64=-88.5000 ;35.6350
P65=-88.3895 ;35.5675
P66=-88.2790 ;35.5000
P67=-88.1395 ;35.4085

P68=-88.0000 ;35.3170
P69=-87.8333 ;35.2670
P70=-87.6667 ;35.2170
P71=-87.5000 ;35.1670
P72=-87.3333 ;35.1290
P73=-87.1667 ;35.0910
P74=-87.0000 ;35.0530
P75=-86.8820 ;35.0265
P76=-86.7640 ;35.0000
P77=-86.6320 ;34.9655
P78=-86.5000 ;34.9310
P79=-86.3333 ;34.9133
P80=-86.1667 ;34.8957
P81=-86.0000 ;34.8780
P82=-85.8333 ;34.8803
P83=-85.6667 ;34.8827
P84=-85.5000 ;34.8850
P85=-85.3333 ;34.9003
P86=-85.1667 ;34.9157
P87=-85.0000 ;34.9310
P88=-84.8225 ;34.9655
P89=-84.6450 ;35.0000
P90=-84.8225 ;35.0655
P91=-85.0000 ;35.1310

[C8]

gain=-30.00

n_point=77

P1=-80.5000 ;37.2130
P2=-80.6250 ;37.1748
P3=-80.7500 ;37.1365
P4=-80.8750 ;37.0982
P5=-81.0000 ;37.0600
P6=-81.0800 ;37.0000
P7=-81.1850 ;36.9297
P8=-81.2900 ;36.8595
P9=-81.3950 ;36.7892
P10=-81.5000 ;36.7190
P11=-81.6297 ;36.6460
P12=-81.7593 ;36.5730
P13=-81.8890 ;36.5000
P14=-81.9445 ;36.4330
P15=-82.0000 ;36.3660
P16=-82.1250 ;36.3510
P17=-82.2500 ;36.3360
P18=-82.3750 ;36.3210
P19=-82.5000 ;36.3060
P20=-82.6130 ;36.2295
P21=-82.7260 ;36.1530
P22=-82.8390 ;36.0765
P23=-82.9520 ;36.0000
P24=-82.9760 ;35.9235
P25=-83.0000 ;35.8470
P26=-83.1250 ;35.8327
P27=-83.2500 ;35.8185
P28=-83.3750 ;35.8043
P29=-83.5000 ;35.7900
P30=-83.6250 ;35.7458

P31=-83.7500 ;35.7015
P32=-83.8750 ;35.6572
P33=-84.0000 ;35.6130
P34=-84.1187 ;35.5753
P35=-84.2373 ;35.5377
P36=-84.3560 ;35.5000
P37=-84.2670 ;35.4322
P38=-84.1780 ;35.3645
P39=-84.0890 ;35.2968
P40=-84.0000 ;35.2290
P41=-83.8750 ;35.2115
P42=-83.7500 ;35.1940
P43=-83.6250 ;35.1765
P44=-83.5000 ;35.1590
P45=-83.3750 ;35.2013
P46=-83.2500 ;35.2435
P47=-83.1250 ;35.2857
P48=-83.0000 ;35.3280
P49=-82.9037 ;35.3853
P50=-82.8073 ;35.4427
P51=-82.7110 ;35.5000
P52=-82.6055 ;35.5370
P53=-82.5000 ;35.5740
P54=-82.3750 ;35.6255
P55=-82.2500 ;35.6770
P56=-82.1250 ;35.7285
P57=-82.0000 ;35.7800
P58=-81.8980 ;35.8533
P59=-81.7960 ;35.9267
P60=-81.6940 ;36.0000
P61=-81.5970 ;36.0825
P62=-81.5000 ;36.1650
P63=-81.4000 ;36.2312
P64=-81.3000 ;36.2974
P65=-81.2000 ;36.3636
P66=-81.1000 ;36.4298
P67=-81.0000 ;36.4960
P68=-80.9950 ;36.5000
P69=-80.8960 ;36.5762
P70=-80.7970 ;36.6524
P71=-80.6980 ;36.7286
P72=-80.5990 ;36.8048
P73=-80.5000 ;36.8810
P74=-80.4210 ;36.9405
P75=-80.3420 ;37.0000
P76=-80.4210 ;37.1065
P77=-80.5000 ;37.2130

[C9]

gain=-30.00

n_point=78

P1=-76.5000 ;42.5020
P2=-76.5010 ;42.5000
P3=-76.6673 ;42.4137
P4=-76.8337 ;42.3273
P5=-77.0000 ;42.2410
P6=-77.0685 ;42.1205
P7=-77.1370 ;42.0000

P8=-77.2150 ;41.8333
P9=-77.2930 ;41.6667
P10=-77.3710 ;41.5000
P11=-77.5000 ;41.4250
P12=-77.5943 ;41.2833
P13=-77.6887 ;41.1417
P14=-77.7830 ;41.0000
P15=-77.8553 ;40.8740
P16=-77.9277 ;40.7480
P17=-78.0000 ;40.6220
P18=-78.0840 ;40.5000
P19=-78.1750 ;40.3333
P20=-78.2660 ;40.1667
P21=-78.3570 ;40.0000
P22=-78.4285 ;39.8650
P23=-78.5000 ;39.7300
P24=-78.5810 ;39.6150
P25=-78.6620 ;39.5000
P26=-78.7543 ;39.3333
P27=-78.8467 ;39.1667
P28=-78.9390 ;39.0000
P29=-79.0000 ;38.9050
P30=-79.0883 ;38.7700
P31=-79.1767 ;38.6350
P32=-79.2650 ;38.5000
P33=-79.3825 ;38.3820
P34=-79.5000 ;38.2640
P35=-79.6200 ;38.1320
P36=-79.7400 ;38.0000
P37=-79.6200 ;37.8510
P38=-79.5000 ;37.7020
P39=-79.3873 ;37.8013
P40=-79.2747 ;37.9007
P41=-79.1620 ;38.0000
P42=-79.0810 ;38.0805
P43=-79.0000 ;38.1610
P44=-78.8737 ;38.2740
P45=-78.7473 ;38.3870
P46=-78.6210 ;38.5000
P47=-78.5000 ;38.5790
P48=-78.3865 ;38.6842
P49=-78.2730 ;38.7895
P50=-78.1595 ;38.8948
P51=-78.0460 ;39.0000
P52=-78.0000 ;39.0390
P53=-77.8888 ;39.1543
P54=-77.7775 ;39.2695
P55=-77.6663 ;39.3848
P56=-77.5550 ;39.5000
P57=-77.5000 ;39.5670
P58=-77.3707 ;39.7113
P59=-77.2413 ;39.8557
P60=-77.1120 ;40.0000
P61=-77.0560 ;40.1290
P62=-77.0000 ;40.2580
P63=-76.8795 ;40.3790
P64=-76.7590 ;40.5000

P65=-76.7083 ;40.6667
P66=-76.6577 ;40.8333
P67=-76.6070 ;41.0000
P68=-76.5713 ;41.1200
P69=-76.5357 ;41.2400
P70=-76.5000 ;41.3600
P71=-76.4100 ;41.5000
P72=-76.3873 ;41.6667
P73=-76.3647 ;41.8333
P74=-76.3420 ;42.0000
P75=-76.3943 ;42.1667
P76=-76.4467 ;42.3333
P77=-76.4990 ;42.5000
P78=-76.5000 ;42.5020
[C10]
gain=-30.00
n_point=209
P1=-73.0000 ;49.1580
P2=-72.9220 ;49.0000
P3=-72.7880 ;48.5000
P4=-72.7080 ;48.0000
P5=-72.6940 ;47.5000
P6=-72.7460 ;47.0000
P7=-72.8270 ;46.5000
P8=-72.9540 ;46.0000
P9=-73.0000 ;45.8610
P10=-73.1390 ;45.5000
P11=-73.3190 ;45.0000
P12=-73.5000 ;44.5820
P13=-73.5440 ;44.5000
P14=-73.8030 ;44.0000
P15=-74.0000 ;43.5800
P16=-74.0490 ;43.5000
P17=-74.3690 ;43.0000
P18=-74.5000 ;42.7410
P19=-74.6700 ;42.5000
P20=-74.9860 ;42.0000
P21=-75.0000 ;41.9740
P22=-75.3510 ;41.5000
P23=-75.5000 ;41.2620
P24=-75.7260 ;41.0000
P25=-76.0000 ;40.5100
P26=-76.0110 ;40.5000
P27=-76.3750 ;40.0000
P28=-76.5000 ;39.7770
P29=-76.7210 ;39.5000
P30=-76.9530 ;39.0000
P31=-77.0000 ;38.9260
P32=-77.3180 ;38.5000
P33=-77.5000 ;38.1930
P34=-77.6370 ;38.0000
P35=-77.9540 ;37.5000
P36=-78.0000 ;37.4410
P37=-78.3680 ;37.0000
P38=-78.5000 ;36.8430
P39=-78.7970 ;36.5000
P40=-79.0000 ;36.2810

P41=-79.2600 ;36.0000
P42=-79.5000 ;35.7650
P43=-79.7600 ;35.5000
P44=-80.0000 ;35.2900
P45=-80.3020 ;35.0000
P46=-80.5000 ;34.8420
P47=-80.8790 ;34.5000
P48=-81.0000 ;34.4140
P49=-81.5000 ;34.0280
P50=-81.5340 ;34.0000
P51=-82.0000 ;33.7260
P52=-82.3130 ;33.5000
P53=-82.5000 ;33.4060
P54=-83.0000 ;33.1190
P55=-83.2000 ;33.0000
P56=-83.5000 ;32.8870
P57=-84.0000 ;32.6690
P58=-84.3760 ;32.5000
P59=-84.5000 ;32.4630
P60=-85.0000 ;32.3730
P61=-85.5000 ;32.3020
P62=-86.0000 ;32.2470
P63=-86.5000 ;32.2380
P64=-87.0000 ;32.2830
P65=-87.5000 ;32.3860
P66=-87.8700 ;32.5000
P67=-88.0000 ;32.5670
P68=-88.5000 ;32.8810
P69=-88.6670 ;33.0000
P70=-89.0000 ;33.3190
P71=-89.1600 ;33.5000
P72=-89.5000 ;33.9800
P73=-89.5120 ;34.0000
P74=-89.7630 ;34.5000
P75=-90.0000 ;34.9450
P76=-90.0230 ;35.0000
P77=-90.2160 ;35.5000
P78=-90.4640 ;36.0000
P79=-90.5000 ;36.0710
P80=-90.6560 ;36.5000
P81=-90.8570 ;37.0000
P82=-91.0000 ;37.3600
P83=-91.0440 ;37.5000
P84=-91.1660 ;38.0000
P85=-91.2680 ;38.5000
P86=-91.3480 ;39.0000
P87=-91.4160 ;39.5000
P88=-91.4630 ;40.0000
P89=-91.4960 ;40.5000
P90=-91.5000 ;40.5870
P91=-91.5460 ;41.0000
P92=-91.6510 ;41.5000
P93=-91.7680 ;42.0000
P94=-91.7950 ;42.5000
P95=-91.7250 ;43.0000
P96=-91.5970 ;43.5000
P97=-91.5000 ;43.7770

P98=-91.4130 ;44.0000
P99=-91.1940 ;44.5000
P100=-91.0000 ;44.9290
P101=-90.9630 ;45.0000
P102=-90.6750 ;45.5000
P103=-90.5000 ;45.7910
P104=-90.3600 ;46.0000
P105=-90.0290 ;46.5000
P106=-90.0000 ;46.5400
P107=-89.6440 ;47.0000
P108=-89.5000 ;47.1840
P109=-89.2290 ;47.5000
P110=-89.0000 ;47.7760
P111=-88.7980 ;48.0000
P112=-88.5000 ;48.3380
P113=-88.3470 ;48.5000
P114=-88.0000 ;48.8690
P115=-87.8720 ;49.0000
P116=-87.5000 ;49.3410
P117=-87.3250 ;49.5000
P118=-87.0000 ;49.7720
P119=-86.7320 ;50.0000
P120=-86.5000 ;50.1890
P121=-86.1350 ;50.5000
P122=-86.0000 ;50.6020
P123=-85.5040 ;51.0000
P124=-85.5000 ;51.0030
P125=-85.0000 ;51.3340
P126=-84.7820 ;51.5000
P127=-84.5000 ;51.6860
P128=-84.0820 ;52.0000
P129=-84.0000 ;52.0470
P130=-83.5000 ;52.3220
P131=-83.2130 ;52.5000
P132=-83.0000 ;52.6090
P133=-82.5000 ;52.8750
P134=-82.2870 ;53.0000
P135=-82.0000 ;53.1260
P136=-81.5000 ;53.3690
P137=-81.2620 ;53.5000
P138=-81.0000 ;53.6080
P139=-80.5000 ;53.8200
P140=-80.1080 ;54.0000
P141=-80.0000 ;54.0330
P142=-79.5000 ;54.1670
P143=-79.0000 ;54.3020
P144=-78.5000 ;54.4400
P145=-78.2450 ;54.5000
P146=-78.0000 ;54.5390
P147=-77.5000 ;54.5880
P148=-77.0000 ;54.5970
P149=-76.5000 ;54.5230
P150=-76.4400 ;54.5000
P151=-76.5000 ;54.3140
P152=-76.5660 ;54.0000
P153=-77.0000 ;53.6800
P154=-77.1890 ;53.5000

P155=-77.5000 ;53.3450
P156=-78.0000 ;53.0860
P157=-78.1580 ;53.0000
P158=-78.5000 ;52.8730
P159=-79.0000 ;52.6840
P160=-79.4100 ;52.5000
P161=-79.5000 ;52.4690
P162=-80.0000 ;52.2920
P163=-80.5000 ;52.0810
P164=-80.6580 ;52.0000
P165=-81.0000 ;51.8700
P166=-81.5000 ;51.6510
P167=-81.7700 ;51.5000
P168=-82.0000 ;51.3960
P169=-82.5000 ;51.1580
P170=-82.7660 ;51.0000
P171=-83.0000 ;50.8530
P172=-83.5000 ;50.5430
P173=-83.5600 ;50.5000
P174=-84.0000 ;50.1610
P175=-84.2170 ;50.0000
P176=-84.5000 ;49.7160
P177=-84.7600 ;49.5000
P178=-84.5000 ;49.3430
P179=-84.0000 ;49.4360
P180=-83.8000 ;49.5000
P181=-83.5000 ;49.6880
P182=-83.0000 ;49.8500
P183=-82.5000 ;49.9660
P184=-82.3590 ;50.0000
P185=-82.0000 ;50.1310
P186=-81.5000 ;50.2410
P187=-81.0000 ;50.3170
P188=-80.5000 ;50.3740
P189=-80.0000 ;50.4130
P190=-79.5000 ;50.4390
P191=-79.0000 ;50.4690
P192=-78.7750 ;50.5000
P193=-78.5000 ;50.5390
P194=-78.0000 ;50.6470
P195=-77.5000 ;50.7830
P196=-77.0000 ;50.9060
P197=-76.5000 ;50.9850
P198=-76.0990 ;51.0000
P199=-76.0000 ;51.0030
P200=-75.9730 ;51.0000
P201=-75.5000 ;50.9460
P202=-75.0000 ;50.8120
P203=-74.5000 ;50.6080
P204=-74.3070 ;50.5000
P205=-74.0000 ;50.3110
P206=-73.6140 ;50.0000
P207=-73.5000 ;49.8800
P208=-73.2130 ;49.5000
P209=-73.0000 ;49.1580
[C11]
gain=-40.00

n_point=73
P1=-90.0000 ;33.6130
P2=-90.0466 ;33.6904
P3=-90.0932 ;33.7678
P4=-90.1398 ;33.8452
P5=-90.1864 ;33.9226
P6=-90.2330 ;34.0000
P7=-90.2775 ;34.0770
P8=-90.3220 ;34.1540
P9=-90.3665 ;34.2310
P10=-90.4110 ;34.3080
P11=-90.4555 ;34.3850
P12=-90.5000 ;34.4620
P13=-90.5300 ;34.5000
P14=-90.5883 ;34.5833
P15=-90.6467 ;34.6667
P16=-90.7050 ;34.7500
P17=-90.7633 ;34.8333
P18=-90.8217 ;34.9167
P19=-90.8800 ;35.0000
P20=-90.9200 ;35.0653
P21=-90.9600 ;35.1307
P22=-91.0000 ;35.1960
P23=-91.1000 ;35.2148
P24=-91.2000 ;35.2336
P25=-91.3000 ;35.2524
P26=-91.4000 ;35.2712
P27=-91.5000 ;35.2900
P28=-91.5103 ;35.1933
P29=-91.5207 ;35.0967
P30=-91.5310 ;35.0000
P31=-91.5000 ;34.9270
P32=-91.4804 ;34.8416
P33=-91.4608 ;34.7562
P34=-91.4412 ;34.6708
P35=-91.4216 ;34.5854
P36=-91.4020 ;34.5000
P37=-91.3685 ;34.4167
P38=-91.3350 ;34.3333
P39=-91.3015 ;34.2500
P40=-91.2680 ;34.1667
P41=-91.2345 ;34.0833
P42=-91.2010 ;34.0000
P43=-91.1507 ;33.9340
P44=-91.1005 ;33.8680
P45=-91.0502 ;33.8020
P46=-91.0000 ;33.7360
P47=-90.9430 ;33.6573
P48=-90.8860 ;33.5787
P49=-90.8290 ;33.5000
P50=-90.7632 ;33.4306
P51=-90.6974 ;33.3612
P52=-90.6316 ;33.2918
P53=-90.5658 ;33.2224
P54=-90.5000 ;33.1530
P55=-90.4243 ;33.1020
P56=-90.3487 ;33.0510

P57=-90.2730 ;33.0000
P58=-90.2048 ;32.9350
P59=-90.1365 ;32.8700
P60=-90.0683 ;32.8050
P61=-90.0000 ;32.7400
P62=-89.9235 ;32.8050
P63=-89.8470 ;32.8700
P64=-89.7705 ;32.9350
P65=-89.6940 ;33.0000
P66=-89.7307 ;33.0833
P67=-89.7673 ;33.1667
P68=-89.8040 ;33.2500
P69=-89.8407 ;33.3333
P70=-89.8773 ;33.4167
P71=-89.9140 ;33.5000
P72=-89.9570 ;33.5565
P73=-90.0000 ;33.6130
[C12]
gain=-40.00
n_point=120
P1=-80.0000 ;31.2360
P2=-80.5000 ;31.0330
P3=-80.5470 ;31.0000
P4=-80.7735 ;30.8475
P5=-81.0000 ;30.6950
P6=-81.3590 ;30.5000
P7=-81.5000 ;30.3840
P8=-82.0000 ;30.1790
P9=-82.2880 ;30.0000
P10=-82.5000 ;29.8250
P11=-83.0000 ;29.6770
P12=-83.3520 ;29.5000
P13=-83.5000 ;29.3860
P14=-84.0000 ;29.2620
P15=-84.2500 ;29.1565
P16=-84.5000 ;29.0510
P17=-84.6100 ;29.0000
P18=-85.0000 ;28.8850
P19=-85.5000 ;28.7840
P20=-86.0000 ;28.6390
P21=-86.5000 ;28.5290
P22=-86.7320 ;28.5000
P23=-87.0000 ;28.4500
P24=-87.5000 ;28.4510
P25=-87.8100 ;28.5000
P26=-88.0000 ;28.5210
P27=-88.5000 ;28.6250
P28=-89.0000 ;28.7380
P29=-89.5000 ;28.8410
P30=-89.8220 ;29.0000
P31=-90.0000 ;29.0900
P32=-90.2500 ;29.2160
P33=-90.5000 ;29.3420
P34=-90.6900 ;29.5000
P35=-91.0000 ;29.7510
P36=-91.2880 ;30.0000
P37=-91.5000 ;30.2060

P38=-91.7430 ;30.5000
P39=-92.0000 ;30.8290
P40=-92.1040 ;31.0000
P41=-92.2785 ;31.2500
P42=-92.4530 ;31.5000
P43=-92.5000 ;31.5730
P44=-92.6890 ;32.0000
P45=-92.8445 ;32.2315
P46=-93.0000 ;32.4630
P47=-93.0260 ;32.5000
P48=-93.1520 ;32.7500
P49=-93.2780 ;33.0000
P50=-93.5000 ;33.4010
P51=-93.5750 ;33.5000
P52=-93.7315 ;33.7500
P53=-93.8880 ;34.0000
P54=-94.0000 ;34.1940
P55=-94.4100 ;34.5000
P56=-94.5000 ;34.6330
P57=-94.6030 ;34.5000
P58=-94.6575 ;34.2500
P59=-94.7120 ;34.0000
P60=-94.7045 ;33.7500
P61=-94.6970 ;33.5000
P62=-94.6365 ;33.2500
P63=-94.5760 ;33.0000
P64=-94.5000 ;32.8500
P65=-94.4060 ;32.5000
P66=-94.3045 ;32.2500
P67=-94.2030 ;32.0000
P68=-94.0000 ;31.7020
P69=-93.9070 ;31.5000
P70=-93.7345 ;31.2500
P71=-93.5620 ;31.0000
P72=-93.5000 ;30.9290
P73=-93.3520 ;30.7145
P74=-93.2040 ;30.5000
P75=-93.0000 ;30.2850
P76=-92.7390 ;30.0000
P77=-92.5000 ;29.7660
P78=-92.1800 ;29.5000
P79=-92.0000 ;29.3520
P80=-91.7500 ;29.1810
P81=-91.5000 ;29.0100
P82=-91.4880 ;29.0000
P83=-91.2440 ;28.8375
P84=-91.0000 ;28.6750
P85=-90.6260 ;28.5000
P86=-90.5000 ;28.4320
P87=-90.0000 ;28.2490
P88=-89.5000 ;28.1160
P89=-89.1570 ;28.0000
P90=-89.0000 ;27.9480
P91=-88.5000 ;27.8280
P92=-88.0000 ;27.7650
P93=-87.5000 ;27.7400
P94=-87.0000 ;27.7430

P95=-86.5000 ;27.7770
P96=-86.0000 ;27.8660
P97=-85.5890 ;28.0000
P98=-85.5000 ;28.0290
P99=-85.0000 ;28.1050
P100=-84.5000 ;28.2560
P101=-84.0550 ;28.5000
P102=-84.0000 ;28.5430
P103=-83.5000 ;28.7220
P104=-83.2500 ;28.8300
P105=-83.0000 ;28.9380
P106=-82.8970 ;29.0000
P107=-82.5000 ;29.2200
P108=-82.2500 ;29.3465
P109=-82.0000 ;29.4730
P110=-81.9570 ;29.5000
P111=-81.5000 ;29.7620
P112=-81.1370 ;30.0000
P113=-81.0000 ;30.1640
P114=-80.7500 ;30.3025
P115=-80.5000 ;30.4410
P116=-80.4160 ;30.5000
P117=-80.2080 ;30.6705
P118=-80.0000 ;30.8410
P119=-79.7740 ;31.0000
P120=-80.0000 ;31.2360

[C13]

gain=-50.00

n_point=70

P1=-95.0000 ;28.7970
P2=-95.0370 ;28.8647
P3=-95.0740 ;28.9323
P4=-95.1110 ;29.0000
P5=-95.1470 ;29.0714
P6=-95.1830 ;29.1429
P7=-95.2190 ;29.2143
P8=-95.2550 ;29.2857
P9=-95.2910 ;29.3571
P10=-95.3270 ;29.4286
P11=-95.3630 ;29.5000
P12=-95.4087 ;29.5670
P13=-95.4543 ;29.6340
P14=-95.5000 ;29.7010
P15=-95.5552 ;29.7608
P16=-95.6104 ;29.8206
P17=-95.6656 ;29.8804
P18=-95.7208 ;29.9402
P19=-95.7760 ;30.0000
P20=-95.8208 ;30.0686
P21=-95.8656 ;30.1372
P22=-95.9104 ;30.2058
P23=-95.9552 ;30.2744
P24=-96.0000 ;30.3430
P25=-96.0438 ;30.2744
P26=-96.0876 ;30.2058
P27=-96.1314 ;30.1372
P28=-96.1752 ;30.0686

P29=-96.2190 ;30.0000
P30=-96.1877 ;29.9314
P31=-96.1564 ;29.8629
P32=-96.1251 ;29.7943
P33=-96.0939 ;29.7257
P34=-96.0626 ;29.6571
P35=-96.0313 ;29.5886
P36=-96.0000 ;29.5200
P37=-95.9770 ;29.5000
P38=-95.9546 ;29.4286
P39=-95.9321 ;29.3571
P40=-95.9097 ;29.2857
P41=-95.8873 ;29.2143
P42=-95.8649 ;29.1429
P43=-95.8424 ;29.0714
P44=-95.8200 ;29.0000
P45=-95.7667 ;28.9330
P46=-95.7133 ;28.8660
P47=-95.6600 ;28.7990
P48=-95.6067 ;28.7320
P49=-95.5533 ;28.6650
P50=-95.5000 ;28.5980
P51=-95.4383 ;28.5653
P52=-95.3767 ;28.5327
P53=-95.3150 ;28.5000
P54=-95.2625 ;28.4332
P55=-95.2100 ;28.3663
P56=-95.1575 ;28.2995
P57=-95.1050 ;28.2327
P58=-95.0525 ;28.1658
P59=-95.0000 ;28.0990
P60=-94.9642 ;28.1658
P61=-94.9283 ;28.2327
P62=-94.8925 ;28.2995
P63=-94.8567 ;28.3663
P64=-94.8208 ;28.4332
P65=-94.7850 ;28.5000
P66=-94.8280 ;28.5594
P67=-94.8710 ;28.6188
P68=-94.9140 ;28.6782
P69=-94.9570 ;28.7376
P70=-95.0000 ;28.7970
[C14]
gain=-50.00
n_point=80
P1=-95.0000 ;24.0730
P2=-95.1223 ;24.1798
P3=-95.2445 ;24.2865
P4=-95.3667 ;24.3932
P5=-95.4890 ;24.5000
P6=-95.5000 ;24.5110
P7=-95.6062 ;24.6332
P8=-95.7125 ;24.7555
P9=-95.8187 ;24.8778
P10=-95.9250 ;25.0000
P11=-96.0000 ;25.0810
P12=-96.1110 ;25.2207

P13=-96.2220 ;25.3603
P14=-96.3330 ;25.5000
P15=-96.4165 ;25.5920
P16=-96.5000 ;25.6840
P17=-96.6010 ;25.8420
P18=-96.7020 ;26.0000
P19=-96.8013 ;26.1267
P20=-96.9007 ;26.2533
P21=-97.0000 ;26.3800
P22=-97.1020 ;26.5000
P23=-97.2017 ;26.6667
P24=-97.3013 ;26.8333
P25=-97.4010 ;27.0000
P26=-97.5000 ;27.1330
P27=-97.5767 ;27.2553
P28=-97.6533 ;27.3777
P29=-97.7300 ;27.5000
P30=-97.8200 ;27.6243
P31=-97.9100 ;27.7487
P32=-98.0000 ;27.8730
P33=-98.1680 ;28.0000
P34=-98.2600 ;28.1667
P35=-98.3520 ;28.3333
P36=-98.4440 ;28.5000
P37=-98.5000 ;28.5980
P38=-98.6260 ;28.5490
P39=-98.7520 ;28.5000
P40=-98.7557 ;28.3333
P41=-98.7593 ;28.1667
P42=-98.7630 ;28.0000
P43=-98.7063 ;27.8333
P44=-98.6497 ;27.6667
P45=-98.5930 ;27.5000
P46=-98.5000 ;27.3670
P47=-98.4403 ;27.2447
P48=-98.3807 ;27.1223
P49=-98.3210 ;27.0000
P50=-98.2140 ;26.8473
P51=-98.1070 ;26.6947
P52=-98.0000 ;26.5420
P53=-97.9670 ;26.5000
P54=-97.8653 ;26.3333
P55=-97.7637 ;26.1667
P56=-97.6620 ;26.0000
P57=-97.5810 ;25.9090
P58=-97.5000 ;25.8180
P59=-97.3755 ;25.6590
P60=-97.2510 ;25.5000
P61=-97.1255 ;25.3615
P62=-97.0000 ;25.2230
P63=-96.8715 ;25.1115
P64=-96.7430 ;25.0000
P65=-96.6215 ;24.8785
P66=-96.5000 ;24.7570
P67=-96.3600 ;24.6285
P68=-96.2200 ;24.5000
P69=-96.1100 ;24.4015

P70=-96.0000 ;24.3030
P71=-95.8577 ;24.2020
P72=-95.7153 ;24.1010
P73=-95.5730 ;24.0000
P74=-95.5000 ;23.9390
P75=-95.3333 ;23.8800
P76=-95.1667 ;23.8210
P77=-95.0000 ;23.7620
P78=-94.9585 ;23.8810
P79=-94.9170 ;24.0000
P80=-95.0000 ;24.0730
[C15]
gain=-50.00
n_point=90
P1=-95.5000 ;20.6170
P2=-95.7500 ;20.7420
P3=-96.0000 ;20.8670
P4=-96.0880 ;21.0000
P5=-96.2940 ;21.1590
P6=-96.5000 ;21.3180
P7=-96.6570 ;21.5000
P8=-96.8285 ;21.6475
P9=-97.0000 ;21.7950
P10=-97.1880 ;22.0000
P11=-97.3440 ;22.1580
P12=-97.5000 ;22.3160
P13=-97.6870 ;22.5000
P14=-97.8435 ;22.6645
P15=-98.0000 ;22.8290
P16=-98.1200 ;23.0000
P17=-98.3100 ;23.2115
P18=-98.5000 ;23.4230
P19=-98.5630 ;23.5000
P20=-98.7660 ;23.7500
P21=-98.9690 ;24.0000
P22=-99.0000 ;24.0380
P23=-99.1340 ;24.2690
P24=-99.2680 ;24.5000
P25=-99.3840 ;24.6465
P26=-99.5000 ;24.7930
P27=-99.6280 ;25.0000
P28=-99.8140 ;25.2380
P29=-100.0000;25.4760
P30=-100.0290;25.5000
P31=-100.1610;25.7500
P32=-100.2930;26.0000
P33=-100.3965;26.1610
P34=-100.5000;26.3220
P35=-100.6420;26.5000
P36=-100.7795;26.7500
P37=-100.9170;27.0000
P38=-101.0000;27.1420
P39=-101.1590;27.3210
P40=-101.3180;27.5000
P41=-101.4090;27.6985
P42=-101.5000;27.8970
P43=-101.6050;27.6985

P44=-101.7100;27.5000
P45=-101.6750;27.2500
P46=-101.6400;27.0000
P47=-101.5700;26.8275
P48=-101.5000;26.6550
P49=-101.4390;26.5000
P50=-101.3570;26.2500
P51=-101.2750;26.0000
P52=-101.1375;25.7735
P53=-101.0000;25.5470
P54=-100.9730;25.5000
P55=-100.8695;25.2500
P56=-100.7660;25.0000
P57=-100.6330;24.8180
P58=-100.5000;24.6360
P59=-100.4310;24.5000
P60=-100.2505;24.2500
P61=-100.0700;24.0000
P62=-100.0000;23.9190
P63=-99.8645 ;23.7095
P64=-99.7290 ;23.5000
P65=-99.6145 ;23.3720
P66=-99.5000 ;23.2440
P67=-99.3010 ;23.0000
P68=-99.1505 ;22.8355
P69=-99.0000 ;22.6710
P70=-98.8450 ;22.5000
P71=-98.6725 ;22.3350
P72=-98.5000 ;22.1700
P73=-98.3050 ;22.0000
P74=-98.1525 ;21.8520
P75=-98.0000 ;21.7040
P76=-97.8605 ;21.6020
P77=-97.7210 ;21.5000
P78=-97.5000 ;21.3120
P79=-97.2800 ;21.1560
P80=-97.0600 ;21.0000
P81=-97.0000 ;20.9520
P82=-96.7500 ;20.8100
P83=-96.5000 ;20.6680
P84=-96.2690 ;20.5000
P85=-96.0000 ;20.3310
P86=-95.7500 ;20.2065
P87=-95.5000 ;20.0820
P88=-95.4145 ;20.2910
P89=-95.3290 ;20.5000
P90=-95.5000 ;20.6170
[C16]
gain=-50.00
n_point=80
P1=-84.5000 ;19.6990
P2=-84.7500 ;19.6765
P3=-85.0000 ;19.6540
P4=-85.2500 ;19.6015
P5=-85.5000 ;19.5490
P6=-85.6250 ;19.5000
P7=-85.8125 ;19.4185

P8=-86.0000 ;19.3370
P9=-86.2500 ;19.3435
P10=-86.5000 ;19.3500
P11=-86.7500 ;19.3115
P12=-87.0000 ;19.2730
P13=-87.2500 ;19.2145
P14=-87.5000 ;19.1560
P15=-87.7500 ;19.1085
P16=-88.0000 ;19.0610
P17=-88.2375 ;19.0305
P18=-88.4750 ;19.0000
P19=-88.5000 ;18.9870
P20=-88.7500 ;18.9595
P21=-89.0000 ;18.9320
P22=-89.2500 ;18.9375
P23=-89.5000 ;18.9430
P24=-89.7920 ;19.0000
P25=-90.0000 ;19.0150
P26=-90.2500 ;19.0445
P27=-90.5000 ;19.0740
P28=-90.7500 ;19.1075
P29=-91.0000 ;19.1410
P30=-91.2500 ;19.1655
P31=-91.5000 ;19.1900
P32=-91.7500 ;19.1930
P33=-92.0000 ;19.1960
P34=-92.2500 ;19.1830
P35=-92.5000 ;19.1700
P36=-92.7500 ;19.1140
P37=-93.0000 ;19.0580
P38=-93.0390 ;19.0000
P39=-93.0000 ;18.9870
P40=-92.7500 ;18.9275
P41=-92.5000 ;18.8680
P42=-92.2500 ;18.8170
P43=-92.0000 ;18.7660
P44=-91.7500 ;18.7285
P45=-91.5000 ;18.6910
P46=-91.2500 ;18.6585
P47=-91.0000 ;18.6260
P48=-90.8365 ;18.5630
P49=-90.6730 ;18.5000
P50=-90.5000 ;18.4700
P51=-90.2500 ;18.4370
P52=-90.0000 ;18.4040
P53=-89.7500 ;18.3850
P54=-89.5000 ;18.3660
P55=-89.2500 ;18.3620
P56=-89.0000 ;18.3580
P57=-88.7500 ;18.3720
P58=-88.5000 ;18.3860
P59=-88.2500 ;18.4210
P60=-88.0000 ;18.4560
P61=-87.7820 ;18.5000
P62=-87.6410 ;18.5560
P63=-87.5000 ;18.6120
P64=-87.2500 ;18.6205

P65=-87.0000 ;18.6290
P66=-86.7500 ;18.6325
P67=-86.5000 ;18.6360
P68=-86.2500 ;18.6960
P69=-86.0000 ;18.7560
P70=-85.7500 ;18.8645
P71=-85.5000 ;18.9730
P72=-85.4390 ;19.0000
P73=-85.2195 ;19.1270
P74=-85.0000 ;19.2540
P75=-84.7500 ;19.2965
P76=-84.5000 ;19.3390
P77=-84.2700 ;19.4195
P78=-84.0400 ;19.5000
P79=-84.2700 ;19.5995
P80=-84.5000 ;19.6990
[C17]
gain=-50.00
n_point=142
P1=-83.5000 ;17.1210
P2=-84.0000 ;17.0800
P3=-84.2380 ;17.0000
P4=-84.5000 ;16.8580
P5=-85.0000 ;16.7630
P6=-85.5000 ;16.6490
P7=-85.9740 ;16.5000
P8=-86.0000 ;16.4820
P9=-86.5000 ;16.3440
P10=-87.0000 ;16.3190
P11=-87.5000 ;16.2620
P12=-88.0000 ;16.1670
P13=-88.5000 ;16.0790
P14=-89.0000 ;16.0200
P15=-89.4190 ;16.0000
P16=-89.5000 ;15.9960
P17=-89.6200 ;16.0000
P18=-90.0000 ;16.0120
P19=-90.5000 ;16.0730
P20=-91.0000 ;16.1630
P21=-91.5000 ;16.2720
P22=-92.0000 ;16.3240
P23=-92.5000 ;16.3110
P24=-93.0000 ;16.3740
P25=-93.3580 ;16.5000
P26=-93.5000 ;16.5510
P27=-94.0000 ;16.7160
P28=-94.5000 ;16.8140
P29=-95.0000 ;16.9610
P30=-95.0400 ;17.0000
P31=-95.5000 ;17.2040
P32=-96.0000 ;17.4170
P33=-96.1070 ;17.5000
P34=-96.5000 ;17.7190
P35=-96.9470 ;18.0000
P36=-97.0000 ;18.0400
P37=-97.5000 ;18.3800
P38=-97.6370 ;18.5000

P39=-98.0000 ;18.7970
P40=-98.2240 ;19.0000
P41=-98.5000 ;19.2430
P42=-98.7970 ;19.5000
P43=-99.0000 ;19.7030
P44=-99.2960 ;20.0000
P45=-99.5000 ;20.2060
P46=-99.7700 ;20.5000
P47=-100.0000;20.7430
P48=-100.2020;21.0000
P49=-100.5000;21.3360
P50=-100.6290;21.5000
P51=-101.0000;21.9150
P52=-101.0550;22.0000
P53=-101.4260;22.5000
P54=-101.5000;22.5950
P55=-101.7410;23.0000
P56=-102.0000;23.3550
P57=-102.0870;23.5000
P58=-102.4220;24.0000
P59=-102.5000;24.1140
P60=-102.7110;24.5000
P61=-103.0000;24.9810
P62=-103.0130;25.0000
P63=-103.2640;25.5000
P64=-103.5000;25.9030
P65=-103.5920;26.0000
P66=-103.8520;26.5000
P67=-104.0000;26.8160
P68=-104.1720;27.0000
P69=-104.4060;27.5000
P70=-104.5000;27.7060
P71=-104.7040;27.5000
P72=-104.7280;27.0000
P73=-104.6300;26.5000
P74=-104.5000;26.1450
P75=-104.4390;26.0000
P76=-104.2920;25.5000
P77=-104.0960;25.0000
P78=-104.0000;24.8290
P79=-103.8760;24.5000
P80=-103.6200;24.0000
P81=-103.5000;23.8210
P82=-103.3670;23.5000
P83=-103.0540;23.0000
P84=-103.0000;22.9260
P85=-102.7810;22.5000
P86=-102.5000;22.1620
P87=-102.4130;22.0000
P88=-102.0100;21.5000
P89=-102.0000;21.4880
P90=-101.6480;21.0000
P91=-101.5000;20.8380
P92=-101.2190;20.5000
P93=-101.0000;20.2760
P94=-100.7540;20.0000
P95=-100.5000;19.7490

P96=-100.2120;19.5000
P97=-100.0000;19.3000
P98=-99.6400 ;19.0000
P99=-99.5000 ;18.8800
P100=-99.0000 ;18.5120
P101=-98.9850 ;18.5000
P102=-98.5000 ;18.1220
P103=-98.3070 ;18.0000
P104=-98.0000 ;17.7760
P105=-97.5250 ;17.5000
P106=-97.5000 ;17.4830
P107=-97.0000 ;17.2150
P108=-96.6210 ;17.0000
P109=-96.5000 ;16.9270
P110=-96.0000 ;16.7050
P111=-95.5000 ;16.5000
P112=-95.0000 ;16.2940
P113=-94.5000 ;16.1470
P114=-94.1080 ;16.0000
P115=-94.0000 ;15.9570
P116=-93.5000 ;15.7880
P117=-93.0000 ;15.7120
P118=-92.5000 ;15.6520
P119=-92.0000 ;15.5510
P120=-91.7010 ;15.5000
P121=-91.5000 ;15.4520
P122=-91.0000 ;15.3520
P123=-90.5000 ;15.2790
P124=-90.0000 ;15.2310
P125=-89.5000 ;15.2120
P126=-89.0000 ;15.2250
P127=-88.5000 ;15.2690
P128=-88.0000 ;15.3500
P129=-87.5000 ;15.4760
P130=-87.4140 ;15.5000
P131=-87.0000 ;15.5830
P132=-86.5000 ;15.6750
P133=-86.0000 ;15.7820
P134=-85.5000 ;15.9360
P135=-85.3400 ;16.0000
P136=-85.0000 ;16.1460
P137=-84.5000 ;16.2720
P138=-84.0000 ;16.4950
P139=-83.9900 ;16.5000
P140=-83.5000 ;16.8530
P141=-83.2020 ;17.0000
P142=-83.5000 ;17.1210
[C18]
gain=-50.00
n_point=114
P1=-67.5000 ;25.6910
P2=-67.8790 ;25.5000
P3=-68.0000 ;25.4290
P4=-68.2500 ;25.2645
P5=-68.5000 ;25.1000
P6=-68.6150 ;25.0000
P7=-69.0000 ;24.6850

P8=-69.2250 ;24.5000
P9=-69.5000 ;24.2690
P10=-69.8320 ;24.0000
P11=-70.0000 ;23.8460
P12=-70.2345 ;23.6730
P13=-70.4690 ;23.5000
P14=-70.5000 ;23.4720
P15=-70.7500 ;23.2815
P16=-71.0000 ;23.0910
P17=-71.1060 ;23.0000
P18=-71.5000 ;22.6760
P19=-71.7120 ;22.5000
P20=-72.0000 ;22.2620
P21=-72.3420 ;22.0000
P22=-72.5000 ;21.8610
P23=-72.7500 ;21.6890
P24=-73.0000 ;21.5170
P25=-73.0200 ;21.5000
P26=-73.2600 ;21.3315
P27=-73.5000 ;21.1630
P28=-73.7110 ;21.0000
P29=-74.0000 ;20.7830
P30=-74.3770 ;20.5000
P31=-74.5000 ;20.3930
P32=-74.7500 ;20.2360
P33=-75.0000 ;20.0790
P34=-75.1020 ;20.0000
P35=-75.5000 ;19.7200
P36=-75.8040 ;19.5000
P37=-76.0000 ;19.3490
P38=-76.2500 ;19.1990
P39=-76.5000 ;19.0490
P40=-76.5670 ;19.0000
P41=-76.7835 ;18.8510
P42=-77.0000 ;18.7020
P43=-77.2800 ;18.5000
P44=-77.5000 ;18.3200
P45=-77.7500 ;18.1660
P46=-78.0000 ;18.0120
P47=-78.0160 ;18.0000
P48=-78.2580 ;17.8230
P49=-78.5000 ;17.6460
P50=-78.7180 ;17.5000
P51=-79.0000 ;17.2520
P52=-79.2350 ;17.1260
P53=-79.4700 ;17.0000
P54=-79.5000 ;16.9030
P55=-79.7500 ;16.7395
P56=-80.0000 ;16.5760
P57=-80.1370 ;16.5000
P58=-80.0000 ;16.3520
P59=-79.5000 ;16.4430
P60=-79.4020 ;16.5000
P61=-79.0000 ;16.7580
P62=-78.7500 ;16.8705
P63=-78.5000 ;16.9830
P64=-78.4760 ;17.0000

P65=-78.2380 ;17.1455
P66=-78.0000 ;17.2910
P67=-77.6360 ;17.5000
P68=-77.5000 ;17.6010
P69=-77.2500 ;17.7275
P70=-77.0000 ;17.8540
P71=-76.7910 ;18.0000
P72=-76.5000 ;18.1840
P73=-76.2605 ;18.3420
P74=-76.0210 ;18.5000
P75=-76.0000 ;18.5200
P76=-75.7500 ;18.6830
P77=-75.5000 ;18.8460
P78=-75.3000 ;19.0000
P79=-75.0000 ;19.2100
P80=-74.5950 ;19.5000
P81=-74.5000 ;19.5850
P82=-74.2500 ;19.7510
P83=-74.0000 ;19.9170
P84=-73.8970 ;20.0000
P85=-73.5000 ;20.2930
P86=-73.2370 ;20.5000
P87=-73.0000 ;20.7100
P88=-72.6140 ;21.0000
P89=-72.5000 ;21.1100
P90=-72.2500 ;21.2835
P91=-72.0000 ;21.4570
P92=-71.9460 ;21.5000
P93=-71.7230 ;21.6795
P94=-71.5000 ;21.8590
P95=-71.3250 ;22.0000
P96=-71.0000 ;22.2700
P97=-70.6980 ;22.5000
P98=-70.5000 ;22.6750
P99=-70.2820 ;22.8375
P100=-70.0640 ;23.0000
P101=-70.0000 ;23.0700
P102=-69.7500 ;23.2630
P103=-69.5000 ;23.4560
P104=-69.4470 ;23.5000
P105=-69.2235 ;23.6950
P106=-69.0000 ;23.8900
P107=-68.8700 ;24.0000
P108=-68.5000 ;24.3540
P109=-68.3240 ;24.5000
P110=-68.0000 ;24.8020
P111=-67.7700 ;25.0000
P112=-67.5000 ;25.3460
P113=-67.3360 ;25.5000
P114=-67.5000 ;25.6910
[C19]
gain=-50.00
n_point=158
P1=-85.0000 ;13.5110
P2=-85.5000 ;13.6150
P3=-86.0000 ;13.5700
P4=-86.3490 ;13.5000

P5=-86.5000 ;13.4470
P6=-87.0000 ;13.3480
P7=-87.5000 ;13.3000
P8=-88.0000 ;13.2550
P9=-88.5000 ;13.1990
P10=-89.0000 ;13.1380
P11=-89.5000 ;13.0830
P12=-90.0000 ;13.0460
P13=-90.5000 ;13.0370
P14=-91.0000 ;13.0640
P15=-91.5000 ;13.1300
P16=-92.0000 ;13.2270
P17=-92.5000 ;13.3470
P18=-93.0000 ;13.3960
P19=-93.5000 ;13.4570
P20=-93.6160 ;13.5000
P21=-94.0000 ;13.6650
P22=-94.5000 ;13.8540
P23=-95.0000 ;13.9510
P24=-95.1880 ;14.0000
P25=-95.5000 ;14.1470
P26=-96.0000 ;14.3210
P27=-96.5000 ;14.4960
P28=-96.5080 ;14.5000
P29=-97.0000 ;14.7520
P30=-97.5000 ;14.9530
P31=-97.5650 ;15.0000
P32=-98.0000 ;15.2780
P33=-98.3950 ;15.5000
P34=-98.5000 ;15.5800
P35=-99.0000 ;15.9330
P36=-99.0860 ;16.0000
P37=-99.5000 ;16.3300
P38=-99.7120 ;16.5000
P39=-100.0000;16.7600
P40=-100.2810;17.0000
P41=-100.5000;17.2130
P42=-100.8100;17.5000
P43=-101.0000;17.6850
P44=-101.3200;18.0000
P45=-101.5000;18.1910
P46=-101.7590;18.5000
P47=-102.0000;18.7650
P48=-102.1980;19.0000
P49=-102.5000;19.3240
P50=-102.6430;19.5000
P51=-103.0000;19.9310
P52=-103.0430;20.0000
P53=-103.4120;20.5000
P54=-103.5000;20.6120
P55=-103.7480;21.0000
P56=-104.0000;21.3340
P57=-104.0920;21.5000
P58=-104.4170;22.0000
P59=-104.5000;22.1240
P60=-104.6970;22.5000
P61=-105.0000;22.9400

P62=-105.0350;23.0000
P63=-105.2670;23.5000
P64=-105.5000;23.8900
P65=-105.5630;24.0000
P66=-105.8050;24.5000
P67=-106.0000;24.8540
P68=-106.0890;25.0000
P69=-106.3090;25.5000
P70=-106.5000;25.8900
P71=-106.5730;26.0000
P72=-106.8060;26.5000
P73=-107.0000;26.9690
P74=-107.0320;27.0000
P75=-107.3080;27.5000
P76=-107.4950;28.0000
P77=-107.5000;28.0110
P78=-107.5600;28.0000
P79=-107.8590;27.5000
P80=-107.7940;27.0000
P81=-107.7040;26.5000
P82=-107.5980;26.0000
P83=-107.5000;25.7070
P84=-107.4430;25.5000
P85=-107.2990;25.0000
P86=-107.1090;24.5000
P87=-107.0000;24.2890
P88=-106.9020;24.0000
P89=-106.7090;23.5000
P90=-106.5000;23.1520
P91=-106.4420;23.0000
P92=-106.2240;22.5000
P93=-106.0000;22.1670
P94=-105.9260;22.0000
P95=-105.6460;21.5000
P96=-105.5000;21.3020
P97=-105.3530;21.0000
P98=-105.0000;20.5210
P99=-104.9890;20.5000
P100=-104.6960;20.0000
P101=-104.5000;19.7670
P102=-104.3140;19.5000
P103=-104.0000;19.1330
P104=-103.9200;19.0000
P105=-103.5000;18.5350
P106=-103.4720;18.5000
P107=-103.0000;18.0040
P108=-102.9960;18.0000
P109=-102.5000;17.5020
P110=-102.4980;17.5000
P111=-102.0000;17.0230
P112=-101.9710;17.0000
P113=-101.5000;16.5590
P114=-101.4250;16.5000
P115=-101.0000;16.1280
P116=-100.8240;16.0000
P117=-100.5000;15.7340
P118=-100.1260;15.5000

P119=-100.0000;15.4000
P120=-99.5000 ;15.0670
P121=-99.3800 ;15.0000
P122=-99.0000 ;14.7360
P123=-98.5250 ;14.5000
P124=-98.5000 ;14.4840
P125=-98.0000 ;14.2010
P126=-97.5000 ;14.0000
P127=-97.0000 ;13.7290
P128=-96.5000 ;13.5710
P129=-96.3100 ;13.5000
P130=-96.0000 ;13.3550
P131=-95.5000 ;13.1770
P132=-95.0000 ;13.0390
P133=-94.8610 ;13.0000
P134=-94.5000 ;12.8400
P135=-94.0000 ;12.6410
P136=-93.5000 ;12.6080
P137=-93.0000 ;12.5130
P138=-92.9380 ;12.5000
P139=-92.5000 ;12.3480
P140=-92.0000 ;12.2170
P141=-91.5000 ;12.1320
P142=-91.0000 ;12.0970
P143=-90.5000 ;12.0990
P144=-90.0000 ;12.1170
P145=-89.5000 ;12.1500
P146=-89.0000 ;12.1980
P147=-88.5000 ;12.2580
P148=-88.0000 ;12.3380
P149=-87.5000 ;12.4470
P150=-87.3010 ;12.5000
P151=-87.0000 ;12.5710
P152=-86.5000 ;12.6860
P153=-86.0000 ;12.8570
P154=-85.7330 ;13.0000
P155=-85.5000 ;13.2340
P156=-85.0000 ;13.4920
P157=-84.9870 ;13.5000
P158=-85.0000 ;13.5110
[C20]
gain=-50.00
n_point=177
P1=-88.5000 ;10.1760
P2=-89.0000 ;10.2620
P3=-89.5000 ;10.2640
P4=-90.0000 ;10.2480
P5=-90.5000 ;10.2190
P6=-91.0000 ;10.1880
P7=-91.5000 ;10.1710
P8=-92.0000 ;10.1780
P9=-92.5000 ;10.2140
P10=-93.0000 ;10.2820
P11=-93.5000 ;10.3730
P12=-94.0000 ;10.4660
P13=-94.1560 ;10.5000
P14=-94.5000 ;10.6350

P15=-95.0000 ;10.8340
P16=-95.5000 ;10.9690
P17=-95.6050 ;11.0000
P18=-96.0000 ;11.2230
P19=-96.5000 ;11.4170
P20=-96.7770 ;11.5000
P21=-97.0000 ;11.6310
P22=-97.5000 ;11.8730
P23=-97.8990 ;12.0000
P24=-98.0000 ;12.0630
P25=-98.5000 ;12.3460
P26=-98.8650 ;12.5000
P27=-99.0000 ;12.5900
P28=-99.5000 ;12.8900
P29=-99.6870 ;13.0000
P30=-100.0000;13.2310
P31=-100.4480;13.5000
P32=-100.5000;13.5420
P33=-101.0000;13.9320
P34=-101.0890;14.0000
P35=-101.5000;14.3670
P36=-101.6570;14.5000
P37=-102.0000;14.8140
P38=-102.2210;15.0000
P39=-102.5000;15.2700
P40=-102.7430;15.5000
P41=-103.0000;15.7690
P42=-103.2040;16.0000
P43=-103.5000;16.3140
P44=-103.6680;16.5000
P45=-104.0000;16.8630
P46=-104.1140;17.0000
P47=-104.5000;17.4430
P48=-104.5390;17.5000
P49=-104.9300;18.0000
P50=-105.0000;18.0890
P51=-105.2730;18.5000
P52=-105.5000;18.7780
P53=-105.6380;19.0000
P54=-106.0000;19.4590
P55=-106.0250;19.5000
P56=-106.3100;20.0000
P57=-106.5000;20.2620
P58=-106.6300;20.5000
P59=-106.9510;21.0000
P60=-107.0000;21.0760
P61=-107.2010;21.5000
P62=-107.5000;21.9720
P63=-107.5140;22.0000
P64=-107.7290;22.5000
P65=-108.0000;22.9770
P66=-108.0120;23.0000
P67=-108.2110;23.5000
P68=-108.4910;24.0000
P69=-108.5000;24.0170
P70=-108.6930;24.5000
P71=-108.9130;25.0000

P72=-109.0000;25.1790
P73=-109.1350;25.5000
P74=-109.3460;26.0000
P75=-109.5000;26.3440
P76=-109.5790;26.5000
P77=-109.7670;27.0000
P78=-109.9500;27.5000
P79=-110.0000;27.6260
P80=-110.1900;28.0000
P81=-110.3730;28.5000
P82=-110.5000;28.8810
P83=-110.6110;29.0000
P84=-110.8230;29.5000
P85=-110.9890;30.0000
P86=-111.0000;30.0280
P87=-111.0540;30.0000
P88=-111.3000;29.5000
P89=-111.2640;29.0000
P90=-111.2180;28.5000
P91=-111.1910;28.0000
P92=-111.1300;27.5000
P93=-111.0000;27.0310
P94=-110.9930;27.0000
P95=-110.8830;26.5000
P96=-110.8000;26.0000
P97=-110.6780;25.5000
P98=-110.5000;25.1210
P99=-110.4670;25.0000
P100=-110.3420;24.5000
P101=-110.1680;24.0000
P102=-110.0000;23.7110
P103=-109.9320;23.5000
P104=-109.7540;23.0000
P105=-109.5000;22.5350
P106=-109.4880;22.5000
P107=-109.2930;22.0000
P108=-109.0000;21.5410
P109=-108.9850;21.5000
P110=-108.8070;21.0000
P111=-108.5000;20.5340
P112=-108.4850;20.5000
P113=-108.2470;20.0000
P114=-108.0000;19.6710
P115=-107.9190;19.5000
P116=-107.6150;19.0000
P117=-107.5000;18.8640
P118=-107.2850;18.5000
P119=-107.0000;18.1630
P120=-106.9060;18.0000
P121=-106.5000;17.5020
P122=-106.4990;17.5000
P123=-106.1220;17.0000
P124=-106.0000;16.8700
P125=-105.7330;16.5000
P126=-105.5000;16.2410
P127=-105.3050;16.0000
P128=-105.0000;15.6970

P129=-104.8000;15.5000
P130=-104.5000;15.2090
P131=-104.3000;15.0000
P132=-104.0000;14.7110
P133=-103.7590;14.5000
P134=-103.5000;14.2730
P135=-103.1280;14.0000
P136=-103.0000;13.8910
P137=-102.5000;13.5030
P138=-102.4960;13.5000
P139=-102.0000;13.0870
P140=-101.8650;13.0000
P141=-101.5000;12.7200
P142=-101.1070;12.5000
P143=-101.0000;12.4210
P144=-100.5000;12.0980
P145=-100.2930;12.0000
P146=-100.0000;11.8060
P147=-99.5000 ;11.5700
P148=-99.3380 ;11.5000
P149=-99.0000 ;11.3080
P150=-98.5000 ;11.0970
P151=-98.2430 ;11.0000
P152=-98.0000 ;10.8720
P153=-97.5000 ;10.6430
P154=-97.0000 ;10.5060
P155=-96.9840 ;10.5000
P156=-96.5000 ;10.2240
P157=-96.0000 ;10.0360
P158=-95.8320 ;10.0000
P159=-95.5000 ;9.8100
P160=-95.0000 ;9.5950
P161=-94.5590 ;9.5000
P162=-94.5000 ;9.4650
P163=-94.0000 ;9.2440
P164=-93.5000 ;9.1380
P165=-93.0000 ;9.1090
P166=-92.5000 ;9.1370
P167=-92.0000 ;9.2050
P168=-91.5000 ;9.2870
P169=-91.0000 ;9.3590
P170=-90.5000 ;9.4250
P171=-90.0260 ;9.5000
P172=-90.0000 ;9.5050
P173=-89.5000 ;9.6150
P174=-89.0000 ;9.7460
P175=-88.5000 ;9.9240
P176=-88.3420 ;10.0000
P177=-88.5000 ;10.1760
[C21]
gain=-50.00
n_point=163
P1=-62.5000 ;27.1430
P2=-62.6450 ;27.0000
P3=-63.0000 ;26.7270
P4=-63.2380 ;26.5000
P5=-63.5000 ;26.2770

P6=-63.7900 ;26.0000
P7=-64.0000 ;25.8460
P8=-64.3850 ;25.5000
P9=-64.5000 ;25.3940
P10=-64.9440 ;25.0000
P11=-65.0000 ;24.9530
P12=-65.5000 ;24.5220
P13=-65.5230 ;24.5000
P14=-66.0000 ;24.0990
P15=-66.1080 ;24.0000
P16=-66.5000 ;23.6810
P17=-66.6980 ;23.5000
P18=-67.0000 ;23.2370
P19=-67.2650 ;23.0000
P20=-67.5000 ;22.8030
P21=-67.8570 ;22.5000
P22=-68.0000 ;22.3840
P23=-68.4620 ;22.0000
P24=-68.5000 ;21.9690
P25=-69.0000 ;21.5770
P26=-69.0880 ;21.5000
P27=-69.5000 ;21.1760
P28=-69.6990 ;21.0000
P29=-70.0000 ;20.7700
P30=-70.3260 ;20.5000
P31=-70.5000 ;20.3690
P32=-70.9520 ;20.0000
P33=-71.0000 ;19.9610
P34=-71.5000 ;19.6140
P35=-71.6390 ;19.5000
P36=-72.0000 ;19.2490
P37=-72.3020 ;19.0000
P38=-72.5000 ;18.8660
P39=-72.9860 ;18.5000
P40=-73.0000 ;18.4900
P41=-73.5000 ;18.1820
P42=-73.7280 ;18.0000
P43=-74.0000 ;17.8410
P44=-74.4390 ;17.5000
P45=-74.5000 ;17.4550
P46=-75.0000 ;17.1440
P47=-75.1850 ;17.0000
P48=-75.5000 ;16.8240
P49=-75.9280 ;16.5000
P50=-76.0000 ;16.4500
P51=-76.5000 ;16.1670
P52=-76.7260 ;16.0000
P53=-77.0000 ;15.8490
P54=-77.4770 ;15.5000
P55=-77.5000 ;15.4840
P56=-78.0000 ;15.2660
P57=-78.3950 ;15.0000
P58=-78.5000 ;14.9420
P59=-79.0000 ;14.7120
P60=-79.3240 ;14.5000
P61=-79.5000 ;14.4210
P62=-80.0000 ;14.1930

P63=-80.3100 ;14.0000
P64=-80.5000 ;13.9030
P65=-81.0000 ;13.6930
P66=-81.3290 ;13.5000
P67=-81.5000 ;13.4180
P68=-82.0000 ;13.2050
P69=-82.3610 ;13.0000
P70=-82.5000 ;12.9250
P71=-83.0000 ;12.7560
P72=-83.5000 ;12.5310
P73=-83.5700 ;12.5000
P74=-84.0000 ;12.3400
P75=-84.5000 ;12.1740
P76=-84.8780 ;12.0000
P77=-85.0000 ;11.9300
P78=-85.5000 ;11.7070
P79=-85.8610 ;11.5000
P80=-86.0000 ;11.2550
P81=-86.4700 ;11.0000
P82=-86.0000 ;10.9140
P83=-85.5000 ;10.9630
P84=-85.3680 ;11.0000
P85=-85.0000 ;11.1130
P86=-84.5000 ;11.2200
P87=-84.0000 ;11.3680
P88=-83.7090 ;11.5000
P89=-83.5000 ;11.5900
P90=-83.0000 ;11.7450
P91=-82.5000 ;11.9550
P92=-82.4170 ;12.0000
P93=-82.0000 ;12.1720
P94=-81.5000 ;12.3760
P95=-81.2840 ;12.5000
P96=-81.0000 ;12.6140
P97=-80.5000 ;12.8340
P98=-80.2270 ;13.0000
P99=-80.0000 ;13.0960
P100=-79.5000 ;13.2950
P101=-79.1700 ;13.5000
P102=-79.0000 ;13.5780
P103=-78.5000 ;13.8170
P104=-78.2320 ;14.0000
P105=-78.0000 ;14.0990
P106=-77.5000 ;14.4110
P107=-77.3720 ;14.5000
P108=-77.0000 ;14.6640
P109=-76.5340 ;15.0000
P110=-76.5000 ;15.0200
P111=-76.0000 ;15.3110
P112=-75.7480 ;15.5000
P113=-75.5000 ;15.6290
P114=-75.0040 ;16.0000
P115=-75.0000 ;16.0030
P116=-74.5000 ;16.2970
P117=-74.2370 ;16.5000
P118=-74.0000 ;16.6340
P119=-73.5130 ;17.0000

P120=-73.5000 ;17.0100
P121=-73.0000 ;17.3120
P122=-72.7600 ;17.5000
P123=-72.5000 ;17.6630
P124=-72.0650 ;18.0000
P125=-72.0000 ;18.0520
P126=-71.5000 ;18.3950
P127=-71.3670 ;18.5000
P128=-71.0000 ;18.7550
P129=-70.6990 ;19.0000
P130=-70.5000 ;19.1510
P131=-70.0680 ;19.5000
P132=-70.0000 ;19.5530
P133=-69.5000 ;19.9300
P134=-69.4140 ;20.0000
P135=-69.0000 ;20.3190
P136=-68.7830 ;20.5000
P137=-68.5000 ;20.7310
P138=-68.1790 ;21.0000
P139=-68.0000 ;21.1540
P140=-67.5870 ;21.5000
P141=-67.5000 ;21.5800
P142=-67.0030 ;22.0000
P143=-67.0000 ;22.0030
P144=-66.5000 ;22.4110
P145=-66.3990 ;22.5000
P146=-66.0000 ;22.8310
P147=-65.7930 ;23.0000
P148=-65.5000 ;23.2570
P149=-65.2180 ;23.5000
P150=-65.0000 ;23.7160
P151=-64.6960 ;24.0000
P152=-64.5000 ;24.2050
P153=-64.1990 ;24.5000
P154=-64.0000 ;24.7070
P155=-63.6890 ;25.0000
P156=-63.5000 ;25.1970
P157=-63.2080 ;25.5000
P158=-63.0000 ;25.7760
P159=-62.8060 ;26.0000
P160=-62.5000 ;26.3780
P161=-62.3950 ;26.5000
P162=-62.0600 ;27.0000
P163=-62.5000 ;27.1430
[C22]
gain=-50.00
n_point=495
P1=-151.4175;76.2853
P2=-150.9530;76.1920
P3=-150.5000;76.0990
P4=-150.0830;76.0000
P5=-150.0000;75.9820
P6=-149.5000;75.8740
P7=-149.0000;75.7820
P8=-148.5000;75.6760
P9=-148.0000;75.5530
P10=-147.8070;75.5000

P11=-147.5000;75.4240
P12=-147.0000;75.3120
P13=-146.5000;75.1970
P14=-146.0000;75.0620
P15=-145.7960;75.0000
P16=-145.5000;74.9180
P17=-145.0000;74.7900
P18=-144.5000;74.6580
P19=-144.0020;74.5000
P20=-144.0000;74.4990
P21=-143.5000;74.3450
P22=-143.0000;74.2050
P23=-142.5000;74.0410
P24=-142.3920;74.0000
P25=-142.0000;73.8670
P26=-141.5000;73.7040
P27=-141.0000;73.5270
P28=-140.9350;73.5000
P29=-140.5000;73.3370
P30=-140.0000;73.1540
P31=-139.6140;73.0000
P32=-139.5000;72.9550
P33=-139.0000;72.7480
P34=-138.5000;72.5420
P35=-138.4090;72.5000
P36=-138.0000;72.3320
P37=-137.5000;72.1100
P38=-137.2540;72.0000
P39=-137.0000;71.8900
P40=-136.5000;71.6560
P41=-136.1610;71.5000
P42=-136.0000;71.4260
P43=-135.5000;71.1770
P44=-135.1490;71.0000
P45=-135.0000;70.9270
P46=-134.5000;70.6600
P47=-134.2090;70.5000
P48=-134.0000;70.3900
P49=-133.5000;70.0980
P50=-133.3320;70.0000
P51=-133.0000;69.8150
P52=-132.5190;69.5000
P53=-132.5000;69.4880
P54=-132.0000;69.1950
P55=-131.7210;69.0000
P56=-131.5000;68.8520
P57=-131.0040;68.5000
P58=-131.0000;68.4970
P59=-130.5000;68.1130
P60=-130.3720;68.0000
P61=-130.0000;67.6740
P62=-129.8040;67.5000
P63=-129.5000;67.1960
P64=-129.2940;67.0000
P65=-129.0000;66.6410
P66=-128.8820;66.5000
P67=-128.5040;66.0000

P68=-128.5000;65.9940
P69=-128.1220;65.5000
P70=-128.0000;65.3230
P71=-127.7730;65.0000
P72=-127.5000;64.6150
P73=-127.4200;64.5000
P74=-127.0310;64.0000
P75=-127.0000;63.9610
P76=-126.6420;63.5000
P77=-126.5000;63.3280
P78=-126.2230;63.0000
P79=-126.0000;62.7110
P80=-125.8320;62.5000
P81=-125.5000;62.0390
P82=-125.4700;62.0000
P83=-125.1360;61.5000
P84=-125.0000;61.2420
P85=-124.8640;61.0000
P86=-124.6400;60.5000
P87=-124.5000;60.1220
P88=-124.4530;60.0000
P89=-124.2420;59.5000
P90=-124.0460;59.0000
P91=-124.0000;58.9050
P92=-123.8080;58.5000
P93=-123.5740;58.0000
P94=-123.5000;57.8410
P95=-123.3390;57.5000
P96=-123.1320;57.0000
P97=-123.0000;56.6700
P98=-122.9270;56.5000
P99=-122.7530;56.0000
P100=-122.5800;55.5000
P101=-122.5000;55.2810
P102=-122.3920;55.0000
P103=-122.2170;54.5000
P104=-122.0450;54.0000
P105=-122.0000;53.8520
P106=-121.8940;53.5000
P107=-121.7520;53.0000
P108=-121.6170;52.5000
P109=-121.5000;52.1520
P110=-121.4480;52.0000
P111=-121.2740;51.5000
P112=-121.0890;51.0000
P113=-121.0000;50.6920
P114=-120.9410;50.5000
P115=-120.8280;50.0000
P116=-120.7490;49.5000
P117=-120.6370;49.0000
P118=-120.5000;48.5400
P119=-120.4880;48.5000
P120=-120.3020;48.0000
P121=-120.1520;47.5000
P122=-120.0400;47.0000
P123=-120.0000;46.7200
P124=-119.9690;46.5000

P125=-119.8950;46.0000
P126=-119.7600;45.5000
P127=-119.6010;45.0000
P128=-119.5000;44.7010
P129=-119.4290;44.5000
P130=-119.3230;44.0000
P131=-119.2660;43.5000
P132=-119.1720;43.0000
P133=-119.0300;42.5000
P134=-119.0000;42.4170
P135=-118.8510;42.0000
P136=-118.7090;41.5000
P137=-118.6380;41.0000
P138=-118.5570;40.5000
P139=-118.5000;40.2980
P140=-118.4150;40.0000
P141=-118.2530;39.5000
P142=-118.1110;39.0000
P143=-118.0070;38.5000
P144=-118.0000;38.4580
P145=-117.9140;38.0000
P146=-117.7910;37.5000
P147=-117.6180;37.0000
P148=-117.5000;36.6100
P149=-117.4560;36.5000
P150=-117.3320;36.0000
P151=-117.2330;35.5000
P152=-117.0780;35.0000
P153=-117.0000;34.7710
P154=-116.8630;34.5000
P155=-116.6910;34.0000
P156=-116.6060;33.5000
P157=-116.5070;33.0000
P158=-116.5000;32.9760
P159=-116.2640;32.5000
P160=-116.0850;32.0000
P161=-116.0100;31.5000
P162=-116.0000;31.3890
P163=-115.8950;31.0000
P164=-115.7050;30.5000
P165=-115.5750;30.0000
P166=-115.5000;29.6650
P167=-115.2510;30.0000
P168=-115.2160;30.5000
P169=-115.2670;31.0000
P170=-115.3670;31.5000
P171=-115.4060;32.0000
P172=-115.4020;32.5000
P173=-115.3970;33.0000
P174=-115.4410;33.5000
P175=-115.5000;33.9640
P176=-115.5050;34.0000
P177=-115.5000;34.0950
P178=-115.4630;34.5000
P179=-115.2610;35.0000
P180=-115.0000;35.2120
P181=-114.9380;35.0000

P182=-114.7770;34.5000
P183=-114.5280;34.0000
P184=-114.5000;33.9470
P185=-114.4050;33.5000
P186=-114.2780;33.0000
P187=-114.0930;32.5000
P188=-114.0000;32.2980
P189=-113.9010;32.0000
P190=-113.7610;31.5000
P191=-113.6480;31.0000
P192=-113.5000;30.5340
P193=-113.4890;30.5000
P194=-113.3220;30.0000
P195=-113.1830;29.5000
P196=-113.0480;29.0000
P197=-113.0000;28.8590
P198=-112.8780;28.5000
P199=-112.7040;28.0000
P200=-112.5360;27.5000
P201=-112.5000;27.3940
P202=-112.3460;27.0000
P203=-112.1740;26.5000
P204=-112.0030;26.0000
P205=-112.0000;25.9920
P206=-111.7640;25.5000
P207=-111.6050;25.0000
P208=-111.5000;24.6870
P209=-111.3980;24.5000
P210=-111.1870;24.0000
P211=-111.0310;23.5000
P212=-111.0000;23.4160
P213=-110.7680;23.0000
P214=-110.5740;22.5000
P215=-110.5000;22.3030
P216=-110.3260;22.0000
P217=-110.1000;21.5000
P218=-110.0000;21.2730
P219=-109.8250;21.0000
P220=-109.5920;20.5000
P221=-109.5000;20.2860
P222=-109.3050;20.0000
P223=-109.0550;19.5000
P224=-109.0000;19.3920
P225=-108.7280;19.0000
P226=-108.5000;18.5090
P227=-108.4930;18.5000
P228=-108.1320;18.0000
P229=-108.0000;17.7810
P230=-107.7850;17.5000
P231=-107.5030;17.0000
P232=-107.5000;16.9960
P233=-107.0930;16.5000
P234=-107.0000;16.3720
P235=-106.6860;16.0000
P236=-106.5000;15.7300
P237=-106.3090;15.5000
P238=-106.0000;15.0920

P239=-105.9200;15.0000
P240=-105.5000;14.5000
P241=-105.0460;14.0000
P242=-105.0000;13.9460
P243=-104.5780;13.5000
P244=-104.5000;13.4250
P245=-104.0680;13.0000
P246=-104.0000;12.9370
P247=-103.5510;12.5000
P248=-103.5000;12.4540
P249=-103.0100;12.0000
P250=-103.0000;11.9920
P251=-102.5000;11.6380
P252=-102.3330;11.5000
P253=-102.0000;11.2760
P254=-101.6530;11.0000
P255=-101.5000;10.9060
P256=-101.0000;10.5600
P257=-100.9200;10.5000
P258=-100.5000;10.3000
P259=-100.0690;10.0000
P260=-100.0000;9.9700
P261=-99.5000 ;9.7180
P262=-99.1920 ;9.5000
P263=-99.0000 ;9.4200
P264=-98.5000 ;9.1380
P265=-98.2940 ;9.0000
P266=-98.0000 ;8.8730
P267=-97.5000 ;8.5840
P268=-97.3500 ;8.5000
P269=-97.0000 ;8.3810
P270=-96.5000 ;8.1970
P271=-96.0000 ;8.0140
P272=-95.9400 ;8.0000
P273=-95.5000 ;7.8700
P274=-95.0000 ;7.7990
P275=-94.5000 ;7.8320
P276=-94.0000 ;7.9550
P277=-93.8540 ;8.0000
P278=-93.5000 ;8.0960
P279=-93.0000 ;8.1860
P280=-92.5000 ;8.2070
P281=-92.0000 ;8.1900
P282=-91.5000 ;8.1730
P283=-91.0000 ;8.1840
P284=-90.5000 ;8.2340
P285=-90.0000 ;8.3120
P286=-89.5000 ;8.3980
P287=-89.0000 ;8.4750
P288=-88.8100 ;8.5000
P289=-88.5000 ;8.6000
P290=-88.0000 ;8.7090
P291=-87.5000 ;8.7870
P292=-87.0000 ;8.8570
P293=-86.5000 ;8.9250
P294=-86.0000 ;8.9820
P295=-85.8920 ;9.0000

P296=-85.5000 ;9.1360
P297=-85.0000 ;9.2990
P298=-84.5000 ;9.4370
P299=-84.1110 ;9.5000
P300=-84.0000 ;9.5500
P301=-83.5000 ;9.7770
P302=-83.0000 ;9.9400
P303=-82.7060 ;10.0000
P304=-82.5000 ;10.1060
P305=-82.0000 ;10.3800
P306=-81.5000 ;10.4770
P307=-81.4340 ;10.5000
P308=-81.0000 ;10.7480
P309=-80.5000 ;10.9460
P310=-80.2940 ;11.0000
P311=-80.0000 ;11.1830
P312=-79.5000 ;11.4320
P313=-79.3220 ;11.5000
P314=-79.0000 ;11.7220
P315=-78.5000 ;11.9570
P316=-78.4090 ;12.0000
P317=-78.0000 ;12.2880
P318=-77.5000 ;12.4930
P319=-77.4820 ;12.5000
P320=-77.0000 ;12.8530
P321=-76.7030 ;13.0000
P322=-76.5000 ;13.1510
P323=-76.0000 ;13.4430
P324=-75.8800 ;13.5000
P325=-75.5000 ;13.7770
P326=-75.0590 ;14.0000
P327=-75.0000 ;14.0460
P328=-74.5000 ;14.3990
P329=-74.3220 ;14.5000
P330=-74.0000 ;14.7420
P331=-73.5570 ;15.0000
P332=-73.5000 ;15.0460
P333=-73.0000 ;15.4170
P334=-72.8700 ;15.5000
P335=-72.5000 ;15.7960
P336=-72.1880 ;16.0000
P337=-72.0000 ;16.1550
P338=-71.5000 ;16.4980
P339=-71.4970 ;16.5000
P340=-71.0000 ;16.8980
P341=-70.8630 ;17.0000
P342=-70.5000 ;17.2980
P343=-70.2200 ;17.5000
P344=-70.0000 ;17.6950
P345=-69.5930 ;18.0000
P346=-69.5000 ;18.0800
P347=-69.0000 ;18.4580
P348=-68.9460 ;18.5000
P349=-68.5000 ;18.8740
P350=-68.3310 ;19.0000
P351=-68.0000 ;19.2790
P352=-67.7110 ;19.5000

P353=-67.5000 ;19.6890
P354=-67.1100 ;20.0000
P355=-67.0000 ;20.0980
P356=-66.5070 ;20.5000
P357=-66.5000 ;20.5060
P358=-66.0000 ;20.9390
P359=-65.9270 ;21.0000
P360=-65.5000 ;21.3770
P361=-65.3640 ;21.5000
P362=-65.0000 ;21.8390
P363=-64.8240 ;22.0000
P364=-64.5000 ;22.3000
P365=-64.2740 ;22.5000
P366=-64.0000 ;22.7580
P367=-63.7340 ;23.0000
P368=-63.5000 ;23.2110
P369=-63.1810 ;23.5000
P370=-63.0000 ;23.6690
P371=-62.6270 ;24.0000
P372=-62.5000 ;24.1130
P373=-62.0490 ;24.5000
P374=-62.0000 ;24.5430
P375=-61.5000 ;24.9730
P376=-61.4730 ;25.0000
P377=-61.0000 ;25.4320
P378=-60.9250 ;25.5000
P379=-60.5000 ;25.8570
P380=-60.3380 ;26.0000
P381=-60.0000 ;26.3090
P382=-59.7830 ;26.5000
P383=-59.5000 ;26.7440
P384=-59.2050 ;27.0000
P385=-59.0000 ;27.1890
P386=-58.6510 ;27.5000
P387=-58.5000 ;27.6360
P388=-58.0830 ;28.0000
P389=-58.0000 ;28.0780
P390=-57.5210 ;28.5000
P391=-57.5000 ;28.5200
P392=-57.0000 ;28.9940
P393=-56.9930 ;29.0000
P394=-56.5000 ;29.4520
P395=-56.4470 ;29.5000
P396=-56.0000 ;29.9080
P397=-55.8940 ;30.0000
P398=-55.5000 ;30.3990
P399=-55.3850 ;30.5000
P400=-55.0000 ;30.8910
P401=-54.8820 ;31.0000
P402=-54.5000 ;31.3830
P403=-54.3710 ;31.5000
P404=-54.0000 ;31.8700
P405=-53.8560 ;32.0000
P406=-53.5000 ;32.3670
P407=-53.3570 ;32.5000
P408=-53.0000 ;32.8940
P409=-52.8940 ;33.0000

P410=-52.5000 ;33.4490
P411=-52.4520 ;33.5000
P412=-52.0000 ;33.9820
P413=-51.9840 ;34.0000
P414=-51.5000 ;34.4700
P415=-51.4720 ;34.5000
P416=-51.0000 ;34.9260
P417=-50.9280 ;35.0000
P418=-50.5000 ;35.3600
P419=-50.3550 ;35.5000
P420=-50.0000 ;35.7780
P421=-49.7500 ;36.0000
P422=-49.5000 ;36.1880
P423=-49.1120 ;36.5000
P424=-49.0000 ;36.5820
P425=-48.5000 ;36.9410
P426=-48.4310 ;37.0000
P427=-48.0000 ;37.2960
P428=-47.7260 ;37.5000
P429=-47.5000 ;37.6510
P430=-47.0000 ;37.9860
P431=-46.9820 ;38.0000
P432=-46.5000 ;38.3080
P433=-46.1980 ;38.5000
P434=-46.0000 ;38.6230
P435=-45.5000 ;38.9270
P436=-45.3840 ;39.0000
P437=-45.0000 ;39.2430
P438=-44.5070 ;39.5000
P439=-44.5000 ;39.5040
P440=-44.0000 ;39.8210
P441=-43.6600 ;40.0000
P442=-43.5000 ;40.0970
P443=-43.0000 ;40.3630
P444=-42.7370 ;40.5000
P445=-42.5000 ;40.6450
P446=-42.0000 ;40.8760
P447=-41.7530 ;41.0000
P448=-41.5000 ;41.1550
P449=-41.0000 ;41.3670
P450=-40.7170 ;41.5000
P451=-40.5000 ;41.6310
P452=-40.0000 ;41.8380
P453=-39.6270 ;42.0000
P454=-39.5000 ;42.0730
P455=-39.0000 ;42.2900
P456=-38.5000 ;42.4820
P457=-38.4580 ;42.5000
P458=-38.0000 ;42.7170
P459=-37.5000 ;42.8860
P460=-37.2110 ;43.0000
P461=-37.0000 ;43.1050
P462=-36.5000 ;43.2830
P463=-36.0000 ;43.4510
P464=-35.8620 ;43.5000
P465=-35.5000 ;43.6560
P466=-35.0000 ;43.8040

P467=-34.5000 ;43.9630
P468=-34.3840 ;44.0000
P469=-34.0000 ;44.1500
P470=-33.5000 ;44.2880
P471=-33.0000 ;44.4260
P472=-32.7330 ;44.5000
P473=-32.5000 ;44.5880
P474=-32.0000 ;44.7290
P475=-31.5000 ;44.8380
P476=-31.0000 ;44.9640
P477=-30.8450 ;45.0000
P478=-30.5000 ;45.1090
P479=-30.0000 ;45.2270
P480=-29.5000 ;45.3170
P481=-29.0000 ;45.4240
P482=-28.6060 ;45.5000
P483=-28.5000 ;45.5310
P484=-28.0000 ;45.6480
P485=-27.5000 ;45.7370
P486=-27.0000 ;45.8090
P487=-26.5000 ;45.8890
P488=-26.0000 ;45.9660
P489=-25.7500 ;46.0000
P490=-25.5000 ;46.0510
P491=-25.0000 ;46.1360
P492=-24.5000 ;46.2030
P493=-24.0000 ;46.2570
P494=-23.8360 ;46.2720
P495=-23.6283 ;46.2907

[C23]

gain=-40.00

n_point=94

P1=-65.5000 ;49.3070
P2=-65.6780 ;49.0000
P3=-65.8390 ;48.8395
P4=-66.0000 ;48.6790
P5=-66.1080 ;48.5000
P6=-66.3040 ;48.2590
P7=-66.5000 ;48.0180
P8=-66.5110 ;48.0000
P9=-66.6520 ;47.7500
P10=-66.7930 ;47.5000
P11=-67.0000 ;47.2460
P12=-67.1460 ;47.0000
P13=-67.3230 ;46.7560
P14=-67.5000 ;46.5120
P15=-67.5080 ;46.5000
P16=-67.6610 ;46.2500
P17=-67.8140 ;46.0000
P18=-68.0000 ;45.8000
P19=-68.2010 ;45.5000
P20=-68.3505 ;45.2875
P21=-68.5000 ;45.0750
P22=-68.5520 ;45.0000
P23=-68.6930 ;44.7500
P24=-68.8340 ;44.5000
P25=-69.0000 ;44.2880

P26=-69.1780 ;44.0000
P27=-69.3390 ;43.7820
P28=-69.5000 ;43.5640
P29=-69.5430 ;43.5000
P30=-69.6825 ;43.2500
P31=-69.8220 ;43.0000
P32=-70.0000 ;42.7630
P33=-70.1610 ;42.5000
P34=-70.3305 ;42.2715
P35=-70.5000 ;42.0430
P36=-70.5290 ;42.0000
P37=-70.6495 ;41.7500
P38=-70.7700 ;41.5000
P39=-71.0000 ;41.2520
P40=-71.1630 ;41.0000
P41=-71.3255 ;40.7500
P42=-71.4880 ;40.5000
P43=-71.5000 ;40.4900
P44=-71.6230 ;40.2450
P45=-71.7460 ;40.0000
P46=-71.6230 ;39.8490
P47=-71.5000 ;39.6980
P48=-71.3650 ;39.8490
P49=-71.2300 ;40.0000
P50=-71.0000 ;40.2490
P51=-70.7970 ;40.5000
P52=-70.5000 ;40.7710
P53=-70.3090 ;41.0000
P54=-70.1545 ;41.1985
P55=-70.0000 ;41.3970
P56=-69.9130 ;41.5000
P57=-69.7345 ;41.7500
P58=-69.5560 ;42.0000
P59=-69.5000 ;42.0590
P60=-69.3280 ;42.2795
P61=-69.1560 ;42.5000
P62=-69.0000 ;42.7110
P63=-68.7770 ;43.0000
P64=-68.6385 ;43.1930
P65=-68.5000 ;43.3860
P66=-68.4150 ;43.5000
P67=-68.2395 ;43.7500
P68=-68.0640 ;44.0000
P69=-68.0000 ;44.0950
P70=-67.8575 ;44.2975
P71=-67.7150 ;44.5000
P72=-67.6075 ;44.6710
P73=-67.5000 ;44.8420
P74=-67.3920 ;45.0000
P75=-67.2385 ;45.2500
P76=-67.0850 ;45.5000
P77=-67.0000 ;45.6260
P78=-66.8750 ;45.8130
P79=-66.7500 ;46.0000
P80=-66.6250 ;46.2015
P81=-66.5000 ;46.4030
P82=-66.4310 ;46.5000

P83=-66.3100 ;46.7500
P84=-66.1890 ;47.0000
P85=-66.0000 ;47.3310
P86=-65.9120 ;47.5000
P87=-65.7895 ;47.7500
P88=-65.6670 ;48.0000
P89=-65.5000 ;48.2520
P90=-65.3640 ;48.5000
P91=-65.2920 ;48.7500
P92=-65.2200 ;49.0000
P93=-65.3600 ;49.1535
P94=-65.5000 ;49.3070
[C24]
gain=-30.00
n_point=72
P1=-77.5000 ;48.7990
P2=-77.5833 ;48.8322
P3=-77.6667 ;48.8653
P4=-77.7500 ;48.8985
P5=-77.8333 ;48.9317
P6=-77.9167 ;48.9648
P7=-78.0000 ;48.9980
P8=-78.1000 ;48.9852
P9=-78.2000 ;48.9724
P10=-78.3000 ;48.9596
P11=-78.4000 ;48.9468
P12=-78.5000 ;48.9340
P13=-78.5490 ;48.8720
P14=-78.5980 ;48.8100
P15=-78.6470 ;48.7480
P16=-78.6960 ;48.6860
P17=-78.7450 ;48.6240
P18=-78.7940 ;48.5620
P19=-78.8430 ;48.5000
P20=-78.8479 ;48.4286
P21=-78.8527 ;48.3571
P22=-78.8576 ;48.2857
P23=-78.8624 ;48.2143
P24=-78.8673 ;48.1429
P25=-78.8721 ;48.0714
P26=-78.8770 ;48.0000
P27=-78.8386 ;47.9375
P28=-78.8002 ;47.8750
P29=-78.7619 ;47.8125
P30=-78.7235 ;47.7500
P31=-78.6851 ;47.6875
P32=-78.6468 ;47.6250
P33=-78.6084 ;47.5625
P34=-78.5700 ;47.5000
P35=-78.5000 ;47.4470
P36=-78.4167 ;47.4053
P37=-78.3333 ;47.3637
P38=-78.2500 ;47.3220
P39=-78.1667 ;47.2803
P40=-78.0833 ;47.2387
P41=-78.0000 ;47.1970
P42=-77.9000 ;47.2032

P43=-77.8000 ;47.2094
P44=-77.7000 ;47.2156
P45=-77.6000 ;47.2218
P46=-77.5000 ;47.2280
P47=-77.4365 ;47.2733
P48=-77.3730 ;47.3187
P49=-77.3095 ;47.3640
P50=-77.2460 ;47.4093
P51=-77.1825 ;47.4547
P52=-77.1190 ;47.5000
P53=-77.1066 ;47.5714
P54=-77.0941 ;47.6429
P55=-77.0817 ;47.7143
P56=-77.0693 ;47.7857
P57=-77.0569 ;47.8571
P58=-77.0444 ;47.9286
P59=-77.0320 ;48.0000
P60=-77.0620 ;48.0625
P61=-77.0920 ;48.1250
P62=-77.1220 ;48.1875
P63=-77.1520 ;48.2500
P64=-77.1820 ;48.3125
P65=-77.2120 ;48.3750
P66=-77.2420 ;48.4375
P67=-77.2720 ;48.5000
P68=-77.3176 ;48.5598
P69=-77.3632 ;48.6196
P70=-77.4088 ;48.6794
P71=-77.4544 ;48.7392
P72=-77.5000 ;48.7990

[C25]

gain=-8.00

n_point=98

P1=-82.0166 ;45.0340
P2=-82.3648 ;44.9654
P3=-82.7130 ;44.8968
P4=-82.9710 ;44.8194
P5=-83.3005 ;44.6701
P6=-83.6300 ;44.5209
P7=-83.9442 ;44.3126
P8=-84.2584 ;44.1043
P9=-84.3899 ;43.9973
P10=-84.5685 ;43.8396
P11=-84.8018 ;43.6006
P12=-85.0351 ;43.3615
P13=-85.1507 ;43.2221
P14=-85.2664 ;43.0828
P15=-85.4228 ;42.8590
P16=-85.5793 ;42.6352
P17=-85.7205 ;42.4083
P18=-85.8218 ;42.2231
P19=-85.9232 ;42.0380
P20=-86.0268 ;41.8245
P21=-86.1300 ;41.5661
P22=-86.2332 ;41.3078
P23=-86.3363 ;41.0494
P24=-86.3601 ;40.9800

P25=-86.3760 ;40.9255
P26=-86.4295 ;40.6737
P27=-86.4829 ;40.4219
P28=-86.5363 ;40.1701
P29=-86.5897 ;39.9183
P30=-86.5833 ;39.6014
P31=-86.5769 ;39.2845
P32=-86.5705 ;38.9677
P33=-86.5498 ;38.8254
P34=-86.4621 ;38.5346
P35=-86.3900 ;38.3569
P36=-86.3179 ;38.1792
P37=-86.1309 ;37.9463
P38=-85.9438 ;37.7134
P39=-85.7951 ;37.5848
P40=-85.6629 ;37.5085
P41=-85.4747 ;37.4237
P42=-85.2864 ;37.3389
P43=-85.0848 ;37.3019
P44=-84.8832 ;37.2650
P45=-84.6520 ;37.2606
P46=-84.4208 ;37.2562
P47=-84.0479 ;37.3013
P48=-83.7690 ;37.3883
P49=-83.4901 ;37.4753
P50=-83.2112 ;37.5623
P51=-83.1279 ;37.5960
P52=-83.0783 ;37.6161
P53=-82.8324 ;37.7532
P54=-82.5866 ;37.8903
P55=-82.3408 ;38.0275
P56=-82.1126 ;38.1987
P57=-81.8845 ;38.3699
P58=-81.6563 ;38.5412
P59=-81.6078 ;38.5833
P60=-81.4075 ;38.7793
P61=-81.2072 ;38.9752
P62=-81.0069 ;39.1712
P63=-80.8449 ;39.3600
P64=-80.6829 ;39.5489
P65=-80.5627 ;39.7071
P66=-80.4425 ;39.8653
P67=-80.3156 ;40.0595
P68=-80.1887 ;40.2536
P69=-80.0618 ;40.4478
P70=-79.9906 ;40.5746
P71=-79.9495 ;40.6492
P72=-79.8638 ;40.8102
P73=-79.7782 ;40.9712
P74=-79.6588 ;41.2514
P75=-79.5393 ;41.5315
P76=-79.5112 ;41.6134
P77=-79.4821 ;41.7057
P78=-79.4190 ;42.0057
P79=-79.3558 ;42.3057
P80=-79.2927 ;42.6057
P81=-79.2849 ;42.6713

P82=-79.2798 ;42.7227
P83=-79.2813 ;42.9734
P84=-79.3197 ;43.2711
P85=-79.3580 ;43.5688
P86=-79.4088 ;43.7567
P87=-79.5552 ;44.0088
P88=-79.7016 ;44.2609
P89=-79.9552 ;44.4789
P90=-80.2089 ;44.6968
P91=-80.3578 ;44.7780
P92=-80.5570 ;44.8591
P93=-80.7562 ;44.9403
P94=-81.1015 ;44.9938
P95=-81.4468 ;45.0473
P96=-81.5164 ;45.0497
P97=-81.5793 ;45.0520
P98=-82.0166 ;45.0340

[C26]

gain=-15.00

n_point=104

P1=-83.9299 ;46.2476
P2=-84.0004 ;46.2077
P3=-84.0676 ;46.1689
P4=-84.4263 ;45.9258
P5=-84.7850 ;45.6827
P6=-85.0338 ;45.4657
P7=-85.2825 ;45.2487
P8=-85.4679 ;45.0724
P9=-85.7748 ;44.7328
P10=-86.0587 ;44.3792
P11=-86.1823 ;44.2175
P12=-86.4193 ;43.8520
P13=-86.5608 ;43.6068
P14=-86.6744 ;43.3867
P15=-86.7880 ;43.1666
P16=-86.8732 ;42.9554
P17=-86.9584 ;42.7441
P18=-87.0414 ;42.4914
P19=-87.1519 ;42.1023
P20=-87.2324 ;41.7702
P21=-87.2734 ;41.5586
P22=-87.3144 ;41.3470
P23=-87.3729 ;41.0303
P24=-87.4222 ;40.7220
P25=-87.4541 ;40.4926
P26=-87.4860 ;40.2633
P27=-87.5204 ;39.9544
P28=-87.5438 ;39.6141
P29=-87.5557 ;39.2445
P30=-87.5345 ;38.8722
P31=-87.4964 ;38.6066
P32=-87.4584 ;38.3409
P33=-87.4482 ;38.2971
P34=-87.3586 ;38.0374
P35=-87.2689 ;37.7777
P36=-87.1768 ;37.5698
P37=-86.9782 ;37.2568

P38=-86.6889 ;36.9480
P39=-86.4553 ;36.7971
P40=-86.2217 ;36.6463
P41=-85.9423 ;36.5160
P42=-85.8115 ;36.4714
P43=-85.6045 ;36.4343
P44=-85.1897 ;36.4095
P45=-84.7750 ;36.3848
P46=-84.5522 ;36.4033
P47=-84.3959 ;36.4209
P48=-84.1304 ;36.4713
P49=-83.8650 ;36.5218
P50=-83.4472 ;36.6745
P51=-83.2227 ;36.7668
P52=-82.9146 ;36.9046
P53=-82.6064 ;37.0424
P54=-82.2453 ;37.2611
P55=-81.8843 ;37.4798
P56=-81.8469 ;37.5061
P57=-81.8074 ;37.5345
P58=-81.4800 ;37.7859
P59=-81.1525 ;38.0374
P60=-80.9119 ;38.2553
P61=-80.6713 ;38.4731
P62=-80.5096 ;38.6367
P63=-80.2345 ;38.9333
P64=-80.0782 ;39.1177
P65=-79.9219 ;39.3020
P66=-79.7872 ;39.4840
P67=-79.6346 ;39.6923
P68=-79.4821 ;39.9006
P69=-79.3959 ;40.0420
P70=-79.2479 ;40.2738
P71=-79.0999 ;40.5055
P72=-78.9186 ;40.8486
P73=-78.8121 ;41.0617
P74=-78.7056 ;41.2748
P75=-78.5802 ;41.5387
P76=-78.5032 ;41.7365
P77=-78.3826 ;42.0822
P78=-78.2620 ;42.4279
P79=-78.2158 ;42.5832
P80=-78.1727 ;42.7313
P81=-78.1215 ;43.0767
P82=-78.0703 ;43.4221
P83=-78.0554 ;43.6441
P84=-78.0527 ;43.9719
P85=-78.1008 ;44.2843
P86=-78.1647 ;44.5093
P87=-78.2285 ;44.7343
P88=-78.3707 ;45.0127
P89=-78.6244 ;45.3383
P90=-78.9048 ;45.5965
P91=-79.1420 ;45.7528
P92=-79.3792 ;45.9092
P93=-79.6681 ;46.0575
P94=-79.8122 ;46.1280

P95=-80.2002 ;46.3057
P96=-80.5587 ;46.4489
P97=-81.0982 ;46.6381
P98=-81.6028 ;46.7579
P99=-81.9646 ;46.7930
P100=-82.4997 ;46.7571
P101=-82.7992 ;46.6856
P102=-83.0987 ;46.6142
P103=-83.5143 ;46.4309
P104=-83.9299 ;46.2476