

```
[FormatInfo]
format_ver=1
[GeoMain]
ntc_id=910100000
adm=USA
sat_name=USABSS-21
long_nom=-101.0000
n_diag=1
[COHeader]
beam_id=CB18
emi_rcp=E
polar_disc=C
reason=B
n_bore=1
n_cont=27
[B1]
gain=0.00
p=-97.2230;31.8530
[C1]
gain=-40.00
n_point=185
P1=-85.5000 ;39.8230
P2=-85.5230 ;40.0000
P3=-85.6310 ;40.5000
P4=-85.7990 ;41.0000
P5=-86.0000 ;41.4540
P6=-86.0210 ;41.5000
P7=-86.2860 ;42.0000
P8=-86.5000 ;42.3180
P9=-86.6420 ;42.5000
P10=-87.0000 ;42.8910
P11=-87.1220 ;43.0000
P12=-87.5000 ;43.3440
P13=-87.7200 ;43.5000
P14=-88.0000 ;43.7020
P15=-88.5000 ;43.9780
P16=-88.5490 ;44.0000
P17=-89.0000 ;44.2100
P18=-89.5000 ;44.3700
P19=-90.0000 ;44.4990
P20=-90.0640 ;44.5000
P21=-90.5000 ;44.5040
P22=-90.5100 ;44.5000
P23=-90.5410 ;44.0000
P24=-90.5000 ;43.9580
P25=-90.1440 ;43.5000
P26=-90.0000 ;43.3540
P27=-89.7000 ;43.0000
P28=-89.5000 ;42.8000
P29=-89.2370 ;42.5000
P30=-89.0000 ;42.2580
P31=-88.7760 ;42.0000
P32=-88.5000 ;41.6900
P33=-88.3560 ;41.5000
P34=-88.0000 ;41.0270
P35=-87.9840 ;41.0000
P36=-87.6940 ;40.5000
```

P37=-87.5000 ;40.1710  
P38=-87.4280 ;40.0000  
P39=-87.2210 ;39.5000  
P40=-87.0360 ;39.0000  
P41=-87.0000 ;38.9100  
P42=-86.9010 ;38.5000  
P43=-86.8220 ;38.0000  
P44=-86.7550 ;37.5000  
P45=-86.6700 ;37.0000  
P46=-86.6810 ;36.5000  
P47=-86.6830 ;36.0000  
P48=-86.6880 ;35.5000  
P49=-86.7990 ;35.0000  
P50=-86.8790 ;34.5000  
P51=-86.9360 ;34.0000  
P52=-86.9850 ;33.5000  
P53=-87.0000 ;33.3100  
P54=-87.1020 ;33.0000  
P55=-87.2770 ;32.5000  
P56=-87.3840 ;32.0000  
P57=-87.5000 ;31.7520  
P58=-87.6460 ;31.5000  
P59=-87.8490 ;31.0000  
P60=-88.0000 ;30.5490  
P61=-88.0300 ;30.5000  
P62=-88.3090 ;30.0000  
P63=-88.5000 ;29.5540  
P64=-88.5370 ;29.5000  
P65=-88.8250 ;29.0000  
P66=-89.0000 ;28.7040  
P67=-89.1550 ;28.5000  
P68=-89.4420 ;28.0000  
P69=-89.5000 ;27.9370  
P70=-89.8430 ;27.5000  
P71=-90.0000 ;27.3050  
P72=-90.2490 ;27.0000  
P73=-90.5000 ;26.6830  
P74=-90.6590 ;26.5000  
P75=-91.0000 ;26.0860  
P76=-91.0770 ;26.0000  
P77=-91.5000 ;25.5590  
P78=-91.5550 ;25.5000  
P79=-92.0000 ;25.0120  
P80=-92.0120 ;25.0000  
P81=-92.5000 ;24.5250  
P82=-92.5250 ;24.5000  
P83=-93.0000 ;24.0400  
P84=-93.0390 ;24.0000  
P85=-93.5000 ;23.5980  
P86=-93.6060 ;23.5000  
P87=-94.0000 ;23.1720  
P88=-94.1850 ;23.0000  
P89=-94.5000 ;22.7530  
P90=-94.8290 ;22.5000  
P91=-95.0000 ;22.3550  
P92=-95.5000 ;22.0450  
P93=-95.5670 ;22.0000

P94=-96.0000 ;21.7590  
P95=-96.5000 ;21.6100  
P96=-96.7550 ;21.5000  
P97=-97.0000 ;21.3810  
P98=-97.5000 ;21.3090  
P99=-98.0000 ;21.2490  
P100=-98.5000 ;21.2260  
P101=-99.0000 ;21.2390  
P102=-99.5000 ;21.2710  
P103=-100.0000;21.3250  
P104=-100.5000;21.3930  
P105=-100.9630;21.5000  
P106=-101.0000;21.5130  
P107=-101.5000;21.6330  
P108=-102.0000;21.6740  
P109=-102.3490;21.5000  
P110=-102.0000;21.2010  
P111=-101.8680;21.0000  
P112=-101.5000;20.8070  
P113=-101.0000;20.6290  
P114=-100.5000;20.5180  
P115=-100.4080;20.5000  
P116=-100.0000;20.4110  
P117=-99.5000 ;20.3520  
P118=-99.0000 ;20.3560  
P119=-98.5000 ;20.4240  
P120=-98.1910 ;20.5000  
P121=-98.0000 ;20.5550  
P122=-97.5000 ;20.6310  
P123=-97.0000 ;20.6950  
P124=-96.5000 ;20.8660  
P125=-96.2380 ;21.0000  
P126=-96.0000 ;21.1360  
P127=-95.5000 ;21.2900  
P128=-95.1610 ;21.5000  
P129=-95.0000 ;21.5960  
P130=-94.5000 ;21.9040  
P131=-94.3820 ;22.0000  
P132=-94.0000 ;22.2510  
P133=-93.7060 ;22.5000  
P134=-93.5000 ;22.6420  
P135=-93.1090 ;23.0000  
P136=-93.0000 ;23.1260  
P137=-92.5820 ;23.5000  
P138=-92.5000 ;23.5610  
P139=-92.0390 ;24.0000  
P140=-92.0000 ;24.0540  
P141=-91.5360 ;24.5000  
P142=-91.5000 ;24.5310  
P143=-91.0260 ;25.0000  
P144=-91.0000 ;25.0310  
P145=-90.5330 ;25.5000  
P146=-90.5000 ;25.5340  
P147=-90.0790 ;26.0000  
P148=-90.0000 ;26.0840  
P149=-89.6010 ;26.5000  
P150=-89.5000 ;26.6170

P151=-89.1640 ;27.0000  
P152=-89.0000 ;27.2240  
P153=-88.7630 ;27.5000  
P154=-88.5000 ;27.9130  
P155=-88.4250 ;28.0000  
P156=-88.0890 ;28.5000  
P157=-88.0000 ;28.6440  
P158=-87.7310 ;29.0000  
P159=-87.5120 ;29.5000  
P160=-87.5000 ;29.5200  
P161=-87.1720 ;30.0000  
P162=-87.0070 ;30.5000  
P163=-87.0000 ;30.5130  
P164=-86.6860 ;31.0000  
P165=-86.5550 ;31.5000  
P166=-86.5000 ;31.6560  
P167=-86.2890 ;32.0000  
P168=-86.1020 ;32.5000  
P169=-86.0090 ;33.0000  
P170=-86.0000 ;33.0990  
P171=-85.8310 ;33.5000  
P172=-85.7020 ;34.0000  
P173=-85.5770 ;34.5000  
P174=-85.5150 ;35.0000  
P175=-85.5000 ;35.2730  
P176=-85.4320 ;35.5000  
P177=-85.3550 ;36.0000  
P178=-85.2910 ;36.5000  
P179=-85.2390 ;37.0000  
P180=-85.2310 ;37.5000  
P181=-85.2530 ;38.0000  
P182=-85.2620 ;38.5000  
P183=-85.3140 ;39.0000  
P184=-85.4360 ;39.5000  
P185=-85.5000 ;39.8230  
[C2]  
gain=-50.00  
n\_point=701  
P1=-126.4440;80.2080  
P2=-126.0160;80.0000  
P3=-126.0000;79.9940  
P4=-125.5000;79.8480  
P5=-125.0000;79.6340  
P6=-124.7440;79.5000  
P7=-124.5000;79.3940  
P8=-124.0000;79.1800  
P9=-123.7180;79.0000  
P10=-123.5000;78.8770  
P11=-123.0000;78.6310  
P12=-122.8180;78.5000  
P13=-122.5000;78.2820  
P14=-122.0640;78.0000  
P15=-122.0000;77.9410  
P16=-121.5000;77.5200  
P17=-121.4760;77.5000  
P18=-121.0600;77.0000  
P19=-121.0000;76.9550

P20=-120.5410;76.5000  
P21=-120.5000;76.4600  
P22=-120.0380;76.0000  
P23=-120.0000;75.9520  
P24=-119.6130;75.5000  
P25=-119.5000;75.3020  
P26=-119.3120;75.0000  
P27=-119.1150;74.5000  
P28=-119.0110;74.0000  
P29=-119.0000;73.9710  
P30=-118.8200;73.5000  
P31=-118.6060;73.0000  
P32=-118.5000;72.6900  
P33=-118.4280;72.5000  
P34=-118.4220;72.0000  
P35=-118.3290;71.5000  
P36=-118.1870;71.0000  
P37=-118.1290;70.5000  
P38=-118.2000;70.0000  
P39=-118.0980;69.5000  
P40=-118.1100;69.0000  
P41=-118.2190;68.5000  
P42=-118.1960;68.0000  
P43=-118.2950;67.5000  
P44=-118.3440;67.0000  
P45=-118.4110;66.5000  
P46=-118.4890;66.0000  
P47=-118.5000;65.7620  
P48=-118.5080;65.5000  
P49=-118.5710;65.0000  
P50=-118.5630;64.5000  
P51=-118.6470;64.0000  
P52=-118.6630;63.5000  
P53=-118.8190;63.0000  
P54=-118.8650;62.5000  
P55=-119.0000;62.1560  
P56=-119.0490;62.0000  
P57=-119.1230;61.5000  
P58=-119.2280;61.0000  
P59=-119.3330;60.5000  
P60=-119.3740;60.0000  
P61=-119.4920;59.5000  
P62=-119.5000;59.4090  
P63=-119.5370;59.0000  
P64=-119.6280;58.5000  
P65=-119.7340;58.0000  
P66=-119.8220;57.5000  
P67=-119.9180;57.0000  
P68=-119.9920;56.5000  
P69=-120.0000;56.4630  
P70=-120.0960;56.0000  
P71=-120.2030;55.5000  
P72=-120.2790;55.0000  
P73=-120.3970;54.5000  
P74=-120.4570;54.0000  
P75=-120.5000;53.7400  
P76=-120.5690;53.5000

P77=-120.5960;53.0000  
P78=-120.7020;52.5000  
P79=-120.7420;52.0000  
P80=-120.8590;51.5000  
P81=-120.9110;51.0000  
P82=-120.9900;50.5000  
P83=-120.9910;50.0000  
P84=-121.0000;49.8650  
P85=-121.0720;49.5000  
P86=-121.1230;49.0000  
P87=-121.2050;48.5000  
P88=-121.3040;48.0000  
P89=-121.3000;47.5000  
P90=-121.3630;47.0000  
P91=-121.3000;46.5000  
P92=-121.3810;46.0000  
P93=-121.2990;45.5000  
P94=-121.3780;45.0000  
P95=-121.2710;44.5000  
P96=-121.3350;44.0000  
P97=-121.2700;43.5000  
P98=-121.2750;43.0000  
P99=-121.1770;42.5000  
P100=-121.0290;42.0000  
P101=-121.0000;41.8170  
P102=-120.9780;41.5000  
P103=-120.9240;41.0000  
P104=-120.9120;40.5000  
P105=-120.8230;40.0000  
P106=-120.7320;39.5000  
P107=-120.6380;39.0000  
P108=-120.5560;38.5000  
P109=-120.5000;38.0980  
P110=-120.4870;38.0000  
P111=-120.3690;37.5000  
P112=-120.2370;37.0000  
P113=-120.1330;36.5000  
P114=-120.0260;36.0000  
P115=-120.0000;35.8720  
P116=-119.8990;35.5000  
P117=-119.7510;35.0000  
P118=-119.5950;34.5000  
P119=-119.5000;34.1180  
P120=-119.4410;34.0000  
P121=-119.2690;33.5000  
P122=-119.1240;33.0000  
P123=-119.0000;32.6000  
P124=-118.8160;32.5000  
P125=-118.5000;32.1070  
P126=-118.4370;32.5000  
P127=-118.4120;33.0000  
P128=-118.3580;33.5000  
P129=-118.2850;34.0000  
P130=-118.2390;34.5000  
P131=-118.1800;35.0000  
P132=-118.0730;35.5000  
P133=-118.0000;35.9650

P134=-117.7990;36.0000  
P135=-117.5000;36.0230  
P136=-117.4950;36.0000  
P137=-117.4280;35.5000  
P138=-117.3050;35.0000  
P139=-117.1470;34.5000  
P140=-117.0000;34.0580  
P141=-116.9850;34.0000  
P142=-116.8660;33.5000  
P143=-116.7360;33.0000  
P144=-116.6010;32.5000  
P145=-116.5000;32.1090  
P146=-116.4660;32.0000  
P147=-116.3180;31.5000  
P148=-116.1870;31.0000  
P149=-116.0710;30.5000  
P150=-116.0000;30.1890  
P151=-115.9340;30.0000  
P152=-115.7860;29.5000  
P153=-115.6640;29.0000  
P154=-115.5690;28.5000  
P155=-115.5000;28.0300  
P156=-115.4910;28.0000  
P157=-115.3260;27.5000  
P158=-115.2130;27.0000  
P159=-115.1130;26.5000  
P160=-115.0220;26.0000  
P161=-115.0000;25.8900  
P162=-114.8840;25.5000  
P163=-114.7550;25.0000  
P164=-114.6460;24.5000  
P165=-114.5480;24.0000  
P166=-114.5000;23.7890  
P167=-114.4120;23.5000  
P168=-114.2740;23.0000  
P169=-114.1560;22.5000  
P170=-114.0280;22.0000  
P171=-114.0000;21.9120  
P172=-113.8650;21.5000  
P173=-113.7410;21.0000  
P174=-113.6180;20.5000  
P175=-113.5000;20.1750  
P176=-113.4430;20.0000  
P177=-113.3460;19.5000  
P178=-113.3340;19.0000  
P179=-113.5000;18.5180  
P180=-113.8300;19.0000  
P181=-114.0000;19.1190  
P182=-114.2670;19.5000  
P183=-114.5000;19.8270  
P184=-114.6300;20.0000  
P185=-114.9190;20.5000  
P186=-115.0000;20.6440  
P187=-115.2590;21.0000  
P188=-115.4920;21.5000  
P189=-115.5000;21.5190  
P190=-115.8590;22.0000

P191=-116.0000;22.4700  
P192=-116.1550;22.0000  
P193=-116.1000;21.5000  
P194=-116.0340;21.0000  
P195=-116.0000;20.8130  
P196=-115.8930;20.5000  
P197=-115.7450;20.0000  
P198=-115.6310;19.5000  
P199=-115.5210;19.0000  
P200=-115.5000;18.9330  
P201=-115.3220;18.5000  
P202=-115.1350;18.0000  
P203=-115.0000;17.6320  
P204=-114.9350;17.5000  
P205=-114.7140;17.0000  
P206=-114.5060;16.5000  
P207=-114.5000;16.4860  
P208=-114.2730;16.0000  
P209=-114.0940;15.5000  
P210=-114.0000;15.2630  
P211=-113.8880;15.0000  
P212=-113.7030;14.5000  
P213=-113.5000;14.1280  
P214=-113.4300;14.0000  
P215=-113.0880;13.5000  
P216=-113.0000;13.3970  
P217=-112.7100;13.0000  
P218=-112.5000;12.7210  
P219=-112.3450;12.5000  
P220=-112.0000;12.0160  
P221=-111.9890;12.0000  
P222=-111.7700;11.5000  
P223=-111.9820;11.0000  
P224=-112.0000;10.9960  
P225=-112.0080;11.0000  
P226=-112.5000;11.2220  
P227=-113.0000;11.4580  
P228=-113.0960;11.5000  
P229=-113.5000;11.7170  
P230=-114.0000;11.9140  
P231=-114.1110;11.5000  
P232=-114.0180;11.0000  
P233=-114.0000;10.9520  
P234=-113.8250;10.5000  
P235=-113.6160;10.0000  
P236=-113.5000;9.8160  
P237=-113.2910;9.5000  
P238=-113.0000;9.1810  
P239=-112.8350;9.0000  
P240=-112.5000;8.7120  
P241=-112.2610;8.5000  
P242=-112.0000;8.3190  
P243=-111.5670;8.0000  
P244=-111.5000;7.9580  
P245=-111.0000;7.6400  
P246=-110.8120;7.5000  
P247=-110.5000;7.2860



P248=-110.1480;7.0000  
P249=-110.0000;6.8860  
P250=-109.5410;6.5000  
P251=-109.5000;6.4620  
P252=-109.0000;6.0690  
P253=-108.9180;6.0000  
P254=-108.5000;5.6910  
P255=-108.2110;5.5000  
P256=-108.0000;5.3760  
P257=-107.5000;5.1560  
P258=-107.1720;5.0000  
P259=-107.0000;4.9450  
P260=-106.5000;4.8000  
P261=-106.0000;4.6260  
P262=-105.6800;4.5000  
P263=-105.5000;4.4700  
P264=-105.0000;4.3660  
P265=-104.5000;4.2510  
P266=-104.0000;4.1540  
P267=-103.5000;4.0920  
P268=-103.0000;4.0760  
P269=-102.5000;4.0970  
P270=-102.0000;4.1370  
P271=-101.5000;4.1810  
P272=-101.0000;4.2210  
P273=-100.5000;4.2580  
P274=-100.0000;4.2970  
P275=-99.5000 ;4.3460  
P276=-99.0000 ;4.4030  
P277=-98.5000 ;4.4600  
P278=-98.1890 ;4.5000  
P279=-98.0000 ;4.5620  
P280=-97.5000 ;4.7370  
P281=-97.0000 ;4.8860  
P282=-96.5110 ;5.0000  
P283=-96.5000 ;5.0050  
P284=-96.0000 ;5.2560  
P285=-95.5000 ;5.4190  
P286=-95.2050 ;5.5000  
P287=-95.0000 ;5.6070  
P288=-94.5000 ;5.8390  
P289=-94.0000 ;5.9710  
P290=-93.8810 ;6.0000  
P291=-93.5000 ;6.1960  
P292=-93.0000 ;6.4040  
P293=-92.6280 ;6.5000  
P294=-92.5000 ;6.5740  
P295=-92.0000 ;6.8710  
P296=-91.6850 ;7.0000  
P297=-91.5000 ;7.1240  
P298=-91.0000 ;7.4240  
P299=-90.8440 ;7.5000  
P300=-90.5000 ;7.7630  
P301=-90.0110 ;8.0000  
P302=-90.0000 ;8.0090  
P303=-89.5000 ;8.4100  
P304=-89.3780 ;8.5000

P305=-89.0000 ;8.8310  
P306=-88.6630 ;9.0000  
P307=-88.5000 ;9.1340  
P308=-88.0000 ;9.4650  
P309=-87.9640 ;9.5000  
P310=-87.5000 ;9.9130  
P311=-87.3500 ;10.0000  
P312=-87.0000 ;10.3200  
P313=-86.7870 ;10.5000  
P314=-86.5000 ;10.7740  
P315=-86.2130 ;11.0000  
P316=-86.0000 ;11.1980  
P317=-85.6100 ;11.5000  
P318=-85.5000 ;11.6080  
P319=-85.0430 ;12.0000  
P320=-85.0000 ;12.0410  
P321=-84.5000 ;12.4740  
P322=-84.4680 ;12.5000  
P323=-84.0000 ;12.9220  
P324=-83.9230 ;13.0000  
P325=-83.5000 ;13.4090  
P326=-83.3950 ;13.5000  
P327=-83.0000 ;13.8950  
P328=-82.9020 ;14.0000  
P329=-82.5000 ;14.4110  
P330=-82.4130 ;14.5000  
P331=-82.0000 ;14.9340  
P332=-81.9330 ;15.0000  
P333=-81.5000 ;15.4760  
P334=-81.4790 ;15.5000  
P335=-81.0000 ;15.9980  
P336=-80.9980 ;16.0000  
P337=-80.5580 ;16.5000  
P338=-80.5000 ;16.5590  
P339=-80.1470 ;17.0000  
P340=-80.0000 ;17.1600  
P341=-79.7430 ;17.5000  
P342=-79.5000 ;17.7790  
P343=-79.3470 ;18.0000  
P344=-79.0000 ;18.4120  
P345=-78.9440 ;18.5000  
P346=-78.5870 ;19.0000  
P347=-78.5000 ;19.1130  
P348=-78.3170 ;19.5000  
P349=-78.0000 ;19.9110  
P350=-77.9520 ;20.0000  
P351=-77.6750 ;20.5000  
P352=-77.5000 ;20.7620  
P353=-77.3990 ;21.0000  
P354=-77.1050 ;21.5000  
P355=-77.0000 ;21.6890  
P356=-76.8760 ;22.0000  
P357=-76.6340 ;22.5000  
P358=-76.5000 ;22.7760  
P359=-76.4080 ;23.0000  
P360=-76.2650 ;23.5000  
P361=-76.3720 ;24.0000

P362=-76.5000 ;24.0930  
P363=-76.8410 ;24.0000  
P364=-77.0000 ;23.9680  
P365=-77.5000 ;23.5840  
P366=-77.5310 ;23.5000  
P367=-77.8480 ;23.0000  
P368=-78.0000 ;22.8220  
P369=-78.1830 ;22.5000  
P370=-78.5000 ;22.0060  
P371=-78.5030 ;22.0000  
P372=-78.7940 ;21.5000  
P373=-79.0000 ;21.2290  
P374=-79.1230 ;21.0000  
P375=-79.4680 ;20.5000  
P376=-79.5000 ;20.4600  
P377=-79.7630 ;20.0000  
P378=-80.0000 ;19.6940  
P379=-80.1240 ;19.5000  
P380=-80.5000 ;19.0030  
P381=-80.5030 ;19.0000  
P382=-80.8040 ;18.5000  
P383=-81.0000 ;18.2610  
P384=-81.1980 ;18.0000  
P385=-81.5000 ;17.6330  
P386=-81.6140 ;17.5000  
P387=-82.0000 ;17.0670  
P388=-82.0860 ;17.0000  
P389=-82.5000 ;16.5740  
P390=-82.5860 ;16.5000  
P391=-83.0000 ;16.0880  
P392=-83.0800 ;16.0000  
P393=-83.5000 ;15.5830  
P394=-83.5980 ;15.5000  
P395=-84.0000 ;15.0980  
P396=-84.0800 ;15.0000  
P397=-84.5000 ;14.5820  
P398=-84.5860 ;14.5000  
P399=-85.0000 ;14.0970  
P400=-85.0950 ;14.0000  
P401=-85.5000 ;13.6310  
P402=-85.6370 ;13.5000  
P403=-86.0000 ;13.1870  
P404=-86.2100 ;13.0000  
P405=-86.5000 ;12.7540  
P406=-86.8050 ;12.5000  
P407=-87.0000 ;12.3430  
P408=-87.4350 ;12.0000  
P409=-87.5000 ;11.9470  
P410=-88.0000 ;11.5640  
P411=-88.0580 ;11.5000  
P412=-88.5000 ;11.1340  
P413=-88.6380 ;11.0000  
P414=-89.0000 ;10.6900  
P415=-89.2690 ;10.5000  
P416=-89.5000 ;10.3060  
P417=-90.0000 ;10.0160  
P418=-90.0200 ;10.0000

P419=-90.5000 ;9.5980  
P420=-90.6480 ;9.5000  
P421=-91.0000 ;9.2150  
P422=-91.5000 ;9.0260  
P423=-91.5260 ;9.0000  
P424=-92.0000 ;8.6250  
P425=-92.4000 ;8.5000  
P426=-92.5000 ;8.4260  
P427=-93.0000 ;8.0950  
P428=-93.2440 ;8.0000  
P429=-93.5000 ;7.8130  
P430=-94.0000 ;7.5780  
P431=-94.1980 ;7.5000  
P432=-94.5000 ;7.3010  
P433=-95.0000 ;7.0770  
P434=-95.4450 ;7.0000  
P435=-95.5000 ;6.9710  
P436=-96.0000 ;6.7550  
P437=-96.5000 ;6.6260  
P438=-97.0000 ;6.5490  
P439=-97.5000 ;6.5190  
P440=-97.6890 ;6.5000  
P441=-98.0000 ;6.4220  
P442=-98.5000 ;6.3260  
P443=-99.0000 ;6.2620  
P444=-99.5000 ;6.2400  
P445=-100.0000;6.2710  
P446=-100.5000;6.3840  
P447=-100.7840;6.5000  
P448=-100.5000;6.6510  
P449=-100.0000;6.8940  
P450=-99.8230 ;7.0000  
P451=-99.5000 ;7.1110  
P452=-99.0000 ;7.2580  
P453=-98.5000 ;7.3610  
P454=-98.0000 ;7.4360  
P455=-97.5030 ;7.5000  
P456=-97.5000 ;7.5010  
P457=-97.0000 ;7.6420  
P458=-96.5000 ;7.7790  
P459=-96.0000 ;7.9030  
P460=-95.5000 ;7.9630  
P461=-95.3910 ;8.0000  
P462=-95.0000 ;8.1920  
P463=-94.5000 ;8.4150  
P464=-94.1730 ;8.5000  
P465=-94.0000 ;8.6070  
P466=-93.5000 ;8.8930  
P467=-93.2330 ;9.0000  
P468=-93.0000 ;9.1570  
P469=-92.5000 ;9.4110  
P470=-92.3370 ;9.5000  
P471=-92.0000 ;9.7440  
P472=-91.5000 ;9.9450  
P473=-91.4350 ;10.0000  
P474=-91.0000 ;10.3530  
P475=-90.7050 ;10.5000

P476=-90.5000 ;10.6670  
P477=-90.0000 ;10.9740  
P478=-89.9560 ;11.0000  
P479=-89.5000 ;11.3710  
P480=-89.3110 ;11.5000  
P481=-89.0000 ;11.7590  
P482=-88.6170 ;12.0000  
P483=-88.5000 ;12.1010  
P484=-88.0000 ;12.4300  
P485=-87.9080 ;12.5000  
P486=-87.5000 ;12.8020  
P487=-87.2420 ;13.0000  
P488=-87.0000 ;13.2010  
P489=-86.6290 ;13.5000  
P490=-86.5000 ;13.6140  
P491=-86.0580 ;14.0000  
P492=-86.0000 ;14.0550  
P493=-85.5180 ;14.5000  
P494=-85.5000 ;14.5180  
P495=-85.0040 ;15.0000  
P496=-85.0000 ;15.0040  
P497=-84.5000 ;15.4900  
P498=-84.4870 ;15.5000  
P499=-84.0000 ;15.9660  
P500=-83.9720 ;16.0000  
P501=-83.5000 ;16.4880  
P502=-83.4870 ;16.5000  
P503=-83.0370 ;17.0000  
P504=-83.0000 ;17.0370  
P505=-82.6290 ;17.5000  
P506=-82.5000 ;17.6520  
P507=-82.2500 ;18.0000  
P508=-82.0000 ;18.3010  
P509=-81.8540 ;18.5000  
P510=-81.5000 ;18.9590  
P511=-81.4650 ;19.0000  
P512=-81.1920 ;19.5000  
P513=-81.0000 ;19.7530  
P514=-80.8420 ;20.0000  
P515=-80.5140 ;20.5000  
P516=-80.5000 ;20.5200  
P517=-80.2240 ;21.0000  
P518=-80.0000 ;21.3520  
P519=-79.8900 ;21.5000  
P520=-79.5860 ;22.0000  
P521=-79.5000 ;22.1410  
P522=-79.2340 ;22.5000  
P523=-79.0000 ;22.8410  
P524=-78.8220 ;23.0000  
P525=-78.5000 ;23.3960  
P526=-78.3260 ;23.5000  
P527=-78.0000 ;23.7700  
P528=-77.6380 ;24.0000  
P529=-77.5000 ;24.1010  
P530=-77.0790 ;24.5000  
P531=-77.0000 ;24.5800  
P532=-76.7420 ;25.0000

P533=-76.5000 ;25.3570  
P534=-76.4320 ;25.5000  
P535=-76.1530 ;26.0000  
P536=-76.0000 ;26.2110  
P537=-75.8480 ;26.5000  
P538=-75.5340 ;27.0000  
P539=-75.5000 ;27.0470  
P540=-75.2640 ;27.5000  
P541=-75.0000 ;27.9010  
P542=-74.9490 ;28.0000  
P543=-74.6940 ;28.5000  
P544=-74.5000 ;28.7840  
P545=-74.3930 ;29.0000  
P546=-74.0880 ;29.5000  
P547=-74.0000 ;29.6320  
P548=-73.8200 ;30.0000  
P549=-73.5040 ;30.5000  
P550=-73.5000 ;30.5050  
P551=-73.2530 ;31.0000  
P552=-73.0000 ;31.3830  
P553=-72.9390 ;31.5000  
P554=-72.6890 ;32.0000  
P555=-72.5000 ;32.2620  
P556=-72.3770 ;32.5000  
P557=-72.0940 ;33.0000  
P558=-72.0000 ;33.1400  
P559=-71.8350 ;33.5000  
P560=-71.5000 ;33.9850  
P561=-71.4920 ;34.0000  
P562=-71.2730 ;34.5000  
P563=-71.0000 ;34.8820  
P564=-70.9370 ;35.0000  
P565=-70.7170 ;35.5000  
P566=-70.5000 ;35.8050  
P567=-70.4000 ;36.0000  
P568=-70.1620 ;36.5000  
P569=-70.0000 ;36.7280  
P570=-69.8570 ;37.0000  
P571=-69.6100 ;37.5000  
P572=-69.5000 ;37.6650  
P573=-69.3350 ;38.0000  
P574=-69.0730 ;38.5000  
P575=-69.0000 ;38.6150  
P576=-68.8220 ;39.0000  
P577=-68.5000 ;39.4930  
P578=-68.4970 ;39.5000  
P579=-68.2960 ;40.0000  
P580=-68.0000 ;40.4550  
P581=-67.9770 ;40.5000  
P582=-67.7570 ;41.0000  
P583=-67.5000 ;41.4340  
P584=-67.4710 ;41.5000  
P585=-67.2050 ;42.0000  
P586=-67.0000 ;42.3250  
P587=-66.9130 ;42.5000  
P588=-66.6790 ;43.0000  
P589=-66.5000 ;43.2910

P590=-66.4010 ;43.5000  
P591=-66.1050 ;44.0000  
P592=-66.0000 ;44.1780  
P593=-65.8440 ;44.5000  
P594=-65.5730 ;45.0000  
P595=-65.5000 ;45.1200  
P596=-65.3190 ;45.5000  
P597=-65.0040 ;46.0000  
P598=-65.0000 ;46.0050  
P599=-64.7460 ;46.5000  
P600=-64.5000 ;46.8770  
P601=-64.4330 ;47.0000  
P602=-64.1700 ;47.5000  
P603=-64.0000 ;47.7740  
P604=-63.8820 ;48.0000  
P605=-63.5770 ;48.5000  
P606=-63.5000 ;48.6150  
P607=-63.2800 ;49.0000  
P608=-63.0000 ;49.4000  
P609=-62.9390 ;49.5000  
P610=-62.6050 ;50.0000  
P611=-62.5000 ;50.1430  
P612=-62.2620 ;50.5000  
P613=-62.0000 ;50.8530  
P614=-61.8960 ;51.0000  
P615=-61.5190 ;51.5000  
P616=-61.5000 ;51.5240  
P617=-61.1530 ;52.0000  
P618=-61.0000 ;52.1920  
P619=-60.7570 ;52.5000  
P620=-60.5000 ;52.8000  
P621=-60.3510 ;53.0000  
P622=-60.0000 ;53.4020  
P623=-59.9190 ;53.5000  
P624=-59.5000 ;53.9920  
P625=-59.4930 ;54.0000  
P626=-59.0750 ;54.5000  
P627=-59.0000 ;54.5970  
P628=-58.6530 ;55.0000  
P629=-58.5000 ;55.1760  
P630=-58.2400 ;55.5000  
P631=-58.0000 ;55.7790  
P632=-57.8100 ;56.0000  
P633=-57.5000 ;56.3580  
P634=-57.3550 ;56.5000  
P635=-57.0000 ;56.8260  
P636=-56.8320 ;57.0000  
P637=-56.5000 ;57.3230  
P638=-56.2910 ;57.5000  
P639=-56.0000 ;57.7580  
P640=-55.7180 ;58.0000  
P641=-55.5000 ;58.1910  
P642=-55.1050 ;58.5000  
P643=-55.0000 ;58.5910  
P644=-54.5000 ;58.9950  
P645=-54.4930 ;59.0000  
P646=-54.0000 ;59.4150

P647=-53.8850 ;59.5000  
P648=-53.5000 ;59.8140  
P649=-53.2420 ;60.0000  
P650=-53.0000 ;60.1870  
P651=-52.5800 ;60.5000  
P652=-52.5000 ;60.5620  
P653=-52.0000 ;60.8710  
P654=-51.8120 ;61.0000  
P655=-51.5000 ;61.2260  
P656=-51.0080 ;61.5000  
P657=-51.0000 ;61.5050  
P658=-50.5000 ;61.7880  
P659=-50.1080 ;62.0000  
P660=-50.0000 ;62.0640  
P661=-49.5000 ;62.3080  
P662=-49.1020 ;62.5000  
P663=-49.0000 ;62.5500  
P664=-48.5000 ;62.7930  
P665=-48.0000 ;62.9900  
P666=-47.9780 ;63.0000  
P667=-47.5000 ;63.2240  
P668=-47.0000 ;63.4300  
P669=-46.8000 ;63.5000  
P670=-46.5000 ;63.6230  
P671=-46.0000 ;63.8180  
P672=-45.5200 ;64.0000  
P673=-45.5000 ;64.0080  
P674=-45.0000 ;64.1920  
P675=-44.5000 ;64.3540  
P676=-44.0580 ;64.5000  
P677=-44.0000 ;64.5230  
P678=-43.5000 ;64.7080  
P679=-43.0000 ;64.8600  
P680=-42.5000 ;64.9860  
P681=-42.4520 ;65.0000  
P682=-42.0000 ;65.1540  
P683=-41.5000 ;65.3090  
P684=-41.0000 ;65.4430  
P685=-40.7530 ;65.5000  
P686=-40.5000 ;65.5670  
P687=-40.0000 ;65.7000  
P688=-39.5000 ;65.8290  
P689=-39.0000 ;65.9480  
P690=-38.7560 ;66.0000  
P691=-38.5000 ;66.0630  
P692=-38.0000 ;66.1690  
P693=-37.5000 ;66.2720  
P694=-37.0000 ;66.3750  
P695=-36.5000 ;66.4740  
P696=-36.3560 ;66.5000  
P697=-36.0000 ;66.5760  
P698=-35.5000 ;66.6670  
P699=-35.0000 ;66.7500  
P700=-34.5000 ;66.8230  
P701=-34.0400 ;66.8970  
[C3]  
gain=-2.00



n\_point=80  
P1=-96.0000 ;33.1830  
P2=-95.9320 ;33.0915  
P3=-95.8640 ;33.0000  
P4=-95.8240 ;32.8750  
P5=-95.7840 ;32.7500  
P6=-95.7440 ;32.6250  
P7=-95.7040 ;32.5000  
P8=-95.7050 ;32.3750  
P9=-95.7060 ;32.2500  
P10=-95.7070 ;32.1250  
P11=-95.7080 ;32.0000  
P12=-95.7397 ;31.8750  
P13=-95.7715 ;31.7500  
P14=-95.8033 ;31.6250  
P15=-95.8350 ;31.5000  
P16=-95.8900 ;31.3860  
P17=-95.9450 ;31.2720  
P18=-96.0000 ;31.1580  
P19=-96.0515 ;31.0790  
P20=-96.1030 ;31.0000  
P21=-96.1824 ;30.9090  
P22=-96.2618 ;30.8180  
P23=-96.3412 ;30.7270  
P24=-96.4206 ;30.6360  
P25=-96.5000 ;30.5450  
P26=-96.5580 ;30.5000  
P27=-96.6685 ;30.4347  
P28=-96.7790 ;30.3695  
P29=-96.8895 ;30.3043  
P30=-97.0000 ;30.2390  
P31=-97.1250 ;30.2062  
P32=-97.2500 ;30.1735  
P33=-97.3750 ;30.1408  
P34=-97.5000 ;30.1080  
P35=-97.6250 ;30.1217  
P36=-97.7500 ;30.1355  
P37=-97.8750 ;30.1493  
P38=-98.0000 ;30.1630  
P39=-98.1250 ;30.2445  
P40=-98.2500 ;30.3260  
P41=-98.3750 ;30.4075  
P42=-98.5000 ;30.4890  
P43=-98.5090 ;30.5000  
P44=-98.5630 ;30.6250  
P45=-98.6170 ;30.7500  
P46=-98.6710 ;30.8750  
P47=-98.7250 ;31.0000  
P48=-98.7330 ;31.1250  
P49=-98.7410 ;31.2500  
P50=-98.7490 ;31.3750  
P51=-98.7570 ;31.5000  
P52=-98.7253 ;31.6250  
P53=-98.6935 ;31.7500  
P54=-98.6618 ;31.8750  
P55=-98.6300 ;32.0000  
P56=-98.5867 ;32.0923

P57=-98.5433 ;32.1847  
P58=-98.5000 ;32.2770  
P59=-98.4325 ;32.3885  
P60=-98.3650 ;32.5000  
P61=-98.2737 ;32.6068  
P62=-98.1825 ;32.7135  
P63=-98.0912 ;32.8203  
P64=-98.0000 ;32.9270  
P65=-97.9160 ;33.0000  
P66=-97.8120 ;33.0698  
P67=-97.7080 ;33.1395  
P68=-97.6040 ;33.2093  
P69=-97.5000 ;33.2790  
P70=-97.3750 ;33.3253  
P71=-97.2500 ;33.3715  
P72=-97.1250 ;33.4177  
P73=-97.0000 ;33.4640  
P74=-96.8333 ;33.4680  
P75=-96.6667 ;33.4720  
P76=-96.5000 ;33.4760  
P77=-96.3750 ;33.4027  
P78=-96.2500 ;33.3295  
P79=-96.1250 ;33.2562  
P80=-96.0000 ;33.1830

[C4]

gain=-4.00

n\_point=85

P1=-95.5000 ;33.7710  
P2=-95.4070 ;33.6355  
P3=-95.3140 ;33.5000  
P4=-95.2500 ;33.3333  
P5=-95.1860 ;33.1667  
P6=-95.1220 ;33.0000  
P7=-95.1063 ;32.8333  
P8=-95.0907 ;32.6667  
P9=-95.0750 ;32.5000  
P10=-95.0923 ;32.3333  
P11=-95.1097 ;32.1667  
P12=-95.1270 ;32.0000  
P13=-95.1710 ;31.8333  
P14=-95.2150 ;31.6667  
P15=-95.2590 ;31.5000  
P16=-95.3297 ;31.3333  
P17=-95.4003 ;31.1667  
P18=-95.4710 ;31.0000  
P19=-95.5000 ;30.9480  
P20=-95.6050 ;30.7987  
P21=-95.7100 ;30.6493  
P22=-95.8150 ;30.5000  
P23=-95.9075 ;30.3905  
P24=-96.0000 ;30.2810  
P25=-96.1565 ;30.1405  
P26=-96.3130 ;30.0000  
P27=-96.4065 ;29.9320  
P28=-96.5000 ;29.8640  
P29=-96.6667 ;29.7740  
P30=-96.8333 ;29.6840

P31=-97.0000 ;29.5940  
P32=-97.1725 ;29.5470  
P33=-97.3450 ;29.5000  
P34=-97.5000 ;29.4650  
P35=-97.6667 ;29.4617  
P36=-97.8333 ;29.4583  
P37=-98.0000 ;29.4550  
P38=-98.1890 ;29.5000  
P39=-98.3445 ;29.5530  
P40=-98.5000 ;29.6060  
P41=-98.6667 ;29.7203  
P42=-98.8333 ;29.8347  
P43=-99.0000 ;29.9490  
P44=-99.0470 ;30.0000  
P45=-99.1370 ;30.1667  
P46=-99.2270 ;30.3333  
P47=-99.3170 ;30.5000  
P48=-99.3547 ;30.6667  
P49=-99.3923 ;30.8333  
P50=-99.4300 ;31.0000  
P51=-99.4247 ;31.1667  
P52=-99.4193 ;31.3333  
P53=-99.4140 ;31.5000  
P54=-99.3687 ;31.6667  
P55=-99.3233 ;31.8333  
P56=-99.2780 ;32.0000  
P57=-99.2053 ;32.1667  
P58=-99.1327 ;32.3333  
P59=-99.0600 ;32.5000  
P60=-99.0000 ;32.5970  
P61=-98.9033 ;32.7313  
P62=-98.8067 ;32.8657  
P63=-98.7100 ;33.0000  
P64=-98.6050 ;33.1170  
P65=-98.5000 ;33.2340  
P66=-98.3540 ;33.3670  
P67=-98.2080 ;33.5000  
P68=-98.1040 ;33.5805  
P69=-98.0000 ;33.6610  
P70=-97.8333 ;33.7667  
P71=-97.6667 ;33.8723  
P72=-97.5000 ;33.9780  
P73=-97.4430 ;34.0000  
P74=-97.2215 ;34.0735  
P75=-97.0000 ;34.1470  
P76=-96.8333 ;34.1673  
P77=-96.6667 ;34.1877  
P78=-96.5000 ;34.2080  
P79=-96.3333 ;34.1800  
P80=-96.1667 ;34.1520  
P81=-96.0000 ;34.1240  
P82=-95.8890 ;34.0620  
P83=-95.7780 ;34.0000  
P84=-95.6390 ;33.8855  
P85=-95.5000 ;33.7710  
[C5]  
gain=-6.00

n\_point=94  
P1=-95.0000 ;34.0700  
P2=-94.9570 ;34.0000  
P3=-94.8903 ;33.8333  
P4=-94.8237 ;33.6667  
P5=-94.7570 ;33.5000  
P6=-94.7223 ;33.3333  
P7=-94.6877 ;33.1667  
P8=-94.6530 ;33.0000  
P9=-94.6507 ;32.8333  
P10=-94.6483 ;32.6667  
P11=-94.6460 ;32.5000  
P12=-94.6683 ;32.3333  
P13=-94.6907 ;32.1667  
P14=-94.7130 ;32.0000  
P15=-94.7560 ;31.8333  
P16=-94.7990 ;31.6667  
P17=-94.8420 ;31.5000  
P18=-94.9210 ;31.2940  
P19=-95.0000 ;31.0880  
P20=-95.0410 ;31.0000  
P21=-95.1403 ;30.8333  
P22=-95.2397 ;30.6667  
P23=-95.3390 ;30.5000  
P24=-95.4195 ;30.3865  
P25=-95.5000 ;30.2730  
P26=-95.6180 ;30.1365  
P27=-95.7360 ;30.0000  
P28=-95.8680 ;29.8690  
P29=-96.0000 ;29.7380  
P30=-96.1575 ;29.6190  
P31=-96.3150 ;29.5000  
P32=-96.5000 ;29.3800  
P33=-96.6667 ;29.2983  
P34=-96.8333 ;29.2167  
P35=-97.0000 ;29.1350  
P36=-97.2415 ;29.0675  
P37=-97.4830 ;29.0000  
P38=-97.5000 ;28.9960  
P39=-97.7500 ;28.9820  
P40=-98.0000 ;28.9680  
P41=-98.2300 ;29.0000  
P42=-98.5000 ;29.0550  
P43=-98.6667 ;29.1303  
P44=-98.8333 ;29.2057  
P45=-99.0000 ;29.2810  
P46=-99.1445 ;29.3905  
P47=-99.2890 ;29.5000  
P48=-99.3945 ;29.6155  
P49=-99.5000 ;29.7310  
P50=-99.5925 ;29.8655  
P51=-99.6850 ;30.0000  
P52=-99.7487 ;30.1667  
P53=-99.8123 ;30.3333  
P54=-99.8760 ;30.5000  
P55=-99.8987 ;30.6667  
P56=-99.9213 ;30.8333

P57=-99.9440 ;31.0000  
P58=-99.9320 ;31.1667  
P59=-99.9200 ;31.3333  
P60=-99.9080 ;31.5000  
P61=-99.8627 ;31.6667  
P62=-99.8173 ;31.8333  
P63=-99.7720 ;32.0000  
P64=-99.7037 ;32.1667  
P65=-99.6353 ;32.3333  
P66=-99.5670 ;32.5000  
P67=-99.5000 ;32.6170  
P68=-99.3765 ;32.8085  
P69=-99.2530 ;33.0000  
P70=-99.1265 ;33.1580  
P71=-99.0000 ;33.3160  
P72=-98.8330 ;33.5000  
P73=-98.6665 ;33.6590  
P74=-98.5000 ;33.8180  
P75=-98.3865 ;33.9090  
P76=-98.2730 ;34.0000  
P77=-98.1365 ;34.0940  
P78=-98.0000 ;34.1880  
P79=-97.8333 ;34.2860  
P80=-97.6667 ;34.3840  
P81=-97.5000 ;34.4820  
P82=-97.4550 ;34.5000  
P83=-97.2275 ;34.5775  
P84=-97.0000 ;34.6550  
P85=-96.7500 ;34.6980  
P86=-96.5000 ;34.7410  
P87=-96.2500 ;34.7310  
P88=-96.0000 ;34.7210  
P89=-95.7500 ;34.6300  
P90=-95.5000 ;34.5390  
P91=-95.4420 ;34.5000  
P92=-95.2947 ;34.3567  
P93=-95.1473 ;34.2133  
P94=-95.0000 ;34.0700

[C6]

gain=-10.00  
n\_point=96  
P1=-94.0000 ;33.3240  
P2=-93.9915 ;33.1620  
P3=-93.9830 ;33.0000  
P4=-94.0000 ;32.6980  
P5=-94.0150 ;32.5000  
P6=-94.0610 ;32.2500  
P7=-94.1070 ;32.0000  
P8=-94.1760 ;31.7500  
P9=-94.2450 ;31.5000  
P10=-94.3365 ;31.2500  
P11=-94.4280 ;31.0000  
P12=-94.5000 ;30.8380  
P13=-94.5930 ;30.6690  
P14=-94.6860 ;30.5000  
P15=-94.8370 ;30.2500  
P16=-94.9880 ;30.0000

P17=-95.0000 ;29.9830  
P18=-95.2105 ;29.7415  
P19=-95.4210 ;29.5000  
P20=-95.5000 ;29.4180  
P21=-95.7340 ;29.2090  
P22=-95.9680 ;29.0000  
P23=-96.0000 ;28.9750  
P24=-96.2500 ;28.8300  
P25=-96.5000 ;28.6850  
P26=-96.7025 ;28.5925  
P27=-96.9050 ;28.5000  
P28=-97.0000 ;28.4630  
P29=-97.2500 ;28.4055  
P30=-97.5000 ;28.3480  
P31=-97.7500 ;28.3250  
P32=-98.0000 ;28.3020  
P33=-98.2500 ;28.3205  
P34=-98.5000 ;28.3390  
P35=-98.7500 ;28.3935  
P36=-99.0000 ;28.4480  
P37=-99.1350 ;28.5000  
P38=-99.3175 ;28.5940  
P39=-99.5000 ;28.6880  
P40=-99.7250 ;28.8440  
P41=-99.9500 ;29.0000  
P42=-100.0000;29.0500  
P43=-100.1715;29.2750  
P44=-100.3430;29.5000  
P45=-100.4215;29.6510  
P46=-100.5000;29.8020  
P47=-100.5870;30.0000  
P48=-100.6450;30.2500  
P49=-100.7030;30.5000  
P50=-100.7170;30.7500  
P51=-100.7310;31.0000  
P52=-100.7075;31.2500  
P53=-100.6840;31.5000  
P54=-100.6205;31.7500  
P55=-100.5570;32.0000  
P56=-100.5000;32.1470  
P57=-100.4265;32.3235  
P58=-100.3530;32.5000  
P59=-100.2150;32.7500  
P60=-100.0770;33.0000  
P61=-100.0000;33.1090  
P62=-99.8515 ;33.3045  
P63=-99.7030 ;33.5000  
P64=-99.5000 ;33.7290  
P65=-99.3710 ;33.8645  
P66=-99.2420 ;34.0000  
P67=-99.0000 ;34.2180  
P68=-98.8350 ;34.3590  
P69=-98.6700 ;34.5000  
P70=-98.5000 ;34.6250  
P71=-98.2500 ;34.7890  
P72=-98.0000 ;34.9530  
P73=-97.9160 ;35.0000

P74=-97.7080 ;35.1045  
P75=-97.5000 ;35.2090  
P76=-97.2500 ;35.3130  
P77=-97.0000 ;35.4170  
P78=-96.6760 ;35.5000  
P79=-96.5000 ;35.5410  
P80=-96.2500 ;35.5595  
P81=-96.0000 ;35.5780  
P82=-95.7500 ;35.5420  
P83=-95.5000 ;35.5060  
P84=-95.4840 ;35.5000  
P85=-95.2420 ;35.3830  
P86=-95.0000 ;35.2660  
P87=-94.8440 ;35.1330  
P88=-94.6880 ;35.0000  
P89=-94.5000 ;34.7860  
P90=-94.4170 ;34.6430  
P91=-94.3340 ;34.5000  
P92=-94.2345 ;34.2500  
P93=-94.1350 ;34.0000  
P94=-94.0745 ;33.7500  
P95=-94.0140 ;33.5000  
P96=-94.0000 ;33.3240  
[C7]  
gain=-20.00  
n\_point=109  
P1=-93.5000 ;35.5700  
P2=-93.4750 ;35.5000  
P3=-93.3925 ;35.2500  
P4=-93.3100 ;35.0000  
P5=-93.2405 ;34.7500  
P6=-93.1710 ;34.5000  
P7=-93.1250 ;34.2500  
P8=-93.0790 ;34.0000  
P9=-93.0545 ;33.7500  
P10=-93.0300 ;33.5000  
P11=-93.0300 ;33.2500  
P12=-93.0300 ;33.0000  
P13=-93.0550 ;32.7500  
P14=-93.0800 ;32.5000  
P15=-93.1230 ;32.2500  
P16=-93.1660 ;32.0000  
P17=-93.2295 ;31.7500  
P18=-93.2930 ;31.5000  
P19=-93.3965 ;31.2520  
P20=-93.5000 ;31.0040  
P21=-93.5020 ;31.0000  
P22=-93.6270 ;30.7500  
P23=-93.7520 ;30.5000  
P24=-93.8760 ;30.2670  
P25=-94.0000 ;30.0340  
P26=-94.0210 ;30.0000  
P27=-94.2005 ;29.7500  
P28=-94.3800 ;29.5000  
P29=-94.5000 ;29.3190  
P30=-94.7620 ;29.0000  
P31=-95.0000 ;28.6880

P32=-95.1940 ;28.5000  
P33=-95.3470 ;28.3355  
P34=-95.5000 ;28.1710  
P35=-95.7210 ;28.0000  
P36=-96.0000 ;27.7130  
P37=-96.3870 ;27.5000  
P38=-96.5000 ;27.3800  
P39=-96.7500 ;27.2750  
P40=-97.0000 ;27.1700  
P41=-97.2500 ;27.1460  
P42=-97.5000 ;27.1220  
P43=-97.7500 ;27.1330  
P44=-98.0000 ;27.1440  
P45=-98.2500 ;27.1800  
P46=-98.5000 ;27.2160  
P47=-98.7500 ;27.2700  
P48=-99.0000 ;27.3240  
P49=-99.2500 ;27.3950  
P50=-99.5000 ;27.4660  
P51=-99.6020 ;27.5000  
P52=-100.0000;27.6660  
P53=-100.2500;27.7885  
P54=-100.5000;27.9110  
P55=-100.6760;28.0000  
P56=-101.0000;28.2510  
P57=-101.3060;28.5000  
P58=-101.5000;28.7230  
P59=-101.7410;29.0000  
P60=-101.8705;29.2340  
P61=-102.0000;29.4680  
P62=-102.0190;29.5000  
P63=-102.1135;29.7500  
P64=-102.2080;30.0000  
P65=-102.2520;30.2500  
P66=-102.2960;30.5000  
P67=-102.3020;30.7500  
P68=-102.3080;31.0000  
P69=-102.2800;31.2500  
P70=-102.2520;31.5000  
P71=-102.1845;31.7500  
P72=-102.1170;32.0000  
P73=-102.0000;32.2850  
P74=-101.9180;32.5000  
P75=-101.7850;32.7500  
P76=-101.6520;33.0000  
P77=-101.5000;33.2090  
P78=-101.2940;33.5000  
P79=-101.0000;33.8190  
P80=-100.8400;34.0000  
P81=-100.5000;34.2970  
P82=-100.2820;34.5000  
P83=-100.0000;34.6950  
P84=-99.8055 ;34.8475  
P85=-99.6110 ;35.0000  
P86=-99.5000 ;35.0640  
P87=-99.2500 ;35.2405  
P88=-99.0000 ;35.4170



P89=-98.8890 ;35.5000  
P90=-98.5000 ;35.7570  
P91=-98.1510 ;36.0000  
P92=-98.0000 ;36.1130  
P93=-97.7500 ;36.2700  
P94=-97.5000 ;36.4270  
P95=-97.3620 ;36.5000  
P96=-97.0000 ;36.7470  
P97=-96.7500 ;36.8545  
P98=-96.5000 ;36.9620  
P99=-96.3450 ;37.0000  
P100=-96.0000 ;37.1310  
P101=-95.5000 ;37.1720  
P102=-95.0000 ;37.0550  
P103=-94.9080 ;37.0000  
P104=-94.5000 ;36.8070  
P105=-94.1590 ;36.5000  
P106=-94.0000 ;36.3520  
P107=-93.7690 ;36.0000  
P108=-93.6345 ;35.7850  
P109=-93.5000 ;35.5700

[C8]

gain=-30.00

n\_point=152

P1=-90.5000 ;36.3630  
P2=-90.3780 ;36.0000  
P3=-90.2390 ;35.5000  
P4=-90.1300 ;35.0000  
P5=-90.0600 ;34.5000  
P6=-90.0520 ;34.0000  
P7=-90.1130 ;33.5000  
P8=-90.1990 ;33.0000  
P9=-90.3130 ;32.5000  
P10=-90.4350 ;32.0000  
P11=-90.5000 ;31.7540  
P12=-90.6140 ;31.5000  
P13=-90.8510 ;31.0000  
P14=-91.0000 ;30.6200  
P15=-91.0740 ;30.5000  
P16=-91.4020 ;30.0000  
P17=-91.5000 ;29.8200  
P18=-91.7620 ;29.5000  
P19=-92.0000 ;29.1600  
P20=-92.1780 ;29.0000  
P21=-92.5000 ;28.6780  
P22=-92.7450 ;28.5000  
P23=-93.0000 ;28.2800  
P24=-93.3320 ;28.0000  
P25=-93.5000 ;27.8290  
P26=-93.7550 ;27.5000  
P27=-94.0000 ;27.1310  
P28=-94.0690 ;27.0000  
P29=-94.4540 ;26.5000  
P30=-94.5000 ;26.4460  
P31=-94.9040 ;26.0000  
P32=-95.0000 ;25.9080  
P33=-95.4400 ;25.5000

P34=-95.5000 ;25.4490  
P35=-96.0000 ;25.0850  
P36=-96.1250 ;25.0000  
P37=-96.5000 ;24.7810  
P38=-97.0000 ;24.5620  
P39=-97.1820 ;24.5000  
P40=-97.5000 ;24.3960  
P41=-98.0000 ;24.3480  
P42=-98.5000 ;24.3600  
P43=-99.0000 ;24.4210  
P44=-99.5000 ;24.4960  
P45=-99.5240 ;24.5000  
P46=-100.0000;24.6840  
P47=-100.5000;24.8790  
P48=-100.7910;25.0000  
P49=-101.0000;25.2250  
P50=-101.2580;25.5000  
P51=-101.1210;26.0000  
P52=-101.0000;26.0390  
P53=-100.5000;26.1960  
P54=-100.0000;26.4440  
P55=-99.9210 ;26.5000  
P56=-100.0000;26.9880  
P57=-100.0010;27.0000  
P58=-100.5000;27.2920  
P59=-101.0000;27.4770  
P60=-101.1630;27.5000  
P61=-101.5000;27.6600  
P62=-102.0000;27.8170  
P63=-102.5000;27.9760  
P64=-102.5670;28.0000  
P65=-103.0000;28.2090  
P66=-103.3820;28.5000  
P67=-103.5000;28.6250  
P68=-103.7740;29.0000  
P69=-104.0000;29.4570  
P70=-104.0180;29.5000  
P71=-104.1580;30.0000  
P72=-104.2260;30.5000  
P73=-104.2350;31.0000  
P74=-104.1860;31.5000  
P75=-104.0640;32.0000  
P76=-104.0000;32.1740  
P77=-103.8780;32.5000  
P78=-103.6210;33.0000  
P79=-103.5000;33.1770  
P80=-103.2870;33.5000  
P81=-103.0000;33.8400  
P82=-102.8720;34.0000  
P83=-102.5000;34.4020  
P84=-102.4050;34.5000  
P85=-102.0000;34.9090  
P86=-101.8850;35.0000  
P87=-101.5000;35.3670  
P88=-101.2430;35.5000  
P89=-101.0000;35.8190  
P90=-100.5630;35.5000

P91=-100.5000;35.4920  
P92=-100.0000;35.4890  
P93=-99.9810 ;35.5000  
P94=-99.5000 ;35.6250  
P95=-99.0000 ;35.9780  
P96=-98.9720 ;36.0000  
P97=-98.5190 ;36.5000  
P98=-99.0000 ;36.8650  
P99=-99.5000 ;36.7450  
P100=-99.9440 ;36.5000  
P101=-100.0000;36.4650  
P102=-100.5000;36.2660  
P103=-100.6140;36.5000  
P104=-100.5000;36.7730  
P105=-100.4200;37.0000  
P106=-100.1060;37.5000  
P107=-100.0000;37.6260  
P108=-99.7120 ;38.0000  
P109=-99.5000 ;38.2060  
P110=-99.2090 ;38.5000  
P111=-99.0000 ;38.6740  
P112=-98.6270 ;39.0000  
P113=-98.5000 ;39.1010  
P114=-98.0000 ;39.4960  
P115=-97.9940 ;39.5000  
P116=-97.5000 ;39.8140  
P117=-97.1560 ;40.0000  
P118=-97.0000 ;40.1000  
P119=-96.5000 ;40.3130  
P120=-96.0000 ;40.4570  
P121=-95.6650 ;40.5000  
P122=-95.5000 ;40.5320  
P123=-95.0600 ;40.5000  
P124=-95.0000 ;40.4970  
P125=-94.5000 ;40.3770  
P126=-94.0000 ;40.1460  
P127=-93.7970 ;40.0000  
P128=-93.5000 ;39.7610  
P129=-93.2370 ;39.5000  
P130=-93.0000 ;39.1960  
P131=-92.8550 ;39.0000  
P132=-92.5960 ;38.5000  
P133=-92.5240 ;38.0000  
P134=-92.8560 ;37.5000  
P135=-93.0000 ;37.4130  
P136=-93.1500 ;37.0000  
P137=-93.1610 ;36.5000  
P138=-93.0000 ;36.0000  
P139=-92.8250 ;35.5000  
P140=-92.6470 ;35.0000  
P141=-92.5000 ;34.5410  
P142=-92.2180 ;35.0000  
P143=-92.0570 ;35.5000  
P144=-92.0000 ;35.8360  
P145=-91.9490 ;36.0000  
P146=-91.9170 ;36.5000  
P147=-91.8690 ;37.0000

P148=-91.5000 ;37.3160  
P149=-91.0000 ;37.0580  
P150=-90.9590 ;37.0000  
P151=-90.6030 ;36.5000  
P152=-90.5000 ;36.3630  
[C9]  
gain=-40.00  
n\_point=71  
P1=-101.0000;27.2610  
P2=-101.0306;27.2436  
P3=-101.0612;27.2262  
P4=-101.0918;27.2088  
P5=-101.1224;27.1914  
P6=-101.1530;27.1740  
P7=-101.1836;27.1566  
P8=-101.2142;27.1392  
P9=-101.2295;27.1305  
P10=-101.2448;27.1218  
P11=-101.2601;27.1131  
P12=-101.2754;27.1044  
P13=-101.2907;27.0957  
P14=-101.3060;27.0870  
P15=-101.3213;27.0783  
P16=-101.3366;27.0696  
P17=-101.3519;27.0609  
P18=-101.3672;27.0522  
P19=-101.3825;27.0435  
P20=-101.3978;27.0348  
P21=-101.4131;27.0261  
P22=-101.4284;27.0174  
P23=-101.4437;27.0087  
P24=-101.4590;27.0000  
P25=-101.4320;26.9804  
P26=-101.4050;26.9607  
P27=-101.3780;26.9411  
P28=-101.3510;26.9214  
P29=-101.3240;26.9018  
P30=-101.2970;26.8821  
P31=-101.2700;26.8625  
P32=-101.2430;26.8428  
P33=-101.2160;26.8232  
P34=-101.1890;26.8035  
P35=-101.1620;26.7839  
P36=-101.1350;26.7642  
P37=-101.1080;26.7446  
P38=-101.0810;26.7249  
P39=-101.0540;26.7053  
P40=-101.0270;26.6856  
P41=-101.0000;26.6660  
P42=-100.9750;26.6869  
P43=-100.9500;26.7077  
P44=-100.9250;26.7286  
P45=-100.9000;26.7495  
P46=-100.8750;26.7704  
P47=-100.8500;26.7913  
P48=-100.8250;26.8121  
P49=-100.8000;26.8330

P50=-100.7750;26.8539  
P51=-100.7500;26.8748  
P52=-100.7250;26.8956  
P53=-100.7000;26.9165  
P54=-100.6750;26.9374  
P55=-100.6500;26.9583  
P56=-100.6250;26.9791  
P57=-100.6000;27.0000  
P58=-100.6286;27.0186  
P59=-100.6571;27.0373  
P60=-100.6857;27.0559  
P61=-100.7143;27.0746  
P62=-100.7429;27.0932  
P63=-100.7714;27.1119  
P64=-100.8000;27.1305  
P65=-100.8286;27.1491  
P66=-100.8571;27.1678  
P67=-100.8857;27.1864  
P68=-100.9143;27.2051  
P69=-100.9429;27.2237  
P70=-100.9714;27.2424  
P71=-101.0000;27.2610  
[C10]  
gain=-40.00  
n\_point=70  
P1=-99.5000 ;24.0370  
P2=-99.5385 ;24.0443  
P3=-99.5769 ;24.0516  
P4=-99.6154 ;24.0589  
P5=-99.6538 ;24.0662  
P6=-99.6923 ;24.0735  
P7=-99.7308 ;24.0808  
P8=-99.7692 ;24.0882  
P9=-99.8077 ;24.0955  
P10=-99.8462 ;24.1028  
P11=-99.8846 ;24.1101  
P12=-99.9231 ;24.1174  
P13=-99.9615 ;24.1247  
P14=-100.0000;24.1320  
P15=-100.0375;24.1218  
P16=-100.0749;24.1117  
P17=-100.1124;24.1015  
P18=-100.1498;24.0914  
P19=-100.1873;24.0812  
P20=-100.2248;24.0711  
P21=-100.2622;24.0609  
P22=-100.2997;24.0508  
P23=-100.3372;24.0406  
P24=-100.3746;24.0305  
P25=-100.4121;24.0203  
P26=-100.4495;24.0102  
P27=-100.4870;24.0000  
P28=-100.4566;23.9744  
P29=-100.4261;23.9487  
P30=-100.3957;23.9231  
P31=-100.3652;23.8975  
P32=-100.3348;23.8719

P33=-100.3044;23.8463  
P34=-100.2739;23.8206  
P35=-100.2435;23.7950  
P36=-100.2131;23.7694  
P37=-100.1826;23.7438  
P38=-100.1522;23.7181  
P39=-100.1217;23.6925  
P40=-100.0913;23.6669  
P41=-100.0609;23.6413  
P42=-100.0304;23.6156  
P43=-100.0000;23.5900  
P44=-99.9583 ;23.5898  
P45=-99.9167 ;23.5895  
P46=-99.8750 ;23.5893  
P47=-99.8333 ;23.5890  
P48=-99.7917 ;23.5887  
P49=-99.7500 ;23.5885  
P50=-99.7083 ;23.5882  
P51=-99.6667 ;23.5880  
P52=-99.6250 ;23.5877  
P53=-99.5833 ;23.5875  
P54=-99.5417 ;23.5872  
P55=-99.5000 ;23.5870  
P56=-99.4902 ;23.6214  
P57=-99.4803 ;23.6558  
P58=-99.4705 ;23.6903  
P59=-99.4607 ;23.7247  
P60=-99.4508 ;23.7591  
P61=-99.4410 ;23.7935  
P62=-99.4312 ;23.8279  
P63=-99.4213 ;23.8623  
P64=-99.4115 ;23.8967  
P65=-99.4017 ;23.9312  
P66=-99.3918 ;23.9656  
P67=-99.3820 ;24.0000  
P68=-99.4213 ;24.0123  
P69=-99.4607 ;24.0247  
P70=-99.5000 ;24.0370  
[C11]  
gain=-30.00  
n\_point=77  
P1=-94.5000 ;24.0190  
P2=-94.4870 ;24.0000  
P3=-94.5000 ;23.9890  
P4=-94.6045 ;23.8668  
P5=-94.7090 ;23.7445  
P6=-94.8135 ;23.6222  
P7=-94.9180 ;23.5000  
P8=-95.0000 ;23.4320  
P9=-95.1108 ;23.3240  
P10=-95.2215 ;23.2160  
P11=-95.3323 ;23.1080  
P12=-95.4430 ;23.0000  
P13=-95.5000 ;22.9660  
P14=-95.6250 ;22.8948  
P15=-95.7500 ;22.8235  
P16=-95.8750 ;22.7523

P17=-96.0000 ;22.6810  
P18=-96.1370 ;22.5905  
P19=-96.2740 ;22.5000  
P20=-96.3870 ;22.4560  
P21=-96.5000 ;22.4120  
P22=-96.6250 ;22.3673  
P23=-96.7500 ;22.3225  
P24=-96.8750 ;22.2778  
P25=-97.0000 ;22.2330  
P26=-97.1250 ;22.1945  
P27=-97.2500 ;22.1560  
P28=-97.3750 ;22.1175  
P29=-97.5000 ;22.0790  
P30=-97.6387 ;22.0527  
P31=-97.7773 ;22.0263  
P32=-97.9160 ;22.0000  
P33=-98.0000 ;21.9940  
P34=-98.1667 ;21.9960  
P35=-98.3333 ;21.9980  
P36=-98.5000 ;22.0000  
P37=-98.5010 ;22.0000  
P38=-98.6257 ;22.0623  
P39=-98.7505 ;22.1245  
P40=-98.8753 ;22.1867  
P41=-99.0000 ;22.2490  
P42=-99.0957 ;22.3327  
P43=-99.1913 ;22.4163  
P44=-99.2870 ;22.5000  
P45=-99.1435 ;22.5710  
P46=-99.0000 ;22.6420  
P47=-98.8750 ;22.7155  
P48=-98.7500 ;22.7890  
P49=-98.6250 ;22.8625  
P50=-98.5000 ;22.9360  
P51=-98.4050 ;23.0000  
P52=-98.2700 ;23.0290  
P53=-98.1350 ;23.0580  
P54=-98.0000 ;23.0870  
P55=-97.8333 ;23.1287  
P56=-97.6667 ;23.1703  
P57=-97.5000 ;23.2120  
P58=-97.3333 ;23.2627  
P59=-97.1667 ;23.3133  
P60=-97.0000 ;23.3640  
P61=-96.8860 ;23.4093  
P62=-96.7720 ;23.4547  
P63=-96.6580 ;23.5000  
P64=-96.5000 ;23.5360  
P65=-96.3333 ;23.5720  
P66=-96.1667 ;23.6080  
P67=-96.0000 ;23.6440  
P68=-95.8333 ;23.6947  
P69=-95.6667 ;23.7453  
P70=-95.5000 ;23.7960  
P71=-95.3757 ;23.8640  
P72=-95.2513 ;23.9320  
P73=-95.1270 ;24.0000

P74=-95.0000 ;24.0370  
P75=-94.8333 ;24.0310  
P76=-94.6667 ;24.0250  
P77=-94.5000 ;24.0190  
[C12]  
gain=-40.00  
n\_point=79  
P1=-90.0000 ;31.8590  
P2=-90.0368 ;31.7693  
P3=-90.0735 ;31.6795  
P4=-90.1103 ;31.5897  
P5=-90.1470 ;31.5000  
P6=-90.1660 ;31.4000  
P7=-90.1850 ;31.3000  
P8=-90.2040 ;31.2000  
P9=-90.2230 ;31.1000  
P10=-90.2420 ;31.0000  
P11=-90.3280 ;30.9113  
P12=-90.4140 ;30.8227  
P13=-90.5000 ;30.7340  
P14=-90.5487 ;30.6560  
P15=-90.5973 ;30.5780  
P16=-90.6460 ;30.5000  
P17=-90.6974 ;30.4000  
P18=-90.7488 ;30.3000  
P19=-90.8002 ;30.2000  
P20=-90.8516 ;30.1000  
P21=-90.9030 ;30.0000  
P22=-90.9515 ;29.9080  
P23=-91.0000 ;29.8160  
P24=-91.0567 ;29.7370  
P25=-91.1135 ;29.6580  
P26=-91.1702 ;29.5790  
P27=-91.2270 ;29.5000  
P28=-91.2030 ;29.4000  
P29=-91.1790 ;29.3000  
P30=-91.1550 ;29.2000  
P31=-91.1310 ;29.1000  
P32=-91.1070 ;29.0000  
P33=-91.1856 ;28.9068  
P34=-91.2642 ;28.8136  
P35=-91.3428 ;28.7204  
P36=-91.4214 ;28.6272  
P37=-91.5000 ;28.5340  
P38=-91.5070 ;28.5000  
P39=-91.5000 ;28.4960  
P40=-91.4960 ;28.5000  
P41=-91.4133 ;28.5810  
P42=-91.3307 ;28.6620  
P43=-91.2480 ;28.7430  
P44=-91.1653 ;28.8240  
P45=-91.0827 ;28.9050  
P46=-91.0000 ;28.9860  
P47=-90.9880 ;29.0000  
P48=-90.9190 ;29.1000  
P49=-90.8500 ;29.2000  
P50=-90.7810 ;29.3000



P51=-90.7120 ;29.4000  
P52=-90.6430 ;29.5000  
P53=-90.5715 ;29.5360  
P54=-90.5000 ;29.5720  
P55=-90.4280 ;29.6576  
P56=-90.3560 ;29.7432  
P57=-90.2840 ;29.8288  
P58=-90.2120 ;29.9144  
P59=-90.1400 ;30.0000  
P60=-90.1434 ;30.1000  
P61=-90.1468 ;30.2000  
P62=-90.1502 ;30.3000  
P63=-90.1536 ;30.4000  
P64=-90.1570 ;30.5000  
P65=-90.0785 ;30.5755  
P66=-90.0000 ;30.6510  
P67=-89.9515 ;30.7382  
P68=-89.9030 ;30.8255  
P69=-89.8545 ;30.9128  
P70=-89.8060 ;31.0000  
P71=-89.7984 ;31.1000  
P72=-89.7908 ;31.2000  
P73=-89.7832 ;31.3000  
P74=-89.7756 ;31.4000  
P75=-89.7680 ;31.5000  
P76=-89.8260 ;31.5897  
P77=-89.8840 ;31.6795  
P78=-89.9420 ;31.7693  
P79=-90.0000 ;31.8590

[C13]

gain=-40.00

n\_point=78

P1=-89.0000 ;36.1850  
P2=-89.0275 ;36.3425  
P3=-89.0550 ;36.5000  
P4=-89.0867 ;36.6667  
P5=-89.1183 ;36.8333  
P6=-89.1500 ;37.0000  
P7=-89.2173 ;37.1667  
P8=-89.2847 ;37.3333  
P9=-89.3520 ;37.5000  
P10=-89.4260 ;37.6565  
P11=-89.5000 ;37.8130  
P12=-89.6607 ;37.8753  
P13=-89.8213 ;37.9377  
P14=-89.9820 ;38.0000  
P15=-90.0000 ;38.0350  
P16=-90.0050 ;38.0000  
P17=-90.0000 ;37.9690  
P18=-89.9573 ;37.8127  
P19=-89.9147 ;37.6563  
P20=-89.8720 ;37.5000  
P21=-89.8613 ;37.3333  
P22=-89.8507 ;37.1667  
P23=-89.8400 ;37.0000  
P24=-89.8013 ;36.8333  
P25=-89.7627 ;36.6667

P26=-89.7240 ;36.5000  
P27=-89.7343 ;36.3333  
P28=-89.7447 ;36.1667  
P29=-89.7550 ;36.0000  
P30=-89.7480 ;35.8333  
P31=-89.7410 ;35.6667  
P32=-89.7340 ;35.5000  
P33=-89.6873 ;35.3333  
P34=-89.6407 ;35.1667  
P35=-89.5940 ;35.0000  
P36=-89.5647 ;34.8333  
P37=-89.5353 ;34.6667  
P38=-89.5060 ;34.5000  
P39=-89.5107 ;34.3333  
P40=-89.5153 ;34.1667  
P41=-89.5200 ;34.0000  
P42=-89.5340 ;33.8333  
P43=-89.5480 ;33.6667  
P44=-89.5620 ;33.5000  
P45=-89.5800 ;33.3333  
P46=-89.5980 ;33.1667  
P47=-89.6160 ;33.0000  
P48=-89.6123 ;32.8333  
P49=-89.6087 ;32.6667  
P50=-89.6050 ;32.5000  
P51=-89.5525 ;32.3785  
P52=-89.5000 ;32.2570  
P53=-89.4585 ;32.3785  
P54=-89.4170 ;32.5000  
P55=-89.3970 ;32.6667  
P56=-89.3770 ;32.8333  
P57=-89.3570 ;33.0000  
P58=-89.3683 ;33.1667  
P59=-89.3797 ;33.3333  
P60=-89.3910 ;33.5000  
P61=-89.4063 ;33.6667  
P62=-89.4217 ;33.8333  
P63=-89.4370 ;34.0000  
P64=-89.4327 ;34.1667  
P65=-89.4283 ;34.3333  
P66=-89.4240 ;34.5000  
P67=-89.2827 ;34.5847  
P68=-89.1413 ;34.6693  
P69=-89.0000 ;34.7540  
P70=-88.9800 ;34.8770  
P71=-88.9600 ;35.0000  
P72=-88.9657 ;35.1667  
P73=-88.9713 ;35.3333  
P74=-88.9770 ;35.5000  
P75=-88.9773 ;35.6667  
P76=-88.9777 ;35.8333  
P77=-88.9780 ;36.0000  
P78=-89.0000 ;36.1850  
[C14]  
gain=-40.00  
n\_point=223  
P1=-84.0000 ;41.0850

P2=-83.9790 ;41.0000  
P3=-83.8530 ;40.5000  
P4=-83.7790 ;40.0000  
P5=-83.6850 ;39.5000  
P6=-83.6460 ;39.0000  
P7=-83.6180 ;38.5000  
P8=-83.5850 ;38.0000  
P9=-83.6340 ;37.5000  
P10=-83.6740 ;37.0000  
P11=-83.7240 ;36.5000  
P12=-83.8080 ;36.0000  
P13=-83.8840 ;35.5000  
P14=-83.9560 ;35.0000  
P15=-84.0000 ;34.7000  
P16=-84.0620 ;34.5000  
P17=-84.2330 ;34.0000  
P18=-84.3700 ;33.5000  
P19=-84.4800 ;33.0000  
P20=-84.5000 ;32.9070  
P21=-84.6690 ;32.5000  
P22=-84.8670 ;32.0000  
P23=-85.0000 ;31.5410  
P24=-85.0230 ;31.5000  
P25=-85.2800 ;31.0000  
P26=-85.4700 ;30.5000  
P27=-85.5000 ;30.4170  
P28=-85.7450 ;30.0000  
P29=-85.9650 ;29.5000  
P30=-86.0000 ;29.4220  
P31=-86.2740 ;29.0000  
P32=-86.5000 ;28.5240  
P33=-86.5160 ;28.5000  
P34=-86.8620 ;28.0000  
P35=-87.0000 ;27.7530  
P36=-87.1830 ;27.5000  
P37=-87.4820 ;27.0000  
P38=-87.5000 ;26.9720  
P39=-87.8560 ;26.5000  
P40=-88.0000 ;26.2800  
P41=-88.2270 ;26.0000  
P42=-88.5000 ;25.6030  
P43=-88.5840 ;25.5000  
P44=-88.9650 ;25.0000  
P45=-89.0000 ;24.9580  
P46=-89.3900 ;24.5000  
P47=-89.5000 ;24.3670  
P48=-89.8170 ;24.0000  
P49=-90.0000 ;23.7960  
P50=-90.2740 ;23.5000  
P51=-90.5000 ;23.2550  
P52=-90.7290 ;23.0000  
P53=-91.0000 ;22.7190  
P54=-91.2180 ;22.5000  
P55=-91.5000 ;22.2360  
P56=-91.7330 ;22.0000  
P57=-92.0000 ;21.7590  
P58=-92.2830 ;21.5000

P59=-92.5000 ;21.3290  
P60=-92.8690 ;21.0000  
P61=-93.0000 ;20.9000  
P62=-93.4880 ;20.5000  
P63=-93.5000 ;20.4900  
P64=-94.0000 ;20.2020  
P65=-94.2830 ;20.0000  
P66=-94.5000 ;19.8850  
P67=-95.0000 ;19.5540  
P68=-95.0780 ;19.5000  
P69=-95.5000 ;19.3410  
P70=-96.0000 ;19.0660  
P71=-96.1180 ;19.0000  
P72=-96.5000 ;18.8850  
P73=-97.0000 ;18.7290  
P74=-97.5000 ;18.5150  
P75=-97.5490 ;18.5000  
P76=-98.0000 ;18.4430  
P77=-98.5000 ;18.3850  
P78=-99.0000 ;18.3450  
P79=-99.5000 ;18.3310  
P80=-100.0000;18.3460  
P81=-100.5000;18.3960  
P82=-100.9160;18.5000  
P83=-101.0000;18.5260  
P84=-101.5000;18.6940  
P85=-102.0000;18.8780  
P86=-102.2480;19.0000  
P87=-102.5000;19.1420  
P88=-103.0000;19.4040  
P89=-103.1580;19.5000  
P90=-103.5000;19.7590  
P91=-103.8480;20.0000  
P92=-104.0000;20.1430  
P93=-104.4200;20.5000  
P94=-104.5000;20.5930  
P95=-104.8970;21.0000  
P96=-105.0000;21.1520  
P97=-105.2770;21.5000  
P98=-105.5000;21.9640  
P99=-105.5230;22.0000  
P100=-105.6500;22.5000  
P101=-105.6820;23.0000  
P102=-105.6920;23.5000  
P103=-105.7440;24.0000  
P104=-105.8450;24.5000  
P105=-105.9690;25.0000  
P106=-106.0000;25.1110  
P107=-106.0890;25.5000  
P108=-106.1930;26.0000  
P109=-106.3020;26.5000  
P110=-106.4440;27.0000  
P111=-106.5000;27.1520  
P112=-106.5840;27.5000  
P113=-106.7190;28.0000  
P114=-106.8790;28.5000  
P115=-107.0000;28.8320

P116=-107.0440;29.0000  
P117=-107.1650;29.5000  
P118=-107.2810;30.0000  
P119=-107.3880;30.5000  
P120=-107.4900;31.0000  
P121=-107.5000;31.0500  
P122=-107.5800;31.5000  
P123=-107.6700;32.0000  
P124=-107.7690;32.5000  
P125=-107.8740;33.0000  
P126=-107.9760;33.5000  
P127=-108.0000;33.6300  
P128=-108.0720;34.0000  
P129=-108.1530;34.5000  
P130=-108.2050;35.0000  
P131=-108.2200;35.5000  
P132=-108.2220;36.0000  
P133=-108.1970;36.5000  
P134=-108.0990;37.0000  
P135=-108.0000;37.1570  
P136=-107.9320;37.5000  
P137=-107.8350;38.0000  
P138=-107.6750;38.5000  
P139=-107.5000;38.7010  
P140=-107.3960;39.0000  
P141=-107.1440;39.5000  
P142=-107.0000;39.6700  
P143=-106.8510;40.0000  
P144=-106.5530;40.5000  
P145=-106.5000;40.5520  
P146=-106.2430;41.0000  
P147=-106.0000;41.3230  
P148=-105.8840;41.5000  
P149=-105.5320;42.0000  
P150=-105.5000;42.0350  
P151=-105.1530;42.5000  
P152=-105.0000;42.6710  
P153=-104.7310;43.0000  
P154=-104.5000;43.2720  
P155=-104.3040;43.5000  
P156=-104.0000;43.8450  
P157=-103.8610;44.0000  
P158=-103.5000;44.3920  
P159=-103.3950;44.5000  
P160=-103.0000;44.8860  
P161=-102.8790;45.0000  
P162=-102.5000;45.3320  
P163=-102.3140;45.5000  
P164=-102.0000;45.7600  
P165=-101.7220;46.0000  
P166=-101.5000;46.1730  
P167=-101.1020;46.5000  
P168=-101.0000;46.5750  
P169=-100.5000;46.9360  
P170=-100.4070;47.0000  
P171=-100.0000;47.2400  
P172=-99.5940 ;47.5000

P173=-99.5000 ;47.5570  
P174=-99.0000 ;47.8220  
P175=-98.6720 ;48.0000  
P176=-98.5000 ;48.0930  
P177=-98.0000 ;48.3180  
P178=-97.5820 ;48.5000  
P179=-97.5000 ;48.5400  
P180=-97.0000 ;48.7240  
P181=-96.5000 ;48.8800  
P182=-96.0600 ;49.0000  
P183=-96.0000 ;49.0200  
P184=-95.5000 ;49.1380  
P185=-95.0000 ;49.2190  
P186=-94.5000 ;49.2690  
P187=-94.0000 ;49.2900  
P188=-93.5000 ;49.2800  
P189=-93.0000 ;49.2400  
P190=-92.5000 ;49.1670  
P191=-92.0000 ;49.0570  
P192=-91.8070 ;49.0000  
P193=-91.5000 ;48.9060  
P194=-91.0000 ;48.7210  
P195=-90.5000 ;48.5000  
P196=-90.4990 ;48.5000  
P197=-90.0000 ;48.2200  
P198=-89.6380 ;48.0000  
P199=-89.5000 ;47.9020  
P200=-89.0000 ;47.5420  
P201=-88.9440 ;47.5000  
P202=-88.5000 ;47.1290  
P203=-88.3460 ;47.0000  
P204=-88.0000 ;46.6820  
P205=-87.7970 ;46.5000  
P206=-87.5000 ;46.2110  
P207=-87.2820 ;46.0000  
P208=-87.0000 ;45.6900  
P209=-86.8260 ;45.5000  
P210=-86.5000 ;45.1390  
P211=-86.3790 ;45.0000  
P212=-86.0000 ;44.5440  
P213=-85.9670 ;44.5000  
P214=-85.5520 ;44.0000  
P215=-85.5000 ;43.9370  
P216=-85.2300 ;43.5000  
P217=-85.0000 ;43.1980  
P218=-84.8870 ;43.0000  
P219=-84.6150 ;42.5000  
P220=-84.5000 ;42.3130  
P221=-84.3740 ;42.0000  
P222=-84.1720 ;41.5000  
P223=-84.0000 ;41.0850  
[C15]  
gain=-50.00  
n\_point=247  
P1=-92.7301 ;81.2191  
P2=-92.8690 ;81.0760  
P3=-92.9410 ;81.0000

P4=-93.0000 ;80.9470  
P5=-93.4710 ;80.5000  
P6=-93.5000 ;80.4750  
P7=-94.0000 ;80.0400  
P8=-94.0440 ;80.0000  
P9=-94.5000 ;79.6350  
P10=-94.6650 ;79.5000  
P11=-95.0000 ;79.2530  
P12=-95.3390 ;79.0000  
P13=-95.5000 ;78.8920  
P14=-96.0000 ;78.5480  
P15=-96.0610 ;78.5000  
P16=-96.5000 ;78.1830  
P17=-96.7440 ;78.0000  
P18=-97.0000 ;77.8220  
P19=-97.4460 ;77.5000  
P20=-97.5000 ;77.4640  
P21=-98.0000 ;77.1160  
P22=-98.1430 ;77.0000  
P23=-98.5000 ;76.7250  
P24=-98.7710 ;76.5000  
P25=-99.0000 ;76.3170  
P26=-99.3690 ;76.0000  
P27=-99.5000 ;75.8890  
P28=-99.9290 ;75.5000  
P29=-100.0000;75.4410  
P30=-100.5000;75.0380  
P31=-100.5480;75.0000  
P32=-101.0000;74.6730  
P33=-101.2090;74.5000  
P34=-101.5000;74.2640  
P35=-101.8020;74.0000  
P36=-102.0000;73.8290  
P37=-102.3290;73.5000  
P38=-102.5000;73.3200  
P39=-102.7750;73.0000  
P40=-103.0000;72.8090  
P41=-103.3680;72.5000  
P42=-103.5000;72.3910  
P43=-103.9410;72.0000  
P44=-104.0000;71.9460  
P45=-104.4170;71.5000  
P46=-104.5000;71.4040  
P47=-104.8410;71.0000  
P48=-105.0000;70.8820  
P49=-105.4910;70.5000  
P50=-105.5000;70.4930  
P51=-106.0000;70.0340  
P52=-106.0310;70.0000  
P53=-106.4200;69.5000  
P54=-106.5000;69.4420  
P55=-107.0000;69.0920  
P56=-107.1260;69.0000  
P57=-107.5000;68.6600  
P58=-107.6490;68.5000  
P59=-108.0000;68.0970  
P60=-108.0820;68.0000

P61=-108.5000;67.6700  
P62=-108.6930;67.5000  
P63=-109.0000;67.0340  
P64=-109.0240;67.0000  
P65=-109.5000;66.5180  
P66=-109.5160;66.5000  
P67=-109.8740;66.0000  
P68=-110.0000;65.8000  
P69=-110.2050;65.5000  
P70=-110.5000;65.0350  
P71=-110.5230;65.0000  
P72=-110.8310;64.5000  
P73=-111.0000;64.2330  
P74=-111.1630;64.0000  
P75=-111.4400;63.5000  
P76=-111.5000;63.4130  
P77=-111.8140;63.0000  
P78=-112.0000;62.6900  
P79=-112.1290;62.5000  
P80=-112.4240;62.0000  
P81=-112.5000;61.8640  
P82=-112.7440;61.5000  
P83=-112.9160;61.0000  
P84=-113.0000;60.8450  
P85=-113.2060;60.5000  
P86=-113.4050;60.0000  
P87=-113.5000;59.8280  
P88=-113.7070;59.5000  
P89=-113.9240;59.0000  
P90=-114.0000;58.7480  
P91=-114.0900;58.5000  
P92=-114.3590;58.0000  
P93=-114.5000;57.5850  
P94=-114.5380;57.5000  
P95=-114.6880;57.0000  
P96=-114.8590;56.5000  
P97=-115.0000;56.0590  
P98=-115.0240;56.0000  
P99=-115.1690;55.5000  
P100=-115.3490;55.0000  
P101=-115.5000;54.5190  
P102=-115.5070;54.5000  
P103=-115.6120;54.0000  
P104=-115.7360;53.5000  
P105=-115.8200;53.0000  
P106=-115.9810;52.5000  
P107=-116.0000;52.4270  
P108=-116.0710;52.0000  
P109=-116.0460;51.5000  
P110=-116.1260;51.0000  
P111=-116.0000;50.7910  
P112=-115.8990;51.0000  
P113=-115.8740;51.5000  
P114=-115.5000;51.7630  
P115=-115.4110;52.0000  
P116=-115.1290;52.5000  
P117=-115.0000;52.7380



P118=-114.9060;53.0000  
P119=-114.7290;53.5000  
P120=-114.5000;53.8640  
P121=-114.4360;54.0000  
P122=-114.2210;54.5000  
P123=-114.0000;54.8700  
P124=-113.9330;55.0000  
P125=-113.6430;55.5000  
P126=-113.5000;55.7470  
P127=-113.3480;56.0000  
P128=-113.0990;56.5000  
P129=-113.0000;56.6890  
P130=-112.8440;57.0000  
P131=-112.5620;57.5000  
P132=-112.5000;57.5990  
P133=-112.2280;58.0000  
P134=-112.0000;58.4070  
P135=-111.9360;58.5000  
P136=-111.5970;59.0000  
P137=-111.5000;59.1430  
P138=-111.2240;59.5000  
P139=-111.0000;59.9890  
P140=-110.9930;60.0000  
P141=-110.5970;60.5000  
P142=-110.5000;60.6320  
P143=-110.2040;61.0000  
P144=-110.0000;61.3570  
P145=-109.8960;61.5000  
P146=-109.5000;61.9190  
P147=-109.4200;62.0000  
P148=-109.0810;62.5000  
P149=-109.0000;62.5780  
P150=-108.5650;63.0000  
P151=-108.5000;63.1230  
P152=-108.2180;63.5000  
P153=-108.0000;63.7240  
P154=-107.7140;64.0000  
P155=-107.5000;64.3660  
P156=-107.4040;64.5000  
P157=-107.0000;64.8620  
P158=-106.8520;65.0000  
P159=-106.5000;65.4840  
P160=-106.4870;65.5000  
P161=-106.0000;65.9170  
P162=-105.9030;66.0000  
P163=-105.5000;66.4330  
P164=-105.4300;66.5000  
P165=-105.0000;66.8920  
P166=-104.8630;67.0000  
P167=-104.5000;67.2600  
P168=-104.1880;67.5000  
P169=-104.0000;67.6760  
P170=-103.6550;68.0000  
P171=-103.5000;68.1340  
P172=-103.0000;68.4640  
P173=-102.9440;68.5000  
P174=-102.5000;68.8120

P175=-102.2370;69.0000  
P176=-102.0000;69.2050  
P177=-101.6310;69.5000  
P178=-101.5000;69.6090  
P179=-101.0000;69.9560  
P180=-100.9270;70.0000  
P181=-100.5000;70.2740  
P182=-100.1620;70.5000  
P183=-100.0000;70.6160  
P184=-99.5000 ;70.9570  
P185=-99.4400 ;71.0000  
P186=-99.0000 ;71.3370  
P187=-98.7270 ;71.5000  
P188=-98.5000 ;71.6360  
P189=-98.0000 ;71.9150  
P190=-97.8370 ;72.0000  
P191=-97.5000 ;72.1820  
P192=-97.0000 ;72.4540  
P193=-96.9130 ;72.5000  
P194=-96.5000 ;72.7330  
P195=-96.0110 ;73.0000  
P196=-96.0000 ;73.0080  
P197=-95.5000 ;73.3310  
P198=-95.1760 ;73.5000  
P199=-95.0000 ;73.5970  
P200=-94.5000 ;73.8430  
P201=-94.1510 ;74.0000  
P202=-94.0000 ;74.0700  
P203=-93.5000 ;74.2870  
P204=-93.0000 ;74.4950  
P205=-92.9870 ;74.5000  
P206=-92.5000 ;74.7090  
P207=-92.0000 ;74.9100  
P208=-91.7740 ;75.0000  
P209=-91.5000 ;75.1130  
P210=-91.0000 ;75.3190  
P211=-90.5500 ;75.5000  
P212=-90.5000 ;75.5210  
P213=-90.0000 ;75.7190  
P214=-89.5000 ;75.9170  
P215=-89.2890 ;76.0000  
P216=-89.0000 ;76.1570  
P217=-88.5000 ;76.3870  
P218=-88.2240 ;76.5000  
P219=-88.0000 ;76.6120  
P220=-87.5000 ;76.8410  
P221=-87.1190 ;77.0000  
P222=-87.0000 ;77.0540  
P223=-86.5000 ;77.2720  
P224=-86.0000 ;77.4690  
P225=-85.9170 ;77.5000  
P226=-85.5000 ;77.6710  
P227=-85.0000 ;77.8640  
P228=-84.6260 ;78.0000  
P229=-84.5000 ;78.0500  
P230=-84.0000 ;78.2430  
P231=-83.5000 ;78.4260

P232=-83.2930 ;78.5000  
P233=-83.0000 ;78.6140  
P234=-82.5000 ;78.8000  
P235=-82.0000 ;78.9800  
P236=-81.9430 ;79.0000  
P237=-81.5000 ;79.1670  
P238=-81.0000 ;79.3500  
P239=-80.5790 ;79.5000  
P240=-80.5000 ;79.5300  
P241=-80.0000 ;79.7180  
P242=-79.5000 ;79.9020  
P243=-79.2240 ;80.0000  
P244=-79.0000 ;80.0860  
P245=-78.5000 ;80.2770  
P246=-78.1430 ;80.4070  
P247=-77.7725 ;80.5379  
[C16]  
gain=-50.00  
n\_point=112  
P1=-111.0000;50.7360  
P2=-111.1140;50.5000  
P3=-111.0950;50.2500  
P4=-111.0760;50.0000  
P5=-111.0000;49.9210  
P6=-110.9530;50.0000  
P7=-110.7265;50.2030  
P8=-110.5000;50.4060  
P9=-110.4390;50.5000  
P10=-110.2765;50.7500  
P11=-110.1140;51.0000  
P12=-110.0000;51.1200  
P13=-109.7540;51.5000  
P14=-109.5000;51.7860  
P15=-109.3420;52.0000  
P16=-109.0000;52.3980  
P17=-108.9200;52.5000  
P18=-108.7160;52.7500  
P19=-108.5120;53.0000  
P20=-108.5000;53.0120  
P21=-108.3025;53.2560  
P22=-108.1050;53.5000  
P23=-108.0000;53.5980  
P24=-107.6420;54.0000  
P25=-107.5000;54.1280  
P26=-107.1240;54.5000  
P27=-107.0000;54.6660  
P28=-106.6510;55.0000  
P29=-106.5000;55.1690  
P30=-106.1660;55.5000  
P31=-106.0000;55.6460  
P32=-105.6690;56.0000  
P33=-105.5000;56.1720  
P34=-105.1290;56.5000  
P35=-105.0000;56.6510  
P36=-104.6070;57.0000  
P37=-104.5000;57.0980  
P38=-104.0910;57.5000

P39=-104.0000;57.5830  
P40=-103.5000;57.9370  
P41=-103.4150;58.0000  
P42=-103.0000;58.3750  
P43=-102.8190;58.5000  
P44=-102.5000;58.7040  
P45=-102.1080;59.0000  
P46=-102.0000;59.1230  
P47=-101.5000;59.4270  
P48=-101.3740;59.5000  
P49=-101.0000;59.8440  
P50=-100.7640;60.0000  
P51=-100.5000;60.1790  
P52=-100.0000;60.4180  
P53=-99.8360 ;60.5000  
P54=-99.5000 ;60.9220  
P55=-99.3760 ;61.0000  
P56=-99.0000 ;61.1710  
P57=-98.5000 ;61.3510  
P58=-98.0700 ;61.5000  
P59=-98.5000 ;61.7660  
P60=-99.0000 ;61.7610  
P61=-99.5000 ;61.6270  
P62=-99.8110 ;61.5000  
P63=-100.0000;61.3070  
P64=-100.5000;61.1130  
P65=-100.8380;61.0000  
P66=-101.0000;60.9400  
P67=-101.5000;60.6620  
P68=-101.7720;60.5000  
P69=-102.0000;60.3890  
P70=-102.5000;60.1600  
P71=-102.7690;60.0000  
P72=-103.0000;59.8320  
P73=-103.5000;59.5640  
P74=-103.5960;59.5000  
P75=-104.0000;59.2490  
P76=-104.2900;59.0000  
P77=-104.5000;58.8800  
P78=-105.0000;58.5470  
P79=-105.0630;58.5000  
P80=-105.5000;58.1680  
P81=-105.6970;58.0000  
P82=-106.0000;57.7040  
P83=-106.1850;57.5000  
P84=-106.5000;57.2500  
P85=-106.7640;57.0000  
P86=-107.0000;56.7560  
P87=-107.2450;56.5000  
P88=-107.5000;56.1940  
P89=-107.6620;56.0000  
P90=-107.8310;55.7755  
P91=-108.0000;55.5510  
P92=-108.0420;55.5000  
P93=-108.2710;55.2520  
P94=-108.5000;55.0040  
P95=-108.5030;55.0000

P96=-108.7005;54.7500  
P97=-108.8980;54.5000  
P98=-109.0000;54.3500  
P99=-109.2420;54.0000  
P100=-109.5000;53.6010  
P101=-109.5680;53.5000  
P102=-109.7165;53.2500  
P103=-109.8650;53.0000  
P104=-110.0000;52.7610  
P105=-110.1690;52.5000  
P106=-110.2775;52.2500  
P107=-110.3860;52.0000  
P108=-110.5000;51.7750  
P109=-110.6210;51.5000  
P110=-110.7230;51.2500  
P111=-110.8250;51.0000  
P112=-111.0000;50.7360  
[C17]  
gain=-50.00  
n\_point=87  
P1=-106.5000;49.0480  
P2=-106.5420;49.0000  
P3=-106.6113;48.8333  
P4=-106.6807;48.6667  
P5=-106.7500;48.5000  
P6=-106.6250;48.3610  
P7=-106.5000;48.2220  
P8=-106.3635;48.3610  
P9=-106.2270;48.5000  
P10=-106.1135;48.5780  
P11=-106.0000;48.6560  
P12=-105.8727;48.7707  
P13=-105.7453;48.8853  
P14=-105.6180;49.0000  
P15=-105.5000;49.1000  
P16=-105.3333;49.2330  
P17=-105.1667;49.3660  
P18=-105.0000;49.4990  
P19=-104.9990;49.5000  
P20=-104.8327;49.6050  
P21=-104.6663;49.7100  
P22=-104.5000;49.8150  
P23=-104.4035;49.9075  
P24=-104.3070;50.0000  
P25=-104.2083;50.1667  
P26=-104.1097;50.3333  
P27=-104.0110;50.5000  
P28=-104.0000;50.5240  
P29=-103.8333;50.6747  
P30=-103.6667;50.8253  
P31=-103.5000;50.9760  
P32=-103.4740;51.0000  
P33=-103.3160;51.1267  
P34=-103.1580;51.2533  
P35=-103.0000;51.3800  
P36=-102.8620;51.5000  
P37=-102.7413;51.6120

P38=-102.6207;51.7240  
P39=-102.5000;51.8360  
P40=-102.3910;51.9180  
P41=-102.2820;52.0000  
P42=-102.1410;52.1750  
P43=-102.0000;52.3500  
P44=-101.8875;52.4250  
P45=-101.7750;52.5000  
P46=-101.6833;52.6457  
P47=-101.5917;52.7913  
P48=-101.5000;52.9370  
P49=-101.4270;53.0000  
P50=-101.5000;53.0420  
P51=-101.7500;53.0240  
P52=-102.0000;53.0060  
P53=-102.0090;53.0000  
P54=-102.1727;52.8810  
P55=-102.3363;52.7620  
P56=-102.5000;52.6430  
P57=-102.6505;52.5715  
P58=-102.8010;52.5000  
P59=-103.0000;52.4130  
P60=-103.1667;52.2967  
P61=-103.3333;52.1803  
P62=-103.5000;52.0640  
P63=-103.5800;52.0000  
P64=-103.7200;51.8943  
P65=-103.8600;51.7887  
P66=-104.0000;51.6830  
P67=-104.1010;51.5915  
P68=-104.2020;51.5000  
P69=-104.3510;51.4090  
P70=-104.5000;51.3180  
P71=-104.6580;51.1590  
P72=-104.8160;51.0000  
P73=-105.0000;50.9040  
P74=-105.1357;50.7693  
P75=-105.2713;50.6347  
P76=-105.4070;50.5000  
P77=-105.4535;50.3780  
P78=-105.5000;50.2560  
P79=-105.6200;50.1280  
P80=-105.7400;50.0000  
P81=-105.8700;49.8420  
P82=-106.0000;49.6840  
P83=-106.0780;49.5920  
P84=-106.1560;49.5000  
P85=-106.2707;49.3493  
P86=-106.3853;49.1987  
P87=-106.5000;49.0480  
[C18]  
gain=-50.00  
n\_point=87  
P1=-78.0000 ;45.1840  
P2=-78.0730 ;45.5000  
P3=-78.3380 ;46.0000  
P4=-78.4660 ;46.5000

P5=-78.5000 ;46.5590  
P6=-78.5560 ;46.5000  
P7=-78.6450 ;46.0000  
P8=-78.7270 ;45.5000  
P9=-78.7160 ;45.0000  
P10=-78.7390 ;44.5000  
P11=-78.7510 ;44.0000  
P12=-78.7680 ;43.5000  
P13=-78.7970 ;43.0000  
P14=-78.8260 ;42.5000  
P15=-78.8690 ;42.0000  
P16=-78.9230 ;41.5000  
P17=-79.0000 ;41.0370  
P18=-79.0060 ;41.0000  
P19=-79.0780 ;40.5000  
P20=-79.1570 ;40.0000  
P21=-79.2710 ;39.5000  
P22=-79.2960 ;39.0000  
P23=-79.4120 ;38.5000  
P24=-79.5000 ;38.0540  
P25=-79.5120 ;38.0000  
P26=-79.6790 ;37.5000  
P27=-79.8210 ;37.0000  
P28=-79.8730 ;36.5000  
P29=-80.0000 ;36.1600  
P30=-80.0710 ;36.0000  
P31=-80.2410 ;35.5000  
P32=-80.3210 ;35.0000  
P33=-80.5000 ;34.5190  
P34=-80.5090 ;34.5000  
P35=-80.7200 ;34.0000  
P36=-80.8490 ;33.5000  
P37=-81.0000 ;33.0100  
P38=-81.0040 ;33.0000  
P39=-81.1870 ;32.5000  
P40=-81.3520 ;32.0000  
P41=-81.5000 ;31.8330  
P42=-81.6610 ;31.5000  
P43=-81.7840 ;31.0000  
P44=-82.0000 ;30.6010  
P45=-82.0510 ;30.5000  
P46=-82.1820 ;30.0000  
P47=-82.0000 ;29.5910  
P48=-81.8180 ;30.0000  
P49=-81.5000 ;30.4470  
P50=-81.4660 ;30.5000  
P51=-81.2260 ;31.0000  
P52=-81.0000 ;31.4620  
P53=-80.9780 ;31.5000  
P54=-80.7670 ;32.0000  
P55=-80.5910 ;32.5000  
P56=-80.5000 ;32.5780  
P57=-80.2760 ;33.0000  
P58=-80.1040 ;33.5000  
P59=-80.0000 ;33.8260  
P60=-79.9200 ;34.0000  
P61=-79.7360 ;34.5000

P62=-79.5530 ;35.0000  
P63=-79.5000 ;35.1280  
P64=-79.3490 ;35.5000  
P65=-79.2150 ;36.0000  
P66=-79.0480 ;36.5000  
P67=-79.0000 ;36.6840  
P68=-78.8960 ;37.0000  
P69=-78.7200 ;37.5000  
P70=-78.5940 ;38.0000  
P71=-78.5180 ;38.5000  
P72=-78.5000 ;38.5480  
P73=-78.3340 ;39.0000  
P74=-78.2590 ;39.5000  
P75=-78.1710 ;40.0000  
P76=-78.0870 ;40.5000  
P77=-78.0270 ;41.0000  
P78=-78.0000 ;41.1530  
P79=-77.9460 ;41.5000  
P80=-77.9060 ;42.0000  
P81=-77.8440 ;42.5000  
P82=-77.8490 ;43.0000  
P83=-77.8180 ;43.5000  
P84=-77.8730 ;44.0000  
P85=-77.8910 ;44.5000  
P86=-77.9830 ;45.0000  
P87=-78.0000 ;45.1840

[C19]

gain=-50.00

n\_point=75

P1=-82.5000 ;41.3140  
P2=-82.5395 ;41.1570  
P3=-82.5790 ;41.0000  
P4=-82.5710 ;40.7500  
P5=-82.5630 ;40.5000  
P6=-82.6355 ;40.2500  
P7=-82.7080 ;40.0000  
P8=-82.6670 ;39.7500  
P9=-82.6260 ;39.5000  
P10=-82.6725 ;39.2500  
P11=-82.7190 ;39.0000  
P12=-82.7355 ;38.7500  
P13=-82.7520 ;38.5000  
P14=-82.7225 ;38.2500  
P15=-82.6930 ;38.0000  
P16=-82.7525 ;37.7500  
P17=-82.8120 ;37.5000  
P18=-82.8380 ;37.2500  
P19=-82.8640 ;37.0000  
P20=-83.0000 ;36.7430  
P21=-83.0720 ;36.5000  
P22=-83.1440 ;36.2500  
P23=-83.2160 ;36.0000  
P24=-83.2455 ;35.7500  
P25=-83.2750 ;35.5000  
P26=-83.2625 ;35.2500  
P27=-83.2500 ;35.0000  
P28=-83.3750 ;34.7830



P29=-83.5000 ;34.5660  
P30=-83.5280 ;34.5000  
P31=-83.6150 ;34.2500  
P32=-83.7020 ;34.0000  
P33=-83.7405 ;33.7500  
P34=-83.7790 ;33.5000  
P35=-83.7650 ;33.2500  
P36=-83.7510 ;33.0000  
P37=-83.6255 ;32.8695  
P38=-83.5000 ;32.7390  
P39=-83.3660 ;33.0000  
P40=-83.2855 ;33.2500  
P41=-83.2050 ;33.5000  
P42=-83.1845 ;33.7500  
P43=-83.1640 ;34.0000  
P44=-83.0820 ;34.2055  
P45=-83.0000 ;34.4110  
P46=-82.9650 ;34.5000  
P47=-82.8830 ;34.7500  
P48=-82.8010 ;35.0000  
P49=-82.7345 ;35.2500  
P50=-82.6680 ;35.5000  
P51=-82.6545 ;35.7500  
P52=-82.6410 ;36.0000  
P53=-82.5705 ;36.1525  
P54=-82.5000 ;36.3050  
P55=-82.4190 ;36.5000  
P56=-82.3585 ;36.7500  
P57=-82.2980 ;37.0000  
P58=-82.2965 ;37.2500  
P59=-82.2950 ;37.5000  
P60=-82.3165 ;37.7500  
P61=-82.3380 ;38.0000  
P62=-82.2785 ;38.2500  
P63=-82.2190 ;38.5000  
P64=-82.2375 ;38.7500  
P65=-82.2560 ;39.0000  
P66=-82.2880 ;39.2500  
P67=-82.3200 ;39.5000  
P68=-82.2840 ;39.7500  
P69=-82.2480 ;40.0000  
P70=-82.3400 ;40.2500  
P71=-82.4320 ;40.5000  
P72=-82.4305 ;40.7500  
P73=-82.4290 ;41.0000  
P74=-82.4645 ;41.1570  
P75=-82.5000 ;41.3140

[C20]

gain=-50.00

n\_point=159

P1=-72.0000 ;51.1360  
P2=-72.0460 ;51.5000  
P3=-72.1250 ;52.0000  
P4=-72.2660 ;52.5000  
P5=-72.4500 ;53.0000  
P6=-72.5000 ;53.1960  
P7=-72.6400 ;53.5000

P8=-72.9250 ;54.0000  
P9=-73.0000 ;54.2000  
P10=-73.2250 ;54.5000  
P11=-73.5000 ;54.6820  
P12=-73.6350 ;54.5000  
P13=-73.5460 ;54.0000  
P14=-73.5880 ;53.5000  
P15=-73.6740 ;53.0000  
P16=-73.6750 ;52.5000  
P17=-73.6910 ;52.0000  
P18=-73.6910 ;51.5000  
P19=-73.6690 ;51.0000  
P20=-73.6910 ;50.5000  
P21=-73.7350 ;50.0000  
P22=-73.7650 ;49.5000  
P23=-73.8040 ;49.0000  
P24=-73.8480 ;48.5000  
P25=-73.8920 ;48.0000  
P26=-73.9580 ;47.5000  
P27=-74.0000 ;47.2810  
P28=-74.0550 ;47.0000  
P29=-74.1330 ;46.5000  
P30=-74.2220 ;46.0000  
P31=-74.3020 ;45.5000  
P32=-74.3700 ;45.0000  
P33=-74.4770 ;44.5000  
P34=-74.5000 ;44.3750  
P35=-74.5800 ;44.0000  
P36=-74.7120 ;43.5000  
P37=-74.8140 ;43.0000  
P38=-74.9170 ;42.5000  
P39=-75.0000 ;42.1300  
P40=-75.0410 ;42.0000  
P41=-75.1750 ;41.5000  
P42=-75.3260 ;41.0000  
P43=-75.4330 ;40.5000  
P44=-75.5000 ;40.2510  
P45=-75.6010 ;40.0000  
P46=-75.7520 ;39.5000  
P47=-75.8950 ;39.0000  
P48=-76.0000 ;38.6010  
P49=-76.0390 ;38.5000  
P50=-76.2380 ;38.0000  
P51=-76.4010 ;37.5000  
P52=-76.5000 ;37.0650  
P53=-76.5250 ;37.0000  
P54=-76.7690 ;36.5000  
P55=-76.9110 ;36.0000  
P56=-77.0000 ;35.7190  
P57=-77.1030 ;35.5000  
P58=-77.3150 ;35.0000  
P59=-77.4460 ;34.5000  
P60=-77.5000 ;34.3800  
P61=-77.6950 ;34.0000  
P62=-77.8900 ;33.5000  
P63=-78.0000 ;33.1940  
P64=-78.0960 ;33.0000

P65=-78.2910 ;32.5000  
P66=-78.5000 ;32.0850  
P67=-78.5500 ;32.0000  
P68=-78.8000 ;31.5000  
P69=-79.0000 ;31.0160  
P70=-79.0090 ;31.0000  
P71=-79.2500 ;30.5000  
P72=-79.5000 ;30.0330  
P73=-79.5200 ;30.0000  
P74=-79.7820 ;29.5000  
P75=-80.0000 ;29.1070  
P76=-80.0660 ;29.0000  
P77=-80.3250 ;28.5000  
P78=-80.5000 ;28.1710  
P79=-80.6040 ;28.0000  
P80=-80.8130 ;27.5000  
P81=-81.0000 ;27.2200  
P82=-81.1310 ;27.0000  
P83=-81.3250 ;26.5000  
P84=-81.5000 ;26.2590  
P85=-81.6280 ;26.0000  
P86=-81.5530 ;25.5000  
P87=-81.5000 ;25.4920  
P88=-81.4940 ;25.5000  
P89=-81.1880 ;26.0000  
P90=-81.0000 ;26.1290  
P91=-80.7550 ;26.5000  
P92=-80.5000 ;26.8110  
P93=-80.3710 ;27.0000  
P94=-80.0880 ;27.5000  
P95=-80.0000 ;27.5950  
P96=-79.7410 ;28.0000  
P97=-79.5000 ;28.4170  
P98=-79.4420 ;28.5000  
P99=-79.1500 ;29.0000  
P100=-79.0000 ;29.3110  
P101=-78.8810 ;29.5000  
P102=-78.6560 ;30.0000  
P103=-78.5000 ;30.2330  
P104=-78.3230 ;30.5000  
P105=-78.0750 ;31.0000  
P106=-78.0000 ;31.1370  
P107=-77.7800 ;31.5000  
P108=-77.5960 ;32.0000  
P109=-77.5000 ;32.1540  
P110=-77.2810 ;32.5000  
P111=-77.0550 ;33.0000  
P112=-77.0000 ;33.1380  
P113=-76.8010 ;33.5000  
P114=-76.6030 ;34.0000  
P115=-76.5000 ;34.2220  
P116=-76.3370 ;34.5000  
P117=-76.1440 ;35.0000  
P118=-76.0000 ;35.3630  
P119=-75.9200 ;35.5000  
P120=-75.6890 ;36.0000  
P121=-75.5570 ;36.5000

P122=-75.5000 ;36.6290  
P123=-75.2900 ;37.0000  
P124=-75.1310 ;37.5000  
P125=-75.0000 ;37.8570  
P126=-74.9180 ;38.0000  
P127=-74.7250 ;38.5000  
P128=-74.5580 ;39.0000  
P129=-74.5000 ;39.2170  
P130=-74.3770 ;39.5000  
P131=-74.1640 ;40.0000  
P132=-74.0290 ;40.5000  
P133=-74.0000 ;40.5980  
P134=-73.8070 ;41.0000  
P135=-73.6710 ;41.5000  
P136=-73.5250 ;42.0000  
P137=-73.5000 ;42.1280  
P138=-73.3850 ;42.5000  
P139=-73.1820 ;43.0000  
P140=-73.0740 ;43.5000  
P141=-73.0000 ;43.8150  
P142=-72.9350 ;44.0000  
P143=-72.7950 ;44.5000  
P144=-72.7030 ;45.0000  
P145=-72.5770 ;45.5000  
P146=-72.5000 ;45.9110  
P147=-72.4760 ;46.0000  
P148=-72.3580 ;46.5000  
P149=-72.2640 ;47.0000  
P150=-72.2110 ;47.5000  
P151=-72.1420 ;48.0000  
P152=-72.0810 ;48.5000  
P153=-72.0310 ;49.0000  
P154=-72.0000 ;49.3110  
P155=-71.9780 ;49.5000  
P156=-71.9660 ;50.0000  
P157=-71.9780 ;50.5000  
P158=-71.9870 ;51.0000  
P159=-72.0000 ;51.1360  
[C21]  
gain=-50.00  
n\_point=76  
P1=-114.5000;31.2640  
P2=-114.5550;31.0000  
P3=-114.5760;30.7500  
P4=-114.5970;30.5000  
P5=-114.5830;30.2500  
P6=-114.5690;30.0000  
P7=-114.5460;29.7500  
P8=-114.5230;29.5000  
P9=-114.5000;29.2660  
P10=-114.4800;29.0000  
P11=-114.4440;28.7500  
P12=-114.4080;28.5000  
P13=-114.3520;28.2500  
P14=-114.2960;28.0000  
P15=-114.2405;27.7500  
P16=-114.1850;27.5000

P17=-114.1165;27.2500  
P18=-114.0480;27.0000  
P19=-114.0000;26.8750  
P20=-113.9500;26.6875  
P21=-113.9000;26.5000  
P22=-113.8200;26.2500  
P23=-113.7400;26.0000  
P24=-113.6380;25.7500  
P25=-113.5360;25.5000  
P26=-113.5000;25.4180  
P27=-113.4145;25.2090  
P28=-113.3290;25.0000  
P29=-113.2395;24.7500  
P30=-113.1500;24.5000  
P31=-113.0750;24.3540  
P32=-113.0000;24.2080  
P33=-112.8990;24.1040  
P34=-112.7980;24.0000  
P35=-112.7117;23.8333  
P36=-112.6253;23.6667  
P37=-112.5390;23.5000  
P38=-112.5000;23.4180  
P39=-112.4310;23.5000  
P40=-112.3875;23.7500  
P41=-112.3440;24.0000  
P42=-112.3615;24.2500  
P43=-112.3790;24.5000  
P44=-112.4175;24.7500  
P45=-112.4560;25.0000  
P46=-112.5000;25.2140  
P47=-112.5495;25.3570  
P48=-112.5990;25.5000  
P49=-112.6500;25.7500  
P50=-112.7010;26.0000  
P51=-112.7380;26.2500  
P52=-112.7750;26.5000  
P53=-112.8185;26.7500  
P54=-112.8620;27.0000  
P55=-112.9210;27.2500  
P56=-112.9800;27.5000  
P57=-113.0000;27.5870  
P58=-113.0540;27.7935  
P59=-113.1080;28.0000  
P60=-113.1605;28.2500  
P61=-113.2130;28.5000  
P62=-113.2745;28.7500  
P63=-113.3360;29.0000  
P64=-113.4040;29.2500  
P65=-113.4720;29.5000  
P66=-113.5000;29.6110  
P67=-113.5790;29.8055  
P68=-113.6580;30.0000  
P69=-113.7265;30.2500  
P70=-113.7950;30.5000  
P71=-113.8610;30.7500  
P72=-113.9270;31.0000  
P73=-113.9635;31.1335

P74=-114.0000;31.2670  
P75=-114.2500;31.2655  
P76=-114.5000;31.2640  
[C22]  
gain=-50.00  
n\_point=98  
P1=-91.0000 ;15.7210  
P2=-91.2290 ;15.6105  
P3=-91.4580 ;15.5000  
P4=-91.5000 ;15.3740  
P5=-91.7500 ;15.2775  
P6=-92.0000 ;15.1810  
P7=-92.2610 ;15.0000  
P8=-92.5000 ;14.7610  
P9=-92.7500 ;14.6805  
P10=-93.0000 ;14.6000  
P11=-93.1560 ;14.5000  
P12=-93.3280 ;14.3960  
P13=-93.5000 ;14.2920  
P14=-93.7500 ;14.1825  
P15=-94.0000 ;14.0730  
P16=-94.1120 ;14.0000  
P17=-94.3060 ;13.9290  
P18=-94.5000 ;13.8580  
P19=-94.7500 ;13.7255  
P20=-95.0000 ;13.5930  
P21=-95.1440 ;13.5000  
P22=-95.3220 ;13.4000  
P23=-95.5000 ;13.3000  
P24=-95.7500 ;13.2530  
P25=-96.0000 ;13.2060  
P26=-96.1770 ;13.1030  
P27=-96.3540 ;13.0000  
P28=-96.5000 ;12.9020  
P29=-96.7500 ;12.8270  
P30=-97.0000 ;12.7520  
P31=-97.2500 ;12.6850  
P32=-97.5000 ;12.6180  
P33=-97.7900 ;12.5000  
P34=-98.0000 ;12.3740  
P35=-98.2500 ;12.3535  
P36=-98.5000 ;12.3330  
P37=-98.7500 ;12.2830  
P38=-99.0000 ;12.2330  
P39=-99.2500 ;12.1500  
P40=-99.5000 ;12.0670  
P41=-99.7210 ;12.0000  
P42=-100.0000;11.8130  
P43=-100.2500;11.7445  
P44=-100.5000;11.6760  
P45=-100.7500;11.6080  
P46=-101.0000;11.5400  
P47=-101.1190;11.5000  
P48=-101.0000;11.4450  
P49=-100.7500;11.3810  
P50=-100.5000;11.3170  
P51=-100.2500;11.3085

P52=-100.0000;11.3000  
P53=-99.7500 ;11.3295  
P54=-99.5000 ;11.3590  
P55=-99.2990 ;11.4295  
P56=-99.0980 ;11.5000  
P57=-99.0000 ;11.5380  
P58=-98.7500 ;11.5805  
P59=-98.5000 ;11.6230  
P60=-98.2500 ;11.6845  
P61=-98.0000 ;11.7460  
P62=-97.7500 ;11.8425  
P63=-97.5000 ;11.9390  
P64=-97.3740 ;12.0000  
P65=-97.1870 ;12.0800  
P66=-97.0000 ;12.1600  
P67=-96.7500 ;12.1740  
P68=-96.5000 ;12.1880  
P69=-96.2500 ;12.3240  
P70=-96.0000 ;12.4600  
P71=-95.9320 ;12.5000  
P72=-95.7160 ;12.5940  
P73=-95.5000 ;12.6880  
P74=-95.2500 ;12.7265  
P75=-95.0000 ;12.7650  
P76=-94.8375 ;12.8825  
P77=-94.6750 ;13.0000  
P78=-94.5000 ;13.1090  
P79=-94.2500 ;13.2480  
P80=-94.0000 ;13.3870  
P81=-93.8320 ;13.5000  
P82=-93.6660 ;13.6000  
P83=-93.5000 ;13.7000  
P84=-93.2500 ;13.8325  
P85=-93.0000 ;13.9650  
P86=-92.9520 ;14.0000  
P87=-92.7260 ;14.1495  
P88=-92.5000 ;14.2990  
P89=-92.3420 ;14.3995  
P90=-92.1840 ;14.5000  
P91=-92.0000 ;14.6840  
P92=-91.7500 ;14.8205  
P93=-91.5000 ;14.9570  
P94=-91.4470 ;15.0000  
P95=-91.2235 ;15.1740  
P96=-91.0000 ;15.3480  
P97=-90.8010 ;15.5000  
P98=-91.0000 ;15.7210  
[C23]  
gain=-50.00  
n\_point=105  
P1=-88.0000 ;15.2270  
P2=-88.2610 ;15.0000  
P3=-88.5000 ;14.7550  
P4=-88.8670 ;14.5000  
P5=-89.0000 ;14.3560  
P6=-89.5000 ;14.0500  
P7=-89.5640 ;14.0000

P8=-90.0000 ;13.6990  
P9=-90.2730 ;13.5000  
P10=-90.5000 ;13.2920  
P11=-91.0000 ;13.0760  
P12=-91.1090 ;13.0000  
P13=-91.5000 ;12.7690  
P14=-91.9360 ;12.5000  
P15=-92.0000 ;12.4650  
P16=-92.5000 ;12.2280  
P17=-92.8030 ;12.0000  
P18=-93.0000 ;11.8930  
P19=-93.5000 ;11.6380  
P20=-93.7010 ;11.5000  
P21=-94.0000 ;11.3610  
P22=-94.5000 ;11.1410  
P23=-94.7180 ;11.0000  
P24=-95.0000 ;10.8990  
P25=-95.5000 ;10.7040  
P26=-95.8480 ;10.5000  
P27=-96.0000 ;10.4380  
P28=-96.5000 ;10.3570  
P29=-97.0000 ;10.1430  
P30=-97.3710 ;10.0000  
P31=-97.5000 ;9.9600  
P32=-98.0000 ;9.8980  
P33=-98.5000 ;9.8810  
P34=-99.0000 ;9.8500  
P35=-99.5000 ;9.8300  
P36=-100.0000;9.8220  
P37=-100.5000;9.8110  
P38=-101.0000;9.7870  
P39=-101.5000;9.7400  
P40=-102.0000;9.6900  
P41=-102.5000;9.6720  
P42=-103.0000;9.7070  
P43=-103.5000;9.7910  
P44=-104.0000;9.9040  
P45=-104.3900;10.0000  
P46=-104.5000;10.0340  
P47=-105.0000;10.2120  
P48=-105.5000;10.3290  
P49=-106.0000;10.3810  
P50=-106.4190;10.0000  
P51=-106.0150;9.5000  
P52=-106.0000;9.4820  
P53=-105.5000;9.0690  
P54=-105.2460;9.0000  
P55=-105.0000;8.8740  
P56=-104.5000;8.8200  
P57=-104.0000;8.8660  
P58=-103.5000;8.9570  
P59=-103.2590;9.0000  
P60=-103.0000;9.0820  
P61=-102.5000;9.1800  
P62=-102.0000;9.1820  
P63=-101.5000;9.1100  
P64=-101.0150;9.0000



P65=-101.0000;8.9980  
P66=-100.5000;8.9200  
P67=-100.0000;8.8540  
P68=-99.5000 ;8.8130  
P69=-99.0000 ;8.8130  
P70=-98.5000 ;8.8680  
P71=-98.0000 ;8.9990  
P72=-97.9960 ;9.0000  
P73=-97.5000 ;9.0800  
P74=-97.0000 ;9.1370  
P75=-96.5000 ;9.3630  
P76=-96.2560 ;9.5000  
P77=-96.0000 ;9.5690  
P78=-95.5000 ;9.7030  
P79=-95.0510 ;10.0000  
P80=-95.0000 ;10.0270  
P81=-94.5000 ;10.1650  
P82=-94.0310 ;10.5000  
P83=-94.0000 ;10.5290  
P84=-93.5000 ;10.6790  
P85=-93.0650 ;11.0000  
P86=-93.0000 ;11.0510  
P87=-92.5000 ;11.2810  
P88=-92.2220 ;11.5000  
P89=-92.0000 ;11.6360  
P90=-91.5270 ;12.0000  
P91=-91.5000 ;12.0500  
P92=-91.0000 ;12.3220  
P93=-90.7590 ;12.5000  
P94=-90.5000 ;12.7360  
P95=-90.0870 ;13.0000  
P96=-90.0000 ;13.0990  
P97=-89.5000 ;13.3790  
P98=-89.3510 ;13.5000  
P99=-89.0000 ;13.8040  
P100=-88.7470 ;14.0000  
P101=-88.5000 ;14.2330  
P102=-88.1830 ;14.5000  
P103=-88.0000 ;14.6770  
P104=-87.6070 ;15.0000  
P105=-88.0000 ;15.2270  
[C24]  
gain=-50.00  
n\_point=82  
P1=-82.0000 ;21.8940  
P2=-82.1265 ;21.6970  
P3=-82.2530 ;21.5000  
P4=-82.3765 ;21.4475  
P5=-82.5000 ;21.3950  
P6=-82.6400 ;21.1975  
P7=-82.7800 ;21.0000  
P8=-82.8900 ;20.8885  
P9=-83.0000 ;20.7770  
P10=-83.0990 ;20.6385  
P11=-83.1980 ;20.5000  
P12=-83.3490 ;20.3195  
P13=-83.5000 ;20.1390

P14=-83.6030 ;20.0000  
P15=-83.7070 ;19.8333  
P16=-83.8110 ;19.6667  
P17=-83.9150 ;19.5000  
P18=-84.0000 ;19.4300  
P19=-84.1017 ;19.2867  
P20=-84.2033 ;19.1433  
P21=-84.3050 ;19.0000  
P22=-84.4025 ;18.8990  
P23=-84.5000 ;18.7980  
P24=-84.6230 ;18.6490  
P25=-84.7460 ;18.5000  
P26=-84.8730 ;18.3260  
P27=-85.0000 ;18.1520  
P28=-85.1290 ;18.0000  
P29=-85.2527 ;17.8563  
P30=-85.3763 ;17.7127  
P31=-85.5000 ;17.5690  
P32=-85.5660 ;17.5000  
P33=-85.7107 ;17.3370  
P34=-85.8553 ;17.1740  
P35=-86.0000 ;17.0110  
P36=-86.0110 ;17.0000  
P37=-86.1740 ;16.8383  
P38=-86.3370 ;16.6767  
P39=-86.5000 ;16.5150  
P40=-86.5160 ;16.5000  
P41=-86.5000 ;16.2700  
P42=-86.3333 ;16.3333  
P43=-86.1667 ;16.3967  
P44=-86.0000 ;16.4600  
P45=-85.9560 ;16.5000  
P46=-85.8040 ;16.6373  
P47=-85.6520 ;16.7747  
P48=-85.5000 ;16.9120  
P49=-85.4100 ;17.0000  
P50=-85.2733 ;17.1287  
P51=-85.1367 ;17.2573  
P52=-85.0000 ;17.3860  
P53=-84.8930 ;17.5000  
P54=-84.7620 ;17.6297  
P55=-84.6310 ;17.7593  
P56=-84.5000 ;17.8890  
P57=-84.3990 ;18.0000  
P58=-84.2660 ;18.1640  
P59=-84.1330 ;18.3280  
P60=-84.0000 ;18.4920  
P61=-83.9940 ;18.5000  
P62=-83.8773 ;18.6667  
P63=-83.7607 ;18.8333  
P64=-83.6440 ;19.0000  
P65=-83.5000 ;19.1690  
P66=-83.3745 ;19.3345  
P67=-83.2490 ;19.5000  
P68=-83.1245 ;19.6560  
P69=-83.0000 ;19.8120  
P70=-82.8470 ;20.0000

P71=-82.7507 ;20.1667  
P72=-82.6543 ;20.3333  
P73=-82.5580 ;20.5000  
P74=-82.5000 ;20.5570  
P75=-82.4073 ;20.7047  
P76=-82.3147 ;20.8523  
P77=-82.2220 ;21.0000  
P78=-82.1110 ;21.1865  
P79=-82.0000 ;21.3730  
P80=-81.9080 ;21.5000  
P81=-81.9540 ;21.6970  
P82=-82.0000 ;21.8940  
[C25]  
gain=-50.00  
n\_point=345  
P1=-45.1164 ;74.3747  
P2=-45.5430 ;74.2860  
P3=-46.0000 ;74.1890  
P4=-46.5000 ;74.0800  
P5=-46.8830 ;74.0000  
P6=-47.0000 ;73.9810  
P7=-47.5000 ;73.9040  
P8=-48.0000 ;73.7950  
P9=-48.5000 ;73.6640  
P10=-49.0000 ;73.5250  
P11=-49.0950 ;73.5000  
P12=-49.5000 ;73.4230  
P13=-50.0000 ;73.3190  
P14=-50.5000 ;73.1780  
P15=-51.0000 ;73.0120  
P16=-51.0360 ;73.0000  
P17=-51.5000 ;72.8550  
P18=-52.0000 ;72.7430  
P19=-52.5000 ;72.6170  
P20=-52.8110 ;72.5000  
P21=-53.0000 ;72.3650  
P22=-53.5000 ;72.1310  
P23=-53.9370 ;72.0000  
P24=-54.0000 ;71.9680  
P25=-54.5000 ;71.6300  
P26=-54.6900 ;71.5000  
P27=-55.0000 ;71.3350  
P28=-55.5000 ;71.0460  
P29=-55.5740 ;71.0000  
P30=-56.0000 ;70.8470  
P31=-56.5000 ;70.5650  
P32=-56.6060 ;70.5000  
P33=-57.0000 ;70.1900  
P34=-57.3250 ;70.0000  
P35=-57.5000 ;69.8540  
P36=-57.8140 ;69.5000  
P37=-58.0000 ;69.3630  
P38=-58.4420 ;69.0000  
P39=-58.5000 ;68.9470  
P40=-59.0000 ;68.5560  
P41=-59.0630 ;68.5000  
P42=-59.4670 ;68.0000

P43=-59.5000 ;67.9730  
P44=-60.0000 ;67.5610  
P45=-60.0560 ;67.5000  
P46=-60.4480 ;67.0000  
P47=-60.5000 ;66.9370  
P48=-60.8660 ;66.5000  
P49=-61.0000 ;66.3610  
P50=-61.3050 ;66.0000  
P51=-61.5000 ;65.6190  
P52=-61.5610 ;65.5000  
P53=-61.9970 ;65.0000  
P54=-62.0000 ;64.9920  
P55=-62.1320 ;64.5000  
P56=-62.4250 ;64.0000  
P57=-62.5000 ;63.7060  
P58=-62.5540 ;63.5000  
P59=-62.8200 ;63.0000  
P60=-63.0000 ;62.5590  
P61=-63.0220 ;62.5000  
P62=-63.3000 ;62.0000  
P63=-63.5000 ;61.6260  
P64=-63.5590 ;61.5000  
P65=-63.8250 ;61.0000  
P66=-64.0000 ;60.6490  
P67=-64.0690 ;60.5000  
P68=-64.2780 ;60.0000  
P69=-64.4670 ;59.5000  
P70=-64.5000 ;59.3860  
P71=-64.6090 ;59.0000  
P72=-64.7760 ;58.5000  
P73=-64.9330 ;58.0000  
P74=-65.0000 ;57.8310  
P75=-65.1310 ;57.5000  
P76=-65.3440 ;57.0000  
P77=-65.5000 ;56.6470  
P78=-65.5630 ;56.5000  
P79=-65.7800 ;56.0000  
P80=-65.9790 ;55.5000  
P81=-66.0000 ;55.4500  
P82=-66.1870 ;55.0000  
P83=-66.3740 ;54.5000  
P84=-66.5000 ;54.1920  
P85=-66.5800 ;54.0000  
P86=-66.7880 ;53.5000  
P87=-66.9860 ;53.0000  
P88=-67.0000 ;52.9660  
P89=-67.1890 ;52.5000  
P90=-67.3730 ;52.0000  
P91=-67.5000 ;51.6250  
P92=-67.5480 ;51.5000  
P93=-67.7530 ;51.0000  
P94=-67.9480 ;50.5000  
P95=-68.0000 ;50.3610  
P96=-68.1520 ;50.0000  
P97=-68.3300 ;49.5000  
P98=-68.4730 ;49.0000  
P99=-68.5000 ;48.9190

P100=-68.6610 ;48.5000  
P101=-68.8590 ;48.0000  
P102=-69.0000 ;47.5980  
P103=-69.0430 ;47.5000  
P104=-69.2380 ;47.0000  
P105=-69.4200 ;46.5000  
P106=-69.5000 ;46.2760  
P107=-69.6260 ;46.0000  
P108=-69.8110 ;45.5000  
P109=-69.9640 ;45.0000  
P110=-70.0000 ;44.9120  
P111=-70.2160 ;44.5000  
P112=-70.4070 ;44.0000  
P113=-70.5000 ;43.6860  
P114=-70.5760 ;43.5000  
P115=-70.8150 ;43.0000  
P116=-70.9670 ;42.5000  
P117=-71.0000 ;42.4020  
P118=-71.1870 ;42.0000  
P119=-71.4000 ;41.5000  
P120=-71.5000 ;41.1170  
P121=-71.5470 ;41.0000  
P122=-71.8100 ;40.5000  
P123=-71.9570 ;40.0000  
P124=-72.0000 ;39.8800  
P125=-72.1960 ;39.5000  
P126=-72.3910 ;39.0000  
P127=-72.5000 ;38.6810  
P128=-72.5940 ;38.5000  
P129=-72.8250 ;38.0000  
P130=-72.9950 ;37.5000  
P131=-73.0000 ;37.4860  
P132=-73.2520 ;37.0000  
P133=-73.4560 ;36.5000  
P134=-73.5000 ;36.3800  
P135=-73.6970 ;36.0000  
P136=-73.9290 ;35.5000  
P137=-74.0000 ;35.2880  
P138=-74.1460 ;35.0000  
P139=-74.3990 ;34.5000  
P140=-74.5000 ;34.2550  
P141=-74.6490 ;34.0000  
P142=-74.8730 ;33.5000  
P143=-75.0000 ;33.2380  
P144=-75.1530 ;33.0000  
P145=-75.3890 ;32.5000  
P146=-75.5000 ;32.2390  
P147=-75.6390 ;32.0000  
P148=-75.9020 ;31.5000  
P149=-76.0000 ;31.2940  
P150=-76.1810 ;31.0000  
P151=-76.4070 ;30.5000  
P152=-76.5000 ;30.3210  
P153=-76.6970 ;30.0000  
P154=-76.9490 ;29.5000  
P155=-77.0000 ;29.4080  
P156=-77.2560 ;29.0000

P157=-77.4890 ;28.5000  
P158=-77.5000 ;28.4800  
P159=-77.7830 ;28.0000  
P160=-78.0000 ;27.5850  
P161=-78.0560 ;27.5000  
P162=-78.3320 ;27.0000  
P163=-78.5000 ;26.7000  
P164=-78.6280 ;26.5000  
P165=-78.8870 ;26.0000  
P166=-79.0000 ;25.7940  
P167=-79.1720 ;25.5000  
P168=-79.4140 ;25.0000  
P169=-79.5000 ;24.8090  
P170=-79.6270 ;24.5000  
P171=-79.5000 ;24.2870  
P172=-79.1170 ;24.5000  
P173=-79.0000 ;24.5460  
P174=-78.5290 ;25.0000  
P175=-78.5000 ;25.0220  
P176=-78.1080 ;25.5000  
P177=-78.0000 ;25.6270  
P178=-77.7350 ;26.0000  
P179=-77.5000 ;26.3860  
P180=-77.4220 ;26.5000  
P181=-77.1180 ;27.0000  
P182=-77.0000 ;27.1970  
P183=-76.7930 ;27.5000  
P184=-76.5290 ;28.0000  
P185=-76.5000 ;28.0440  
P186=-76.1870 ;28.5000  
P187=-76.0000 ;28.8660  
P188=-75.9050 ;29.0000  
P189=-75.6180 ;29.5000  
P190=-75.5000 ;29.7380  
P191=-75.3250 ;30.0000  
P192=-75.0550 ;30.5000  
P193=-75.0000 ;30.6100  
P194=-74.7370 ;31.0000  
P195=-74.5240 ;31.5000  
P196=-74.5000 ;31.5430  
P197=-74.1890 ;32.0000  
P198=-74.0000 ;32.4110  
P199=-73.9360 ;32.5000  
P200=-73.6570 ;33.0000  
P201=-73.5000 ;33.3250  
P202=-73.3800 ;33.5000  
P203=-73.1120 ;34.0000  
P204=-73.0000 ;34.2730  
P205=-72.8630 ;34.5000  
P206=-72.5860 ;35.0000  
P207=-72.5000 ;35.2440  
P208=-72.3520 ;35.5000  
P209=-72.0690 ;36.0000  
P210=-72.0000 ;36.1980  
P211=-71.8270 ;36.5000  
P212=-71.5630 ;37.0000  
P213=-71.5000 ;37.1830

P214=-71.3190 ;37.5000  
P215=-71.0560 ;38.0000  
P216=-71.0000 ;38.1760  
P217=-70.8240 ;38.5000  
P218=-70.5580 ;39.0000  
P219=-70.5000 ;39.1730  
P220=-70.3250 ;39.5000  
P221=-70.0700 ;40.0000  
P222=-70.0000 ;40.1800  
P223=-69.8090 ;40.5000  
P224=-69.5940 ;41.0000  
P225=-69.5000 ;41.2150  
P226=-69.3150 ;41.5000  
P227=-69.1020 ;42.0000  
P228=-69.0000 ;42.2550  
P229=-68.8520 ;42.5000  
P230=-68.5910 ;43.0000  
P231=-68.5000 ;43.2470  
P232=-68.3570 ;43.5000  
P233=-68.1140 ;44.0000  
P234=-68.0000 ;44.2480  
P235=-67.8320 ;44.5000  
P236=-67.5870 ;45.0000  
P237=-67.5000 ;45.2320  
P238=-67.3510 ;45.5000  
P239=-67.0870 ;46.0000  
P240=-67.0000 ;46.1860  
P241=-66.7950 ;46.5000  
P242=-66.5510 ;47.0000  
P243=-66.5000 ;47.1200  
P244=-66.2750 ;47.5000  
P245=-66.0480 ;48.0000  
P246=-66.0000 ;48.1020  
P247=-65.7620 ;48.5000  
P248=-65.5160 ;49.0000  
P249=-65.5000 ;49.0380  
P250=-65.2390 ;49.5000  
P251=-65.0230 ;50.0000  
P252=-65.0000 ;50.0540  
P253=-64.7610 ;50.5000  
P254=-64.5200 ;51.0000  
P255=-64.5000 ;51.0420  
P256=-64.2320 ;51.5000  
P257=-64.0000 ;51.9940  
P258=-63.9970 ;52.0000  
P259=-63.7420 ;52.5000  
P260=-63.5420 ;53.0000  
P261=-63.5000 ;53.1160  
P262=-63.3210 ;53.5000  
P263=-63.0590 ;54.0000  
P264=-63.0000 ;54.1130  
P265=-62.7550 ;54.5000  
P266=-62.5000 ;54.9200  
P267=-62.4450 ;55.0000  
P268=-62.1090 ;55.5000  
P269=-62.0000 ;55.6860  
P270=-61.7920 ;56.0000

P271=-61.5250 ;56.5000  
P272=-61.5000 ;56.5600  
P273=-61.3040 ;57.0000  
P274=-61.0650 ;57.5000  
P275=-61.0000 ;57.6250  
P276=-60.8010 ;58.0000  
P277=-60.5400 ;58.5000  
P278=-60.5000 ;58.5610  
P279=-60.1580 ;59.0000  
P280=-60.0000 ;59.2300  
P281=-59.8030 ;59.5000  
P282=-59.5000 ;59.9490  
P283=-59.4630 ;60.0000  
P284=-59.1550 ;60.5000  
P285=-59.0000 ;60.8030  
P286=-58.8880 ;61.0000  
P287=-58.6210 ;61.5000  
P288=-58.5000 ;61.7280  
P289=-58.3600 ;62.0000  
P290=-58.0750 ;62.5000  
P291=-58.0000 ;62.6090  
P292=-57.7230 ;63.0000  
P293=-57.5000 ;63.3290  
P294=-57.3780 ;63.5000  
P295=-57.0000 ;63.9800  
P296=-56.9830 ;64.0000  
P297=-56.6310 ;64.5000  
P298=-56.5000 ;64.6660  
P299=-56.2290 ;65.0000  
P300=-56.0000 ;65.3750  
P301=-55.9100 ;65.5000  
P302=-55.5000 ;65.9170  
P303=-55.4260 ;66.0000  
P304=-55.0030 ;66.5000  
P305=-55.0000 ;66.5020  
P306=-54.5000 ;66.9460  
P307=-54.4380 ;67.0000  
P308=-54.0000 ;67.2940  
P309=-53.6980 ;67.5000  
P310=-53.5000 ;67.6440  
P311=-53.0000 ;67.9670  
P312=-52.9390 ;68.0000  
P313=-52.5000 ;68.2060  
P314=-52.0000 ;68.4700  
P315=-51.9450 ;68.5000  
P316=-51.5000 ;68.7400  
P317=-51.0000 ;68.9520  
P318=-50.8800 ;69.0000  
P319=-50.5000 ;69.1670  
P320=-50.0000 ;69.3910  
P321=-49.7250 ;69.5000  
P322=-49.5000 ;69.5870  
P323=-49.0000 ;69.7680  
P324=-48.5000 ;69.9370  
P325=-48.3260 ;70.0000  
P326=-48.0000 ;70.1140  
P327=-47.5000 ;70.2640



P328=-47.0000 ;70.4110  
P329=-46.6870 ;70.5000  
P330=-46.5000 ;70.5680  
P331=-46.0000 ;70.7260  
P332=-45.5000 ;70.8610  
P333=-45.0000 ;70.9770  
P334=-44.8890 ;71.0000  
P335=-44.5000 ;71.1150  
P336=-44.0000 ;71.2460  
P337=-43.5000 ;71.3620  
P338=-43.0000 ;71.4670  
P339=-42.8260 ;71.5000  
P340=-42.5000 ;71.5810  
P341=-42.0000 ;71.6920  
P342=-41.5000 ;71.7860  
P343=-41.0000 ;71.8640  
P344=-40.6640 ;71.9230  
P345=-40.2552 ;71.9935  
[C26]  
gain=-15.00  
n\_point=105  
P1=-97.3252 ;35.8981  
P2=-97.6773 ;35.6993  
P3=-98.0293 ;35.5005  
P4=-98.2649 ;35.3441  
P5=-98.5006 ;35.1876  
P6=-98.7388 ;35.0270  
P7=-99.0112 ;34.8246  
P8=-99.2098 ;34.6725  
P9=-99.4084 ;34.5204  
P10=-99.5844 ;34.3728  
P11=-99.7604 ;34.2252  
P12=-100.0293;33.9747  
P13=-100.2640;33.7416  
P14=-100.4231;33.5567  
P15=-100.5822;33.3718  
P16=-100.7911;33.0607  
P17=-101.0000;32.7497  
P18=-101.0348;32.6855  
P19=-101.0918;32.5726  
P20=-101.2285;32.2319  
P21=-101.3652;31.8912  
P22=-101.4516;31.5652  
P23=-101.4803;31.3357  
P24=-101.5089;31.1062  
P25=-101.5133;30.9381  
P26=-101.4988;30.7074  
P27=-101.4843;30.4767  
P28=-101.4472;30.2905  
P29=-101.4101;30.1044  
P30=-101.3139;29.8453  
P31=-101.2177;29.5862  
P32=-101.1169;29.3890  
P33=-101.0709;29.3244  
P34=-101.0000;29.2244  
P35=-100.7758;28.9668  
P36=-100.5516;28.7093

P37=-100.2657;28.5042  
P38=-99.9799 ;28.2991  
P39=-99.8774 ;28.2405  
P40=-99.8141 ;28.2057  
P41=-99.6049 ;28.1044  
P42=-99.3304 ;28.0049  
P43=-99.0559 ;27.9053  
P44=-98.8451 ;27.8564  
P45=-98.6343 ;27.8075  
P46=-98.3439 ;27.7713  
P47=-98.0534 ;27.7351  
P48=-97.7531 ;27.7386  
P49=-97.4528 ;27.7421  
P50=-97.2083 ;27.7858  
P51=-96.9638 ;27.8295  
P52=-96.7175 ;27.9541  
P53=-96.4712 ;28.0787  
P54=-96.2565 ;28.1945  
P55=-96.2051 ;28.2234  
P56=-96.1353 ;28.2689  
P57=-95.8549 ;28.5040  
P58=-95.5744 ;28.7392  
P59=-95.3916 ;28.9342  
P60=-95.2087 ;29.1291  
P61=-95.0258 ;29.3241  
P62=-94.9795 ;29.3791  
P63=-94.7522 ;29.6833  
P64=-94.5249 ;29.9874  
P65=-94.3945 ;30.1999  
P66=-94.2641 ;30.4124  
P67=-94.1025 ;30.7161  
P68=-94.0023 ;30.9505  
P69=-93.9022 ;31.1849  
P70=-93.8021 ;31.4192  
P71=-93.7760 ;31.4896  
P72=-93.7619 ;31.5292  
P73=-93.7059 ;31.7387  
P74=-93.6558 ;31.9837  
P75=-93.6057 ;32.2287  
P76=-93.5556 ;32.4737  
P77=-93.5424 ;32.5707  
P78=-93.5317 ;32.6777  
P79=-93.5328 ;32.9853  
P80=-93.5339 ;33.2929  
P81=-93.5349 ;33.6006  
P82=-93.5401 ;33.6571  
P83=-93.5439 ;33.7000  
P84=-93.5807 ;33.9009  
P85=-93.6677 ;34.2304  
P86=-93.7547 ;34.5598  
P87=-93.8209 ;34.7495  
P88=-93.9242 ;34.9810  
P89=-94.0276 ;35.2125  
P90=-94.0971 ;35.3152  
P91=-94.3258 ;35.5839  
P92=-94.5544 ;35.8525  
P93=-94.6374 ;35.9169

P94=-94.7073 ;35.9660  
P95=-95.0660 ;36.1807  
P96=-95.4416 ;36.3067  
P97=-95.6952 ;36.3300  
P98=-95.9488 ;36.3533  
P99=-96.1778 ;36.3144  
P100=-96.4067 ;36.2754  
P101=-96.7106 ;36.1737  
P102=-97.0144 ;36.0720  
P103=-97.2253 ;35.9549  
P104=-97.2659 ;35.9319  
P105=-97.3252 ;35.8981  
[C27]  
gain=-8.00  
n\_point=95  
P1=-97.5618 ;34.8124  
P2=-97.7522 ;34.7022  
P3=-97.9425 ;34.5919  
P4=-98.1329 ;34.4817  
P5=-98.3271 ;34.3452  
P6=-98.5212 ;34.2087  
P7=-98.6587 ;34.0904  
P8=-98.7962 ;33.9720  
P9=-98.9226 ;33.8543  
P10=-99.0489 ;33.7365  
P11=-99.2083 ;33.5596  
P12=-99.3677 ;33.3826  
P13=-99.5033 ;33.1971  
P14=-99.6388 ;33.0115  
P15=-99.7744 ;32.8260  
P16=-99.8418 ;32.7113  
P17=-99.8747 ;32.6526  
P18=-99.9576 ;32.4919  
P19=-100.0333;32.3023  
P20=-100.1091;32.1127  
P21=-100.1848;31.9231  
P22=-100.2318;31.7439  
P23=-100.2789;31.5647  
P24=-100.3049;31.3211  
P25=-100.3310;31.0774  
P26=-100.3312;30.9614  
P27=-100.3045;30.7189  
P28=-100.2778;30.4763  
P29=-100.2305;30.3017  
P30=-100.1832;30.1270  
P31=-100.0569;29.9047  
P32=-99.9306 ;29.6824  
P33=-99.8043 ;29.4601  
P34=-99.7705 ;29.4181  
P35=-99.7448 ;29.3870  
P36=-99.5376 ;29.2315  
P37=-99.3304 ;29.0761  
P38=-99.1232 ;28.9206  
P39=-98.8717 ;28.8215  
P40=-98.6203 ;28.7225  
P41=-98.4211 ;28.6885  
P42=-98.2219 ;28.6545

P43=-98.0239 ;28.6502  
P44=-97.8258 ;28.6460  
P45=-97.6284 ;28.6675  
P46=-97.4311 ;28.6889  
P47=-97.1508 ;28.7723  
P48=-96.8705 ;28.8557  
P49=-96.7010 ;28.9356  
P50=-96.4631 ;29.0662  
P51=-96.2251 ;29.1969  
P52=-96.1217 ;29.2637  
P53=-96.0105 ;29.3545  
P54=-95.8477 ;29.5077  
P55=-95.6849 ;29.6609  
P56=-95.5221 ;29.8140  
P57=-95.3960 ;29.9712  
P58=-95.2700 ;30.1284  
P59=-95.1439 ;30.2856  
P60=-95.0564 ;30.4273  
P61=-95.0290 ;30.4728  
P62=-94.9741 ;30.5644  
P63=-94.8635 ;30.7877  
P64=-94.7530 ;31.0110  
P65=-94.6424 ;31.2343  
P66=-94.5932 ;31.3694  
P67=-94.5441 ;31.5044  
P68=-94.4858 ;31.7195  
P69=-94.4276 ;31.9345  
P70=-94.3892 ;32.1281  
P71=-94.3569 ;32.3575  
P72=-94.3246 ;32.5868  
P73=-94.3240 ;32.8234  
P74=-94.3234 ;33.0601  
P75=-94.3356 ;33.2163  
P76=-94.3827 ;33.4460  
P77=-94.4298 ;33.6757  
P78=-94.5216 ;33.9356  
P79=-94.6107 ;34.1105  
P80=-94.6998 ;34.2855  
P81=-94.7889 ;34.4605  
P82=-94.9452 ;34.6285  
P83=-95.1040 ;34.7760  
P84=-95.2916 ;34.8772  
P85=-95.4792 ;34.9785  
P86=-95.6668 ;35.0797  
P87=-95.8348 ;35.1098  
P88=-96.0027 ;35.1398  
P89=-96.2035 ;35.1430  
P90=-96.4044 ;35.1462  
P91=-96.6972 ;35.0913  
P92=-96.9900 ;35.0364  
P93=-97.2587 ;34.9368  
P94=-97.3605 ;34.8978  
P95=-97.5618 ;34.8124