

```
[FormatInfo]
format_ver=1
[GeoMain]
ntc_id=910100000
adm=USA
sat_name=USABSS-21
long_nom=-101.0000
n_diag=1
[COHeader]
beam_id=RB01
emi_rcp=E
polar_disc=C
reason=B
n_bore=1
n_cont=25
[B1]
gain=0.00
p=-71.3820;42.0150
[C1]
gain=-40.00
n_point=576
P1=-31.8330 ;64.4180
P2=-32.0000 ;64.3940
P3=-32.5000 ;64.3220
P4=-33.0000 ;64.2530
P5=-33.5000 ;64.2230
P6=-34.0000 ;64.1730
P7=-34.5000 ;64.0830
P8=-34.7720 ;64.0000
P9=-35.0000 ;63.9680
P10=-35.5000 ;63.9000
P11=-36.0000 ;63.8330
P12=-36.5000 ;63.7730
P13=-37.0000 ;63.7430
P14=-37.5000 ;63.6930
P15=-38.0000 ;63.6130
P16=-38.4170 ;63.5000
P17=-38.5000 ;63.4890
P18=-39.0000 ;63.4210
P19=-39.5000 ;63.3500
P20=-40.0000 ;63.2900
P21=-40.5000 ;63.2610
P22=-41.0000 ;63.2110
P23=-41.5000 ;63.1280
P24=-41.9550 ;63.0000
P25=-42.0000 ;62.9940
P26=-42.5000 ;62.9230
P27=-43.0000 ;62.8470
P28=-43.5000 ;62.7780
P29=-44.0000 ;62.7370
P30=-44.5000 ;62.6700
P31=-45.0000 ;62.5660
P32=-45.2210 ;62.5000
P33=-45.5000 ;62.4580
P34=-46.0000 ;62.3730
P35=-46.5000 ;62.2900
P36=-47.0000 ;62.2070
```

P37=-47.5000 ;62.1340
P38=-48.0000 ;62.0320
P39=-48.1160 ;62.0000
P40=-48.5000 ;61.9320
P41=-49.0000 ;61.8390
P42=-49.5000 ;61.7450
P43=-50.0000 ;61.6440
P44=-50.5000 ;61.5350
P45=-50.6470 ;61.5000
P46=-51.0000 ;61.4270
P47=-51.5000 ;61.3220
P48=-52.0000 ;61.2140
P49=-52.5000 ;61.0850
P50=-52.8030 ;61.0000
P51=-53.0000 ;60.9550
P52=-53.5000 ;60.8360
P53=-54.0000 ;60.7180
P54=-54.5000 ;60.5790
P55=-54.7390 ;60.5000
P56=-55.0000 ;60.4310
P57=-55.5000 ;60.2940
P58=-56.0000 ;60.1620
P59=-56.5000 ;60.0270
P60=-56.5940 ;60.0000
P61=-57.0000 ;59.8800
P62=-57.5000 ;59.7350
P63=-58.0000 ;59.5970
P64=-58.3130 ;59.5000
P65=-58.5000 ;59.4330
P66=-59.0000 ;59.2660
P67=-59.5000 ;59.1060
P68=-59.8220 ;59.0000
P69=-60.0000 ;58.9360
P70=-60.5000 ;58.7660
P71=-61.0000 ;58.5970
P72=-61.2970 ;58.5000
P73=-61.5000 ;58.4150
P74=-62.0000 ;58.2200
P75=-62.5000 ;58.0400
P76=-62.6150 ;58.0000
P77=-63.0000 ;57.8400
P78=-63.5000 ;57.6440
P79=-63.8830 ;57.5000
P80=-64.0000 ;57.4410
P81=-64.5000 ;57.2060
P82=-65.0000 ;57.0060
P83=-65.0160 ;57.0000
P84=-65.5000 ;56.7580
P85=-66.0000 ;56.5430
P86=-66.1030 ;56.5000
P87=-66.5000 ;56.2550
P88=-66.9990 ;56.0000
P89=-67.0000 ;56.0000
P90=-67.5000 ;55.6710
P91=-67.8190 ;55.5000
P92=-68.0000 ;55.3430
P93=-68.4570 ;55.0000

P94=-68.5000 ;54.8680
P95=-68.6620 ;54.5000
P96=-68.5000 ;54.3420
P97=-68.0000 ;54.0210
P98=-67.9570 ;54.0000
P99=-67.6530 ;53.5000
P100=-68.0000 ;53.3090
P101=-68.3170 ;53.0000
P102=-68.5000 ;52.9300
P103=-69.0000 ;52.7340
P104=-69.5000 ;52.5190
P105=-69.5360 ;52.5000
P106=-70.0000 ;52.3040
P107=-70.5000 ;52.0830
P108=-70.6630 ;52.0000
P109=-71.0000 ;51.8450
P110=-71.5000 ;51.6250
P111=-71.7800 ;51.5000
P112=-72.0000 ;51.3890
P113=-72.5000 ;51.1400
P114=-72.7980 ;51.0000
P115=-73.0000 ;50.8820
P116=-73.5000 ;50.6060
P117=-73.7040 ;50.5000
P118=-74.0000 ;50.3110
P119=-74.5000 ;50.0370
P120=-74.5690 ;50.0000
P121=-75.0000 ;49.6900
P122=-75.3040 ;49.5000
P123=-75.5000 ;49.3590
P124=-76.0000 ;49.0260
P125=-76.0370 ;49.0000
P126=-76.5000 ;48.6330
P127=-76.6940 ;48.5000
P128=-77.0000 ;48.2360
P129=-77.2510 ;48.0000
P130=-77.5000 ;47.7890
P131=-77.8730 ;47.5000
P132=-78.0000 ;47.3830
P133=-78.3590 ;47.0000
P134=-78.5000 ;46.8710
P135=-78.9100 ;46.5000
P136=-79.0000 ;46.4070
P137=-79.3110 ;46.0000
P138=-79.5000 ;45.8100
P139=-79.8050 ;45.5000
P140=-80.0000 ;45.2660
P141=-80.1970 ;45.0000
P142=-80.5000 ;44.6330
P143=-80.6550 ;44.5000
P144=-80.9670 ;44.0000
P145=-81.0000 ;43.9530
P146=-81.3750 ;43.5000
P147=-81.5000 ;43.2880
P148=-81.7720 ;43.0000
P149=-81.9350 ;42.5000
P150=-82.0000 ;42.3670

P151=-82.2060 ;42.5000
P152=-82.1980 ;43.0000
P153=-82.0140 ;43.5000
P154=-82.0000 ;43.5260
P155=-81.8140 ;44.0000
P156=-81.5990 ;44.5000
P157=-81.5000 ;44.6500
P158=-81.3190 ;45.0000
P159=-81.0000 ;45.4910
P160=-80.9960 ;45.5000
P161=-80.7660 ;46.0000
P162=-80.5000 ;46.3290
P163=-80.3750 ;46.5000
P164=-80.0140 ;47.0000
P165=-80.0000 ;47.0170
P166=-79.6330 ;47.5000
P167=-79.5000 ;47.6860
P168=-79.2960 ;48.0000
P169=-79.0000 ;48.3340
P170=-78.8420 ;48.5000
P171=-78.5000 ;48.9300
P172=-78.4430 ;49.0000
P173=-78.0000 ;49.4800
P174=-77.9780 ;49.5000
P175=-77.7420 ;50.0000
P176=-78.0000 ;50.2210
P177=-78.5000 ;50.0340
P178=-78.5500 ;50.0000
P179=-79.0000 ;49.7060
P180=-79.3220 ;49.5000
P181=-79.5000 ;49.3610
P182=-79.9380 ;49.0000
P183=-80.0000 ;48.9560
P184=-80.5000 ;48.5410
P185=-80.5450 ;48.5000
P186=-81.0000 ;48.0380
P187=-81.0320 ;48.0000
P188=-81.5000 ;47.5380
P189=-81.5330 ;47.5000
P190=-81.9780 ;47.0000
P191=-82.0000 ;46.9770
P192=-82.3710 ;46.5000
P193=-82.5000 ;46.3620
P194=-82.7840 ;46.0000
P195=-83.0000 ;45.7210
P196=-83.1240 ;45.5000
P197=-83.5000 ;45.0010
P198=-83.5010 ;45.0000
P199=-83.8020 ;44.5000
P200=-84.0000 ;44.1860
P201=-84.0810 ;44.0000
P202=-84.3390 ;43.5000
P203=-84.5000 ;43.2420
P204=-84.6090 ;43.0000
P205=-84.8140 ;42.5000
P206=-85.0000 ;42.0800
P207=-85.0260 ;42.0000

P208=-85.1840 ;41.5000
P209=-85.3360 ;41.0000
P210=-85.4540 ;40.5000
P211=-85.5000 ;40.2780
P212=-85.5440 ;40.0000
P213=-85.6030 ;39.5000
P214=-85.5970 ;39.0000
P215=-85.5790 ;38.5000
P216=-85.5560 ;38.0000
P217=-85.5000 ;37.5730
P218=-85.4840 ;37.5000
P219=-85.3440 ;37.0000
P220=-85.2120 ;36.5000
P221=-85.0790 ;36.0000
P222=-85.0000 ;35.6430
P223=-84.9520 ;35.5000
P224=-84.7450 ;35.0000
P225=-84.5880 ;34.5000
P226=-84.5000 ;34.2930
P227=-84.3740 ;34.0000
P228=-84.2010 ;33.5000
P229=-84.0000 ;33.1410
P230=-83.9270 ;33.0000
P231=-83.7710 ;32.5000
P232=-84.0000 ;32.0980
P233=-84.3110 ;32.5000
P234=-84.5000 ;32.6630
P235=-84.8080 ;33.0000
P236=-85.0000 ;33.2150
P237=-85.2620 ;33.5000
P238=-85.5000 ;33.7830
P239=-85.7340 ;34.0000
P240=-86.0000 ;34.2920
P241=-86.2760 ;34.5000
P242=-86.5000 ;34.7600
P243=-86.8220 ;35.0000
P244=-87.0000 ;35.2290
P245=-87.5000 ;35.3550
P246=-87.5380 ;35.0000
P247=-87.5510 ;34.5000
P248=-87.5450 ;34.0000
P249=-87.5020 ;33.5000
P250=-87.5000 ;33.4860
P251=-87.3890 ;33.0000
P252=-87.2770 ;32.5000
P253=-87.1500 ;32.0000
P254=-87.0000 ;31.5180
P255=-86.9940 ;31.5000
P256=-86.7820 ;31.0000
P257=-86.5610 ;30.5000
P258=-86.5000 ;30.3910
P259=-86.2820 ;30.0000
P260=-86.0000 ;29.5540
P261=-85.9640 ;29.5000
P262=-85.6230 ;29.0000
P263=-85.5000 ;28.8700
P264=-85.1900 ;28.5000

P265=-85.0000 ;28.2660
P266=-84.6930 ;28.0000
P267=-84.5000 ;27.8380
P268=-84.0000 ;27.5250
P269=-83.9640 ;27.5000
P270=-83.5000 ;27.1630
P271=-83.0790 ;27.0000
P272=-83.0000 ;26.9510
P273=-82.5000 ;26.7790
P274=-82.0000 ;26.6430
P275=-81.5000 ;26.5210
P276=-81.3930 ;26.5000
P277=-81.0000 ;26.4330
P278=-80.5000 ;26.4120
P279=-80.0000 ;26.4130
P280=-79.5000 ;26.4230
P281=-79.0000 ;26.4440
P282=-78.5000 ;26.4770
P283=-78.2100 ;26.5000
P284=-78.0000 ;26.5470
P285=-77.5000 ;26.6820
P286=-77.0000 ;26.8200
P287=-76.5000 ;26.9430
P288=-76.2460 ;27.0000
P289=-76.0000 ;27.1240
P290=-75.5000 ;27.3420
P291=-75.0150 ;27.5000
P292=-75.0000 ;27.5120
P293=-74.5000 ;27.8410
P294=-74.1640 ;28.0000
P295=-74.0000 ;28.2010
P296=-73.5960 ;28.5000
P297=-74.0000 ;28.6800
P298=-74.5000 ;28.7180
P299=-75.0000 ;28.7010
P300=-75.5000 ;28.6620
P301=-76.0000 ;28.6210
P302=-76.5000 ;28.5880
P303=-77.0000 ;28.5810
P304=-77.5000 ;28.6130
P305=-78.0000 ;28.6770
P306=-78.5000 ;28.7770
P307=-79.0000 ;28.9230
P308=-79.2070 ;29.0000
P309=-79.0000 ;29.2200
P310=-78.5000 ;29.3630
P311=-78.0000 ;29.4340
P312=-77.5000 ;29.5000
P313=-77.4980 ;29.5000
P314=-77.0000 ;29.5930
P315=-76.5000 ;29.7060
P316=-76.0000 ;29.8130
P317=-75.5000 ;29.9110
P318=-75.0950 ;30.0000
P319=-75.0000 ;30.0390
P320=-74.5000 ;30.2420
P321=-74.0000 ;30.4120

P322=-73.7190 ;30.5000
P323=-73.5000 ;30.6180
P324=-73.0000 ;30.8490
P325=-72.5990 ;31.0000
P326=-72.5000 ;31.0640
P327=-72.0000 ;31.3320
P328=-71.5860 ;31.5000
P329=-71.5000 ;31.5660
P330=-71.0000 ;31.8590
P331=-70.6610 ;32.0000
P332=-70.5000 ;32.1310
P333=-70.0000 ;32.4120
P334=-69.8090 ;32.5000
P335=-69.5000 ;32.7650
P336=-69.0000 ;32.9980
P337=-68.9970 ;33.0000
P338=-68.5000 ;33.3950
P339=-68.2820 ;33.5000
P340=-68.0000 ;33.7520
P341=-67.5000 ;33.9460
P342=-67.3730 ;34.0000
P343=-67.0000 ;34.2790
P344=-66.5000 ;34.4760
P345=-66.4480 ;34.5000
P346=-66.0000 ;34.7910
P347=-65.5080 ;35.0000
P348=-65.5000 ;35.0050
P349=-65.0000 ;35.3730
P350=-64.7840 ;35.5000
P351=-64.5000 ;35.7030
P352=-64.0000 ;35.9870
P353=-63.9780 ;36.0000
P354=-63.5000 ;36.3700
P355=-63.3020 ;36.5000
P356=-63.0000 ;36.7420
P357=-62.6300 ;37.0000
P358=-62.5000 ;37.1030
P359=-62.0000 ;37.4690
P360=-61.9570 ;37.5000
P361=-61.5000 ;37.8750
P362=-61.3210 ;38.0000
P363=-61.0000 ;38.2730
P364=-60.6710 ;38.5000
P365=-60.5000 ;38.6460
P366=-60.0400 ;39.0000
P367=-60.0000 ;39.0340
P368=-59.5000 ;39.4480
P369=-59.4320 ;39.5000
P370=-59.0000 ;39.8680
P371=-58.8260 ;40.0000
P372=-58.5000 ;40.2740
P373=-58.1970 ;40.5000
P374=-58.0000 ;40.6630
P375=-57.5330 ;41.0000
P376=-57.5000 ;41.0270
P377=-57.0000 ;41.4230
P378=-56.8910 ;41.5000

P379=-56.5000 ;41.8150
P380=-56.2320 ;42.0000
P381=-56.0000 ;42.1860
P382=-55.5390 ;42.5000
P383=-55.5000 ;42.5310
P384=-55.0000 ;42.9400
P385=-54.9190 ;43.0000
P386=-54.5000 ;43.3500
P387=-54.2920 ;43.5000
P388=-54.0000 ;43.7400
P389=-53.6220 ;44.0000
P390=-53.5000 ;44.0980
P391=-53.0000 ;44.4430
P392=-52.9200 ;44.5000
P393=-52.5000 ;44.8270
P394=-52.2530 ;45.0000
P395=-52.0000 ;45.2080
P396=-51.5650 ;45.5000
P397=-51.5000 ;45.5520
P398=-51.0000 ;45.9040
P399=-50.8630 ;46.0000
P400=-50.5000 ;46.2990
P401=-50.1930 ;46.5000
P402=-50.0000 ;46.6470
P403=-49.5000 ;46.9730
P404=-49.4580 ;47.0000
P405=-49.0000 ;47.3430
P406=-48.7390 ;47.5000
P407=-48.5000 ;47.6630
P408=-48.0000 ;47.9900
P409=-47.9820 ;48.0000
P410=-47.5000 ;48.3090
P411=-47.1960 ;48.5000
P412=-47.0000 ;48.6350
P413=-46.5000 ;48.9180
P414=-46.3670 ;49.0000
P415=-46.0000 ;49.2340
P416=-45.5000 ;49.4900
P417=-45.4840 ;49.5000
P418=-45.0000 ;49.7840
P419=-44.5480 ;50.0000
P420=-44.5000 ;50.0260
P421=-44.0000 ;50.2850
P422=-43.5530 ;50.5000
P423=-43.5000 ;50.5270
P424=-43.0000 ;50.7140
P425=-42.5000 ;50.9550
P426=-42.3410 ;51.0000
P427=-42.0000 ;51.1010
P428=-41.5000 ;51.2790
P429=-41.0000 ;51.4880
P430=-40.9430 ;51.5000
P431=-40.5000 ;51.5700
P432=-40.0000 ;51.7070
P433=-39.5000 ;51.7370
P434=-39.0000 ;51.5000
P435=-39.5000 ;51.0910

P436=-39.5610 ;51.0000
P437=-40.0000 ;50.7250
P438=-40.3140 ;50.5000
P439=-40.5000 ;50.3910
P440=-41.0000 ;50.0590
P441=-41.0880 ;50.0000
P442=-41.5000 ;49.7860
P443=-41.9420 ;49.5000
P444=-42.0000 ;49.4630
P445=-42.5000 ;49.1810
P446=-42.8300 ;49.0000
P447=-43.0000 ;48.9040
P448=-43.5000 ;48.6160
P449=-43.7330 ;48.5000
P450=-44.0000 ;48.3550
P451=-44.5000 ;48.0540
P452=-44.6070 ;48.0000
P453=-45.0000 ;47.7770
P454=-45.4440 ;47.5000
P455=-45.5000 ;47.4530
P456=-46.0000 ;47.1590
P457=-46.2400 ;47.0000
P458=-46.5000 ;46.7810
P459=-47.0000 ;46.5030
P460=-47.0040 ;46.5000
P461=-47.5000 ;46.1170
P462=-47.6810 ;46.0000
P463=-48.0000 ;45.7520
P464=-48.5000 ;45.5090
P465=-48.5130 ;45.5000
P466=-49.0000 ;45.1060
P467=-49.1910 ;45.0000
P468=-49.5000 ;44.7760
P469=-50.0000 ;44.5150
P470=-50.0230 ;44.5000
P471=-50.5000 ;44.1050
P472=-50.6770 ;44.0000
P473=-51.0000 ;43.7320
P474=-51.4550 ;43.5000
P475=-51.5000 ;43.4630
P476=-52.0000 ;43.0360
P477=-52.0510 ;43.0000
P478=-52.5000 ;42.6000
P479=-52.6510 ;42.5000
P480=-53.0000 ;42.2030
P481=-53.3520 ;42.0000
P482=-53.5000 ;41.8770
P483=-54.0000 ;41.5590
P484=-54.0860 ;41.5000
P485=-54.5000 ;41.1390
P486=-54.7000 ;41.0000
P487=-55.0000 ;40.7010
P488=-55.2700 ;40.5000
P489=-55.5000 ;40.2290
P490=-55.7770 ;40.0000
P491=-55.5000 ;39.7130
P492=-55.0000 ;39.9540

P493=-54.9210 ;40.0000
P494=-54.5000 ;40.3190
P495=-54.1650 ;40.5000
P496=-54.0000 ;40.6340
P497=-53.5000 ;40.9400
P498=-53.3910 ;41.0000
P499=-53.0000 ;41.3060
P500=-52.6320 ;41.5000
P501=-52.5000 ;41.6090
P502=-52.0000 ;41.9210
P503=-51.8780 ;42.0000
P504=-51.5000 ;42.3180
P505=-51.1950 ;42.5000
P506=-51.0000 ;42.6550
P507=-50.5000 ;42.9330
P508=-50.3760 ;43.0000
P509=-50.0000 ;43.2420
P510=-49.5440 ;43.5000
P511=-49.5000 ;43.5370
P512=-49.0000 ;43.8530
P513=-48.6810 ;44.0000
P514=-48.5000 ;44.1140
P515=-48.0000 ;44.4340
P516=-47.8650 ;44.5000
P517=-47.5000 ;44.7460
P518=-47.0000 ;44.9980
P519=-46.9970 ;45.0000
P520=-46.5000 ;45.3480
P521=-46.1390 ;45.5000
P522=-46.0000 ;45.5800
P523=-45.5000 ;45.8970
P524=-45.2300 ;46.0000
P525=-45.0000 ;46.1170
P526=-44.5000 ;46.4070
P527=-44.2440 ;46.5000
P528=-44.0000 ;46.6190
P529=-43.5000 ;46.8910
P530=-43.1570 ;47.0000
P531=-43.0000 ;47.0730
P532=-42.5000 ;47.3530
P533=-42.0390 ;47.5000
P534=-42.0000 ;47.5190
P535=-41.5000 ;47.8010
P536=-41.0000 ;47.9780
P537=-40.9370 ;48.0000
P538=-40.5000 ;48.2210
P539=-40.0000 ;48.4310
P540=-39.7560 ;48.5000
P541=-39.5000 ;48.6140
P542=-39.0000 ;48.8520
P543=-38.5420 ;49.0000
P544=-38.5000 ;49.0220
P545=-38.0000 ;49.2210
P546=-37.5000 ;49.4230
P547=-37.2390 ;49.5000
P548=-37.0000 ;49.6070
P549=-36.5000 ;49.7680

P550=-36.0000 ;49.9390
P551=-35.7800 ;50.0000
P552=-35.5000 ;50.1160
P553=-35.0000 ;50.2650
P554=-34.5000 ;50.4000
P555=-34.1280 ;50.5000
P556=-34.0000 ;50.5520
P557=-33.5000 ;50.7100
P558=-33.0000 ;50.8230
P559=-32.5000 ;50.9360
P560=-32.2190 ;51.0000
P561=-32.0000 ;51.0760
P562=-31.5000 ;51.2130
P563=-31.0000 ;51.3130
P564=-30.5000 ;51.3980
P565=-30.0000 ;51.4930
P566=-29.9600 ;51.5000
P567=-29.5000 ;51.6270
P568=-29.0000 ;51.7330
P569=-28.5000 ;51.8160
P570=-28.0000 ;51.8830
P571=-27.5000 ;51.9450
P572=-27.1260 ;52.0000
P573=-27.0000 ;52.0300
P574=-26.5000 ;52.1300
P575=-26.0000 ;52.2120
P576=-25.5350 ;52.2730

[C2]

gain=-50.00

n_point=139

P1=-64.5000 ;58.7360
P2=-65.0000 ;58.7490
P3=-65.5000 ;58.7150
P4=-66.0000 ;58.6520
P5=-66.5000 ;58.5470
P6=-66.6760 ;58.5000
P7=-67.0000 ;58.4430
P8=-67.5000 ;58.3730
P9=-68.0000 ;58.3050
P10=-68.5000 ;58.2220
P11=-69.0000 ;58.1090
P12=-69.3470 ;58.0000
P13=-69.5000 ;57.9700
P14=-70.0000 ;57.8640
P15=-70.5000 ;57.7230
P16=-70.9940 ;57.5000
P17=-71.0000 ;57.4990
P18=-71.5000 ;57.3810
P19=-72.0000 ;57.1940
P20=-72.3090 ;57.0000
P21=-72.5000 ;56.9300
P22=-73.0000 ;56.6710
P23=-73.2130 ;56.5000
P24=-73.5000 ;56.3850
P25=-74.0000 ;56.0960
P26=-74.1230 ;56.0000
P27=-74.5000 ;55.8180

P28=-74.9090 ;55.5000
P29=-75.0000 ;55.4540
P30=-75.5000 ;55.0820
P31=-75.5910 ;55.0000
P32=-76.0000 ;54.7930
P33=-76.3480 ;54.5000
P34=-76.5000 ;54.4220
P35=-77.0000 ;54.0030
P36=-77.0030 ;54.0000
P37=-77.5000 ;53.6370
P38=-77.6450 ;53.5000
P39=-78.0000 ;53.2050
P40=-78.2120 ;53.0000
P41=-78.5000 ;52.7640
P42=-78.7640 ;52.5000
P43=-79.0000 ;52.2680
P44=-79.2690 ;52.0000
P45=-79.5000 ;51.7540
P46=-79.7240 ;51.5000
P47=-80.0000 ;51.2190
P48=-80.2110 ;51.0000
P49=-80.5000 ;50.6560
P50=-80.6370 ;50.5000
P51=-81.0000 ;50.1140
P52=-81.1050 ;50.0000
P53=-81.5000 ;49.5100
P54=-81.5080 ;49.5000
P55=-81.9020 ;49.0000
P56=-82.0000 ;48.9480
P57=-82.3360 ;48.5000
P58=-82.5000 ;48.2430
P59=-82.6870 ;48.0000
P60=-83.0000 ;47.7220
P61=-83.1700 ;47.5000
P62=-83.4310 ;47.0000
P63=-83.5000 ;46.8720
P64=-83.7140 ;46.5000
P65=-84.0000 ;46.2940
P66=-84.2040 ;46.0000
P67=-84.3580 ;45.5000
P68=-84.5000 ;45.2010
P69=-84.5950 ;45.0000
P70=-84.5000 ;44.6860
P71=-84.3760 ;45.0000
P72=-84.0000 ;45.2240
P73=-83.8110 ;45.5000
P74=-83.6270 ;46.0000
P75=-83.5000 ;46.1970
P76=-83.3090 ;46.5000
P77=-83.0000 ;46.7130
P78=-82.7810 ;47.0000
P79=-82.5000 ;47.4780
P80=-82.4810 ;47.5000
P81=-82.0930 ;48.0000
P82=-82.0000 ;48.0480
P83=-81.6740 ;48.5000
P84=-81.5000 ;48.7640

P85=-81.2750 ;49.0000
P86=-81.0000 ;49.2100
P87=-80.7290 ;49.5000
P88=-80.5000 ;49.7770
P89=-80.2470 ;50.0000
P90=-80.0000 ;50.1670
P91=-79.6450 ;50.5000
P92=-79.5000 ;50.6590
P93=-79.0230 ;51.0000
P94=-79.0000 ;51.0140
P95=-78.5000 ;51.4000
P96=-78.3710 ;51.5000
P97=-78.0000 ;51.7300
P98=-77.6580 ;52.0000
P99=-77.5000 ;52.1150
P100=-77.0000 ;52.4410
P101=-76.9160 ;52.5000
P102=-76.5000 ;52.7440
P103=-76.1360 ;53.0000
P104=-76.0000 ;53.0670
P105=-75.5000 ;53.3520
P106=-75.2630 ;53.5000
P107=-75.0000 ;53.6260
P108=-74.5000 ;53.9250
P109=-74.3700 ;54.0000
P110=-74.0000 ;54.1720
P111=-73.5000 ;54.4640
P112=-73.4330 ;54.5000
P113=-73.0000 ;54.6690
P114=-72.5000 ;54.9060
P115=-72.3090 ;55.0000
P116=-72.0000 ;55.1310
P117=-71.5000 ;55.3480
P118=-71.1910 ;55.5000
P119=-71.0000 ;55.5760
P120=-70.5000 ;55.7800
P121=-70.0270 ;56.0000
P122=-70.0000 ;56.0130
P123=-69.5000 ;56.2170
P124=-69.0000 ;56.4190
P125=-68.8240 ;56.5000
P126=-68.5000 ;56.6390
P127=-68.0000 ;56.8380
P128=-67.6360 ;57.0000
P129=-67.5000 ;57.0820
P130=-67.0000 ;57.2970
P131=-66.5000 ;57.4760
P132=-66.4430 ;57.5000
P133=-66.0000 ;57.7260
P134=-65.5000 ;57.9020
P135=-65.2260 ;58.0000
P136=-65.0000 ;58.2320
P137=-64.5000 ;58.4370
P138=-64.3160 ;58.5000
P139=-64.5000 ;58.7360
[C3]
gain=-50.00

n_point=105
P1=-55.5000 ;38.1550
P2=-55.9650 ;38.0000
P3=-56.0000 ;37.9770
P4=-56.5000 ;37.6480
P5=-56.7240 ;37.5000
P6=-57.0000 ;37.3020
P7=-57.5000 ;37.0360
P8=-57.5460 ;37.0000
P9=-58.0000 ;36.7010
P10=-58.2520 ;36.5000
P11=-58.5000 ;36.2980
P12=-58.8840 ;36.0000
P13=-59.0000 ;35.9420
P14=-59.5000 ;35.5550
P15=-59.5660 ;35.5000
P16=-60.0000 ;35.1860
P17=-60.2200 ;35.0000
P18=-60.5000 ;34.8530
P19=-60.9230 ;34.5000
P20=-61.0000 ;34.4310
P21=-61.5000 ;34.0500
P22=-61.5620 ;34.0000
P23=-62.0000 ;33.6830
P24=-62.2180 ;33.5000
P25=-62.5000 ;33.3290
P26=-62.9090 ;33.0000
P27=-63.0000 ;32.9350
P28=-63.5000 ;32.6060
P29=-63.6440 ;32.5000
P30=-64.0000 ;32.2970
P31=-64.4110 ;32.0000
P32=-64.5000 ;31.9520
P33=-65.0000 ;31.6810
P34=-65.2630 ;31.5000
P35=-65.5000 ;31.3920
P36=-66.0000 ;31.1150
P37=-66.1840 ;31.0000
P38=-66.5000 ;30.8760
P39=-67.0000 ;30.5710
P40=-67.1100 ;30.5000
P41=-67.5000 ;30.3440
P42=-67.9790 ;30.0000
P43=-68.0000 ;29.9870
P44=-68.5000 ;29.7020
P45=-68.7670 ;29.5000
P46=-69.0000 ;29.3240
P47=-69.4530 ;29.0000
P48=-69.5000 ;28.9410
P49=-70.0000 ;28.5810
P50=-70.1250 ;28.5000
P51=-70.5000 ;28.1160
P52=-70.7400 ;28.0000
P53=-70.5000 ;27.8180
P54=-70.0000 ;27.8250
P55=-69.5000 ;27.9890
P56=-69.4810 ;28.0000

P57=-69.0000 ;28.1490
P58=-68.5000 ;28.3680
P59=-68.3050 ;28.5000
P60=-68.0000 ;28.6000
P61=-67.5000 ;28.8470
P62=-67.2670 ;29.0000
P63=-67.0000 ;29.1070
P64=-66.5000 ;29.3970
P65=-66.3420 ;29.5000
P66=-66.0000 ;29.6350
P67=-65.5000 ;29.9410
P68=-65.4100 ;30.0000
P69=-65.0000 ;30.1420
P70=-64.5000 ;30.4210
P71=-64.3780 ;30.5000
P72=-64.0000 ;30.6550
P73=-63.5630 ;31.0000
P74=-63.5000 ;31.0300
P75=-63.0000 ;31.3750
P76=-62.8930 ;31.5000
P77=-62.5000 ;31.8010
P78=-62.3230 ;32.0000
P79=-62.0000 ;32.2050
P80=-61.6860 ;32.5000
P81=-61.5000 ;32.6080
P82=-61.0800 ;33.0000
P83=-61.0000 ;33.0780
P84=-60.5800 ;33.5000
P85=-60.5000 ;33.5450
P86=-60.0190 ;34.0000
P87=-60.0000 ;34.0250
P88=-59.5000 ;34.4270
P89=-59.4240 ;34.5000
P90=-59.0000 ;34.7970
P91=-58.7800 ;35.0000
P92=-58.5000 ;35.2360
P93=-58.2060 ;35.5000
P94=-58.0000 ;35.6390
P95=-57.6120 ;36.0000
P96=-57.5000 ;36.1180
P97=-57.0520 ;36.5000
P98=-57.0000 ;36.5870
P99=-56.5000 ;36.9430
P100=-56.4350 ;37.0000
P101=-56.0000 ;37.3700
P102=-55.8470 ;37.5000
P103=-55.5000 ;37.8910
P104=-55.3580 ;38.0000
P105=-55.5000 ;38.1550
[C4]
gain=-2.00
n_point=86
P1=-69.0000 ;43.6110
P2=-68.9350 ;43.5000
P3=-68.9197 ;43.3333
P4=-68.9043 ;43.1667
P5=-68.8890 ;43.0000

P6=-68.9260 ;42.8407
P7=-68.9630 ;42.6813
P8=-69.0000 ;42.5220
P9=-69.0060 ;42.5000
P10=-69.0993 ;42.3333
P11=-69.1927 ;42.1667
P12=-69.2860 ;42.0000
P13=-69.3930 ;41.8635
P14=-69.5000 ;41.7270
P15=-69.5950 ;41.6135
P16=-69.6900 ;41.5000
P17=-69.7933 ;41.3990
P18=-69.8967 ;41.2980
P19=-70.0000 ;41.1970
P20=-70.1095 ;41.0985
P21=-70.2190 ;41.0000
P22=-70.3595 ;40.8995
P23=-70.5000 ;40.7990
P24=-70.6557 ;40.6993
P25=-70.8113 ;40.5997
P26=-70.9670 ;40.5000
P27=-71.0000 ;40.4820
P28=-71.1667 ;40.4117
P29=-71.3333 ;40.3413
P30=-71.5000 ;40.2710
P31=-71.6667 ;40.2187
P32=-71.8333 ;40.1663
P33=-72.0000 ;40.1140
P34=-72.1667 ;40.0877
P35=-72.3333 ;40.0613
P36=-72.5000 ;40.0350
P37=-72.6667 ;40.0480
P38=-72.8333 ;40.0610
P39=-73.0000 ;40.0740
P40=-73.1667 ;40.1387
P41=-73.3333 ;40.2033
P42=-73.5000 ;40.2680
P43=-73.6535 ;40.3840
P44=-73.8070 ;40.5000
P45=-73.9035 ;40.6680
P46=-74.0000 ;40.8360
P47=-74.0590 ;41.0000
P48=-74.0623 ;41.1667
P49=-74.0657 ;41.3333
P50=-74.0690 ;41.5000
P51=-74.0345 ;41.6110
P52=-74.0000 ;41.7220
P53=-73.9500 ;41.8610
P54=-73.9000 ;42.0000
P55=-73.8050 ;42.1667
P56=-73.7100 ;42.3333
P57=-73.6150 ;42.5000
P58=-73.5000 ;42.6390
P59=-73.3850 ;42.7593
P60=-73.2700 ;42.8797
P61=-73.1550 ;43.0000
P62=-73.0000 ;43.1380

P63=-72.8450 ;43.2587
P64=-72.6900 ;43.3793
P65=-72.5350 ;43.5000
P66=-72.5000 ;43.5220
P67=-72.3333 ;43.6087
P68=-72.1667 ;43.6953
P69=-72.0000 ;43.7820
P70=-71.8333 ;43.8540
P71=-71.6667 ;43.9260
P72=-71.5000 ;43.9980
P73=-71.4940 ;44.0000
P74=-71.2470 ;44.0600
P75=-71.0000 ;44.1200
P76=-70.7500 ;44.1510
P77=-70.5000 ;44.1820
P78=-70.2500 ;44.1740
P79=-70.0000 ;44.1660
P80=-69.8333 ;44.1267
P81=-69.6667 ;44.0873
P82=-69.5000 ;44.0480
P83=-69.4000 ;44.0000
P84=-69.2667 ;43.8703
P85=-69.1333 ;43.7407
P86=-69.0000 ;43.6110
[C5]
gain=-4.00
n_point=92
P1=-68.0000 ;44.4540
P2=-67.8780 ;44.2270
P3=-67.7560 ;44.0000
P4=-67.7355 ;43.7500
P5=-67.7150 ;43.5000
P6=-67.7680 ;43.2500
P7=-67.8210 ;43.0000
P8=-67.9105 ;42.7730
P9=-68.0000 ;42.5460
P10=-68.0190 ;42.5000
P11=-68.1223 ;42.3333
P12=-68.2257 ;42.1667
P13=-68.3290 ;42.0000
P14=-68.5000 ;41.7790
P15=-68.6125 ;41.6395
P16=-68.7250 ;41.5000
P17=-68.8625 ;41.3510
P18=-69.0000 ;41.2020
P19=-69.1960 ;41.0000
P20=-69.3480 ;40.8665
P21=-69.5000 ;40.7330
P22=-69.6405 ;40.6165
P23=-69.7810 ;40.5000
P24=-70.0000 ;40.3420
P25=-70.2500 ;40.1725
P26=-70.5000 ;40.0030
P27=-70.5050 ;40.0000
P28=-70.7525 ;39.8745
P29=-71.0000 ;39.7490
P30=-71.2500 ;39.6380

P31=-71.5000 ;39.5270
P32=-71.5840 ;39.5000
P33=-71.7920 ;39.4425
P34=-72.0000 ;39.3850
P35=-72.2500 ;39.3415
P36=-72.5000 ;39.2980
P37=-72.7500 ;39.2865
P38=-73.0000 ;39.2750
P39=-73.2500 ;39.3020
P40=-73.5000 ;39.3290
P41=-73.7500 ;39.4010
P42=-74.0000 ;39.4730
P43=-74.0590 ;39.5000
P44=-74.2795 ;39.6525
P45=-74.5000 ;39.8050
P46=-74.6900 ;40.0000
P47=-74.7833 ;40.1667
P48=-74.8767 ;40.3333
P49=-74.9700 ;40.5000
P50=-75.0000 ;40.7350
P51=-75.0125 ;40.8675
P52=-75.0250 ;41.0000
P53=-75.0000 ;41.2380
P54=-74.9690 ;41.5000
P55=-74.8760 ;41.7500
P56=-74.7830 ;42.0000
P57=-74.6987 ;42.1667
P58=-74.6143 ;42.3333
P59=-74.5300 ;42.5000
P60=-74.5000 ;42.5430
P61=-74.3235 ;42.7715
P62=-74.1470 ;43.0000
P63=-74.0000 ;43.1640
P64=-73.8330 ;43.3320
P65=-73.6660 ;43.5000
P66=-73.5000 ;43.6440
P67=-73.2725 ;43.8220
P68=-73.0450 ;44.0000
P69=-73.0000 ;44.0310
P70=-72.7500 ;44.1805
P71=-72.5000 ;44.3300
P72=-72.3385 ;44.4150
P73=-72.1770 ;44.5000
P74=-72.0000 ;44.5840
P75=-71.7500 ;44.6810
P76=-71.5000 ;44.7780
P77=-71.2500 ;44.8565
P78=-71.0000 ;44.9350
P79=-70.7010 ;45.0000
P80=-70.5000 ;45.0370
P81=-70.2500 ;45.0595
P82=-70.0000 ;45.0820
P83=-69.7500 ;45.0795
P84=-69.5000 ;45.0770
P85=-69.2500 ;45.0445
P86=-69.0000 ;45.0120
P87=-68.9530 ;45.0000

P88=-68.7265 ;44.9125
P89=-68.5000 ;44.8250
P90=-68.2680 ;44.6625
P91=-68.0360 ;44.5000
P92=-68.0000 ;44.4540
[C6]
gain=-6.00
n_point=105
P1=-67.0000 ;44.7390
P2=-66.8810 ;44.5000
P3=-66.8420 ;44.2500
P4=-66.8030 ;44.0000
P5=-66.8395 ;43.7500
P6=-66.8760 ;43.5000
P7=-66.9380 ;43.3115
P8=-67.0000 ;43.1230
P9=-67.0420 ;43.0000
P10=-67.1680 ;42.7500
P11=-67.2940 ;42.5000
P12=-67.3970 ;42.3390
P13=-67.5000 ;42.1780
P14=-67.6160 ;42.0000
P15=-67.8080 ;41.7540
P16=-68.0000 ;41.5080
P17=-68.0060 ;41.5000
P18=-68.2350 ;41.2500
P19=-68.4640 ;41.0000
P20=-68.5000 ;40.9650
P21=-68.7480 ;40.7325
P22=-68.9960 ;40.5000
P23=-69.0000 ;40.4970
P24=-69.2500 ;40.3010
P25=-69.5000 ;40.1050
P26=-69.6400 ;40.0000
P27=-69.8200 ;39.8785
P28=-70.0000 ;39.7570
P29=-70.2025 ;39.6285
P30=-70.4050 ;39.5000
P31=-70.5000 ;39.4490
P32=-70.7500 ;39.3290
P33=-71.0000 ;39.2090
P34=-71.2425 ;39.1045
P35=-71.4850 ;39.0000
P36=-71.5000 ;38.9940
P37=-71.7500 ;38.9240
P38=-72.0000 ;38.8540
P39=-72.2500 ;38.8045
P40=-72.5000 ;38.7550
P41=-72.7500 ;38.7340
P42=-73.0000 ;38.7130
P43=-73.2500 ;38.7230
P44=-73.5000 ;38.7330
P45=-73.7500 ;38.7785
P46=-74.0000 ;38.8240
P47=-74.2500 ;38.9085
P48=-74.5000 ;38.9930
P49=-74.5150 ;39.0000

P50=-74.7575 ;39.1605
P51=-75.0000 ;39.3210
P52=-75.1990 ;39.5000
P53=-75.3495 ;39.7155
P54=-75.5000 ;39.9310
P55=-75.5370 ;40.0000
P56=-75.6035 ;40.2500
P57=-75.6700 ;40.5000
P58=-75.6760 ;40.7500
P59=-75.6820 ;41.0000
P60=-75.6415 ;41.2500
P61=-75.6010 ;41.5000
P62=-75.5505 ;41.6575
P63=-75.5000 ;41.8150
P64=-75.4320 ;42.0000
P65=-75.3020 ;42.2500
P66=-75.1720 ;42.5000
P67=-75.0000 ;42.7700
P68=-74.8360 ;43.0000
P69=-74.6680 ;43.2035
P70=-74.5000 ;43.4070
P71=-74.4160 ;43.5000
P72=-74.2080 ;43.7020
P73=-74.0000 ;43.9040
P74=-73.8910 ;44.0000
P75=-73.6955 ;44.1530
P76=-73.5000 ;44.3060
P77=-73.2290 ;44.5000
P78=-73.0000 ;44.6510
P79=-72.7500 ;44.7990
P80=-72.5000 ;44.9470
P81=-72.3960 ;45.0000
P82=-72.1980 ;45.0890
P83=-72.0000 ;45.1780
P84=-71.7500 ;45.2755
P85=-71.5000 ;45.3730
P86=-71.1080 ;45.5000
P87=-71.0000 ;45.5320
P88=-70.7500 ;45.5855
P89=-70.5000 ;45.6390
P90=-70.2500 ;45.6745
P91=-70.0000 ;45.7100
P92=-69.7500 ;45.7250
P93=-69.5000 ;45.7400
P94=-69.2500 ;45.7335
P95=-69.0000 ;45.7270
P96=-68.7500 ;45.6950
P97=-68.5000 ;45.6630
P98=-68.2500 ;45.6005
P99=-68.0000 ;45.5380
P100=-67.9020 ;45.5000
P101=-67.7010 ;45.3855
P102=-67.5000 ;45.2710
P103=-67.3375 ;45.1355
P104=-67.1750 ;45.0000
P105=-67.0000 ;44.7390

[C7]

gain=-10.00
n_point=111
P1=-65.5000 ;45.2240
P2=-65.4220 ;45.0000
P3=-65.4040 ;44.7500
P4=-65.3860 ;44.5000
P5=-65.4285 ;44.2500
P6=-65.4710 ;44.0000
P7=-65.5000 ;43.9160
P8=-65.5740 ;43.7080
P9=-65.6480 ;43.5000
P10=-65.7660 ;43.2500
P11=-65.8840 ;43.0000
P12=-66.0000 ;42.8020
P13=-66.1790 ;42.5000
P14=-66.3395 ;42.2725
P15=-66.5000 ;42.0450
P16=-66.5320 ;42.0000
P17=-66.7360 ;41.7500
P18=-66.9400 ;41.5000
P19=-67.0000 ;41.4330
P20=-67.1960 ;41.2165
P21=-67.3920 ;41.0000
P22=-67.5000 ;40.8930
P23=-67.6990 ;40.6965
P24=-67.8980 ;40.5000
P25=-68.0000 ;40.4100
P26=-68.2335 ;40.2050
P27=-68.4670 ;40.0000
P28=-68.5000 ;39.9740
P29=-68.7500 ;39.7790
P30=-69.0000 ;39.5840
P31=-69.1110 ;39.5000
P32=-69.5000 ;39.2420
P33=-69.8740 ;39.0000
P34=-70.0000 ;38.9260
P35=-70.2500 ;38.7905
P36=-70.5000 ;38.6550
P37=-70.8060 ;38.5000
P38=-71.0000 ;38.4160
P39=-71.2500 ;38.3230
P40=-71.5000 ;38.2300
P41=-71.7500 ;38.1515
P42=-72.0000 ;38.0730
P43=-72.3170 ;38.0000
P44=-72.5000 ;37.9640
P45=-73.0000 ;37.9090
P46=-73.5000 ;37.8980
P47=-74.0000 ;37.9380
P48=-74.3260 ;38.0000
P49=-74.5000 ;38.0440
P50=-74.7500 ;38.1385
P51=-75.0000 ;38.2330
P52=-75.2500 ;38.3590
P53=-75.5000 ;38.4850
P54=-75.5240 ;38.5000
P55=-75.7620 ;38.7045

P56=-76.0000 ;38.9090
P57=-76.0870 ;39.0000
P58=-76.2550 ;39.2500
P59=-76.4230 ;39.5000
P60=-76.5000 ;39.6880
P61=-76.6010 ;40.0000
P62=-76.6265 ;40.2500
P63=-76.6520 ;40.5000
P64=-76.6430 ;40.7500
P65=-76.6340 ;41.0000
P66=-76.5825 ;41.2500
P67=-76.5310 ;41.5000
P68=-76.5000 ;41.6020
P69=-76.4295 ;41.8010
P70=-76.3590 ;42.0000
P71=-76.2370 ;42.2500
P72=-76.1150 ;42.5000
P73=-76.0000 ;42.7080
P74=-75.8170 ;43.0000
P75=-75.6585 ;43.2190
P76=-75.5000 ;43.4380
P77=-75.4510 ;43.5000
P78=-75.2365 ;43.7500
P79=-75.0220 ;44.0000
P80=-75.0000 ;44.0220
P81=-74.7500 ;44.2610
P82=-74.5000 ;44.5000
P83=-74.2500 ;44.7080
P84=-74.0000 ;44.9160
P85=-73.8900 ;45.0000
P86=-73.5000 ;45.2670
P87=-73.1370 ;45.5000
P88=-73.0000 ;45.5830
P89=-72.7500 ;45.7180
P90=-72.5000 ;45.8530
P91=-72.2000 ;46.0000
P92=-72.0000 ;46.0900
P93=-71.5000 ;46.2850
P94=-71.0000 ;46.4540
P95=-70.8310 ;46.5000
P96=-70.5000 ;46.5800
P97=-70.0000 ;46.6680
P98=-69.5000 ;46.7250
P99=-69.0000 ;46.7500
P100=-68.5000 ;46.7400
P101=-68.0000 ;46.6900
P102=-67.5000 ;46.5980
P103=-67.1210 ;46.5000
P104=-67.0000 ;46.4600
P105=-66.7500 ;46.3515
P106=-66.5000 ;46.2430
P107=-66.0750 ;46.0000
P108=-66.0000 ;45.9330
P109=-65.8105 ;45.7165
P110=-65.6210 ;45.5000
P111=-65.5000 ;45.2240

[C8]

gain=-20.00
n_point=119
P1=-63.0000 ;46.4510
P2=-62.7870 ;46.0000
P3=-62.7140 ;45.5000
P4=-62.7500 ;45.0000
P5=-62.8790 ;44.5000
P6=-63.0000 ;44.2320
P7=-63.0900 ;44.0000
P8=-63.3620 ;43.5000
P9=-63.5000 ;43.3030
P10=-63.6910 ;43.0000
P11=-64.0000 ;42.5990
P12=-64.0690 ;42.5000
P13=-64.2835 ;42.2500
P14=-64.4980 ;42.0000
P15=-64.5000 ;41.9980
P16=-64.7330 ;41.7490
P17=-64.9660 ;41.5000
P18=-65.0000 ;41.4710
P19=-65.2450 ;41.2355
P20=-65.4900 ;41.0000
P21=-65.5000 ;40.9910
P22=-65.7500 ;40.7630
P23=-66.0000 ;40.5350
P24=-66.0360 ;40.5000
P25=-66.5000 ;40.1030
P26=-66.6160 ;40.0000
P27=-67.0000 ;39.7010
P28=-67.2430 ;39.5000
P29=-67.5000 ;39.3160
P30=-67.9160 ;39.0000
P31=-68.0000 ;38.9440
P32=-68.5000 ;38.6020
P33=-68.6440 ;38.5000
P34=-69.0000 ;38.2820
P35=-69.4300 ;38.0000
P36=-69.5000 ;37.9620
P37=-70.0000 ;37.6930
P38=-70.3500 ;37.5000
P39=-70.5000 ;37.4280
P40=-71.0000 ;37.2070
P41=-71.4950 ;37.0000
P42=-71.5000 ;36.9980
P43=-72.0000 ;36.8460
P44=-72.5000 ;36.7240
P45=-73.0000 ;36.6430
P46=-73.5000 ;36.6040
P47=-74.0000 ;36.6050
P48=-74.5000 ;36.6430
P49=-75.0000 ;36.7230
P50=-75.5000 ;36.8840
P51=-75.6810 ;37.0000
P52=-76.0000 ;37.1420
P53=-76.5000 ;37.4870
P54=-76.5120 ;37.5000
P55=-76.7560 ;37.7065

P56=-77.0000 ;37.9130
P57=-77.0710 ;38.0000
P58=-77.2745 ;38.2500
P59=-77.4780 ;38.5000
P60=-77.5000 ;38.5320
P61=-77.7480 ;39.0000
P62=-77.9610 ;39.5000
P63=-78.0000 ;39.6950
P64=-78.0500 ;40.0000
P65=-78.0750 ;40.5000
P66=-78.0340 ;41.0000
P67=-78.0000 ;41.1530
P68=-77.9190 ;41.5000
P69=-77.7540 ;42.0000
P70=-77.5330 ;42.5000
P71=-77.5000 ;42.5610
P72=-77.2550 ;43.0000
P73=-77.0000 ;43.3970
P74=-76.9280 ;43.5000
P75=-76.7470 ;43.7500
P76=-76.5660 ;44.0000
P77=-76.5000 ;44.0790
P78=-76.1280 ;44.5000
P79=-76.0000 ;44.6450
P80=-75.6670 ;45.0000
P81=-75.5000 ;45.1630
P82=-75.1350 ;45.5000
P83=-75.0000 ;45.6230
P84=-74.5630 ;46.0000
P85=-74.5000 ;46.0520
P86=-74.0000 ;46.4340
P87=-73.9080 ;46.5000
P88=-73.5000 ;46.7750
P89=-73.1510 ;47.0000
P90=-73.0000 ;47.0980
P91=-72.5000 ;47.3880
P92=-72.2850 ;47.5000
P93=-72.0000 ;47.6480
P94=-71.5000 ;47.8780
P95=-71.1940 ;48.0000
P96=-71.0000 ;48.0810
P97=-70.5000 ;48.2480
P98=-70.0000 ;48.3790
P99=-69.5000 ;48.4720
P100=-69.2200 ;48.5000
P101=-69.0000 ;48.5260
P102=-68.5000 ;48.5340
P103=-68.1170 ;48.5000
P104=-68.0000 ;48.4920
P105=-67.5000 ;48.4150
P106=-67.0000 ;48.3020
P107=-66.5000 ;48.1630
P108=-66.0000 ;48.0060
P109=-65.9830 ;48.0000
P110=-65.5000 ;47.8250
P111=-65.0000 ;47.6480
P112=-64.5340 ;47.5000

P113=-64.5000 ;47.4840
P114=-64.0000 ;47.2400
P115=-63.5450 ;47.0000
P116=-63.5000 ;46.9610
P117=-63.2625 ;46.7305
P118=-63.0250 ;46.5000
P119=-63.0000 ;46.4510
[C9]
gain=-30.00
n_point=191
P1=-56.5000 ;51.5930
P2=-56.4490 ;51.5000
P3=-56.3620 ;51.0000
P4=-56.3950 ;50.5000
P5=-56.4760 ;50.0000
P6=-56.5000 ;49.8110
P7=-56.5410 ;49.5000
P8=-56.5590 ;49.0000
P9=-56.5720 ;48.5000
P10=-56.6280 ;48.0000
P11=-56.7470 ;47.5000
P12=-56.9340 ;47.0000
P13=-57.0000 ;46.8730
P14=-57.1910 ;46.5000
P15=-57.4730 ;46.0000
P16=-57.5000 ;45.9620
P17=-57.8130 ;45.5000
P18=-58.0000 ;45.2520
P19=-58.1880 ;45.0000
P20=-58.5000 ;44.6120
P21=-58.5890 ;44.5000
P22=-59.0000 ;44.0220
P23=-59.0190 ;44.0000
P24=-59.4810 ;43.5000
P25=-59.5000 ;43.4810
P26=-59.9660 ;43.0000
P27=-60.0000 ;42.9680
P28=-60.4690 ;42.5000
P29=-60.5000 ;42.4710
P30=-60.9900 ;42.0000
P31=-61.0000 ;41.9910
P32=-61.5000 ;41.5370
P33=-61.5400 ;41.5000
P34=-62.0000 ;41.1050
P35=-62.1200 ;41.0000
P36=-62.5000 ;40.6870
P37=-62.7210 ;40.5000
P38=-63.0000 ;40.2760
P39=-63.3340 ;40.0000
P40=-63.5000 ;39.8690
P41=-63.9540 ;39.5000
P42=-64.0000 ;39.4680
P43=-64.5000 ;39.1300
P44=-64.6930 ;39.0000
P45=-65.0000 ;38.8160
P46=-65.5000 ;38.5010
P47=-65.5030 ;38.5000

P48=-66.0000 ;38.2950
P49=-66.5000 ;38.1530
P50=-67.0000 ;38.2140
P51=-67.5000 ;38.2130
P52=-68.0000 ;38.0850
P53=-68.1440 ;38.0000
P54=-68.5000 ;37.8300
P55=-69.0000 ;37.5760
P56=-69.1200 ;37.5000
P57=-69.5000 ;37.3270
P58=-69.9910 ;37.0000
P59=-70.0000 ;36.9940
P60=-70.5000 ;36.7060
P61=-70.8690 ;36.5000
P62=-71.0000 ;36.3180
P63=-71.4130 ;36.0000
P64=-71.3890 ;35.5000
P65=-71.4870 ;35.0000
P66=-71.5000 ;34.9890
P67=-71.9960 ;34.5000
P68=-72.0000 ;34.4980
P69=-72.5000 ;34.2210
P70=-72.8620 ;34.0000
P71=-73.0000 ;33.9490
P72=-73.5000 ;33.7650
P73=-74.0000 ;33.5770
P74=-74.2160 ;33.5000
P75=-74.5000 ;33.4460
P76=-75.0000 ;33.3510
P77=-75.5000 ;33.2590
P78=-76.0000 ;33.1760
P79=-76.5000 ;33.1180
P80=-77.0000 ;33.0930
P81=-77.5000 ;33.1140
P82=-78.0000 ;33.2040
P83=-78.5000 ;33.4410
P84=-78.5590 ;33.5000
P85=-79.0000 ;33.7980
P86=-79.1970 ;34.0000
P87=-79.5000 ;34.3150
P88=-79.6250 ;34.5000
P89=-79.9590 ;35.0000
P90=-80.0000 ;35.0730
P91=-80.1990 ;35.5000
P92=-80.4700 ;36.0000
P93=-80.5000 ;36.0690
P94=-80.6670 ;36.5000
P95=-80.9230 ;37.0000
P96=-81.0000 ;37.1450
P97=-81.1520 ;37.5000
P98=-81.4370 ;38.0000
P99=-81.5000 ;38.1500
P100=-81.5900 ;38.5000
P101=-81.7080 ;39.0000
P102=-81.7490 ;39.5000
P103=-81.7440 ;40.0000
P104=-81.6940 ;40.5000

P105=-81.5810 ;41.0000
P106=-81.5000 ;41.3210
P107=-81.4350 ;41.5000
P108=-81.2130 ;42.0000
P109=-81.0000 ;42.4820
P110=-80.9890 ;42.5000
P111=-80.6920 ;43.0000
P112=-80.5000 ;43.3160
P113=-80.3590 ;43.5000
P114=-80.0120 ;44.0000
P115=-80.0000 ;44.0170
P116=-79.5920 ;44.5000
P117=-79.5000 ;44.6080
P118=-79.0800 ;45.0000
P119=-79.0000 ;45.0900
P120=-78.5340 ;45.5000
P121=-78.5000 ;45.5290
P122=-78.0000 ;45.7800
P123=-77.7420 ;45.5000
P124=-77.8310 ;45.0000
P125=-77.8810 ;44.5000
P126=-77.5000 ;44.1030
P127=-77.0570 ;44.5000
P128=-77.0000 ;44.5210
P129=-76.5460 ;45.0000
P130=-76.5000 ;45.0340
P131=-76.0090 ;45.5000
P132=-76.0000 ;45.5070
P133=-75.5000 ;45.9900
P134=-75.4890 ;46.0000
P135=-75.0000 ;46.4670
P136=-74.9630 ;46.5000
P137=-74.5000 ;46.9200
P138=-74.4010 ;47.0000
P139=-74.0000 ;47.4040
P140=-73.8800 ;47.5000
P141=-73.5000 ;47.8930
P142=-73.3570 ;48.0000
P143=-73.0000 ;48.4060
P144=-72.8800 ;48.5000
P145=-72.5000 ;48.9420
P146=-72.4320 ;49.0000
P147=-72.0000 ;49.4890
P148=-71.9880 ;49.5000
P149=-71.5000 ;49.9410
P150=-71.4310 ;50.0000
P151=-71.0000 ;50.2960
P152=-70.7060 ;50.5000
P153=-70.5000 ;50.6060
P154=-70.0000 ;50.8770
P155=-69.7840 ;51.0000
P156=-69.5000 ;51.1270
P157=-69.0000 ;51.3650
P158=-68.7330 ;51.5000
P159=-68.5000 ;51.5940
P160=-68.0000 ;51.8060
P161=-67.5770 ;52.0000

P162=-67.5000 ;52.0280
P163=-67.0000 ;52.2100
P164=-66.5000 ;52.3950
P165=-66.2180 ;52.5000
P166=-66.0000 ;52.5690
P167=-65.5000 ;52.7240
P168=-65.0000 ;52.8820
P169=-64.6300 ;53.0000
P170=-64.5000 ;53.0370
P171=-64.0000 ;53.1690
P172=-63.5000 ;53.2910
P173=-63.0000 ;53.3970
P174=-62.5000 ;53.4900
P175=-62.4330 ;53.5000
P176=-62.0000 ;53.5650
P177=-61.5000 ;53.6160
P178=-61.0000 ;53.6390
P179=-60.5000 ;53.6410
P180=-60.0000 ;53.6170
P181=-59.5000 ;53.5400
P182=-59.3070 ;53.5000
P183=-59.0000 ;53.4250
P184=-58.5000 ;53.2620
P185=-58.0000 ;53.0310
P186=-57.9340 ;53.0000
P187=-57.5000 ;52.7180
P188=-57.1950 ;52.5000
P189=-57.0000 ;52.2830
P190=-56.7150 ;52.0000
P191=-56.5000 ;51.5930

[C10]

gain=-30.00

n_point=68

P1=-78.5000 ;38.9650
P2=-78.5560 ;39.0000
P3=-78.6049 ;39.0625
P4=-78.6538 ;39.1250
P5=-78.7026 ;39.1875
P6=-78.7515 ;39.2500
P7=-78.8004 ;39.3125
P8=-78.8493 ;39.3750
P9=-78.8981 ;39.4375
P10=-78.9470 ;39.5000
P11=-78.9735 ;39.5495
P12=-79.0000 ;39.5990
P13=-79.0485 ;39.5495
P14=-79.0970 ;39.5000
P15=-79.1291 ;39.4375
P16=-79.1612 ;39.3750
P17=-79.1934 ;39.3125
P18=-79.2255 ;39.2500
P19=-79.2576 ;39.1875
P20=-79.2897 ;39.1250
P21=-79.3219 ;39.0625
P22=-79.3540 ;39.0000
P23=-79.3666 ;38.9286
P24=-79.3791 ;38.8571

P25=-79.3917 ;38.7857
P26=-79.4043 ;38.7143
P27=-79.4169 ;38.6429
P28=-79.4294 ;38.5714
P29=-79.4420 ;38.5000
P30=-79.4113 ;38.4286
P31=-79.3806 ;38.3571
P32=-79.3499 ;38.2857
P33=-79.3191 ;38.2143
P34=-79.2884 ;38.1429
P35=-79.2577 ;38.0714
P36=-79.2270 ;38.0000
P37=-79.1702 ;37.9475
P38=-79.1135 ;37.8950
P39=-79.0567 ;37.8425
P40=-79.0000 ;37.7900
P41=-78.9167 ;37.7558
P42=-78.8333 ;37.7217
P43=-78.7500 ;37.6875
P44=-78.6667 ;37.6533
P45=-78.5833 ;37.6192
P46=-78.5000 ;37.5850
P47=-78.4465 ;37.6369
P48=-78.3930 ;37.6888
P49=-78.3395 ;37.7406
P50=-78.2860 ;37.7925
P51=-78.2325 ;37.8444
P52=-78.1790 ;37.8962
P53=-78.1255 ;37.9481
P54=-78.0720 ;38.0000
P55=-78.0946 ;38.0714
P56=-78.1171 ;38.1429
P57=-78.1397 ;38.2143
P58=-78.1623 ;38.2857
P59=-78.1849 ;38.3571
P60=-78.2074 ;38.4286
P61=-78.2300 ;38.5000
P62=-78.2686 ;38.5664
P63=-78.3071 ;38.6329
P64=-78.3457 ;38.6993
P65=-78.3843 ;38.7657
P66=-78.4229 ;38.8321
P67=-78.4614 ;38.8986
P68=-78.5000 ;38.9650
[C11]
gain=-30.00
n_point=74
P1=-62.0000 ;48.8080
P2=-62.0567 ;48.8720
P3=-62.1133 ;48.9360
P4=-62.1700 ;49.0000
P5=-62.2525 ;49.0322
P6=-62.3350 ;49.0645
P7=-62.4175 ;49.0968
P8=-62.5000 ;49.1290
P9=-62.6000 ;49.1594
P10=-62.7000 ;49.1898

P11=-62.8000 ;49.2202
P12=-62.9000 ;49.2506
P13=-63.0000 ;49.2810
P14=-63.1000 ;49.2932
P15=-63.2000 ;49.3054
P16=-63.3000 ;49.3176
P17=-63.4000 ;49.3298
P18=-63.5000 ;49.3420
P19=-63.6000 ;49.3428
P20=-63.7000 ;49.3436
P21=-63.8000 ;49.3444
P22=-63.9000 ;49.3452
P23=-64.0000 ;49.3460
P24=-64.1000 ;49.3214
P25=-64.2000 ;49.2968
P26=-64.3000 ;49.2722
P27=-64.4000 ;49.2476
P28=-64.5000 ;49.2230
P29=-64.5827 ;49.1673
P30=-64.6655 ;49.1115
P31=-64.7483 ;49.0558
P32=-64.8310 ;49.0000
P33=-64.7897 ;48.9286
P34=-64.7484 ;48.8571
P35=-64.7071 ;48.7857
P36=-64.6659 ;48.7143
P37=-64.6246 ;48.6429
P38=-64.5833 ;48.5714
P39=-64.5420 ;48.5000
P40=-64.5000 ;48.4820
P41=-64.4000 ;48.4460
P42=-64.3000 ;48.4100
P43=-64.2000 ;48.3740
P44=-64.1000 ;48.3380
P45=-64.0000 ;48.3020
P46=-63.9000 ;48.2740
P47=-63.8000 ;48.2460
P48=-63.7000 ;48.2180
P49=-63.6000 ;48.1900
P50=-63.5000 ;48.1620
P51=-63.4000 ;48.1476
P52=-63.3000 ;48.1332
P53=-63.2000 ;48.1188
P54=-63.1000 ;48.1044
P55=-63.0000 ;48.0900
P56=-62.9000 ;48.0894
P57=-62.8000 ;48.0888
P58=-62.7000 ;48.0882
P59=-62.6000 ;48.0876
P60=-62.5000 ;48.0870
P61=-62.4000 ;48.1264
P62=-62.3000 ;48.1658
P63=-62.2000 ;48.2052
P64=-62.1000 ;48.2446
P65=-62.0000 ;48.2840
P66=-61.9397 ;48.3380
P67=-61.8795 ;48.3920

P68=-61.8192 ;48.4460
P69=-61.7590 ;48.5000
P70=-61.8072 ;48.5616
P71=-61.8554 ;48.6232
P72=-61.9036 ;48.6848
P73=-61.9518 ;48.7464
P74=-62.0000 ;48.8080
[C12]
gain=-50.00
n_point=106
P1=-59.5000 ;38.6960
P2=-59.7400 ;38.5000
P3=-60.0000 ;38.1860
P4=-60.3220 ;38.0000
P5=-60.5000 ;37.8850
P6=-60.7500 ;37.7470
P7=-61.0000 ;37.6090
P8=-61.1270 ;37.5000
P9=-61.3135 ;37.3300
P10=-61.5000 ;37.1600
P11=-61.6920 ;37.0000
P12=-62.0000 ;36.8170
P13=-62.1815 ;36.6585
P14=-62.3630 ;36.5000
P15=-62.5000 ;36.3580
P16=-62.7235 ;36.1790
P17=-62.9470 ;36.0000
P18=-63.0000 ;35.9400
P19=-63.2500 ;35.8070
P20=-63.5000 ;35.6740
P21=-63.7100 ;35.5000
P22=-64.0000 ;35.2380
P23=-64.2970 ;35.0000
P24=-64.5000 ;34.8550
P25=-64.7500 ;34.6955
P26=-65.0000 ;34.5360
P27=-65.0480 ;34.5000
P28=-65.2740 ;34.3655
P29=-65.5000 ;34.2310
P30=-65.8240 ;34.0000
P31=-66.0000 ;33.8770
P32=-66.2500 ;33.7430
P33=-66.5000 ;33.6090
P34=-66.6490 ;33.5000
P35=-67.0000 ;33.2950
P36=-67.2020 ;33.1475
P37=-67.4040 ;33.0000
P38=-67.5000 ;32.9280
P39=-67.7500 ;32.8030
P40=-68.0000 ;32.6780
P41=-68.2480 ;32.5000
P42=-68.5000 ;32.3260
P43=-68.7500 ;32.1685
P44=-69.0000 ;32.0110
P45=-69.0170 ;32.0000
P46=-69.2585 ;31.8430
P47=-69.5000 ;31.6860

P48=-69.8500 ;31.5000
P49=-70.0000 ;31.2650
P50=-70.2500 ;31.1765
P51=-70.5000 ;31.0880
P52=-70.7010 ;31.0000
P53=-70.5000 ;30.8410
P54=-70.2500 ;30.8575
P55=-70.0000 ;30.8740
P56=-69.6910 ;31.0000
P57=-69.5000 ;31.1150
P58=-69.2500 ;31.1820
P59=-69.0000 ;31.2490
P60=-68.7660 ;31.3745
P61=-68.5320 ;31.5000
P62=-68.5000 ;31.5160
P63=-68.2500 ;31.6070
P64=-68.0000 ;31.6980
P65=-67.7910 ;31.8490
P66=-67.5820 ;32.0000
P67=-67.5000 ;32.0460
P68=-67.2500 ;32.1645
P69=-67.0000 ;32.2830
P70=-66.7310 ;32.5000
P71=-66.5000 ;32.6180
P72=-66.2570 ;32.8090
P73=-66.0140 ;33.0000
P74=-66.0000 ;33.0140
P75=-65.7500 ;33.1595
P76=-65.5000 ;33.3050
P77=-65.2660 ;33.5000
P78=-65.0000 ;33.6630
P79=-64.7860 ;33.8315
P80=-64.5720 ;34.0000
P81=-64.5000 ;34.0590
P82=-64.2500 ;34.2180
P83=-64.0000 ;34.3770
P84=-63.8590 ;34.5000
P85=-63.5000 ;34.7320
P86=-63.2030 ;35.0000
P87=-63.0000 ;35.1560
P88=-62.7930 ;35.3280
P89=-62.5860 ;35.5000
P90=-62.5000 ;35.5780
P91=-62.2500 ;35.7575
P92=-62.0000 ;35.9370
P93=-61.9300 ;36.0000
P94=-61.7150 ;36.1745
P95=-61.5000 ;36.3490
P96=-61.3390 ;36.5000
P97=-61.0000 ;36.7160
P98=-60.6920 ;37.0000
P99=-60.5000 ;37.2400
P100=-60.2040 ;37.5000
P101=-60.0000 ;37.7800
P102=-59.7220 ;38.0000
P103=-59.5000 ;38.1680
P104=-59.3090 ;38.3340

P105=-59.1180 ;38.5000
P106=-59.5000 ;38.6960
[C13]
gain=-40.00
n_point=107
P1=-61.0000 ;40.6880
P2=-61.2930 ;40.5000
P3=-61.5000 ;40.3460
P4=-62.0000 ;40.0720
P5=-62.0850 ;40.0000
P6=-62.5000 ;39.6920
P7=-62.7330 ;39.5000
P8=-63.0000 ;39.2670
P9=-63.3720 ;39.0000
P10=-63.5000 ;38.8990
P11=-63.7500 ;38.7325
P12=-64.0000 ;38.5660
P13=-64.0850 ;38.5000
P14=-64.5000 ;38.2070
P15=-64.7690 ;38.0000
P16=-65.0000 ;37.8690
P17=-65.2375 ;37.6845
P18=-65.4750 ;37.5000
P19=-65.5000 ;37.4780
P20=-66.0000 ;37.2000
P21=-66.2760 ;37.0000
P22=-66.5000 ;36.8610
P23=-66.7390 ;36.6805
P24=-66.9780 ;36.5000
P25=-67.0000 ;36.4930
P26=-67.5000 ;36.2520
P27=-67.8810 ;36.0000
P28=-68.0000 ;35.9520
P29=-68.2500 ;35.8075
P30=-68.5000 ;35.6630
P31=-68.7360 ;35.5000
P32=-69.0000 ;35.4030
P33=-69.2500 ;35.2400
P34=-69.5000 ;35.0770
P35=-69.5960 ;35.0000
P36=-70.0000 ;34.8050
P37=-70.4070 ;34.5000
P38=-70.5000 ;34.4510
P39=-70.7500 ;34.3130
P40=-71.0000 ;34.1750
P41=-71.2580 ;34.0000
P42=-71.5000 ;33.8870
P43=-72.0000 ;33.6610
P44=-72.3000 ;33.5000
P45=-72.5000 ;33.4170
P46=-73.0000 ;33.3010
P47=-73.5000 ;33.1640
P48=-74.0000 ;33.0090
P49=-74.0330 ;33.0000
P50=-74.5000 ;32.8830
P51=-75.0000 ;32.7690
P52=-75.5000 ;32.5840

P53=-75.6960 ;32.5000
P54=-75.5000 ;32.4000
P55=-75.0000 ;32.2200
P56=-74.5000 ;32.1550
P57=-74.0000 ;32.1740
P58=-73.5000 ;32.2280
P59=-73.0000 ;32.3100
P60=-72.5000 ;32.4340
P61=-72.2910 ;32.5000
P62=-72.0000 ;32.5380
P63=-71.5000 ;32.6290
P64=-71.0000 ;32.7810
P65=-70.5850 ;33.0000
P66=-70.5000 ;33.0200
P67=-70.0000 ;33.1520
P68=-69.7500 ;33.2930
P69=-69.5000 ;33.4340
P70=-69.4110 ;33.5000
P71=-69.0000 ;33.6030
P72=-68.5000 ;33.8380
P73=-68.3630 ;34.0000
P74=-68.0000 ;34.1340
P75=-67.7835 ;34.3170
P76=-67.5670 ;34.5000
P77=-67.5000 ;34.5310
P78=-67.2500 ;34.6880
P79=-67.0000 ;34.8450
P80=-66.8770 ;35.0000
P81=-66.5000 ;35.2120
P82=-66.1950 ;35.5000
P83=-66.0000 ;35.6170
P84=-65.7945 ;35.8085
P85=-65.5890 ;36.0000
P86=-65.5000 ;36.0640
P87=-65.2675 ;36.2820
P88=-65.0350 ;36.5000
P89=-65.0000 ;36.5220
P90=-64.7500 ;36.7195
P91=-64.5000 ;36.9170
P92=-64.4170 ;37.0000
P93=-64.0000 ;37.3370
P94=-63.8360 ;37.5000
P95=-63.5000 ;37.7860
P96=-63.2840 ;38.0000
P97=-63.0000 ;38.2320
P98=-62.7070 ;38.5000
P99=-62.5000 ;38.7120
P100=-62.1940 ;39.0000
P101=-62.0000 ;39.2190
P102=-61.7180 ;39.5000
P103=-61.5000 ;39.7120
P104=-61.2260 ;40.0000
P105=-61.0000 ;40.2830
P106=-60.7950 ;40.5000
P107=-61.0000 ;40.6880
[C14]
gain=-50.00

n_point=74
P1=-76.5000 ;26.2290
P2=-76.6000 ;26.2412
P3=-76.7000 ;26.2534
P4=-76.8000 ;26.2656
P5=-76.9000 ;26.2778
P6=-77.0000 ;26.2900
P7=-77.1000 ;26.2936
P8=-77.2000 ;26.2972
P9=-77.3000 ;26.3008
P10=-77.4000 ;26.3044
P11=-77.5000 ;26.3080
P12=-77.6000 ;26.2930
P13=-77.7000 ;26.2780
P14=-77.8000 ;26.2630
P15=-77.9000 ;26.2480
P16=-78.0000 ;26.2330
P17=-78.1000 ;26.2136
P18=-78.2000 ;26.1942
P19=-78.3000 ;26.1748
P20=-78.4000 ;26.1554
P21=-78.5000 ;26.1360
P22=-78.6000 ;26.1220
P23=-78.7000 ;26.1080
P24=-78.8000 ;26.0940
P25=-78.9000 ;26.0800
P26=-79.0000 ;26.0660
P27=-79.1000 ;26.0568
P28=-79.2000 ;26.0476
P29=-79.3000 ;26.0384
P30=-79.4000 ;26.0292
P31=-79.5000 ;26.0200
P32=-79.5823 ;26.0133
P33=-79.6647 ;26.0067
P34=-79.7470 ;26.0000
P35=-79.6647 ;25.9860
P36=-79.5823 ;25.9720
P37=-79.5000 ;25.9580
P38=-79.4000 ;25.9392
P39=-79.3000 ;25.9204
P40=-79.2000 ;25.9016
P41=-79.1000 ;25.8828
P42=-79.0000 ;25.8640
P43=-78.9000 ;25.8452
P44=-78.8000 ;25.8264
P45=-78.7000 ;25.8076
P46=-78.6000 ;25.7888
P47=-78.5000 ;25.7700
P48=-78.4000 ;25.7548
P49=-78.3000 ;25.7396
P50=-78.2000 ;25.7244
P51=-78.1000 ;25.7092
P52=-78.0000 ;25.6940
P53=-77.9000 ;25.6876
P54=-77.8000 ;25.6812
P55=-77.7000 ;25.6748
P56=-77.6000 ;25.6684

P57=-77.5000 ;25.6620
P58=-77.4000 ;25.6762
P59=-77.3000 ;25.6904
P60=-77.2000 ;25.7046
P61=-77.1000 ;25.7188
P62=-77.0000 ;25.7330
P63=-76.9000 ;25.7630
P64=-76.8000 ;25.7930
P65=-76.7000 ;25.8230
P66=-76.6000 ;25.8530
P67=-76.5000 ;25.8830
P68=-76.3897 ;25.9220
P69=-76.2793 ;25.9610
P70=-76.1690 ;26.0000
P71=-76.2517 ;26.0573
P72=-76.3345 ;26.1145
P73=-76.4173 ;26.1717
P74=-76.5000 ;26.2290
[C15]
gain=-50.00
n_point=68
P1=-86.0000 ;37.1160
P2=-86.0638 ;37.0928
P3=-86.1276 ;37.0696
P4=-86.1914 ;37.0464
P5=-86.2552 ;37.0232
P6=-86.3190 ;37.0000
P7=-86.3289 ;36.9444
P8=-86.3388 ;36.8889
P9=-86.3487 ;36.8333
P10=-86.3586 ;36.7778
P11=-86.3684 ;36.7222
P12=-86.3783 ;36.6667
P13=-86.3882 ;36.6111
P14=-86.3981 ;36.5556
P15=-86.4080 ;36.5000
P16=-86.3977 ;36.4500
P17=-86.3874 ;36.4000
P18=-86.3771 ;36.3500
P19=-86.3668 ;36.3000
P20=-86.3565 ;36.2500
P21=-86.3462 ;36.2000
P22=-86.3359 ;36.1500
P23=-86.3256 ;36.1000
P24=-86.3153 ;36.0500
P25=-86.3050 ;36.0000
P26=-86.2745 ;35.9527
P27=-86.2440 ;35.9054
P28=-86.2135 ;35.8581
P29=-86.1830 ;35.8108
P30=-86.1525 ;35.7635
P31=-86.1220 ;35.7162
P32=-86.0915 ;35.6689
P33=-86.0610 ;35.6216
P34=-86.0305 ;35.5743
P35=-86.0000 ;35.5270
P36=-85.9713 ;35.5743

P37=-85.9426 ;35.6216
P38=-85.9139 ;35.6689
P39=-85.8852 ;35.7162
P40=-85.8565 ;35.7635
P41=-85.8278 ;35.8108
P42=-85.7991 ;35.8581
P43=-85.7704 ;35.9054
P44=-85.7417 ;35.9527
P45=-85.7130 ;36.0000
P46=-85.7260 ;36.0500
P47=-85.7390 ;36.1000
P48=-85.7520 ;36.1500
P49=-85.7650 ;36.2000
P50=-85.7780 ;36.2500
P51=-85.7910 ;36.3000
P52=-85.8040 ;36.3500
P53=-85.8170 ;36.4000
P54=-85.8300 ;36.4500
P55=-85.8430 ;36.5000
P56=-85.8541 ;36.5500
P57=-85.8652 ;36.6000
P58=-85.8763 ;36.6500
P59=-85.8874 ;36.7000
P60=-85.8985 ;36.7500
P61=-85.9096 ;36.8000
P62=-85.9207 ;36.8500
P63=-85.9318 ;36.9000
P64=-85.9429 ;36.9500
P65=-85.9540 ;37.0000
P66=-85.9693 ;37.0387
P67=-85.9847 ;37.0773
P68=-86.0000 ;37.1160
[C16]
gain=-50.00
n_point=72
P1=-75.0000 ;50.7930
P2=-75.1000 ;50.7434
P3=-75.2000 ;50.6938
P4=-75.3000 ;50.6442
P5=-75.4000 ;50.5946
P6=-75.5000 ;50.5450
P7=-75.5560 ;50.5000
P8=-75.6300 ;50.4467
P9=-75.7040 ;50.3933
P10=-75.7780 ;50.3400
P11=-75.8520 ;50.2867
P12=-75.9260 ;50.2333
P13=-76.0000 ;50.1800
P14=-76.0700 ;50.1200
P15=-76.1400 ;50.0600
P16=-76.2100 ;50.0000
P17=-76.2825 ;49.9557
P18=-76.3550 ;49.9115
P19=-76.4275 ;49.8672
P20=-76.5000 ;49.8230
P21=-76.5686 ;49.7584
P22=-76.6372 ;49.6938

P23=-76.7058 ;49.6292
P24=-76.7744 ;49.5646
P25=-76.8430 ;49.5000
P26=-76.8822 ;49.4345
P27=-76.9215 ;49.3690
P28=-76.9608 ;49.3035
P29=-77.0000 ;49.2380
P30=-77.0798 ;49.1904
P31=-77.1596 ;49.1428
P32=-77.2394 ;49.0952
P33=-77.3192 ;49.0476
P34=-77.3990 ;49.0000
P35=-77.2993 ;48.9660
P36=-77.1995 ;48.9320
P37=-77.0997 ;48.8980
P38=-77.0000 ;48.8640
P39=-76.9400 ;48.9093
P40=-76.8800 ;48.9547
P41=-76.8200 ;49.0000
P42=-76.7400 ;49.0532
P43=-76.6600 ;49.1065
P44=-76.5800 ;49.1597
P45=-76.5000 ;49.2130
P46=-76.4244 ;49.2704
P47=-76.3488 ;49.3278
P48=-76.2732 ;49.3852
P49=-76.1976 ;49.4426
P50=-76.1220 ;49.5000
P51=-76.0813 ;49.5743
P52=-76.0407 ;49.6487
P53=-76.0000 ;49.7230
P54=-75.9000 ;49.7648
P55=-75.8000 ;49.8066
P56=-75.7000 ;49.8484
P57=-75.6000 ;49.8902
P58=-75.5000 ;49.9320
P59=-75.4570 ;49.9660
P60=-75.4140 ;50.0000
P61=-75.3450 ;50.0662
P62=-75.2760 ;50.1323
P63=-75.2070 ;50.1985
P64=-75.1380 ;50.2647
P65=-75.0690 ;50.3308
P66=-75.0000 ;50.3970
P67=-74.9110 ;50.4485
P68=-74.8220 ;50.5000
P69=-74.8665 ;50.5732
P70=-74.9110 ;50.6465
P71=-74.9555 ;50.7197
P72=-75.0000 ;50.7930
[C17]
gain=-50.00
n_point=67
P1=-78.0000 ;48.3320
P2=-78.0500 ;48.3114
P3=-78.1000 ;48.2908
P4=-78.1500 ;48.2702

P5=-78.2000 ;48.2496
P6=-78.2500 ;48.2290
P7=-78.3000 ;48.2084
P8=-78.3500 ;48.1878
P9=-78.4000 ;48.1672
P10=-78.4500 ;48.1466
P11=-78.5000 ;48.1260
P12=-78.5310 ;48.0945
P13=-78.5620 ;48.0630
P14=-78.5930 ;48.0315
P15=-78.6240 ;48.0000
P16=-78.6408 ;47.9615
P17=-78.6577 ;47.9231
P18=-78.6745 ;47.8846
P19=-78.6914 ;47.8462
P20=-78.7082 ;47.8077
P21=-78.7251 ;47.7692
P22=-78.7419 ;47.7308
P23=-78.7588 ;47.6923
P24=-78.7756 ;47.6538
P25=-78.7925 ;47.6154
P26=-78.8093 ;47.5769
P27=-78.8262 ;47.5385
P28=-78.8430 ;47.5000
P29=-78.8001 ;47.4760
P30=-78.7572 ;47.4520
P31=-78.7144 ;47.4280
P32=-78.6715 ;47.4040
P33=-78.6286 ;47.3800
P34=-78.5858 ;47.3560
P35=-78.5429 ;47.3320
P36=-78.5000 ;47.3080
P37=-78.4688 ;47.3400
P38=-78.4377 ;47.3720
P39=-78.4065 ;47.4040
P40=-78.3753 ;47.4360
P41=-78.3442 ;47.4680
P42=-78.3130 ;47.5000
P43=-78.2845 ;47.5331
P44=-78.2561 ;47.5662
P45=-78.2276 ;47.5993
P46=-78.1992 ;47.6324
P47=-78.1707 ;47.6655
P48=-78.1423 ;47.6985
P49=-78.1138 ;47.7316
P50=-78.0854 ;47.7647
P51=-78.0569 ;47.7978
P52=-78.0285 ;47.8309
P53=-78.0000 ;47.8640
P54=-77.9690 ;47.8912
P55=-77.9380 ;47.9184
P56=-77.9070 ;47.9456
P57=-77.8760 ;47.9728
P58=-77.8450 ;48.0000
P59=-77.8622 ;48.0369
P60=-77.8794 ;48.0738
P61=-77.8967 ;48.1107

P62=-77.9139 ;48.1476
P63=-77.9311 ;48.1844
P64=-77.9483 ;48.2213
P65=-77.9656 ;48.2582
P66=-77.9828 ;48.2951
P67=-78.0000 ;48.3320
[C18]
gain=-40.00
n_point=78
P1=-81.5000 ;36.2420
P2=-81.5600 ;36.3710
P3=-81.6200 ;36.5000
P4=-81.6748 ;36.6250
P5=-81.7295 ;36.7500
P6=-81.7842 ;36.8750
P7=-81.8390 ;37.0000
P8=-81.8927 ;37.0980
P9=-81.9463 ;37.1960
P10=-82.0000 ;37.2940
P11=-82.0415 ;37.3970
P12=-82.0830 ;37.5000
P13=-82.1312 ;37.6250
P14=-82.1795 ;37.7500
P15=-82.2278 ;37.8750
P16=-82.2760 ;38.0000
P17=-82.3262 ;38.1250
P18=-82.3765 ;38.2500
P19=-82.4268 ;38.3750
P20=-82.4770 ;38.5000
P21=-82.5000 ;38.5740
P22=-82.5747 ;38.6805
P23=-82.6495 ;38.7870
P24=-82.7243 ;38.8935
P25=-82.7990 ;39.0000
P26=-82.8260 ;39.1250
P27=-82.8530 ;39.2500
P28=-82.8800 ;39.3750
P29=-82.9070 ;39.5000
P30=-82.9228 ;39.6250
P31=-82.9385 ;39.7500
P32=-82.9543 ;39.8750
P33=-82.9700 ;40.0000
P34=-83.0000 ;40.0720
P35=-83.0210 ;40.0000
P36=-83.0347 ;39.8750
P37=-83.0485 ;39.7500
P38=-83.0622 ;39.6250
P39=-83.0760 ;39.5000
P40=-83.0993 ;39.3750
P41=-83.1225 ;39.2500
P42=-83.1458 ;39.1250
P43=-83.1690 ;39.0000
P44=-83.1998 ;38.8750
P45=-83.2305 ;38.7500
P46=-83.2612 ;38.6250
P47=-83.2920 ;38.5000
P48=-83.2890 ;38.3750

P49=-83.2860 ;38.2500
P50=-83.2830 ;38.1250
P51=-83.2800 ;38.0000
P52=-83.2630 ;37.8750
P53=-83.2460 ;37.7500
P54=-83.2290 ;37.6250
P55=-83.2120 ;37.5000
P56=-83.1413 ;37.3923
P57=-83.0707 ;37.2847
P58=-83.0000 ;37.1770
P59=-82.9525 ;37.0885
P60=-82.9050 ;37.0000
P61=-82.8115 ;36.8750
P62=-82.7180 ;36.7500
P63=-82.6245 ;36.6250
P64=-82.5310 ;36.5000
P65=-82.5000 ;36.4730
P66=-82.3750 ;36.3770
P67=-82.2500 ;36.2810
P68=-82.1250 ;36.1850
P69=-82.0000 ;36.0890
P70=-81.8935 ;36.0445
P71=-81.7870 ;36.0000
P72=-81.6913 ;35.9070
P73=-81.5957 ;35.8140
P74=-81.5000 ;35.7210
P75=-81.4495 ;35.8605
P76=-81.3990 ;36.0000
P77=-81.4495 ;36.1210
P78=-81.5000 ;36.2420
[C19]
gain=-40.00
n_point=89
P1=-87.0000 ;16.1060
P2=-86.7580 ;16.0000
P3=-87.0000 ;15.9220
P4=-87.2500 ;15.9230
P5=-87.5000 ;15.9240
P6=-87.7500 ;15.9575
P7=-88.0000 ;15.9910
P8=-88.0380 ;16.0000
P9=-88.2690 ;16.1060
P10=-88.5000 ;16.2120
P11=-88.7500 ;16.2985
P12=-89.0000 ;16.3850
P13=-89.1720 ;16.4425
P14=-89.3440 ;16.5000
P15=-89.5000 ;16.6090
P16=-89.6667 ;16.7023
P17=-89.8333 ;16.7957
P18=-90.0000 ;16.8890
P19=-90.2340 ;17.0000
P20=-90.3670 ;17.0970
P21=-90.5000 ;17.1940
P22=-90.6667 ;17.2893
P23=-90.8333 ;17.3847
P24=-91.0000 ;17.4800

P25=-91.0330 ;17.5000
P26=-91.1887 ;17.6253
P27=-91.3443 ;17.7507
P28=-91.5000 ;17.8760
P29=-91.6820 ;18.0000
P30=-91.8410 ;18.1540
P31=-92.0000 ;18.3080
P32=-92.1045 ;18.4040
P33=-92.2090 ;18.5000
P34=-92.3545 ;18.6485
P35=-92.5000 ;18.7970
P36=-92.5975 ;18.8985
P37=-92.6950 ;19.0000
P38=-92.8475 ;19.1700
P39=-93.0000 ;19.3400
P40=-93.1400 ;19.5000
P41=-93.2600 ;19.6493
P42=-93.3800 ;19.7987
P43=-93.5000 ;19.9480
P44=-93.5380 ;20.0000
P45=-93.6217 ;20.1667
P46=-93.7053 ;20.3333
P47=-93.7890 ;20.5000
P48=-93.6445 ;20.5630
P49=-93.5000 ;20.6260
P50=-93.3610 ;20.5000
P51=-93.1805 ;20.3480
P52=-93.0000 ;20.1960
P53=-92.8970 ;20.0980
P54=-92.7940 ;20.0000
P55=-92.6470 ;19.8820
P56=-92.5000 ;19.7640
P57=-92.3400 ;19.6320
P58=-92.1800 ;19.5000
P59=-92.0000 ;19.3380
P60=-91.8453 ;19.2253
P61=-91.6907 ;19.1127
P62=-91.5360 ;19.0000
P63=-91.5000 ;18.9700
P64=-91.3333 ;18.8397
P65=-91.1667 ;18.7093
P66=-91.0000 ;18.5790
P67=-90.8820 ;18.5000
P68=-90.6910 ;18.3530
P69=-90.5000 ;18.2060
P70=-90.2995 ;18.1030
P71=-90.0990 ;18.0000
P72=-90.0000 ;17.9160
P73=-89.8333 ;17.8093
P74=-89.6667 ;17.7027
P75=-89.5000 ;17.5960
P76=-89.2940 ;17.5000
P77=-89.1470 ;17.3930
P78=-89.0000 ;17.2860
P79=-88.7500 ;17.1670
P80=-88.5000 ;17.0480
P81=-88.3790 ;17.0000

P82=-88.1895 ;16.8655
P83=-88.0000 ;16.7310
P84=-87.7500 ;16.6335
P85=-87.5000 ;16.5360
P86=-87.3960 ;16.5000
P87=-87.2640 ;16.3687
P88=-87.1320 ;16.2373
P89=-87.0000 ;16.1060

[C20]

gain=-40.00

n_point=106

P1=-83.5000 ;18.5840
P2=-83.1070 ;18.5000
P3=-83.3035 ;18.3065
P4=-83.5000 ;18.1130
P5=-83.7500 ;18.0660
P6=-84.0000 ;18.0190
P7=-84.2500 ;18.0305
P8=-84.5000 ;18.0420
P9=-84.7500 ;18.0795
P10=-85.0000 ;18.1170
P11=-85.2500 ;18.1640
P12=-85.5000 ;18.2110
P13=-85.7500 ;18.2665
P14=-86.0000 ;18.3220
P15=-86.2500 ;18.3785
P16=-86.5000 ;18.4350
P17=-86.7750 ;18.5000
P18=-87.0000 ;18.5910
P19=-87.2500 ;18.6975
P20=-87.5000 ;18.8040
P21=-87.7500 ;18.8890
P22=-88.0000 ;18.9740
P23=-88.0700 ;19.0000
P24=-88.2850 ;19.1270
P25=-88.5000 ;19.2540
P26=-88.7500 ;19.3740
P27=-89.0000 ;19.4940
P28=-89.0120 ;19.5000
P29=-89.2560 ;19.6740
P30=-89.5000 ;19.8480
P31=-89.7500 ;20.0000
P32=-90.0000 ;20.1930
P33=-90.2110 ;20.3465
P34=-90.4220 ;20.5000
P35=-90.5000 ;20.5740
P36=-90.7230 ;20.7870
P37=-90.9460 ;21.0000
P38=-91.0000 ;21.0560
P39=-91.2085 ;21.2780
P40=-91.4170 ;21.5000
P41=-91.5000 ;21.5970
P42=-91.6605 ;21.7985
P43=-91.8210 ;22.0000
P44=-92.0000 ;22.2270
P45=-92.1760 ;22.5000
P46=-92.3380 ;22.7195

P47=-92.5000 ;22.9390
P48=-92.5380 ;23.0000
P49=-92.6590 ;23.2500
P50=-92.7800 ;23.5000
P51=-92.8900 ;23.6890
P52=-93.0000 ;23.8780
P53=-93.0560 ;24.0000
P54=-93.1235 ;24.2500
P55=-93.1910 ;24.5000
P56=-93.2005 ;24.7500
P57=-93.2100 ;25.0000
P58=-93.0000 ;25.1230
P59=-92.8860 ;25.0000
P60=-92.6930 ;24.8470
P61=-92.5000 ;24.6940
P62=-92.3450 ;24.5000
P63=-92.1725 ;24.3380
P64=-92.0000 ;24.1760
P65=-91.8450 ;24.0000
P66=-91.6725 ;23.8250
P67=-91.5000 ;23.6500
P68=-91.3770 ;23.5000
P69=-91.1885 ;23.3190
P70=-91.0000 ;23.1380
P71=-90.8690 ;23.0000
P72=-90.6845 ;22.8175
P73=-90.5000 ;22.6350
P74=-90.3570 ;22.5000
P75=-90.1785 ;22.3395
P76=-90.0000 ;22.1790
P77=-89.7790 ;22.0000
P78=-89.5000 ;21.7690
P79=-89.3095 ;21.6345
P80=-89.1190 ;21.5000
P81=-89.0000 ;21.4040
P82=-88.7500 ;21.2295
P83=-88.5000 ;21.0550
P84=-88.4100 ;21.0000
P85=-88.2050 ;20.8565
P86=-88.0000 ;20.7130
P87=-87.7835 ;20.6065
P88=-87.5670 ;20.5000
P89=-87.5000 ;20.4510
P90=-87.2500 ;20.2925
P91=-87.0000 ;20.1340
P92=-86.6790 ;20.0000
P93=-86.5000 ;19.8810
P94=-86.2500 ;19.7510
P95=-86.0000 ;19.6210
P96=-85.6490 ;19.5000
P97=-85.5000 ;19.4060
P98=-85.2500 ;19.2880
P99=-85.0000 ;19.1700
P100=-84.7500 ;19.0970
P101=-84.5000 ;19.0240
P102=-84.3890 ;19.0000
P103=-84.1945 ;18.8780

P104=-84.0000 ;18.7560
P105=-83.7500 ;18.6700
P106=-83.5000 ;18.5840
[C21]
gain=-40.00
n_point=111
P1=-76.5000 ;25.0580
P2=-76.1230 ;25.0000
P3=-76.2965 ;24.7500
P4=-76.4700 ;24.5000
P5=-76.5000 ;24.4890
P6=-76.7500 ;24.3905
P7=-77.0000 ;24.2920
P8=-77.2465 ;24.1460
P9=-77.4930 ;24.0000
P10=-77.5000 ;23.9980
P11=-78.0000 ;23.8930
P12=-78.5000 ;23.7730
P13=-79.0000 ;23.6430
P14=-79.5000 ;23.5190
P15=-79.5920 ;23.5000
P16=-80.0000 ;23.4670
P17=-80.5000 ;23.4400
P18=-81.0000 ;23.4320
P19=-81.5000 ;23.4430
P20=-82.0000 ;23.4680
P21=-82.4180 ;23.5000
P22=-82.5000 ;23.5150
P23=-83.0000 ;23.6410
P24=-83.5000 ;23.7790
P25=-84.0000 ;23.9180
P26=-84.2640 ;24.0000
P27=-84.5000 ;24.1060
P28=-84.7500 ;24.2105
P29=-85.0000 ;24.3150
P30=-85.3750 ;24.5000
P31=-85.5000 ;24.5780
P32=-85.7500 ;24.7285
P33=-86.0000 ;24.8790
P34=-86.1840 ;25.0000
P35=-86.5000 ;25.2370
P36=-86.8220 ;25.5000
P37=-87.0000 ;25.6600
P38=-87.3740 ;26.0000
P39=-87.5000 ;26.1340
P40=-87.8200 ;26.5000
P41=-88.0000 ;26.7160
P42=-88.2130 ;27.0000
P43=-88.5000 ;27.4070
P44=-88.5640 ;27.5000
P45=-88.6930 ;27.7500
P46=-88.8220 ;28.0000
P47=-89.0000 ;28.3330
P48=-89.0780 ;28.5000
P49=-89.1695 ;28.7500
P50=-89.2610 ;29.0000
P51=-89.3555 ;29.2500

P52=-89.4500 ;29.5000
P53=-89.5000 ;29.6620
P54=-89.5780 ;30.0000
P55=-89.6225 ;30.2500
P56=-89.6670 ;30.5000
P57=-89.6835 ;30.7500
P58=-89.7000 ;31.0000
P59=-89.6795 ;31.2500
P60=-89.6590 ;31.5000
P61=-89.5000 ;31.8140
P62=-89.0000 ;31.7100
P63=-88.7990 ;31.5000
P64=-88.5000 ;31.2540
P65=-88.2960 ;31.0000
P66=-88.0000 ;30.7000
P67=-87.8680 ;30.5000
P68=-87.6840 ;30.2895
P69=-87.5000 ;30.0790
P70=-87.4320 ;30.0000
P71=-87.2335 ;29.7500
P72=-87.0350 ;29.5000
P73=-87.0000 ;29.4640
P74=-86.7975 ;29.2320
P75=-86.5950 ;29.0000
P76=-86.5000 ;28.9040
P77=-86.3070 ;28.7020
P78=-86.1140 ;28.5000
P79=-86.0000 ;28.3890
P80=-85.7855 ;28.1945
P81=-85.5710 ;28.0000
P82=-85.5000 ;27.9390
P83=-85.2500 ;27.7600
P84=-85.0000 ;27.5810
P85=-84.9360 ;27.5000
P86=-84.7180 ;27.3455
P87=-84.5000 ;27.1910
P88=-84.2160 ;27.0000
P89=-84.0000 ;26.8680
P90=-83.7500 ;26.7180
P91=-83.5000 ;26.5680
P92=-83.4590 ;26.5000
P93=-83.2295 ;26.3685
P94=-83.0000 ;26.2370
P95=-82.7500 ;26.1185
P96=-82.5000 ;26.0000
P97=-82.4990 ;26.0000
P98=-82.2495 ;25.8915
P99=-82.0000 ;25.7830
P100=-81.5000 ;25.6360
P101=-81.0360 ;25.5000
P102=-81.0000 ;25.4850
P103=-80.5000 ;25.3180
P104=-80.0000 ;25.2120
P105=-79.5000 ;25.1470
P106=-79.0000 ;25.1100
P107=-78.5000 ;25.0940
P108=-78.0000 ;25.0890

P109=-77.5000 ;25.0900
P110=-77.0000 ;25.0830
P111=-76.5000 ;25.0580
[C22]
gain=-40.00
n_point=122
P1=-79.5000 ;21.5430
P2=-79.1350 ;21.5000
P3=-79.2870 ;21.2500
P4=-79.4390 ;21.0000
P5=-79.5000 ;20.9890
P6=-79.7500 ;20.9455
P7=-80.0000 ;20.9020
P8=-80.2500 ;20.8570
P9=-80.5000 ;20.8120
P10=-80.7500 ;20.7710
P11=-81.0000 ;20.7300
P12=-81.2500 ;20.6975
P13=-81.5000 ;20.6650
P14=-81.7500 ;20.6460
P15=-82.0000 ;20.6270
P16=-82.2500 ;20.6265
P17=-82.5000 ;20.6260
P18=-82.7500 ;20.6425
P19=-83.0000 ;20.6590
P20=-83.2500 ;20.6895
P21=-83.5000 ;20.7200
P22=-83.7500 ;20.7630
P23=-84.0000 ;20.8060
P24=-84.2500 ;20.8535
P25=-84.5000 ;20.9010
P26=-84.7500 ;20.9490
P27=-85.0000 ;20.9970
P28=-85.0130 ;21.0000
P29=-85.2565 ;21.0985
P30=-85.5000 ;21.1970
P31=-85.7500 ;21.2855
P32=-86.0000 ;21.3740
P33=-86.3890 ;21.5000
P34=-86.5000 ;21.5600
P35=-86.7500 ;21.6970
P36=-87.0000 ;21.8340
P37=-87.3340 ;22.0000
P38=-87.5000 ;22.1060
P39=-87.7500 ;22.2620
P40=-88.0000 ;22.4180
P41=-88.1250 ;22.5000
P42=-88.5000 ;22.7990
P43=-88.7600 ;23.0000
P44=-89.0000 ;23.2180
P45=-89.2960 ;23.5000
P46=-89.5000 ;23.7150
P47=-89.7630 ;24.0000
P48=-90.0000 ;24.2910
P49=-90.1530 ;24.5000
P50=-90.3265 ;24.7260
P51=-90.5000 ;24.9520

P52=-90.5310 ;25.0000
P53=-90.6600 ;25.2500
P54=-90.7890 ;25.5000
P55=-91.0000 ;25.8380
P56=-91.0790 ;26.0000
P57=-91.1770 ;26.2500
P58=-91.2750 ;26.5000
P59=-91.3875 ;26.7340
P60=-91.5000 ;26.9680
P61=-91.5120 ;27.0000
P62=-91.5680 ;27.2500
P63=-91.6240 ;27.5000
P64=-91.6660 ;27.7500
P65=-91.7080 ;28.0000
P66=-91.6745 ;28.2500
P67=-91.6410 ;28.5000
P68=-91.5000 ;28.6670
P69=-91.2270 ;28.5000
P70=-91.0000 ;28.3990
P71=-90.8100 ;28.1995
P72=-90.6200 ;28.0000
P73=-90.5000 ;27.9020
P74=-90.3585 ;27.7010
P75=-90.2170 ;27.5000
P76=-90.0000 ;27.2820
P77=-89.7850 ;27.0000
P78=-89.5000 ;26.6850
P79=-89.3540 ;26.5000
P80=-89.1770 ;26.3190
P81=-89.0000 ;26.1380
P82=-88.8800 ;26.0000
P83=-88.6900 ;25.8080
P84=-88.5000 ;25.6160
P85=-88.3770 ;25.5000
P86=-88.1885 ;25.3260
P87=-88.0000 ;25.1520
P88=-87.8340 ;25.0000
P89=-87.5000 ;24.7090
P90=-87.2250 ;24.5000
P91=-87.0000 ;24.3230
P92=-86.7595 ;24.1615
P93=-86.5190 ;24.0000
P94=-86.5000 ;23.9860
P95=-86.2500 ;23.8160
P96=-86.0000 ;23.6460
P97=-85.7300 ;23.5000
P98=-85.5000 ;23.3450
P99=-85.2500 ;23.2125
P100=-85.0000 ;23.0800
P101=-84.8290 ;23.0000
P102=-84.5000 ;22.8120
P103=-84.2500 ;22.7100
P104=-84.0000 ;22.6080
P105=-83.6270 ;22.5000
P106=-83.5000 ;22.4320
P107=-83.2500 ;22.3245
P108=-83.0000 ;22.2170

P109=-82.7500 ;22.1490
P110=-82.5000 ;22.0810
P111=-82.0060 ;22.0000
P112=-82.0000 ;21.9970
P113=-81.7500 ;21.9165
P114=-81.5000 ;21.8360
P115=-81.2500 ;21.7815
P116=-81.0000 ;21.7270
P117=-80.7500 ;21.6890
P118=-80.5000 ;21.6510
P119=-80.2500 ;21.6225
P120=-80.0000 ;21.5940
P121=-79.7500 ;21.5685
P122=-79.5000 ;21.5430

[C23]

gain=-50.00

n_point=578

P1=-36.2595 ;69.2663
P2=-36.2917 ;69.2613
P3=-37.7316 ;69.0312
P4=-39.1684 ;68.7865
P5=-40.6021 ;68.5271
P6=-42.0327 ;68.2530
P7=-43.4601 ;67.9643
P8=-44.8844 ;67.6608
P9=-46.3056 ;67.3427
P10=-47.7237 ;67.0098
P11=-49.1386 ;66.6623
P12=-50.5505 ;66.3001
P13=-51.9591 ;65.9232
P14=-53.3647 ;65.5317
P15=-54.7671 ;65.1254
P16=-56.1665 ;64.7045
P17=-57.5605 ;64.2645
P18=-58.9422 ;63.7918
P19=-60.3111 ;63.2851
P20=-61.6673 ;62.7446
P21=-63.0107 ;62.1702
P22=-64.3446 ;61.5716
P23=-65.6802 ;60.9798
P24=-67.0181 ;60.3970
P25=-68.3583 ;59.8231
P26=-69.7007 ;59.2576
P27=-71.0429 ;58.6898
P28=-72.3839 ;58.1160
P29=-73.7237 ;57.5363
P30=-75.0625 ;56.9505
P31=-76.3874 ;56.3389
P32=-77.6672 ;55.6521
P33=-78.9005 ;54.8879
P34=-80.0872 ;54.0462
P35=-81.2270 ;53.1273
P36=-82.3101 ;52.1387
P37=-83.3321 ;51.0838
P38=-84.2931 ;49.9626
P39=-85.1930 ;48.7751
P40=-86.0379 ;47.5637

P41=-86.8326 ;46.3647
P42=-87.5771 ;45.1781
P43=-88.2716 ;44.0037
P44=-88.8395 ;42.7544
P45=-89.0083 ;42.0328
P46=-89.1771 ;41.3113
P47=-89.2304 ;40.4925
P48=-89.2837 ;39.6737
P49=-89.2215 ;38.7578
P50=-89.1594 ;37.8418
P51=-89.0338 ;36.9394
P52=-88.9081 ;36.0369
P53=-88.8165 ;34.8700
P54=-88.9013 ;34.3766
P55=-89.1624 ;34.5565
P56=-89.5233 ;35.3055
P57=-89.7591 ;36.3169
P58=-89.8551 ;37.5710
P59=-89.8333 ;38.3193
P60=-89.8114 ;39.0676
P61=-89.7213 ;39.9246
P62=-89.6312 ;40.7817
P63=-89.4918 ;41.5987
P64=-89.3524 ;42.4158
P65=-89.1693 ;43.1497
P66=-88.9861 ;43.8837
P67=-88.5323 ;45.1853
P68=-87.9881 ;46.3307
P69=-87.3041 ;47.4934
P70=-86.8832 ;48.1147
P71=-86.4624 ;48.7360
P72=-85.9627 ;49.3973
P73=-85.4630 ;50.0586
P74=-84.9006 ;50.7503
P75=-84.3382 ;51.4421
P76=-83.8744 ;52.0695
P77=-83.4105 ;52.6968
P78=-82.7633 ;53.7736
P79=-82.3966 ;54.6725
P80=-82.3149 ;55.3741
P81=-82.5739 ;55.6444
P82=-83.1898 ;55.4148
P83=-84.1625 ;54.6854
P84=-84.8233 ;54.0745
P85=-85.4841 ;53.4636
P86=-86.1332 ;52.7823
P87=-86.7823 ;52.1011
P88=-87.3183 ;51.4454
P89=-87.8542 ;50.7896
P90=-88.2770 ;50.1594
P91=-88.6998 ;49.5291
P92=-89.3191 ;48.3196
P93=-89.8326 ;47.1190
P94=-90.3778 ;45.8792
P95=-90.9550 ;44.6001
P96=-91.2593 ;43.9409
P97=-91.5637 ;43.2818

P98=-91.8073 ;42.5869
P99=-92.0508 ;41.8921
P100=-92.1699 ;41.1484
P101=-92.2889 ;40.4046
P102=-92.2835 ;39.6119
P103=-92.2781 ;38.8191
P104=-92.1482 ;37.9774
P105=-92.0183 ;37.1357
P106=-91.8279 ;36.3055
P107=-91.6376 ;35.4753
P108=-91.5251 ;34.7873
P109=-91.4127 ;34.0994
P110=-91.3532 ;33.0169
P111=-91.4590 ;32.2278
P112=-91.7104 ;31.7962
P113=-92.0345 ;31.9592
P114=-92.4243 ;32.7391
P115=-92.6522 ;33.4375
P116=-92.8800 ;34.1359
P117=-93.1133 ;35.0698
P118=-93.3467 ;36.0037
P119=-93.4783 ;36.8873
P120=-93.6100 ;37.7709
P121=-93.6292 ;38.5752
P122=-93.6483 ;39.3796
P123=-93.5549 ;40.1047
P124=-93.4615 ;40.8297
P125=-93.0791 ;42.1422
P126=-92.6599 ;43.4299
P127=-92.2273 ;44.7093
P128=-91.7814 ;45.9806
P129=-91.3061 ;47.2596
P130=-91.0133 ;47.9431
P131=-90.7205 ;48.6265
P132=-90.3671 ;49.3594
P133=-90.0136 ;50.0923
P134=-89.5994 ;50.8746
P135=-89.1853 ;51.6569
P136=-88.7378 ;52.4567
P137=-88.2903 ;53.2564
P138=-87.7859 ;54.3525
P139=-87.7754 ;54.8240
P140=-88.2588 ;54.6707
P141=-89.1928 ;53.9281
P142=-90.1387 ;52.9553
P143=-90.9818 ;51.8461
P144=-91.7221 ;50.6003
P145=-92.0434 ;49.9149
P146=-92.3648 ;49.2295
P147=-92.6564 ;48.5267
P148=-92.9480 ;47.8239
P149=-93.2140 ;47.1133
P150=-93.4800 ;46.4026
P151=-93.7204 ;45.6840
P152=-93.9608 ;44.9655
P153=-94.1728 ;44.2421
P154=-94.3847 ;43.5188

P155=-94.5475 ;42.8131
P156=-94.7103 ;42.1074
P157=-94.8196 ;41.4240
P158=-94.9289 ;40.7407
P159=-95.0407 ;39.4185
P160=-95.0449 ;38.1309
P161=-94.9888 ;37.4312
P162=-94.9326 ;36.7314
P163=-94.8168 ;35.9518
P164=-94.7009 ;35.1722
P165=-94.5252 ;34.3127
P166=-94.3496 ;33.4533
P167=-94.1145 ;32.5144
P168=-93.8794 ;31.5755
P169=-93.7053 ;30.8042
P170=-93.5313 ;30.0330
P171=-93.5068 ;29.2379
P172=-93.8059 ;29.1903
P173=-94.4241 ;29.8827
P174=-95.1250 ;30.9070
P175=-95.7736 ;32.0303
P176=-96.3699 ;33.2526
P177=-96.8782 ;34.4164
P178=-97.1251 ;34.7526
P179=-97.0873 ;34.1584
P180=-96.9261 ;33.3961
P181=-96.7649 ;32.6339
P182=-96.4946 ;31.5092
P183=-96.2243 ;30.3846
P184=-96.0278 ;29.4637
P185=-95.8314 ;28.5428
P186=-95.6422 ;27.2814
P187=-95.6565 ;26.6005
P188=-95.8774 ;26.4879
P189=-96.3367 ;26.8163
P190=-97.0428 ;27.5515
P191=-97.5067 ;28.0991
P192=-97.9706 ;28.6468
P193=-98.5883 ;29.1256
P194=-98.6836 ;28.5972
P195=-98.4700 ;27.8294
P196=-98.2564 ;27.0617
P197=-97.8123 ;25.8529
P198=-97.3682 ;24.6442
P199=-97.0612 ;23.7433
P200=-96.7542 ;22.8424
P201=-96.6290 ;22.0935
P202=-96.9926 ;22.3974
P203=-97.3792 ;22.9732
P204=-97.7659 ;23.5489
P205=-98.5375 ;24.4790
P206=-99.2482 ;25.0340
P207=-99.8617 ;25.1948
P208=-100.1131 ;24.8207
P209=-99.9493 ;23.8834
P210=-99.6597 ;23.1332
P211=-99.3701 ;22.3831

P212=-98.8751 ;21.3548
P213=-98.3801 ;20.3265
P214=-97.9991 ;19.5184
P215=-97.6181 ;18.7104
P216=-97.5389 ;18.2443
P217=-98.1424 ;18.9281
P218=-98.6386 ;19.5800
P219=-99.1348 ;20.2318
P220=-99.5925 ;20.7734
P221=-100.0502;21.3149
P222=-100.8829;22.1667
P223=-101.5351;22.6536
P224=-101.8015;22.4938
P225=-101.6754;21.6781
P226=-101.4162;20.9424
P227=-101.1570;20.2066
P228=-100.7761;19.3510
P229=-100.3952;18.4955
P230=-99.9677 ;17.7299
P231=-99.5401 ;16.9644
P232=-99.0660 ;16.2889
P233=-98.5919 ;15.6133
P234=-98.1351 ;15.0655
P235=-97.6783 ;14.5178
P236=-97.3425 ;13.9992
P237=-97.6453 ;14.0934
P238=-98.5315 ;14.7725
P239=-99.0485 ;15.2938
P240=-99.5656 ;15.8151
P241=-100.1102;16.4947
P242=-100.6548;17.1743
P243=-101.2170;17.9855
P244=-101.7792;18.7967
P245=-102.6207;19.8356
P246=-103.0691;19.9981
P247=-103.1259;19.2917
P248=-102.8879;18.1969
P249=-102.4129;17.0019
P250=-102.0569;16.3542
P251=-101.7010;15.7065
P252=-101.2402;15.0240
P253=-100.7794;14.3414
P254=-100.2967;13.7171
P255=-99.8140 ;13.0927
P256=-99.3232 ;12.5421
P257=-98.8325 ;11.9915
P258=-98.3335 ;11.5145
P259=-97.8344 ;11.0374
P260=-97.2947 ;10.6039
P261=-96.7551 ;10.1704
P262=-96.1516 ;9.7590
P263=-95.5480 ;9.3476
P264=-94.8861 ;8.9608
P265=-94.2241 ;8.5741
P266=-93.5567 ;8.2364
P267=-92.8893 ;7.8987
P268=-92.2298 ;7.6162

P269=-91.5703 ;7.3337
P270=-90.9186 ;7.1063
P271=-90.2670 ;6.8790
P272=-88.9610 ;6.5316
P273=-88.2583 ;6.4035
P274=-87.5556 ;6.2754
P275=-86.7963 ;6.1917
P276=-86.0369 ;6.1079
P277=-85.2210 ;6.0686
P278=-84.4051 ;6.0293
P279=-83.5482 ;6.0350
P280=-82.6913 ;6.0406
P281=-81.9253 ;6.0965
P282=-81.1593 ;6.1525
P283=-79.8684 ;6.3673
P284=-78.8188 ;6.6850
P285=-78.0106 ;7.1054
P286=-77.6921 ;7.4830
P287=-78.0854 ;7.6876
P288=-79.1903 ;7.7191
P289=-80.0954 ;7.6494
P290=-81.0005 ;7.5796
P291=-81.9716 ;7.5104
P292=-82.9428 ;7.4412
P293=-83.7944 ;7.4283
P294=-84.6461 ;7.4155
P295=-85.3783 ;7.4590
P296=-86.1104 ;7.5026
P297=-87.3358 ;7.7023
P298=-88.4777 ;8.0396
P299=-89.1418 ;8.2986
P300=-89.8059 ;8.5576
P301=-90.5657 ;8.9074
P302=-91.3254 ;9.2571
P303=-92.1403 ;9.6789
P304=-92.9551 ;10.1007
P305=-93.5798 ;10.4815
P306=-94.2045 ;10.8623
P307=-94.9910 ;11.5038
P308=-95.3104 ;12.0120
P309=-95.0907 ;12.1641
P310=-94.3062 ;11.8805
P311=-93.6316 ;11.5209
P312=-92.9569 ;11.1614
P313=-92.1113 ;10.6922
P314=-91.2656 ;10.2231
P315=-90.4791 ;9.8683
P316=-89.6926 ;9.5135
P317=-88.9722 ;9.2799
P318=-88.2518 ;9.0462
P319=-86.9434 ;8.8210
P320=-85.7089 ;8.7950
P321=-84.3509 ;8.8219
P322=-83.6020 ;8.8559
P323=-82.8530 ;8.8898
P324=-82.0342 ;8.9443
P325=-81.2154 ;8.9988

P326=-80.3428 ;9.0761
P327=-79.4703 ;9.1534
P328=-78.7016 ;9.2766
P329=-77.9330 ;9.3998
P330=-76.6833 ;9.7497
P331=-75.7210 ;10.2031
P332=-75.0636 ;10.7454
P333=-75.0310 ;11.1074
P334=-75.7435 ;11.1880
P335=-76.4724 ;11.0876
P336=-77.2013 ;10.9871
P337=-78.1863 ;10.7946
P338=-79.1713 ;10.6020
P339=-80.0648 ;10.4626
P340=-80.9583 ;10.3231
P341=-81.7371 ;10.2465
P342=-82.5159 ;10.1698
P343=-83.8439 ;10.1421
P344=-84.9792 ;10.2462
P345=-86.2374 ;10.5350
P346=-86.9642 ;10.7779
P347=-87.6911 ;11.0207
P348=-88.5157 ;11.3619
P349=-89.3404 ;11.7032
P350=-90.2222 ;12.1217
P351=-91.1040 ;12.5402
P352=-92.2265 ;13.1358
P353=-92.5235 ;13.3933
P354=-91.9964 ;13.3135
P355=-91.0055 ;13.0547
P356=-89.8242 ;12.7371
P357=-89.1384 ;12.5488
P358=-88.4525 ;12.3605
P359=-87.6720 ;12.1433
P360=-86.8914 ;11.9261
P361=-86.0978 ;11.7461
P362=-85.3042 ;11.5662
P363=-84.5554 ;11.4705
P364=-83.8066 ;11.3749
P365=-83.1025 ;11.3635
P366=-82.3985 ;11.3522
P367=-81.0801 ;11.4981
P368=-79.7547 ;11.7825
P369=-79.0349 ;11.9771
P370=-78.3150 ;12.1718
P371=-77.5380 ;12.4189
P372=-76.7610 ;12.6660
P373=-75.9268 ;12.9656
P374=-75.0926 ;13.2651
P375=-74.3963 ;13.5531
P376=-73.7001 ;13.8412
P377=-73.2241 ;14.1845
P378=-73.6739 ;14.2920
P379=-75.0323 ;14.1672
P380=-75.8296 ;14.0578
P381=-76.6269 ;13.9485
P382=-77.3690 ;13.8280

P383=-78.1110 ;13.7075
P384=-78.7979 ;13.5757
P385=-79.4848 ;13.4440
P386=-80.7483 ;13.1583
P387=-82.0500 ;12.9958
P388=-82.7848 ;13.0399
P389=-83.5196 ;13.0841
P390=-84.3385 ;13.2536
P391=-85.1573 ;13.4231
P392=-86.0602 ;13.7181
P393=-86.9631 ;14.0130
P394=-87.8222 ;14.3626
P395=-88.6813 ;14.7123
P396=-89.7093 ;15.1876
P397=-90.0217 ;15.4250
P398=-89.6235 ;15.4262
P399=-88.8062 ;15.2963
P400=-87.7401 ;15.0968
P401=-86.4252 ;14.8275
P402=-85.6454 ;14.6599
P403=-84.8657 ;14.4922
P404=-84.0555 ;14.3715
P405=-83.2454 ;14.2509
P406=-82.4544 ;14.2206
P407=-81.6633 ;14.1903
P408=-80.8914 ;14.2503
P409=-80.1196 ;14.3103
P410=-79.3670 ;14.4607
P411=-78.6143 ;14.6110
P412=-77.8974 ;14.8306
P413=-77.1806 ;15.0501
P414=-76.5245 ;15.3076
P415=-75.8684 ;15.5650
P416=-74.6782 ;16.1551
P417=-73.6099 ;16.8203
P418=-72.8911 ;17.3942
P419=-72.8294 ;17.6519
P420=-73.4264 ;17.5920
P421=-74.6820 ;17.2147
P422=-75.5388 ;16.9465
P423=-76.3956 ;16.6782
P424=-77.2651 ;16.5007
P425=-78.1346 ;16.3232
P426=-79.0096 ;16.2423
P427=-79.8846 ;16.1614
P428=-80.7650 ;16.1770
P429=-81.6454 ;16.1927
P430=-82.4840 ;16.2858
P431=-83.3226 ;16.3789
P432=-84.5786 ;16.5840
P433=-85.3834 ;16.7958
P434=-85.7370 ;17.0144
P435=-85.6472 ;17.2241
P436=-85.1498 ;17.3528
P437=-84.2493 ;17.3917
P438=-82.9456 ;17.3408
P439=-82.1030 ;17.2779

P440=-81.2604 ;17.2150
P441=-80.3863 ;17.2255
P442=-79.5122 ;17.2359
P443=-78.6595 ;17.3564
P444=-77.8068 ;17.4770
P445=-76.9755 ;17.7076
P446=-76.1442 ;17.9382
P447=-75.3372 ;18.2765
P448=-74.5301 ;18.6148
P449=-73.8710 ;18.9612
P450=-73.2119 ;19.3076
P451=-72.3210 ;19.9105
P452=-71.8574 ;20.4236
P453=-71.8241 ;20.8289
P454=-72.2455 ;20.9842
P455=-73.1270 ;20.8591
P456=-74.4684 ;20.4536
P457=-75.3352 ;20.1439
P458=-76.2020 ;19.8342
P459=-77.0682 ;19.6101
P460=-77.9345 ;19.3860
P461=-78.7684 ;19.2786
P462=-79.6023 ;19.1712
P463=-80.4040 ;19.1805
P464=-81.2057 ;19.1898
P465=-81.9702 ;19.3136
P466=-82.7346 ;19.4373
P467=-83.7244 ;19.7086
P468=-83.9203 ;19.8913
P469=-83.3223 ;19.9852
P470=-81.9419 ;19.9931
P471=-81.1416 ;20.0169
P472=-80.3413 ;20.0408
P473=-79.5872 ;20.1196
P474=-78.8330 ;20.1985
P475=-78.1248 ;20.3323
P476=-77.4167 ;20.4660
P477=-76.0926 ;20.8435
P478=-74.7851 ;21.3291
P479=-74.1046 ;21.6252
P480=-73.4241 ;21.9214
P481=-72.7169 ;22.2708
P482=-72.0097 ;22.6203
P483=-71.2757 ;23.0231
P484=-70.5418 ;23.4259
P485=-69.3812 ;24.1581
P486=-69.0185 ;24.5721
P487=-69.4565 ;24.6666
P488=-70.6482 ;24.4602
P489=-71.3829 ;24.3011
P490=-72.1177 ;24.1420
P491=-72.9293 ;23.9516
P492=-73.7410 ;23.7612
P493=-74.6295 ;23.5396
P494=-75.5181 ;23.3179
P495=-76.4500 ;23.0768
P496=-77.3818 ;22.8357

P497=-78.7923 ;22.5049
P498=-79.6325 ;22.3668
P499=-79.9025 ;22.4213
P500=-79.6099 ;22.6637
P501=-78.9390 ;22.9777
P502=-77.9680 ;23.3139
P503=-76.6970 ;23.6725
P504=-75.9114 ;23.8629
P505=-75.1258 ;24.0533
P506=-74.2904 ;24.2718
P507=-73.4549 ;24.4904
P508=-72.6938 ;24.7582
P509=-71.9327 ;25.0259
P510=-71.2462 ;25.3429
P511=-70.5598 ;25.6600
P512=-69.3363 ;26.3925
P513=-68.1822 ;27.1619
P514=-67.0193 ;27.9077
P515=-65.8474 ;28.6297
P516=-64.6664 ;29.3284
P517=-63.4369 ;30.0590
P518=-62.7834 ;30.4606
P519=-62.1299 ;30.8622
P520=-61.4376 ;31.3001
P521=-60.7452 ;31.7380
P522=-60.0176 ;32.2084
P523=-59.2900 ;32.6788
P524=-57.9846 ;33.4443
P525=-56.9334 ;33.9208
P526=-56.1364 ;34.1085
P527=-55.6323 ;33.9968
P528=-55.8955 ;33.4589
P529=-56.4809 ;32.9581
P530=-57.0662 ;32.4573
P531=-57.9779 ;31.7946
P532=-58.8896 ;31.1318
P533=-59.5343 ;30.6329
P534=-60.1791 ;30.1339
P535=-60.7848 ;29.5457
P536=-60.7066 ;29.3672
P537=-60.0608 ;29.5484
P538=-58.9816 ;30.0313
P539=-58.2254 ;30.4236
P540=-57.4693 ;30.8159
P541=-56.4973 ;31.3584
P542=-55.5253 ;31.9009
P543=-54.6426 ;32.3719
P544=-53.7598 ;32.8428
P545=-52.6692 ;33.2803
P546=-52.2535 ;33.2135
P547=-52.5032 ;32.6501
P548=-52.9804 ;31.9457
P549=-53.4475 ;31.2936
P550=-53.9045 ;30.6938
P551=-54.3199 ;30.1632
P552=-54.2696 ;29.9326
P553=-53.6199 ;30.0744

P554=-52.3708 ;30.5889
P555=-51.4704 ;31.0172
P556=-50.5700 ;31.4455
P557=-49.6856 ;31.8588
P558=-48.8013 ;32.2721
P559=-48.0195 ;32.6152
P560=-47.2377 ;32.9582
P561=-45.8791 ;33.5040
P562=-44.7119 ;33.9179
P563=-43.5272 ;34.3296
P564=-42.2546 ;34.7828
P565=-40.8940 ;35.2777
P566=-39.4468 ;35.8132
P567=-37.9855 ;36.3390
P568=-36.5520 ;36.8262
P569=-35.1463 ;37.2748
P570=-33.7675 ;37.6849
P571=-32.3876 ;38.0631
P572=-30.9931 ;38.4125
P573=-29.5838 ;38.7332
P574=-28.1598 ;39.0251
P575=-26.7211 ;39.2883
P576=-25.2678 ;39.5227
P577=-23.7998 ;39.7283
P578=-22.3570 ;39.9007
[C24]
gain=-15.00
n_point=111
P1=-71.0937 ;47.2294
P2=-71.4557 ;47.0850
P3=-71.8177 ;46.9407
P4=-72.1308 ;46.7907
P5=-72.4439 ;46.6408
P6=-72.7106 ;46.4953
P7=-72.9324 ;46.3660
P8=-73.2388 ;46.1747
P9=-73.5451 ;45.9835
P10=-73.8770 ;45.7458
P11=-74.2088 ;45.5081
P12=-74.2958 ;45.4390
P13=-74.3555 ;45.3903
P14=-74.6956 ;45.0928
P15=-75.0357 ;44.7952
P16=-75.3624 ;44.4712
P17=-75.6909 ;44.1158
P18=-75.8802 ;43.8916
P19=-76.0695 ;43.6675
P20=-76.2065 ;43.4795
P21=-76.2799 ;43.3781
P22=-76.5287 ;43.0116
P23=-76.6599 ;42.7870
P24=-76.7910 ;42.5624
P25=-76.8424 ;42.4645
P26=-76.9074 ;42.3278
P27=-77.0469 ;41.9784
P28=-77.1865 ;41.6289
P29=-77.2458 ;41.4269

P30=-77.2907 ;41.2255
P31=-77.3258 ;40.8453
P32=-77.3609 ;40.4650
P33=-77.3598 ;40.3651
P34=-77.3591 ;40.3000
P35=-77.3353 ;40.0812
P36=-77.2655 ;39.7952
P37=-77.1956 ;39.5092
P38=-77.0987 ;39.2712
P39=-76.9714 ;39.0522
P40=-76.8441 ;38.8332
P41=-76.6486 ;38.5988
P42=-76.4532 ;38.3644
P43=-76.3319 ;38.2583
P44=-76.1743 ;38.1239
P45=-75.9205 ;37.9511
P46=-75.6666 ;37.7784
P47=-75.3428 ;37.6145
P48=-74.8304 ;37.4055
P49=-74.6401 ;37.3528
P50=-74.1371 ;37.2763
P51=-73.6392 ;37.2482
P52=-73.3901 ;37.2504
P53=-72.8414 ;37.2896
P54=-72.3374 ;37.3757
P55=-71.9759 ;37.4758
P56=-71.6144 ;37.5759
P57=-71.4458 ;37.6335
P58=-71.3471 ;37.6728
P59=-70.9496 ;37.8425
P60=-70.5520 ;38.0121
P61=-70.2360 ;38.1814
P62=-69.9200 ;38.3507
P63=-69.7453 ;38.4451
P64=-69.5832 ;38.5436
P65=-69.2822 ;38.7369
P66=-68.9812 ;38.9302
P67=-68.6515 ;39.1636
P68=-68.3218 ;39.3970
P69=-68.2531 ;39.4500
P70=-68.2164 ;39.4782
P71=-67.8720 ;39.7536
P72=-67.5275 ;40.0289
P73=-67.1298 ;40.3690
P74=-66.8344 ;40.6382
P75=-66.5076 ;40.9591
P76=-66.1808 ;41.2800
P77=-66.1436 ;41.3179
P78=-65.8344 ;41.6581
P79=-65.5252 ;41.9983
P80=-65.3287 ;42.2474
P81=-65.0370 ;42.6387
P82=-64.9346 ;42.7874
P83=-64.6678 ;43.2123
P84=-64.5426 ;43.4561
P85=-64.4173 ;43.6998
P86=-64.3208 ;43.9530

P87=-64.2243 ;44.2063
P88=-64.1286 ;44.6090
P89=-64.0955 ;44.9129
P90=-64.1174 ;45.2497
P91=-64.1327 ;45.3806
P92=-64.1947 ;45.6063
P93=-64.4236 ;46.0273
P94=-64.7982 ;46.4078
P95=-64.9998 ;46.5571
P96=-65.1242 ;46.6393
P97=-65.4762 ;46.8235
P98=-65.8524 ;46.9712
P99=-66.3380 ;47.1559
P100=-66.8687 ;47.3189
P101=-67.1367 ;47.3867
P102=-67.6510 ;47.4970
P103=-68.1161 ;47.5678
P104=-68.5592 ;47.6065
P105=-69.0798 ;47.6144
P106=-69.4298 ;47.5831
P107=-69.7798 ;47.5519
P108=-70.0533 ;47.5061
P109=-70.6735 ;47.3642
P110=-70.8491 ;47.3111
P111=-71.0937 ;47.2294
[C25]
gain=-8.00
n_point=99
P1=-70.5516 ;46.0943
P2=-71.0354 ;45.9799
P3=-71.3018 ;45.8929
P4=-71.6510 ;45.7617
P5=-72.0003 ;45.6305
P6=-72.3647 ;45.4516
P7=-72.7291 ;45.2727
P8=-72.8757 ;45.1889
P9=-73.0465 ;45.0850
P10=-73.3628 ;44.8736
P11=-73.6790 ;44.6622
P12=-73.8791 ;44.5028
P13=-74.0792 ;44.3433
P14=-74.2402 ;44.1997
P15=-74.4012 ;44.0561
P16=-74.6126 ;43.8308
P17=-74.8241 ;43.6054
P18=-75.0355 ;43.3800
P19=-75.2214 ;43.1167
P20=-75.4073 ;42.8534
P21=-75.5933 ;42.5901
P22=-75.7151 ;42.3612
P23=-75.8768 ;42.0398
P24=-75.9445 ;41.8566
P25=-76.0122 ;41.6734
P26=-76.1016 ;41.3256
P27=-76.1531 ;41.0090
P28=-76.1542 ;40.7346
P29=-76.1553 ;40.4601

P30=-76.1348 ;40.2589
P31=-76.1130 ;40.1560
P32=-76.0477 ;39.9362
P33=-75.9212 ;39.7004
P34=-75.7946 ;39.4646
P35=-75.6601 ;39.2998
P36=-75.5256 ;39.1350
P37=-75.2514 ;38.9096
P38=-75.0425 ;38.7698
P39=-74.7541 ;38.6395
P40=-74.4656 ;38.5092
P41=-74.1569 ;38.4303
P42=-73.8482 ;38.3513
P43=-73.5834 ;38.3289
P44=-73.3186 ;38.3064
P45=-73.1227 ;38.3080
P46=-72.8311 ;38.3324
P47=-72.5395 ;38.3568
P48=-72.3054 ;38.4013
P49=-72.0713 ;38.4459
P50=-71.6485 ;38.5829
P51=-71.2257 ;38.7200
P52=-71.1533 ;38.7488
P53=-71.1019 ;38.7692
P54=-70.7109 ;38.9589
P55=-70.3200 ;39.1486
P56=-69.9574 ;39.3758
P57=-69.5947 ;39.6030
P58=-69.5440 ;39.6370
P59=-69.4793 ;39.6803
P60=-69.1478 ;39.9318
P61=-68.8163 ;40.1833
P62=-68.6208 ;40.3542
P63=-68.4254 ;40.5251
P64=-68.1313 ;40.8003
P65=-67.9303 ;41.0137
P66=-67.7294 ;41.2270
P67=-67.5284 ;41.4404
P68=-67.5014 ;41.4723
P69=-67.4439 ;41.5404
P70=-67.2631 ;41.7795
P71=-67.0823 ;42.0185
P72=-66.9015 ;42.2575
P73=-66.7800 ;42.4378
P74=-66.6389 ;42.6789
P75=-66.5175 ;42.9167
P76=-66.3962 ;43.1545
P77=-66.2896 ;43.4319
P78=-66.2054 ;43.6783
P79=-66.1619 ;44.0324
P80=-66.1184 ;44.3865
P81=-66.1279 ;44.4710
P82=-66.1400 ;44.5789
P83=-66.2569 ;44.8800
P84=-66.3738 ;45.1810
P85=-66.5901 ;45.4020
P86=-66.8065 ;45.6229

P87=-66.9449 ;45.7155
P88=-67.0242 ;45.7608
P89=-67.2322 ;45.8671
P90=-67.5518 ;45.9793
P91=-67.8713 ;46.0916
P92=-68.2856 ;46.1721
P93=-68.7436 ;46.2247
P94=-69.0252 ;46.2314
P95=-69.3068 ;46.2382
P96=-69.7187 ;46.2158
P97=-69.9561 ;46.1887
P98=-70.2539 ;46.1415
P99=-70.5516 ;46.0943