

```
[FormatInfo]
format_ver=1
[GeoMain]
ntc_id=910100000
adm=USA
sat_name=USABSS-21
long_nom=-101.0000
n_diag=1
[COHeader]
beam_id=RB04
emi_rcp=E
polar_disc=C
reason=B
n_bore=1
n_cont=26
[B1]
gain=0.00
p=-79.9150;40.2070
[C1]
gain=-50.00
n_point=559
P1=-84.2128 ;80.9211
P2=-85.3657 ;80.2702
P3=-86.6028 ;79.5078
P4=-87.7969 ;78.7001
P5=-88.9481 ;77.8472
P6=-90.0563 ;76.9489
P7=-91.1217 ;76.0053
P8=-92.1440 ;75.0164
P9=-93.1235 ;73.9822
P10=-94.0600 ;72.9027
P11=-94.9536 ;71.7779
P12=-95.8025 ;70.6097
P13=-96.5948 ;69.4098
P14=-97.3283 ;68.1807
P15=-98.0030 ;66.9222
P16=-98.6219 ;65.6356
P17=-99.2090 ;64.3297
P18=-99.7693 ;63.0065
P19=-100.0360;62.3362
P20=-100.3027;61.6659
P21=-100.5563;60.9895
P22=-100.8098;60.3132
P23=-101.0507;59.6376
P24=-101.2915;58.9621
P25=-101.5197;58.2878
P26=-101.7479;57.6136
P27=-101.9635;56.9403
P28=-102.1792;56.2669
P29=-102.3844;55.5818
P30=-102.5895;54.8968
P31=-102.7853;54.1934
P32=-102.9811;53.4900
P33=-103.1674;52.7686
P34=-103.3538;52.0472
P35=-103.5161;51.3369
P36=-103.6783;50.6266
```

P37=-103.8069;49.9469
P38=-103.9354;49.2672
P39=-104.1250;47.9690
P40=-104.1884;47.2824
P41=-104.2518;46.5959
P42=-104.2860;45.8095
P43=-104.3202;45.0231
P44=-104.3251;44.1369
P45=-104.3301;43.2507
P46=-104.2928;42.5708
P47=-104.2554;41.8908
P48=-104.0681;41.5924
P49=-103.7682;42.3557
P50=-103.5822;43.0552
P51=-103.3962;43.7547
P52=-103.2046;44.4504
P53=-103.0130;45.1460
P54=-102.8161;45.8345
P55=-102.6193;46.5230
P56=-102.4159;47.2058
P57=-102.2124;47.8886
P58=-101.9930;48.5751
P59=-101.7737;49.2617
P60=-101.5367;49.9539
P61=-101.2997;50.6461
P62=-101.0450;51.3435
P63=-100.7904;52.0410
P64=-100.5231;52.7185
P65=-100.2558;53.3960
P66=-99.7012 ;54.6832
P67=-99.1267 ;55.9023
P68=-98.5186 ;57.0739
P69=-97.8124 ;58.2941
P70=-96.9996 ;59.5754
P71=-96.5400 ;60.2465
P72=-96.0804 ;60.9176
P73=-95.5732 ;61.6118
P74=-95.0660 ;62.3061
P75=-94.1320 ;63.5125
P76=-93.3384 ;64.4588
P77=-92.6852 ;65.1450
P78=-92.1751 ;65.5689
P79=-91.9782 ;65.6032
P80=-92.1949 ;65.1725
P81=-92.8252 ;64.2766
P82=-93.3464 ;63.5968
P83=-93.8677 ;62.9171
P84=-94.4267 ;62.1716
P85=-94.9857 ;61.4262
P86=-95.4539 ;60.7417
P87=-95.9221 ;60.0573
P88=-96.6771 ;58.8106
P89=-97.2506 ;57.6860
P90=-97.7381 ;56.5630
P91=-98.2561 ;55.2950
P92=-98.5304 ;54.5883
P93=-98.8047 ;53.8817

P94=-99.0807 ;53.1400
P95=-99.3566 ;52.3983
P96=-99.6022 ;51.7085
P97=-99.8478 ;51.0187
P98=-100.2758;49.7501
P99=-100.6458;48.5557
P100=-100.8203;47.8665
P101=-100.9948;47.1772
P102=-101.1623;46.3709
P103=-101.3298;45.5647
P104=-101.4820;44.6658
P105=-101.6342;43.7669
P106=-101.6712;43.0670
P107=-101.7082;42.3670
P108=-101.4936;41.5349
P109=-101.0121;41.2713
P110=-100.5148;41.5863
P111=-100.0736;42.4827
P112=-99.8805 ;43.2192
P113=-99.6873 ;43.9556
P114=-99.4782 ;44.7846
P115=-99.2692 ;45.6137
P116=-99.0165 ;46.4104
P117=-98.7639 ;47.2071
P118=-98.4675 ;47.9715
P119=-98.1712 ;48.7358
P120=-97.8499 ;49.4354
P121=-97.5286 ;50.1350
P122=-96.9313 ;51.2393
P123=-96.3842 ;52.0406
P124=-95.8882 ;52.5376
P125=-95.6403 ;52.5107
P126=-95.7857 ;51.7981
P127=-96.0549 ;51.0989
P128=-96.3242 ;50.3996
P129=-96.7123 ;49.4904
P130=-97.1005 ;48.5812
P131=-97.4147 ;47.7914
P132=-97.7289 ;47.0017
P133=-98.1913 ;45.6922
P134=-98.4981 ;44.5952
P135=-98.7227 ;43.3030
P136=-98.8010 ;42.5195
P137=-98.8794 ;41.7360
P138=-98.9208 ;40.8393
P139=-98.9622 ;39.9425
P140=-98.8636 ;38.7797
P141=-98.5439 ;38.5638
P142=-98.0068 ;39.2850
P143=-97.4202 ;40.5064
P144=-97.1471 ;41.2499
P145=-96.8741 ;41.9934
P146=-96.6214 ;42.8696
P147=-96.3686 ;43.7459
P148=-96.1361 ;44.5445
P149=-95.9037 ;45.3431
P150=-95.4797 ;46.3124

P151=-95.0964 ;46.6534
P152=-94.7924 ;46.3875
P153=-94.7953 ;45.6427
P154=-95.1429 ;44.4399
P155=-95.4700 ;43.6270
P156=-95.7970 ;42.8142
P157=-96.0486 ;42.0002
P158=-96.3002 ;41.1862
P159=-96.4094 ;40.4326
P160=-96.5186 ;39.6790
P161=-96.4857 ;38.9857
P162=-96.4529 ;38.2924
P163=-96.3268 ;36.9659
P164=-96.3183 ;35.6514
P165=-96.4275 ;34.3488
P166=-96.4670 ;33.6732
P167=-96.5065 ;32.9976
P168=-96.4151 ;32.2502
P169=-96.3236 ;31.5027
P170=-96.0997 ;30.6828
P171=-95.8757 ;29.8628
P172=-95.5695 ;29.0373
P173=-95.2632 ;28.2118
P174=-94.7821 ;26.9456
P175=-94.4522 ;26.0903
P176=-94.2734 ;25.6458
P177=-94.3435 ;25.5775
P178=-94.7463 ;25.8554
P179=-95.4818 ;26.4795
P180=-96.0160 ;26.9646
P181=-96.5501 ;27.4498
P182=-97.6514 ;28.3763
P183=-98.1185 ;28.3913
P184=-97.9272 ;27.4632
P185=-97.5302 ;26.5794
P186=-97.1332 ;25.6957
P187=-96.6794 ;24.8471
P188=-96.2256 ;23.9986
P189=-95.7720 ;23.2914
P190=-95.3184 ;22.5842
P191=-94.8651 ;22.0184
P192=-94.4118 ;21.4526
P193=-93.6516 ;20.6812
P194=-93.5178 ;20.5245
P195=-94.0479 ;21.0024
P196=-94.6449 ;21.5587
P197=-95.2419 ;22.1150
P198=-95.9999 ;22.7938
P199=-96.7578 ;23.4725
P200=-97.8940 ;24.2753
P201=-98.6296 ;24.4996
P202=-98.9650 ;24.1524
P203=-98.9195 ;23.4621
P204=-98.5022 ;22.5379
P205=-98.1077 ;21.9588
P206=-97.7133 ;21.3798
P207=-97.1509 ;20.7071

P208=-96.5886 ;20.0343
P209=-95.9949 ;19.4431
P210=-95.4013 ;18.8519
P211=-94.8046 ;18.3786
P212=-94.2079 ;17.9053
P213=-93.0084 ;17.1945
P214=-91.9736 ;16.7294
P215=-91.7668 ;16.5487
P216=-92.4543 ;16.6562
P217=-93.1553 ;16.8524
P218=-93.8562 ;17.0487
P219=-94.5663 ;17.3811
P220=-95.2763 ;17.7135
P221=-95.9609 ;18.1816
P222=-96.6454 ;18.6496
P223=-97.3045 ;19.2531
P224=-97.9636 ;19.8567
P225=-98.5409 ;20.4550
P226=-99.1183 ;21.0532
P227=-99.8234 ;21.5209
P228=-100.0645;21.2241
P229=-99.8508 ;20.1985
P230=-99.3319 ;19.0317
P231=-98.5607 ;17.9309
P232=-98.0490 ;17.4135
P233=-97.5372 ;16.8961
P234=-96.9130 ;16.4167
P235=-96.2889 ;15.9372
P236=-95.6457 ;15.5290
P237=-95.0025 ;15.1208
P238=-94.3577 ;14.7902
P239=-93.7128 ;14.4596
P240=-93.0660 ;14.2060
P241=-92.4192 ;13.9524
P242=-91.0946 ;13.5647
P243=-90.4104 ;13.4223
P244=-89.7263 ;13.2800
P245=-89.0203 ;13.1891
P246=-88.3142 ;13.0983
P247=-87.5965 ;13.0767
P248=-86.8787 ;13.0552
P249=-86.1615 ;13.1240
P250=-85.4443 ;13.1928
P251=-84.7276 ;13.3521
P252=-84.0109 ;13.5114
P253=-83.3068 ;13.7353
P254=-82.6028 ;13.9591
P255=-81.9380 ;14.1910
P256=-81.2732 ;14.4230
P257=-80.0239 ;14.8991
P258=-78.8506 ;15.3912
P259=-77.6419 ;16.0002
P260=-76.9953 ;16.3853
P261=-76.3488 ;16.7703
P262=-75.6600 ;17.2360
P263=-74.9713 ;17.7016
P264=-74.2529 ;18.2329

P265=-73.5345 ;18.7641
P266=-72.9294 ;19.1891
P267=-72.3243 ;19.6142
P268=-71.4221 ;20.1543
P269=-70.8277 ;20.3844
P270=-70.5977 ;20.3086
P271=-70.8661 ;19.9363
P272=-71.6385 ;19.2679
P273=-72.2768 ;18.7857
P274=-72.9151 ;18.3034
P275=-73.6947 ;17.7544
P276=-74.4744 ;17.2055
P277=-75.1894 ;16.7411
P278=-75.9044 ;16.2766
P279=-76.5501 ;15.9001
P280=-77.1958 ;15.5235
P281=-78.3486 ;14.9464
P282=-79.4798 ;14.4630
P283=-80.7264 ;13.9770
P284=-81.4077 ;13.7326
P285=-82.0889 ;13.4883
P286=-82.8104 ;13.2684
P287=-83.5319 ;13.0486
P288=-84.2484 ;12.9194
P289=-84.9649 ;12.7902
P290=-85.6743 ;12.7550
P291=-86.3837 ;12.7198
P292=-87.0879 ;12.7626
P293=-87.7920 ;12.8055
P294=-88.5005 ;12.8518
P295=-89.2090 ;12.8981
P296=-89.9230 ;12.9384
P297=-90.6371 ;12.9786
P298=-91.3535 ;13.0261
P299=-92.0698 ;13.0736
P300=-92.7637 ;13.2317
P301=-93.4576 ;13.3898
P302=-94.1240 ;13.6803
P303=-94.7903 ;13.9708
P304=-95.4290 ;14.3937
P305=-96.0677 ;14.8166
P306=-96.6760 ;15.2881
P307=-97.2844 ;15.7597
P308=-97.8587 ;16.1644
P309=-98.4331 ;16.5690
P310=-99.5136 ;17.2433
P311=-100.5215;17.7786
P312=-101.1061;17.8768
P313=-101.0461;17.3500
P314=-100.3413;16.1980
P315=-99.7458 ;15.4276
P316=-99.1503 ;14.6572
P317=-98.5493 ;14.0470
P318=-97.9484 ;13.4367
P319=-97.3580 ;13.0105
P320=-96.7677 ;12.5844
P321=-95.6005 ;12.0770

P322=-94.3614 ;11.6573
P323=-93.6940 ;11.4556
P324=-93.0267 ;11.2538
P325=-92.3116 ;11.0601
P326=-91.5966 ;10.8665
P327=-90.8599 ;10.7062
P328=-90.1233 ;10.5458
P329=-89.4051 ;10.4572
P330=-88.6868 ;10.3685
P331=-87.9874 ;10.3520
P332=-87.2880 ;10.3354
P333=-86.5982 ;10.3891
P334=-85.9085 ;10.4428
P335=-85.2047 ;10.5620
P336=-84.5009 ;10.6813
P337=-83.7820 ;10.8659
P338=-83.0630 ;11.0505
P339=-82.3425 ;11.2890
P340=-81.6221 ;11.5276
P341=-80.9520 ;11.7770
P342=-80.2820 ;12.0265
P343=-79.0526 ;12.5387
P344=-77.9269 ;13.0687
P345=-76.7319 ;13.7213
P346=-76.0627 ;14.1313
P347=-75.3935 ;14.5413
P348=-74.6525 ;15.0352
P349=-73.9115 ;15.5290
P350=-73.1621 ;16.0457
P351=-72.4127 ;16.5624
P352=-71.3162 ;17.2388
P353=-70.6554 ;17.5263
P354=-70.4301 ;17.4252
P355=-70.6462 ;17.0302
P356=-71.3085 ;16.4198
P357=-72.4170 ;15.5937
P358=-73.1663 ;15.0904
P359=-73.9155 ;14.5872
P360=-74.6403 ;14.1309
P361=-75.3651 ;13.6746
P362=-76.0187 ;13.2944
P363=-76.6724 ;12.9141
P364=-77.8374 ;12.3059
P365=-78.9857 ;11.7860
P366=-80.2469 ;11.2888
P367=-80.9338 ;11.0515
P368=-81.6208 ;10.8143
P369=-82.3492 ;10.5977
P370=-83.0775 ;10.3811
P371=-83.7948 ;10.2179
P372=-84.5120 ;10.0547
P373=-85.2136 ;9.9476
P374=-85.9153 ;9.8406
P375=-86.6039 ;9.7895
P376=-87.2926 ;9.7385
P377=-87.9978 ;9.7413
P378=-88.7030 ;9.7441

P379=-89.4329 ;9.8001
P380=-90.1628 ;9.8561
P381=-90.9143 ;9.9638
P382=-91.6657 ;10.0716
P383=-92.3839 ;10.2050
P384=-93.1021 ;10.3385
P385=-94.4322 ;10.6380
P386=-95.6566 ;10.9712
P387=-96.8778 ;11.4913
P388=-97.5224 ;11.8983
P389=-98.1670 ;12.3053
P390=-98.8456 ;12.8593
P391=-99.5241 ;13.4132
P392=-100.1956;14.0422
P393=-100.8672;14.6713
P394=-101.7599;15.3159
P395=-102.1380;15.2349
P396=-102.0016;14.4281
P397=-101.4484;13.1969
P398=-101.0501;12.6367
P399=-100.6519;12.0765
P400=-100.1337;11.5770
P401=-99.6155 ;11.0775
P402=-98.9902 ;10.6404
P403=-98.3648 ;10.2034
P404=-97.7138 ;9.8401
P405=-97.0629 ;9.4769
P406=-96.4008 ;9.1895
P407=-95.7387 ;8.9020
P408=-95.0655 ;8.6904
P409=-94.3923 ;8.4787
P410=-93.7066 ;8.3287
P411=-93.0210 ;8.1787
P412=-92.3205 ;8.0658
P413=-91.6201 ;7.9528
P414=-90.9050 ;7.8765
P415=-90.1898 ;7.8002
P416=-89.4649 ;7.7643
P417=-88.7399 ;7.7284
P418=-88.0201 ;7.7439
P419=-87.3004 ;7.7595
P420=-86.5870 ;7.8273
P421=-85.8735 ;7.8950
P422=-85.1675 ;8.0132
P423=-84.4615 ;8.1313
P424=-83.7674 ;8.2937
P425=-83.0733 ;8.4561
P426=-82.3914 ;8.6622
P427=-81.7096 ;8.8683
P428=-81.0399 ;9.1175
P429=-80.3701 ;9.3668
P430=-79.7097 ;9.6412
P431=-79.0494 ;9.9155
P432=-78.3969 ;10.2064
P433=-77.7445 ;10.4974
P434=-77.1001 ;10.8049
P435=-76.4556 ;11.1124

P436=-75.8190 ;11.4366
P437=-75.1825 ;11.7608
P438=-74.5529 ;12.1026
P439=-73.9234 ;12.4444
P440=-73.3007 ;12.8041
P441=-72.6780 ;13.1637
P442=-72.0621 ;13.5412
P443=-71.4463 ;13.9187
P444=-70.8405 ;14.3119
P445=-70.2346 ;14.7051
P446=-69.6449 ;15.1099
P447=-69.0552 ;15.5147
P448=-68.4818 ;15.9309
P449=-67.9084 ;16.3471
P450=-67.3502 ;16.7761
P451=-66.7920 ;17.2051
P452=-66.2395 ;17.6578
P453=-65.6870 ;18.1106
P454=-65.1381 ;18.5896
P455=-64.5891 ;19.0685
P456=-64.0437 ;19.5738
P457=-63.4983 ;20.0791
P458=-62.9555 ;20.5936
P459=-62.4127 ;21.1081
P460=-61.8692 ;21.5695
P461=-61.3256 ;22.0308
P462=-60.2364 ;22.8358
P463=-59.1436 ;23.5259
P464=-57.9817 ;24.2326
P465=-57.3489 ;24.6292
P466=-56.7161 ;25.0258
P467=-56.0313 ;25.4656
P468=-55.3466 ;25.9053
P469=-54.6186 ;26.3850
P470=-53.8906 ;26.8647
P471=-53.2641 ;27.3290
P472=-52.6376 ;27.7933
P473=-51.6914 ;28.6514
P474=-51.0519 ;29.4390
P475=-50.7014 ;30.1523
P476=-50.5096 ;30.7629
P477=-50.4505 ;31.2651
P478=-50.5240 ;31.6588
P479=-50.7303 ;31.9441
P480=-50.8895 ;32.2389
P481=-50.5890 ;32.8135
P482=-49.8124 ;33.6786
P483=-49.1861 ;34.2565
P484=-48.5598 ;34.8344
P485=-48.0097 ;35.3650
P486=-47.4597 ;35.8955
P487=-47.3342 ;36.3577
P488=-48.1871 ;36.2189
P489=-49.1027 ;35.8489
P490=-50.0183 ;35.4789
P491=-51.1215 ;34.9867
P492=-52.2247 ;34.4945

P493=-53.4699 ;34.0556
P494=-53.7053 ;34.1910
P495=-52.9309 ;34.9007
P496=-52.0606 ;35.5310
P497=-51.1903 ;36.1612
P498=-50.4275 ;36.7479
P499=-49.6646 ;37.3346
P500=-48.8838 ;38.1344
P501=-48.8481 ;38.5609
P502=-49.4975 ;38.6294
P503=-50.3999 ;38.4528
P504=-51.4695 ;38.0534
P505=-52.7062 ;37.4313
P506=-53.4082 ;37.0089
P507=-54.1102 ;36.5864
P508=-54.8205 ;36.1117
P509=-55.5309 ;35.6370
P510=-56.1524 ;35.1868
P511=-56.7738 ;34.7365
P512=-57.8380 ;33.8856
P513=-58.7239 ;33.0840
P514=-59.6432 ;32.2291
P515=-60.2098 ;31.7314
P516=-60.7764 ;31.2336
P517=-61.4499 ;30.6655
P518=-62.1234 ;30.0975
P519=-62.8755 ;29.4839
P520=-63.6275 ;28.8703
P521=-64.6941 ;28.0704
P522=-65.1647 ;27.8361
P523=-65.0393 ;28.1672
P524=-64.3882 ;28.9884
P525=-63.5586 ;29.9261
P526=-62.5975 ;30.9298
P527=-62.0517 ;31.4642
P528=-61.5058 ;31.9985
P529=-60.9341 ;32.5220
P530=-60.3624 ;33.0454
P531=-59.7916 ;33.5287
P532=-59.2208 ;34.0119
P533=-58.0811 ;34.8977
P534=-56.9431 ;35.7039
P535=-55.7996 ;36.4930
P536=-54.6463 ;37.3036
P537=-53.4830 ;38.1357
P538=-52.3100 ;38.9891
P539=-51.1270 ;39.8366
P540=-49.9340 ;40.6570
P541=-48.7309 ;41.4504
P542=-47.5179 ;42.2167
P543=-46.2929 ;42.9537
P544=-45.0455 ;43.6488
P545=-43.7740 ;44.3001
P546=-42.4784 ;44.9076
P547=-41.1588 ;45.4714
P548=-39.8166 ;45.9925
P549=-38.4636 ;46.4801

P550=-37.1023 ;46.9361
P551=-35.7325 ;47.3604
P552=-34.3545 ;47.7531
P553=-32.9680 ;48.1141
P554=-31.5732 ;48.4435
P555=-30.1701 ;48.7412
P556=-28.7586 ;49.0072
P557=-27.3387 ;49.2417
P558=-25.9104 ;49.4444
P559=-24.4831 ;49.6145

[C2]

gain=-50.00

n_point=122

P1=-69.3659 ;79.7797
P2=-69.7970 ;79.6570
P3=-70.0000 ;79.5980
P4=-70.3180 ;79.5000
P5=-70.5000 ;79.4460
P6=-71.0000 ;79.2940
P7=-71.5000 ;79.1390
P8=-71.9180 ;79.0000
P9=-72.0000 ;78.9710
P10=-72.5000 ;78.8070
P11=-73.0000 ;78.6390
P12=-73.3840 ;78.5000
P13=-73.5000 ;78.4510
P14=-74.0000 ;78.2600
P15=-74.5000 ;78.0830
P16=-74.7180 ;78.0000
P17=-75.0000 ;77.8640
P18=-75.5000 ;77.6580
P19=-75.9300 ;77.5000
P20=-76.0000 ;77.4610
P21=-76.5000 ;77.2080
P22=-77.0000 ;77.0270
P23=-77.0650 ;77.0000
P24=-77.5000 ;76.7370
P25=-78.0000 ;76.5610
P26=-78.1430 ;76.5000
P27=-78.5000 ;76.2500
P28=-79.0000 ;76.0970
P29=-79.2000 ;76.0000
P30=-79.5000 ;75.7630
P31=-80.0000 ;75.5970
P32=-80.1790 ;75.5000
P33=-80.5000 ;75.2900
P34=-81.0000 ;75.0470
P35=-81.0810 ;75.0000
P36=-81.5000 ;74.7590
P37=-81.9360 ;74.5000
P38=-82.0000 ;74.4620
P39=-82.5000 ;74.1570
P40=-82.7490 ;74.0000
P41=-83.0000 ;73.7650
P42=-83.4160 ;73.5000
P43=-83.5000 ;73.3900
P44=-83.7500 ;73.2220

P45=-84.0000 ;73.0540
P46=-84.0910 ;73.0000
P47=-84.5000 ;72.6810
P48=-84.8630 ;72.5000
P49=-85.0000 ;72.4100
P50=-85.2500 ;72.2485
P51=-85.5000 ;72.0870
P52=-85.6090 ;72.0000
P53=-85.8045 ;71.8305
P54=-86.0000 ;71.6610
P55=-86.1950 ;71.5000
P56=-86.3475 ;71.2970
P57=-86.5000 ;71.0940
P58=-86.6210 ;71.0000
P59=-86.8105 ;70.7750
P60=-87.0000 ;70.5500
P61=-87.1940 ;70.5000
P62=-87.0000 ;70.4140
P63=-86.5000 ;70.4760
P64=-86.4710 ;70.5000
P65=-86.2355 ;70.6975
P66=-86.0000 ;70.8950
P67=-85.8640 ;71.0000
P68=-85.5000 ;71.2880
P69=-85.2100 ;71.5000
P70=-85.0000 ;71.7350
P71=-84.6090 ;72.0000
P72=-84.5000 ;72.1620
P73=-84.0000 ;72.4420
P74=-83.8800 ;72.5000
P75=-83.5000 ;72.7630
P76=-83.0000 ;72.9440
P77=-82.9130 ;73.0000
P78=-82.5000 ;73.2600
P79=-82.1120 ;73.5000
P80=-82.0000 ;73.5740
P81=-81.5000 ;73.8690
P82=-81.2770 ;74.0000
P83=-81.0000 ;74.2240
P84=-80.5000 ;74.4910
P85=-80.4810 ;74.5000
P86=-80.2405 ;74.6645
P87=-80.0000 ;74.8290
P88=-79.5360 ;75.0000
P89=-79.5000 ;75.0300
P90=-79.0000 ;75.3370
P91=-78.5000 ;75.4520
P92=-78.3990 ;75.5000
P93=-78.0000 ;75.7880
P94=-77.5000 ;75.9130
P95=-77.3100 ;76.0000
P96=-77.0000 ;76.2170
P97=-76.5000 ;76.3600
P98=-76.1790 ;76.5000
P99=-76.0000 ;76.6300
P100=-75.5000 ;76.7860
P101=-75.0000 ;76.9920

P102=-74.9800 ;77.0000
P103=-74.5000 ;77.1900
P104=-74.0000 ;77.3840
P105=-73.6990 ;77.5000
P106=-73.5000 ;77.5970
P107=-73.0000 ;77.7580
P108=-72.5000 ;77.9350
P109=-72.3240 ;78.0000
P110=-72.0000 ;78.1180
P111=-71.5000 ;78.2820
P112=-71.0000 ;78.4440
P113=-70.8390 ;78.5000
P114=-70.5000 ;78.6140
P115=-70.0000 ;78.7630
P116=-69.5000 ;78.9130
P117=-69.2240 ;79.0000
P118=-69.0000 ;79.0870
P119=-68.5000 ;79.2130
P120=-68.0000 ;79.3450
P121=-67.7440 ;79.4180
P122=-67.3096 ;79.5392

[C3]

gain=-50.00

n_point=66

P1=-87.5000 ;70.3630
P2=-87.5714 ;70.3179
P3=-87.6429 ;70.2727
P4=-87.7143 ;70.2276
P5=-87.7857 ;70.1824
P6=-87.8571 ;70.1373
P7=-87.9286 ;70.0921
P8=-88.0000 ;70.0470
P9=-88.0500 ;70.0000
P10=-88.0888 ;69.9500
P11=-88.1276 ;69.9000
P12=-88.1664 ;69.8500
P13=-88.2052 ;69.8000
P14=-88.2440 ;69.7500
P15=-88.2828 ;69.7000
P16=-88.3216 ;69.6500
P17=-88.3604 ;69.6000
P18=-88.3992 ;69.5500
P19=-88.4380 ;69.5000
P20=-88.4690 ;69.4700
P21=-88.5000 ;69.4400
P22=-88.5357 ;69.3911
P23=-88.5713 ;69.3422
P24=-88.6070 ;69.2933
P25=-88.6427 ;69.2444
P26=-88.6783 ;69.1956
P27=-88.7140 ;69.1467
P28=-88.7497 ;69.0978
P29=-88.7853 ;69.0489
P30=-88.8210 ;69.0000
P31=-88.7408 ;68.9640
P32=-88.6605 ;68.9280
P33=-88.5802 ;68.8920

P34=-88.5000 ;68.8560
P35=-88.4517 ;68.9040
P36=-88.4033 ;68.9520
P37=-88.3550 ;69.0000
P38=-88.3106 ;69.0447
P39=-88.2663 ;69.0895
P40=-88.2219 ;69.1343
P41=-88.1775 ;69.1790
P42=-88.1331 ;69.2237
P43=-88.0888 ;69.2685
P44=-88.0444 ;69.3132
P45=-88.0000 ;69.3580
P46=-87.9413 ;69.4053
P47=-87.8827 ;69.4527
P48=-87.8240 ;69.5000
P49=-87.7777 ;69.5507
P50=-87.7314 ;69.6014
P51=-87.6851 ;69.6521
P52=-87.6389 ;69.7029
P53=-87.5926 ;69.7536
P54=-87.5463 ;69.8043
P55=-87.5000 ;69.8550
P56=-87.4415 ;69.8913
P57=-87.3830 ;69.9275
P58=-87.3245 ;69.9638
P59=-87.2660 ;70.0000
P60=-87.2994 ;70.0519
P61=-87.3329 ;70.1037
P62=-87.3663 ;70.1556
P63=-87.3997 ;70.2074
P64=-87.4331 ;70.2593
P65=-87.4666 ;70.3111
P66=-87.5000 ;70.3630

[C4]

gain=-50.00

n_point=71

P1=-90.0000 ;68.1650
P2=-90.0378 ;68.1237
P3=-90.0755 ;68.0825
P4=-90.1133 ;68.0413
P5=-90.1510 ;68.0000
P6=-90.1859 ;67.9505
P7=-90.2208 ;67.9010
P8=-90.2557 ;67.8515
P9=-90.2906 ;67.8020
P10=-90.3255 ;67.7525
P11=-90.3604 ;67.7030
P12=-90.3953 ;67.6535
P13=-90.4302 ;67.6040
P14=-90.4651 ;67.5545
P15=-90.5000 ;67.5050
P16=-90.5060 ;67.5000
P17=-90.5678 ;67.4531
P18=-90.6295 ;67.4063
P19=-90.6913 ;67.3594
P20=-90.7530 ;67.3125
P21=-90.8148 ;67.2656

P22=-90.8765 ;67.2188
P23=-90.9382 ;67.1719
P24=-91.0000 ;67.1250
P25=-91.0467 ;67.0833
P26=-91.0933 ;67.0417
P27=-91.1400 ;67.0000
P28=-91.1225 ;66.9469
P29=-91.1050 ;66.8938
P30=-91.0875 ;66.8406
P31=-91.0700 ;66.7875
P32=-91.0525 ;66.7344
P33=-91.0350 ;66.6813
P34=-91.0175 ;66.6281
P35=-91.0000 ;66.5750
P36=-90.9286 ;66.6187
P37=-90.8571 ;66.6624
P38=-90.7857 ;66.7061
P39=-90.7143 ;66.7499
P40=-90.6429 ;66.7936
P41=-90.5714 ;66.8373
P42=-90.5000 ;66.8810
P43=-90.4630 ;66.9207
P44=-90.4260 ;66.9603
P45=-90.3890 ;67.0000
P46=-90.3501 ;67.0497
P47=-90.3112 ;67.0994
P48=-90.2723 ;67.1491
P49=-90.2334 ;67.1988
P50=-90.1945 ;67.2485
P51=-90.1556 ;67.2982
P52=-90.1167 ;67.3479
P53=-90.0778 ;67.3976
P54=-90.0389 ;67.4473
P55=-90.0000 ;67.4970
P56=-89.9970 ;67.5000
P57=-89.9517 ;67.5500
P58=-89.9064 ;67.6000
P59=-89.8611 ;67.6500
P60=-89.8158 ;67.7000
P61=-89.7705 ;67.7500
P62=-89.7252 ;67.8000
P63=-89.6799 ;67.8500
P64=-89.6346 ;67.9000
P65=-89.5893 ;67.9500
P66=-89.5440 ;68.0000
P67=-89.6352 ;68.0330
P68=-89.7264 ;68.0660
P69=-89.8176 ;68.0990
P70=-89.9088 ;68.1320
P71=-90.0000 ;68.1650
[C5]
gain=-40.00
n_point=561
P1=-36.4286 ;69.4009
P2=-36.8010 ;69.3400
P3=-37.0000 ;69.3070
P4=-37.5000 ;69.2280

P5=-38.0000 ;69.1510
P6=-38.5000 ;69.0790
P7=-39.0000 ;69.0080
P8=-39.0580 ;69.0000
P9=-39.5000 ;68.9200
P10=-40.0000 ;68.8350
P11=-40.5000 ;68.7550
P12=-41.0000 ;68.6740
P13=-41.5000 ;68.5960
P14=-42.0000 ;68.5240
P15=-42.1730 ;68.5000
P16=-42.5000 ;68.4420
P17=-43.0000 ;68.3550
P18=-43.5000 ;68.2650
P19=-44.0000 ;68.1800
P20=-44.5000 ;68.1030
P21=-45.0000 ;68.0330
P22=-45.2090 ;68.0000
P23=-45.5000 ;67.9420
P24=-46.0000 ;67.8460
P25=-46.5000 ;67.7580
P26=-47.0000 ;67.6720
P27=-47.5000 ;67.5860
P28=-48.0000 ;67.5110
P29=-48.0780 ;67.5000
P30=-48.5000 ;67.4190
P31=-49.0000 ;67.3120
P32=-49.5000 ;67.2170
P33=-50.0000 ;67.1310
P34=-50.5000 ;67.0440
P35=-50.7820 ;67.0000
P36=-51.0000 ;66.9520
P37=-51.5000 ;66.8500
P38=-52.0000 ;66.7380
P39=-52.5000 ;66.6420
P40=-53.0000 ;66.5590
P41=-53.3470 ;66.5000
P42=-53.5000 ;66.4570
P43=-54.0000 ;66.3350
P44=-54.5000 ;66.2270
P45=-55.0000 ;66.1290
P46=-55.5000 ;66.0520
P47=-55.8040 ;66.0000
P48=-56.0000 ;65.9300
P49=-56.5000 ;65.7810
P50=-57.0000 ;65.6910
P51=-57.5000 ;65.6250
P52=-58.0000 ;65.5600
P53=-58.3120 ;65.5000
P54=-58.5000 ;65.4400
P55=-59.0000 ;65.2830
P56=-59.5000 ;65.1610
P57=-60.0000 ;65.0580
P58=-60.1800 ;65.0000
P59=-60.5000 ;64.8900
P60=-61.0000 ;64.7490
P61=-61.5000 ;64.5970

P62=-61.9950 ;64.5000
P63=-62.0000 ;64.4980
P64=-62.5000 ;64.3050
P65=-63.0000 ;64.1740
P66=-63.5000 ;64.0670
P67=-63.8010 ;64.0000
P68=-64.0000 ;63.9220
P69=-64.5000 ;63.7620
P70=-65.0000 ;63.6530
P71=-65.5000 ;63.5500
P72=-65.6130 ;63.5000
P73=-66.0000 ;63.3320
P74=-66.5000 ;63.1580
P75=-67.0000 ;63.0100
P76=-67.0330 ;63.0000
P77=-67.5000 ;62.8030
P78=-68.0000 ;62.6500
P79=-68.5000 ;62.5390
P80=-68.6110 ;62.5000
P81=-69.0000 ;62.3390
P82=-69.5000 ;62.1890
P83=-69.9580 ;62.0000
P84=-70.0000 ;61.9820
P85=-70.5000 ;61.7540
P86=-71.0000 ;61.5830
P87=-71.2400 ;61.5000
P88=-71.5000 ;61.3800
P89=-72.0000 ;61.2400
P90=-72.5000 ;61.0220
P91=-72.5300 ;61.0000
P92=-73.0000 ;60.7750
P93=-73.5000 ;60.5770
P94=-73.6970 ;60.5000
P95=-74.0000 ;60.3560
P96=-74.5000 ;60.2040
P97=-74.8290 ;60.0000
P98=-75.0000 ;59.9060
P99=-75.5000 ;59.6840
P100=-75.9210 ;59.5000
P101=-76.0000 ;59.4600
P102=-76.5000 ;59.2360
P103=-76.8880 ;59.0000
P104=-77.0000 ;58.9360
P105=-77.5000 ;58.6680
P106=-77.8600 ;58.5000
P107=-78.0000 ;58.4170
P108=-78.5000 ;58.1420
P109=-78.7010 ;58.0000
P110=-79.0000 ;57.8270
P111=-79.5000 ;57.5400
P112=-79.5530 ;57.5000
P113=-80.0000 ;57.2080
P114=-80.3110 ;57.0000
P115=-80.5000 ;56.8770
P116=-81.0000 ;56.5560
P117=-81.0550 ;56.5000
P118=-81.5000 ;56.1910

P119=-81.7860 ;56.0000
P120=-82.0000 ;55.8340
P121=-82.4520 ;55.5000
P122=-82.5000 ;55.4640
P123=-83.0000 ;55.1200
P124=-83.1170 ;55.0000
P125=-83.5000 ;54.6880
P126=-83.7590 ;54.5000
P127=-84.0000 ;54.2880
P128=-84.3230 ;54.0000
P129=-84.5000 ;53.8380
P130=-84.8990 ;53.5000
P131=-85.0000 ;53.4070
P132=-85.4320 ;53.0000
P133=-85.5000 ;52.9330
P134=-85.9560 ;52.5000
P135=-86.0000 ;52.4560
P136=-86.4530 ;52.0000
P137=-86.5000 ;51.9490
P138=-86.8950 ;51.5000
P139=-87.0000 ;51.3890
P140=-87.3650 ;51.0000
P141=-87.5000 ;50.8520
P142=-87.7900 ;50.5000
P143=-88.0000 ;50.2490
P144=-88.1920 ;50.0000
P145=-88.5000 ;49.6290
P146=-88.6100 ;49.5000
P147=-89.0000 ;49.0140
P148=-89.0100 ;49.0000
P149=-89.3240 ;48.5000
P150=-89.5000 ;48.2520
P151=-89.6500 ;48.0000
P152=-89.9900 ;47.5000
P153=-90.0000 ;47.4860
P154=-90.2670 ;47.0000
P155=-90.5000 ;46.6620
P156=-90.5920 ;46.5000
P157=-90.8490 ;46.0000
P158=-91.0000 ;45.7330
P159=-91.0940 ;45.5000
P160=-91.3080 ;45.0000
P161=-91.5000 ;44.6100
P162=-91.5360 ;44.5000
P163=-91.6940 ;44.0000
P164=-91.8940 ;43.5000
P165=-92.0000 ;43.2290
P166=-92.0550 ;43.0000
P167=-92.1280 ;42.5000
P168=-92.1250 ;42.0000
P169=-92.0000 ;41.5740
P170=-91.5000 ;41.8650
P171=-91.4210 ;42.0000
P172=-91.0000 ;42.4760
P173=-90.9880 ;42.5000
P174=-90.6970 ;43.0000
P175=-90.5000 ;43.2310

P176=-90.3630 ;43.5000
P177=-90.0000 ;43.9630
P178=-89.9770 ;44.0000
P179=-89.6670 ;44.5000
P180=-89.5000 ;44.6900
P181=-89.2870 ;45.0000
P182=-89.0000 ;45.3470
P183=-88.9000 ;45.5000
P184=-88.5160 ;46.0000
P185=-88.5000 ;46.0180
P186=-88.1750 ;46.5000
P187=-88.0000 ;46.6910
P188=-87.7340 ;47.0000
P189=-87.5000 ;47.2440
P190=-87.2470 ;47.5000
P191=-87.0000 ;47.7640
P192=-86.8260 ;48.0000
P193=-86.5000 ;48.3430
P194=-86.3190 ;48.5000
P195=-86.0000 ;48.8080
P196=-85.7450 ;49.0000
P197=-85.5000 ;49.2170
P198=-85.2150 ;49.5000
P199=-85.0000 ;49.6990
P200=-84.5760 ;50.0000
P201=-84.5000 ;50.0620
P202=-84.0140 ;50.0000
P203=-84.4560 ;49.5000
P204=-84.5000 ;49.4560
P205=-84.9530 ;49.0000
P206=-85.0000 ;48.9530
P207=-85.4590 ;48.5000
P208=-85.5000 ;48.4580
P209=-85.9140 ;48.0000
P210=-86.0000 ;47.8980
P211=-86.3140 ;47.5000
P212=-86.5000 ;47.2780
P213=-86.7430 ;47.0000
P214=-87.0000 ;46.6860
P215=-87.1640 ;46.5000
P216=-87.5000 ;46.0370
P217=-87.5240 ;46.0000
P218=-87.8080 ;45.5000
P219=-88.0000 ;45.2270
P220=-88.1540 ;45.0000
P221=-88.4590 ;44.5000
P222=-88.5000 ;44.4390
P223=-88.7500 ;44.0000
P224=-89.0000 ;43.5940
P225=-89.0530 ;43.5000
P226=-89.2510 ;43.0000
P227=-89.5000 ;42.5340
P228=-89.5140 ;42.5000
P229=-89.6760 ;42.0000
P230=-89.8790 ;41.5000
P231=-90.0000 ;41.2230
P232=-90.0620 ;41.0000

P233=-90.1820 ;40.5000
P234=-90.3050 ;40.0000
P235=-90.3960 ;39.5000
P236=-90.4810 ;39.0000
P237=-90.5000 ;38.8440
P238=-90.5140 ;38.5000
P239=-90.5300 ;38.0000
P240=-90.5000 ;37.6460
P241=-90.3910 ;38.0000
P242=-90.0000 ;38.2970
P243=-89.9520 ;38.5000
P244=-89.7420 ;39.0000
P245=-89.5000 ;39.2590
P246=-89.4030 ;39.5000
P247=-89.0680 ;40.0000
P248=-89.0000 ;40.0750
P249=-88.8160 ;40.5000
P250=-88.5000 ;40.9060
P251=-88.4500 ;41.0000
P252=-88.1500 ;41.5000
P253=-88.0000 ;41.6640
P254=-87.7700 ;42.0000
P255=-87.5000 ;42.3060
P256=-87.2860 ;42.5000
P257=-87.0000 ;42.8480
P258=-86.8800 ;43.0000
P259=-86.5100 ;43.5000
P260=-86.5000 ;43.5110
P261=-86.1580 ;44.0000
P262=-86.0000 ;44.1640
P263=-85.6980 ;44.0000
P264=-85.8750 ;43.5000
P265=-86.0000 ;43.3350
P266=-86.2680 ;43.0000
P267=-86.5000 ;42.6510
P268=-86.6880 ;42.5000
P269=-86.9320 ;42.0000
P270=-87.0000 ;41.9030
P271=-87.2560 ;41.5000
P272=-87.5000 ;41.0690
P273=-87.5440 ;41.0000
P274=-87.7290 ;40.5000
P275=-88.0000 ;40.0240
P276=-88.0170 ;40.0000
P277=-88.1930 ;39.5000
P278=-88.3940 ;39.0000
P279=-88.5000 ;38.7560
P280=-88.5950 ;38.5000
P281=-88.6610 ;38.0000
P282=-88.7070 ;37.5000
P283=-88.7330 ;37.0000
P284=-88.7220 ;36.5000
P285=-88.6890 ;36.0000
P286=-88.5840 ;35.5000
P287=-88.5000 ;35.0290
P288=-88.4900 ;35.0000
P289=-88.2750 ;34.5000

P290=-88.0660 ;34.0000
P291=-88.0000 ;33.8770
P292=-87.7760 ;33.5000
P293=-87.5000 ;33.0740
P294=-87.4380 ;33.0000
P295=-87.0000 ;32.5520
P296=-86.9410 ;32.5000
P297=-87.0000 ;32.3640
P298=-87.5000 ;32.3960
P299=-87.7100 ;32.5000
P300=-88.0000 ;32.6410
P301=-88.4700 ;33.0000
P302=-88.5000 ;33.0240
P303=-88.9720 ;33.5000
P304=-89.0000 ;33.5310
P305=-89.4330 ;34.0000
P306=-89.5000 ;34.1540
P307=-89.7590 ;34.5000
P308=-89.9540 ;35.0000
P309=-90.0000 ;35.1680
P310=-90.2520 ;35.5000
P311=-90.4310 ;36.0000
P312=-90.5000 ;36.3480
P313=-90.5900 ;36.0000
P314=-90.7310 ;35.5000
P315=-90.8240 ;35.0000
P316=-90.8470 ;34.5000
P317=-90.7930 ;34.0000
P318=-90.7140 ;33.5000
P319=-90.6020 ;33.0000
P320=-90.5000 ;32.6820
P321=-90.4180 ;32.5000
P322=-90.1770 ;32.0000
P323=-90.0000 ;31.6060
P324=-89.9410 ;31.5000
P325=-89.6260 ;31.0000
P326=-89.5000 ;30.7840
P327=-89.3050 ;30.5000
P328=-89.0000 ;30.1160
P329=-88.9030 ;30.0000
P330=-88.5000 ;29.5810
P331=-88.4180 ;29.5000
P332=-88.0000 ;29.1220
P333=-87.8080 ;29.0000
P334=-87.5000 ;28.7280
P335=-87.0000 ;28.6200
P336=-86.6000 ;28.5000
P337=-87.0000 ;28.2870
P338=-87.5000 ;28.3420
P339=-88.0000 ;28.4770
P340=-88.0590 ;28.5000
P341=-88.5000 ;28.6970
P342=-89.0000 ;28.8840
P343=-89.2050 ;29.0000
P344=-89.5000 ;29.1680
P345=-89.9840 ;29.5000
P346=-90.0000 ;29.5100

P347=-90.5000 ;29.8050
P348=-90.8020 ;30.0000
P349=-91.0000 ;30.1420
P350=-91.5000 ;30.4550
P351=-92.0000 ;30.3730
P352=-92.0560 ;30.0000
P353=-92.0000 ;29.6340
P354=-91.9730 ;29.5000
P355=-91.7320 ;29.0000
P356=-91.5000 ;28.5650
P357=-91.4630 ;28.5000
P358=-91.1090 ;28.0000
P359=-91.0000 ;27.8740
P360=-90.6840 ;27.5000
P361=-90.5000 ;27.3000
P362=-90.2150 ;27.0000
P363=-90.0000 ;26.8120
P364=-89.6370 ;26.5000
P365=-89.5000 ;26.3930
P366=-89.0000 ;26.0330
P367=-88.9520 ;26.0000
P368=-88.5000 ;25.7760
P369=-88.0000 ;25.5810
P370=-87.7970 ;25.5000
P371=-87.5000 ;25.3940
P372=-87.0000 ;25.2950
P373=-86.5000 ;25.2320
P374=-86.0000 ;25.2040
P375=-85.5000 ;25.2030
P376=-85.0000 ;25.2210
P377=-84.5000 ;25.2520
P378=-84.0000 ;25.3120
P379=-83.5000 ;25.4100
P380=-83.2930 ;25.5000
P381=-83.0000 ;25.6110
P382=-82.5000 ;25.8090
P383=-82.0000 ;25.9210
P384=-81.8310 ;26.0000
P385=-81.5000 ;26.1940
P386=-81.0000 ;26.3330
P387=-80.6380 ;26.5000
P388=-80.5000 ;26.5880
P389=-80.0000 ;26.8020
P390=-79.5900 ;27.0000
P391=-79.5000 ;27.0630
P392=-79.0000 ;27.3780
P393=-78.7790 ;27.5000
P394=-78.5000 ;27.7070
P395=-78.0000 ;27.9130
P396=-77.9140 ;28.0000
P397=-77.5000 ;28.3020
P398=-77.2260 ;28.5000
P399=-77.0000 ;28.6860
P400=-76.5230 ;29.0000
P401=-76.5000 ;29.0200
P402=-76.0000 ;29.3820
P403=-75.8670 ;29.5000

P404=-75.5000 ;29.8210
P405=-75.2810 ;30.0000
P406=-75.0000 ;30.2560
P407=-74.7040 ;30.5000
P408=-74.5000 ;30.6880
P409=-74.1190 ;31.0000
P410=-74.0000 ;31.1140
P411=-73.5580 ;31.5000
P412=-73.5000 ;31.5560
P413=-73.0010 ;32.0000
P414=-73.0000 ;32.0010
P415=-72.5000 ;32.4480
P416=-72.4460 ;32.5000
P417=-72.0000 ;32.9370
P418=-71.9440 ;33.0000
P419=-71.5000 ;33.4510
P420=-71.4440 ;33.5000
P421=-71.0000 ;33.9270
P422=-70.9230 ;34.0000
P423=-70.5000 ;34.4310
P424=-70.4340 ;34.5000
P425=-70.0000 ;34.9310
P426=-69.9260 ;35.0000
P427=-69.5000 ;35.4330
P428=-69.4370 ;35.5000
P429=-69.0000 ;35.9560
P430=-68.9540 ;36.0000
P431=-68.5000 ;36.4560
P432=-68.4560 ;36.5000
P433=-68.0000 ;36.9680
P434=-67.9660 ;37.0000
P435=-67.5000 ;37.4810
P436=-67.4820 ;37.5000
P437=-67.0070 ;38.0000
P438=-67.0000 ;38.0090
P439=-66.6030 ;38.5000
P440=-66.5000 ;38.6200
P441=-66.1610 ;39.0000
P442=-66.0000 ;39.1930
P443=-65.7390 ;39.5000
P444=-65.5000 ;39.8020
P445=-65.3420 ;40.0000
P446=-65.0000 ;40.4200
P447=-64.9340 ;40.5000
P448=-64.5250 ;41.0000
P449=-64.5000 ;41.0460
P450=-64.2590 ;41.5000
P451=-64.0000 ;41.8580
P452=-63.8990 ;42.0000
P453=-63.5000 ;42.4590
P454=-63.4650 ;42.5000
P455=-63.0000 ;42.9900
P456=-62.9910 ;43.0000
P457=-62.5000 ;43.4920
P458=-62.4920 ;43.5000
P459=-62.0000 ;43.9660
P460=-61.9640 ;44.0000

P461=-61.5000 ;44.4280
P462=-61.4190 ;44.5000
P463=-61.0000 ;44.8570
P464=-60.8270 ;45.0000
P465=-60.5000 ;45.2670
P466=-60.2110 ;45.5000
P467=-60.0000 ;45.6740
P468=-59.6040 ;46.0000
P469=-59.5000 ;46.0900
P470=-59.0280 ;46.5000
P471=-59.0000 ;46.5260
P472=-58.5000 ;46.9860
P473=-58.4840 ;47.0000
P474=-58.0000 ;47.4570
P475=-57.9510 ;47.5000
P476=-57.5000 ;47.9180
P477=-57.4030 ;48.0000
P478=-57.0000 ;48.3630
P479=-56.8430 ;48.5000
P480=-56.5000 ;48.8080
P481=-56.3000 ;49.0000
P482=-56.0000 ;49.3210
P483=-55.8140 ;49.5000
P484=-55.5000 ;49.8410
P485=-55.3300 ;50.0000
P486=-55.0000 ;50.3450
P487=-54.8470 ;50.5000
P488=-54.5000 ;50.8600
P489=-54.3720 ;51.0000
P490=-54.0000 ;51.4030
P491=-53.8920 ;51.5000
P492=-53.5000 ;51.8400
P493=-53.3160 ;52.0000
P494=-53.0000 ;52.2700
P495=-52.7180 ;52.5000
P496=-52.5000 ;52.6780
P497=-52.0000 ;52.9990
P498=-51.9980 ;53.0000
P499=-51.5000 ;53.4230
P500=-51.3800 ;53.5000
P501=-51.0000 ;53.7650
P502=-50.7000 ;54.0000
P503=-50.5000 ;54.1640
P504=-50.0000 ;54.4620
P505=-49.9480 ;54.5000
P506=-49.5000 ;54.8430
P507=-49.2270 ;55.0000
P508=-49.0000 ;55.1370
P509=-48.5000 ;55.4660
P510=-48.4390 ;55.5000
P511=-48.0000 ;55.7540
P512=-47.5490 ;56.0000
P513=-47.5000 ;56.0280
P514=-47.0000 ;56.3130
P515=-46.6080 ;56.5000
P516=-46.5000 ;56.5560
P517=-46.0000 ;56.8420

P518=-45.6550 ;57.0000
P519=-45.5000 ;57.0780
P520=-45.0000 ;57.3230
P521=-44.6370 ;57.5000
P522=-44.5000 ;57.5820
P523=-44.0000 ;57.8280
P524=-43.6170 ;58.0000
P525=-43.5000 ;58.0560
P526=-43.0000 ;58.3010
P527=-42.5350 ;58.5000
P528=-42.5000 ;58.5200
P529=-42.0000 ;58.7690
P530=-41.5050 ;59.0000
P531=-41.5000 ;59.0020
P532=-41.0000 ;59.2290
P533=-40.5000 ;59.4230
P534=-40.3100 ;59.5000
P535=-40.0000 ;59.6480
P536=-39.5000 ;59.8750
P537=-39.1750 ;60.0000
P538=-39.0000 ;60.0710
P539=-38.5000 ;60.2510
P540=-38.0000 ;60.4180
P541=-37.7770 ;60.5000
P542=-37.5000 ;60.6150
P543=-37.0000 ;60.8000
P544=-36.5000 ;60.9500
P545=-36.2970 ;61.0000
P546=-36.0000 ;61.0870
P547=-35.5000 ;61.2300
P548=-35.0000 ;61.3760
P549=-34.5710 ;61.5000
P550=-34.5000 ;61.5220
P551=-34.0000 ;61.6510
P552=-33.5000 ;61.7530
P553=-33.0000 ;61.8540
P554=-32.5000 ;61.9450
P555=-32.2450 ;62.0000
P556=-32.0000 ;62.0650
P557=-31.5000 ;62.1720
P558=-31.0000 ;62.2600
P559=-30.5000 ;62.3280
P560=-30.3220 ;62.3460
P561=-30.0152 ;62.3764
[C6]
gain=-50.00
n_point=250
P1=-25.3963 ;52.5829
P2=-25.6290 ;52.5510
P3=-25.9940 ;52.5000
P4=-26.0000 ;52.4990
P5=-26.5000 ;52.4080
P6=-27.0000 ;52.3370
P7=-27.5000 ;52.2860
P8=-28.0000 ;52.2150
P9=-28.5000 ;52.1320
P10=-29.0000 ;52.0410

P11=-29.2060 ;52.0000
P12=-29.5000 ;51.9280
P13=-30.0000 ;51.8340
P14=-30.5000 ;51.7640
P15=-31.0000 ;51.6630
P16=-31.5000 ;51.5530
P17=-31.7200 ;51.5000
P18=-32.0000 ;51.4200
P19=-32.5000 ;51.3190
P20=-33.0000 ;51.2200
P21=-33.5000 ;51.0950
P22=-33.8450 ;51.0000
P23=-34.0000 ;50.9480
P24=-34.5000 ;50.8270
P25=-35.0000 ;50.7100
P26=-35.5000 ;50.5660
P27=-35.7070 ;50.5000
P28=-36.0000 ;50.4020
P29=-36.5000 ;50.2820
P30=-37.0000 ;50.1310
P31=-37.3780 ;50.0000
P32=-37.5000 ;49.9530
P33=-38.0000 ;49.8130
P34=-38.5000 ;49.6510
P35=-38.8980 ;49.5000
P36=-39.0000 ;49.4590
P37=-39.5000 ;49.3050
P38=-40.0000 ;49.1240
P39=-40.2900 ;49.0000
P40=-40.5000 ;48.9170
P41=-41.0000 ;48.7500
P42=-41.5000 ;48.5350
P43=-41.5790 ;48.5000
P44=-42.0000 ;48.3410
P45=-42.5000 ;48.1300
P46=-42.7620 ;48.0000
P47=-43.0000 ;47.8990
P48=-43.5000 ;47.6850
P49=-43.8360 ;47.5000
P50=-44.0000 ;47.4220
P51=-44.5000 ;47.2000
P52=-44.8370 ;47.0000
P53=-45.0000 ;46.9170
P54=-45.5000 ;46.6770
P55=-45.7810 ;46.5000
P56=-46.0000 ;46.3830
P57=-46.5000 ;46.1110
P58=-46.6680 ;46.0000
P59=-47.0000 ;45.8150
P60=-47.4930 ;45.5000
P61=-47.5000 ;45.4950
P62=-48.0000 ;45.2110
P63=-48.2990 ;45.0000
P64=-48.5000 ;44.8740
P65=-49.0000 ;44.5620
P66=-49.0880 ;44.5000
P67=-49.5000 ;44.2410

P68=-49.8380 ;44.0000
P69=-50.0000 ;43.8920
P70=-50.5000 ;43.5650
P71=-50.5910 ;43.5000
P72=-51.0000 ;43.2280
P73=-51.3250 ;43.0000
P74=-51.5000 ;42.8770
P75=-52.0000 ;42.5480
P76=-52.0670 ;42.5000
P77=-52.5000 ;42.2020
P78=-52.8020 ;42.0000
P79=-53.0000 ;41.8530
P80=-53.5000 ;41.5510
P81=-53.5680 ;41.5000
P82=-54.0000 ;41.2080
P83=-54.2960 ;41.0000
P84=-54.5000 ;40.8520
P85=-55.0000 ;40.5160
P86=-55.0220 ;40.5000
P87=-55.5000 ;40.1730
P88=-55.7390 ;40.0000
P89=-56.0000 ;39.8130
P90=-56.4480 ;39.5000
P91=-56.5000 ;39.4610
P92=-57.0000 ;39.1190
P93=-57.1570 ;39.0000
P94=-57.5000 ;38.7540
P95=-57.8410 ;38.5000
P96=-58.0000 ;38.3860
P97=-58.5000 ;38.0090
P98=-58.5110 ;38.0000
P99=-59.0000 ;37.6250
P100=-59.1440 ;37.5000
P101=-59.5000 ;37.2290
P102=-59.7490 ;37.0000
P103=-60.0000 ;36.8110
P104=-60.3360 ;36.5000
P105=-60.5000 ;36.3640
P106=-60.9050 ;36.0000
P107=-61.0000 ;35.9080
P108=-61.4430 ;35.5000
P109=-61.5000 ;35.4560
P110=-61.9480 ;35.0000
P111=-62.0000 ;34.9540
P112=-62.4580 ;34.5000
P113=-62.5000 ;34.4450
P114=-62.9610 ;34.0000
P115=-63.0000 ;33.9720
P116=-63.4470 ;33.5000
P117=-63.5000 ;33.4300
P118=-63.9790 ;33.0000
P119=-64.0000 ;32.9770
P120=-64.4600 ;32.5000
P121=-64.5000 ;32.4450
P122=-64.9900 ;32.0000
P123=-65.0000 ;31.9870
P124=-65.4400 ;31.5000

P125=-65.5000 ;31.2500
P126=-65.8970 ;31.0000
P127=-65.5000 ;30.9690
P128=-65.4610 ;31.0000
P129=-65.0000 ;31.3070
P130=-64.7490 ;31.5000
P131=-64.5000 ;31.7120
P132=-64.1310 ;32.0000
P133=-64.0000 ;32.0990
P134=-63.5000 ;32.4640
P135=-63.4550 ;32.5000
P136=-63.0000 ;32.8450
P137=-62.8170 ;33.0000
P138=-62.5000 ;33.2650
P139=-62.2420 ;33.5000
P140=-62.0000 ;33.6840
P141=-61.6360 ;34.0000
P142=-61.5000 ;34.1380
P143=-61.1000 ;34.5000
P144=-61.0000 ;34.5850
P145=-60.5770 ;35.0000
P146=-60.5000 ;35.0720
P147=-60.0190 ;35.5000
P148=-60.0000 ;35.5220
P149=-59.5000 ;35.9380
P150=-59.4300 ;36.0000
P151=-59.0000 ;36.3670
P152=-58.8480 ;36.5000
P153=-58.5000 ;36.8050
P154=-58.2730 ;37.0000
P155=-58.0000 ;37.2240
P156=-57.6700 ;37.5000
P157=-57.5000 ;37.6330
P158=-57.0460 ;38.0000
P159=-57.0000 ;38.0420
P160=-56.5000 ;38.3990
P161=-56.3670 ;38.5000
P162=-56.0000 ;38.7570
P163=-55.6690 ;39.0000
P164=-55.5000 ;39.1270
P165=-55.0000 ;39.4720
P166=-54.9600 ;39.5000
P167=-54.5000 ;39.8040
P168=-54.2030 ;40.0000
P169=-54.0000 ;40.1470
P170=-53.5000 ;40.4410
P171=-53.4130 ;40.5000
P172=-53.0000 ;40.7600
P173=-52.6340 ;41.0000
P174=-52.5000 ;41.0930
P175=-52.0000 ;41.3780
P176=-51.8010 ;41.5000
P177=-51.5000 ;41.6840
P178=-51.0000 ;41.9710
P179=-50.9580 ;42.0000
P180=-50.5000 ;42.2620
P181=-50.1100 ;42.5000

P182=-50.0000 ;42.5680
P183=-49.5000 ;42.8200
P184=-49.2120 ;43.0000
P185=-49.0000 ;43.1140
P186=-48.5000 ;43.3850
P187=-48.2960 ;43.5000
P188=-48.0000 ;43.6430
P189=-47.5000 ;43.9200
P190=-47.3610 ;44.0000
P191=-47.0000 ;44.1760
P192=-46.5000 ;44.4390
P193=-46.4070 ;44.5000
P194=-46.0000 ;44.7080
P195=-45.5000 ;44.9670
P196=-45.4530 ;45.0000
P197=-45.0000 ;45.2300
P198=-44.5000 ;45.4910
P199=-44.4870 ;45.5000
P200=-44.0000 ;45.7340
P201=-43.5000 ;45.9960
P202=-43.4940 ;46.0000
P203=-43.0000 ;46.2300
P204=-42.5000 ;46.4710
P205=-42.4560 ;46.5000
P206=-42.0000 ;46.7120
P207=-41.5000 ;46.9210
P208=-41.3640 ;47.0000
P209=-41.0000 ;47.1600
P210=-40.5000 ;47.3550
P211=-40.2080 ;47.5000
P212=-40.0000 ;47.5850
P213=-39.5000 ;47.7830
P214=-39.0000 ;47.9880
P215=-38.9760 ;48.0000
P216=-38.5000 ;48.1830
P217=-38.0000 ;48.3600
P218=-37.6570 ;48.5000
P219=-37.5000 ;48.5560
P220=-37.0000 ;48.7350
P221=-36.5000 ;48.8980
P222=-36.2260 ;49.0000
P223=-36.0000 ;49.0730
P224=-35.5000 ;49.2330
P225=-35.0000 ;49.3850
P226=-34.6420 ;49.5000
P227=-34.5000 ;49.5410
P228=-34.0000 ;49.6830
P229=-33.5000 ;49.8240
P230=-33.0000 ;49.9550
P231=-32.8440 ;50.0000
P232=-32.5000 ;50.0850
P233=-32.0000 ;50.2060
P234=-31.5000 ;50.3270
P235=-31.0000 ;50.4400
P236=-30.7480 ;50.5000
P237=-30.5000 ;50.5520
P238=-30.0000 ;50.6540

P239=-29.5000 ;50.7530
P240=-29.0000 ;50.8490
P241=-28.5000 ;50.9390
P242=-28.1720 ;51.0000
P243=-28.0000 ;51.0290
P244=-27.5000 ;51.1090
P245=-27.0000 ;51.1870
P246=-26.5000 ;51.2630
P247=-26.0000 ;51.3340
P248=-25.5000 ;51.3980
P249=-25.2590 ;51.4290
P250=-25.0313 ;51.4578

[C7]

gain=-40.00

n_point=259

P1=-55.5000 ;55.7860
P2=-55.5320 ;56.0000
P3=-55.5910 ;56.5000
P4=-55.6610 ;57.0000
P5=-55.7670 ;57.5000
P6=-55.9290 ;58.0000
P7=-56.0000 ;58.0840
P8=-56.3780 ;58.5000
P9=-56.5000 ;58.5630
P10=-57.0000 ;58.7730
P11=-57.5000 ;58.9420
P12=-57.7110 ;59.0000
P13=-58.0000 ;59.0520
P14=-58.5000 ;59.1180
P15=-59.0000 ;59.1600
P16=-59.5000 ;59.1820
P17=-60.0000 ;59.1810
P18=-60.5000 ;59.1700
P19=-61.0000 ;59.1380
P20=-61.5000 ;59.1070
P21=-62.0000 ;59.0730
P22=-62.5000 ;59.0430
P23=-63.0000 ;59.0080
P24=-63.0760 ;59.0000
P25=-63.5000 ;58.9440
P26=-64.0000 ;58.8720
P27=-64.5000 ;58.8000
P28=-65.0000 ;58.7290
P29=-65.5000 ;58.6640
P30=-66.0000 ;58.5910
P31=-66.4920 ;58.5000
P32=-66.5000 ;58.4990
P33=-67.0000 ;58.4110
P34=-67.5000 ;58.3560
P35=-68.0000 ;58.3280
P36=-68.5000 ;58.2380
P37=-69.0000 ;58.0860
P38=-69.2190 ;58.0000
P39=-69.5000 ;57.9130
P40=-70.0000 ;57.7690
P41=-70.5000 ;57.5810
P42=-70.6930 ;57.5000

P43=-71.0000 ;57.3160
P44=-71.5000 ;57.2430
P45=-72.0000 ;57.1870
P46=-72.4190 ;57.0000
P47=-72.5000 ;56.9660
P48=-73.0000 ;56.7810
P49=-73.5000 ;56.5570
P50=-73.6100 ;56.5000
P51=-74.0000 ;56.2180
P52=-74.5000 ;56.1300
P53=-74.8680 ;56.0000
P54=-75.0000 ;55.8980
P55=-75.5000 ;55.6360
P56=-75.7920 ;55.5000
P57=-75.5000 ;55.3340
P58=-75.0000 ;55.3480
P59=-74.5000 ;55.4820
P60=-74.4590 ;55.5000
P61=-74.0000 ;55.8050
P62=-73.5000 ;55.9480
P63=-73.1950 ;56.0000
P64=-73.0000 ;56.0420
P65=-72.5000 ;56.1260
P66=-72.0000 ;56.2420
P67=-71.5000 ;56.4150
P68=-71.2680 ;56.5000
P69=-71.0000 ;56.6840
P70=-70.5000 ;56.8170
P71=-70.0000 ;56.8710
P72=-69.5000 ;56.9270
P73=-69.1760 ;57.0000
P74=-69.0000 ;57.0250
P75=-68.5000 ;57.0970
P76=-68.0000 ;57.1800
P77=-67.5000 ;57.2590
P78=-67.0000 ;57.3440
P79=-66.5000 ;57.4300
P80=-66.0240 ;57.5000
P81=-66.0000 ;57.5040
P82=-65.5000 ;57.5610
P83=-65.0000 ;57.5940
P84=-64.5000 ;57.6200
P85=-64.0000 ;57.6380
P86=-63.5000 ;57.6450
P87=-63.0000 ;57.6280
P88=-62.5000 ;57.5740
P89=-62.1180 ;57.5000
P90=-62.0000 ;57.4690
P91=-61.5000 ;57.3170
P92=-61.0000 ;57.1560
P93=-60.6670 ;57.0000
P94=-60.5000 ;56.8710
P95=-60.0000 ;56.5080
P96=-59.9910 ;56.5000
P97=-59.6540 ;56.0000
P98=-59.5000 ;55.5920
P99=-59.4620 ;55.5000

P100=-59.3440 ;55.0000
P101=-59.2910 ;54.5000
P102=-59.2880 ;54.0000
P103=-59.3420 ;53.5000
P104=-59.4440 ;53.0000
P105=-59.5000 ;52.7910
P106=-59.5720 ;52.5000
P107=-59.7190 ;52.0000
P108=-59.8840 ;51.5000
P109=-60.0000 ;51.2230
P110=-60.0940 ;51.0000
P111=-60.3400 ;50.5000
P112=-60.5000 ;50.2290
P113=-60.6290 ;50.0000
P114=-60.9420 ;49.5000
P115=-61.0000 ;49.4170
P116=-61.2730 ;49.0000
P117=-61.5000 ;48.6770
P118=-61.6200 ;48.5000
P119=-61.9670 ;48.0000
P120=-62.0000 ;47.9570
P121=-62.3230 ;47.5000
P122=-62.5000 ;47.2790
P123=-62.7120 ;47.0000
P124=-63.0000 ;46.6450
P125=-63.1150 ;46.5000
P126=-63.5000 ;46.0140
P127=-63.5110 ;46.0000
P128=-63.9000 ;45.5000
P129=-64.0000 ;45.3750
P130=-64.2840 ;45.0000
P131=-64.5000 ;44.7150
P132=-64.6630 ;44.5000
P133=-65.0000 ;44.0600
P134=-65.0480 ;44.0000
P135=-65.4390 ;43.5000
P136=-65.5000 ;43.4270
P137=-65.8400 ;43.0000
P138=-66.0000 ;42.8140
P139=-66.2500 ;42.5000
P140=-66.5000 ;42.1960
P141=-66.6640 ;42.0000
P142=-67.0000 ;41.5860
P143=-67.0730 ;41.5000
P144=-67.4870 ;41.0000
P145=-67.5000 ;40.9870
P146=-67.9450 ;40.5000
P147=-68.0000 ;40.4330
P148=-68.3930 ;40.0000
P149=-68.5000 ;39.8990
P150=-68.8560 ;39.5000
P151=-69.0000 ;39.3430
P152=-69.3270 ;39.0000
P153=-69.5000 ;38.8200
P154=-69.7920 ;38.5000
P155=-70.0000 ;38.3090
P156=-70.3040 ;38.0000

P157=-70.5000 ;37.7950
P158=-70.7790 ;37.5000
P159=-71.0000 ;37.3050
P160=-71.3010 ;37.0000
P161=-71.5000 ;36.7990
P162=-71.7750 ;36.5000
P163=-72.0000 ;36.2730
P164=-72.2770 ;36.0000
P165=-72.5000 ;35.8130
P166=-72.8050 ;35.5000
P167=-73.0000 ;35.2660
P168=-73.2640 ;35.0000
P169=-73.5000 ;34.7720
P170=-73.7820 ;34.5000
P171=-74.0000 ;34.3260
P172=-74.3260 ;34.0000
P173=-74.5000 ;33.7700
P174=-74.7900 ;33.5000
P175=-74.5000 ;33.2540
P176=-74.1930 ;33.5000
P177=-74.0000 ;33.6410
P178=-73.5940 ;34.0000
P179=-73.5000 ;34.1250
P180=-73.0570 ;34.5000
P181=-73.0000 ;34.5610
P182=-72.5000 ;34.9590
P183=-72.4510 ;35.0000
P184=-72.0000 ;35.4020
P185=-71.8900 ;35.5000
P186=-71.5000 ;35.8770
P187=-71.3650 ;36.0000
P188=-71.0000 ;36.3270
P189=-70.8070 ;36.5000
P190=-70.5000 ;36.8200
P191=-70.3140 ;37.0000
P192=-70.0000 ;37.2940
P193=-69.7620 ;37.5000
P194=-69.5000 ;37.7630
P195=-69.2450 ;38.0000
P196=-69.0000 ;38.2260
P197=-68.6790 ;38.5000
P198=-68.5000 ;38.6820
P199=-68.1480 ;39.0000
P200=-68.0000 ;39.1280
P201=-67.5880 ;39.5000
P202=-67.5000 ;39.5880
P203=-67.0150 ;40.0000
P204=-67.0000 ;40.0140
P205=-66.5000 ;40.4410
P206=-66.4250 ;40.5000
P207=-66.0000 ;40.8430
P208=-65.8020 ;41.0000
P209=-65.5000 ;41.2440
P210=-65.1600 ;41.5000
P211=-65.0000 ;41.6470
P212=-64.5800 ;42.0000
P213=-64.5000 ;42.0830

P214=-64.0550 ;42.5000
P215=-64.0000 ;42.5640
P216=-63.5720 ;43.0000
P217=-63.5000 ;43.0740
P218=-63.0930 ;43.5000
P219=-63.0000 ;43.6080
P220=-62.6150 ;44.0000
P221=-62.5000 ;44.1680
P222=-62.2320 ;44.5000
P223=-62.0000 ;44.9590
P224=-61.9750 ;45.0000
P225=-61.6320 ;45.5000
P226=-61.5000 ;45.7040
P227=-61.2850 ;46.0000
P228=-61.0000 ;46.4130
P229=-60.9330 ;46.5000
P230=-60.5470 ;47.0000
P231=-60.5000 ;47.0610
P232=-60.1350 ;47.5000
P233=-60.0000 ;47.6710
P234=-59.7230 ;48.0000
P235=-59.5000 ;48.2720
P236=-59.3060 ;48.5000
P237=-59.0000 ;48.8550
P238=-58.8730 ;49.0000
P239=-58.5000 ;49.4140
P240=-58.4200 ;49.5000
P241=-58.0000 ;49.9550
P242=-57.9480 ;50.0000
P243=-57.5000 ;50.4350
P244=-57.4270 ;50.5000
P245=-57.0000 ;50.9310
P246=-56.9320 ;51.0000
P247=-56.5250 ;51.5000
P248=-56.5000 ;51.5380
P249=-56.1930 ;52.0000
P250=-56.0000 ;52.4180
P251=-55.9460 ;52.5000
P252=-55.6710 ;53.0000
P253=-55.5000 ;53.4530
P254=-55.4790 ;53.5000
P255=-55.3370 ;54.0000
P256=-55.2990 ;54.5000
P257=-55.3600 ;55.0000
P258=-55.4520 ;55.5000
P259=-55.5000 ;55.7860
[C8]
gain=-30.00
n_point=177
P1=-69.0000 ;47.1120
P2=-68.9770 ;47.0000
P3=-68.9440 ;46.5000
P4=-68.9620 ;46.0000
P5=-69.0000 ;45.6640
P6=-69.0220 ;45.5000
P7=-69.1630 ;45.0000
P8=-69.3510 ;44.5000

P9=-69.5000 ;44.1420
P10=-69.5660 ;44.0000
P11=-69.8330 ;43.5000
P12=-70.0000 ;43.2270
P13=-70.1510 ;43.0000
P14=-70.4690 ;42.5000
P15=-70.5000 ;42.4600
P16=-70.8530 ;42.0000
P17=-71.0000 ;41.8160
P18=-71.2630 ;41.5000
P19=-71.5000 ;41.1990
P20=-71.6660 ;41.0000
P21=-72.0000 ;40.6330
P22=-72.1260 ;40.5000
P23=-72.5000 ;40.0560
P24=-72.5510 ;40.0000
P25=-73.0000 ;39.5420
P26=-73.0430 ;39.5000
P27=-73.4890 ;39.0000
P28=-73.5000 ;38.9890
P29=-73.9830 ;38.5000
P30=-74.0000 ;38.4820
P31=-74.4500 ;38.0000
P32=-74.5000 ;37.9480
P33=-74.9130 ;37.5000
P34=-75.0000 ;37.4130
P35=-75.3930 ;37.0000
P36=-75.5000 ;36.8900
P37=-75.8600 ;36.5000
P38=-76.0000 ;36.3620
P39=-76.3380 ;36.0000
P40=-76.5000 ;35.8560
P41=-76.8620 ;35.5000
P42=-77.0000 ;35.3830
P43=-77.4090 ;35.0000
P44=-77.5000 ;34.9270
P45=-78.0000 ;34.5200
P46=-78.0230 ;34.5000
P47=-78.5000 ;34.1890
P48=-78.7300 ;34.0000
P49=-79.0000 ;33.8550
P50=-79.4520 ;33.5000
P51=-79.5000 ;33.4800
P52=-80.0000 ;33.2120
P53=-80.3140 ;33.0000
P54=-80.5000 ;32.9040
P55=-81.0000 ;32.7070
P56=-81.4210 ;32.5000
P57=-81.5000 ;32.4460
P58=-82.0000 ;32.2920
P59=-82.5000 ;32.1950
P60=-83.0000 ;32.0880
P61=-83.5000 ;32.0130
P62=-84.0000 ;32.0060
P63=-84.5000 ;32.0660
P64=-85.0000 ;32.1910
P65=-85.5000 ;32.3720

P66=-85.7630 ;32.5000
P67=-86.0000 ;32.6850
P68=-86.3870 ;33.0000
P69=-86.5000 ;33.1340
P70=-86.7950 ;33.5000
P71=-87.0000 ;33.8930
P72=-87.0540 ;34.0000
P73=-87.1900 ;34.5000
P74=-87.2270 ;35.0000
P75=-87.0000 ;35.4130
P76=-86.5000 ;35.2420
P77=-86.0000 ;35.0580
P78=-85.7060 ;35.0000
P79=-85.5000 ;34.9460
P80=-85.0000 ;34.8640
P81=-84.5000 ;34.8970
P82=-84.0820 ;35.0000
P83=-84.5000 ;35.2580
P84=-84.6050 ;35.5000
P85=-85.0000 ;35.7560
P86=-85.3210 ;36.0000
P87=-85.5000 ;36.1930
P88=-85.7100 ;36.5000
P89=-85.9330 ;37.0000
P90=-86.0000 ;37.2380
P91=-86.0540 ;37.5000
P92=-86.0180 ;38.0000
P93=-86.0000 ;38.0880
P94=-85.9230 ;38.5000
P95=-85.7860 ;39.0000
P96=-85.6660 ;39.5000
P97=-85.5000 ;39.7800
P98=-85.3660 ;40.0000
P99=-85.1580 ;40.5000
P100=-85.0000 ;40.7410
P101=-84.8250 ;41.0000
P102=-84.5000 ;41.4920
P103=-84.4940 ;41.5000
P104=-84.2800 ;42.0000
P105=-84.5000 ;42.2020
P106=-84.7810 ;42.0000
P107=-85.0000 ;41.8750
P108=-85.4260 ;41.5000
P109=-85.5000 ;41.4230
P110=-85.9510 ;41.0000
P111=-86.0000 ;40.9330
P112=-86.4750 ;40.5000
P113=-86.5000 ;40.4530
P114=-86.5540 ;40.5000
P115=-86.5520 ;41.0000
P116=-86.5000 ;41.1950
P117=-86.3770 ;41.5000
P118=-86.1570 ;42.0000
P119=-86.0000 ;42.3290
P120=-85.9040 ;42.5000
P121=-85.5960 ;43.0000
P122=-85.5000 ;43.1700

P123=-85.2750 ;43.5000
P124=-85.0000 ;43.9610
P125=-84.9730 ;44.0000
P126=-84.5570 ;44.5000
P127=-84.5000 ;44.5680
P128=-84.1090 ;45.0000
P129=-84.0000 ;45.1260
P130=-83.6510 ;45.5000
P131=-83.5000 ;45.6610
P132=-83.1710 ;46.0000
P133=-83.0000 ;46.1540
P134=-82.6140 ;46.5000
P135=-82.5000 ;46.5980
P136=-82.0340 ;47.0000
P137=-82.0000 ;47.0330
P138=-81.5000 ;47.4020
P139=-81.3760 ;47.5000
P140=-81.0000 ;47.7590
P141=-80.6440 ;48.0000
P142=-80.5000 ;48.1090
P143=-80.0000 ;48.3870
P144=-79.8250 ;48.5000
P145=-79.5000 ;48.7080
P146=-79.0000 ;48.9490
P147=-78.9060 ;49.0000
P148=-78.5000 ;49.1950
P149=-78.0000 ;49.4190
P150=-77.8370 ;49.5000
P151=-77.5000 ;49.6170
P152=-77.0000 ;49.7720
P153=-76.5000 ;49.9670
P154=-76.4080 ;50.0000
P155=-76.0000 ;50.0930
P156=-75.5000 ;50.1820
P157=-75.0000 ;50.2950
P158=-74.5000 ;50.4150
P159=-74.0950 ;50.5000
P160=-74.0000 ;50.5150
P161=-73.5000 ;50.5570
P162=-73.0000 ;50.5860
P163=-72.5000 ;50.6030
P164=-72.0000 ;50.5890
P165=-71.5000 ;50.5360
P166=-71.2890 ;50.5000
P167=-71.0000 ;50.4000
P168=-70.5000 ;50.1460
P169=-70.2600 ;50.0000
P170=-70.0000 ;49.7110
P171=-69.8340 ;49.5000
P172=-69.5880 ;49.0000
P173=-69.5000 ;48.7770
P174=-69.3990 ;48.5000
P175=-69.2590 ;48.0000
P176=-69.1140 ;47.5000
P177=-69.0000 ;47.1120
[C9]
gain=-30.00

n_point=72
P1=-72.5000 ;46.9520
P2=-72.5250 ;47.0000
P3=-72.6437 ;47.0455
P4=-72.7625 ;47.0910
P5=-72.8813 ;47.1365
P6=-73.0000 ;47.1820
P7=-73.1250 ;47.1958
P8=-73.2500 ;47.2095
P9=-73.3750 ;47.2233
P10=-73.5000 ;47.2370
P11=-73.6250 ;47.2230
P12=-73.7500 ;47.2090
P13=-73.8750 ;47.1950
P14=-74.0000 ;47.1810
P15=-74.1250 ;47.1455
P16=-74.2500 ;47.1100
P17=-74.3750 ;47.0745
P18=-74.5000 ;47.0390
P19=-74.6200 ;47.0000
P20=-74.7467 ;46.9663
P21=-74.8733 ;46.9327
P22=-75.0000 ;46.8990
P23=-75.1250 ;46.8565
P24=-75.2500 ;46.8140
P25=-75.3750 ;46.7715
P26=-75.5000 ;46.7290
P27=-75.6250 ;46.6860
P28=-75.7500 ;46.6430
P29=-75.8750 ;46.6000
P30=-76.0000 ;46.5570
P31=-76.0780 ;46.5285
P32=-76.1560 ;46.5000
P33=-76.0780 ;46.4750
P34=-76.0000 ;46.4500
P35=-75.8750 ;46.4235
P36=-75.7500 ;46.3970
P37=-75.6250 ;46.3705
P38=-75.5000 ;46.3440
P39=-75.3750 ;46.3230
P40=-75.2500 ;46.3020
P41=-75.1250 ;46.2810
P42=-75.0000 ;46.2600
P43=-74.8750 ;46.2387
P44=-74.7500 ;46.2175
P45=-74.6250 ;46.1963
P46=-74.5000 ;46.1750
P47=-74.3750 ;46.1570
P48=-74.2500 ;46.1390
P49=-74.1250 ;46.1210
P50=-74.0000 ;46.1030
P51=-73.8750 ;46.0938
P52=-73.7500 ;46.0845
P53=-73.6250 ;46.0752
P54=-73.5000 ;46.0660
P55=-73.3750 ;46.0525
P56=-73.2500 ;46.0390

P57=-73.1250 ;46.0255
P58=-73.0000 ;46.0120
P59=-72.9000 ;46.0490
P60=-72.8000 ;46.0860
P61=-72.7000 ;46.1230
P62=-72.6000 ;46.1600
P63=-72.5000 ;46.1970
P64=-72.4427 ;46.2728
P65=-72.3855 ;46.3485
P66=-72.3282 ;46.4242
P67=-72.2710 ;46.5000
P68=-72.3168 ;46.5904
P69=-72.3626 ;46.6808
P70=-72.4084 ;46.7712
P71=-72.4542 ;46.8616
P72=-72.5000 ;46.9520
[C10]
gain=-20.00
n_point=115
P1=-73.5000 ;44.5050
P2=-73.4970 ;44.5000
P3=-73.4475 ;44.2500
P4=-73.3980 ;44.0000
P5=-73.4110 ;43.7500
P6=-73.4240 ;43.5000
P7=-73.5000 ;43.1490
P8=-73.5290 ;43.0000
P9=-73.6170 ;42.7500
P10=-73.7050 ;42.5000
P11=-73.8145 ;42.2500
P12=-73.9240 ;42.0000
P13=-74.0000 ;41.8840
P14=-74.2090 ;41.5000
P15=-74.3545 ;41.2800
P16=-74.5000 ;41.0600
P17=-74.5380 ;41.0000
P18=-74.7205 ;40.7500
P19=-74.9030 ;40.5000
P20=-75.0000 ;40.3900
P21=-75.1595 ;40.1950
P22=-75.3190 ;40.0000
P23=-75.5000 ;39.8220
P24=-75.7950 ;39.5000
P25=-76.0000 ;39.3070
P26=-76.3090 ;39.0000
P27=-76.5000 ;38.8470
P28=-76.6960 ;38.6735
P29=-76.8920 ;38.5000
P30=-77.0000 ;38.4260
P31=-77.2500 ;38.2215
P32=-77.5000 ;38.0170
P33=-77.5200 ;38.0000
P34=-77.7600 ;37.8425
P35=-78.0000 ;37.6850
P36=-78.2460 ;37.5000
P37=-78.5000 ;37.3840
P38=-78.7500 ;37.1985

P39=-79.0000 ;37.0130
P40=-79.0200 ;37.0000
P41=-79.5000 ;36.7890
P42=-79.7360 ;36.6445
P43=-79.9720 ;36.5000
P44=-80.0000 ;36.4810
P45=-80.5000 ;36.2890
P46=-81.0000 ;36.1000
P47=-81.2760 ;36.0000
P48=-81.5000 ;35.9130
P49=-82.0000 ;35.8070
P50=-82.5000 ;35.7530
P51=-83.0000 ;35.7410
P52=-83.5000 ;35.7840
P53=-84.0000 ;35.8900
P54=-84.3100 ;36.0000
P55=-84.5000 ;36.1150
P56=-84.7325 ;36.3075
P57=-84.9650 ;36.5000
P58=-85.0000 ;36.5440
P59=-85.1230 ;36.7720
P60=-85.2460 ;37.0000
P61=-85.3220 ;37.2500
P62=-85.3980 ;37.5000
P63=-85.4190 ;37.7500
P64=-85.4400 ;38.0000
P65=-85.4065 ;38.2500
P66=-85.3730 ;38.5000
P67=-85.3135 ;38.7500
P68=-85.2540 ;39.0000
P69=-85.1775 ;39.2500
P70=-85.1010 ;39.5000
P71=-85.0000 ;39.7620
P72=-84.8850 ;40.0000
P73=-84.7390 ;40.2500
P74=-84.5930 ;40.5000
P75=-84.5000 ;40.6600
P76=-84.2560 ;41.0000
P77=-84.0000 ;41.3600
P78=-83.8870 ;41.5000
P79=-83.6935 ;41.7310
P80=-83.5000 ;41.9620
P81=-83.4650 ;42.0000
P82=-83.2325 ;42.2295
P83=-83.0000 ;42.4590
P84=-82.9580 ;42.5000
P85=-82.7290 ;42.6980
P86=-82.5000 ;42.8960
P87=-82.3760 ;43.0000
P88=-82.0000 ;43.2950
P89=-81.7300 ;43.5000
P90=-81.5000 ;43.6710
P91=-81.2510 ;43.8355
P92=-81.0020 ;44.0000
P93=-81.0000 ;44.0020
P94=-80.7500 ;44.1510
P95=-80.5000 ;44.3000

P96=-80.1350 ;44.5000
P97=-80.0000 ;44.5930
P98=-79.5000 ;44.8140
P99=-79.0580 ;45.0000
P100=-79.0000 ;45.0330
P101=-78.5000 ;45.2210
P102=-78.0000 ;45.3630
P103=-77.5260 ;45.5000
P104=-77.5000 ;45.5080
P105=-77.0000 ;45.6120
P106=-76.5000 ;45.6710
P107=-76.0000 ;45.7000
P108=-75.5000 ;45.6960
P109=-75.0000 ;45.6420
P110=-74.5000 ;45.5150
P111=-74.4590 ;45.5000
P112=-74.0000 ;45.2000
P113=-73.7720 ;45.0000
P114=-73.6360 ;44.7525
P115=-73.5000 ;44.5050
[C11]
gain=-10.00
n_point=105
P1=-75.5000 ;43.9340
P2=-75.3955 ;43.7170
P3=-75.2910 ;43.5000
P4=-75.2560 ;43.2500
P5=-75.2210 ;43.0000
P6=-75.2485 ;42.7500
P7=-75.2760 ;42.5000
P8=-75.3440 ;42.2500
P9=-75.4120 ;42.0000
P10=-75.5000 ;41.7800
P11=-75.6200 ;41.5000
P12=-75.7540 ;41.2500
P13=-75.8880 ;41.0000
P14=-76.0000 ;40.8230
P15=-76.1070 ;40.6615
P16=-76.2140 ;40.5000
P17=-76.3570 ;40.3030
P18=-76.5000 ;40.1060
P19=-76.5790 ;40.0000
P20=-76.7895 ;39.7560
P21=-77.0000 ;39.5120
P22=-77.0110 ;39.5000
P23=-77.2555 ;39.2545
P24=-77.5000 ;39.0090
P25=-77.5090 ;39.0000
P26=-77.7545 ;38.7890
P27=-78.0000 ;38.5780
P28=-78.0920 ;38.5000
P29=-78.2960 ;38.3530
P30=-78.5000 ;38.2060
P31=-78.7790 ;38.0000
P32=-79.0000 ;37.8620
P33=-79.2500 ;37.7065
P34=-79.5000 ;37.5510

P35=-79.5890 ;37.5000
P36=-79.7945 ;37.4035
P37=-80.0000 ;37.3070
P38=-80.2500 ;37.1915
P39=-80.5000 ;37.0760
P40=-80.6920 ;37.0000
P41=-81.0000 ;36.9040
P42=-81.2500 ;36.8440
P43=-81.5000 ;36.7840
P44=-81.7500 ;36.7460
P45=-82.0000 ;36.7080
P46=-82.2500 ;36.7045
P47=-82.5000 ;36.7010
P48=-82.7500 ;36.7400
P49=-83.0000 ;36.7790
P50=-83.2500 ;36.8770
P51=-83.5000 ;36.9750
P52=-83.5380 ;37.0000
P53=-83.7690 ;37.2375
P54=-84.0000 ;37.4750
P55=-84.0170 ;37.5000
P56=-84.0955 ;37.7500
P57=-84.1740 ;38.0000
P58=-84.1920 ;38.2500
P59=-84.2100 ;38.5000
P60=-84.1825 ;38.7500
P61=-84.1550 ;39.0000
P62=-84.0895 ;39.2500
P63=-84.0240 ;39.5000
P64=-84.0000 ;39.5620
P65=-83.9025 ;39.7810
P66=-83.8050 ;40.0000
P67=-83.6745 ;40.2500
P68=-83.5440 ;40.5000
P69=-83.5000 ;40.5670
P70=-83.3465 ;40.7835
P71=-83.1930 ;41.0000
P72=-83.0000 ;41.2420
P73=-82.7770 ;41.5000
P74=-82.6385 ;41.6470
P75=-82.5000 ;41.7940
P76=-82.2920 ;42.0000
P77=-82.0000 ;42.2640
P78=-81.7260 ;42.5000
P79=-81.5000 ;42.6720
P80=-81.2845 ;42.8360
P81=-81.0690 ;43.0000
P82=-81.0000 ;43.0440
P83=-80.7500 ;43.1945
P84=-80.5000 ;43.3450
P85=-80.2390 ;43.5000
P86=-80.0000 ;43.6220
P87=-79.7500 ;43.7420
P88=-79.5000 ;43.8620
P89=-79.1860 ;44.0000
P90=-79.0000 ;44.0700
P91=-78.7500 ;44.1500

P92=-78.5000 ;44.2300
P93=-78.2500 ;44.2975
P94=-78.0000 ;44.3650
P95=-77.7500 ;44.4125
P96=-77.5000 ;44.4600
P97=-77.2500 ;44.4790
P98=-77.0000 ;44.4980
P99=-76.7500 ;44.4775
P100=-76.5000 ;44.4570
P101=-76.2500 ;44.3790
P102=-76.0000 ;44.3010
P103=-75.7740 ;44.1505
P104=-75.5480 ;44.0000
P105=-75.5000 ;43.9340

[C12]

gain=-4.00

n_point=87

P1=-77.0000 ;42.3060
P2=-76.9745 ;42.1530
P3=-76.9490 ;42.0000
P4=-76.9745 ;41.8525
P5=-77.0000 ;41.7050
P6=-77.0380 ;41.5000
P7=-77.1027 ;41.3333
P8=-77.1673 ;41.1667
P9=-77.2320 ;41.0000
P10=-77.3213 ;40.8360
P11=-77.4107 ;40.6720
P12=-77.5000 ;40.5080
P13=-77.5050 ;40.5000
P14=-77.6290 ;40.3333
P15=-77.7530 ;40.1667
P16=-77.8770 ;40.0000
P17=-78.0000 ;39.8580
P18=-78.1620 ;39.6790
P19=-78.3240 ;39.5000
P20=-78.5000 ;39.3360
P21=-78.6915 ;39.1680
P22=-78.8830 ;39.0000
P23=-79.0000 ;38.9120
P24=-79.1667 ;38.7957
P25=-79.3333 ;38.6793
P26=-79.5000 ;38.5630
P27=-79.6030 ;38.5000
P28=-79.8015 ;38.3975
P29=-80.0000 ;38.2950
P30=-80.2500 ;38.1830
P31=-80.5000 ;38.0710
P32=-80.7200 ;38.0000
P33=-80.8600 ;37.9625
P34=-81.0000 ;37.9250
P35=-81.2500 ;37.8940
P36=-81.5000 ;37.8630
P37=-81.7500 ;37.8850
P38=-82.0000 ;37.9070
P39=-82.2530 ;38.0000
P40=-82.3765 ;38.0885

P41=-82.5000 ;38.1770
P42=-82.6150 ;38.3385
P43=-82.7300 ;38.5000
P44=-82.7617 ;38.6667
P45=-82.7933 ;38.8333
P46=-82.8250 ;39.0000
P47=-82.8047 ;39.1667
P48=-82.7843 ;39.3333
P49=-82.7640 ;39.5000
P50=-82.7100 ;39.6667
P51=-82.6560 ;39.8333
P52=-82.6020 ;40.0000
P53=-82.5000 ;40.1940
P54=-82.4095 ;40.3470
P55=-82.3190 ;40.5000
P56=-82.2127 ;40.6497
P57=-82.1063 ;40.7993
P58=-82.0000 ;40.9490
P59=-81.9590 ;41.0000
P60=-81.8060 ;41.1647
P61=-81.6530 ;41.3293
P62=-81.5000 ;41.4940
P63=-81.4930 ;41.5000
P64=-81.3287 ;41.6367
P65=-81.1643 ;41.7733
P66=-81.0000 ;41.9100
P67=-80.8840 ;42.0000
P68=-80.6920 ;42.1250
P69=-80.5000 ;42.2500
P70=-80.2935 ;42.3750
P71=-80.0870 ;42.5000
P72=-80.0000 ;42.5470
P73=-79.7500 ;42.6550
P74=-79.5000 ;42.7630
P75=-79.2500 ;42.8520
P76=-79.0000 ;42.9410
P77=-78.7340 ;43.0000
P78=-78.5000 ;43.0450
P79=-78.2500 ;43.0535
P80=-78.0000 ;43.0620
P81=-77.8265 ;43.0310
P82=-77.6530 ;43.0000
P83=-77.5000 ;42.9490
P84=-77.3513 ;42.7993
P85=-77.2027 ;42.6497
P86=-77.0540 ;42.5000
P87=-77.0000 ;42.3060
[C13]
gain=-2.00
n_point=83
P1=-78.0000 ;42.0020
P2=-77.9980 ;42.0000
P3=-77.9673 ;41.8750
P4=-77.9365 ;41.7500
P5=-77.9058 ;41.6250
P6=-77.8750 ;41.5000
P7=-77.8980 ;41.3750

P8=-77.9210 ;41.2500
P9=-77.9440 ;41.1250
P10=-77.9670 ;41.0000
P11=-78.0000 ;40.9300
P12=-78.0733 ;40.7867
P13=-78.1467 ;40.6433
P14=-78.2200 ;40.5000
P15=-78.3133 ;40.3680
P16=-78.4067 ;40.2360
P17=-78.5000 ;40.1040
P18=-78.5820 ;40.0000
P19=-78.6865 ;39.8905
P20=-78.7910 ;39.7810
P21=-78.8955 ;39.6715
P22=-79.0000 ;39.5620
P23=-79.0670 ;39.5000
P24=-79.2113 ;39.3903
P25=-79.3557 ;39.2807
P26=-79.5000 ;39.1710
P27=-79.6285 ;39.0855
P28=-79.7570 ;39.0000
P29=-79.8785 ;38.9355
P30=-80.0000 ;38.8710
P31=-80.1667 ;38.8013
P32=-80.3333 ;38.7317
P33=-80.5000 ;38.6620
P34=-80.6667 ;38.6223
P35=-80.8333 ;38.5827
P36=-81.0000 ;38.5430
P37=-81.1667 ;38.5623
P38=-81.3333 ;38.5817
P39=-81.5000 ;38.6010
P40=-81.6250 ;38.6980
P41=-81.7500 ;38.7950
P42=-81.8750 ;38.8920
P43=-82.0000 ;38.9890
P44=-82.0060 ;39.0000
P45=-82.0163 ;39.1250
P46=-82.0265 ;39.2500
P47=-82.0367 ;39.3750
P48=-82.0470 ;39.5000
P49=-82.0235 ;39.6015
P50=-82.0000 ;39.7030
P51=-81.9590 ;39.8515
P52=-81.9180 ;40.0000
P53=-81.8512 ;40.1250
P54=-81.7845 ;40.2500
P55=-81.7178 ;40.3750
P56=-81.6510 ;40.5000
P57=-81.5755 ;40.6000
P58=-81.5000 ;40.7000
P59=-81.4137 ;40.8000
P60=-81.3273 ;40.9000
P61=-81.2410 ;41.0000
P62=-81.1205 ;41.1150
P63=-81.0000 ;41.2300
P64=-80.8937 ;41.3200

P65=-80.7873 ;41.4100
P66=-80.6810 ;41.5000
P67=-80.5905 ;41.5655
P68=-80.5000 ;41.6310
P69=-80.3333 ;41.7330
P70=-80.1667 ;41.8350
P71=-80.0000 ;41.9370
P72=-79.8630 ;42.0000
P73=-79.6815 ;42.0700
P74=-79.5000 ;42.1400
P75=-79.3333 ;42.1803
P76=-79.1667 ;42.2207
P77=-79.0000 ;42.2610
P78=-78.8333 ;42.2587
P79=-78.6667 ;42.2563
P80=-78.5000 ;42.2540
P81=-78.3333 ;42.1700
P82=-78.1667 ;42.0860
P83=-78.0000 ;42.0020
[C14]
gain=-40.00
n_point=84
P1=-77.5000 ;31.2110
P2=-77.6667 ;31.1463
P3=-77.8333 ;31.0817
P4=-78.0000 ;31.0170
P5=-78.0220 ;31.0000
P6=-78.1813 ;30.9067
P7=-78.3407 ;30.8133
P8=-78.5000 ;30.7200
P9=-78.6430 ;30.6100
P10=-78.7860 ;30.5000
P11=-78.8930 ;30.3690
P12=-79.0000 ;30.2380
P13=-79.1667 ;30.1967
P14=-79.3333 ;30.1553
P15=-79.5000 ;30.1140
P16=-79.6620 ;30.0000
P17=-79.7747 ;29.9060
P18=-79.8873 ;29.8120
P19=-80.0000 ;29.7180
P20=-80.1667 ;29.6893
P21=-80.3333 ;29.6607
P22=-80.5000 ;29.6320
P23=-80.5990 ;29.5660
P24=-80.6980 ;29.5000
P25=-80.8490 ;29.3845
P26=-81.0000 ;29.2690
P27=-81.1667 ;29.2390
P28=-81.3333 ;29.2090
P29=-81.5000 ;29.1790
P30=-81.6500 ;29.0895
P31=-81.8000 ;29.0000
P32=-81.9000 ;28.8620
P33=-82.0000 ;28.7240
P34=-82.1667 ;28.7160
P35=-82.3333 ;28.7080

P36=-82.5000 ;28.7000
P37=-82.6667 ;28.6477
P38=-82.8333 ;28.5953
P39=-83.0000 ;28.5430
P40=-83.1830 ;28.5000
P41=-83.0000 ;28.4080
P42=-82.8333 ;28.3677
P43=-82.6667 ;28.3273
P44=-82.5000 ;28.2870
P45=-82.3333 ;28.3160
P46=-82.1667 ;28.3450
P47=-82.0000 ;28.3740
P48=-81.8860 ;28.4370
P49=-81.7720 ;28.5000
P50=-81.6360 ;28.5980
P51=-81.5000 ;28.6960
P52=-81.3333 ;28.7173
P53=-81.1667 ;28.7387
P54=-81.0000 ;28.7600
P55=-80.8740 ;28.8400
P56=-80.7480 ;28.9200
P57=-80.6220 ;29.0000
P58=-80.5610 ;29.0910
P59=-80.5000 ;29.1820
P60=-80.3333 ;29.2197
P61=-80.1667 ;29.2573
P62=-80.0000 ;29.2950
P63=-79.8487 ;29.3633
P64=-79.6973 ;29.4317
P65=-79.5460 ;29.5000
P66=-79.5000 ;29.5710
P67=-79.3333 ;29.6527
P68=-79.1667 ;29.7343
P69=-79.0000 ;29.8160
P70=-78.8675 ;29.9080
P71=-78.7350 ;30.0000
P72=-78.6175 ;30.0940
P73=-78.5000 ;30.1880
P74=-78.3333 ;30.2847
P75=-78.1667 ;30.3813
P76=-78.0000 ;30.4780
P77=-77.9720 ;30.5000
P78=-77.8147 ;30.6170
P79=-77.6573 ;30.7340
P80=-77.5000 ;30.8510
P81=-77.3980 ;30.9255
P82=-77.2960 ;31.0000
P83=-77.3980 ;31.1055
P84=-77.5000 ;31.2110
[C15]
gain=-6.00
n_point=92
P1=-76.5000 ;43.1610
P2=-76.3890 ;43.0000
P3=-76.3365 ;42.7500
P4=-76.2840 ;42.5000
P5=-76.3005 ;42.2500

P6=-76.3170 ;42.0000
P7=-76.3890 ;41.7500
P8=-76.4610 ;41.5000
P9=-76.5000 ;41.4120
P10=-76.5955 ;41.2060
P11=-76.6910 ;41.0000
P12=-76.8385 ;40.7500
P13=-76.9860 ;40.5000
P14=-77.0000 ;40.4800
P15=-77.1187 ;40.3200
P16=-77.2373 ;40.1600
P17=-77.3560 ;40.0000
P18=-77.5000 ;39.8350
P19=-77.6490 ;39.6675
P20=-77.7980 ;39.5000
P21=-78.0000 ;39.3030
P22=-78.1610 ;39.1515
P23=-78.3220 ;39.0000
P24=-78.5000 ;38.8530
P25=-78.7230 ;38.6765
P26=-78.9460 ;38.5000
P27=-79.0000 ;38.4640
P28=-79.2500 ;38.3065
P29=-79.5000 ;38.1490
P30=-79.7560 ;38.0000
P31=-80.0000 ;37.8810
P32=-80.2500 ;37.7725
P33=-80.5000 ;37.6640
P34=-80.7315 ;37.5820
P35=-80.9630 ;37.5000
P36=-81.0000 ;37.4890
P37=-81.2500 ;37.4460
P38=-81.5000 ;37.4030
P39=-81.7500 ;37.3925
P40=-82.0000 ;37.3820
P41=-82.2500 ;37.4190
P42=-82.5000 ;37.4560
P43=-82.6130 ;37.5000
P44=-82.8065 ;37.6305
P45=-83.0000 ;37.7610
P46=-83.1020 ;37.8805
P47=-83.2040 ;38.0000
P48=-83.2895 ;38.2500
P49=-83.3750 ;38.5000
P50=-83.3780 ;38.7500
P51=-83.3810 ;39.0000
P52=-83.3300 ;39.2500
P53=-83.2790 ;39.5000
P54=-83.1840 ;39.7500
P55=-83.0890 ;40.0000
P56=-83.0000 ;40.1740
P57=-82.9055 ;40.3370
P58=-82.8110 ;40.5000
P59=-82.6555 ;40.7285
P60=-82.5000 ;40.9570
P61=-82.4680 ;41.0000
P62=-82.3227 ;41.1667

P63=-82.1773 ;41.3333
P64=-82.0320 ;41.5000
P65=-82.0000 ;41.5320
P66=-81.8333 ;41.6853
P67=-81.6667 ;41.8387
P68=-81.5000 ;41.9920
P69=-81.4900 ;42.0000
P70=-81.2450 ;42.1845
P71=-81.0000 ;42.3690
P72=-80.8140 ;42.5000
P73=-80.6570 ;42.5990
P74=-80.5000 ;42.6980
P75=-80.2500 ;42.8470
P76=-80.0000 ;42.9960
P77=-79.9920 ;43.0000
P78=-79.7460 ;43.1070
P79=-79.5000 ;43.2140
P80=-79.2500 ;43.3130
P81=-79.0000 ;43.4120
P82=-78.7040 ;43.5000
P83=-78.5000 ;43.5510
P84=-78.2500 ;43.5865
P85=-78.0000 ;43.6220
P86=-77.7500 ;43.6245
P87=-77.5000 ;43.6270
P88=-77.2500 ;43.5795
P89=-77.0000 ;43.5320
P90=-76.9260 ;43.5000
P91=-76.7130 ;43.3305
P92=-76.5000 ;43.1610
[C16]
gain=-30.00
n_point=71
P1=-77.0000 ;37.6910
P2=-77.0833 ;37.6723
P3=-77.1667 ;37.6537
P4=-77.2500 ;37.6350
P5=-77.3333 ;37.6163
P6=-77.4167 ;37.5977
P7=-77.5000 ;37.5790
P8=-77.5510 ;37.5395
P9=-77.6020 ;37.5000
P10=-77.6816 ;37.4530
P11=-77.7612 ;37.4060
P12=-77.8408 ;37.3590
P13=-77.9204 ;37.3120
P14=-78.0000 ;37.2650
P15=-78.0802 ;37.2208
P16=-78.1603 ;37.1767
P17=-78.2405 ;37.1325
P18=-78.3207 ;37.0883
P19=-78.4008 ;37.0442
P20=-78.4810 ;37.0000
P21=-78.4873 ;36.9387
P22=-78.4937 ;36.8773
P23=-78.5000 ;36.8160
P24=-78.5833 ;36.7853

P25=-78.6667 ;36.7547
P26=-78.7500 ;36.7240
P27=-78.8333 ;36.6933
P28=-78.9167 ;36.6627
P29=-79.0000 ;36.6320
P30=-79.0763 ;36.5880
P31=-79.1527 ;36.5440
P32=-79.2290 ;36.5000
P33=-79.1717 ;36.4525
P34=-79.1145 ;36.4050
P35=-79.0573 ;36.3575
P36=-79.0000 ;36.3100
P37=-78.9167 ;36.3362
P38=-78.8333 ;36.3623
P39=-78.7500 ;36.3885
P40=-78.6667 ;36.4147
P41=-78.5833 ;36.4408
P42=-78.5000 ;36.4670
P43=-78.4490 ;36.5000
P44=-78.3742 ;36.5308
P45=-78.2993 ;36.5617
P46=-78.2245 ;36.5925
P47=-78.1497 ;36.6233
P48=-78.0748 ;36.6542
P49=-78.0000 ;36.6850
P50=-77.9350 ;36.7300
P51=-77.8700 ;36.7750
P52=-77.8050 ;36.8200
P53=-77.7400 ;36.8650
P54=-77.6750 ;36.9100
P55=-77.6100 ;36.9550
P56=-77.5450 ;37.0000
P57=-77.5225 ;37.0755
P58=-77.5000 ;37.1510
P59=-77.4167 ;37.1882
P60=-77.3333 ;37.2253
P61=-77.2500 ;37.2625
P62=-77.1667 ;37.2997
P63=-77.0833 ;37.3368
P64=-77.0000 ;37.3740
P65=-76.9403 ;37.4160
P66=-76.8807 ;37.4580
P67=-76.8210 ;37.5000
P68=-76.8658 ;37.5477
P69=-76.9105 ;37.5955
P70=-76.9552 ;37.6432
P71=-77.0000 ;37.6910
[C17]
gain=-50.00
n_point=97
P1=-71.5000 ;23.2280
P2=-71.7750 ;23.0000
P3=-72.0000 ;22.8300
P4=-72.2100 ;22.6650
P5=-72.4200 ;22.5000
P6=-72.5000 ;22.3870
P7=-72.7500 ;22.2640

P8=-73.0000 ;22.1410
P9=-73.1650 ;22.0000
P10=-73.3325 ;21.8785
P11=-73.5000 ;21.7570
P12=-73.6490 ;21.6285
P13=-73.7980 ;21.5000
P14=-74.0000 ;21.2950
P15=-74.2205 ;21.1475
P16=-74.4410 ;21.0000
P17=-74.5000 ;20.9370
P18=-74.7500 ;20.7880
P19=-75.0000 ;20.6390
P20=-75.1670 ;20.5000
P21=-75.3335 ;20.3795
P22=-75.5000 ;20.2590
P23=-75.6880 ;20.1295
P24=-75.8760 ;20.0000
P25=-76.0000 ;19.8520
P26=-76.2500 ;19.7365
P27=-76.5000 ;19.6210
P28=-76.6530 ;19.5000
P29=-76.8265 ;19.3780
P30=-77.0000 ;19.2560
P31=-77.2340 ;19.1280
P32=-77.4680 ;19.0000
P33=-77.5000 ;18.8970
P34=-77.7500 ;18.8250
P35=-78.0000 ;18.7530
P36=-78.1880 ;18.6265
P37=-78.3760 ;18.5000
P38=-78.5000 ;18.2060
P39=-78.7500 ;18.2415
P40=-79.0000 ;18.2770
P41=-79.2140 ;18.1385
P42=-79.4280 ;18.0000
P43=-79.5000 ;17.8500
P44=-79.7500 ;17.7840
P45=-80.0000 ;17.7180
P46=-80.2500 ;17.6140
P47=-80.5000 ;17.5100
P48=-80.5180 ;17.5000
P49=-80.5000 ;17.1820
P50=-80.2500 ;17.2170
P51=-80.0000 ;17.2520
P52=-79.7500 ;17.3000
P53=-79.5000 ;17.3480
P54=-79.2790 ;17.5000
P55=-79.0000 ;17.6650
P56=-78.7500 ;17.7895
P57=-78.5000 ;17.9140
P58=-78.3670 ;18.0000
P59=-78.1835 ;18.0975
P60=-78.0000 ;18.1950
P61=-77.7500 ;18.3055
P62=-77.5000 ;18.4160
P63=-77.3840 ;18.5000
P64=-77.1920 ;18.6170

P65=-77.0000 ;18.7340
P66=-76.7815 ;18.8670
P67=-76.5630 ;19.0000
P68=-76.5000 ;19.1270
P69=-76.2500 ;19.2055
P70=-76.0000 ;19.2840
P71=-75.7220 ;19.5000
P72=-75.5000 ;19.6930
P73=-75.2500 ;19.8270
P74=-75.0000 ;19.9610
P75=-74.9520 ;20.0000
P76=-74.7260 ;20.1300
P77=-74.5000 ;20.2600
P78=-74.3575 ;20.3800
P79=-74.2150 ;20.5000
P80=-74.0000 ;20.7050
P81=-73.7965 ;20.8525
P82=-73.5930 ;21.0000
P83=-73.5000 ;21.0910
P84=-73.2500 ;21.2470
P85=-73.0000 ;21.4030
P86=-72.8850 ;21.5000
P87=-72.6925 ;21.6335
P88=-72.5000 ;21.7670
P89=-72.2220 ;22.0000
P90=-72.0000 ;22.1730
P91=-71.8065 ;22.3365
P92=-71.6130 ;22.5000
P93=-71.5000 ;22.6580
P94=-71.2725 ;22.8290
P95=-71.0450 ;23.0000
P96=-71.2725 ;23.1140
P97=-71.5000 ;23.2280

[C18]

gain=-50.00

n_point=69

P1=-81.0000 ;17.2350
P2=-81.1000 ;17.2354
P3=-81.2000 ;17.2358
P4=-81.3000 ;17.2362
P5=-81.4000 ;17.2366
P6=-81.5000 ;17.2370
P7=-81.5766 ;17.1896
P8=-81.6532 ;17.1422
P9=-81.7298 ;17.0948
P10=-81.8064 ;17.0474
P11=-81.8830 ;17.0000
P12=-81.9220 ;16.9433
P13=-81.9610 ;16.8867
P14=-82.0000 ;16.8300
P15=-82.1000 ;16.8120
P16=-82.2000 ;16.7940
P17=-82.3000 ;16.7760
P18=-82.4000 ;16.7580
P19=-82.5000 ;16.7400
P20=-82.6000 ;16.7162
P21=-82.7000 ;16.6924

P22=-82.8000 ;16.6686
P23=-82.9000 ;16.6448
P24=-83.0000 ;16.6210
P25=-83.0896 ;16.5968
P26=-83.1792 ;16.5726
P27=-83.2688 ;16.5484
P28=-83.3584 ;16.5242
P29=-83.4480 ;16.5000
P30=-83.3584 ;16.4584
P31=-83.2688 ;16.4168
P32=-83.1792 ;16.3752
P33=-83.0896 ;16.3336
P34=-83.0000 ;16.2920
P35=-82.9000 ;16.2872
P36=-82.8000 ;16.2824
P37=-82.7000 ;16.2776
P38=-82.6000 ;16.2728
P39=-82.5000 ;16.2680
P40=-82.4000 ;16.2796
P41=-82.3000 ;16.2912
P42=-82.2000 ;16.3028
P43=-82.1000 ;16.3144
P44=-82.0000 ;16.3260
P45=-81.9297 ;16.3695
P46=-81.8595 ;16.4130
P47=-81.7892 ;16.4565
P48=-81.7190 ;16.5000
P49=-81.6460 ;16.5527
P50=-81.5730 ;16.6053
P51=-81.5000 ;16.6580
P52=-81.4167 ;16.6803
P53=-81.3333 ;16.7027
P54=-81.2500 ;16.7250
P55=-81.1667 ;16.7473
P56=-81.0833 ;16.7697
P57=-81.0000 ;16.7920
P58=-80.9187 ;16.8267
P59=-80.8373 ;16.8613
P60=-80.7560 ;16.8960
P61=-80.6747 ;16.9307
P62=-80.5933 ;16.9653
P63=-80.5120 ;17.0000
P64=-80.5933 ;17.0392
P65=-80.6747 ;17.0783
P66=-80.7560 ;17.1175
P67=-80.8373 ;17.1567
P68=-80.9187 ;17.1958
P69=-81.0000 ;17.2350
[C19]
gain=-50.00
n_point=67
P1=-84.0000 ;16.2060
P2=-84.0714 ;16.2117
P3=-84.1429 ;16.2174
P4=-84.2143 ;16.2231
P5=-84.2857 ;16.2289
P6=-84.3571 ;16.2346

P7=-84.4286 ;16.2403
P8=-84.5000 ;16.2460
P9=-84.5714 ;16.2367
P10=-84.6429 ;16.2274
P11=-84.7143 ;16.2181
P12=-84.7857 ;16.2089
P13=-84.8571 ;16.1996
P14=-84.9286 ;16.1903
P15=-85.0000 ;16.1810
P16=-85.0714 ;16.1646
P17=-85.1429 ;16.1481
P18=-85.2143 ;16.1317
P19=-85.2857 ;16.1153
P20=-85.3571 ;16.0989
P21=-85.4286 ;16.0824
P22=-85.5000 ;16.0660
P23=-85.5664 ;16.0528
P24=-85.6328 ;16.0396
P25=-85.6992 ;16.0264
P26=-85.7656 ;16.0132
P27=-85.8320 ;16.0000
P28=-85.7656 ;15.9686
P29=-85.6992 ;15.9372
P30=-85.6328 ;15.9058
P31=-85.5664 ;15.8744
P32=-85.5000 ;15.8430
P33=-85.4286 ;15.8294
P34=-85.3571 ;15.8159
P35=-85.2857 ;15.8023
P36=-85.2143 ;15.7887
P37=-85.1429 ;15.7751
P38=-85.0714 ;15.7616
P39=-85.0000 ;15.7480
P40=-84.9286 ;15.7469
P41=-84.8571 ;15.7457
P42=-84.7857 ;15.7446
P43=-84.7143 ;15.7434
P44=-84.6429 ;15.7423
P45=-84.5714 ;15.7411
P46=-84.5000 ;15.7400
P47=-84.4286 ;15.7557
P48=-84.3571 ;15.7714
P49=-84.2857 ;15.7871
P50=-84.2143 ;15.8029
P51=-84.1429 ;15.8186
P52=-84.0714 ;15.8343
P53=-84.0000 ;15.8500
P54=-83.9350 ;15.8714
P55=-83.8700 ;15.8929
P56=-83.8050 ;15.9143
P57=-83.7400 ;15.9357
P58=-83.6750 ;15.9571
P59=-83.6100 ;15.9786
P60=-83.5450 ;16.0000
P61=-83.6100 ;16.0294
P62=-83.6750 ;16.0589
P63=-83.7400 ;16.0883

P64=-83.8050 ;16.1177
P65=-83.8700 ;16.1471
P66=-83.9350 ;16.1766
P67=-84.0000 ;16.2060
[C20]
gain=-50.00
n_point=80
P1=-91.0000 ;32.1180
P2=-91.1540 ;32.3090
P3=-91.3080 ;32.5000
P4=-91.3585 ;32.7500
P5=-91.4090 ;33.0000
P6=-91.5000 ;33.2350
P7=-91.5965 ;33.3675
P8=-91.6930 ;33.5000
P9=-91.7470 ;33.7500
P10=-91.8010 ;34.0000
P11=-91.8045 ;34.2500
P12=-91.8080 ;34.5000
P13=-91.7955 ;34.7500
P14=-91.7830 ;35.0000
P15=-91.7745 ;35.2500
P16=-91.7660 ;35.5000
P17=-91.7670 ;35.7500
P18=-91.7680 ;36.0000
P19=-91.7525 ;36.2500
P20=-91.7370 ;36.5000
P21=-91.7025 ;36.7500
P22=-91.6680 ;37.0000
P23=-91.6165 ;37.2500
P24=-91.5650 ;37.5000
P25=-91.5000 ;37.6970
P26=-91.4650 ;37.8485
P27=-91.4300 ;38.0000
P28=-91.3735 ;38.2500
P29=-91.3170 ;38.5000
P30=-91.2700 ;38.7500
P31=-91.2230 ;39.0000
P32=-91.2075 ;39.2500
P33=-91.1920 ;39.5000
P34=-91.1710 ;39.7500
P35=-91.1500 ;40.0000
P36=-91.3250 ;40.0935
P37=-91.5000 ;40.1870
P38=-91.6120 ;40.0000
P39=-91.7140 ;39.7500
P40=-91.8160 ;39.5000
P41=-91.8935 ;39.2500
P42=-91.9710 ;39.0000
P43=-92.0000 ;38.9330
P44=-92.0935 ;38.7165
P45=-92.1870 ;38.5000
P46=-92.2385 ;38.2500
P47=-92.2900 ;38.0000
P48=-92.3060 ;37.7500
P49=-92.3220 ;37.5000
P50=-92.3415 ;37.2500

P51=-92.3610 ;37.0000
P52=-92.4015 ;36.7500
P53=-92.4420 ;36.5000
P54=-92.4650 ;36.2500
P55=-92.4880 ;36.0000
P56=-92.4760 ;35.7500
P57=-92.4640 ;35.5000
P58=-92.4390 ;35.2500
P59=-92.4140 ;35.0000
P60=-92.3795 ;34.7500
P61=-92.3450 ;34.5000
P62=-92.3100 ;34.2500
P63=-92.2750 ;34.0000
P64=-92.2560 ;33.7500
P65=-92.2370 ;33.5000
P66=-92.1650 ;33.2500
P67=-92.0930 ;33.0000
P68=-92.0000 ;32.8510
P69=-91.8745 ;32.6755
P70=-91.7490 ;32.5000
P71=-91.6375 ;32.2500
P72=-91.5260 ;32.0000
P73=-91.5000 ;31.9700
P74=-91.2935 ;31.7350
P75=-91.0870 ;31.5000
P76=-91.0000 ;31.4030
P77=-90.8870 ;31.5000
P78=-90.9095 ;31.7500
P79=-90.9320 ;32.0000
P80=-91.0000 ;32.1180
[C21]
gain=-50.00
n_point=91
P1=-92.5000 ;28.5450
P2=-92.8110 ;29.0000
P3=-93.0000 ;29.3350
P4=-93.1950 ;29.5000
P5=-93.3620 ;30.0000
P6=-93.5000 ;30.4480
P7=-93.5290 ;30.5000
P8=-93.6910 ;31.0000
P9=-93.7480 ;31.5000
P10=-93.8010 ;32.0000
P11=-93.9080 ;32.5000
P12=-94.0000 ;32.8150
P13=-94.0310 ;33.0000
P14=-94.0780 ;33.5000
P15=-94.1280 ;34.0000
P16=-94.2010 ;34.5000
P17=-94.2560 ;35.0000
P18=-94.2720 ;35.5000
P19=-94.2440 ;36.0000
P20=-94.2110 ;36.5000
P21=-94.1800 ;37.0000
P22=-94.1230 ;37.5000
P23=-94.0260 ;38.0000
P24=-94.0000 ;38.0830

P25=-93.8840 ;38.5000
P26=-93.7720 ;39.0000
P27=-93.6810 ;39.5000
P28=-93.6000 ;40.0000
P29=-93.5000 ;40.4800
P30=-93.4940 ;40.5000
P31=-93.3390 ;41.0000
P32=-93.2380 ;41.5000
P33=-93.1710 ;42.0000
P34=-93.0000 ;42.4860
P35=-92.9940 ;42.5000
P36=-92.8700 ;43.0000
P37=-92.7880 ;43.5000
P38=-93.0000 ;43.8260
P39=-93.1500 ;43.5000
P40=-93.4320 ;43.0000
P41=-93.5000 ;42.9610
P42=-93.7330 ;42.5000
P43=-93.8610 ;42.0000
P44=-94.0000 ;41.5860
P45=-94.0400 ;41.5000
P46=-94.2380 ;41.0000
P47=-94.3730 ;40.5000
P48=-94.4660 ;40.0000
P49=-94.5000 ;39.8630
P50=-94.6270 ;39.5000
P51=-94.7570 ;39.0000
P52=-94.8650 ;38.5000
P53=-95.0000 ;38.0400
P54=-95.0190 ;38.0000
P55=-95.2400 ;37.5000
P56=-95.3860 ;37.0000
P57=-95.5000 ;36.5170
P58=-95.5130 ;36.5000
P59=-95.6565 ;36.2500
P60=-95.8000 ;36.0000
P61=-95.9270 ;35.5000
P62=-95.9750 ;35.0000
P63=-95.9940 ;34.5000
P64=-95.9490 ;34.0000
P65=-95.7960 ;33.5000
P66=-95.5000 ;33.0740
P67=-95.4850 ;33.0000
P68=-95.3360 ;32.5000
P69=-95.2010 ;32.2500
P70=-95.0660 ;32.0000
P71=-95.0000 ;31.8980
P72=-94.8340 ;31.5000
P73=-94.6060 ;31.0000
P74=-94.5000 ;30.8100
P75=-94.3520 ;30.5000
P76=-94.2270 ;30.2500
P77=-94.1020 ;30.0000
P78=-94.0000 ;29.8570
P79=-93.7430 ;29.5000
P80=-93.6215 ;29.2505
P81=-93.5000 ;29.0010

P82=-93.4990 ;29.0000
P83=-93.2960 ;28.7500
P84=-93.0930 ;28.5000
P85=-93.0000 ;28.4120
P86=-92.6410 ;28.0000
P87=-92.5000 ;27.8750
P88=-92.1840 ;28.0000
P89=-92.3265 ;28.2500
P90=-92.4690 ;28.5000
P91=-92.5000 ;28.5450
[C22]
gain=-40.00
n_point=69
P1=-71.5000 ;51.6860
P2=-71.5833 ;51.7038
P3=-71.6667 ;51.7217
P4=-71.7500 ;51.7395
P5=-71.8333 ;51.7573
P6=-71.9167 ;51.7752
P7=-72.0000 ;51.7930
P8=-72.1000 ;51.7996
P9=-72.2000 ;51.8062
P10=-72.3000 ;51.8128
P11=-72.4000 ;51.8194
P12=-72.5000 ;51.8260
P13=-72.6000 ;51.8192
P14=-72.7000 ;51.8124
P15=-72.8000 ;51.8056
P16=-72.9000 ;51.7988
P17=-73.0000 ;51.7920
P18=-73.0833 ;51.7723
P19=-73.1667 ;51.7527
P20=-73.2500 ;51.7330
P21=-73.3333 ;51.7133
P22=-73.4167 ;51.6937
P23=-73.5000 ;51.6740
P24=-73.5737 ;51.6450
P25=-73.6473 ;51.6160
P26=-73.7210 ;51.5870
P27=-73.7947 ;51.5580
P28=-73.8683 ;51.5290
P29=-73.9420 ;51.5000
P30=-73.8789 ;51.4574
P31=-73.8157 ;51.4149
P32=-73.7526 ;51.3723
P33=-73.6894 ;51.3297
P34=-73.6263 ;51.2871
P35=-73.5631 ;51.2446
P36=-73.5000 ;51.2020
P37=-73.4000 ;51.1946
P38=-73.3000 ;51.1872
P39=-73.2000 ;51.1798
P40=-73.1000 ;51.1724
P41=-73.0000 ;51.1650
P42=-72.9000 ;51.1748
P43=-72.8000 ;51.1846
P44=-72.7000 ;51.1944

P45=-72.6000 ;51.2042
P46=-72.5000 ;51.2140
P47=-72.4167 ;51.2277
P48=-72.3333 ;51.2413
P49=-72.2500 ;51.2550
P50=-72.1667 ;51.2687
P51=-72.0833 ;51.2823
P52=-72.0000 ;51.2960
P53=-71.9167 ;51.3125
P54=-71.8333 ;51.3290
P55=-71.7500 ;51.3455
P56=-71.6667 ;51.3620
P57=-71.5833 ;51.3785
P58=-71.5000 ;51.3950
P59=-71.4144 ;51.4160
P60=-71.3288 ;51.4370
P61=-71.2432 ;51.4580
P62=-71.1576 ;51.4790
P63=-71.0720 ;51.5000
P64=-71.1433 ;51.5310
P65=-71.2147 ;51.5620
P66=-71.2860 ;51.5930
P67=-71.3573 ;51.6240
P68=-71.4287 ;51.6550
P69=-71.5000 ;51.6860
[C23]
gain=-50.00
n_point=109
P1=-56.0000 ;28.5550
P2=-56.5000 ;28.5940
P3=-56.6630 ;28.5000
P4=-57.0000 ;28.2410
P5=-57.2500 ;28.1450
P6=-57.5000 ;28.0490
P7=-57.5750 ;28.0000
P8=-57.7875 ;27.8710
P9=-58.0000 ;27.7420
P10=-58.4000 ;27.5000
P11=-58.5000 ;27.4510
P12=-58.7500 ;27.3065
P13=-59.0000 ;27.1620
P14=-59.2090 ;27.0000
P15=-59.5000 ;26.8230
P16=-59.7065 ;26.6615
P17=-59.9130 ;26.5000
P18=-60.0000 ;26.4440
P19=-60.2475 ;26.2220
P20=-60.4950 ;26.0000
P21=-60.5000 ;25.9970
P22=-60.7500 ;25.8140
P23=-61.0000 ;25.6310
P24=-61.1410 ;25.5000
P25=-61.3205 ;25.3240
P26=-61.5000 ;25.1480
P27=-61.6420 ;25.0000
P28=-62.0000 ;24.7150
P29=-62.2160 ;24.5000

P30=-62.5000 ;24.2070
P31=-62.7000 ;24.0000
P32=-63.0000 ;23.7400
P33=-63.2310 ;23.5000
P34=-63.5000 ;23.2740
P35=-63.7890 ;23.0000
P36=-64.0000 ;22.8060
P37=-64.3200 ;22.5000
P38=-64.5000 ;22.3340
P39=-64.6780 ;22.1670
P40=-64.8560 ;22.0000
P41=-65.0000 ;21.8500
P42=-65.1930 ;21.6750
P43=-65.3860 ;21.5000
P44=-65.5000 ;21.3670
P45=-65.7325 ;21.1835
P46=-65.9650 ;21.0000
P47=-66.0000 ;20.9550
P48=-66.2500 ;20.7610
P49=-66.5000 ;20.5670
P50=-66.5780 ;20.5000
P51=-66.7890 ;20.3080
P52=-67.0000 ;20.1160
P53=-67.1520 ;20.0000
P54=-67.0000 ;19.6770
P55=-66.7500 ;19.7820
P56=-66.5000 ;19.8870
P57=-66.3420 ;20.0000
P58=-66.0000 ;20.2310
P59=-65.8040 ;20.3655
P60=-65.6080 ;20.5000
P61=-65.5000 ;20.5860
P62=-65.2500 ;20.7250
P63=-65.0000 ;20.8640
P64=-64.8180 ;21.0000
P65=-64.5000 ;21.1840
P66=-64.2950 ;21.3420
P67=-64.0900 ;21.5000
P68=-64.0000 ;21.5580
P69=-63.7500 ;21.7410
P70=-63.5000 ;21.9240
P71=-63.4040 ;22.0000
P72=-63.2020 ;22.1460
P73=-63.0000 ;22.2920
P74=-62.7550 ;22.5000
P75=-62.5000 ;22.6540
P76=-62.3055 ;22.8270
P77=-62.1110 ;23.0000
P78=-62.0000 ;23.0910
P79=-61.7755 ;23.2955
P80=-61.5510 ;23.5000
P81=-61.5000 ;23.5450
P82=-61.2725 ;23.7725
P83=-61.0450 ;24.0000
P84=-61.0000 ;24.0330
P85=-60.7500 ;24.2665
P86=-60.5000 ;24.5000

P87=-60.2500 ;24.7480
P88=-60.0000 ;24.9960
P89=-59.9960 ;25.0000
P90=-59.7480 ;25.2045
P91=-59.5000 ;25.4090
P92=-59.4040 ;25.5000
P93=-59.2020 ;25.6925
P94=-59.0000 ;25.8850
P95=-58.8800 ;26.0000
P96=-58.6900 ;26.1580
P97=-58.5000 ;26.3160
P98=-58.2870 ;26.5000
P99=-58.0000 ;26.7790
P100=-57.7480 ;27.0000
P101=-57.5000 ;27.2520
P102=-57.1840 ;27.5000
P103=-57.0000 ;27.7320
P104=-56.6310 ;28.0000
P105=-56.5000 ;28.2030
P106=-56.2500 ;28.3425
P107=-56.0000 ;28.4820
P108=-55.9740 ;28.5000
P109=-56.0000 ;28.5550
[C24]
gain=-50.00
n_point=100
P1=-57.0000 ;31.8100
P2=-57.2500 ;31.6840
P3=-57.5000 ;31.5580
P4=-57.5820 ;31.5000
P5=-57.7910 ;31.3825
P6=-58.0000 ;31.2650
P7=-58.1790 ;31.1325
P8=-58.3580 ;31.0000
P9=-58.5000 ;30.9020
P10=-58.7500 ;30.7425
P11=-59.0000 ;30.5830
P12=-59.1010 ;30.5000
P13=-59.3005 ;30.3675
P14=-59.5000 ;30.2350
P15=-59.7810 ;30.0000
P16=-60.0000 ;29.8390
P17=-60.1825 ;29.6695
P18=-60.3650 ;29.5000
P19=-60.5000 ;29.4090
P20=-60.7225 ;29.2045
P21=-60.9450 ;29.0000
P22=-61.0000 ;28.9450
P23=-61.2265 ;28.7225
P24=-61.4530 ;28.5000
P25=-61.5000 ;28.4680
P26=-61.7410 ;28.2340
P27=-61.9820 ;28.0000
P28=-62.0000 ;27.9760
P29=-62.2410 ;27.7380
P30=-62.4820 ;27.5000
P31=-62.5000 ;27.4870

P32=-62.7450 ;27.2435
P33=-62.9900 ;27.0000
P34=-63.0000 ;26.9870
P35=-63.2445 ;26.7435
P36=-63.4890 ;26.5000
P37=-63.5000 ;26.4860
P38=-63.7500 ;26.2690
P39=-64.0000 ;26.0520
P40=-64.0540 ;26.0000
P41=-64.2770 ;25.7860
P42=-64.5000 ;25.5720
P43=-64.5740 ;25.5000
P44=-64.7870 ;25.2980
P45=-65.0000 ;25.0960
P46=-65.1030 ;25.0000
P47=-65.3015 ;24.8185
P48=-65.5000 ;24.6370
P49=-65.6610 ;24.5000
P50=-65.5805 ;24.3015
P51=-65.5000 ;24.1030
P52=-65.2500 ;24.2370
P53=-65.0000 ;24.3710
P54=-64.8230 ;24.5000
P55=-64.6615 ;24.6115
P56=-64.5000 ;24.7230
P57=-64.2990 ;24.8615
P58=-64.0980 ;25.0000
P59=-64.0000 ;25.0570
P60=-63.7500 ;25.2325
P61=-63.5000 ;25.4080
P62=-63.3840 ;25.5000
P63=-63.1920 ;25.6205
P64=-63.0000 ;25.7410
P65=-62.8420 ;25.8705
P66=-62.6840 ;26.0000
P67=-62.5000 ;26.1210
P68=-62.2825 ;26.3105
P69=-62.0650 ;26.5000
P70=-62.0000 ;26.5570
P71=-61.7580 ;26.7785
P72=-61.5160 ;27.0000
P73=-61.5000 ;27.0110
P74=-61.2500 ;27.2400
P75=-61.0000 ;27.4690
P76=-60.9680 ;27.5000
P77=-60.7340 ;27.7025
P78=-60.5000 ;27.9050
P79=-60.4040 ;28.0000
P80=-60.2020 ;28.1915
P81=-60.0000 ;28.3830
P82=-59.8810 ;28.5000
P83=-59.6905 ;28.6655
P84=-59.5000 ;28.8310
P85=-59.3240 ;29.0000
P86=-59.1620 ;29.1710
P87=-59.0000 ;29.3420
P88=-58.8430 ;29.5000

P89=-58.6715 ;29.6505
P90=-58.5000 ;29.8010
P91=-58.2810 ;30.0000
P92=-58.1405 ;30.1465
P93=-58.0000 ;30.2930
P94=-57.7680 ;30.5000
P95=-57.5000 ;30.7700
P96=-57.2460 ;31.0000
P97=-57.0000 ;31.2920
P98=-56.7380 ;31.5000
P99=-56.8690 ;31.6550
P100=-57.0000 ;31.8100

[C25]

gain=-15.00

n_point=109

P1=-78.3996 ;44.7493
P2=-78.6792 ;44.6654
P3=-78.8348 ;44.6110
P4=-79.2164 ;44.4503
P5=-79.5981 ;44.2896
P6=-79.8618 ;44.1687
P7=-80.1438 ;44.0165
P8=-80.4258 ;43.8643
P9=-80.4658 ;43.8410
P10=-80.8548 ;43.6003
P11=-81.2438 ;43.3596
P12=-81.2855 ;43.3302
P13=-81.5920 ;43.0989
P14=-81.8984 ;42.8676
P15=-81.9721 ;42.8104
P16=-82.0685 ;42.7316
P17=-82.3629 ;42.4743
P18=-82.6573 ;42.2169
P19=-82.8342 ;42.0400
P20=-83.0110 ;41.8630
P21=-83.2762 ;41.5675
P22=-83.5326 ;41.2384
P23=-83.7889 ;40.9092
P24=-83.8255 ;40.8581
P25=-83.8771 ;40.7861
P26=-84.0903 ;40.4321
P27=-84.3035 ;40.0780
P28=-84.4430 ;39.7922
P29=-84.5251 ;39.5750
P30=-84.6073 ;39.3578
P31=-84.6578 ;39.1826
P32=-84.7121 ;38.9566
P33=-84.7664 ;38.7306
P34=-84.7972 ;38.4940
P35=-84.8280 ;38.2574
P36=-84.8175 ;38.0972
P37=-84.7892 ;37.8740
P38=-84.7609 ;37.6507
P39=-84.6851 ;37.4036
P40=-84.5753 ;37.1873
P41=-84.4654 ;36.9710
P42=-84.2456 ;36.7569

P43=-83.9811 ;36.5283
P44=-83.7347 ;36.4317
P45=-83.4882 ;36.3350
P46=-83.3007 ;36.2913
P47=-83.0442 ;36.2499
P48=-82.6612 ;36.2387
P49=-82.2783 ;36.2276
P50=-82.0373 ;36.2559
P51=-81.8834 ;36.2755
P52=-81.6411 ;36.3238
P53=-81.3988 ;36.3720
P54=-81.1650 ;36.4466
P55=-80.9312 ;36.5211
P56=-80.7021 ;36.6039
P57=-80.3853 ;36.7340
P58=-80.0686 ;36.8641
P59=-79.7639 ;37.0249
P60=-79.4592 ;37.1857
P61=-79.2884 ;37.2738
P62=-79.2421 ;37.2978
P63=-78.8805 ;37.5279
P64=-78.5188 ;37.7580
P65=-78.2424 ;37.9490
P66=-77.9660 ;38.1401
P67=-77.7948 ;38.2586
P68=-77.4518 ;38.5451
P69=-77.1088 ;38.8317
P70=-76.8916 ;39.0335
P71=-76.6744 ;39.2354
P72=-76.4632 ;39.4486
P73=-76.2622 ;39.6671
P74=-76.0613 ;39.8857
P75=-75.8574 ;40.1207
P76=-75.7751 ;40.2267
P77=-75.5898 ;40.4612
P78=-75.4483 ;40.6619
P79=-75.3068 ;40.8627
P80=-75.1891 ;41.0465
P81=-75.0714 ;41.2304
P82=-74.9438 ;41.4600
P83=-74.8163 ;41.6896
P84=-74.7580 ;41.8020
P85=-74.6641 ;42.0269
P86=-74.5703 ;42.2518
P87=-74.5053 ;42.4590
P88=-74.4404 ;42.6661
P89=-74.3955 ;42.8602
P90=-74.3684 ;43.0796
P91=-74.3412 ;43.2990
P92=-74.3545 ;43.5138
P93=-74.3678 ;43.7286
P94=-74.4431 ;43.9618
P95=-74.5185 ;44.1951
P96=-74.6295 ;44.4004
P97=-74.6786 ;44.4620
P98=-74.9536 ;44.7009
P99=-75.3400 ;44.9191

P100=-75.6150 ;44.9853
P101=-75.8900 ;45.0514
P102=-76.2184 ;45.0713
P103=-76.5469 ;45.0911
P104=-76.6409 ;45.0854
P105=-76.9758 ;45.0521
P106=-77.3107 ;45.0188
P107=-77.6769 ;44.9482
P108=-78.0382 ;44.8488
P109=-78.3996 ;44.7493
[C26]
gain=-8.00
n_point=100
P1=-79.0262 ;43.7265
P2=-79.0858 ;43.7054
P3=-79.1941 ;43.6642
P4=-79.4496 ;43.5516
P5=-79.7052 ;43.4390
P6=-79.9608 ;43.3264
P7=-80.1941 ;43.1918
P8=-80.4275 ;43.0572
P9=-80.6608 ;42.9226
P10=-80.7675 ;42.8571
P11=-80.8714 ;42.7932
P12=-81.0851 ;42.6360
P13=-81.2987 ;42.4788
P14=-81.5124 ;42.3216
P15=-81.7111 ;42.1600
P16=-81.9075 ;41.9815
P17=-82.1038 ;41.8031
P18=-82.1849 ;41.7255
P19=-82.3170 ;41.5906
P20=-82.4729 ;41.4124
P21=-82.6288 ;41.2343
P22=-82.7847 ;41.0562
P23=-82.8836 ;40.9192
P24=-82.9824 ;40.7821
P25=-83.1359 ;40.5403
P26=-83.2893 ;40.2984
P27=-83.3454 ;40.1963
P28=-83.4512 ;39.9678
P29=-83.5570 ;39.7393
P30=-83.6144 ;39.5822
P31=-83.6719 ;39.4250
P32=-83.7193 ;39.2021
P33=-83.7668 ;38.9791
P34=-83.7960 ;38.6749
P35=-83.7857 ;38.4725
P36=-83.7754 ;38.2702
P37=-83.7176 ;38.0689
P38=-83.5874 ;37.8226
P39=-83.4573 ;37.5764
P40=-83.2948 ;37.4141
P41=-83.1346 ;37.2902
P42=-82.8990 ;37.1965
P43=-82.6633 ;37.1028
P44=-82.4237 ;37.0663

P45=-82.1603 ;37.0579
P46=-81.8968 ;37.0494
P47=-81.6832 ;37.0743
P48=-81.4695 ;37.0991
P49=-81.2079 ;37.1665
P50=-80.9462 ;37.2340
P51=-80.6846 ;37.3014
P52=-80.5584 ;37.3464
P53=-80.4652 ;37.3848
P54=-80.2068 ;37.5043
P55=-79.9484 ;37.6238
P56=-79.6900 ;37.7433
P57=-79.4026 ;37.9167
P58=-79.1151 ;38.0901
P59=-78.9246 ;38.2095
P60=-78.7522 ;38.3326
P61=-78.4849 ;38.5371
P62=-78.2176 ;38.7416
P63=-77.9633 ;38.9692
P64=-77.7090 ;39.1968
P65=-77.5919 ;39.3131
P66=-77.5606 ;39.3440
P67=-77.5063 ;39.3979
P68=-77.3243 ;39.6023
P69=-77.1424 ;39.8068
P70=-76.9605 ;40.0112
P71=-76.8498 ;40.1612
P72=-76.7392 ;40.3111
P73=-76.5845 ;40.5409
P74=-76.4297 ;40.7707
P75=-76.3563 ;40.8908
P76=-76.2398 ;41.1091
P77=-76.1232 ;41.3275
P78=-76.0536 ;41.4844
P79=-75.9839 ;41.6412
P80=-75.9199 ;41.8464
P81=-75.8559 ;42.0516
P82=-75.8233 ;42.2098
P83=-75.7907 ;42.3681
P84=-75.7784 ;42.5777
P85=-75.7662 ;42.7872
P86=-75.7917 ;42.9548
P87=-75.8729 ;43.2050
P88=-75.9542 ;43.4553
P89=-76.1172 ;43.6414
P90=-76.2983 ;43.7721
P91=-76.5668 ;43.8879
P92=-76.8354 ;44.0038
P93=-76.9874 ;44.0291
P94=-77.2961 ;44.0375
P95=-77.6048 ;44.0458
P96=-77.8352 ;44.0160
P97=-78.0656 ;43.9861
P98=-78.3858 ;43.8996
P99=-78.7060 ;43.8131
P100=-79.0262 ;43.7265