

```
[FormatInfo]
format_ver=1
[GeoMain]
ntc_id=910100000
adm=USA
sat_name=USABSS-21
long_nom=-101.0000
n_diag=1
[COHeader]
beam_id=RB05
emi_rcp=E
polar_disc=C
reason=B
n_bore=1
n_cont=17
[B1]
gain=0.00
p=-87.5710;42.5470
[C1]
gain=-50.00
n_point=906
P1=-50.0050 ;75.8770
P2=-50.5000 ;75.7630
P3=-51.0000 ;75.6630
P4=-51.5000 ;75.5770
P5=-52.0000 ;75.5050
P6=-52.0320 ;75.5000
P7=-52.5000 ;75.3970
P8=-53.0000 ;75.2740
P9=-53.5000 ;75.1690
P10=-54.0000 ;75.0810
P11=-54.5000 ;75.0070
P12=-54.5370 ;75.0000
P13=-55.0000 ;74.8780
P14=-55.5000 ;74.7570
P15=-56.0000 ;74.6550
P16=-56.5000 ;74.5700
P17=-56.8720 ;74.5000
P18=-57.0000 ;74.4650
P19=-57.5000 ;74.3330
P20=-58.0000 ;74.2220
P21=-58.5000 ;74.1250
P22=-59.0000 ;74.0220
P23=-59.1120 ;74.0000
P24=-59.5000 ;73.8970
P25=-60.0000 ;73.7820
P26=-60.5000 ;73.6670
P27=-61.0000 ;73.5620
P28=-61.3200 ;73.5000
P29=-61.5000 ;73.4550
P30=-62.0000 ;73.3250
P31=-62.5000 ;73.2090
P32=-63.0000 ;73.1050
P33=-63.5000 ;73.0020
P34=-63.5070 ;73.0000
P35=-64.0000 ;72.8750
P36=-64.5000 ;72.7790
```

P37=-65.0000 ;72.7310
P38=-65.5000 ;72.6380
P39=-66.0000 ;72.5280
P40=-66.2590 ;72.5000
P41=-66.5000 ;72.4900
P42=-67.0000 ;72.4900
P43=-67.5000 ;72.4410
P44=-68.0000 ;72.4130
P45=-68.5000 ;72.3200
P46=-69.0000 ;72.1560
P47=-69.2690 ;72.0000
P48=-69.5000 ;71.9400
P49=-70.0000 ;71.7490
P50=-70.4240 ;71.5000
P51=-70.5000 ;71.4730
P52=-71.0000 ;71.3000
P53=-71.5000 ;71.1120
P54=-71.7720 ;71.0000
P55=-72.0000 ;70.9130
P56=-72.5000 ;70.6860
P57=-73.0000 ;70.5400
P58=-73.1150 ;70.5000
P59=-73.5000 ;70.2930
P60=-74.0000 ;70.1200
P61=-74.3730 ;70.0000
P62=-74.5000 ;69.9400
P63=-75.0000 ;69.7690
P64=-75.5000 ;69.7390
P65=-76.0000 ;69.7400
P66=-76.5000 ;69.6750
P67=-76.8500 ;69.5000
P68=-77.0000 ;69.4580
P69=-77.5000 ;69.2670
P70=-77.8530 ;69.0000
P71=-78.0000 ;68.9260
P72=-78.5000 ;68.6420
P73=-78.8320 ;68.5000
P74=-79.0000 ;68.4090
P75=-79.5000 ;68.1510
P76=-79.8970 ;68.0000
P77=-80.0000 ;67.9460
P78=-80.5000 ;67.8210
P79=-81.0000 ;67.7990
P80=-81.5000 ;67.5440
P81=-81.5320 ;67.5000
P82=-82.0000 ;67.2010
P83=-82.3210 ;67.0000
P84=-82.5000 ;66.8890
P85=-83.0000 ;66.6380
P86=-83.3690 ;66.5000
P87=-83.5000 ;66.4400
P88=-84.0000 ;66.2810
P89=-84.3820 ;66.0000
P90=-84.5000 ;65.9200
P91=-85.0000 ;65.5910
P92=-85.1510 ;65.5000
P93=-85.5000 ;65.2840

P94=-86.0000 ;65.0410
P95=-86.0490 ;65.0000
P96=-86.5000 ;64.6850
P97=-86.7130 ;64.5000
P98=-87.0000 ;64.2950
P99=-87.5000 ;64.0390
P100=-87.5500 ;64.0000
P101=-88.0000 ;63.6800
P102=-88.1900 ;63.5000
P103=-88.5000 ;63.2790
P104=-88.9030 ;63.0000
P105=-89.0000 ;62.9260
P106=-89.5000 ;62.5570
P107=-89.5410 ;62.5000
P108=-90.0000 ;62.0950
P109=-90.1650 ;62.0000
P110=-90.5000 ;61.7630
P111=-90.7660 ;61.5000
P112=-91.0000 ;61.2770
P113=-91.3890 ;61.0000
P114=-91.5000 ;60.9090
P115=-91.9350 ;60.5000
P116=-92.0000 ;60.4380
P117=-92.5000 ;60.0050
P118=-92.5050 ;60.0000
P119=-93.0000 ;59.5220
P120=-93.0140 ;59.5000
P121=-93.5000 ;59.0220
P122=-93.5300 ;59.0000
P123=-93.9760 ;58.5000
P124=-94.0000 ;58.4760
P125=-94.5000 ;58.0030
P126=-94.5020 ;58.0000
P127=-94.9300 ;57.5000
P128=-95.0000 ;57.4090
P129=-95.2450 ;57.0000
P130=-95.5000 ;56.6890
P131=-95.6540 ;56.5000
P132=-96.0000 ;56.0650
P133=-96.0380 ;56.0000
P134=-96.3100 ;55.5000
P135=-96.5000 ;55.2180
P136=-96.6040 ;55.0000
P137=-96.9570 ;54.5000
P138=-97.0000 ;54.4360
P139=-97.2410 ;54.0000
P140=-97.5000 ;53.5810
P141=-97.5390 ;53.5000
P142=-97.7750 ;53.0000
P143=-98.0000 ;52.6310
P144=-98.0580 ;52.5000
P145=-98.3290 ;52.0000
P146=-98.5000 ;51.7370
P147=-98.6210 ;51.5000
P148=-98.9620 ;51.0000
P149=-99.0000 ;50.9470
P150=-99.2460 ;50.5000

P151=-99.5000 ;50.1390
P152=-99.5730 ;50.0000
P153=-99.8600 ;49.5000
P154=-100.0000;49.2840
P155=-100.1290;49.0000
P156=-100.3910;48.5000
P157=-100.5000;48.3050
P158=-100.6020;48.0000
P159=-100.7690;47.5000
P160=-100.9520;47.0000
P161=-101.0000;46.8550
P162=-101.0570;46.5000
P163=-101.1180;46.0000
P164=-101.1860;45.5000
P165=-101.2430;45.0000
P166=-101.2800;44.5000
P167=-101.3020;44.0000
P168=-101.3120;43.5000
P169=-101.3150;43.0000
P170=-101.3180;42.5000
P171=-101.3270;42.0000
P172=-101.3540;41.5000
P173=-101.4030;41.0000
P174=-101.4740;40.5000
P175=-101.5000;40.3170
P176=-101.5200;40.0000
P177=-101.5410;39.5000
P178=-101.5490;39.0000
P179=-101.5440;38.5000
P180=-101.5310;38.0000
P181=-101.5000;37.5910
P182=-101.4860;37.5000
P183=-101.3610;37.0000
P184=-101.1960;36.5000
P185=-101.2260;36.0000
P186=-101.1380;35.5000
P187=-101.0000;35.1100
P188=-100.9620;35.0000
P189=-100.7640;34.5000
P190=-100.6200;34.0000
P191=-100.5000;33.7600
P192=-100.3490;33.5000
P193=-100.3490;33.0000
P194=-100.3030;32.5000
P195=-100.0000;32.3880
P196=-99.7840 ;32.0000
P197=-100.0000;31.5540
P198=-100.2650;32.0000
P199=-100.5000;32.4130
P200=-100.5590;32.5000
P201=-100.6700;33.0000
P202=-100.9170;33.5000
P203=-101.0000;33.5320
P204=-101.3420;34.0000
P205=-101.3900;34.5000
P206=-101.5000;34.6200
P207=-101.7450;35.0000

P208=-101.8330;35.5000
P209=-102.0000;35.9870
P210=-102.0080;36.0000
P211=-102.2800;36.5000
P212=-102.3830;37.0000
P213=-102.4890;37.5000
P214=-102.5000;37.5700
P215=-102.6680;38.0000
P216=-102.7780;38.5000
P217=-102.8460;39.0000
P218=-102.8910;39.5000
P219=-102.9160;40.0000
P220=-102.9240;40.5000
P221=-102.9270;41.0000
P222=-102.9360;41.5000
P223=-102.9510;42.0000
P224=-102.9610;42.5000
P225=-102.9610;43.0000
P226=-102.9550;43.5000
P227=-102.9560;44.0000
P228=-102.9590;44.5000
P229=-102.9610;45.0000
P230=-102.9540;45.5000
P231=-102.9320;46.0000
P232=-102.8970;46.5000
P233=-102.8600;47.0000
P234=-102.8310;47.5000
P235=-102.8140;48.0000
P236=-102.8030;48.5000
P237=-103.0000;48.9120
P238=-103.0990;48.5000
P239=-103.3800;48.0000
P240=-103.5000;47.8880
P241=-103.6380;47.5000
P242=-103.8360;47.0000
P243=-104.0000;46.5530
P244=-104.0090;46.5000
P245=-104.0520;46.0000
P246=-104.0790;45.5000
P247=-104.0960;45.0000
P248=-104.1040;44.5000
P249=-104.1000;44.0000
P250=-104.0860;43.5000
P251=-104.0700;43.0000
P252=-104.0620;42.5000
P253=-104.0640;42.0000
P254=-104.0710;41.5000
P255=-104.0690;41.0000
P256=-104.0620;40.5000
P257=-104.0570;40.0000
P258=-104.0540;39.5000
P259=-104.0450;39.0000
P260=-104.0300;38.5000
P261=-104.0150;38.0000
P262=-104.0000;37.5000
P263=-104.0000;37.4910
P264=-103.9620;37.0000

P265=-103.9190;36.5000
P266=-103.8630;36.0000
P267=-103.7880;35.5000
P268=-103.7000;35.0000
P269=-103.6010;34.5000
P270=-103.5780;34.0000
P271=-103.5000;33.6750
P272=-103.4340;33.5000
P273=-103.2310;33.0000
P274=-103.1880;32.5000
P275=-103.0100;32.0000
P276=-103.0000;31.9920
P277=-102.6970;31.5000
P278=-102.5530;31.0000
P279=-102.5000;30.9210
P280=-102.2860;30.5000
P281=-102.1940;30.0000
P282=-102.0000;29.8790
P283=-101.7440;29.5000
P284=-101.6470;29.0000
P285=-101.5000;28.9230
P286=-101.2800;28.5000
P287=-101.5000;28.1530
P288=-101.7280;28.5000
P289=-102.0000;28.8660
P290=-102.1060;29.0000
P291=-102.3700;29.5000
P292=-102.5000;29.7060
P293=-102.6840;30.0000
P294=-102.8610;30.5000
P295=-103.0000;30.5990
P296=-103.3110;31.0000
P297=-103.4670;31.5000
P298=-103.5000;31.5420
P299=-103.8040;32.0000
P300=-103.9330;32.5000
P301=-104.0000;32.5810
P302=-104.2800;33.0000
P303=-104.3840;33.5000
P304=-104.5000;33.9260
P305=-104.5430;34.0000
P306=-104.7790;34.5000
P307=-104.9270;35.0000
P308=-105.0000;35.3730
P309=-105.0660;35.5000
P310=-105.2730;36.0000
P311=-105.4200;36.5000
P312=-105.5000;36.8520
P313=-105.6130;37.0000
P314=-105.8820;37.5000
P315=-106.0000;37.8780
P316=-106.2560;37.5000
P317=-106.4150;37.0000
P318=-106.4790;36.5000
P319=-106.4750;36.0000
P320=-106.4280;35.5000
P321=-106.3620;35.0000

P322=-106.2880;34.5000
P323=-106.2000;34.0000
P324=-106.1090;33.5000
P325=-106.0280;33.0000
P326=-106.0000;32.8130
P327=-105.9000;32.5000
P328=-105.7380;32.0000
P329=-105.5980;31.5000
P330=-105.5050;31.0000
P331=-105.5000;30.9830
P332=-105.2620;30.5000
P333=-105.1060;30.0000
P334=-105.0000;29.6360
P335=-104.9220;29.5000
P336=-104.7420;29.0000
P337=-104.5290;28.5000
P338=-104.5000;28.4810
P339=-104.1370;28.0000
P340=-104.0000;27.6330
P341=-103.9050;27.5000
P342=-103.6880;27.0000
P343=-103.5000;26.8080
P344=-103.2500;26.5000
P345=-103.0030;26.0000
P346=-103.0000;25.9960
P347=-102.7420;25.5000
P348=-102.5000;25.3200
P349=-102.2250;25.0000
P350=-102.0000;24.6150
P351=-101.8990;24.5000
P352=-101.5000;24.0770
P353=-101.4270;24.0000
P354=-101.0000;23.5580
P355=-100.9380;23.5000
P356=-100.5000;23.1880
P357=-100.2950;23.0000
P358=-100.0000;22.6650
P359=-99.7390 ;22.5000
P360=-99.5000 ;22.3540
P361=-99.0000 ;22.0920
P362=-98.8740 ;22.0000
P363=-99.0000 ;21.5570
P364=-99.5000 ;21.7390
P365=-99.8190 ;22.0000
P366=-100.0000;22.2790
P367=-100.5000;22.4460
P368=-100.5620;22.5000
P369=-101.0000;22.9060
P370=-101.1030;23.0000
P371=-101.5000;23.3660
P372=-101.6370;23.5000
P373=-102.0000;23.8700
P374=-102.1220;24.0000
P375=-102.5000;24.4610
P376=-102.5360;24.5000
P377=-102.9440;25.0000
P378=-103.0000;25.0870

P379=-103.2630;25.5000
P380=-103.5000;25.6880
P381=-103.7760;26.0000
P382=-104.0000;26.3990
P383=-104.0840;26.5000
P384=-104.3460;27.0000
P385=-104.5000;27.2050
P386=-104.7360;27.5000
P387=-104.9920;28.0000
P388=-105.0000;28.0120
P389=-105.3540;28.5000
P390=-105.5000;28.8650
P391=-105.6000;29.0000
P392=-105.8590;29.5000
P393=-106.0000;29.9360
P394=-106.0430;30.0000
P395=-106.3460;30.5000
P396=-106.5000;30.9990
P397=-106.5010;31.0000
P398=-106.7990;31.5000
P399=-106.9750;32.0000
P400=-107.0000;32.1130
P401=-107.2340;32.5000
P402=-107.4360;33.0000
P403=-107.5000;33.2290
P404=-107.7120;33.5000
P405=-107.9290;34.0000
P406=-108.0000;34.2510
P407=-108.4410;34.5000
P408=-108.5000;34.6170
P409=-108.5170;34.5000
P410=-108.5700;34.0000
P411=-108.5860;33.5000
P412=-108.5680;33.0000
P413=-108.5330;32.5000
P414=-108.5000;32.0710
P415=-108.4870;32.0000
P416=-108.3290;31.5000
P417=-108.1860;31.0000
P418=-108.0690;30.5000
P419=-108.0000;30.0410
P420=-107.9840;30.0000
P421=-107.7380;29.5000
P422=-107.5980;29.0000
P423=-107.5000;28.6430
P424=-107.4310;28.5000
P425=-107.1830;28.0000
P426=-107.0120;27.5000
P427=-107.0000;27.4750
P428=-106.7100;27.0000
P429=-106.5380;26.5000
P430=-106.5000;26.4330
P431=-106.2110;26.0000
P432=-106.0490;25.5000
P433=-106.0000;25.4630
P434=-105.6400;25.0000
P435=-105.5000;24.7240

P436=-105.3270;24.5000
P437=-105.0970;24.0000
P438=-105.0000;23.8970
P439=-104.6640;23.5000
P440=-104.5000;23.3270
P441=-104.2170;23.0000
P442=-104.0000;22.6320
P443=-103.8810;22.5000
P444=-103.5400;22.0000
P445=-103.5000;21.9550
P446=-103.0950;21.5000
P447=-103.0000;21.4060
P448=-102.6240;21.0000
P449=-102.5000;20.8720
P450=-102.0120;20.5000
P451=-102.0000;20.4860
P452=-101.5000;20.1360
P453=-101.3290;20.0000
P454=-101.0000;19.8230
P455=-100.5710;19.5000
P456=-100.5000;19.3720
P457=-100.0000;19.2550
P458=-99.6000 ;19.0000
P459=-99.5000 ;18.9290
P460=-99.0000 ;18.7310
P461=-98.5000 ;18.5150
P462=-98.4750 ;18.5000
P463=-98.0000 ;18.3970
P464=-97.5000 ;18.1450
P465=-97.2250 ;18.0000
P466=-97.0000 ;17.8910
P467=-96.5000 ;17.7560
P468=-96.0000 ;17.7700
P469=-95.5000 ;17.6050
P470=-95.1330 ;17.5000
P471=-95.0000 ;17.4510
P472=-94.5000 ;17.4160
P473=-94.0000 ;17.3950
P474=-93.5000 ;17.3770
P475=-93.0000 ;17.3760
P476=-92.5000 ;17.3910
P477=-92.0000 ;17.4260
P478=-91.5910 ;17.5000
P479=-91.5000 ;17.5170
P480=-91.0000 ;17.6350
P481=-90.5000 ;17.7600
P482=-90.0000 ;17.8560
P483=-89.5000 ;17.8980
P484=-89.2160 ;18.0000
P485=-89.0000 ;18.1040
P486=-88.5000 ;18.3010
P487=-88.0000 ;18.4610
P488=-87.8850 ;18.5000
P489=-87.5000 ;18.7180
P490=-87.0000 ;18.8900
P491=-86.6790 ;19.0000
P492=-86.5000 ;19.1070

P493=-86.0000 ;19.3630
P494=-85.6330 ;19.5000
P495=-85.5000 ;19.5820
P496=-85.0000 ;19.8490
P497=-84.6500 ;20.0000
P498=-84.5000 ;20.1070
P499=-84.0000 ;20.4290
P500=-83.8730 ;20.5000
P501=-83.5000 ;20.7830
P502=-83.1280 ;21.0000
P503=-83.0000 ;21.1080
P504=-82.5000 ;21.4620
P505=-82.4390 ;21.5000
P506=-82.0000 ;21.8790
P507=-81.8260 ;22.0000
P508=-81.5000 ;22.3110
P509=-81.2470 ;22.5000
P510=-81.0000 ;22.7310
P511=-80.6290 ;23.0000
P512=-80.5000 ;23.1210
P513=-80.0340 ;23.5000
P514=-80.0000 ;23.5330
P515=-79.5000 ;23.9730
P516=-79.4680 ;24.0000
P517=-79.0000 ;24.4300
P518=-78.9150 ;24.5000
P519=-78.5000 ;24.8920
P520=-78.3740 ;25.0000
P521=-78.0000 ;25.4130
P522=-77.9210 ;25.5000
P523=-77.5000 ;25.9570
P524=-77.4600 ;26.0000
P525=-77.0000 ;26.4960
P526=-76.9960 ;26.5000
P527=-76.6260 ;27.0000
P528=-77.0000 ;27.2080
P529=-77.5000 ;27.0120
P530=-77.5200 ;27.0000
P531=-78.0000 ;26.6170
P532=-78.1660 ;26.5000
P533=-78.5000 ;26.2330
P534=-78.8330 ;26.0000
P535=-79.0000 ;25.8640
P536=-79.4940 ;25.5000
P537=-79.5000 ;25.4950
P538=-80.0000 ;25.0610
P539=-80.0700 ;25.0000
P540=-80.5000 ;24.6250
P541=-80.6560 ;24.5000
P542=-81.0000 ;24.2120
P543=-81.3210 ;24.0000
P544=-81.5000 ;23.8610
P545=-82.0000 ;23.5590
P546=-82.1060 ;23.5000
P547=-82.5000 ;23.2170
P548=-82.9390 ;23.0000
P549=-83.0000 ;22.9610

P550=-83.5000 ;22.6700
P551=-83.9110 ;22.5000
P552=-84.0000 ;22.4470
P553=-84.5000 ;22.1560
P554=-84.8630 ;22.0000
P555=-85.0000 ;21.9170
P556=-85.5000 ;21.6770
P557=-85.8620 ;21.5000
P558=-86.0000 ;21.4120
P559=-86.5000 ;21.1200
P560=-86.8240 ;21.0000
P561=-87.0000 ;20.8970
P562=-87.5000 ;20.6890
P563=-88.0000 ;20.5980
P564=-88.2350 ;20.5000
P565=-88.5000 ;20.3810
P566=-89.0000 ;20.2030
P567=-89.5000 ;20.1290
P568=-90.0000 ;20.1210
P569=-90.4440 ;20.0000
P570=-90.5000 ;19.9860
P571=-91.0000 ;19.8870
P572=-91.5000 ;19.8410
P573=-92.0000 ;19.8220
P574=-92.5000 ;19.8090
P575=-93.0000 ;19.7980
P576=-93.5000 ;19.7820
P577=-94.0000 ;19.7410
P578=-94.5000 ;19.7270
P579=-95.0000 ;19.9310
P580=-95.1670 ;20.0000
P581=-95.5000 ;20.1390
P582=-96.0000 ;20.1760
P583=-96.5000 ;20.3920
P584=-96.7440 ;20.5000
P585=-97.0000 ;20.7640
P586=-97.5000 ;20.7400
P587=-97.9410 ;21.0000
P588=-98.0000 ;21.1560
P589=-98.5000 ;21.3360
P590=-98.9620 ;21.5000
P591=-98.5000 ;21.6730
P592=-98.0000 ;21.5920
P593=-97.8460 ;21.5000
P594=-97.5000 ;21.3000
P595=-97.0000 ;21.1000
P596=-96.6880 ;21.0000
P597=-96.5000 ;20.8190
P598=-96.0000 ;20.8210
P599=-95.5000 ;20.7350
P600=-95.0000 ;20.5130
P601=-94.9590 ;20.5000
P602=-94.5000 ;20.3840
P603=-94.0000 ;20.3140
P604=-93.5000 ;20.2430
P605=-93.0000 ;20.2150
P606=-92.5000 ;20.2110

P607=-92.0000 ;20.2220
P608=-91.5000 ;20.2500
P609=-91.0000 ;20.3100
P610=-90.7630 ;20.5000
P611=-90.5000 ;20.5770
P612=-90.0000 ;20.7360
P613=-89.5000 ;20.8530
P614=-89.0000 ;20.9250
P615=-88.8820 ;21.0000
P616=-88.5000 ;21.1890
P617=-88.0000 ;21.3040
P618=-87.5000 ;21.4700
P619=-87.4700 ;21.5000
P620=-87.0000 ;21.7930
P621=-86.5000 ;21.9800
P622=-86.4690 ;22.0000
P623=-86.0000 ;22.2720
P624=-85.5000 ;22.4700
P625=-85.4730 ;22.5000
P626=-85.0000 ;22.8240
P627=-84.6520 ;23.0000
P628=-84.5000 ;23.1070
P629=-84.0000 ;23.3860
P630=-83.8500 ;23.5000
P631=-83.5000 ;23.7660
P632=-83.1080 ;24.0000
P633=-83.0000 ;24.0820
P634=-82.5000 ;24.4210
P635=-82.3970 ;24.5000
P636=-82.0000 ;24.8550
P637=-81.8180 ;25.0000
P638=-81.5000 ;25.3030
P639=-81.2680 ;25.5000
P640=-81.0000 ;25.7710
P641=-80.7510 ;26.0000
P642=-80.5000 ;26.2560
P643=-80.2400 ;26.5000
P644=-80.0000 ;26.7530
P645=-79.7410 ;27.0000
P646=-79.5000 ;27.2540
P647=-79.2330 ;27.5000
P648=-79.0000 ;27.7240
P649=-78.6720 ;28.0000
P650=-78.5000 ;28.1680
P651=-78.1420 ;28.5000
P652=-78.0000 ;28.6340
P653=-77.6060 ;29.0000
P654=-77.5000 ;29.0980
P655=-77.0360 ;29.5000
P656=-77.0000 ;29.5360
P657=-76.5320 ;30.0000
P658=-76.5000 ;30.0380
P659=-76.1110 ;30.5000
P660=-76.0000 ;30.6540
P661=-75.7430 ;31.0000
P662=-75.5000 ;31.3320
P663=-75.3780 ;31.5000

P664=-75.0000 ;31.9530
P665=-74.9590 ;32.0000
P666=-74.7630 ;32.5000
P667=-75.0000 ;32.5320
P668=-75.0630 ;32.5000
P669=-75.5000 ;32.1980
P670=-75.9090 ;32.0000
P671=-76.0000 ;31.9390
P672=-76.5000 ;31.5750
P673=-76.6030 ;31.5000
P674=-77.0000 ;31.1770
P675=-77.2300 ;31.0000
P676=-77.5000 ;30.7740
P677=-77.8180 ;30.5000
P678=-78.0000 ;30.3270
P679=-78.3210 ;30.0000
P680=-78.5000 ;29.8180
P681=-78.8010 ;29.5000
P682=-79.0000 ;29.2990
P683=-79.3050 ;29.0000
P684=-79.5000 ;28.8110
P685=-79.8420 ;28.5000
P686=-80.0000 ;28.3620
P687=-80.4910 ;28.0000
P688=-80.5000 ;27.9930
P689=-81.0000 ;27.6020
P690=-81.1550 ;27.5000
P691=-81.5000 ;27.2560
P692=-82.0000 ;27.0000
P693=-82.5000 ;26.7040
P694=-82.8220 ;26.5000
P695=-83.0000 ;26.3750
P696=-83.5000 ;26.0920
P697=-83.6090 ;26.0000
P698=-84.0000 ;25.7530
P699=-84.3430 ;25.5000
P700=-84.5000 ;25.3900
P701=-85.0000 ;25.1160
P702=-85.1000 ;25.0000
P703=-85.5000 ;24.7320
P704=-86.0000 ;24.5410
P705=-86.0330 ;24.5000
P706=-86.5000 ;24.2570
P707=-87.0000 ;24.0970
P708=-87.1410 ;24.0000
P709=-87.5000 ;23.8080
P710=-88.0000 ;23.7270
P711=-88.5000 ;23.8700
P712=-88.5720 ;24.0000
P713=-88.5000 ;24.0310
P714=-88.0000 ;24.2440
P715=-87.5000 ;24.3950
P716=-87.4300 ;24.5000
P717=-87.0000 ;24.7520
P718=-86.5000 ;24.8480
P719=-86.3220 ;25.0000
P720=-86.0000 ;25.1870

P721=-85.5000 ;25.4080
P722=-85.3930 ;25.5000
P723=-85.0000 ;25.7570
P724=-84.6100 ;26.0000
P725=-84.5000 ;26.0840
P726=-84.0000 ;26.3690
P727=-83.8880 ;26.5000
P728=-83.5000 ;26.7860
P729=-83.2230 ;27.0000
P730=-83.0000 ;27.1740
P731=-82.5710 ;27.5000
P732=-82.5000 ;27.5620
P733=-82.0000 ;27.9550
P734=-81.9540 ;28.0000
P735=-81.5000 ;28.4020
P736=-81.3900 ;28.5000
P737=-81.0000 ;28.8520
P738=-80.8400 ;29.0000
P739=-80.5000 ;29.3330
P740=-80.3160 ;29.5000
P741=-80.0000 ;29.8270
P742=-79.8230 ;30.0000
P743=-79.5000 ;30.3590
P744=-79.3650 ;30.5000
P745=-79.0000 ;30.9210
P746=-78.9240 ;31.0000
P747=-78.5000 ;31.4760
P748=-78.4780 ;31.5000
P749=-78.0470 ;32.0000
P750=-78.0000 ;32.0560
P751=-77.6100 ;32.5000
P752=-77.5000 ;32.6140
P753=-77.0940 ;33.0000
P754=-77.0000 ;33.0870
P755=-76.5180 ;33.5000
P756=-76.5000 ;33.5170
P757=-76.0000 ;33.9820
P758=-75.9810 ;34.0000
P759=-75.5000 ;34.4700
P760=-75.4680 ;34.5000
P761=-75.0000 ;34.9480
P762=-74.9460 ;35.0000
P763=-74.5000 ;35.4200
P764=-74.4200 ;35.5000
P765=-74.0000 ;35.9140
P766=-73.9160 ;36.0000
P767=-73.5000 ;36.4890
P768=-73.4920 ;36.5000
P769=-73.0930 ;37.0000
P770=-73.0000 ;37.1010
P771=-72.6480 ;37.5000
P772=-72.5000 ;37.6550
P773=-72.2100 ;38.0000
P774=-72.0000 ;38.2300
P775=-71.7670 ;38.5000
P776=-71.5000 ;38.8400
P777=-71.3930 ;39.0000

P778=-71.0000 ;39.4730
P779=-70.9800 ;39.5000
P780=-70.6260 ;40.0000
P781=-70.5000 ;40.1400
P782=-70.2260 ;40.5000
P783=-70.0000 ;40.7550
P784=-69.8270 ;41.0000
P785=-69.5000 ;41.4060
P786=-69.4410 ;41.5000
P787=-69.0000 ;41.9990
P788=-68.9990 ;42.0000
P789=-68.6410 ;42.5000
P790=-68.5000 ;42.6530
P791=-68.2170 ;43.0000
P792=-68.0000 ;43.2210
P793=-67.7400 ;43.5000
P794=-67.5000 ;43.7530
P795=-67.2660 ;44.0000
P796=-67.0000 ;44.3080
P797=-66.8450 ;44.5000
P798=-66.5000 ;44.8880
P799=-66.4070 ;45.0000
P800=-66.0000 ;45.4420
P801=-65.9510 ;45.5000
P802=-65.5000 ;45.9760
P803=-65.4800 ;46.0000
P804=-65.0040 ;46.5000
P805=-65.0000 ;46.5040
P806=-64.5640 ;47.0000
P807=-64.5000 ;47.0720
P808=-64.1570 ;47.5000
P809=-64.0000 ;47.6770
P810=-63.7420 ;48.0000
P811=-63.5000 ;48.2680
P812=-63.3100 ;48.5000
P813=-63.0000 ;48.8290
P814=-62.8500 ;49.0000
P815=-62.5000 ;49.3570
P816=-62.3510 ;49.5000
P817=-62.0000 ;49.8480
P818=-61.8530 ;50.0000
P819=-61.5000 ;50.3420
P820=-61.3540 ;50.5000
P821=-61.0000 ;50.8440
P822=-60.8570 ;51.0000
P823=-60.5000 ;51.3650
P824=-60.3740 ;51.5000
P825=-60.0000 ;51.8760
P826=-59.8850 ;52.0000
P827=-59.5000 ;52.3720
P828=-59.3100 ;52.5000
P829=-59.0000 ;52.7700
P830=-58.7060 ;53.0000
P831=-58.5000 ;53.1680
P832=-58.1190 ;53.5000
P833=-58.0000 ;53.6060
P834=-57.5000 ;53.9920

P835=-57.4920 ;54.0000
P836=-57.0000 ;54.3720
P837=-56.8680 ;54.5000
P838=-56.5000 ;54.8390
P839=-56.2480 ;55.0000
P840=-56.0000 ;55.2060
P841=-55.5000 ;55.5000
P842=-55.0000 ;55.9310
P843=-54.8910 ;56.0000
P844=-54.5000 ;56.2580
P845=-54.2040 ;56.5000
P846=-54.0000 ;56.6700
P847=-53.5000 ;56.9010
P848=-53.4110 ;57.0000
P849=-53.0000 ;57.3570
P850=-52.5070 ;57.5000
P851=-52.5000 ;57.5040
P852=-52.0000 ;57.9120
P853=-51.6850 ;58.0000
P854=-51.5000 ;58.1020
P855=-51.0000 ;58.4320
P856=-50.8690 ;58.5000
P857=-50.5000 ;58.6980
P858=-50.0000 ;58.9270
P859=-49.9110 ;59.0000
P860=-49.5000 ;59.2490
P861=-49.0000 ;59.4130
P862=-48.8920 ;59.5000
P863=-48.5000 ;59.7680
P864=-48.0000 ;59.9270
P865=-47.8290 ;60.0000
P866=-47.5000 ;60.2130
P867=-47.0000 ;60.4440
P868=-46.7750 ;60.5000
P869=-46.5000 ;60.6160
P870=-46.0000 ;60.8330
P871=-45.6350 ;61.0000
P872=-45.5000 ;61.0760
P873=-45.0000 ;61.2660
P874=-44.5000 ;61.3940
P875=-44.3060 ;61.5000
P876=-44.0000 ;61.6560
P877=-43.5000 ;61.8270
P878=-43.0000 ;61.9120
P879=-42.8250 ;62.0000
P880=-42.5000 ;62.1610
P881=-42.0000 ;62.3390
P882=-41.5000 ;62.4500
P883=-41.2750 ;62.5000
P884=-41.0000 ;62.5890
P885=-40.5000 ;62.7840
P886=-40.0000 ;62.9400
P887=-39.7380 ;63.0000
P888=-39.5000 ;63.0680
P889=-39.0000 ;63.1700
P890=-38.5000 ;63.2890
P891=-38.0000 ;63.4550

P892=-37.8350 ;63.5000
P893=-37.5000 ;63.5980
P894=-37.0000 ;63.6990
P895=-36.5000 ;63.7460
P896=-36.0000 ;63.8450
P897=-35.5300 ;64.0000
P898=-35.5000 ;64.0100
P899=-35.0000 ;64.1380
P900=-34.5000 ;64.2250
P901=-34.0000 ;64.2670
P902=-33.5000 ;64.2900
P903=-33.0000 ;64.4080
P904=-32.7040 ;64.5000
P905=-32.5000 ;64.5550
P906=-32.0190 ;64.6500
[C2]
gain=-40.00
n_point=348
P1=-46.8954 ;75.0686
P2=-47.4390 ;75.0160
P3=-47.5000 ;75.0100
P4=-47.5900 ;75.0000
P5=-48.0000 ;74.9040
P6=-48.5000 ;74.7650
P7=-49.0000 ;74.6680
P8=-49.5000 ;74.5930
P9=-50.0000 ;74.5360
P10=-50.4000 ;74.5000
P11=-50.5000 ;74.4810
P12=-51.0000 ;74.3460
P13=-51.5000 ;74.2230
P14=-52.0000 ;74.1330
P15=-52.5000 ;74.0670
P16=-53.0000 ;74.0170
P17=-53.1820 ;74.0000
P18=-53.5000 ;73.9400
P19=-54.0000 ;73.7920
P20=-54.5000 ;73.6830
P21=-55.0000 ;73.6050
P22=-55.5000 ;73.5400
P23=-55.8760 ;73.5000
P24=-56.0000 ;73.4750
P25=-56.5000 ;73.3790
P26=-57.0000 ;73.2450
P27=-57.5000 ;73.1380
P28=-58.0000 ;73.0600
P29=-58.5000 ;73.0030
P30=-58.5240 ;73.0000
P31=-59.0000 ;72.8960
P32=-59.5000 ;72.7930
P33=-60.0000 ;72.6760
P34=-60.5000 ;72.5720
P35=-60.9840 ;72.5000
P36=-61.0000 ;72.4970
P37=-61.5000 ;72.3930
P38=-62.0000 ;72.2790
P39=-62.5000 ;72.1740

P40=-63.0000 ;72.0690
P41=-63.3340 ;72.0000
P42=-63.5000 ;71.9610
P43=-64.0000 ;71.8500
P44=-64.5000 ;71.7330
P45=-65.0000 ;71.6210
P46=-65.5000 ;71.5150
P47=-65.5650 ;71.5000
P48=-66.0000 ;71.3900
P49=-66.5000 ;71.2740
P50=-67.0000 ;71.1510
P51=-67.5000 ;71.0390
P52=-67.6660 ;71.0000
P53=-68.0000 ;70.9120
P54=-68.5000 ;70.7860
P55=-69.0000 ;70.6610
P56=-69.5000 ;70.5420
P57=-69.6760 ;70.5000
P58=-70.0000 ;70.4130
P59=-70.5000 ;70.2800
P60=-71.0000 ;70.1540
P61=-71.5000 ;70.0330
P62=-71.6380 ;70.0000
P63=-72.0000 ;69.8800
P64=-72.5000 ;69.7340
P65=-73.0000 ;69.6070
P66=-73.5000 ;69.5090
P67=-73.5450 ;69.5000
P68=-74.0000 ;69.3270
P69=-74.5000 ;69.1410
P70=-74.9570 ;69.0000
P71=-75.0000 ;68.9840
P72=-75.5000 ;68.7960
P73=-76.0000 ;68.6240
P74=-76.3560 ;68.5000
P75=-76.5000 ;68.4460
P76=-77.0000 ;68.2630
P77=-77.5000 ;68.0940
P78=-77.7780 ;68.0000
P79=-78.0000 ;67.8990
P80=-78.5000 ;67.6960
P81=-79.0000 ;67.5320
P82=-79.1010 ;67.5000
P83=-79.5000 ;67.2980
P84=-80.0000 ;67.0660
P85=-80.1450 ;67.0000
P86=-80.5000 ;66.8300
P87=-81.0000 ;66.6040
P88=-81.2460 ;66.5000
P89=-81.5000 ;66.3620
P90=-82.0000 ;66.1130
P91=-82.2550 ;66.0000
P92=-82.5000 ;65.8510
P93=-83.0000 ;65.5650
P94=-83.1130 ;65.5000
P95=-83.5000 ;65.2770
P96=-84.0000 ;65.0200

P97=-84.0400 ;65.0000
P98=-84.5000 ;64.6770
P99=-84.7740 ;64.5000
P100=-85.0000 ;64.3510
P101=-85.5000 ;64.0390
P102=-85.5620 ;64.0000
P103=-86.0000 ;63.6860
P104=-86.2830 ;63.5000
P105=-86.5000 ;63.3400
P106=-87.0000 ;63.0120
P107=-87.0180 ;63.0000
P108=-87.5000 ;62.6280
P109=-87.6980 ;62.5000
P110=-88.0000 ;62.2640
P111=-88.3550 ;62.0000
P112=-88.5000 ;61.8830
P113=-89.0000 ;61.5060
P114=-89.0080 ;61.5000
P115=-89.5000 ;61.0880
P116=-89.6170 ;61.0000
P117=-90.0000 ;60.6350
P118=-90.1460 ;60.5000
P119=-90.5000 ;60.1820
P120=-90.7240 ;60.0000
P121=-91.0000 ;59.6770
P122=-91.1520 ;59.5000
P123=-91.5000 ;59.1340
P124=-91.6420 ;59.0000
P125=-92.0000 ;58.5850
P126=-92.0710 ;58.5000
P127=-92.4430 ;58.0000
P128=-92.5000 ;57.9240
P129=-92.8410 ;57.5000
P130=-93.0000 ;57.1950
P131=-93.0890 ;57.0000
P132=-93.0000 ;56.7030
P133=-92.5000 ;56.7660
P134=-92.0000 ;56.9850
P135=-91.9770 ;57.0000
P136=-91.5000 ;57.3500
P137=-91.2640 ;57.5000
P138=-91.0000 ;57.6790
P139=-90.5000 ;57.9660
P140=-90.4460 ;58.0000
P141=-90.0000 ;58.3040
P142=-89.5940 ;58.5000
P143=-89.5000 ;58.5560
P144=-89.0000 ;58.8580
P145=-88.7330 ;59.0000
P146=-88.5000 ;59.1390
P147=-88.0000 ;59.3890
P148=-87.6880 ;59.5000
P149=-87.5000 ;59.5980
P150=-87.0000 ;59.8520
P151=-86.6030 ;60.0000
P152=-86.5000 ;60.0540
P153=-86.0000 ;60.3070

P154=-85.5000 ;60.4770
P155=-85.4130 ;60.5000
P156=-85.0000 ;60.6830
P157=-84.5000 ;60.8730
P158=-84.0590 ;61.0000
P159=-84.0000 ;61.0270
P160=-83.5000 ;61.2490
P161=-83.0000 ;61.3990
P162=-82.5540 ;61.5000
P163=-82.5000 ;61.5200
P164=-82.0000 ;61.7020
P165=-81.5000 ;61.8510
P166=-81.0000 ;61.9750
P167=-80.8950 ;62.0000
P168=-80.5000 ;62.1320
P169=-80.0000 ;62.2670
P170=-79.5000 ;62.3700
P171=-79.0000 ;62.4430
P172=-78.5000 ;62.4940
P173=-78.4290 ;62.5000
P174=-78.0000 ;62.5990
P175=-77.5000 ;62.6920
P176=-77.0000 ;62.7900
P177=-76.5000 ;62.8630
P178=-76.0000 ;62.9080
P179=-75.5000 ;62.9260
P180=-75.0000 ;62.9250
P181=-74.5000 ;62.9050
P182=-74.0000 ;62.8530
P183=-73.5000 ;62.7720
P184=-73.0000 ;62.6520
P185=-72.5510 ;62.5000
P186=-72.5000 ;62.4680
P187=-72.0000 ;62.0490
P188=-71.9460 ;62.0000
P189=-71.5000 ;61.7200
P190=-71.2090 ;61.5000
P191=-71.1340 ;61.0000
P192=-71.0000 ;60.9310
P193=-70.5030 ;60.5000
P194=-70.5000 ;60.4750
P195=-70.3950 ;60.0000
P196=-70.1780 ;59.5000
P197=-70.0000 ;59.3530
P198=-69.8320 ;59.0000
P199=-69.7690 ;58.5000
P200=-69.6710 ;58.0000
P201=-69.5890 ;57.5000
P202=-69.5140 ;57.0000
P203=-69.5000 ;56.8770
P204=-69.4670 ;56.5000
P205=-69.4980 ;56.0000
P206=-69.5000 ;55.9770
P207=-69.5280 ;55.5000
P208=-69.5420 ;55.0000
P209=-69.6210 ;54.5000
P210=-69.7110 ;54.0000

P211=-69.8630 ;53.5000
P212=-69.9190 ;53.0000
P213=-70.0000 ;52.6330
P214=-70.0200 ;52.5000
P215=-70.1100 ;52.0000
P216=-70.2550 ;51.5000
P217=-70.3680 ;51.0000
P218=-70.5000 ;50.6490
P219=-70.5310 ;50.5000
P220=-70.6730 ;50.0000
P221=-70.8640 ;49.5000
P222=-70.9730 ;49.0000
P223=-71.0000 ;48.9250
P224=-71.0900 ;48.5000
P225=-71.2640 ;48.0000
P226=-71.3960 ;47.5000
P227=-71.5000 ;47.2020
P228=-71.5410 ;47.0000
P229=-71.6720 ;46.5000
P230=-71.6910 ;46.0000
P231=-71.5000 ;45.6620
P232=-71.1410 ;46.0000
P233=-71.0000 ;46.0720
P234=-70.5940 ;46.5000
P235=-70.5000 ;46.5920
P236=-70.2230 ;47.0000
P237=-70.0000 ;47.2340
P238=-69.8080 ;47.5000
P239=-69.5000 ;47.8390
P240=-69.3820 ;48.0000
P241=-69.0000 ;48.4450
P242=-68.9610 ;48.5000
P243=-68.6310 ;49.0000
P244=-68.5000 ;49.1720
P245=-68.3030 ;49.5000
P246=-68.0000 ;49.8990
P247=-67.9380 ;50.0000
P248=-67.5740 ;50.5000
P249=-67.5000 ;50.5920
P250=-67.2230 ;51.0000
P251=-67.0000 ;51.2850
P252=-66.8560 ;51.5000
P253=-66.5000 ;51.9660
P254=-66.4780 ;52.0000
P255=-66.1550 ;52.5000
P256=-66.0000 ;52.7080
P257=-65.8170 ;53.0000
P258=-65.5000 ;53.4060
P259=-65.4390 ;53.5000
P260=-65.0640 ;54.0000
P261=-65.0000 ;54.0820
P262=-64.7300 ;54.5000
P263=-64.5000 ;54.7830
P264=-64.3550 ;55.0000
P265=-64.0000 ;55.4500
P266=-63.9650 ;55.5000
P267=-63.5820 ;56.0000

P268=-63.5000 ;56.1040
P269=-63.2130 ;56.5000
P270=-63.0000 ;56.7550
P271=-62.7960 ;57.0000
P272=-62.5000 ;57.3270
P273=-62.3250 ;57.5000
P274=-62.0000 ;57.8550
P275=-61.8950 ;58.0000
P276=-61.5000 ;58.4410
P277=-61.4460 ;58.5000
P278=-61.0110 ;59.0000
P279=-61.0000 ;59.0130
P280=-60.5320 ;59.5000
P281=-60.5000 ;59.5310
P282=-60.0450 ;60.0000
P283=-60.0000 ;60.0490
P284=-59.6030 ;60.5000
P285=-59.5000 ;60.6030
P286=-59.0000 ;60.9960
P287=-58.9960 ;61.0000
P288=-58.5220 ;61.5000
P289=-58.5000 ;61.5220
P290=-58.0000 ;61.8960
P291=-57.8800 ;62.0000
P292=-57.5000 ;62.3720
P293=-57.3220 ;62.5000
P294=-57.0000 ;62.7360
P295=-56.6660 ;63.0000
P296=-56.5000 ;63.1580
P297=-56.0390 ;63.5000
P298=-56.0000 ;63.5290
P299=-55.5000 ;63.9010
P300=-55.3450 ;64.0000
P301=-55.0000 ;64.3010
P302=-54.7170 ;64.5000
P303=-54.5000 ;64.6360
P304=-54.0000 ;64.9930
P305=-53.9890 ;65.0000
P306=-53.5000 ;65.3530
P307=-53.2470 ;65.5000
P308=-53.0000 ;65.6560
P309=-52.5030 ;66.0000
P310=-52.5000 ;66.0020
P311=-52.0000 ;66.2830
P312=-51.5310 ;66.5000
P313=-51.5000 ;66.5190
P314=-51.0000 ;66.8560
P315=-50.7030 ;67.0000
P316=-50.5000 ;67.1020
P317=-50.0000 ;67.3150
P318=-49.6430 ;67.5000
P319=-49.5000 ;67.5790
P320=-49.0000 ;67.8040
P321=-48.5000 ;67.9690
P322=-48.4150 ;68.0000
P323=-48.0000 ;68.1940
P324=-47.5000 ;68.4090

P325=-47.2220 ;68.5000
P326=-47.0000 ;68.5890
P327=-46.5000 ;68.7650
P328=-46.0000 ;68.9180
P329=-45.7670 ;69.0000
P330=-45.5000 ;69.0930
P331=-45.0000 ;69.2540
P332=-44.5000 ;69.3970
P333=-44.0860 ;69.5000
P334=-44.0000 ;69.5260
P335=-43.5000 ;69.6710
P336=-43.0000 ;69.7960
P337=-42.5000 ;69.9100
P338=-42.0940 ;70.0000
P339=-42.0000 ;70.0290
P340=-41.5000 ;70.1560
P341=-41.0000 ;70.2660
P342=-40.5000 ;70.3580
P343=-40.0000 ;70.4440
P344=-39.6490 ;70.5000
P345=-39.5000 ;70.5350
P346=-39.0000 ;70.6470
P347=-38.6890 ;70.7010
P348=-38.2982 ;70.7677

[C3]

gain=-50.00

n_point=74

P1=-75.5000 ;62.0650
P2=-75.6667 ;62.0737
P3=-75.8333 ;62.0823
P4=-76.0000 ;62.0910
P5=-76.1667 ;62.0917
P6=-76.3333 ;62.0923
P7=-76.5000 ;62.0930
P8=-76.6667 ;62.0870
P9=-76.8333 ;62.0810
P10=-77.0000 ;62.0750
P11=-77.1667 ;62.0630
P12=-77.3333 ;62.0510
P13=-77.5000 ;62.0390
P14=-77.6620 ;62.0195
P15=-77.8240 ;62.0000
P16=-77.9120 ;61.9875
P17=-78.0000 ;61.9750
P18=-78.1667 ;61.9497
P19=-78.3333 ;61.9243
P20=-78.5000 ;61.8990
P21=-78.6250 ;61.8732
P22=-78.7500 ;61.8475
P23=-78.8750 ;61.8218
P24=-79.0000 ;61.7960
P25=-79.1250 ;61.7610
P26=-79.2500 ;61.7260
P27=-79.3750 ;61.6910
P28=-79.5000 ;61.6560
P29=-79.6135 ;61.6170
P30=-79.7270 ;61.5780

P31=-79.8405 ;61.5390
P32=-79.9540 ;61.5000
P33=-79.8632 ;61.4422
P34=-79.7724 ;61.3844
P35=-79.6816 ;61.3266
P36=-79.5908 ;61.2688
P37=-79.5000 ;61.2110
P38=-79.3750 ;61.1917
P39=-79.2500 ;61.1725
P40=-79.1250 ;61.1533
P41=-79.0000 ;61.1340
P42=-78.8333 ;61.1337
P43=-78.6667 ;61.1333
P44=-78.5000 ;61.1330
P45=-78.3333 ;61.1463
P46=-78.1667 ;61.1597
P47=-78.0000 ;61.1730
P48=-77.8333 ;61.1903
P49=-77.6667 ;61.2077
P50=-77.5000 ;61.2250
P51=-77.3333 ;61.2450
P52=-77.1667 ;61.2650
P53=-77.0000 ;61.2850
P54=-76.8750 ;61.3030
P55=-76.7500 ;61.3210
P56=-76.6250 ;61.3390
P57=-76.5000 ;61.3570
P58=-76.3750 ;61.3790
P59=-76.2500 ;61.4010
P60=-76.1250 ;61.4230
P61=-76.0000 ;61.4450
P62=-75.8885 ;61.4725
P63=-75.7770 ;61.5000
P64=-75.7077 ;61.5730
P65=-75.6385 ;61.6460
P66=-75.5693 ;61.7190
P67=-75.5000 ;61.7920
P68=-75.4073 ;61.8440
P69=-75.3145 ;61.8960
P70=-75.2217 ;61.9480
P71=-75.1290 ;62.0000
P72=-75.2527 ;62.0217
P73=-75.3763 ;62.0433
P74=-75.5000 ;62.0650
[C4]
gain=-50.00
n_point=145
P1=-87.0000 ;59.0100
P2=-87.0190 ;59.0000
P3=-87.5000 ;58.7990
P4=-87.8930 ;58.5000
P5=-88.0000 ;58.1120
P6=-88.5000 ;58.0770
P7=-88.6630 ;58.0000
P8=-89.0000 ;57.7810
P9=-89.3700 ;57.5000
P10=-89.5000 ;57.4030

P11=-90.0000 ;57.0940
P12=-90.1180 ;57.0000
P13=-90.5000 ;56.6060
P14=-90.6400 ;56.5000
P15=-91.0000 ;56.1600
P16=-91.1860 ;56.0000
P17=-91.5000 ;55.7430
P18=-91.8650 ;55.5000
P19=-92.0000 ;55.3390
P20=-92.5000 ;55.0350
P21=-92.5400 ;55.0000
P22=-93.0000 ;54.5760
P23=-93.0940 ;54.5000
P24=-93.5000 ;54.1750
P25=-93.7010 ;54.0000
P26=-94.0000 ;53.7990
P27=-94.3240 ;53.5000
P28=-94.5000 ;53.3710
P29=-94.9050 ;53.0000
P30=-95.0000 ;52.9170
P31=-95.4340 ;52.5000
P32=-95.5000 ;52.4150
P33=-95.9350 ;52.0000
P34=-96.0000 ;51.9210
P35=-96.4000 ;51.5000
P36=-96.5000 ;51.3670
P37=-96.8190 ;51.0000
P38=-97.0000 ;50.7110
P39=-97.1680 ;50.5000
P40=-97.4520 ;50.0000
P41=-97.5000 ;49.9250
P42=-97.7890 ;49.5000
P43=-97.9850 ;49.0000
P44=-98.0000 ;48.9710
P45=-98.2650 ;48.5000
P46=-98.4220 ;48.0000
P47=-98.5000 ;47.5500
P48=-98.5200 ;47.5000
P49=-98.7240 ;47.0000
P50=-98.8630 ;46.5000
P51=-98.9440 ;46.0000
P52=-99.0000 ;45.6840
P53=-99.0660 ;45.5000
P54=-99.2080 ;45.0000
P55=-99.3010 ;44.5000
P56=-99.3770 ;44.0000
P57=-99.5000 ;43.5470
P58=-99.5170 ;43.5000
P59=-99.6880 ;43.0000
P60=-99.8060 ;42.5000
P61=-99.8800 ;42.0000
P62=-99.9190 ;41.5000
P63=-99.9330 ;41.0000
P64=-99.9230 ;40.5000
P65=-99.8720 ;40.0000
P66=-99.7560 ;39.5000
P67=-99.5620 ;39.0000

P68=-99.5000 ;38.8660
P69=-99.4270 ;38.5000
P70=-99.2400 ;38.0000
P71=-99.1060 ;37.5000
P72=-99.0380 ;37.0000
P73=-99.0000 ;36.9280
P74=-98.7990 ;37.0000
P75=-98.8190 ;37.5000
P76=-98.7860 ;38.0000
P77=-98.6740 ;38.5000
P78=-98.7850 ;39.0000
P79=-98.9090 ;39.5000
P80=-98.9990 ;40.0000
P81=-99.0000 ;40.0110
P82=-99.0290 ;40.5000
P83=-99.0370 ;41.0000
P84=-99.0270 ;41.5000
P85=-99.0000 ;41.7850
P86=-98.9770 ;42.0000
P87=-98.9120 ;42.5000
P88=-98.8330 ;43.0000
P89=-98.7440 ;43.5000
P90=-98.6320 ;44.0000
P91=-98.5000 ;44.3450
P92=-98.4480 ;44.5000
P93=-98.2990 ;45.0000
P94=-98.1570 ;45.5000
P95=-98.0000 ;45.9440
P96=-97.9750 ;46.0000
P97=-97.7890 ;46.5000
P98=-97.6290 ;47.0000
P99=-97.5000 ;47.2840
P100=-97.3870 ;47.5000
P101=-97.2220 ;48.0000
P102=-97.0370 ;48.5000
P103=-97.0000 ;48.5670
P104=-96.7640 ;49.0000
P105=-96.5000 ;49.4680
P106=-96.4770 ;49.5000
P107=-96.1460 ;50.0000
P108=-96.0000 ;50.1880
P109=-95.7550 ;50.5000
P110=-95.5000 ;50.8150
P111=-95.3450 ;51.0000
P112=-95.0000 ;51.3910
P113=-94.9000 ;51.5000
P114=-94.5000 ;51.9400
P115=-94.4440 ;52.0000
P116=-94.0070 ;52.5000
P117=-94.0000 ;52.5100
P118=-93.5700 ;53.0000
P119=-93.5000 ;53.0820
P120=-93.1230 ;53.5000
P121=-93.0000 ;53.6520
P122=-92.6630 ;54.0000
P123=-92.5000 ;54.2030
P124=-92.2060 ;54.5000

P125=-92.0000 ;54.7540
P126=-91.7660 ;55.0000
P127=-91.5000 ;55.2360
P128=-91.1160 ;55.5000
P129=-91.0000 ;55.6620
P130=-90.5000 ;55.9160
P131=-90.4030 ;56.0000
P132=-90.0000 ;56.4240
P133=-89.8910 ;56.5000
P134=-89.5000 ;56.7290
P135=-89.1950 ;57.0000
P136=-89.0000 ;57.2410
P137=-88.5000 ;57.4790
P138=-88.4670 ;57.5000
P139=-88.0000 ;57.9550
P140=-87.8230 ;58.0000
P141=-87.5000 ;58.0630
P142=-87.0000 ;58.3050
P143=-86.7240 ;58.5000
P144=-86.9260 ;59.0000
P145=-87.0000 ;59.0100
[C5]
gain=-50.00
n_point=114
P1=-72.0000 ;49.8370
P2=-72.0550 ;49.5000
P3=-72.1495 ;49.2500
P4=-72.2440 ;49.0000
P5=-72.5000 ;48.6510
P6=-72.5820 ;48.5000
P7=-72.6130 ;48.2500
P8=-72.6440 ;48.0000
P9=-72.7120 ;47.7500
P10=-72.7800 ;47.5000
P11=-73.0000 ;47.3680
P12=-73.2320 ;47.0000
P13=-73.3660 ;46.7720
P14=-73.5000 ;46.5440
P15=-73.5310 ;46.5000
P16=-73.6065 ;46.2500
P17=-73.6820 ;46.0000
P18=-73.6760 ;45.7500
P19=-73.6700 ;45.5000
P20=-73.8350 ;45.2855
P21=-74.0000 ;45.0710
P22=-74.0310 ;45.0000
P23=-74.1190 ;44.7500
P24=-74.2070 ;44.5000
P25=-74.3535 ;44.2705
P26=-74.5000 ;44.0410
P27=-74.5220 ;44.0000
P28=-74.6580 ;43.7500
P29=-74.7940 ;43.5000
P30=-75.0000 ;43.1590
P31=-75.0870 ;43.0000
P32=-75.2275 ;42.7500
P33=-75.3680 ;42.5000

P34=-75.5000 ;42.3560
P35=-75.6880 ;42.0000
P36=-76.0000 ;41.6820
P37=-76.1420 ;41.5000
P38=-76.2675 ;41.2500
P39=-76.3930 ;41.0000
P40=-76.5000 ;40.8530
P41=-76.7670 ;40.5000
P42=-77.0000 ;40.2440
P43=-77.1900 ;40.0000
P44=-77.5000 ;39.6190
P45=-77.6030 ;39.5000
P46=-77.7585 ;39.2500
P47=-77.9140 ;39.0000
P48=-78.0000 ;38.8860
P49=-78.3090 ;38.5000
P50=-78.5000 ;38.1950
P51=-78.6670 ;38.0000
P52=-78.8335 ;37.7565
P53=-79.0000 ;37.5130
P54=-79.0110 ;37.5000
P55=-79.1195 ;37.2500
P56=-79.2280 ;37.0000
P57=-79.0000 ;36.8190
P58=-78.8230 ;37.0000
P59=-78.5000 ;37.3200
P60=-78.3450 ;37.5000
P61=-78.0000 ;37.7990
P62=-77.8150 ;38.0000
P63=-77.6575 ;38.2070
P64=-77.5000 ;38.4140
P65=-77.4260 ;38.5000
P66=-77.2470 ;38.7500
P67=-77.0680 ;39.0000
P68=-77.0000 ;39.0830
P69=-76.8215 ;39.2915
P70=-76.6430 ;39.5000
P71=-76.5000 ;39.7660
P72=-76.3220 ;40.0000
P73=-76.1715 ;40.2500
P74=-76.0210 ;40.5000
P75=-76.0000 ;40.5140
P76=-75.8245 ;40.7570
P77=-75.6490 ;41.0000
P78=-75.5000 ;41.3240
P79=-75.3770 ;41.5000
P80=-75.2145 ;41.7500
P81=-75.0520 ;42.0000
P82=-75.0000 ;42.0470
P83=-74.8780 ;42.2735
P84=-74.7560 ;42.5000
P85=-74.5000 ;42.8040
P86=-74.3560 ;43.0000
P87=-74.2635 ;43.2500
P88=-74.1710 ;43.5000
P89=-74.0000 ;43.6840
P90=-73.7950 ;44.0000

P91=-73.7350 ;44.2500
P92=-73.6750 ;44.5000
P93=-73.5000 ;44.6780
P94=-73.3440 ;45.0000
P95=-73.3155 ;45.2500
P96=-73.2870 ;45.5000
P97=-73.1435 ;45.7440
P98=-73.0000 ;45.9880
P99=-72.9950 ;46.0000
P100=-72.7940 ;46.2500
P101=-72.5930 ;46.5000
P102=-72.5000 ;46.7410
P103=-72.3050 ;47.0000
P104=-72.3145 ;47.2500
P105=-72.3240 ;47.5000
P106=-72.3015 ;47.7500
P107=-72.2790 ;48.0000
P108=-72.0000 ;48.3630
P109=-71.9380 ;48.5000
P110=-71.8530 ;48.7500
P111=-71.7680 ;49.0000
P112=-71.8300 ;49.2500
P113=-71.8920 ;49.5000
P114=-72.0000 ;49.8370

[C6]

gain=-40.00

n_point=363

P1=-71.0000 ;57.2720
P2=-70.9700 ;57.0000
P3=-71.0000 ;56.8650
P4=-71.0560 ;56.5000
P5=-71.1040 ;56.0000
P6=-71.1210 ;55.5000
P7=-71.1960 ;55.0000
P8=-71.3190 ;54.5000
P9=-71.4010 ;54.0000
P10=-71.5000 ;53.6170
P11=-71.5410 ;53.5000
P12=-71.6650 ;53.0000
P13=-71.7890 ;52.5000
P14=-71.9100 ;52.0000
P15=-72.0000 ;51.6300
P16=-72.0490 ;51.5000
P17=-72.2230 ;51.0000
P18=-72.3670 ;50.5000
P19=-72.5000 ;50.1140
P20=-72.5580 ;50.0000
P21=-72.7880 ;49.5000
P22=-72.9060 ;49.0000
P23=-73.0000 ;48.7190
P24=-73.1100 ;48.5000
P25=-73.3440 ;48.0000
P26=-73.4690 ;47.5000
P27=-73.5000 ;47.4240
P28=-73.7580 ;47.0000
P29=-73.9720 ;46.5000
P30=-74.0000 ;46.3690

P31=-74.1900 ;46.0000
P32=-74.4400 ;45.5000
P33=-74.5000 ;45.2920
P34=-74.6460 ;45.0000
P35=-74.9440 ;44.5000
P36=-75.0000 ;44.3660
P37=-75.2290 ;44.0000
P38=-75.4980 ;43.5000
P39=-75.5000 ;43.4960
P40=-75.8330 ;43.0000
P41=-76.0000 ;42.6880
P42=-76.1430 ;42.5000
P43=-76.4430 ;42.0000
P44=-76.5000 ;41.9060
P45=-76.8370 ;41.5000
P46=-77.0000 ;41.2230
P47=-77.1830 ;41.0000
P48=-77.5000 ;40.5840
P49=-77.5790 ;40.5000
P50=-77.9580 ;40.0000
P51=-78.0000 ;39.9370
P52=-78.3590 ;39.5000
P53=-78.5000 ;39.3150
P54=-78.8080 ;39.0000
P55=-79.0000 ;38.7550
P56=-79.2670 ;38.5000
P57=-79.5000 ;38.1930
P58=-79.7040 ;38.0000
P59=-80.0000 ;37.6150
P60=-80.1080 ;37.5000
P61=-80.4920 ;37.0000
P62=-80.5000 ;36.9900
P63=-80.9450 ;36.5000
P64=-81.0000 ;36.4410
P65=-81.4180 ;36.0000
P66=-81.5000 ;35.9190
P67=-81.9060 ;35.5000
P68=-82.0000 ;35.4060
P69=-82.3750 ;35.0000
P70=-82.5000 ;34.8790
P71=-82.8500 ;34.5000
P72=-83.0000 ;34.3680
P73=-83.3580 ;34.0000
P74=-83.5000 ;33.8900
P75=-83.9230 ;33.5000
P76=-84.0000 ;33.4390
P77=-84.4810 ;33.0000
P78=-84.5000 ;32.9840
P79=-85.0000 ;32.5520
P80=-85.0530 ;32.5000
P81=-85.5000 ;32.1580
P82=-85.6800 ;32.0000
P83=-86.0000 ;31.7730
P84=-86.3680 ;31.5000
P85=-86.5000 ;31.4120
P86=-87.0000 ;31.1430
P87=-87.2240 ;31.0000

P88=-87.5000 ;30.8590
P89=-88.0000 ;30.6660
P90=-88.3580 ;30.5000
P91=-88.5000 ;30.4300
P92=-89.0000 ;30.3190
P93=-89.5000 ;30.2740
P94=-90.0000 ;30.1820
P95=-90.5000 ;30.0920
P96=-91.0000 ;30.0510
P97=-91.5000 ;30.0720
P98=-92.0000 ;30.1630
P99=-92.5000 ;30.1930
P100=-93.0000 ;30.2670
P101=-93.5000 ;30.4470
P102=-93.5630 ;30.5000
P103=-94.0000 ;30.7930
P104=-94.3820 ;31.0000
P105=-94.5000 ;31.0870
P106=-95.0000 ;31.3820
P107=-95.0690 ;31.5000
P108=-95.5000 ;31.9160
P109=-95.6480 ;32.0000
P110=-96.0000 ;32.4370
P111=-96.0420 ;32.5000
P112=-96.4290 ;33.0000
P113=-96.5000 ;33.0960
P114=-96.6890 ;33.5000
P115=-97.0000 ;33.9310
P116=-97.0520 ;34.0000
P117=-97.2440 ;34.5000
P118=-97.5000 ;34.9580
P119=-97.5200 ;35.0000
P120=-97.6280 ;35.5000
P121=-97.8390 ;36.0000
P122=-98.0000 ;36.4490
P123=-98.0120 ;36.5000
P124=-98.0780 ;37.0000
P125=-98.1310 ;37.5000
P126=-98.1950 ;38.0000
P127=-98.2300 ;38.5000
P128=-98.2470 ;39.0000
P129=-98.2470 ;39.5000
P130=-98.2240 ;40.0000
P131=-98.1710 ;40.5000
P132=-98.0990 ;41.0000
P133=-98.0230 ;41.5000
P134=-98.0000 ;41.6580
P135=-97.7450 ;42.0000
P136=-97.5400 ;42.5000
P137=-97.5000 ;42.6540
P138=-97.4810 ;42.5000
P139=-97.4370 ;42.0000
P140=-97.3960 ;41.5000
P141=-97.3380 ;41.0000
P142=-97.2400 ;40.5000
P143=-97.0770 ;40.0000
P144=-97.0000 ;39.8520

P145=-96.9470 ;39.5000
P146=-96.7890 ;39.0000
P147=-96.5000 ;38.5550
P148=-96.4780 ;38.5000
P149=-96.3210 ;38.0000
P150=-96.0820 ;37.5000
P151=-96.0000 ;37.3950
P152=-95.8410 ;37.0000
P153=-95.5000 ;36.5880
P154=-95.3480 ;36.5000
P155=-95.2260 ;36.0000
P156=-95.0000 ;35.7400
P157=-94.7700 ;35.5000
P158=-94.5000 ;35.2040
P159=-94.2120 ;35.0000
P160=-94.0000 ;34.7910
P161=-93.8340 ;35.0000
P162=-94.0000 ;35.2440
P163=-94.1740 ;35.5000
P164=-94.4970 ;36.0000
P165=-94.5000 ;36.0050
P166=-94.8080 ;36.5000
P167=-95.0000 ;36.9340
P168=-95.0340 ;37.0000
P169=-95.2200 ;37.5000
P170=-95.3900 ;38.0000
P171=-95.5000 ;38.2570
P172=-95.5980 ;38.5000
P173=-95.6350 ;39.0000
P174=-95.7900 ;39.5000
P175=-95.8930 ;40.0000
P176=-95.9380 ;40.5000
P177=-95.9610 ;41.0000
P178=-95.9460 ;41.5000
P179=-95.8990 ;42.0000
P180=-95.8260 ;42.5000
P181=-95.7350 ;43.0000
P182=-95.6290 ;43.5000
P183=-95.5000 ;43.9820
P184=-95.4930 ;44.0000
P185=-95.2970 ;44.5000
P186=-95.1140 ;45.0000
P187=-95.0000 ;45.2760
P188=-94.8880 ;45.5000
P189=-94.6480 ;46.0000
P190=-94.5000 ;46.2740
P191=-94.3610 ;46.5000
P192=-94.0700 ;47.0000
P193=-94.0000 ;47.0960
P194=-93.7060 ;47.5000
P195=-93.5000 ;47.7840
P196=-93.3250 ;48.0000
P197=-93.0000 ;48.4210
P198=-92.9290 ;48.5000
P199=-92.5000 ;48.9790
P200=-92.4790 ;49.0000
P201=-92.0000 ;49.4600

P202=-91.9570 ;49.5000
P203=-91.5000 ;49.8950
P204=-91.3820 ;50.0000
P205=-91.0000 ;50.2950
P206=-90.7580 ;50.5000
P207=-90.5000 ;50.6690
P208=-90.0790 ;51.0000
P209=-90.0000 ;51.0820
P210=-89.5000 ;51.4320
P211=-89.4130 ;51.5000
P212=-89.0000 ;51.8540
P213=-88.7930 ;52.0000
P214=-88.5000 ;52.2500
P215=-88.1060 ;52.5000
P216=-88.0000 ;52.6170
P217=-87.5000 ;52.8280
P218=-87.0910 ;53.0000
P219=-87.0000 ;53.3610
P220=-86.5000 ;53.3750
P221=-86.0000 ;53.4160
P222=-85.6810 ;53.5000
P223=-85.5000 ;53.6580
P224=-85.0000 ;53.8410
P225=-84.5000 ;53.9140
P226=-84.0000 ;53.9600
P227=-83.7190 ;54.0000
P228=-83.5000 ;54.0270
P229=-83.0000 ;54.1110
P230=-82.5000 ;54.2230
P231=-82.0000 ;54.3940
P232=-81.7990 ;54.5000
P233=-82.0000 ;54.6130
P234=-82.5000 ;54.8170
P235=-83.0000 ;54.8980
P236=-83.5000 ;54.8790
P237=-84.0000 ;54.7980
P238=-84.5000 ;54.6430
P239=-84.8520 ;54.5000
P240=-85.0000 ;54.3150
P241=-85.5000 ;54.1690
P242=-86.0000 ;54.0470
P243=-86.1210 ;54.0000
P244=-86.5000 ;53.7190
P245=-87.0000 ;53.5230
P246=-87.0610 ;53.5000
P247=-87.5000 ;53.3090
P248=-88.0000 ;53.1980
P249=-88.4560 ;53.0000
P250=-88.5000 ;52.9610
P251=-89.0000 ;52.7910
P252=-89.5000 ;52.6000
P253=-89.7010 ;52.5000
P254=-90.0000 ;52.3810
P255=-90.5000 ;52.1760
P256=-90.8200 ;52.0000
P257=-91.0000 ;51.9230
P258=-91.5000 ;51.6810

P259=-91.7960 ;51.5000
P260=-92.0000 ;51.3910
P261=-92.5000 ;51.0390
P262=-92.5610 ;51.0000
P263=-93.0000 ;50.7240
P264=-93.2950 ;50.5000
P265=-93.5000 ;50.3380
P266=-93.8850 ;50.0000
P267=-94.0000 ;49.8750
P268=-94.3640 ;49.5000
P269=-94.5000 ;49.3150
P270=-94.7840 ;49.0000
P271=-95.0000 ;48.5800
P272=-95.0860 ;48.5000
P273=-95.4170 ;48.0000
P274=-95.5000 ;47.8000
P275=-95.7930 ;47.5000
P276=-95.9780 ;47.0000
P277=-96.0000 ;46.9380
P278=-96.1460 ;47.0000
P279=-96.1420 ;47.5000
P280=-96.0200 ;48.0000
P281=-96.0000 ;48.0500
P282=-95.6840 ;48.5000
P283=-95.5000 ;48.8700
P284=-95.3780 ;49.0000
P285=-95.0380 ;49.5000
P286=-95.0000 ;49.5560
P287=-94.6170 ;50.0000
P288=-94.5000 ;50.1710
P289=-94.2400 ;50.5000
P290=-94.0000 ;50.8660
P291=-93.9080 ;51.0000
P292=-93.5390 ;51.5000
P293=-93.5000 ;51.5490
P294=-93.1550 ;52.0000
P295=-93.0000 ;52.2100
P296=-92.7930 ;52.5000
P297=-92.5000 ;52.8800
P298=-92.4120 ;53.0000
P299=-92.0330 ;53.5000
P300=-92.0000 ;53.5360
P301=-91.5810 ;54.0000
P302=-91.5000 ;54.0830
P303=-91.0990 ;54.5000
P304=-91.0000 ;54.5870
P305=-90.5720 ;55.0000
P306=-90.5000 ;55.0710
P307=-90.0640 ;55.5000
P308=-90.0000 ;55.5490
P309=-89.5000 ;55.9570
P310=-89.4490 ;56.0000
P311=-89.0000 ;56.3220
P312=-88.7840 ;56.5000
P313=-88.5000 ;56.7290
P314=-88.1710 ;57.0000
P315=-88.0000 ;57.0900

P316=-87.5000 ;57.4100
P317=-87.3670 ;57.5000
P318=-87.0000 ;57.6850
P319=-86.5120 ;58.0000
P320=-86.5000 ;58.0060
P321=-86.0000 ;58.2770
P322=-85.6310 ;58.5000
P323=-85.5000 ;58.5440
P324=-85.0000 ;58.7200
P325=-84.5000 ;58.9750
P326=-84.4480 ;59.0000
P327=-84.0000 ;59.1850
P328=-83.5000 ;59.4270
P329=-83.3440 ;59.5000
P330=-83.0000 ;59.5840
P331=-82.5000 ;59.7080
P332=-82.0000 ;59.8720
P333=-81.6220 ;60.0000
P334=-81.5000 ;60.0400
P335=-81.0000 ;60.1850
P336=-80.5000 ;60.3310
P337=-80.0000 ;60.4730
P338=-79.8910 ;60.5000
P339=-79.5000 ;60.5480
P340=-79.0000 ;60.5890
P341=-78.5000 ;60.6220
P342=-78.0000 ;60.6590
P343=-77.5000 ;60.7000
P344=-77.0000 ;60.7440
P345=-76.5000 ;60.7930
P346=-76.0000 ;60.8460
P347=-75.5000 ;60.8850
P348=-75.0000 ;60.8800
P349=-74.5000 ;60.8010
P350=-74.0000 ;60.7040
P351=-73.5000 ;60.6250
P352=-73.0000 ;60.5630
P353=-72.6800 ;60.5000
P354=-72.5000 ;60.4090
P355=-72.0000 ;60.1120
P356=-71.6670 ;60.0000
P357=-71.5980 ;59.5000
P358=-71.5000 ;59.3860
P359=-71.1360 ;59.0000
P360=-71.0210 ;58.5000
P361=-71.0960 ;58.0000
P362=-71.0200 ;57.5000
P363=-71.0000 ;57.2720
[C7]
gain=-40.00
n_point=107
P1=-77.0000 ;49.0560
P2=-77.1620 ;49.0000
P3=-77.5000 ;48.8070
P4=-77.5420 ;48.5000
P5=-77.5590 ;48.0000
P6=-77.5960 ;47.5000

P7=-77.6790 ;47.0000
P8=-77.7200 ;46.5000
P9=-77.8290 ;46.0000
P10=-77.9640 ;45.5000
P11=-78.0000 ;45.4360
P12=-78.1830 ;45.0000
P13=-78.2530 ;44.5000
P14=-78.4420 ;44.0000
P15=-78.5000 ;43.8720
P16=-78.6430 ;43.5000
P17=-78.7665 ;43.2500
P18=-78.8900 ;43.0000
P19=-79.0000 ;42.6420
P20=-79.0710 ;42.5000
P21=-79.2170 ;42.2500
P22=-79.3630 ;42.0000
P23=-79.5000 ;41.7210
P24=-79.6380 ;41.5000
P25=-79.7600 ;41.2500
P26=-79.8820 ;41.0000
P27=-80.0000 ;40.8600
P28=-80.2790 ;40.5000
P29=-80.5000 ;40.0420
P30=-80.5320 ;40.0000
P31=-80.7130 ;39.7500
P32=-80.8940 ;39.5000
P33=-81.0000 ;39.3760
P34=-81.3340 ;39.0000
P35=-81.5000 ;38.7670
P36=-81.7400 ;38.5000
P37=-82.0000 ;38.1540
P38=-82.1440 ;38.0000
P39=-82.5000 ;37.5950
P40=-82.5960 ;37.5000
P41=-82.7980 ;37.2915
P42=-83.0000 ;37.0830
P43=-83.0870 ;37.0000
P44=-83.2935 ;36.7965
P45=-83.5000 ;36.5930
P46=-83.6000 ;36.5000
P47=-84.0000 ;36.1160
P48=-84.1270 ;36.0000
P49=-84.5000 ;35.6580
P50=-84.6870 ;35.5000
P51=-85.0000 ;35.1820
P52=-85.2840 ;35.0000
P53=-85.0000 ;34.7440
P54=-84.5000 ;34.9530
P55=-84.4210 ;35.0000
P56=-84.0000 ;35.2440
P57=-83.5900 ;35.5000
P58=-83.5000 ;35.5590
P59=-83.0000 ;35.8380
P60=-82.7850 ;36.0000
P61=-82.5000 ;36.1770
P62=-82.1030 ;36.5000
P63=-82.0000 ;36.5720

P64=-81.7585 ;36.7860
P65=-81.5170 ;37.0000
P66=-81.5000 ;37.0140
P67=-81.2500 ;37.2495
P68=-81.0000 ;37.4850
P69=-80.9820 ;37.5000
P70=-80.7555 ;37.7500
P71=-80.5290 ;38.0000
P72=-80.5000 ;38.0460
P73=-80.3205 ;38.2730
P74=-80.1410 ;38.5000
P75=-80.0000 ;38.7330
P76=-79.8090 ;39.0000
P77=-79.6625 ;39.2500
P78=-79.5160 ;39.5000
P79=-79.5000 ;39.5370
P80=-79.3325 ;39.7685
P81=-79.1650 ;40.0000
P82=-79.0000 ;40.3980
P83=-78.9370 ;40.5000
P84=-78.7765 ;40.7500
P85=-78.6160 ;41.0000
P86=-78.5020 ;41.5000
P87=-78.5000 ;41.5030
P88=-78.3175 ;41.7515
P89=-78.1350 ;42.0000
P90=-78.0140 ;42.5000
P91=-78.0000 ;42.5450
P92=-77.7020 ;43.0000
P93=-77.5730 ;43.5000
P94=-77.5000 ;43.8890
P95=-77.4510 ;44.0000
P96=-77.2720 ;44.5000
P97=-77.2160 ;45.0000
P98=-77.0800 ;45.5000
P99=-77.0000 ;45.9130
P100=-76.9730 ;46.0000
P101=-76.8990 ;46.5000
P102=-76.8900 ;47.0000
P103=-76.8460 ;47.5000
P104=-76.9100 ;48.0000
P105=-76.9000 ;48.5000
P106=-76.9820 ;49.0000
P107=-77.0000 ;49.0560
[C8]
gain=-30.00
n_point=215
P1=-78.5000 ;49.7190
P2=-78.4570 ;49.5000
P3=-78.4300 ;49.0000
P4=-78.3850 ;48.5000
P5=-78.4090 ;48.0000
P6=-78.4130 ;47.5000
P7=-78.4630 ;47.0000
P8=-78.5000 ;46.5400
P9=-78.5050 ;46.5000
P10=-78.6310 ;46.0000

P11=-78.7500 ;45.5000
P12=-78.9010 ;45.0000
P13=-79.0000 ;44.5750
P14=-79.0270 ;44.5000
P15=-79.2630 ;44.0000
P16=-79.4280 ;43.5000
P17=-79.5000 ;43.3280
P18=-79.6990 ;43.0000
P19=-79.9380 ;42.5000
P20=-80.0000 ;42.3730
P21=-80.2540 ;42.0000
P22=-80.5000 ;41.5760
P23=-80.5770 ;41.5000
P24=-80.9290 ;41.0000
P25=-81.0000 ;40.8920
P26=-81.3690 ;40.5000
P27=-81.5000 ;40.3440
P28=-81.7520 ;40.5000
P29=-81.6290 ;41.0000
P30=-81.5660 ;41.5000
P31=-81.5000 ;41.8110
P32=-81.4150 ;42.0000
P33=-81.2770 ;42.5000
P34=-81.2520 ;43.0000
P35=-81.2030 ;43.5000
P36=-81.2640 ;44.0000
P37=-81.5000 ;44.3810
P38=-81.7700 ;44.0000
P39=-82.0000 ;43.5540
P40=-82.0130 ;43.5000
P41=-82.2410 ;43.0000
P42=-82.3550 ;42.5000
P43=-82.5000 ;42.1760
P44=-82.5950 ;42.0000
P45=-82.7850 ;41.5000
P46=-82.8990 ;41.0000
P47=-83.0000 ;40.7950
P48=-83.1680 ;40.5000
P49=-83.4070 ;40.0000
P50=-83.5000 ;39.8810
P51=-83.7470 ;39.5000
P52=-84.0000 ;39.1320
P53=-84.1060 ;39.0000
P54=-84.5000 ;38.5440
P55=-84.5430 ;38.5000
P56=-85.0000 ;38.0760
P57=-85.0930 ;38.0000
P58=-85.5000 ;37.6930
P59=-85.8220 ;37.5000
P60=-86.0000 ;37.3590
P61=-86.5000 ;37.1800
P62=-87.0000 ;37.0370
P63=-87.1560 ;37.0000
P64=-87.5000 ;36.8690
P65=-88.0000 ;36.8480
P66=-88.5000 ;36.8730
P67=-89.0000 ;36.8690

P68=-89.3770 ;37.0000
P69=-89.5000 ;37.0260
P70=-90.0000 ;37.0790
P71=-90.3010 ;37.0000
P72=-90.0000 ;36.8400
P73=-89.5410 ;36.5000
P74=-89.5000 ;36.4780
P75=-89.0000 ;36.2550
P76=-88.5000 ;36.1600
P77=-88.0000 ;36.1650
P78=-87.5000 ;36.1920
P79=-87.0000 ;36.2230
P80=-86.5000 ;36.2410
P81=-86.0000 ;36.1440
P82=-85.8860 ;36.0000
P83=-86.0000 ;35.8580
P84=-86.2070 ;35.5000
P85=-86.5000 ;35.2590
P86=-86.7520 ;35.0000
P87=-87.0000 ;34.8490
P88=-87.4830 ;34.5000
P89=-87.5000 ;34.4920
P90=-88.0000 ;34.2710
P91=-88.5000 ;34.0190
P92=-88.5450 ;34.0000
P93=-89.0000 ;33.8940
P94=-89.5000 ;33.8010
P95=-90.0000 ;33.7510
P96=-90.5000 ;33.7650
P97=-91.0000 ;33.8450
P98=-91.5000 ;33.9580
P99=-91.6560 ;34.0000
P100=-92.0000 ;34.1840
P101=-92.5000 ;34.4390
P102=-92.6110 ;34.5000
P103=-93.0000 ;34.8420
P104=-93.1700 ;35.0000
P105=-93.5000 ;35.3620
P106=-93.5920 ;35.5000
P107=-93.9910 ;36.0000
P108=-94.0000 ;36.0140
P109=-94.2330 ;36.5000
P110=-94.4910 ;37.0000
P111=-94.5000 ;37.0220
P112=-94.6410 ;37.5000
P113=-94.7940 ;38.0000
P114=-94.9050 ;38.5000
P115=-94.9580 ;39.0000
P116=-94.9550 ;39.5000
P117=-94.8290 ;40.0000
P118=-94.5000 ;40.3620
P119=-94.3410 ;40.0000
P120=-94.0000 ;39.6680
P121=-93.9140 ;39.5000
P122=-93.5000 ;39.0860
P123=-93.3620 ;39.0000
P124=-93.0000 ;38.7340

P125=-92.7910 ;39.0000
P126=-92.8820 ;39.5000
P127=-93.0000 ;39.9250
P128=-93.0240 ;40.0000
P129=-93.1050 ;40.5000
P130=-93.2170 ;41.0000
P131=-93.3690 ;41.5000
P132=-93.4650 ;42.0000
P133=-93.5000 ;42.2990
P134=-93.5760 ;42.5000
P135=-93.6930 ;43.0000
P136=-93.7640 ;43.5000
P137=-93.7880 ;44.0000
P138=-93.7490 ;44.5000
P139=-93.6400 ;45.0000
P140=-93.5000 ;45.4620
P141=-93.4880 ;45.5000
P142=-93.2480 ;46.0000
P143=-93.0000 ;46.4800
P144=-92.9880 ;46.5000
P145=-92.6360 ;47.0000
P146=-92.5000 ;47.1950
P147=-92.2350 ;47.5000
P148=-92.0000 ;47.7690
P149=-91.7490 ;48.0000
P150=-91.5000 ;48.2250
P151=-91.1280 ;48.5000
P152=-91.0000 ;48.5980
P153=-90.5000 ;48.8980
P154=-90.1210 ;49.0000
P155=-90.0000 ;49.0610
P156=-89.9550 ;49.0000
P157=-89.6540 ;48.5000
P158=-89.5000 ;48.4800
P159=-89.0000 ;48.4670
P160=-88.5000 ;48.4950
P161=-88.4340 ;48.5000
P162=-88.0000 ;48.5290
P163=-87.5000 ;48.5470
P164=-87.0000 ;48.5900
P165=-86.5000 ;48.6890
P166=-86.0000 ;48.8140
P167=-85.5120 ;49.0000
P168=-86.0000 ;49.3760
P169=-86.2900 ;49.5000
P170=-86.5000 ;49.5840
P171=-87.0000 ;49.6990
P172=-87.5000 ;49.7080
P173=-88.0000 ;49.6660
P174=-88.5000 ;49.5910
P175=-88.8710 ;49.5000
P176=-89.0000 ;49.4710
P177=-89.5000 ;49.3880
P178=-89.6440 ;49.5000
P179=-89.5000 ;49.6860
P180=-89.3800 ;50.0000
P181=-89.0000 ;50.4210

P182=-88.9520 ;50.5000
P183=-88.5000 ;50.9210
P184=-88.4330 ;51.0000
P185=-88.0000 ;51.3420
P186=-87.8250 ;51.5000
P187=-87.5000 ;51.7170
P188=-87.1170 ;52.0000
P189=-87.0000 ;52.0650
P190=-86.5000 ;52.3440
P191=-86.2310 ;52.5000
P192=-86.0000 ;52.5930
P193=-85.5000 ;52.7880
P194=-85.0000 ;52.9780
P195=-84.9320 ;53.0000
P196=-84.5000 ;53.0890
P197=-84.0000 ;53.1830
P198=-83.5000 ;53.2590
P199=-83.0000 ;53.3070
P200=-82.5000 ;53.3200
P201=-82.0000 ;53.2930
P202=-81.5000 ;53.2210
P203=-81.0000 ;53.0960
P204=-80.7560 ;53.0000
P205=-80.5000 ;52.8770
P206=-80.0000 ;52.5690
P207=-79.9210 ;52.5000
P208=-79.5000 ;52.0530
P209=-79.4590 ;52.0000
P210=-79.1260 ;51.5000
P211=-79.0000 ;51.2530
P212=-78.8990 ;51.0000
P213=-78.7010 ;50.5000
P214=-78.5790 ;50.0000
P215=-78.5000 ;49.7190

[C9]

gain=-20.00

n_point=117

P1=-83.0000 ;46.7260
P2=-82.8700 ;46.5000
P3=-82.7740 ;46.2500
P4=-82.6780 ;46.0000
P5=-82.6280 ;45.7500
P6=-82.5780 ;45.5000
P7=-82.5480 ;45.2500
P8=-82.5180 ;45.0000
P9=-82.5255 ;44.7500
P10=-82.5330 ;44.5000
P11=-82.5555 ;44.2500
P12=-82.5780 ;44.0000
P13=-82.6220 ;43.7500
P14=-82.6660 ;43.5000
P15=-82.7285 ;43.2500
P16=-82.7910 ;43.0000
P17=-82.8490 ;42.7500
P18=-82.9070 ;42.5000
P19=-83.0000 ;42.1950
P20=-83.0770 ;42.0000

P21=-83.1865 ;41.7500
P22=-83.2960 ;41.5000
P23=-83.3950 ;41.2500
P24=-83.4940 ;41.0000
P25=-83.5000 ;40.9870
P26=-83.6450 ;40.7435
P27=-83.7900 ;40.5000
P28=-84.0000 ;40.1420
P29=-84.1010 ;40.0000
P30=-84.2845 ;39.7500
P31=-84.4680 ;39.5000
P32=-84.5000 ;39.4590
P33=-84.7085 ;39.2295
P34=-84.9170 ;39.0000
P35=-85.0000 ;38.9150
P36=-85.2285 ;38.7075
P37=-85.4570 ;38.5000
P38=-85.5000 ;38.4660
P39=-85.7500 ;38.2925
P40=-86.0000 ;38.1190
P41=-86.1910 ;38.0000
P42=-86.5000 ;37.8480
P43=-86.7500 ;37.7415
P44=-87.0000 ;37.6350
P45=-87.3970 ;37.5000
P46=-87.5000 ;37.4770
P47=-88.0000 ;37.4120
P48=-88.5000 ;37.3930
P49=-89.0000 ;37.4170
P50=-89.5000 ;37.4760
P51=-89.6310 ;37.5000
P52=-90.0000 ;37.6220
P53=-90.2500 ;37.7200
P54=-90.5000 ;37.8180
P55=-90.8820 ;38.0000
P56=-91.0000 ;38.0790
P57=-91.2500 ;38.2685
P58=-91.5000 ;38.4580
P59=-91.5420 ;38.5000
P60=-91.7435 ;38.7500
P61=-91.9450 ;39.0000
P62=-92.0000 ;39.0850
P63=-92.1080 ;39.2925
P64=-92.2160 ;39.5000
P65=-92.3335 ;39.7500
P66=-92.4510 ;40.0000
P67=-92.5000 ;40.1520
P68=-92.5740 ;40.5000
P69=-92.6185 ;40.7500
P70=-92.6630 ;41.0000
P71=-92.6915 ;41.2500
P72=-92.7200 ;41.5000
P73=-92.7265 ;41.7500
P74=-92.7330 ;42.0000
P75=-92.7170 ;42.2500
P76=-92.7010 ;42.5000
P77=-92.6655 ;42.7500

P78=-92.6300 ;43.0000
P79=-92.5760 ;43.2500
P80=-92.5220 ;43.5000
P81=-92.5000 ;43.5770
P82=-92.4295 ;43.7885
P83=-92.3590 ;44.0000
P84=-92.2570 ;44.2500
P85=-92.1550 ;44.5000
P86=-92.0000 ;44.8110
P87=-91.8930 ;45.0000
P88=-91.7315 ;45.2500
P89=-91.5700 ;45.5000
P90=-91.5000 ;45.5930
P91=-91.3305 ;45.7965
P92=-91.1610 ;46.0000
P93=-91.0000 ;46.1680
P94=-90.6460 ;46.5000
P95=-90.5000 ;46.6190
P96=-90.2500 ;46.8000
P97=-90.0000 ;46.9810
P98=-89.9720 ;47.0000
P99=-89.5000 ;47.2630
P100=-89.0230 ;47.5000
P101=-89.0000 ;47.5090
P102=-88.5000 ;47.6820
P103=-88.0000 ;47.8320
P104=-87.5000 ;47.9600
P105=-87.2890 ;48.0000
P106=-87.0000 ;48.0370
P107=-86.5000 ;48.0810
P108=-86.0000 ;48.0950
P109=-85.5000 ;48.0710
P110=-85.0000 ;48.0030
P111=-84.9850 ;48.0000
P112=-84.5000 ;47.8530
P113=-84.0000 ;47.6430
P114=-83.7570 ;47.5000
P115=-83.5000 ;47.3060
P116=-83.1910 ;47.0000
P117=-83.0000 ;46.7260
[C10]
gain=-10.00
n_point=108
P1=-84.0000 ;45.1610
P2=-83.9440 ;45.0000
P3=-83.8885 ;44.7500
P4=-83.8330 ;44.5000
P5=-83.8210 ;44.2500
P6=-83.8090 ;44.0000
P7=-83.8190 ;43.7500
P8=-83.8290 ;43.5000
P9=-83.8655 ;43.2500
P10=-83.9020 ;43.0000
P11=-83.9510 ;42.7905
P12=-84.0000 ;42.5810
P13=-84.0220 ;42.5000
P14=-84.1100 ;42.2500

P15=-84.1980 ;42.0000
P16=-84.3030 ;41.7500
P17=-84.4080 ;41.5000
P18=-84.5000 ;41.3150
P19=-84.5915 ;41.1575
P20=-84.6830 ;41.0000
P21=-84.8380 ;40.7500
P22=-84.9930 ;40.5000
P23=-85.0000 ;40.4910
P24=-85.1970 ;40.2455
P25=-85.3940 ;40.0000
P26=-85.5000 ;39.8820
P27=-85.6945 ;39.6910
P28=-85.8890 ;39.5000
P29=-86.0000 ;39.4050
P30=-86.2500 ;39.2180
P31=-86.5000 ;39.0310
P32=-86.5510 ;39.0000
P33=-86.7755 ;38.8835
P34=-87.0000 ;38.7670
P35=-87.2500 ;38.6640
P36=-87.5000 ;38.5610
P37=-87.7220 ;38.5000
P38=-88.0000 ;38.4400
P39=-88.2500 ;38.4170
P40=-88.5000 ;38.3940
P41=-88.7500 ;38.4070
P42=-89.0000 ;38.4200
P43=-89.2130 ;38.4600
P44=-89.4260 ;38.5000
P45=-89.5000 ;38.5180
P46=-89.7500 ;38.6260
P47=-90.0000 ;38.7340
P48=-90.2140 ;38.8670
P49=-90.4280 ;39.0000
P50=-90.5000 ;39.0600
P51=-90.7095 ;39.2800
P52=-90.9190 ;39.5000
P53=-91.0000 ;39.6140
P54=-91.1060 ;39.8070
P55=-91.2120 ;40.0000
P56=-91.3145 ;40.2500
P57=-91.4170 ;40.5000
P58=-91.5000 ;40.8080
P59=-91.5410 ;41.0000
P60=-91.5630 ;41.2500
P61=-91.5850 ;41.5000
P62=-91.5770 ;41.7500
P63=-91.5690 ;42.0000
P64=-91.5365 ;42.2500
P65=-91.5040 ;42.5000
P66=-91.5000 ;42.5190
P67=-91.4360 ;42.7595
P68=-91.3720 ;43.0000
P69=-91.2820 ;43.2500
P70=-91.1920 ;43.5000
P71=-91.0960 ;43.7155

P72=-91.0000 ;43.9310
P73=-90.9640 ;44.0000
P74=-90.8045 ;44.2500
P75=-90.6450 ;44.5000
P76=-90.5000 ;44.6990
P77=-90.3730 ;44.8495
P78=-90.2460 ;45.0000
P79=-90.0000 ;45.2590
P80=-89.7370 ;45.5000
P81=-89.5000 ;45.6940
P82=-89.2835 ;45.8470
P83=-89.0670 ;46.0000
P84=-89.0000 ;46.0420
P85=-88.7500 ;46.1720
P86=-88.5000 ;46.3020
P87=-88.2690 ;46.4010
P88=-88.0380 ;46.5000
P89=-88.0000 ;46.5140
P90=-87.7500 ;46.5805
P91=-87.5000 ;46.6470
P92=-87.2500 ;46.6890
P93=-87.0000 ;46.7310
P94=-86.7500 ;46.7435
P95=-86.5000 ;46.7560
P96=-86.2500 ;46.7360
P97=-86.0000 ;46.7160
P98=-85.7500 ;46.6575
P99=-85.5000 ;46.5990
P100=-85.2510 ;46.5000
P101=-85.0000 ;46.3690
P102=-84.7585 ;46.1845
P103=-84.5170 ;46.0000
P104=-84.5000 ;45.9830
P105=-84.3285 ;45.7415
P106=-84.1570 ;45.5000
P107=-84.0785 ;45.3305
P108=-84.0000 ;45.1610
[C11]
gain=-6.00
n_point=89
P1=-85.0000 ;44.9640
P2=-84.8900 ;44.7320
P3=-84.7800 ;44.5000
P4=-84.7200 ;44.2500
P5=-84.6600 ;44.0000
P6=-84.6480 ;43.7500
P7=-84.6360 ;43.5000
P8=-84.6560 ;43.2500
P9=-84.6760 ;43.0000
P10=-84.7330 ;42.7500
P11=-84.7900 ;42.5000
P12=-84.8710 ;42.2500
P13=-84.9520 ;42.0000
P14=-85.0000 ;41.8820
P15=-85.0920 ;41.6910
P16=-85.1840 ;41.5000
P17=-85.2780 ;41.3333

P18=-85.3720 ;41.1667
P19=-85.4660 ;41.0000
P20=-85.5000 ;40.9500
P21=-85.6795 ;40.7250
P22=-85.8590 ;40.5000
P23=-86.0000 ;40.3420
P24=-86.1795 ;40.1710
P25=-86.3590 ;40.0000
P26=-86.5000 ;39.8830
P27=-86.7500 ;39.7105
P28=-87.0000 ;39.5380
P29=-87.0730 ;39.5000
P30=-87.2865 ;39.4085
P31=-87.5000 ;39.3170
P32=-87.7500 ;39.2480
P33=-88.0000 ;39.1790
P34=-88.2500 ;39.1565
P35=-88.5000 ;39.1340
P36=-88.7500 ;39.1610
P37=-89.0000 ;39.1880
P38=-89.2500 ;39.2710
P39=-89.5000 ;39.3540
P40=-89.7500 ;39.5000
P41=-89.8750 ;39.5970
P42=-90.0000 ;39.6940
P43=-90.1430 ;39.8470
P44=-90.2860 ;40.0000
P45=-90.3930 ;40.1615
P46=-90.5000 ;40.3230
P47=-90.5870 ;40.5000
P48=-90.6640 ;40.7500
P49=-90.7410 ;41.0000
P50=-90.7780 ;41.2500
P51=-90.8150 ;41.5000
P52=-90.8130 ;41.7500
P53=-90.8110 ;42.0000
P54=-90.7685 ;42.2500
P55=-90.7260 ;42.5000
P56=-90.6525 ;42.7500
P57=-90.5790 ;43.0000
P58=-90.5000 ;43.1970
P59=-90.4270 ;43.3485
P60=-90.3540 ;43.5000
P61=-90.2557 ;43.6667
P62=-90.1573 ;43.8333
P63=-90.0590 ;44.0000
P64=-90.0000 ;44.0830
P65=-89.8260 ;44.2915
P66=-89.6520 ;44.5000
P67=-89.5000 ;44.6590
P68=-89.3055 ;44.8295
P69=-89.1110 ;45.0000
P70=-89.0000 ;45.0850
P71=-88.7500 ;45.2425
P72=-88.5000 ;45.4000
P73=-88.2930 ;45.5000
P74=-88.0000 ;45.6230

P75=-87.7500 ;45.6960
P76=-87.5000 ;45.7690
P77=-87.2500 ;45.8050
P78=-87.0000 ;45.8410
P79=-86.7500 ;45.8340
P80=-86.5000 ;45.8270
P81=-86.2500 ;45.7705
P82=-86.0000 ;45.7140
P83=-85.7650 ;45.6070
P84=-85.5300 ;45.5000
P85=-85.5000 ;45.4810
P86=-85.3413 ;45.3207
P87=-85.1827 ;45.1603
P88=-85.0240 ;45.0000
P89=-85.0000 ;44.9640
[C12]
gain=-4.00
n_point=92
P1=-85.5000 ;44.5030
P2=-85.4980 ;44.5000
P3=-85.4243 ;44.3333
P4=-85.3507 ;44.1667
P5=-85.2770 ;44.0000
P6=-85.2517 ;43.8333
P7=-85.2263 ;43.6667
P8=-85.2010 ;43.5000
P9=-85.2050 ;43.3333
P10=-85.2090 ;43.1667
P11=-85.2130 ;43.0000
P12=-85.2423 ;42.8333
P13=-85.2717 ;42.6667
P14=-85.3010 ;42.5000
P15=-85.3553 ;42.3333
P16=-85.4097 ;42.1667
P17=-85.4640 ;42.0000
P18=-85.5000 ;41.9180
P19=-85.5730 ;41.7787
P20=-85.6460 ;41.6393
P21=-85.7190 ;41.5000
P22=-85.8127 ;41.3490
P23=-85.9063 ;41.1980
P24=-86.0000 ;41.0470
P25=-86.0350 ;41.0000
P26=-86.1840 ;40.8333
P27=-86.3330 ;40.6667
P28=-86.4820 ;40.5000
P29=-86.5000 ;40.4830
P30=-86.6667 ;40.3557
P31=-86.8333 ;40.2283
P32=-87.0000 ;40.1010
P33=-87.1770 ;40.0000
P34=-87.3385 ;39.9235
P35=-87.5000 ;39.8470
P36=-87.7500 ;39.7750
P37=-88.0000 ;39.7030
P38=-88.2500 ;39.6850
P39=-88.5000 ;39.6670

P40=-88.7500 ;39.7115
P41=-89.0000 ;39.7560
P42=-89.1667 ;39.8363
P43=-89.3333 ;39.9167
P44=-89.5000 ;39.9970
P45=-89.5040 ;40.0000
P46=-89.6607 ;40.1667
P47=-89.8173 ;40.3333
P48=-89.9740 ;40.5000
P49=-90.0000 ;40.5430
P50=-90.0633 ;40.6953
P51=-90.1267 ;40.8477
P52=-90.1900 ;41.0000
P53=-90.2227 ;41.1667
P54=-90.2553 ;41.3333
P55=-90.2880 ;41.5000
P56=-90.2900 ;41.6667
P57=-90.2920 ;41.8333
P58=-90.2940 ;42.0000
P59=-90.2663 ;42.1667
P60=-90.2387 ;42.3333
P61=-90.2110 ;42.5000
P62=-90.1577 ;42.6667
P63=-90.1043 ;42.8333
P64=-90.0510 ;43.0000
P65=-90.0000 ;43.1100
P66=-89.8905 ;43.3050
P67=-89.7810 ;43.5000
P68=-89.6873 ;43.6360
P69=-89.5937 ;43.7720
P70=-89.5000 ;43.9080
P71=-89.4220 ;44.0000
P72=-89.2813 ;44.1410
P73=-89.1407 ;44.2820
P74=-89.0000 ;44.4230
P75=-88.9030 ;44.5000
P76=-88.7015 ;44.6380
P77=-88.5000 ;44.7760
P78=-88.2850 ;44.8880
P79=-88.0700 ;45.0000
P80=-88.0000 ;45.0320
P81=-87.7500 ;45.1025
P82=-87.5000 ;45.1730
P83=-87.2500 ;45.1995
P84=-87.0000 ;45.2260
P85=-86.7500 ;45.2000
P86=-86.5000 ;45.1740
P87=-86.2625 ;45.0870
P88=-86.0250 ;45.0000
P89=-86.0000 ;44.9870
P90=-85.8333 ;44.8257
P91=-85.6667 ;44.6643
P92=-85.5000 ;44.5030
[C13]
gain=-2.00
n_point=87
P1=-86.0000 ;43.5310

P2=-85.9890 ;43.5000
P3=-85.9773 ;43.3750
P4=-85.9655 ;43.2500
P5=-85.9538 ;43.1250
P6=-85.9420 ;43.0000
P7=-85.9548 ;42.8750
P8=-85.9675 ;42.7500
P9=-85.9803 ;42.6250
P10=-85.9930 ;42.5000
P11=-86.0000 ;42.4760
P12=-86.0435 ;42.3570
P13=-86.0870 ;42.2380
P14=-86.1305 ;42.1190
P15=-86.1740 ;42.0000
P16=-86.2428 ;41.8750
P17=-86.3115 ;41.7500
P18=-86.3802 ;41.6250
P19=-86.4490 ;41.5000
P20=-86.5000 ;41.4290
P21=-86.5982 ;41.3218
P22=-86.6965 ;41.2145
P23=-86.7948 ;41.1073
P24=-86.8930 ;41.0000
P25=-87.0000 ;40.9050
P26=-87.1250 ;40.8248
P27=-87.2500 ;40.7445
P28=-87.3750 ;40.6642
P29=-87.5000 ;40.5840
P30=-87.6165 ;40.5420
P31=-87.7330 ;40.5000
P32=-87.8665 ;40.4615
P33=-88.0000 ;40.4230
P34=-88.1667 ;40.4220
P35=-88.3333 ;40.4210
P36=-88.5000 ;40.4200
P37=-88.6210 ;40.4600
P38=-88.7420 ;40.5000
P39=-88.8710 ;40.5660
P40=-89.0000 ;40.6320
P41=-89.1190 ;40.7547
P42=-89.2380 ;40.8773
P43=-89.3570 ;41.0000
P44=-89.4285 ;41.1430
P45=-89.5000 ;41.2860
P46=-89.5335 ;41.3930
P47=-89.5670 ;41.5000
P48=-89.5740 ;41.6250
P49=-89.5810 ;41.7500
P50=-89.5880 ;41.8750
P51=-89.5950 ;42.0000
P52=-89.5760 ;42.1250
P53=-89.5570 ;42.2500
P54=-89.5380 ;42.3750
P55=-89.5190 ;42.5000
P56=-89.5000 ;42.5530
P57=-89.4337 ;42.7020
P58=-89.3673 ;42.8510

P59=-89.3010 ;43.0000
P60=-89.2258 ;43.1205
P61=-89.1505 ;43.2410
P62=-89.0752 ;43.3615
P63=-89.0000 ;43.4820
P64=-88.9850 ;43.5000
P65=-88.8638 ;43.6127
P66=-88.7425 ;43.7255
P67=-88.6212 ;43.8382
P68=-88.5000 ;43.9510
P69=-88.4250 ;44.0000
P70=-88.2833 ;44.0750
P71=-88.1417 ;44.1500
P72=-88.0000 ;44.2250
P73=-87.8333 ;44.2767
P74=-87.6667 ;44.3283
P75=-87.5000 ;44.3800
P76=-87.3333 ;44.3800
P77=-87.1667 ;44.3800
P78=-87.0000 ;44.3800
P79=-86.8333 ;44.3143
P80=-86.6667 ;44.2487
P81=-86.5000 ;44.1830
P82=-86.3945 ;44.0915
P83=-86.2890 ;44.0000
P84=-86.2167 ;43.8828
P85=-86.1445 ;43.7655
P86=-86.0723 ;43.6483
P87=-86.0000 ;43.5310

[C14]

gain=-50.00

n_point=74

P1=-99.0000 ;25.7270
P2=-99.0570 ;25.8180
P3=-99.1140 ;25.9090
P4=-99.1710 ;26.0000
P5=-99.2533 ;26.0895
P6=-99.3355 ;26.1790
P7=-99.4178 ;26.2685
P8=-99.5000 ;26.3580
P9=-99.5450 ;26.4290
P10=-99.5900 ;26.5000
P11=-99.6720 ;26.5758
P12=-99.7540 ;26.6516
P13=-99.8360 ;26.7274
P14=-99.9180 ;26.8032
P15=-100.0000;26.8790
P16=-100.0965;26.9395
P17=-100.1930;27.0000
P18=-100.2544;27.0904
P19=-100.3158;27.1808
P20=-100.3772;27.2712
P21=-100.4386;27.3616
P22=-100.5000;27.4520
P23=-100.6080;27.5000
P24=-100.6676;27.6000
P25=-100.7272;27.7000

P26=-100.7868;27.8000
P27=-100.8464;27.9000
P28=-100.9060;28.0000
P29=-100.9530;28.0635
P30=-101.0000;28.1270
P31=-101.0823;28.0847
P32=-101.1647;28.0423
P33=-101.2470;28.0000
P34=-101.2220;27.9000
P35=-101.1970;27.8000
P36=-101.1720;27.7000
P37=-101.1470;27.6000
P38=-101.1220;27.5000
P39=-101.0610;27.4335
P40=-101.0000;27.3670
P41=-100.9355;27.2753
P42=-100.8710;27.1835
P43=-100.8065;27.0918
P44=-100.7420;27.0000
P45=-100.6613;26.9120
P46=-100.5807;26.8240
P47=-100.5000;26.7360
P48=-100.4480;26.6573
P49=-100.3960;26.5787
P50=-100.3440;26.5000
P51=-100.2580;26.4135
P52=-100.1720;26.3270
P53=-100.0860;26.2405
P54=-100.0000;26.1540
P55=-99.9257 ;26.1027
P56=-99.8513 ;26.0513
P57=-99.7770 ;26.0000
P58=-99.7077 ;25.9345
P59=-99.6385 ;25.8690
P60=-99.5693 ;25.8035
P61=-99.5000 ;25.7380
P62=-99.4155 ;25.6785
P63=-99.3310 ;25.6190
P64=-99.2465 ;25.5595
P65=-99.1620 ;25.5000
P66=-99.0810 ;25.4275
P67=-99.0000 ;25.3550
P68=-98.8840 ;25.4033
P69=-98.7680 ;25.4517
P70=-98.6520 ;25.5000
P71=-98.7390 ;25.5568
P72=-98.8260 ;25.6135
P73=-98.9130 ;25.6702
P74=-99.0000 ;25.7270
[C15]
gain=-50.00
n_point=195
P1=-60.5000 ;58.2200
P2=-60.7060 ;58.0000
P3=-61.0000 ;57.6200
P4=-61.1510 ;57.5000
P5=-61.5000 ;57.2180

P6=-61.6580 ;57.0000
P7=-62.0000 ;56.6810
P8=-62.1590 ;56.5000
P9=-62.5000 ;56.0920
P10=-62.5860 ;56.0000
P11=-63.0000 ;55.5020
P12=-63.0020 ;55.5000
P13=-63.4360 ;55.0000
P14=-63.5000 ;54.8640
P15=-63.7170 ;54.5000
P16=-64.0000 ;54.2570
P17=-64.1860 ;54.0000
P18=-64.5000 ;53.5860
P19=-64.5690 ;53.5000
P20=-64.8180 ;53.0000
P21=-65.0000 ;52.8110
P22=-65.1980 ;52.5000
P23=-65.5000 ;52.1600
P24=-65.6240 ;52.0000
P25=-65.8030 ;51.5000
P26=-66.0000 ;51.2850
P27=-66.1990 ;51.0000
P28=-66.5000 ;50.6510
P29=-66.6180 ;50.5000
P30=-66.9530 ;50.0000
P31=-67.0000 ;49.8970
P32=-67.2560 ;49.5000
P33=-67.5000 ;49.0550
P34=-67.5390 ;49.0000
P35=-67.9180 ;48.5000
P36=-68.0000 ;48.4190
P37=-68.3670 ;48.0000
P38=-68.5000 ;47.7240
P39=-68.6870 ;47.5000
P40=-68.9610 ;47.0000
P41=-69.0000 ;46.9370
P42=-69.3460 ;46.5000
P43=-69.5000 ;46.2440
P44=-69.7000 ;46.0000
P45=-69.9760 ;45.5000
P46=-70.0000 ;45.4740
P47=-70.3300 ;45.0000
P48=-70.5000 ;44.7620
P49=-70.7260 ;44.5000
P50=-71.0000 ;44.0770
P51=-71.0630 ;44.0000
P52=-71.4020 ;43.5000
P53=-71.5000 ;43.3520
P54=-71.7910 ;43.0000
P55=-72.0000 ;42.6140
P56=-72.0830 ;42.5000
P57=-72.4490 ;42.0000
P58=-72.5000 ;41.9180
P59=-72.8410 ;41.5000
P60=-73.0000 ;41.2740
P61=-73.2250 ;41.0000
P62=-73.5000 ;40.6050

P63=-73.5860 ;40.5000
P64=-73.9420 ;40.0000
P65=-74.0000 ;39.9080
P66=-74.3430 ;39.5000
P67=-74.5000 ;39.2480
P68=-74.7140 ;39.0000
P69=-75.0000 ;38.5750
P70=-75.0630 ;38.5000
P71=-75.4700 ;38.0000
P72=-75.5000 ;37.9630
P73=-75.8840 ;37.5000
P74=-76.0000 ;37.3380
P75=-76.2960 ;37.0000
P76=-76.5000 ;36.7830
P77=-76.7740 ;36.5000
P78=-77.0000 ;36.2630
P79=-77.2490 ;36.0000
P80=-77.5000 ;35.7180
P81=-77.7030 ;35.5000
P82=-78.0000 ;35.2000
P83=-78.1910 ;35.0000
P84=-78.5000 ;34.7030
P85=-78.7080 ;34.5000
P86=-79.0000 ;34.2110
P87=-79.2130 ;34.0000
P88=-79.5000 ;33.7000
P89=-79.6950 ;33.5000
P90=-80.0000 ;33.1820
P91=-80.1770 ;33.0000
P92=-80.5000 ;32.6650
P93=-80.6680 ;32.5000
P94=-81.0000 ;32.1370
P95=-81.1340 ;32.0000
P96=-81.5000 ;31.5830
P97=-81.5760 ;31.5000
P98=-81.5000 ;31.1580
P99=-81.0000 ;31.3770
P100=-80.8340 ;31.5000
P101=-80.5000 ;31.7220
P102=-80.0980 ;32.0000
P103=-80.0000 ;32.0590
P104=-79.5000 ;32.3750
P105=-79.3330 ;32.5000
P106=-79.0000 ;32.7260
P107=-78.6710 ;33.0000
P108=-78.5000 ;33.1380
P109=-78.1090 ;33.5000
P110=-78.0000 ;33.6070
P111=-77.6060 ;34.0000
P112=-77.5000 ;34.1160
P113=-77.1430 ;34.5000
P114=-77.0000 ;34.6610
P115=-76.6990 ;35.0000
P116=-76.5000 ;35.2460
P117=-76.2730 ;35.5000
P118=-76.0000 ;35.8500
P119=-75.8650 ;36.0000

P120=-75.5000 ;36.4490
P121=-75.4540 ;36.5000
P122=-75.0000 ;36.9950
P123=-74.9950 ;37.0000
P124=-74.5580 ;37.5000
P125=-74.5000 ;37.5710
P126=-74.1330 ;38.0000
P127=-74.0000 ;38.1480
P128=-73.6720 ;38.5000
P129=-73.5000 ;38.7370
P130=-73.2710 ;39.0000
P131=-73.0000 ;39.3350
P132=-72.8440 ;39.5000
P133=-72.5510 ;40.0000
P134=-72.5000 ;40.0700
P135=-72.1350 ;40.5000
P136=-72.0000 ;40.7760
P137=-71.8390 ;41.0000
P138=-71.5000 ;41.4850
P139=-71.4860 ;41.5000
P140=-71.0890 ;42.0000
P141=-71.0000 ;42.1480
P142=-70.7310 ;42.5000
P143=-70.5000 ;42.8990
P144=-70.4240 ;43.0000
P145=-70.1370 ;43.5000
P146=-70.0000 ;43.6910
P147=-69.7560 ;44.0000
P148=-69.5000 ;44.3660
P149=-69.3870 ;44.5000
P150=-69.0640 ;45.0000
P151=-69.0000 ;45.0850
P152=-68.6910 ;45.5000
P153=-68.5000 ;45.8180
P154=-68.3600 ;46.0000
P155=-68.0750 ;46.5000
P156=-68.0000 ;46.6100
P157=-67.7270 ;47.0000
P158=-67.5000 ;47.3630
P159=-67.3990 ;47.5000
P160=-67.0150 ;48.0000
P161=-67.0000 ;48.0250
P162=-66.5830 ;48.5000
P163=-66.5000 ;48.6720
P164=-66.2370 ;49.0000
P165=-66.0050 ;49.5000
P166=-66.0000 ;49.5070
P167=-65.7190 ;50.0000
P168=-65.5000 ;50.2930
P169=-65.3500 ;50.5000
P170=-65.0100 ;51.0000
P171=-65.0000 ;51.0220
P172=-64.6470 ;51.5000
P173=-64.5000 ;51.8160
P174=-64.3740 ;52.0000
P175=-64.0530 ;52.5000
P176=-64.0000 ;52.5730

P177=-63.6440 ;53.0000
P178=-63.5000 ;53.4110
P179=-63.4450 ;53.5000
P180=-63.0230 ;54.0000
P181=-63.0000 ;54.0340
P182=-62.5550 ;54.5000
P183=-62.5000 ;54.7230
P184=-62.3780 ;55.0000
P185=-62.0000 ;55.2580
P186=-61.8010 ;55.5000
P187=-61.5000 ;55.8750
P188=-61.3960 ;56.0000
P189=-61.2710 ;56.5000
P190=-61.0000 ;56.6360
P191=-60.6680 ;57.0000
P192=-60.5000 ;57.3500
P193=-60.3470 ;57.5000
P194=-60.0990 ;58.0000
P195=-60.5000 ;58.2200

[C16]

gain=-15.00

n_point=110

P1=-89.4131 ;46.5478
P2=-89.5593 ;46.4572
P3=-89.6996 ;46.3665
P4=-89.9961 ;46.1333
P5=-90.2926 ;45.9001
P6=-90.4879 ;45.7072
P7=-90.6831 ;45.5142
P8=-90.9088 ;45.2484
P9=-91.1217 ;44.9441
P10=-91.3346 ;44.6398
P11=-91.4143 ;44.5064
P12=-91.4416 ;44.4575
P13=-91.4978 ;44.3570
P14=-91.6507 ;44.0096
P15=-91.8036 ;43.6623
P16=-91.8976 ;43.3861
P17=-91.9494 ;43.1963
P18=-92.0011 ;43.0064
P19=-92.0624 ;42.7090
P20=-92.0919 ;42.5080
P21=-92.1213 ;42.3071
P22=-92.1359 ;42.1019
P23=-92.1505 ;41.8967
P24=-92.1503 ;41.6063
P25=-92.1374 ;41.4137
P26=-92.1245 ;41.2211
P27=-92.0876 ;40.9374
P28=-92.0050 ;40.5772
P29=-91.9223 ;40.2169
P30=-91.8831 ;40.1282
P31=-91.8679 ;40.0941
P32=-91.8348 ;40.0192
P33=-91.6691 ;39.6881
P34=-91.5034 ;39.3570
P35=-91.3748 ;39.1888

P36=-91.2463 ;39.0207
P37=-90.9719 ;38.7486
P38=-90.6833 ;38.5164
P39=-90.4714 ;38.3969
P40=-90.2595 ;38.2773
P41=-89.9434 ;38.1534
P42=-89.6272 ;38.0295
P43=-89.4519 ;37.9829
P44=-89.3411 ;37.9622
P45=-88.9860 ;37.9438
P46=-88.6308 ;37.9255
P47=-88.2757 ;37.9072
P48=-88.1748 ;37.9135
P49=-88.0449 ;37.9215
P50=-87.6484 ;38.0116
P51=-87.2520 ;38.1018
P52=-86.8403 ;38.2691
P53=-86.6239 ;38.3741
P54=-86.4074 ;38.4792
P55=-86.1755 ;38.6366
P56=-85.9436 ;38.7941
P57=-85.6862 ;38.9865
P58=-85.3946 ;39.2575
P59=-85.2289 ;39.4282
P60=-85.0632 ;39.5989
P61=-84.8751 ;39.8170
P62=-84.6961 ;40.0566
P63=-84.5170 ;40.2963
P64=-84.4356 ;40.4176
P65=-84.3042 ;40.6370
P66=-84.1728 ;40.8563
P67=-84.0422 ;41.0785
P68=-83.9324 ;41.3280
P69=-83.8225 ;41.5775
P70=-83.7127 ;41.8270
P71=-83.6785 ;41.9068
P72=-83.6560 ;41.9626
P73=-83.5751 ;42.1873
P74=-83.4942 ;42.4120
P75=-83.4272 ;42.6806
P76=-83.3602 ;42.9492
P77=-83.3115 ;43.2119
P78=-83.2629 ;43.4746
P79=-83.2142 ;43.7373
P80=-83.1923 ;44.0065
P81=-83.1879 ;44.0735
P82=-83.1941 ;44.3545
P83=-83.2004 ;44.6355
P84=-83.2066 ;44.9165
P85=-83.2402 ;45.1194
P86=-83.2868 ;45.3245
P87=-83.3333 ;45.5296
P88=-83.4051 ;45.7150
P89=-83.5404 ;45.9725
P90=-83.6757 ;46.2301
P91=-83.7973 ;46.4024
P92=-83.9692 ;46.5969

P93=-84.2014 ;46.7720
P94=-84.4337 ;46.9470
P95=-84.7280 ;47.0829
P96=-85.0223 ;47.2188
P97=-85.2452 ;47.2873
P98=-85.3723 ;47.3197
P99=-85.7654 ;47.3492
P100=-86.1585 ;47.3787
P101=-86.5516 ;47.4082
P102=-86.6604 ;47.4039
P103=-86.8086 ;47.3934
P104=-87.2644 ;47.3169
P105=-87.7201 ;47.2405
P106=-88.1515 ;47.1179
P107=-88.4306 ;47.0135
P108=-88.7097 ;46.9091
P109=-89.0614 ;46.7284
P110=-89.4131 ;46.5478

[C17]

gain=-8.00

n_point=97

P1=-89.1594 ;45.4504
P2=-89.3325 ;45.3134
P3=-89.5056 ;45.1764
P4=-89.7197 ;44.9702
P5=-89.9338 ;44.7640
P6=-90.1284 ;44.5343
P7=-90.2285 ;44.4110
P8=-90.3431 ;44.2448
P9=-90.4578 ;44.0787
P10=-90.5457 ;43.9333
P11=-90.6336 ;43.7879
P12=-90.7378 ;43.5682
P13=-90.8421 ;43.3485
P14=-90.9200 ;43.1354
P15=-90.9979 ;42.9223
P16=-91.0694 ;42.6664
P17=-91.1091 ;42.4703
P18=-91.1489 ;42.2741
P19=-91.1712 ;42.0912
P20=-91.1935 ;41.9082
P21=-91.1964 ;41.7437
P22=-91.1993 ;41.5792
P23=-91.1842 ;41.3841
P24=-91.1690 ;41.1890
P25=-91.1142 ;40.9357
P26=-91.0595 ;40.6825
P27=-91.0092 ;40.5439
P28=-90.9143 ;40.3177
P29=-90.8194 ;40.0915
P30=-90.7238 ;39.9300
P31=-90.5586 ;39.7008
P32=-90.3733 ;39.5126
P33=-90.1880 ;39.3245
P34=-89.9725 ;39.2026
P35=-89.7569 ;39.0807
P36=-89.5413 ;38.9589

P37=-89.4034 ;38.9056
P38=-89.3484 ;38.8844
P39=-89.2409 ;38.8537
P40=-88.8933 ;38.8324
P41=-88.5456 ;38.8112
P42=-88.1980 ;38.7900
P43=-88.0617 ;38.8024
P44=-87.9693 ;38.8169
P45=-87.7078 ;38.8804
P46=-87.3799 ;39.0032
P47=-87.0519 ;39.1259
P48=-86.8700 ;39.2285
P49=-86.6881 ;39.3312
P50=-86.4946 ;39.4690
P51=-86.3012 ;39.6069
P52=-86.1455 ;39.7423
P53=-85.9898 ;39.8777
P54=-85.8267 ;40.0426
P55=-85.6635 ;40.2075
P56=-85.4889 ;40.4375
P57=-85.3143 ;40.6676
P58=-85.1397 ;40.8977
P59=-85.1119 ;40.9443
P60=-84.9701 ;41.2085
P61=-84.8282 ;41.4726
P62=-84.6863 ;41.7368
P63=-84.5924 ;41.9620
P64=-84.5393 ;42.1136
P65=-84.4861 ;42.2652
P66=-84.4246 ;42.4739
P67=-84.3630 ;42.6826
P68=-84.3255 ;42.8535
P69=-84.2879 ;43.0244
P70=-84.2677 ;43.1879
P71=-84.2474 ;43.3515
P72=-84.2382 ;43.5921
P73=-84.2289 ;43.8327
P74=-84.2420 ;44.1032
P75=-84.2565 ;44.2772
P76=-84.3156 ;44.5264
P77=-84.3748 ;44.7757
P78=-84.5005 ;45.0566
P79=-84.5754 ;45.2059
P80=-84.7785 ;45.4489
P81=-84.9815 ;45.6920
P82=-85.2462 ;45.8708
P83=-85.5108 ;46.0496
P84=-85.7574 ;46.1538
P85=-86.0775 ;46.1994
P86=-86.3977 ;46.2451
P87=-86.7178 ;46.2907
P88=-86.8793 ;46.2881
P89=-87.0993 ;46.2687
P90=-87.4762 ;46.1881
P91=-87.8531 ;46.1075
P92=-88.1064 ;46.0110
P93=-88.3597 ;45.9144

P94=-88.5574 ;45.8121
P95=-88.7551 ;45.7098
P96=-88.9573 ;45.5801
P97=-89.1594 ;45.4504