

```
[FormatInfo]
format_ver=1
[GeoMain]
ntc_id=910100000
adm=USA
sat_name=USABSS-21
long_nom=-101.0000
n_diag=1
[COHeader]
beam_id=RB25
emi_rcp=E
polar_disc=C
reason=B
n_bore=1
n_cont=24
[B1]
gain=0.00
p=-98.0090;28.9930
[C1]
gain=-50.00
n_point=527
P1=-158.2720;73.4980
P2=-158.0000;73.4490
P3=-157.5000;73.3820
P4=-157.0000;73.3060
P5=-156.5000;73.2140
P6=-156.0000;73.0970
P7=-155.6680;73.0000
P8=-155.5000;72.9650
P9=-155.0000;72.8740
P10=-154.5000;72.7840
P11=-154.0000;72.6730
P12=-153.5000;72.5260
P13=-153.4270;72.5000
P14=-153.0000;72.3890
P15=-152.5000;72.2850
P16=-152.0000;72.1670
P17=-151.5000;72.0040
P18=-151.4890;72.0000
P19=-151.0000;71.8530
P20=-150.5000;71.7130
P21=-150.0000;71.5660
P22=-149.8280;71.5000
P23=-149.5000;71.4010
P24=-149.0000;71.2020
P25=-148.5000;71.0250
P26=-148.4370;71.0000
P27=-148.0000;70.8800
P28=-147.5000;70.6730
P29=-147.1430;70.5000
P30=-147.0000;70.4450
P31=-146.5000;70.2890
P32=-146.0000;70.0550
P33=-145.8920;70.0000
P34=-145.5000;69.8200
P35=-145.0000;69.6150
P36=-144.8020;69.5000
```

P37=-144.5000;69.3410
P38=-144.0000;69.0400
P39=-143.9300;69.0000
P40=-143.5000;68.8200
P41=-143.0480;68.5000
P42=-143.0000;68.4710
P43=-142.5000;68.2340
P44=-142.1480;68.0000
P45=-142.0000;67.9030
P46=-141.5000;67.5440
P47=-141.4400;67.5000
P48=-141.0000;67.2370
P49=-140.7110;67.0000
P50=-140.5000;66.8460
P51=-140.0190;66.5000
P52=-140.0000;66.4860
P53=-139.5000;66.0200
P54=-139.4770;66.0000
P55=-139.0000;65.6370
P56=-138.8500;65.5000
P57=-138.5000;65.1470
P58=-138.3620;65.0000
P59=-138.0000;64.5800
P60=-137.9250;64.5000
P61=-137.5000;64.0090
P62=-137.4930;64.0000
P63=-137.1280;63.5000
P64=-137.0000;63.3170
P65=-136.7760;63.0000
P66=-136.5000;62.5540
P67=-136.4610;62.5000
P68=-136.0860;62.0000
P69=-136.0000;61.8760
P70=-135.7240;61.5000
P71=-135.5000;61.1630
P72=-135.3900;61.0000
P73=-135.0530;60.5000
P74=-135.0000;60.4040
P75=-134.7770;60.0000
P76=-134.5200;59.5000
P77=-134.5000;59.4470
P78=-134.3200;59.0000
P79=-134.1710;58.5000
P80=-134.0170;58.0000
P81=-134.0000;57.9290
P82=-133.8930;57.5000
P83=-133.8120;57.0000
P84=-133.8040;56.5000
P85=-134.0000;56.0170
P86=-134.0220;56.0000
P87=-134.5000;55.7710
P88=-135.0000;55.8130
P89=-135.5000;55.9030
P90=-135.9500;55.5000
P91=-135.7980;55.0000
P92=-135.6340;54.5000
P93=-135.5000;54.0780

P94=-135.4750;54.0000
P95=-135.2690;53.5000
P96=-135.0900;53.0000
P97=-135.0000;52.7290
P98=-134.9230;52.5000
P99=-134.7720;52.0000
P100=-134.6380;51.5000
P101=-134.5170;51.0000
P102=-134.5000;50.9520
P103=-134.3230;50.5000
P104=-134.1580;50.0000
P105=-134.0310;49.5000
P106=-134.0000;49.3640
P107=-133.8990;49.0000
P108=-133.7680;48.5000
P109=-133.6070;48.0000
P110=-133.5000;47.5990
P111=-133.4620;47.5000
P112=-133.2980;47.0000
P113=-133.1800;46.5000
P114=-133.0360;46.0000
P115=-133.0000;45.8350
P116=-132.8750;45.5000
P117=-132.7690;45.0000
P118=-132.6120;44.5000
P119=-132.5050;44.0000
P120=-132.5000;43.9720
P121=-132.3700;43.5000
P122=-132.2120;43.0000
P123=-132.0870;42.5000
P124=-132.0210;42.0000
P125=-132.0000;41.9150
P126=-131.8330;41.5000
P127=-131.7120;41.0000
P128=-131.6100;40.5000
P129=-131.5000;40.0440
P130=-131.4830;40.0000
P131=-131.3700;39.5000
P132=-131.2160;39.0000
P133=-131.1390;38.5000
P134=-131.0000;38.0510
P135=-130.9830;38.0000
P136=-130.8490;37.5000
P137=-130.7090;37.0000
P138=-130.6330;36.5000
P139=-130.5000;36.1530
P140=-130.4550;36.0000
P141=-130.3640;35.5000
P142=-130.2320;35.0000
P143=-130.2350;34.5000
P144=-130.0090;34.0000
P145=-130.5000;33.8500
P146=-130.5650;34.0000
P147=-130.6740;34.5000
P148=-130.9590;35.0000
P149=-131.0000;35.0840
P150=-131.1150;35.5000

P151=-131.3150;36.0000
P152=-131.5000;36.4900
P153=-131.5040;36.5000
P154=-131.7080;37.0000
P155=-131.8510;37.5000
P156=-132.0000;37.9010
P157=-132.0350;38.0000
P158=-132.2490;38.5000
P159=-132.3860;39.0000
P160=-132.5000;39.2920
P161=-132.5880;39.5000
P162=-132.7810;40.0000
P163=-132.9010;40.5000
P164=-133.0000;40.7980
P165=-133.0970;41.0000
P166=-133.2780;41.5000
P167=-133.3910;42.0000
P168=-133.5000;42.3830
P169=-133.5550;42.5000
P170=-133.7560;43.0000
P171=-133.8580;43.5000
P172=-134.0000;43.9800
P173=-134.0100;44.0000
P174=-134.2420;44.5000
P175=-134.3630;45.0000
P176=-134.4950;45.5000
P177=-134.5000;45.5160
P178=-134.7540;46.0000
P179=-134.9270;46.5000
P180=-135.0000;46.7580
P181=-135.1080;47.0000
P182=-135.3010;47.5000
P183=-135.4970;48.0000
P184=-135.5000;48.0090
P185=-135.7570;48.5000
P186=-135.9550;49.0000
P187=-136.0000;49.1140
P188=-136.1910;49.5000
P189=-136.4060;50.0000
P190=-136.5000;50.2380
P191=-136.6370;50.5000
P192=-136.8800;51.0000
P193=-137.0000;51.2450
P194=-137.1550;51.5000
P195=-137.4210;52.0000
P196=-137.5000;52.1540
P197=-137.7030;52.5000
P198=-137.9760;53.0000
P199=-138.0000;53.0450
P200=-138.2600;53.5000
P201=-138.5000;53.8910
P202=-138.5760;54.0000
P203=-138.9030;54.5000
P204=-139.0000;54.6490
P205=-139.2460;55.0000
P206=-139.5000;55.3560
P207=-139.6200;55.5000

P208=-140.0000;55.9840
P209=-140.0150;56.0000
P210=-140.4150;56.5000
P211=-140.5000;56.6340
P212=-140.8050;57.0000
P213=-141.0000;57.2470
P214=-141.2660;57.5000
P215=-141.5000;57.7440
P216=-141.7550;58.0000
P217=-142.0000;58.2820
P218=-142.2920;58.5000
P219=-142.5000;58.6690
P220=-143.0000;58.9250
P221=-143.1220;59.0000
P222=-143.5000;59.2950
P223=-143.9730;59.5000
P224=-144.0000;59.5130
P225=-144.5000;59.7940
P226=-145.0000;59.9870
P227=-145.0280;60.0000
P228=-145.5000;60.2440
P229=-146.0000;60.4350
P230=-146.1560;60.5000
P231=-146.5000;60.6560
P232=-147.0000;60.8300
P233=-147.4340;61.0000
P234=-147.5000;61.0280
P235=-148.0000;61.1900
P236=-148.5000;61.3540
P237=-148.9250;61.5000
P238=-149.0000;61.5240
P239=-149.5000;61.6190
P240=-150.0000;61.7590
P241=-150.5000;61.5390
P242=-150.5360;61.5000
P243=-150.5000;61.4840
P244=-150.1390;61.0000
P245=-150.0000;60.8900
P246=-149.6140;60.5000
P247=-149.5000;60.4130
P248=-149.0530;60.0000
P249=-149.0000;59.9640
P250=-148.5400;59.5000
P251=-148.5000;59.4670
P252=-148.0000;59.1150
P253=-147.9010;59.0000
P254=-147.5000;58.6170
P255=-147.3630;58.5000
P256=-147.0000;58.2640
P257=-146.7400;58.0000
P258=-146.5000;57.7760
P259=-146.1850;57.5000
P260=-146.0000;57.3550
P261=-145.6570;57.0000
P262=-145.5000;56.8400
P263=-145.1710;56.5000
P264=-145.0000;56.3190

P265=-144.7180;56.0000
P266=-144.5000;55.7590
P267=-144.3000;55.5000
P268=-144.0000;55.1010
P269=-143.9130;55.0000
P270=-143.5090;54.5000
P271=-143.5000;54.4890
P272=-143.1110;54.0000
P273=-143.0000;53.8580
P274=-142.7350;53.5000
P275=-142.5000;53.1360
P276=-142.4100;53.0000
P277=-142.0970;52.5000
P278=-142.0000;52.3270
P279=-141.7820;52.0000
P280=-141.5190;51.5000
P281=-141.5000;51.4670
P282=-141.1660;51.0000
P283=-141.0000;50.6500
P284=-140.9110;50.5000
P285=-140.6070;50.0000
P286=-140.5000;49.7440
P287=-140.3670;49.5000
P288=-140.0990;49.0000
P289=-140.0000;48.7770
P290=-139.8380;48.5000
P291=-139.5770;48.0000
P292=-139.5000;47.8310
P293=-139.2970;47.5000
P294=-139.0450;47.0000
P295=-139.0000;46.8910
P296=-138.7670;46.5000
P297=-138.5390;46.0000
P298=-138.5000;45.9020
P299=-138.2670;45.5000
P300=-138.0700;45.0000
P301=-138.0000;44.8170
P302=-137.8410;44.5000
P303=-137.5780;44.0000
P304=-137.5000;43.7990
P305=-137.3250;43.5000
P306=-137.0970;43.0000
P307=-137.0000;42.6710
P308=-136.9190;42.5000
P309=-136.6760;42.0000
P310=-136.5000;41.5380
P311=-136.4790;41.5000
P312=-136.2350;41.0000
P313=-136.0830;40.5000
P314=-136.0000;40.2850
P315=-135.8430;40.0000
P316=-135.6500;39.5000
P317=-135.5190;39.0000
P318=-135.5000;38.9520
P319=-135.2660;38.5000
P320=-135.1020;38.0000
P321=-135.0000;37.6920

P322=-134.9220;37.5000
P323=-134.6940;37.0000
P324=-134.5570;36.5000
P325=-134.5000;36.3680
P326=-134.3290;36.0000
P327=-134.1630;35.5000
P328=-134.0000;35.0350
P329=-133.9850;35.0000
P330=-133.7740;34.5000
P331=-133.6260;34.0000
P332=-133.5000;33.6420
P333=-133.4350;33.5000
P334=-133.2730;33.0000
P335=-133.1310;32.5000
P336=-133.0000;32.0720
P337=-132.9770;32.0000
P338=-132.8330;31.5000
P339=-132.7060;31.0000
P340=-132.6060;30.5000
P341=-132.5000;30.2610
P342=-132.4260;30.0000
P343=-132.3670;29.5000
P344=-132.2390;29.0000
P345=-132.1690;28.5000
P346=-132.0000;28.2320
P347=-131.9410;28.0000
P348=-131.8280;27.5000
P349=-131.8290;27.0000
P350=-131.5000;26.6570
P351=-131.4450;26.5000
P352=-131.3370;26.0000
P353=-131.2780;25.5000
P354=-131.0000;25.2530
P355=-130.9140;25.0000
P356=-130.8040;24.5000
P357=-130.7170;24.0000
P358=-130.5000;23.7220
P359=-130.4400;23.5000
P360=-130.3410;23.0000
P361=-130.3360;22.5000
P362=-130.3210;22.0000
P363=-130.5000;21.8270
P364=-130.5390;22.0000
P365=-130.6130;22.5000
P366=-130.7590;23.0000
P367=-131.0000;23.3800
P368=-131.0370;23.5000
P369=-131.1040;24.0000
P370=-131.2220;24.5000
P371=-131.4700;25.0000
P372=-131.5000;25.0380
P373=-131.5710;25.5000
P374=-131.6910;26.0000
P375=-132.0000;26.4980
P376=-132.0010;26.5000
P377=-132.0720;27.0000
P378=-132.2400;27.5000

P379=-132.5000;27.9520
P380=-132.5160;28.0000
P381=-132.6530;28.5000
P382=-132.8460;29.0000
P383=-133.0000;29.3080
P384=-133.0600;29.5000
P385=-133.2580;30.0000
P386=-133.4030;30.5000
P387=-133.5000;30.6450
P388=-133.6440;31.0000
P389=-133.7810;31.5000
P390=-134.0000;31.9930
P391=-134.0030;32.0000
P392=-134.1890;32.5000
P393=-134.3890;33.0000
P394=-134.5000;33.2960
P395=-134.5900;33.5000
P396=-134.8050;34.0000
P397=-134.9910;34.5000
P398=-135.0000;34.5180
P399=-135.2130;35.0000
P400=-135.4230;35.5000
P401=-135.5000;35.7030
P402=-135.6370;36.0000
P403=-135.8710;36.5000
P404=-136.0000;36.8320
P405=-136.0910;37.0000
P406=-136.2940;37.5000
P407=-136.5000;37.9660
P408=-136.5210;38.0000
P409=-136.7860;38.5000
P410=-136.9570;39.0000
P411=-137.0000;39.0970
P412=-137.2490;39.5000
P413=-137.4610;40.0000
P414=-137.5000;40.1010
P415=-137.7110;40.5000
P416=-137.9340;41.0000
P417=-138.0000;41.1480
P418=-138.2250;41.5000
P419=-138.4550;42.0000
P420=-138.5000;42.1210
P421=-138.7140;42.5000
P422=-138.9200;43.0000
P423=-139.0000;43.1720
P424=-139.2110;43.5000
P425=-139.4730;44.0000
P426=-139.5000;44.0620
P427=-139.7890;44.5000
P428=-140.0000;44.9610
P429=-140.0250;45.0000
P430=-140.3430;45.5000
P431=-140.5000;45.8380
P432=-140.6070;46.0000
P433=-140.8960;46.5000
P434=-141.0000;46.6990
P435=-141.2010;47.0000

P436=-141.4900;47.5000
P437=-141.5000;47.5200
P438=-141.8450;48.0000
P439=-142.0000;48.2750
P440=-142.1640;48.5000
P441=-142.5000;49.0000
P442=-142.8760;49.5000
P443=-143.0000;49.6750
P444=-143.2500;50.0000
P445=-143.5000;50.3600
P446=-143.6120;50.5000
P447=-143.9860;51.0000
P448=-144.0000;51.0190
P449=-144.3960;51.5000
P450=-144.5000;51.6410
P451=-144.8190;52.0000
P452=-145.0000;52.2340
P453=-145.2600;52.5000
P454=-145.5000;52.7410
P455=-145.7430;53.0000
P456=-146.0000;53.2790
P457=-146.2110;53.5000
P458=-146.5000;53.8230
P459=-146.6990;54.0000
P460=-147.0000;54.2600
P461=-147.2370;54.5000
P462=-147.5000;54.7520
P463=-147.8030;55.0000
P464=-148.0000;55.1500
P465=-148.4190;55.5000
P466=-148.5000;55.5660
P467=-149.0000;55.9650
P468=-149.0470;56.0000
P469=-149.5000;56.3090
P470=-149.7600;56.5000
P471=-150.0000;56.6650
P472=-150.4830;57.0000
P473=-150.5000;57.0120
P474=-151.0000;57.3370
P475=-151.2430;57.5000
P476=-151.5000;57.6570
P477=-152.0000;57.9500
P478=-152.0750;58.0000
P479=-152.5000;58.2710
P480=-152.9170;58.5000
P481=-153.0000;58.5390
P482=-153.5000;58.8150
P483=-153.8560;59.0000
P484=-154.0000;59.0710
P485=-154.5000;59.3060
P486=-154.8200;59.5000
P487=-155.0000;59.5920
P488=-155.5000;59.7860
P489=-155.9600;60.0000
P490=-156.0000;60.0170
P491=-156.5000;60.2400
P492=-157.0000;60.4420

P493=-157.1270;60.5000
P494=-157.5000;60.6370
P495=-158.0000;60.8370
P496=-158.4400;61.0000
P497=-158.5000;61.0210
P498=-159.0000;61.1830
P499=-159.5000;61.3760
P500=-159.8270;61.5000
P501=-160.0000;61.5560
P502=-160.5000;61.6860
P503=-161.0000;61.8400
P504=-161.4390;62.0000
P505=-161.5000;62.0190
P506=-162.0000;62.1560
P507=-162.5000;62.2810
P508=-163.0000;62.4190
P509=-163.2640;62.5000
P510=-163.5000;62.5620
P511=-164.0000;62.6890
P512=-164.5000;62.8060
P513=-165.0000;62.9220
P514=-165.3040;63.0000
P515=-165.5000;63.0400
P516=-166.0000;63.1500
P517=-166.5000;63.2510
P518=-167.0000;63.3540
P519=-167.5000;63.4570
P520=-167.6920;63.5000
P521=-168.0000;63.5520
P522=-168.5000;63.6370
P523=-169.0000;63.7250
P524=-169.5000;63.8040
P525=-170.0000;63.8850
P526=-170.5000;63.9660
P527=-170.5170;63.9690
[C2]
gain=-50.00
n_point=305
P1=-107.4130;81.1100
P2=-107.3360;81.0000
P3=-107.1120;80.5000
P4=-107.0160;80.0000
P5=-107.0160;79.5000
P6=-107.0850;79.0000
P7=-107.2130;78.5000
P8=-107.4060;78.0000
P9=-107.5000;77.7920
P10=-107.6190;77.5000
P11=-107.7910;77.0000
P12=-107.9630;76.5000
P13=-108.0000;76.3750
P14=-108.1060;76.0000
P15=-108.3520;75.5000
P16=-108.5000;75.2930
P17=-108.7530;75.0000
P18=-109.0000;74.6830
P19=-109.1420;74.5000

P20=-109.5000;74.0360
P21=-109.5290;74.0000
P22=-109.8370;73.5000
P23=-110.0000;73.2460
P24=-110.1880;73.0000
P25=-110.5000;72.5520
P26=-110.5480;72.5000
P27=-111.0000;72.0050
P28=-111.0040;72.0000
P29=-111.4250;71.5000
P30=-111.5000;71.3810
P31=-111.7370;71.0000
P32=-112.0000;70.5100
P33=-112.0060;70.5000
P34=-112.2790;70.0000
P35=-112.5000;69.5520
P36=-112.5250;69.5000
P37=-112.7090;69.0000
P38=-113.0000;68.5960
P39=-113.0680;68.5000
P40=-113.4050;68.0000
P41=-113.5000;67.8930
P42=-113.8310;67.5000
P43=-114.0000;67.4000
P44=-114.5000;67.0170
P45=-114.5170;67.0000
P46=-114.7750;66.5000
P47=-115.0000;66.3310
P48=-115.3530;66.0000
P49=-115.5000;65.7120
P50=-115.5780;65.5000
P51=-115.9650;65.0000
P52=-116.0000;64.9340
P53=-116.1500;64.5000
P54=-116.5000;64.0210
P55=-116.5100;64.0000
P56=-116.7890;63.5000
P57=-117.0000;63.2520
P58=-117.1690;63.0000
P59=-117.4380;62.5000
P60=-117.5000;62.4390
P61=-117.8040;62.0000
P62=-118.0000;61.6220
P63=-118.0430;61.5000
P64=-118.2840;61.0000
P65=-118.4460;60.5000
P66=-118.5000;60.3790
P67=-118.6180;60.0000
P68=-118.7750;59.5000
P69=-118.8970;59.0000
P70=-119.0000;58.7400
P71=-119.0770;58.5000
P72=-119.2420;58.0000
P73=-119.3990;57.5000
P74=-119.5000;57.1730
P75=-119.5450;57.0000
P76=-119.7010;56.5000

P77=-119.8670;56.0000
P78=-120.0000;55.6160
P79=-120.0350;55.5000
P80=-120.2230;55.0000
P81=-120.4010;54.5000
P82=-120.5000;54.2310
P83=-120.5740;54.0000
P84=-120.6970;53.5000
P85=-120.8070;53.0000
P86=-120.9410;52.5000
P87=-121.0000;52.2610
P88=-121.0780;52.0000
P89=-121.2590;51.5000
P90=-121.3860;51.0000
P91=-121.5000;50.6380
P92=-121.6210;50.5000
P93=-121.9390;50.0000
P94=-122.0000;49.8840
P95=-122.0470;50.0000
P96=-122.2440;50.5000
P97=-122.3180;51.0000
P98=-122.4130;51.5000
P99=-122.4490;52.0000
P100=-122.5000;52.4090
P101=-122.5090;52.5000
P102=-122.5340;53.0000
P103=-122.5510;53.5000
P104=-122.5680;54.0000
P105=-122.5540;54.5000
P106=-122.5520;55.0000
P107=-122.5000;55.4390
P108=-122.4940;55.5000
P109=-122.4620;56.0000
P110=-122.4300;56.5000
P111=-122.4290;57.0000
P112=-122.4180;57.5000
P113=-122.4480;58.0000
P114=-122.4820;58.5000
P115=-122.4840;59.0000
P116=-122.5000;59.1380
P117=-122.5590;59.5000
P118=-122.5820;60.0000
P119=-122.6760;60.5000
P120=-122.7880;61.0000
P121=-122.8640;61.5000
P122=-123.0000;61.8940
P123=-123.0510;62.0000
P124=-123.1790;62.5000
P125=-123.3460;63.0000
P126=-123.5000;63.4690
P127=-123.5140;63.5000
P128=-123.7180;64.0000
P129=-123.8590;64.5000
P130=-124.0000;64.8270
P131=-124.1000;65.0000
P132=-124.2890;65.5000
P133=-124.5000;65.8630

P134=-124.6060;66.0000
P135=-124.8360;66.5000
P136=-125.0000;66.7930
P137=-125.1570;67.0000
P138=-125.4870;67.5000
P139=-125.5000;67.5270
P140=-125.8120;68.0000
P141=-126.0000;68.2580
P142=-126.2920;68.5000
P143=-126.4870;69.0000
P144=-126.5000;69.0250
P145=-126.8620;69.5000
P146=-127.0000;69.6780
P147=-127.4670;70.0000
P148=-127.5000;70.0770
P149=-127.8090;70.5000
P150=-127.9240;71.0000
P151=-128.0000;71.0600
P152=-128.5000;71.3300
P153=-128.7880;71.5000
P154=-129.0000;71.6740
P155=-129.5000;71.7390
P156=-129.8230;71.5000
P157=-129.6310;71.0000
P158=-129.5000;70.8640
P159=-129.0000;70.5710
P160=-128.9180;70.5000
P161=-128.6830;70.0000
P162=-128.6030;69.5000
P163=-128.5000;69.2450
P164=-128.3080;69.0000
P165=-128.1730;68.5000
P166=-128.1550;68.0000
P167=-128.0000;67.5910
P168=-127.9600;67.5000
P169=-127.9570;67.0000
P170=-127.7950;66.5000
P171=-127.6610;66.0000
P172=-127.5390;65.5000
P173=-127.5000;65.3710
P174=-127.3710;65.0000
P175=-127.2920;64.5000
P176=-127.2080;64.0000
P177=-127.1870;63.5000
P178=-127.1330;63.0000
P179=-127.1350;62.5000
P180=-127.1060;62.0000
P181=-127.0210;61.5000
P182=-127.0000;61.2780
P183=-126.9670;61.0000
P184=-126.8390;60.5000
P185=-126.7420;60.0000
P186=-126.6400;59.5000
P187=-126.5890;59.0000
P188=-126.5570;58.5000
P189=-126.5040;58.0000
P190=-126.5000;57.7860

P191=-126.4940;57.5000
P192=-126.4550;57.0000
P193=-126.4290;56.5000
P194=-126.4260;56.0000
P195=-126.4420;55.5000
P196=-126.5000;55.0600
P197=-126.5070;55.0000
P198=-126.5410;54.5000
P199=-126.5940;54.0000
P200=-126.6360;53.5000
P201=-126.7210;53.0000
P202=-126.8430;52.5000
P203=-127.0000;52.0890
P204=-127.0970;52.0000
P205=-127.5000;51.6600
P206=-128.0000;51.8370
P207=-128.1030;52.0000
P208=-128.3250;52.5000
P209=-128.4870;53.0000
P210=-128.5000;53.0430
P211=-128.6220;53.5000
P212=-128.7390;54.0000
P213=-128.8430;54.5000
P214=-128.9410;55.0000
P215=-129.0000;55.3440
P216=-129.0290;55.5000
P217=-129.1070;56.0000
P218=-129.1940;56.5000
P219=-129.3250;57.0000
P220=-129.4650;57.5000
P221=-129.5000;57.6270
P222=-129.6210;58.0000
P223=-129.8230;58.5000
P224=-130.0000;58.9610
P225=-130.0180;59.0000
P226=-130.2430;59.5000
P227=-130.4700;60.0000
P228=-130.5000;60.0710
P229=-130.7050;60.5000
P230=-130.9710;61.0000
P231=-131.0000;61.0550
P232=-131.2620;61.5000
P233=-131.5000;61.8910
P234=-131.5750;62.0000
P235=-131.9160;62.5000
P236=-132.0000;62.6270
P237=-132.2730;63.0000
P238=-132.5000;63.3120
P239=-132.6440;63.5000
P240=-133.0000;63.9880
P241=-133.0100;64.0000
P242=-133.3950;64.5000
P243=-133.5000;64.6320
P244=-133.8230;65.0000
P245=-134.0000;65.2360
P246=-134.2510;65.5000
P247=-134.5000;65.7240

P248=-134.7970;66.0000
P249=-135.0000;66.2040
P250=-135.2780;66.5000
P251=-135.5000;66.6980
P252=-135.9140;67.0000
P253=-136.0000;67.0630
P254=-136.5000;67.4830
P255=-136.5250;67.5000
P256=-137.0000;67.8560
P257=-137.1740;68.0000
P258=-137.5000;68.2120
P259=-137.9240;68.5000
P260=-138.0000;68.5540
P261=-138.5000;68.8820
P262=-138.6820;69.0000
P263=-139.0000;69.2140
P264=-139.3930;69.5000
P265=-139.5000;69.5600
P266=-140.0000;69.8150
P267=-140.2610;70.0000
P268=-140.5000;70.1490
P269=-141.0000;70.3780
P270=-141.1950;70.5000
P271=-141.5000;70.6760
P272=-142.0000;70.9450
P273=-142.1050;71.0000
P274=-142.5000;71.1690
P275=-142.9990;71.5000
P276=-143.0000;71.5010
P277=-143.5000;71.6540
P278=-144.0000;71.8470
P279=-144.2790;72.0000
P280=-144.5000;72.0900
P281=-145.0000;72.2490
P282=-145.5000;72.4330
P283=-145.6450;72.5000
P284=-146.0000;72.6240
P285=-146.5000;72.8010
P286=-147.0000;72.9580
P287=-147.1080;73.0000
P288=-147.5000;73.1100
P289=-148.0000;73.2880
P290=-148.5000;73.4420
P291=-148.6900;73.5000
P292=-149.0000;73.5660
P293=-149.5000;73.6960
P294=-150.0000;73.8590
P295=-150.4610;74.0000
P296=-150.5000;74.0080
P297=-151.0000;74.0940
P298=-151.5000;74.2050
P299=-152.0000;74.3360
P300=-152.5000;74.5000
P301=-153.0000;74.5660
P302=-153.5000;74.6430
P303=-154.0000;74.7440
P304=-154.5000;74.8600

P305=-154.7810;74.9360

[C3]

gain=-50.00

n_point=103

P1=-86.0000 ;14.7080

P2=-86.2000 ;14.5000

P3=-86.5000 ;14.2290

P4=-86.7430 ;14.0000

P5=-87.0000 ;13.7790

P6=-87.3270 ;13.5000

P7=-87.5000 ;13.3680

P8=-87.9380 ;13.0000

P9=-88.0000 ;12.9500

P10=-88.5000 ;12.5590

P11=-88.5660 ;12.5000

P12=-89.0000 ;12.1680

P13=-89.1990 ;12.0000

P14=-89.5000 ;11.8080

P15=-89.8780 ;11.5000

P16=-90.0000 ;11.4270

P17=-90.5000 ;11.0890

P18=-90.6250 ;11.0000

P19=-91.0000 ;10.8210

P20=-91.4240 ;10.5000

P21=-91.5000 ;10.4610

P22=-92.0000 ;10.1700

P23=-92.2410 ;10.0000

P24=-92.5000 ;9.8790

P25=-93.0000 ;9.5290

P26=-93.0440 ;9.5000

P27=-93.5000 ;9.2670

P28=-93.9500 ;9.0000

P29=-94.0000 ;8.9700

P30=-94.5000 ;8.7810

P31=-95.0000 ;8.6360

P32=-95.5000 ;8.5950

P33=-96.0000 ;8.6270

P34=-96.5000 ;8.6250

P35=-97.0000 ;8.5380

P36=-97.1030 ;8.5000

P37=-97.5000 ;8.4250

P38=-98.0000 ;8.3490

P39=-98.5000 ;8.2250

P40=-99.0000 ;8.0360

P41=-99.0960 ;8.0000

P42=-99.5000 ;7.9010

P43=-100.0000;7.8230

P44=-100.5000;7.7730

P45=-101.0000;7.7240

P46=-101.5000;7.6850

P47=-102.0000;7.6600

P48=-102.5000;7.6420

P49=-103.0000;7.5880

P50=-103.2140;7.5000

P51=-103.0000;7.4430

P52=-102.5000;7.3620

P53=-102.0000;7.2950

P54=-101.5000;7.2140
P55=-101.0000;7.1340
P56=-100.5000;7.0910
P57=-100.0000;7.0900
P58=-99.5000 ;7.1020
P59=-99.0000 ;7.0990
P60=-98.5000 ;7.1820
P61=-98.0000 ;7.2980
P62=-97.5000 ;7.4280
P63=-97.1840 ;7.5000
P64=-97.0000 ;7.5370
P65=-96.5000 ;7.5950
P66=-96.0000 ;7.6170
P67=-95.5000 ;7.5600
P68=-95.2600 ;7.5000
P69=-95.0000 ;7.3960
P70=-94.5000 ;7.3430
P71=-94.1410 ;7.5000
P72=-94.0000 ;7.5240
P73=-93.5000 ;7.7050
P74=-93.1310 ;8.0000
P75=-93.0000 ;8.0580
P76=-92.5000 ;8.3990
P77=-92.3920 ;8.5000
P78=-92.0000 ;8.7060
P79=-91.6470 ;9.0000
P80=-91.5000 ;9.0720
P81=-91.0000 ;9.4350
P82=-90.9200 ;9.5000
P83=-90.5000 ;9.7400
P84=-90.1890 ;10.0000
P85=-90.0000 ;10.1120
P86=-89.5260 ;10.5000
P87=-89.5000 ;10.5200
P88=-89.0000 ;10.8940
P89=-88.8880 ;11.0000
P90=-88.5000 ;11.3490
P91=-88.3510 ;11.5000
P92=-88.0000 ;11.8550
P93=-87.8660 ;12.0000
P94=-87.5000 ;12.4280
P95=-87.4320 ;12.5000
P96=-87.0020 ;13.0000
P97=-87.0000 ;13.0020
P98=-86.5900 ;13.5000
P99=-86.5000 ;13.6140
P100=-86.1720 ;14.0000
P101=-86.0000 ;14.2000
P102=-85.7490 ;14.5000
P103=-86.0000 ;14.7080
[C4]
gain=-50.00
n_point=229
P1=-31.4718 ;64.4092
P2=-31.7970 ;64.3730
P3=-32.0000 ;64.3500
P4=-32.5000 ;64.2790

P5=-33.0000 ;64.1950
P6=-33.5000 ;64.0970
P7=-33.9260 ;64.0000
P8=-34.0000 ;63.9850
P9=-34.5000 ;63.9050
P10=-35.0000 ;63.8320
P11=-35.5000 ;63.7390
P12=-36.0000 ;63.6260
P13=-36.4700 ;63.5000
P14=-36.5000 ;63.4930
P15=-37.0000 ;63.3850
P16=-37.5000 ;63.2960
P17=-38.0000 ;63.1810
P18=-38.5000 ;63.0360
P19=-38.6080 ;63.0000
P20=-39.0000 ;62.8920
P21=-39.5000 ;62.7760
P22=-40.0000 ;62.6490
P23=-40.4570 ;62.5000
P24=-40.5000 ;62.4880
P25=-41.0000 ;62.3330
P26=-41.5000 ;62.1780
P27=-42.0000 ;62.0200
P28=-42.0540 ;62.0000
P29=-42.5000 ;61.8710
P30=-43.0000 ;61.6760
P31=-43.4340 ;61.5000
P32=-43.5000 ;61.4770
P33=-44.0000 ;61.3320
P34=-44.5000 ;61.1280
P35=-44.7560 ;61.0000
P36=-45.0000 ;60.8980
P37=-45.5000 ;60.7260
P38=-45.9730 ;60.5000
P39=-46.0000 ;60.4890
P40=-46.5000 ;60.2660
P41=-47.0000 ;60.0420
P42=-47.0760 ;60.0000
P43=-47.5000 ;59.8210
P44=-48.0000 ;59.5330
P45=-48.0680 ;59.5000
P46=-48.5000 ;59.3430
P47=-49.0000 ;59.0450
P48=-49.0760 ;59.0000
P49=-49.5000 ;58.7990
P50=-50.0000 ;58.5140
P51=-50.0200 ;58.5000
P52=-50.5000 ;58.2150
P53=-50.8690 ;58.0000
P54=-51.0000 ;57.9450
P55=-51.5000 ;57.5810
P56=-51.6300 ;57.5000
P57=-52.0000 ;57.3200
P58=-52.3980 ;57.0000
P59=-52.5000 ;56.9290
P60=-53.0000 ;56.5840
P61=-53.0940 ;56.5000

P62=-53.5000 ;56.1790
P63=-53.7410 ;56.0000
P64=-54.0000 ;55.8360
P65=-54.3470 ;55.5000
P66=-54.5000 ;55.3400
P67=-54.9260 ;55.0000
P68=-55.0000 ;54.9590
P69=-55.4740 ;54.5000
P70=-55.5000 ;54.4720
P71=-56.0000 ;54.0160
P72=-56.0170 ;54.0000
P73=-56.5000 ;53.5300
P74=-56.5280 ;53.5000
P75=-56.9670 ;53.0000
P76=-57.0000 ;52.9600
P77=-57.4440 ;52.5000
P78=-57.5000 ;52.4260
P79=-57.9000 ;52.0000
P80=-58.0000 ;51.9000
P81=-58.3400 ;51.5000
P82=-58.5000 ;51.2910
P83=-58.7340 ;51.0000
P84=-59.0000 ;50.6160
P85=-59.0910 ;50.5000
P86=-59.4440 ;50.0000
P87=-59.5000 ;49.9180
P88=-59.8190 ;49.5000
P89=-60.0000 ;49.2070
P90=-60.1570 ;49.0000
P91=-60.4670 ;48.5000
P92=-60.5000 ;48.4480
P93=-60.8240 ;48.0000
P94=-61.0000 ;47.6940
P95=-61.1320 ;47.5000
P96=-61.4190 ;47.0000
P97=-61.5000 ;46.8690
P98=-61.7390 ;46.5000
P99=-62.0000 ;46.0480
P100=-62.0320 ;46.0000
P101=-62.3160 ;45.5000
P102=-62.5000 ;45.1750
P103=-62.6050 ;45.0000
P104=-62.8380 ;44.5000
P105=-63.0000 ;44.2190
P106=-63.1140 ;44.0000
P107=-63.3910 ;43.5000
P108=-63.5000 ;43.3250
P109=-63.6850 ;43.0000
P110=-63.9110 ;42.5000
P111=-64.0000 ;42.3210
P112=-64.1100 ;42.0000
P113=-64.2790 ;41.5000
P114=-64.5000 ;41.2690
P115=-64.6380 ;41.0000
P116=-64.5000 ;40.5740
P117=-64.1810 ;41.0000
P118=-64.0000 ;41.1720

P119=-63.7920 ;41.5000
P120=-63.5000 ;41.8310
P121=-63.3850 ;42.0000
P122=-63.0000 ;42.4880
P123=-62.9920 ;42.5000
P124=-62.6540 ;43.0000
P125=-62.5000 ;43.1850
P126=-62.2840 ;43.5000
P127=-62.0000 ;43.9060
P128=-61.9340 ;44.0000
P129=-61.6000 ;44.5000
P130=-61.5000 ;44.6250
P131=-61.2250 ;45.0000
P132=-61.0000 ;45.3040
P133=-60.8510 ;45.5000
P134=-60.5040 ;46.0000
P135=-60.5000 ;46.0050
P136=-60.1450 ;46.5000
P137=-60.0000 ;46.7000
P138=-59.7780 ;47.0000
P139=-59.5000 ;47.3920
P140=-59.4180 ;47.5000
P141=-59.0490 ;48.0000
P142=-59.0000 ;48.0570
P143=-58.6420 ;48.5000
P144=-58.5000 ;48.6810
P145=-58.2150 ;49.0000
P146=-58.0000 ;49.2910
P147=-57.8130 ;49.5000
P148=-57.5000 ;49.8470
P149=-57.3650 ;50.0000
P150=-57.0000 ;50.4080
P151=-56.9190 ;50.5000
P152=-56.5000 ;50.9860
P153=-56.4870 ;51.0000
P154=-56.0340 ;51.5000
P155=-56.0000 ;51.5390
P156=-55.5000 ;51.9680
P157=-55.4680 ;52.0000
P158=-55.0000 ;52.4440
P159=-54.9430 ;52.5000
P160=-54.5000 ;52.9390
P161=-54.4250 ;53.0000
P162=-54.0000 ;53.2960
P163=-53.7860 ;53.5000
P164=-53.5000 ;53.7770
P165=-53.2270 ;54.0000
P166=-53.0000 ;54.1360
P167=-52.5780 ;54.5000
P168=-52.5000 ;54.5650
P169=-52.0000 ;54.9380
P170=-51.9200 ;55.0000
P171=-51.5000 ;55.2990
P172=-51.2410 ;55.5000
P173=-51.0000 ;55.6260
P174=-50.5090 ;56.0000
P175=-50.5000 ;56.0070

P176=-50.0000 ;56.2800
P177=-49.7000 ;56.5000
P178=-49.5000 ;56.6400
P179=-49.0000 ;56.9170
P180=-48.8840 ;57.0000
P181=-48.5000 ;57.2380
P182=-48.0080 ;57.5000
P183=-48.0000 ;57.5030
P184=-47.5000 ;57.7610
P185=-47.1160 ;58.0000
P186=-47.0000 ;58.0590
P187=-46.5000 ;58.2550
P188=-46.1130 ;58.5000
P189=-46.0000 ;58.5600
P190=-45.5000 ;58.7600
P191=-45.0200 ;59.0000
P192=-45.0000 ;59.0080
P193=-44.5000 ;59.2280
P194=-44.0000 ;59.4310
P195=-43.8440 ;59.5000
P196=-43.5000 ;59.6140
P197=-43.0000 ;59.8360
P198=-42.6340 ;60.0000
P199=-42.5000 ;60.0480
P200=-42.0000 ;60.1830
P201=-41.5000 ;60.3670
P202=-41.2130 ;60.5000
P203=-41.0000 ;60.5840
P204=-40.5000 ;60.7120
P205=-40.0000 ;60.8610
P206=-39.6250 ;61.0000
P207=-39.5000 ;61.0380
P208=-39.0000 ;61.1870
P209=-38.5000 ;61.3130
P210=-38.0000 ;61.4560
P211=-37.8700 ;61.5000
P212=-37.5000 ;61.5930
P213=-37.0000 ;61.7280
P214=-36.5000 ;61.8480
P215=-36.0000 ;61.9600
P216=-35.8440 ;62.0000
P217=-35.5000 ;62.0650
P218=-35.0000 ;62.1720
P219=-34.5000 ;62.2880
P220=-34.0000 ;62.4050
P221=-33.5000 ;62.4970
P222=-33.4870 ;62.5000
P223=-33.0000 ;62.5680
P224=-32.5000 ;62.6480
P225=-32.0000 ;62.7390
P226=-31.5000 ;62.8310
P227=-31.0000 ;62.9310
P228=-30.7480 ;62.9670
P229=-30.4432 ;63.0098
[C5]
gain=-50.00
n_point=254

P1=-35.5083 ;68.6431
P2=-35.8970 ;68.6060
P3=-36.0000 ;68.5960
P4=-36.5000 ;68.5760
P5=-37.0000 ;68.5460
P6=-37.2590 ;68.5000
P7=-37.5000 ;68.3930
P8=-38.0000 ;68.2260
P9=-38.5000 ;68.1200
P10=-39.0000 ;68.0660
P11=-39.5000 ;68.0420
P12=-39.7460 ;68.0000
P13=-40.0000 ;67.8870
P14=-40.5000 ;67.7180
P15=-41.0000 ;67.5840
P16=-41.5000 ;67.5090
P17=-41.6170 ;67.5000
P18=-42.0000 ;67.4140
P19=-42.5000 ;67.2650
P20=-43.0000 ;67.0870
P21=-43.3350 ;67.0000
P22=-43.5000 ;66.8670
P23=-44.0000 ;66.7700
P24=-44.5000 ;66.7140
P25=-45.0000 ;66.5330
P26=-45.0990 ;66.5000
P27=-45.5000 ;66.1790
P28=-46.0000 ;66.1100
P29=-46.5000 ;66.0600
P30=-46.6600 ;66.0000
P31=-47.0000 ;65.6860
P32=-47.5000 ;65.5020
P33=-47.5140 ;65.5000
P34=-48.0000 ;65.3570
P35=-48.5000 ;65.1680
P36=-48.8450 ;65.0000
P37=-49.0000 ;64.5710
P38=-49.5000 ;64.6200
P39=-50.0000 ;64.5490
P40=-50.1020 ;64.5000
P41=-50.5000 ;64.1010
P42=-51.0000 ;64.0140
P43=-51.0370 ;64.0000
P44=-51.5000 ;63.7760
P45=-52.0000 ;63.5250
P46=-52.0900 ;63.5000
P47=-52.5000 ;63.3190
P48=-53.0000 ;63.0530
P49=-53.1090 ;63.0000
P50=-53.5000 ;62.7650
P51=-54.0000 ;62.6120
P52=-54.1880 ;62.5000
P53=-54.5000 ;62.2300
P54=-55.0000 ;62.0770
P55=-55.1240 ;62.0000
P56=-55.5000 ;61.7080
P57=-55.9330 ;61.5000

P58=-56.0000 ;61.4640
P59=-56.5000 ;61.0900
P60=-56.6410 ;61.0000
P61=-57.0000 ;60.7820
P62=-57.3630 ;60.5000
P63=-57.5000 ;60.3460
P64=-58.0000 ;60.0210
P65=-58.0250 ;60.0000
P66=-58.5000 ;59.5380
P67=-58.5420 ;59.5000
P68=-59.0000 ;59.1180
P69=-59.1210 ;59.0000
P70=-59.5000 ;58.6340
P71=-59.6450 ;58.5000
P72=-60.0000 ;58.1860
P73=-60.1870 ;58.0000
P74=-60.5000 ;57.7460
P75=-60.7470 ;57.5000
P76=-61.0000 ;57.2500
P77=-61.2550 ;57.0000
P78=-61.5000 ;56.7520
P79=-61.7260 ;56.5000
P80=-62.0000 ;56.2230
P81=-62.1830 ;56.0000
P82=-62.5000 ;55.5940
P83=-62.5790 ;55.5000
P84=-62.9490 ;55.0000
P85=-63.0000 ;54.9330
P86=-63.3460 ;54.5000
P87=-63.5000 ;54.2660
P88=-63.6870 ;54.0000
P89=-64.0000 ;53.5340
P90=-64.0230 ;53.5000
P91=-64.3510 ;53.0000
P92=-64.5000 ;52.7480
P93=-64.6540 ;52.5000
P94=-64.9270 ;52.0000
P95=-65.0000 ;51.8360
P96=-65.1820 ;51.5000
P97=-65.4290 ;51.0000
P98=-65.5000 ;50.8290
P99=-65.6900 ;50.5000
P100=-65.9480 ;50.0000
P101=-66.0000 ;49.8150
P102=-66.1790 ;49.5000
P103=-66.3830 ;49.0000
P104=-66.5000 ;48.6470
P105=-66.5710 ;48.5000
P106=-66.7290 ;48.0000
P107=-66.9060 ;47.5000
P108=-67.0000 ;47.2160
P109=-67.1050 ;47.0000
P110=-67.2700 ;46.5000
P111=-67.4230 ;46.0000
P112=-67.5000 ;45.7920
P113=-67.6070 ;45.5000
P114=-67.7850 ;45.0000

P115=-67.9140 ;44.5000
P116=-68.0000 ;44.2760
P117=-68.0790 ;44.0000
P118=-68.2630 ;43.5000
P119=-68.4120 ;43.0000
P120=-68.5000 ;42.8270
P121=-68.5930 ;42.5000
P122=-68.7630 ;42.0000
P123=-68.8400 ;41.5000
P124=-69.0000 ;41.2650
P125=-69.0690 ;41.0000
P126=-69.1860 ;40.5000
P127=-69.0630 ;40.0000
P128=-69.0000 ;39.9660
P129=-68.9860 ;40.0000
P130=-68.7960 ;40.5000
P131=-68.5000 ;40.8800
P132=-68.4390 ;41.0000
P133=-68.3090 ;41.5000
P134=-68.0230 ;42.0000
P135=-68.0000 ;42.0250
P136=-67.7630 ;42.5000
P137=-67.5620 ;43.0000
P138=-67.5000 ;43.0950
P139=-67.3470 ;43.5000
P140=-67.1130 ;44.0000
P141=-67.0000 ;44.2140
P142=-66.8470 ;44.5000
P143=-66.6480 ;45.0000
P144=-66.5000 ;45.2950
P145=-66.4020 ;45.5000
P146=-66.1640 ;46.0000
P147=-66.0000 ;46.3770
P148=-65.9320 ;46.5000
P149=-65.6750 ;47.0000
P150=-65.5000 ;47.3690
P151=-65.4230 ;47.5000
P152=-65.1750 ;48.0000
P153=-65.0000 ;48.3730
P154=-64.9270 ;48.5000
P155=-64.6770 ;49.0000
P156=-64.5000 ;49.4570
P157=-64.4770 ;49.5000
P158=-64.1620 ;50.0000
P159=-64.0000 ;50.3530
P160=-63.9030 ;50.5000
P161=-63.5700 ;51.0000
P162=-63.5000 ;51.1840
P163=-63.2800 ;51.5000
P164=-63.0180 ;52.0000
P165=-63.0000 ;52.0340
P166=-62.6810 ;52.5000
P167=-62.5000 ;52.8570
P168=-62.4010 ;53.0000
P169=-62.0750 ;53.5000
P170=-62.0000 ;53.6180
P171=-61.7110 ;54.0000

P172=-61.5000 ;54.3520
P173=-61.3790 ;54.5000
P174=-61.0080 ;55.0000
P175=-61.0000 ;55.0120
P176=-60.5750 ;55.5000
P177=-60.5000 ;55.5990
P178=-60.1730 ;56.0000
P179=-60.0000 ;56.1980
P180=-59.7580 ;56.5000
P181=-59.5000 ;56.8120
P182=-59.3050 ;57.0000
P183=-59.0000 ;57.3730
P184=-58.8800 ;57.5000
P185=-58.5000 ;57.8880
P186=-58.3950 ;58.0000
P187=-58.0000 ;58.4120
P188=-57.8970 ;58.5000
P189=-57.5000 ;58.8940
P190=-57.3830 ;59.0000
P191=-57.0000 ;59.3060
P192=-56.7670 ;59.5000
P193=-56.5000 ;59.7850
P194=-56.1830 ;60.0000
P195=-56.0000 ;60.1080
P196=-55.5230 ;60.5000
P197=-55.5000 ;60.5320
P198=-55.0000 ;60.8550
P199=-54.7940 ;61.0000
P200=-54.5000 ;61.2670
P201=-54.0730 ;61.5000
P202=-54.0000 ;61.5530
P203=-53.5000 ;61.9330
P204=-53.3850 ;62.0000
P205=-53.0000 ;62.2840
P206=-52.5300 ;62.5000
P207=-52.5000 ;62.5280
P208=-52.0000 ;62.9380
P209=-51.7640 ;63.0000
P210=-51.5000 ;63.1190
P211=-51.0000 ;63.4510
P212=-50.8950 ;63.5000
P213=-50.5000 ;63.8830
P214=-50.0000 ;63.8800
P215=-49.7580 ;64.0000
P216=-49.5000 ;64.3290
P217=-49.0000 ;64.4870
P218=-48.8630 ;64.5000
P219=-48.5000 ;64.5820
P220=-48.0000 ;64.8480
P221=-47.5610 ;65.0000
P222=-47.5000 ;65.4610
P223=-47.0000 ;65.2770
P224=-46.5000 ;65.3830
P225=-46.1630 ;65.5000
P226=-46.0000 ;65.6830
P227=-45.5000 ;65.8400
P228=-45.0000 ;65.8690

P229=-44.5520 ;66.0000
P230=-44.5000 ;66.0280
P231=-44.0000 ;66.2580
P232=-43.5000 ;66.3670
P233=-43.0000 ;66.4140
P234=-42.6840 ;66.5000
P235=-42.5000 ;66.5980
P236=-42.0000 ;66.7920
P237=-41.5000 ;66.8860
P238=-41.0000 ;66.9270
P239=-40.5080 ;67.0000
P240=-40.5000 ;67.0040
P241=-40.0000 ;67.2320
P242=-39.5000 ;67.3670
P243=-39.0000 ;67.4410
P244=-38.5000 ;67.4780
P245=-38.2780 ;67.5000
P246=-38.0000 ;67.5850
P247=-37.5000 ;67.7140
P248=-37.0000 ;67.8480
P249=-36.5000 ;67.9320
P250=-36.0000 ;67.9810
P251=-35.5910 ;68.0000
P252=-35.5000 ;68.0190
P253=-35.2840 ;68.0740
P254=-34.9553 ;68.1567

[C6]

gain=-50.00

n_point=113

P1=-70.0000 ;53.8010
P2=-70.2240 ;53.5000
P3=-70.5000 ;53.1820
P4=-70.5840 ;53.0000
P5=-70.6360 ;52.7500
P6=-70.6880 ;52.5000
P7=-70.7995 ;52.2500
P8=-70.9110 ;52.0000
P9=-71.0000 ;51.8920
P10=-71.1300 ;51.5000
P11=-71.2445 ;51.2500
P12=-71.3590 ;51.0000
P13=-71.5000 ;50.6920
P14=-71.5810 ;50.5000
P15=-71.6635 ;50.2500
P16=-71.7460 ;50.0000
P17=-71.8130 ;49.7500
P18=-71.8800 ;49.5000
P19=-71.9400 ;49.2555
P20=-72.0000 ;49.0110
P21=-72.0030 ;49.0000
P22=-72.0990 ;48.7500
P23=-72.1950 ;48.5000
P24=-72.2345 ;48.2500
P25=-72.2740 ;48.0000
P26=-72.3375 ;47.7500
P27=-72.4010 ;47.5000
P28=-72.4395 ;47.2500

P29=-72.4780 ;47.0000
P30=-72.5000 ;46.9020
P31=-72.6150 ;46.5000
P32=-72.6400 ;46.2500
P33=-72.6650 ;46.0000
P34=-72.7150 ;45.7500
P35=-72.7650 ;45.5000
P36=-72.7835 ;45.2500
P37=-72.8020 ;45.0000
P38=-72.8290 ;44.7500
P39=-72.8560 ;44.5000
P40=-72.8755 ;44.2500
P41=-72.8950 ;44.0000
P42=-72.9320 ;43.7500
P43=-72.9690 ;43.5000
P44=-73.0000 ;43.3480
P45=-73.0590 ;43.0000
P46=-73.0925 ;42.7500
P47=-73.1260 ;42.5000
P48=-73.1475 ;42.2500
P49=-73.1690 ;42.0000
P50=-73.1830 ;41.7500
P51=-73.1970 ;41.5000
P52=-73.2140 ;41.2500
P53=-73.2310 ;41.0000
P54=-73.2075 ;40.7500
P55=-73.1840 ;40.5000
P56=-73.0000 ;40.2850
P57=-72.9350 ;40.5000
P58=-72.8855 ;40.7500
P59=-72.8360 ;41.0000
P60=-72.7685 ;41.2500
P61=-72.7010 ;41.5000
P62=-72.6110 ;41.7500
P63=-72.5210 ;42.0000
P64=-72.5000 ;42.0180
P65=-72.4130 ;42.2590
P66=-72.3260 ;42.5000
P67=-72.2890 ;42.7500
P68=-72.2520 ;43.0000
P69=-72.1830 ;43.2500
P70=-72.1140 ;43.5000
P71=-72.0000 ;43.8260
P72=-71.9350 ;44.0000
P73=-71.8770 ;44.2500
P74=-71.8190 ;44.5000
P75=-71.7550 ;44.7500
P76=-71.6910 ;45.0000
P77=-71.6310 ;45.2500
P78=-71.5710 ;45.5000
P79=-71.5000 ;45.7580
P80=-71.4110 ;46.0000
P81=-71.3655 ;46.2500
P82=-71.3200 ;46.5000
P83=-71.2210 ;46.7500
P84=-71.1220 ;47.0000
P85=-71.0970 ;47.2500

P86=-71.0720 ;47.5000
P87=-71.0410 ;47.7500
P88=-71.0100 ;48.0000
P89=-71.0000 ;48.0420
P90=-70.8990 ;48.2710
P91=-70.7980 ;48.5000
P92=-70.7530 ;48.7500
P93=-70.7080 ;49.0000
P94=-70.6545 ;49.2500
P95=-70.6010 ;49.5000
P96=-70.5545 ;49.7500
P97=-70.5080 ;50.0000
P98=-70.5000 ;50.0340
P99=-70.4365 ;50.2670
P100=-70.3730 ;50.5000
P101=-70.3465 ;50.7500
P102=-70.3200 ;51.0000
P103=-70.2670 ;51.2500
P104=-70.2140 ;51.5000
P105=-70.1850 ;51.7500
P106=-70.1560 ;52.0000
P107=-70.1145 ;52.2500
P108=-70.0730 ;52.5000
P109=-70.0000 ;52.7180
P110=-69.9630 ;53.0000
P111=-69.9010 ;53.2500
P112=-69.8390 ;53.5000
P113=-70.0000 ;53.8010

[C7]

gain=-50.00

n_point=71

P1=-77.0000 ;47.8010
P2=-77.0735 ;47.6505
P3=-77.1470 ;47.5000
P4=-77.1670 ;47.2500
P5=-77.1870 ;47.0000
P6=-77.2610 ;46.7500
P7=-77.3350 ;46.5000
P8=-77.3910 ;46.2500
P9=-77.4470 ;46.0000
P10=-77.4725 ;45.7500
P11=-77.4980 ;45.5000
P12=-77.5000 ;45.4890
P13=-77.5335 ;45.2445
P14=-77.5670 ;45.0000
P15=-77.5900 ;44.7500
P16=-77.6130 ;44.5000
P17=-77.6135 ;44.2500
P18=-77.6140 ;44.0000
P19=-77.6420 ;43.7500
P20=-77.6700 ;43.5000
P21=-77.6330 ;43.2500
P22=-77.5960 ;43.0000
P23=-77.6000 ;42.7500
P24=-77.6040 ;42.5000
P25=-77.6000 ;42.2500
P26=-77.5960 ;42.0000

P27=-77.5610 ;41.7500
P28=-77.5260 ;41.5000
P29=-77.5635 ;41.2500
P30=-77.6010 ;41.0000
P31=-77.5530 ;40.7500
P32=-77.5050 ;40.5000
P33=-77.5495 ;40.2500
P34=-77.5940 ;40.0000
P35=-77.5470 ;39.7830
P36=-77.5000 ;39.5660
P37=-77.3960 ;39.7830
P38=-77.2920 ;40.0000
P39=-77.3715 ;40.2500
P40=-77.4510 ;40.5000
P41=-77.2255 ;40.7060
P42=-77.0000 ;40.9120
P43=-76.9910 ;41.0000
P44=-76.9500 ;41.2500
P45=-76.9090 ;41.5000
P46=-76.8820 ;41.7500
P47=-76.8550 ;42.0000
P48=-76.8050 ;42.2500
P49=-76.7550 ;42.5000
P50=-76.7530 ;42.7500
P51=-76.7510 ;43.0000
P52=-76.6955 ;43.2500
P53=-76.6400 ;43.5000
P54=-76.6580 ;43.7500
P55=-76.6760 ;44.0000
P56=-76.6515 ;44.2500
P57=-76.6270 ;44.5000
P58=-76.6370 ;44.7500
P59=-76.6470 ;45.0000
P60=-76.6495 ;45.2500
P61=-76.6520 ;45.5000
P62=-76.6755 ;45.7500
P63=-76.6990 ;46.0000
P64=-76.7110 ;46.2500
P65=-76.7230 ;46.5000
P66=-76.7890 ;46.7500
P67=-76.8550 ;47.0000
P68=-76.8595 ;47.2500
P69=-76.8640 ;47.5000
P70=-76.9320 ;47.6505
P71=-77.0000 ;47.8010
[C8]
gain=-40.00
n_point=294
P1=-117.8625;38.4638
P2=-117.3901;39.1954
P3=-117.0917;38.2532
P4=-117.0073;37.3638
P5=-116.9230;36.4744
P6=-116.8698;35.7833
P7=-116.8166;35.0922
P8=-116.7216;33.9015
P9=-116.6078;33.0920

P10=-116.4941;32.2825
P11=-116.3327;31.4578
P12=-116.1714;30.6331
P13=-115.9105;30.4252
P14=-115.7185;31.5485
P15=-115.6437;32.2525
P16=-115.5689;32.9565
P17=-115.5104;33.7227
P18=-115.4518;34.4888
P19=-115.3841;35.1998
P20=-115.3165;35.9108
P21=-115.1421;37.1984
P22=-114.9683;37.9160
P23=-114.7944;38.6337
P24=-114.5178;39.4370
P25=-114.2411;40.2404
P26=-113.5763;41.2682
P27=-112.9200;41.4511
P28=-112.7685;40.5654
P29=-112.8944;39.7168
P30=-113.0203;38.8682
P31=-113.1098;38.0075
P32=-113.1993;37.1468
P33=-113.2255;36.3820
P34=-113.2518;35.6171
P35=-113.0969;34.7937
P36=-112.7606;34.7831
P37=-112.3589;35.8535
P38=-112.1398;36.7490
P39=-111.9206;37.6444
P40=-111.7085;38.3473
P41=-111.4964;39.0502
P42=-110.9303;40.1602
P43=-110.3878;40.7538
P44=-109.8453;41.3475
P45=-108.9849;41.5529
P46=-108.9592;40.7581
P47=-108.9335;39.9633
P48=-108.9623;39.2287
P49=-108.9910;38.4941
P50=-108.7259;38.2779
P51=-108.0009;39.0829
P52=-107.4216;39.8613
P53=-106.8423;40.6397
P54=-105.9739;40.7925
P55=-105.7330;40.0499
P56=-105.4920;39.3074
P57=-104.6708;38.7289
P58=-103.5572;38.6196
P59=-102.3457;38.0981
P60=-101.7053;38.2620
P61=-101.8133;38.9489
P62=-101.9213;39.6358
P63=-101.7837;40.9027
P64=-101.2506;41.8290
P65=-101.5936;43.0294
P66=-101.8783;44.2831

P67=-100.7147;45.2022
P68=-99.2007 ;45.7340
P69=-97.7971 ;45.8618
P70=-96.4635 ;45.7386
P71=-95.1789 ;45.4382
P72=-93.8573 ;44.8212
P73=-93.1491 ;44.3076
P74=-92.4410 ;43.7940
P75=-91.3734 ;43.1220
P76=-91.1475 ;43.6556
P77=-91.6767 ;44.7509
P78=-92.8487 ;45.6342
P79=-94.2178 ;46.2989
P80=-95.5251 ;46.7423
P81=-96.8869 ;46.9336
P82=-98.4138 ;46.8437
P83=-99.9375 ;46.7388
P84=-101.1235;47.1481
P85=-101.7407;47.9789
P86=-101.1117;48.9037
P87=-99.6016 ;49.7777
P88=-98.2130 ;50.3043
P89=-96.9150 ;50.5145
P90=-95.5189 ;50.5185
P91=-94.0585 ;50.3152
P92=-92.6937 ;49.8810
P93=-91.4340 ;49.2303
P94=-90.2550 ;48.4340
P95=-89.1714 ;47.4979
P96=-88.2389 ;46.4158
P97=-87.4845 ;45.1981
P98=-87.2299 ;44.5377
P99=-86.9754 ;43.8773
P100=-86.8233 ;43.1757
P101=-86.6713 ;42.4741
P102=-86.5219 ;41.7736
P103=-86.3725 ;41.0732
P104=-86.2147 ;40.3784
P105=-86.0569 ;39.6837
P106=-85.9046 ;38.9876
P107=-85.7524 ;38.2915
P108=-85.6131 ;37.5916
P109=-85.4738 ;36.8917
P110=-85.3867 ;36.1843
P111=-85.2995 ;35.4768
P112=-85.2764 ;34.7612
P113=-85.2533 ;34.0455
P114=-85.2942 ;33.3329
P115=-85.3351 ;32.6203
P116=-85.4400 ;31.9157
P117=-85.5449 ;31.2111
P118=-85.7056 ;30.5166
P119=-85.8663 ;29.8222
P120=-86.0764 ;29.1395
P121=-86.2864 ;28.4567
P122=-86.5311 ;27.7859
P123=-86.7757 ;27.1152

P124=-87.0454 ;26.4566
P125=-87.3151 ;25.7980
P126=-87.6216 ;25.1544
P127=-87.9280 ;24.5108
P128=-88.2789 ;23.8846
P129=-88.6298 ;23.2584
P130=-89.0463 ;22.6820
P131=-89.4628 ;22.1056
P132=-89.9467 ;21.5847
P133=-90.4306 ;21.0639
P134=-90.9147 ;20.5198
P135=-91.3988 ;19.9757
P136=-92.4837 ;19.0996
P137=-93.0881 ;18.7334
P138=-93.6925 ;18.3672
P139=-94.3279 ;17.9694
P140=-94.9632 ;17.5716
P141=-96.2485 ;17.0267
P142=-97.5425 ;16.8518
P143=-98.2814 ;16.7563
P144=-99.0202 ;16.6608
P145=-99.8450 ;16.5089
P146=-100.6698;16.3570
P147=-100.9566;15.9907
P148=-100.1375;15.7845
P149=-99.3184 ;15.5782
P150=-98.2385 ;14.9968
P151=-98.6039 ;14.2409
P152=-99.6771 ;13.7474
P153=-100.4544;13.6869
P154=-101.2317;13.6264
P155=-101.9944;13.6982
P156=-102.7571;13.7701
P157=-104.0733;14.1391
P158=-105.3078;14.7221
P159=-105.9098;15.1187
P160=-106.5118;15.5152
P161=-107.0400;16.0292
P162=-107.5681;16.5432
P163=-108.0309;17.0669
P164=-108.4937;17.5906
P165=-109.3545;18.5827
P166=-109.8108;19.3153
P167=-110.2671;20.0480
P168=-111.1867;20.7813
P169=-111.8603;20.0895
P170=-111.5626;18.8950
P171=-111.0452;18.2294
P172=-110.5277;17.5638
P173=-109.9671;17.1417
P174=-109.4065;16.7196
P175=-108.2652;15.9787
P176=-107.6937;15.5315
P177=-107.1222;15.0844
P178=-106.5003;14.7088
P179=-105.8783;14.3332
P180=-105.2151;14.0571

P181=-104.5520;13.7811
P182=-103.2343;13.4194
P183=-102.5574;13.2738
P184=-101.8804;13.1283
P185=-101.1327;12.8892
P186=-100.3850;12.6502
P187=-99.2097 ;12.0158
P188=-99.6992 ;11.3389
P189=-100.4265;11.0983
P190=-101.1537;10.8577
P191=-101.8714;10.8595
P192=-102.5891;10.8614
P193=-103.2823;11.0473
P194=-103.9756;11.2333
P195=-104.6244;11.5153
P196=-105.2732;11.7972
P197=-105.8942;12.1448
P198=-106.5152;12.4924
P199=-107.1301;12.8676
P200=-107.7451;13.2427
P201=-108.3279;13.6530
P202=-108.9108;14.0633
P203=-109.4348;14.5300
P204=-109.9587;14.9966
P205=-110.3845;15.5957
P206=-110.8102;16.1947
P207=-111.1699;16.8251
P208=-111.5296;17.4556
P209=-112.2117;18.5295
P210=-112.5438;19.2427
P211=-112.8758;19.9558
P212=-113.1962;20.7413
P213=-113.5167;21.5268
P214=-114.0936;21.8858
P215=-114.5025;21.1476
P216=-114.5242;20.4474
P217=-114.5459;19.7472
P218=-114.3885;18.9461
P219=-114.2311;18.1451
P220=-113.9038;17.5436
P221=-113.5765;16.9422
P222=-112.6897;15.9020
P223=-112.1632;15.3968
P224=-111.6367;14.8917
P225=-111.0770;14.4422
P226=-110.5173;13.9927
P227=-109.9490;13.5784
P228=-109.3807;13.1640
P229=-108.8154;12.7059
P230=-108.2500;12.2478
P231=-107.6636;11.8427
P232=-107.0772;11.4377
P233=-106.4491;11.1630
P234=-105.8210;10.8884
P235=-105.1272;10.6791
P236=-104.4334;10.4698
P237=-103.6731;10.2947

P238=-102.9129;10.1197
P239=-102.2643;9.8798
P240=-101.6156;9.6398
P241=-100.7292;8.9788
P242=-100.9476;8.5298
P243=-101.7109;8.4757
P244=-102.4742;8.4216
P245=-103.3256;8.5145
P246=-104.1769;8.6075
P247=-105.4543;9.0623
P248=-106.6285;9.6711
P249=-107.2869;10.0045
P250=-107.9454;10.3380
P251=-108.5751;10.7002
P252=-109.2049;11.0625
P253=-109.7834;11.4583
P254=-110.3619;11.8542
P255=-110.8956;12.3267
P256=-111.4293;12.7993
P257=-111.9049;13.3389
P258=-112.3806;13.8786
P259=-112.7837;14.4652
P260=-113.1868;15.0517
P261=-113.5200;15.6813
P262=-113.8532;16.3110
P263=-114.1422;16.9613
P264=-114.4312;17.6115
P265=-114.6960;18.2661
P266=-114.9609;18.9208
P267=-115.2206;19.5804
P268=-115.4803;20.2400
P269=-115.7403;20.9048
P270=-116.0004;21.5695
P271=-116.2476;22.2400
P272=-116.4948;22.9106
P273=-116.7233;23.5875
P274=-116.9517;24.2644
P275=-117.1468;24.9511
P276=-117.3420;25.6378
P277=-117.4988;26.3350
P278=-117.6556;27.0322
P279=-117.7690;27.7375
P280=-117.8825;28.4428
P281=-117.9519;29.1552
P282=-118.0213;29.8676
P283=-118.0567;30.5812
P284=-118.0921;31.2947
P285=-118.0984;32.0072
P286=-118.1048;32.7196
P287=-118.1223;33.4338
P288=-118.1398;34.1481
P289=-118.1901;34.8657
P290=-118.2404;35.5832
P291=-118.2290;36.3029
P292=-118.2177;37.0226
P293=-118.0401;37.7432
P294=-117.8625;38.4638

[C9]

gain=-40.00

n_point=79

P1=-92.5000 ;21.6930
P2=-92.7500 ;21.6365
P3=-93.0000 ;21.5800
P4=-93.1030 ;21.5000
P5=-93.3015 ;21.3590
P6=-93.5000 ;21.2180
P7=-93.6315 ;21.1090
P8=-93.7630 ;21.0000
P9=-94.0000 ;20.8520
P10=-94.2055 ;20.6760
P11=-94.4110 ;20.5000
P12=-94.5000 ;20.4250
P13=-94.6667 ;20.3150
P14=-94.8333 ;20.2050
P15=-95.0000 ;20.0950
P16=-95.1400 ;20.0000
P17=-95.3200 ;19.9105
P18=-95.5000 ;19.8210
P19=-95.7500 ;19.7055
P20=-96.0000 ;19.5900
P21=-96.2350 ;19.5000
P22=-96.5000 ;19.4550
P23=-96.7500 ;19.4460
P24=-97.0000 ;19.4370
P25=-97.2500 ;19.4250
P26=-97.5000 ;19.4130
P27=-97.7500 ;19.4115
P28=-98.0000 ;19.4100
P29=-98.2500 ;19.4105
P30=-98.5000 ;19.4110
P31=-98.7500 ;19.3755
P32=-99.0000 ;19.3400
P33=-99.2500 ;19.2830
P34=-99.5000 ;19.2260
P35=-99.7500 ;19.1500
P36=-100.0000;19.0740
P37=-100.2140;19.0000
P38=-100.0000;18.8860
P39=-99.7500 ;18.7635
P40=-99.5000 ;18.6410
P41=-99.2640 ;18.5705
P42=-99.0280 ;18.5000
P43=-99.0000 ;18.4910
P44=-98.7500 ;18.4195
P45=-98.5000 ;18.3480
P46=-98.2500 ;18.2910
P47=-98.0000 ;18.2340
P48=-97.7500 ;18.1950
P49=-97.5000 ;18.1560
P50=-97.2500 ;18.1455
P51=-97.0000 ;18.1350
P52=-96.7500 ;18.1605
P53=-96.5000 ;18.1860
P54=-96.2500 ;18.2590

P55=-96.0000 ;18.3320
P56=-95.8360 ;18.4160
P57=-95.6720 ;18.5000
P58=-95.5000 ;18.5470
P59=-95.2500 ;18.6525
P60=-95.0000 ;18.7580
P61=-94.8500 ;18.8790
P62=-94.7000 ;19.0000
P63=-94.5000 ;19.1210
P64=-94.3100 ;19.3105
P65=-94.1200 ;19.5000
P66=-94.0000 ;19.6040
P67=-93.8050 ;19.8020
P68=-93.6100 ;20.0000
P69=-93.5000 ;20.1330
P70=-93.3395 ;20.3165
P71=-93.1790 ;20.5000
P72=-93.0895 ;20.6205
P73=-93.0000 ;20.7410
P74=-92.8830 ;20.8705
P75=-92.7660 ;21.0000
P76=-92.6330 ;21.2020
P77=-92.5000 ;21.4040
P78=-92.4160 ;21.5000
P79=-92.5000 ;21.6930
[C10]
gain=-30.00
n_point=161
P1=-91.5000 ;32.7470
P2=-91.4390 ;32.5000
P3=-91.3570 ;32.0000
P4=-91.2690 ;31.5000
P5=-91.2300 ;31.0000
P6=-91.2480 ;30.5000
P7=-91.3100 ;30.0000
P8=-91.4030 ;29.5000
P9=-91.5000 ;29.1890
P10=-91.5580 ;29.0000
P11=-91.7440 ;28.5000
P12=-91.9130 ;28.0000
P13=-92.0000 ;27.6180
P14=-92.0630 ;27.5000
P15=-92.3310 ;27.0000
P16=-92.5000 ;26.5370
P17=-92.5280 ;26.5000
P18=-92.8480 ;26.0000
P19=-93.0000 ;25.7310
P20=-93.2170 ;25.5000
P21=-93.5000 ;25.1370
P22=-93.6420 ;25.0000
P23=-94.0000 ;24.5870
P24=-94.0880 ;24.5000
P25=-94.5000 ;24.0170
P26=-94.5130 ;24.0000
P27=-94.9740 ;23.5000
P28=-95.0000 ;23.4740
P29=-95.5000 ;23.0270

P30=-95.5330 ;23.0000
P31=-96.0000 ;22.7180
P32=-96.4470 ;22.5000
P33=-96.5000 ;22.4800
P34=-97.0000 ;22.3680
P35=-97.5000 ;22.3280
P36=-98.0000 ;22.3370
P37=-98.5000 ;22.3530
P38=-99.0000 ;22.3250
P39=-99.5000 ;22.2700
P40=-100.0000;22.2270
P41=-100.5000;22.2310
P42=-101.0000;22.3710
P43=-101.0680;22.5000
P44=-101.5000;22.7200
P45=-101.7480;23.0000
P46=-102.0000;23.2430
P47=-102.2370;23.5000
P48=-102.5000;23.9630
P49=-102.5310;24.0000
P50=-102.5000;24.1210
P51=-102.4390;24.5000
P52=-102.2390;25.0000
P53=-102.5000;25.2950
P54=-102.8880;25.5000
P55=-103.0000;25.5500
P56=-103.1860;25.5000
P57=-103.5000;25.1370
P58=-103.6740;25.0000
P59=-104.0000;24.8310
P60=-104.5000;24.9410
P61=-104.7000;25.0000
P62=-105.0000;25.1250
P63=-105.5000;25.2730
P64=-106.0000;25.3560
P65=-106.5000;25.2940
P66=-107.0000;25.0210
P67=-107.5000;25.0050
P68=-108.0000;25.1950
P69=-108.3640;25.5000
P70=-108.5000;25.6290
P71=-108.7360;26.0000
P72=-109.0000;26.4780
P73=-109.0100;26.5000
P74=-109.1800;27.0000
P75=-109.3060;27.5000
P76=-109.4120;28.0000
P77=-109.4930;28.5000
P78=-109.5000;28.5730
P79=-109.5350;29.0000
P80=-109.5450;29.5000
P81=-109.5320;30.0000
P82=-109.5010;30.5000
P83=-109.5000;30.5060
P84=-109.4130;31.0000
P85=-109.2940;31.5000
P86=-109.1400;32.0000

P87=-109.0000;32.4580
P88=-108.9450;32.5000
P89=-108.5000;32.8920
P90=-108.3110;32.5000
P91=-108.0610;32.0000
P92=-108.0000;31.8900
P93=-107.5000;31.8760
P94=-107.4540;32.0000
P95=-107.2250;32.5000
P96=-107.0000;32.8370
P97=-106.9150;33.0000
P98=-106.5980;33.5000
P99=-106.5000;33.6240
P100=-106.1650;34.0000
P101=-106.0000;34.1880
P102=-105.5260;34.5000
P103=-105.5000;34.5200
P104=-105.4020;34.5000
P105=-105.0000;34.4130
P106=-104.5000;34.0320
P107=-104.0000;34.1100
P108=-103.5000;34.3500
P109=-103.2780;34.5000
P110=-103.0000;34.6570
P111=-102.5000;34.9950
P112=-102.4920;35.0000
P113=-102.0810;35.5000
P114=-102.0240;36.0000
P115=-102.0000;36.1020
P116=-101.8960;36.5000
P117=-101.5000;36.9020
P118=-101.3970;37.0000
P119=-101.0000;37.2620
P120=-100.6320;37.5000
P121=-100.5000;37.6290
P122=-100.0940;38.0000
P123=-100.1990;38.5000
P124=-100.3830;39.0000
P125=-100.4220;39.5000
P126=-100.2330;40.0000
P127=-100.0000;40.2580
P128=-99.7140 ;40.5000
P129=-99.5000 ;40.6120
P130=-99.0000 ;40.7910
P131=-98.5000 ;40.8800
P132=-98.0000 ;40.8880
P133=-97.5000 ;40.8230
P134=-97.0000 ;40.6840
P135=-96.5000 ;40.5050
P136=-96.4880 ;40.5000
P137=-96.0000 ;40.2000
P138=-95.6850 ;40.0000
P139=-95.5000 ;39.8400
P140=-95.1110 ;39.5000
P141=-95.0000 ;39.3740
P142=-94.6810 ;39.0000
P143=-94.5000 ;38.7390

P144=-94.3490 ;38.5000
P145=-94.0820 ;38.0000
P146=-94.0000 ;37.8620
P147=-93.8380 ;37.5000
P148=-93.5910 ;37.0000
P149=-93.5000 ;36.8470
P150=-93.3590 ;36.5000
P151=-93.1000 ;36.0000
P152=-93.0000 ;35.8290
P153=-92.8790 ;35.5000
P154=-92.5860 ;35.0000
P155=-92.5000 ;34.8890
P156=-92.3150 ;34.5000
P157=-92.0000 ;34.0160
P158=-91.9940 ;34.0000
P159=-91.7920 ;33.5000
P160=-91.5900 ;33.0000
P161=-91.5000 ;32.7470

[C11]

gain=-10.00

n_point=109

P1=-95.0000 ;30.5430
P2=-94.9900 ;30.5000
P3=-94.9620 ;30.2500
P4=-94.9340 ;30.0000
P5=-94.9335 ;29.7500
P6=-94.9330 ;29.5000
P7=-94.9570 ;29.2500
P8=-94.9810 ;29.0000
P9=-95.0000 ;28.9020
P10=-95.0520 ;28.7010
P11=-95.1040 ;28.5000
P12=-95.1880 ;28.2500
P13=-95.2720 ;28.0000
P14=-95.3695 ;27.7500
P15=-95.4670 ;27.5000
P16=-95.5000 ;27.4230
P17=-95.6320 ;27.2115
P18=-95.7640 ;27.0000
P19=-95.8820 ;26.8275
P20=-96.0000 ;26.6550
P21=-96.1420 ;26.5000
P22=-96.3210 ;26.3235
P23=-96.5000 ;26.1470
P24=-96.7400 ;26.0000
P25=-97.0000 ;25.8620
P26=-97.2500 ;25.7975
P27=-97.5000 ;25.7330
P28=-97.7500 ;25.7365
P29=-98.0000 ;25.7400
P30=-98.2500 ;25.7860
P31=-98.5000 ;25.8320
P32=-98.7500 ;25.8960
P33=-99.0000 ;25.9600
P34=-99.1640 ;26.0000
P35=-99.5000 ;26.0960
P36=-99.7500 ;26.1505

P37=-100.0000;26.2050
P38=-100.2500;26.2485
P39=-100.5000;26.2920
P40=-100.7500;26.3445
P41=-101.0000;26.3970
P42=-101.3390;26.5000
P43=-101.5000;26.5590
P44=-101.7500;26.6825
P45=-102.0000;26.8060
P46=-102.3240;27.0000
P47=-102.5000;27.1330
P48=-102.7050;27.3165
P49=-102.9100;27.5000
P50=-103.0000;27.6030
P51=-103.1495;27.8015
P52=-103.2990;28.0000
P53=-103.3995;28.1840
P54=-103.5000;28.3680
P55=-103.5640;28.5000
P56=-103.6475;28.7500
P57=-103.7310;29.0000
P58=-103.7730;29.2500
P59=-103.8150;29.5000
P60=-103.8250;29.7500
P61=-103.8350;30.0000
P62=-103.8080;30.2500
P63=-103.7810;30.5000
P64=-103.7200;30.7500
P65=-103.6590;31.0000
P66=-103.5795;31.2135
P67=-103.5000;31.4270
P68=-103.4680;31.5000
P69=-103.3120;31.7500
P70=-103.1560;32.0000
P71=-103.0000;32.2000
P72=-102.8470;32.3500
P73=-102.6940;32.5000
P74=-102.5000;32.6540
P75=-102.2500;32.8015
P76=-102.0000;32.9490
P77=-101.8460;33.0000
P78=-101.5000;33.0940
P79=-101.2500;33.1215
P80=-101.0000;33.1490
P81=-100.7500;33.1245
P82=-100.5000;33.1000
P83=-100.1650;33.0000
P84=-100.0000;32.9470
P85=-99.7500 ;32.8205
P86=-99.5000 ;32.6940
P87=-99.3075 ;32.5970
P88=-99.1150 ;32.5000
P89=-99.0000 ;32.4430
P90=-98.7500 ;32.3585
P91=-98.5000 ;32.2740
P92=-98.2500 ;32.2555
P93=-98.0000 ;32.2370

P94=-97.7500 ;32.2565
P95=-97.5000 ;32.2760
P96=-97.2500 ;32.2960
P97=-97.0000 ;32.3160
P98=-96.7500 ;32.2995
P99=-96.5000 ;32.2830
P100=-96.2500 ;32.1900
P101=-96.0000 ;32.0970
P102=-95.8590 ;32.0000
P103=-95.6795 ;31.8350
P104=-95.5000 ;31.6700
P105=-95.3870 ;31.5000
P106=-95.2680 ;31.2500
P107=-95.1490 ;31.0000
P108=-95.0745 ;30.7715
P109=-95.0000 ;30.5430
[C12]
gain=-6.00
n_point=97
P1=-95.5000 ;29.9090
P2=-95.4900 ;29.7045
P3=-95.4800 ;29.5000
P4=-95.4900 ;29.3455
P5=-95.5000 ;29.1910
P6=-95.5170 ;29.0000
P7=-95.5805 ;28.7500
P8=-95.6440 ;28.5000
P9=-95.7350 ;28.2500
P10=-95.8260 ;28.0000
P11=-95.9130 ;27.8175
P12=-96.0000 ;27.6350
P13=-96.0880 ;27.5000
P14=-96.2167 ;27.3333
P15=-96.3453 ;27.1667
P16=-96.4740 ;27.0000
P17=-96.5000 ;26.9720
P18=-96.7500 ;26.7990
P19=-97.0000 ;26.6260
P20=-97.1645 ;26.5630
P21=-97.3290 ;26.5000
P22=-97.5000 ;26.4470
P23=-97.7500 ;26.4365
P24=-98.0000 ;26.4260
P25=-98.2500 ;26.4595
P26=-98.5000 ;26.4930
P27=-98.5290 ;26.5000
P28=-98.7645 ;26.5650
P29=-99.0000 ;26.6300
P30=-99.2500 ;26.6955
P31=-99.5000 ;26.7610
P32=-99.7500 ;26.8115
P33=-100.0000;26.8620
P34=-100.2500;26.9070
P35=-100.5000;26.9520
P36=-100.7150;27.0000
P37=-101.0000;27.0810
P38=-101.2500;27.1860

P39=-101.5000;27.2910
P40=-101.6860;27.3955
P41=-101.8720;27.5000
P42=-102.0000;27.5920
P43=-102.2180;27.7960
P44=-102.4360;28.0000
P45=-102.5000;28.0820
P46=-102.6315;28.2910
P47=-102.7630;28.5000
P48=-102.8755;28.7500
P49=-102.9880;29.0000
P50=-103.0000;29.0530
P51=-103.0405;29.2765
P52=-103.0810;29.5000
P53=-103.0900;29.7500
P54=-103.0990;30.0000
P55=-103.0660;30.2500
P56=-103.0330;30.5000
P57=-103.0000;30.6150
P58=-102.9275;30.8075
P59=-102.8550;31.0000
P60=-102.7105;31.2500
P61=-102.5660;31.5000
P62=-102.5000;31.5810
P63=-102.2710;31.7905
P64=-102.0420;32.0000
P65=-102.0000;32.0300
P66=-101.7500;32.1365
P67=-101.5000;32.2430
P68=-101.2500;32.2880
P69=-101.0000;32.3330
P70=-100.7500;32.3110
P71=-100.5000;32.2890
P72=-100.2500;32.2185
P73=-100.0000;32.1480
P74=-99.8125 ;32.0740
P75=-99.6250 ;32.0000
P76=-99.5000 ;31.9470
P77=-99.2500 ;31.8475
P78=-99.0000 ;31.7480
P79=-98.7500 ;31.6960
P80=-98.5000 ;31.6440
P81=-98.2500 ;31.6345
P82=-98.0000 ;31.6250
P83=-97.7500 ;31.6325
P84=-97.5000 ;31.6400
P85=-97.2500 ;31.6330
P86=-97.0000 ;31.6260
P87=-96.7500 ;31.5700
P88=-96.5000 ;31.5140
P89=-96.4740 ;31.5000
P90=-96.2370 ;31.3165
P91=-96.0000 ;31.1330
P92=-95.9010 ;31.0000
P93=-95.7725 ;30.7500
P94=-95.6440 ;30.5000
P95=-95.5755 ;30.2500

P96=-95.5070 ;30.0000
P97=-95.5000 ;29.9090
[C13]
gain=-4.00
n_point=89
P1=-96.0000 ;30.2200
P2=-95.9320 ;30.0000
P3=-95.9030 ;29.7500
P4=-95.8740 ;29.5000
P5=-95.8865 ;29.2500
P6=-95.8990 ;29.0000
P7=-95.9495 ;28.7595
P8=-96.0000 ;28.5190
P9=-96.0060 ;28.5000
P10=-96.0840 ;28.3333
P11=-96.1620 ;28.1667
P12=-96.2400 ;28.0000
P13=-96.3700 ;27.7905
P14=-96.5000 ;27.5810
P15=-96.5750 ;27.5000
P16=-96.7167 ;27.3800
P17=-96.8583 ;27.2600
P18=-97.0000 ;27.1400
P19=-97.1485 ;27.0700
P20=-97.2970 ;27.0000
P21=-97.5000 ;26.9260
P22=-97.7500 ;26.9065
P23=-98.0000 ;26.8870
P24=-98.2500 ;26.9185
P25=-98.5000 ;26.9500
P26=-98.7270 ;27.0000
P27=-99.0000 ;27.0760
P28=-99.2500 ;27.1430
P29=-99.5000 ;27.2100
P30=-99.7500 ;27.2620
P31=-100.0000;27.3140
P32=-100.2500;27.3635
P33=-100.5000;27.4130
P34=-100.6705;27.4565
P35=-100.8410;27.5000
P36=-101.0000;27.5530
P37=-101.1667;27.6380
P38=-101.3333;27.7230
P39=-101.5000;27.8080
P40=-101.6370;27.9040
P41=-101.7740;28.0000
P42=-101.8870;28.1085
P43=-102.0000;28.2170
P44=-102.1095;28.3585
P45=-102.2190;28.5000
P46=-102.3100;28.6667
P47=-102.4010;28.8333
P48=-102.4920;29.0000
P49=-102.5000;29.0310
P50=-102.5480;29.2655
P51=-102.5960;29.5000
P52=-102.6030;29.7500

P53=-102.6100;30.0000
P54=-102.5640;30.2500
P55=-102.5180;30.5000
P56=-102.5000;30.5460
P57=-102.3835;30.7730
P58=-102.2670;31.0000
P59=-102.1335;31.1715
P60=-102.0000;31.3430
P61=-101.7980;31.5000
P62=-101.6490;31.5820
P63=-101.5000;31.6640
P64=-101.2500;31.7285
P65=-101.0000;31.7930
P66=-100.7500;31.7810
P67=-100.5000;31.7690
P68=-100.2500;31.7065
P69=-100.0000;31.6440
P70=-99.7905 ;31.5720
P71=-99.5810 ;31.5000
P72=-99.5000 ;31.4670
P73=-99.2500 ;31.3770
P74=-99.0000 ;31.2870
P75=-98.7500 ;31.2430
P76=-98.5000 ;31.1990
P77=-98.2500 ;31.1910
P78=-98.0000 ;31.1830
P79=-97.7500 ;31.1835
P80=-97.5000 ;31.1840
P81=-97.2500 ;31.1560
P82=-97.0000 ;31.1280
P83=-96.8350 ;31.0640
P84=-96.6700 ;31.0000
P85=-96.5000 ;30.9030
P86=-96.3220 ;30.7015
P87=-96.1440 ;30.5000
P88=-96.0720 ;30.3600
P89=-96.0000 ;30.2200
[C14]
gain=-2.00
n_point=91
P1=-96.5000 ;29.7530
P2=-96.4690 ;29.6265
P3=-96.4380 ;29.5000
P4=-96.4367 ;29.3333
P5=-96.4353 ;29.1667
P6=-96.4340 ;29.0000
P7=-96.4670 ;28.8635
P8=-96.5000 ;28.7270
P9=-96.5405 ;28.6135
P10=-96.5810 ;28.5000
P11=-96.6837 ;28.3333
P12=-96.7863 ;28.1667
P13=-96.8890 ;28.0000
P14=-97.0000 ;27.8800
P15=-97.1667 ;27.7807
P16=-97.3333 ;27.6813
P17=-97.5000 ;27.5820

P18=-97.6607 ;27.5547
P19=-97.8213 ;27.5273
P20=-97.9820 ;27.5000
P21=-98.0000 ;27.4980
P22=-98.0190 ;27.5000
P23=-98.1793 ;27.5250
P24=-98.3397 ;27.5500
P25=-98.5000 ;27.5750
P26=-98.6667 ;27.6210
P27=-98.8333 ;27.6670
P28=-99.0000 ;27.7130
P29=-99.1667 ;27.7540
P30=-99.3333 ;27.7950
P31=-99.5000 ;27.8360
P32=-99.6667 ;27.8670
P33=-99.8333 ;27.8980
P34=-100.0000;27.9290
P35=-100.1775;27.9645
P36=-100.3550;28.0000
P37=-100.5000;28.0410
P38=-100.6667;28.1103
P39=-100.8333;28.1797
P40=-101.0000;28.2490
P41=-101.1260;28.3327
P42=-101.2520;28.4163
P43=-101.3780;28.5000
P44=-101.5000;28.6190
P45=-101.5903;28.7460
P46=-101.6807;28.8730
P47=-101.7710;29.0000
P48=-101.8270;29.1667
P49=-101.8830;29.3333
P50=-101.9390;29.5000
P51=-101.9397;29.6667
P52=-101.9403;29.8333
P53=-101.9410;30.0000
P54=-101.8710;30.1667
P55=-101.8010;30.3333
P56=-101.7310;30.5000
P57=-101.6155;30.6375
P58=-101.5000;30.7750
P59=-101.3180;30.8875
P60=-101.1360;31.0000
P61=-101.0000;31.0550
P62=-100.8333;31.0613
P63=-100.6667;31.0677
P64=-100.5000;31.0740
P65=-100.3115;31.0370
P66=-100.1230;31.0000
P67=-100.0000;30.9700
P68=-99.8333 ;30.9073
P69=-99.6667 ;30.8447
P70=-99.5000 ;30.7820
P71=-99.3333 ;30.7357
P72=-99.1667 ;30.6893
P73=-99.0000 ;30.6430
P74=-98.8333 ;30.6243

P75=-98.6667 ;30.6057
P76=-98.5000 ;30.5870
P77=-98.3333 ;30.5843
P78=-98.1667 ;30.5817
P79=-98.0000 ;30.5790
P80=-97.8333 ;30.5707
P81=-97.6667 ;30.5623
P82=-97.5000 ;30.5540
P83=-97.3845 ;30.5270
P84=-97.2690 ;30.5000
P85=-97.1345 ;30.4500
P86=-97.0000 ;30.4000
P87=-96.8680 ;30.2667
P88=-96.7360 ;30.1333
P89=-96.6040 ;30.0000
P90=-96.5520 ;29.8765
P91=-96.5000 ;29.7530
[C15]
gain=-40.00
n_point=73
P1=-107.0000;22.7390
P2=-107.0445;22.6793
P3=-107.0890;22.6195
P4=-107.1335;22.5597
P5=-107.1780;22.5000
P6=-107.1572;22.4167
P7=-107.1363;22.3333
P8=-107.1155;22.2500
P9=-107.0947;22.1667
P10=-107.0738;22.0833
P11=-107.0530;22.0000
P12=-107.0000;21.9300
P13=-106.9413;21.8583
P14=-106.8827;21.7867
P15=-106.8240;21.7150
P16=-106.7653;21.6433
P17=-106.7067;21.5717
P18=-106.6480;21.5000
P19=-106.5740;21.4405
P20=-106.5000;21.3810
P21=-106.4167;21.3370
P22=-106.3333;21.2930
P23=-106.2500;21.2490
P24=-106.1667;21.2050
P25=-106.0833;21.1610
P26=-106.0000;21.1170
P27=-105.9022;21.0936
P28=-105.8044;21.0702
P29=-105.7066;21.0468
P30=-105.6088;21.0234
P31=-105.5110;21.0000
P32=-105.5000;20.9960
P33=-105.4000;20.9762
P34=-105.3000;20.9564
P35=-105.2000;20.9366
P36=-105.1000;20.9168
P37=-105.0000;20.8970

P38=-104.9190;20.9485
P39=-104.8380;21.0000
P40=-104.8920;21.0767
P41=-104.9460;21.1533
P42=-105.0000;21.2300
P43=-105.0270;21.2975
P44=-105.0540;21.3650
P45=-105.0810;21.4325
P46=-105.1080;21.5000
P47=-105.1733;21.5682
P48=-105.2387;21.6363
P49=-105.3040;21.7045
P50=-105.3693;21.7727
P51=-105.4347;21.8408
P52=-105.5000;21.9090
P53=-105.5265;21.9545
P54=-105.5530;22.0000
P55=-105.6169;22.0611
P56=-105.6807;22.1223
P57=-105.7446;22.1834
P58=-105.8084;22.2446
P59=-105.8723;22.3057
P60=-105.9361;22.3669
P61=-106.0000;22.4280
P62=-106.0675;22.4640
P63=-106.1350;22.5000
P64=-106.2080;22.5544
P65=-106.2810;22.6088
P66=-106.3540;22.6632
P67=-106.4270;22.7176
P68=-106.5000;22.7720
P69=-106.6000;22.7654
P70=-106.7000;22.7588
P71=-106.8000;22.7522
P72=-106.9000;22.7456
P73=-107.0000;22.7390
[C16]
gain=-50.00
n_point=80
P1=-109.0000;47.4890
P2=-109.0378;47.3667
P3=-109.0755;47.2445
P4=-109.1133;47.1222
P5=-109.1510;47.0000
P6=-109.1505;46.8750
P7=-109.1500;46.7500
P8=-109.1495;46.6250
P9=-109.1490;46.5000
P10=-109.0745;46.3485
P11=-109.0000;46.1970
P12=-108.8333;46.2657
P13=-108.6667;46.3343
P14=-108.5000;46.4030
P15=-108.4050;46.5000
P16=-108.2700;46.6037
P17=-108.1350;46.7073
P18=-108.0000;46.8110

P19=-107.9070;46.9055
P20=-107.8140;47.0000
P21=-107.7093;47.0923
P22=-107.6047;47.1847
P23=-107.5000;47.2770
P24=-107.3835;47.3885
P25=-107.2670;47.5000
P26=-107.1335;47.6250
P27=-107.0000;47.7500
P28=-106.8690;47.8750
P29=-106.7380;48.0000
P30=-106.6190;48.1285
P31=-106.5000;48.2570
P32=-106.3730;48.3785
P33=-106.2460;48.5000
P34=-106.1640;48.6057
P35=-106.0820;48.7113
P36=-106.0000;48.8170
P37=-105.9060;48.9085
P38=-105.8120;49.0000
P39=-105.7340;49.1162
P40=-105.6560;49.2325
P41=-105.5780;49.3487
P42=-105.5000;49.4650
P43=-105.4680;49.5000
P44=-105.4352;49.6250
P45=-105.4025;49.7500
P46=-105.3698;49.8750
P47=-105.3370;50.0000
P48=-105.4185;50.1210
P49=-105.5000;50.2420
P50=-105.6667;50.3210
P51=-105.8333;50.4000
P52=-106.0000;50.4790
P53=-106.2500;50.4415
P54=-106.5000;50.4040
P55=-106.6667;50.3223
P56=-106.8333;50.2407
P57=-107.0000;50.1590
P58=-107.0945;50.0795
P59=-107.1890;50.0000
P60=-107.3445;49.8885
P61=-107.5000;49.7770
P62=-107.6385;49.6385
P63=-107.7770;49.5000
P64=-107.8885;49.3850
P65=-108.0000;49.2700
P66=-108.1155;49.1350
P67=-108.2310;49.0000
P68=-108.3207;48.8590
P69=-108.4103;48.7180
P70=-108.5000;48.5770
P71=-108.5540;48.5000
P72=-108.6210;48.3750
P73=-108.6880;48.2500
P74=-108.7550;48.1250
P75=-108.8220;48.0000

P76=-108.8658;47.8750
P77=-108.9095;47.7500
P78=-108.9533;47.6250
P79=-108.9970;47.5000
P80=-109.0000;47.4890
[C17]
gain=-50.00
n_point=91
P1=-112.5000;49.0510
P2=-112.5070;49.0000
P3=-112.5000;48.9710
P4=-112.2500;48.9390
P5=-112.0000;48.9070
P6=-111.9160;49.0000
P7=-111.7080;49.2000
P8=-111.5000;49.4000
P9=-111.4150;49.5000
P10=-111.2075;49.7255
P11=-111.0000;49.9510
P12=-110.9590;50.0000
P13=-110.8585;50.1250
P14=-110.7580;50.2500
P15=-110.5570;50.5000
P16=-110.5000;50.5620
P17=-110.3120;50.7810
P18=-110.1240;51.0000
P19=-110.0000;51.1460
P20=-109.8420;51.3230
P21=-109.6840;51.5000
P22=-109.5000;51.7260
P23=-109.3765;51.8630
P24=-109.2530;52.0000
P25=-109.1265;52.1675
P26=-109.0000;52.3350
P27=-108.8530;52.5000
P28=-108.6765;52.7395
P29=-108.5000;52.9790
P30=-108.4810;53.0000
P31=-108.3735;53.1250
P32=-108.2660;53.2500
P33=-108.0510;53.5000
P34=-108.0000;53.5690
P35=-107.7995;53.7845
P36=-107.5990;54.0000
P37=-107.5000;54.1420
P38=-107.3335;54.3210
P39=-107.1670;54.5000
P40=-107.0835;54.6440
P41=-107.0000;54.7880
P42=-106.8310;55.0000
P43=-106.7295;55.2500
P44=-106.6280;55.5000
P45=-106.6875;55.7500
P46=-106.7470;56.0000
P47=-106.8735;56.1305
P48=-107.0000;56.2610
P49=-107.2175;56.3805

P50=-107.4350;56.5000
P51=-107.5000;56.5290
P52=-108.0000;56.5650
P53=-108.2250;56.5000
P54=-108.5000;56.4370
P55=-108.7500;56.3100
P56=-109.0000;56.1830
P57=-109.2260;56.0000
P58=-109.5000;55.8080
P59=-109.6530;55.6540
P60=-109.8060;55.5000
P61=-110.0000;55.3310
P62=-110.1505;55.1655
P63=-110.3010;55.0000
P64=-110.5000;54.7640
P65=-110.5975;54.6320
P66=-110.6950;54.5000
P67=-110.8440;54.2500
P68=-110.9930;54.0000
P69=-111.0000;53.9870
P70=-111.1360;53.7435
P71=-111.2720;53.5000
P72=-111.3780;53.2500
P73=-111.4840;53.0000
P74=-111.5000;52.9540
P75=-111.6040;52.7270
P76=-111.7080;52.5000
P77=-111.7990;52.2500
P78=-111.8900;52.0000
P79=-111.9450;51.7655
P80=-112.0000;51.5310
P81=-112.0100;51.5000
P82=-112.0705;51.2500
P83=-112.1310;51.0000
P84=-112.1935;50.7500
P85=-112.2560;50.5000
P86=-112.3015;50.2500
P87=-112.3470;50.0000
P88=-112.3780;49.7500
P89=-112.4090;49.5000
P90=-112.4545;49.2755
P91=-112.5000;49.0510
[C18]
gain=-50.00
n_point=102
P1=-116.5000;55.4170
P2=-116.5820;55.0000
P3=-116.7030;54.5000
P4=-116.7780;54.0000
P5=-116.8200;53.5000
P6=-116.8730;53.0000
P7=-116.9070;52.5000
P8=-116.9460;52.0000
P9=-116.9380;51.5000
P10=-116.9970;51.0000
P11=-116.8320;50.5000
P12=-116.5000;50.2770

P13=-116.4130;50.5000
P14=-116.2280;50.7500
P15=-116.0430;51.0000
P16=-116.0000;51.0600
P17=-115.8070;51.5000
P18=-115.6660;51.7500
P19=-115.5250;52.0000
P20=-115.5000;52.0340
P21=-115.2400;52.5000
P22=-115.0000;52.9390
P23=-114.9630;53.0000
P24=-114.8165;53.2500
P25=-114.6700;53.5000
P26=-114.5000;53.7940
P27=-114.3650;54.0000
P28=-114.1925;54.2500
P29=-114.0200;54.5000
P30=-114.0000;54.5300
P31=-113.6460;55.0000
P32=-113.5000;55.2210
P33=-113.2820;55.5000
P34=-113.0000;55.8860
P35=-112.9050;56.0000
P36=-112.7165;56.2500
P37=-112.5280;56.5000
P38=-112.5000;56.5480
P39=-112.1710;57.0000
P40=-112.0000;57.2510
P41=-111.7960;57.5000
P42=-111.5000;57.8960
P43=-111.4060;58.0000
P44=-111.2320;58.2500
P45=-111.0580;58.5000
P46=-111.0000;58.5830
P47=-110.6600;59.0000
P48=-110.5000;59.2380
P49=-110.2860;59.5000
P50=-110.0000;59.9820
P51=-109.9860;60.0000
P52=-109.8035;60.2500
P53=-109.6210;60.5000
P54=-109.5000;60.7110
P55=-109.2780;61.0000
P56=-109.0000;61.3840
P57=-108.8880;61.5000
P58=-108.5800;62.0000
P59=-108.5000;62.1480
P60=-108.2280;62.5000
P61=-108.4290;63.0000
P62=-108.5000;63.1690
P63=-108.6100;63.5000
P64=-109.0000;63.8610
P65=-109.1490;64.0000
P66=-109.5000;64.3170
P67=-109.7380;64.5000
P68=-110.0000;64.7250
P69=-110.3870;65.0000

P70=-110.5000;65.0810
P71=-111.0000;65.3090
P72=-111.5000;65.4600
P73=-112.0000;65.4460
P74=-112.5000;65.3350
P75=-113.0000;65.0300
P76=-113.0320;65.0000
P77=-113.5000;64.5900
P78=-113.5790;64.5000
P79=-114.0000;64.0510
P80=-114.0370;64.0000
P81=-114.3560;63.5000
P82=-114.5000;63.1790
P83=-114.5720;63.0000
P84=-114.7270;62.5000
P85=-114.8150;62.0000
P86=-114.9630;61.5000
P87=-114.9900;61.0000
P88=-115.0000;60.9740
P89=-115.1870;60.5000
P90=-115.3270;60.0000
P91=-115.4620;59.5000
P92=-115.5000;59.3610
P93=-115.6210;59.0000
P94=-115.7700;58.5000
P95=-115.8990;58.0000
P96=-115.9860;57.5000
P97=-116.0000;57.4340
P98=-116.1230;57.0000
P99=-116.2410;56.5000
P100=-116.3660;56.0000
P101=-116.4870;55.5000
P102=-116.5000;55.4170

[C19]

gain=-50.00

n_point=88

P1=-89.5000 ;14.6710
P2=-89.7170 ;14.5000
P3=-89.8585 ;14.3800
P4=-90.0000 ;14.2600
P5=-90.2000 ;14.1300
P6=-90.4000 ;14.0000
P7=-90.5000 ;13.9390
P8=-90.6667 ;13.8440
P9=-90.8333 ;13.7490
P10=-91.0000 ;13.6540
P11=-91.2050 ;13.5000
P12=-91.3525 ;13.4255
P13=-91.5000 ;13.3510
P14=-91.6520 ;13.2340
P15=-91.8040 ;13.1170
P16=-91.9560 ;13.0000
P17=-92.0000 ;12.9700
P18=-92.1667 ;12.8770
P19=-92.3333 ;12.7840
P20=-92.5000 ;12.6910
P21=-92.6250 ;12.5955

P22=-92.7500 ;12.5000
P23=-92.8750 ;12.4275
P24=-93.0000 ;12.3550
P25=-93.1600 ;12.2367
P26=-93.3200 ;12.1183
P27=-93.4800 ;12.0000
P28=-93.5000 ;11.9830
P29=-93.7500 ;11.8870
P30=-94.0000 ;11.7910
P31=-94.2500 ;11.6645
P32=-94.5000 ;11.5380
P33=-94.5900 ;11.5000
P34=-94.7950 ;11.4140
P35=-95.0000 ;11.3280
P36=-95.2500 ;11.2450
P37=-95.5000 ;11.1620
P38=-95.7500 ;11.0920
P39=-96.0000 ;11.0220
P40=-96.1760 ;11.0000
P41=-96.2300 ;10.7500
P42=-96.2840 ;10.5000
P43=-96.1420 ;10.4725
P44=-96.0000 ;10.4450
P45=-95.7500 ;10.3925
P46=-95.5000 ;10.3400
P47=-95.2500 ;10.3510
P48=-95.0000 ;10.3620
P49=-94.8035 ;10.4310
P50=-94.6070 ;10.5000
P51=-94.5000 ;10.5250
P52=-94.2500 ;10.5895
P53=-94.0000 ;10.6540
P54=-93.8333 ;10.7410
P55=-93.6667 ;10.8280
P56=-93.5000 ;10.9150
P57=-93.3770 ;11.0000
P58=-93.1885 ;11.0775
P59=-93.0000 ;11.1550
P60=-92.8490 ;11.2700
P61=-92.6980 ;11.3850
P62=-92.5470 ;11.5000
P63=-92.5000 ;11.5190
P64=-92.3333 ;11.6347
P65=-92.1667 ;11.7503
P66=-92.0000 ;11.8660
P67=-91.8480 ;12.0000
P68=-91.6740 ;12.0925
P69=-91.5000 ;12.1850
P70=-91.3235 ;12.3425
P71=-91.1470 ;12.5000
P72=-91.0000 ;12.6440
P73=-90.8030 ;12.8220
P74=-90.6060 ;13.0000
P75=-90.5000 ;13.1140
P76=-90.3580 ;13.2427
P77=-90.2160 ;13.3713
P78=-90.0740 ;13.5000

P79=-90.0000 ;13.6190
P80=-89.8503 ;13.7460
P81=-89.7007 ;13.8730
P82=-89.5510 ;14.0000
P83=-89.5000 ;14.0690
P84=-89.3497 ;14.2127
P85=-89.1993 ;14.3563
P86=-89.0490 ;14.5000
P87=-89.2745 ;14.5855
P88=-89.5000 ;14.6710
[C20]
gain=-50.00
n_point=75
P1=-91.5000 ;16.1970
P2=-91.6265 ;16.0985
P3=-91.7530 ;16.0000
P4=-91.8765 ;15.8990
P5=-92.0000 ;15.7980
P6=-92.1400 ;15.6987
P7=-92.2800 ;15.5993
P8=-92.4200 ;15.5000
P9=-92.5000 ;15.4350
P10=-92.6250 ;15.3688
P11=-92.7500 ;15.3025
P12=-92.8750 ;15.2362
P13=-93.0000 ;15.1700
P14=-93.1205 ;15.0850
P15=-93.2410 ;15.0000
P16=-93.3705 ;14.9370
P17=-93.5000 ;14.8740
P18=-93.6667 ;14.8037
P19=-93.8333 ;14.7333
P20=-94.0000 ;14.6630
P21=-94.1355 ;14.5815
P22=-94.2710 ;14.5000
P23=-94.3855 ;14.4330
P24=-94.5000 ;14.3660
P25=-94.6250 ;14.3042
P26=-94.7500 ;14.2425
P27=-94.8750 ;14.1807
P28=-95.0000 ;14.1190
P29=-95.1135 ;14.0595
P30=-95.2270 ;14.0000
P31=-95.3180 ;13.8987
P32=-95.4090 ;13.7973
P33=-95.5000 ;13.6960
P34=-95.6587 ;13.6307
P35=-95.8173 ;13.5653
P36=-95.9760 ;13.5000
P37=-95.8173 ;13.4523
P38=-95.6587 ;13.4047
P39=-95.5000 ;13.3570
P40=-95.3333 ;13.3757
P41=-95.1667 ;13.3943
P42=-95.0000 ;13.4130
P43=-94.8985 ;13.4565
P44=-94.7970 ;13.5000

P45=-94.6485 ;13.5400
P46=-94.5000 ;13.5800
P47=-94.3333 ;13.6217
P48=-94.1667 ;13.6633
P49=-94.0000 ;13.7050
P50=-93.8583 ;13.8033
P51=-93.7167 ;13.9017
P52=-93.5750 ;14.0000
P53=-93.5000 ;14.0470
P54=-93.3333 ;14.1233
P55=-93.1667 ;14.1997
P56=-93.0000 ;14.2760
P57=-92.8645 ;14.3880
P58=-92.7290 ;14.5000
P59=-92.6145 ;14.5970
P60=-92.5000 ;14.6940
P61=-92.3823 ;14.7960
P62=-92.2647 ;14.8980
P63=-92.1470 ;15.0000
P64=-92.0735 ;15.0860
P65=-92.0000 ;15.1720
P66=-91.8827 ;15.2813
P67=-91.7653 ;15.3907
P68=-91.6480 ;15.5000
P69=-91.5740 ;15.5950
P70=-91.5000 ;15.6900
P71=-91.3973 ;15.7933
P72=-91.2947 ;15.8967
P73=-91.1920 ;16.0000
P74=-91.3460 ;16.0985
P75=-91.5000 ;16.1970
[C21]
gain=-50.00
n_point=531
P1=-172.4033;61.7243
P2=-170.9863;61.5437
P3=-169.5810;61.3200
P4=-168.1903;61.0537
P5=-166.8140;60.7447
P6=-165.4521;60.3930
P7=-164.1047;59.9987
P8=-162.7718;59.5618
P9=-161.4533;59.0821
P10=-160.1493;58.5598
P11=-158.8597;57.9949
P12=-157.5846;57.3873
P13=-156.3258;56.7360
P14=-155.1017;56.0314
P15=-153.9173;55.2709
P16=-152.7723;54.4545
P17=-151.6669;53.5822
P18=-150.6010;52.6552
P19=-149.5733;51.6888
P20=-148.5834;50.6873
P21=-147.6313;49.6509
P22=-146.7170;48.5794
P23=-145.8281;47.4853

P24=-144.9548;46.3784
P25=-144.0969;45.2587
P26=-143.2549;44.1260
P27=-142.4497;42.9693
P28=-141.6934;41.7821
P29=-140.9861;40.5644
P30=-140.3170;39.3234
P31=-139.9902;38.6987
P32=-139.6634;38.0739
P33=-139.3441;37.4452
P34=-139.0247;36.8166
P35=-138.7138;36.1835
P36=-138.4029;35.5505
P37=-138.1100;34.9098
P38=-137.8170;34.2691
P39=-137.5443;33.6200
P40=-137.2716;32.9709
P41=-137.0191;32.3133
P42=-136.7665;31.6557
P43=-136.5259;30.9933
P44=-136.2854;30.3310
P45=-136.0454;29.6688
P46=-135.8054;29.0067
P47=-135.5659;28.3449
P48=-135.3263;27.6831
P49=-135.0882;27.0206
P50=-134.8501;26.3581
P51=-134.6147;25.6935
P52=-134.3794;25.0288
P53=-134.1469;24.3620
P54=-133.9144;23.6952
P55=-133.6872;23.0265
P56=-133.4601;22.3578
P57=-133.2440;21.6877
P58=-133.0280;21.0175
P59=-132.8232;20.3459
P60=-132.6185;19.6744
P61=-132.4238;19.0013
P62=-132.2290;18.3282
P63=-132.0337;17.6530
P64=-131.8384;16.9777
P65=-131.6400;16.3002
P66=-131.4417;15.6227
P67=-131.2413;14.9429
P68=-131.0410;14.2632
P69=-130.8777;13.5846
P70=-130.7144;12.9060
P71=-130.6083;12.2303
P72=-130.5022;11.5546
P73=-130.4534;10.8818
P74=-130.4045;10.2089
P75=-130.2785;8.8715
P76=-130.1017;8.2087
P77=-129.9250;7.5459
P78=-129.6339;6.8890
P79=-129.3427;6.2321
P80=-128.9741;5.6348

P81=-128.6055;5.0376
P82=-128.1319;4.5717
P83=-127.9876;4.9301
P84=-128.1725;6.1128
P85=-128.2982;6.8616
P86=-128.4240;7.6104
P87=-128.4975;8.9489
P88=-128.3928;10.1282
P89=-128.1778;11.2099
P90=-128.1865;12.4986
P91=-128.3253;13.2669
P92=-128.4640;14.0353
P93=-128.6906;14.8659
P94=-128.9171;15.6966
P95=-129.0733;16.3801
P96=-129.2296;17.0637
P97=-129.3755;18.1023
P98=-129.3508;18.7735
P99=-129.1255;18.7891
P100=-128.6939;18.0904
P101=-128.3748;17.3839
P102=-128.0557;16.6774
P103=-127.7325;15.8337
P104=-127.4093;14.9900
P105=-127.1784;14.2230
P106=-126.9475;13.4560
P107=-126.8089;12.7657
P108=-126.6703;12.0754
P109=-126.4616;10.8250
P110=-125.9351;9.6279
P111=-125.4975;9.0529
P112=-125.0599;8.4780
P113=-124.4724;7.9443
P114=-123.8848;7.4106
P115=-123.0714;6.9083
P116=-122.8289;7.1235
P117=-123.1572;8.0563
P118=-123.4847;8.7750
P119=-123.8121;9.4938
P120=-124.0746;10.2661
P121=-124.3372;11.0385
P122=-124.5296;11.8599
P123=-124.7220;12.6813
P124=-124.8323;13.4692
P125=-124.9425;14.2571
P126=-124.9219;15.2398
P127=-124.6542;15.5902
P128=-124.2253;15.3366
P129=-123.8302;14.5427
P130=-123.6533;13.8770
P131=-123.4764;13.2112
P132=-123.3091;12.3287
P133=-123.1417;11.4462
P134=-122.9160;10.6667
P135=-122.6903;9.8872
P136=-122.3946;9.2652
P137=-122.0988;8.6432

P138=-121.3673;7.7143
P139=-120.4963;6.8552
P140=-119.9913;6.3328
P141=-119.4863;5.8105
P142=-118.9117;5.1954
P143=-118.3371;4.5802
P144=-117.7742;3.9491
P145=-117.2112;3.3179
P146=-116.9013;2.7745
P147=-117.5133;3.0502
P148=-118.2652;3.5827
P149=-119.0170;4.1151
P150=-119.7259;4.5605
P151=-120.4347;5.0058
P152=-121.2966;5.2595
P153=-121.6029;4.8762
P154=-121.3816;3.9338
P155=-120.8191;2.9488
P156=-119.9496;2.0160
P157=-119.3614;1.5756
P158=-118.7731;1.1352
P159=-118.0947;0.7133
P160=-117.4162;0.2915
P161=-116.7866;-0.1283
P162=-116.1571;-0.5480
P163=-115.5813;-0.9662
P164=-115.0055;-1.3844
P165=-113.9574;-2.2160
P166=-112.8623;-2.9777
P167=-112.2537;-3.3074
P168=-111.6452;-3.6370
P169=-110.9756;-3.9155
P170=-110.3060;-4.1940
P171=-109.5933;-4.4236
P172=-108.8806;-4.6532
P173=-108.1996;-4.8439
P174=-107.5185;-5.0346
P175=-106.2359;-5.3403
P176=-105.0066;-5.5616
P177=-104.3042;-5.5929
P178=-103.6018;-5.6242
P179=-102.7852;-5.5676
P180=-101.9685;-5.5110
P181=-101.0639;-5.3715
P182=-100.1594;-5.2320
P183=-98.9793 ;-4.9424
P184=-98.7010 ;-4.6948
P185=-99.3194 ;-4.4889
P186=-100.4251;-4.3106
P187=-101.7621;-4.1509
P188=-102.5428;-4.0793
P189=-103.3235;-4.0078
P190=-104.0872;-3.9059
P191=-104.8508;-3.8040
P192=-105.5313;-3.6521
P193=-106.2118;-3.5002
P194=-107.4065;-3.0963

P195=-108.5636;-2.5986
P196=-109.2316;-2.3082
P197=-109.8996;-2.0177
P198=-110.6587;-1.6856
P199=-111.4178;-1.3536
P200=-112.2151;-0.9952
P201=-113.0125;-0.6367
P202=-114.2019;-0.0043
P203=-114.9268;0.5267
P204=-115.1871;0.9554
P205=-114.9419;1.0940
P206=-114.1607;0.8007
P207=-113.5020;0.4381
P208=-112.8433;0.0755
P209=-112.0409;-0.3782
P210=-111.2386;-0.8318
P211=-110.5018;-1.1666
P212=-109.7651;-1.5013
P213=-109.0973;-1.7137
P214=-108.4294;-1.9261
P215=-107.1933;-2.1653
P216=-105.9270;-2.4196
P217=-104.6195;-2.7056
P218=-103.9359;-2.8348
P219=-103.2522;-2.9640
P220=-102.5018;-2.9634
P221=-101.7513;-2.9627
P222=-100.9303;-2.8205
P223=-100.1094;-2.6782
P224=-99.3348 ;-2.4403
P225=-98.5602 ;-2.2024
P226=-97.8937 ;-1.8453
P227=-98.1743 ;-1.6325
P228=-99.2659 ;-1.5210
P229=-99.9736 ;-1.4396
P230=-100.6813;-1.3581
P231=-101.5292;-1.2441
P232=-102.3772;-1.1300
P233=-103.2180;-0.9950
P234=-104.0589;-0.8599
P235=-104.8678;-0.6145
P236=-104.7491;-0.3982
P237=-103.7988;-0.2121
P238=-103.1281;-0.1372
P239=-102.4574;-0.0622
P240=-101.6183;-0.0056
P241=-100.7792;0.0509
P242=-99.8809 ;0.1082
P243=-98.9826 ;0.1656
P244=-97.8589 ;0.4216
P245=-97.4802 ;0.8316
P246=-97.8292 ;1.3578
P247=-98.7658 ;1.6919
P248=-99.5125 ;1.7290
P249=-100.2591;1.7661
P250=-101.2177;1.7009
P251=-102.1763;1.6356

P252=-102.9329;1.6400
P253=-103.6895;1.6443
P254=-104.6557;1.8517
P255=-105.0656;2.2332
P256=-104.8115;2.5002
P257=-103.8621;2.5694
P258=-103.0666;2.5196
P259=-102.2711;2.4699
P260=-101.4246;2.4826
P261=-100.5782;2.4952
P262=-99.7509 ;2.6082
P263=-98.9236 ;2.7211
P264=-98.1466 ;2.9217
P265=-97.3695 ;3.1223
P266=-96.3082 ;3.5378
P267=-95.8082 ;3.9398
P268=-95.8786 ;4.3169
P269=-96.6338 ;4.5281
P270=-97.3711 ;4.5293
P271=-98.1083 ;4.5306
P272=-99.1253 ;4.4507
P273=-100.1423;4.3708
P274=-100.8999;4.3660
P275=-101.6575;4.3613
P276=-102.4526;4.5604
P277=-102.5338;4.9433
P278=-101.9652;5.2602
P279=-100.7633;5.4468
P280=-99.9058 ;5.4911
P281=-99.0483 ;5.5353
P282=-98.2431 ;5.6129
P283=-97.4379 ;5.6905
P284=-96.7287 ;5.8131
P285=-96.0195 ;5.9357
P286=-94.7801 ;6.2731
P287=-93.5527 ;6.7315
P288=-92.9192 ;7.0257
P289=-92.2858 ;7.3199
P290=-91.6325 ;7.6790
P291=-90.9792 ;8.0381
P292=-90.3411 ;8.4290
P293=-89.7029 ;8.8199
P294=-89.1278 ;9.1969
P295=-88.5526 ;9.5739
P296=-87.5291 ;10.2997
P297=-86.5820 ;11.0518
P298=-86.0600 ;11.5358
P299=-85.5380 ;12.0197
P300=-84.9602 ;12.6195
P301=-84.3823 ;13.2192
P302=-83.7514 ;13.9307
P303=-83.1206 ;14.6422
P304=-82.5931 ;15.2362
P305=-82.0657 ;15.8301
P306=-81.3976 ;16.5192
P307=-81.1162 ;16.7095
P308=-81.2195 ;16.4040

P309=-81.5989 ;15.7609
P310=-82.1921 ;14.8705
P311=-82.5957 ;14.3017
P312=-82.9993 ;13.7329
P313=-83.4957 ;13.0708
P314=-83.9921 ;12.4087
P315=-84.5125 ;11.8012
P316=-85.0329 ;11.1937
P317=-85.5682 ;10.6603
P318=-86.1035 ;10.1270
P319=-86.6537 ;9.6678
P320=-87.2038 ;9.2086
P321=-87.7480 ;8.7930
P322=-88.2922 ;8.3774
P323=-89.2965 ;7.5275
P324=-90.2155 ;6.6569
P325=-91.0397 ;5.7747
P326=-91.3867 ;5.2409
P327=-91.0572 ;5.2432
P328=-90.0512 ;5.7818
P329=-89.2985 ;6.2602
P330=-88.5457 ;6.7386
P331=-87.8486 ;7.2227
P332=-87.1515 ;7.7067
P333=-86.5359 ;8.1793
P334=-85.9203 ;8.6519
P335=-85.3861 ;9.1130
P336=-84.8519 ;9.5741
P337=-83.9141 ;10.4814
P338=-82.9984 ;11.4003
P339=-82.0962 ;12.3330
P340=-81.2073 ;13.2796
P341=-80.7561 ;13.7942
P342=-80.3048 ;14.3087
P343=-79.8253 ;14.9195
P344=-79.3457 ;15.5302
P345=-78.8376 ;16.2378
P346=-78.3294 ;16.9454
P347=-77.8297 ;17.6726
P348=-77.3299 ;18.3997
P349=-76.6794 ;19.1986
P350=-76.4178 ;19.2586
P351=-76.5359 ;18.6221
P352=-76.9387 ;17.7192
P353=-77.6016 ;16.6620
P354=-78.0630 ;16.0561
P355=-78.5245 ;15.4503
P356=-79.0614 ;14.8011
P357=-79.5983 ;14.1518
P358=-80.0628 ;13.5504
P359=-80.5273 ;12.9489
P360=-81.2950 ;11.8521
P361=-81.9250 ;10.8518
P362=-82.7157 ;9.8322
P363=-83.2369 ;9.2950
P364=-83.7580 ;8.7579
P365=-84.4049 ;8.1934

P366=-85.0518 ;7.6289
P367=-85.7442 ;7.0713
P368=-86.4366 ;6.5136
P369=-87.3784 ;5.6396
P370=-87.8344 ;5.0250
P371=-87.8094 ;4.6743
P372=-87.4162 ;4.6909
P373=-86.7021 ;5.1181
P374=-85.6672 ;5.9560
P375=-85.0089 ;6.5565
P376=-84.3507 ;7.1570
P377=-83.7197 ;7.7353
P378=-83.0888 ;8.3137
P379=-82.5236 ;8.8233
P380=-81.9584 ;9.3330
P381=-80.9595 ;10.2149
P382=-80.0530 ;11.0484
P383=-79.1655 ;12.0011
P384=-78.7303 ;12.5391
P385=-78.2952 ;13.0771
P386=-77.8685 ;13.6750
P387=-77.4417 ;14.2730
P388=-77.0167 ;14.8768
P389=-76.5916 ;15.4806
P390=-76.1651 ;16.0638
P391=-75.7387 ;16.6469
P392=-75.3107 ;17.2094
P393=-74.8828 ;17.7719
P394=-74.4609 ;18.3235
P395=-74.0390 ;18.8752
P396=-73.6414 ;19.4401
P397=-73.2439 ;20.0050
P398=-72.8716 ;20.5842
P399=-72.4993 ;21.1633
P400=-72.1499 ;21.7568
P401=-71.8005 ;22.3502
P402=-71.4480 ;22.9587
P403=-71.0955 ;23.5673
P404=-70.7324 ;24.1911
P405=-70.3693 ;24.8149
P406=-69.9957 ;25.4539
P407=-69.6220 ;26.0930
P408=-69.2518 ;26.7282
P409=-68.8815 ;27.3634
P410=-68.1944 ;28.5632
P411=-67.5613 ;29.6912
P412=-66.9794 ;30.7512
P413=-66.3243 ;31.9032
P414=-65.9268 ;32.5680
P415=-65.5294 ;33.2328
P416=-65.0621 ;33.9865
P417=-64.5948 ;34.7401
P418=-64.1017 ;35.5068
P419=-63.6086 ;36.2735
P420=-62.9262 ;37.2225
P421=-62.5851 ;37.5230
P422=-62.5851 ;37.1752

P423=-62.8760 ;36.3282
P424=-63.3471 ;35.3114
P425=-63.9943 ;34.1368
P426=-64.4052 ;33.4712
P427=-64.8160 ;32.8057
P428=-65.2404 ;32.1301
P429=-65.6648 ;31.4545
P430=-66.0542 ;30.8137
P431=-66.4437 ;30.1729
P432=-66.7983 ;29.5669
P433=-67.1529 ;28.9608
P434=-67.8103 ;27.8048
P435=-68.4953 ;26.6461
P436=-69.2172 ;25.4780
P437=-69.5965 ;24.8892
P438=-69.9758 ;24.3004
P439=-70.3568 ;23.7006
P440=-70.7377 ;23.1008
P441=-71.1055 ;22.4845
P442=-71.4733 ;21.8682
P443=-71.8279 ;21.2355
P444=-72.1825 ;20.6027
P445=-72.5250 ;19.9566
P446=-72.8675 ;19.3105
P447=-73.2131 ;18.6975
P448=-73.5586 ;18.0846
P449=-74.2659 ;16.9557
P450=-74.9895 ;15.9238
P451=-75.7718 ;14.8775
P452=-76.2130 ;14.2926
P453=-76.6542 ;13.7077
P454=-77.1455 ;13.0611
P455=-77.6368 ;12.4146
P456=-78.1761 ;11.7083
P457=-78.7155 ;11.0021
P458=-79.1574 ;10.3890
P459=-79.5993 ;9.7759
P460=-80.1080 ;8.9249
P461=-80.2416 ;8.4491
P462=-80.0106 ;8.3545
P463=-79.4652 ;8.6702
P464=-78.6118 ;9.3999
P465=-78.0321 ;9.9708
P466=-77.4524 ;10.5418
P467=-76.8632 ;11.1787
P468=-76.2739 ;11.8156
P469=-75.7781 ;12.4178
P470=-75.2822 ;13.0200
P471=-74.8797 ;13.5876
P472=-74.4772 ;14.1552
P473=-73.8252 ;15.2323
P474=-73.1118 ;16.3216
P475=-72.7056 ;16.8785
P476=-72.2994 ;17.4355
P477=-71.8440 ;18.0048
P478=-71.3886 ;18.5740
P479=-70.9313 ;19.1509

P480=-70.4740 ;19.7278
P481=-70.0517 ;20.3088
P482=-69.6294 ;20.8898
P483=-69.2421 ;21.4750
P484=-68.8548 ;22.0601
P485=-68.4959 ;22.6495
P486=-68.1371 ;23.2388
P487=-67.7773 ;23.8326
P488=-67.4176 ;24.4263
P489=-67.0533 ;25.0245
P490=-66.6891 ;25.6227
P491=-66.3204 ;26.2253
P492=-65.9516 ;26.8279
P493=-65.5773 ;27.4315
P494=-65.2030 ;28.0352
P495=-64.8205 ;28.6310
P496=-64.4380 ;29.2267
P497=-64.0472 ;29.8142
P498=-63.6564 ;30.4016
P499=-62.8581 ;31.5599
P500=-62.0468 ;32.7058
P501=-61.2380 ;33.8571
P502=-60.4333 ;35.0159
P503=-59.6316 ;36.1808
P504=-58.7972 ;37.3190
P505=-57.9143 ;38.4156
P506=-56.9828 ;39.4707
P507=-56.0050 ;40.4858
P508=-55.0005 ;41.4743
P509=-53.9738 ;42.4395
P510=-52.9250 ;43.3813
P511=-51.8555 ;44.3005
P512=-50.7697 ;45.1998
P513=-49.6681 ;46.0794
P514=-48.5506 ;46.9391
P515=-47.4154 ;47.7753
P516=-46.2519 ;48.5670
P517=-45.0584 ;49.3108
P518=-43.8350 ;50.0070
P519=-42.5818 ;50.6554
P520=-41.2995 ;51.2565
P521=-40.0015 ;51.8178
P522=-38.6922 ;52.3417
P523=-37.3715 ;52.8280
P524=-36.0395 ;53.2769
P525=-34.6961 ;53.6883
P526=-33.3414 ;54.0622
P527=-31.9754 ;54.3987
P528=-30.5981 ;54.6977
P529=-29.2094 ;54.9593
P530=-27.8093 ;55.1833
P531=-26.4159 ;55.3677
[C22]
gain=-20.00
n_point=76
P1=-92.4176 ;31.6798
P2=-92.2534 ;31.0841

P3=-92.1923 ;30.4825
P4=-92.2241 ;29.8752
P5=-92.3296 ;29.2726
P6=-92.5128 ;28.7050
P7=-92.8464 ;28.1868
P8=-93.3581 ;28.2653
P9=-93.6469 ;28.8720
P10=-94.1133 ;28.7847
P11=-94.3220 ;28.1841
P12=-94.6100 ;27.6528
P13=-94.8700 ;27.1040
P14=-95.1409 ;26.5579
P15=-95.4142 ;26.0141
P16=-95.7097 ;25.4820
P17=-96.0484 ;24.9762
P18=-96.4677 ;24.5368
P19=-96.9982 ;24.2466
P20=-97.6033 ;24.2307
P21=-98.1774 ;24.4323
P22=-98.7517 ;24.6331
P23=-99.3455 ;24.7133
P24=-99.8579 ;24.4258
P25=-100.1175;23.9039
P26=-100.6665;24.0388
P27=-100.9057;24.6044
P28=-101.2367;25.1076
P29=-101.7161;25.4859
P30=-102.2353;25.8010
P31=-102.7737;26.0847
P32=-103.3142;26.3648
P33=-103.8498;26.6539
P34=-104.3568;26.9904
P35=-104.8361;27.3658
P36=-105.2731;27.7889
P37=-105.6104;28.2937
P38=-105.8278;28.8626
P39=-105.9310;29.4614
P40=-105.9056;30.0686
P41=-105.7411;30.6534
P42=-105.4620;31.1938
P43=-105.1127;31.6921
P44=-104.7274;32.1634
P45=-104.3384;32.6316
P46=-103.9270;33.0801
P47=-103.4758;33.4887
P48=-102.9830;33.8455
P49=-102.4486;34.1365
P50=-101.8861;34.3688
P51=-101.3198;34.5923
P52=-100.7941;34.8961
P53=-100.3838;35.3430
P54=-100.0150;35.8259
P55=-99.5068 ;36.1536
P56=-98.9018 ;36.2450
P57=-98.3051 ;36.1311
P58=-97.7913 ;35.8068
P59=-97.5463 ;35.2623

P60=-97.7682 ;34.7089
P61=-98.2512 ;34.3380
P62=-98.6298 ;33.8797
P63=-98.4335 ;33.3422
P64=-97.8606 ;33.1365
P65=-97.2606 ;33.2038
P66=-96.6635 ;33.3222
P67=-96.0579 ;33.2968
P68=-95.4911 ;33.0766
P69=-95.0258 ;32.6881
P70=-94.6569 ;32.2064
P71=-94.3170 ;31.6925
P72=-94.0935 ;31.1318
P73=-93.6356 ;30.8201
P74=-93.2685 ;31.2559
P75=-92.9893 ;31.7852
P76=-92.4176 ;31.6798
[C23]
gain=-15.00
n_point=103
P1=-101.6292;33.7020
P2=-102.0927;33.5633
P3=-102.5216;33.3420
P4=-102.9368;33.0958
P5=-103.3033;32.7802
P6=-103.4674;32.6028
P7=-103.6315;32.4255
P8=-103.7817;32.2360
P9=-103.9318;32.0465
P10=-104.0697;31.8480
P11=-104.2077;31.6496
P12=-104.3282;31.4402
P13=-104.4487;31.2308
P14=-104.5487;31.0108
P15=-104.6486;30.7907
P16=-104.7208;30.5605
P17=-104.7930;30.3302
P18=-104.8202;30.0900
P19=-104.8473;29.8497
P20=-104.8484;29.6083
P21=-104.8495;29.3669
P22=-104.7907;29.1329
P23=-104.7320;28.8989
P24=-104.6624;28.6671
P25=-104.5927;28.4353
P26=-104.4659;28.2309
P27=-104.3390;28.0265
P28=-104.1901;27.8363
P29=-104.0413;27.6460
P30=-103.8685;27.4767
P31=-103.6958;27.3074
P32=-103.5067;27.1573
P33=-103.3176;27.0072
P34=-103.1151;26.8750
P35=-102.9127;26.7428
P36=-102.4925;26.5045
P37=-102.0640;26.2806

P38=-101.6252;26.0776
P39=-101.1836;25.8808
P40=-100.9727;25.7628
P41=-100.7618;25.6449
P42=-100.5655;25.5040
P43=-100.3692;25.3630
P44=-100.1815;25.2103
P45=-99.9938 ;25.0575
P46=-99.5372 ;25.0716
P47=-99.0830 ;25.2372
P48=-98.6056 ;25.2238
P49=-98.1388 ;25.0953
P50=-97.6655 ;24.9938
P51=-97.1854 ;25.0233
P52=-96.7435 ;25.2160
P53=-96.5515 ;25.3620
P54=-96.3594 ;25.5081
P55=-96.1991 ;25.6889
P56=-96.0387 ;25.8697
P57=-95.8997 ;26.0674
P58=-95.7608 ;26.2651
P59=-95.6349 ;26.4715
P60=-95.5090 ;26.6778
P61=-95.3909 ;26.8887
P62=-95.2727 ;27.0996
P63=-95.1688 ;27.3178
P64=-95.0649 ;27.5359
P65=-94.9673 ;27.7573
P66=-94.8698 ;27.9787
P67=-94.7730 ;28.2003
P68=-94.6761 ;28.4218
P69=-94.5430 ;28.6155
P70=-94.4099 ;28.8092
P71=-93.9356 ;28.8825
P72=-93.7900 ;29.0715
P73=-93.6443 ;29.2604
P74=-93.6216 ;29.5002
P75=-93.5988 ;29.7400
P76=-93.5917 ;29.9805
P77=-93.5846 ;30.2210
P78=-93.6457 ;30.4487
P79=-93.7067 ;30.6764
P80=-94.1719 ;30.7790
P81=-94.5918 ;30.9941
P82=-94.6904 ;31.2152
P83=-94.7890 ;31.4363
P84=-94.9165 ;31.6410
P85=-95.0440 ;31.8457
P86=-95.1952 ;32.0340
P87=-95.3464 ;32.2222
P88=-95.7187 ;32.5305
P89=-96.1528 ;32.7400
P90=-96.6325 ;32.7849
P91=-97.1152 ;32.7578
P92=-97.5984 ;32.7467
P93=-98.0791 ;32.7710
P94=-98.4792 ;33.0230

P95=-98.5265 ;33.2649
P96=-98.5737 ;33.5067
P97=-98.8114 ;33.8930
P98=-99.2561 ;34.0960
P99=-99.7231 ;34.0143
P100=-100.1945;33.9098
P101=-100.6749;33.8532
P102=-101.1547;33.7946
P103=-101.6292;33.7020
[C24]
gain=-8.00
n_point=101
P1=-101.4911;32.6536
P2=-101.7477;32.5559
P3=-102.0044;32.4583
P4=-102.2210;32.3425
P5=-102.4440;32.1524
P6=-102.6670;31.9624
P7=-102.8215;31.7611
P8=-102.9760;31.5598
P9=-103.1309;31.2960
P10=-103.2227;31.0212
P11=-103.3145;30.7464
P12=-103.4063;30.4715
P13=-103.4131;30.2086
P14=-103.4200;29.9457
P15=-103.4268;29.6827
P16=-103.4336;29.4198
P17=-103.4268;29.3811
P18=-103.3865;29.1491
P19=-103.3108;28.9301
P20=-103.2351;28.7112
P21=-103.1593;28.4922
P22=-103.0492;28.2946
P23=-102.8796;28.0525
P24=-102.7100;27.8103
P25=-102.5331;27.6468
P26=-102.3561;27.4832
P27=-102.1792;27.3197
P28=-102.1118;27.2723
P29=-102.0183;27.2107
P30=-101.8000;27.0986
P31=-101.5818;26.9865
P32=-101.3635;26.8744
P33=-101.1818;26.8086
P34=-101.0000;26.7428
P35=-100.7322;26.6807
P36=-100.4644;26.6186
P37=-100.3342;26.5929
P38=-100.0804;26.5451
P39=-99.8267 ;26.4973
P40=-99.4995 ;26.4240
P41=-99.2614 ;26.3614
P42=-99.0233 ;26.2988
P43=-98.7851 ;26.2363
P44=-98.6573 ;26.2024
P45=-98.5853 ;26.1835

P46=-98.3889 ;26.1484
P47=-98.1926 ;26.1134
P48=-97.8474 ;26.1044
P49=-97.5021 ;26.0955
P50=-97.4283 ;26.1078
P51=-97.1770 ;26.2181
P52=-96.9256 ;26.3284
P53=-96.6743 ;26.4387
P54=-96.4866 ;26.5989
P55=-96.2990 ;26.7592
P56=-96.1041 ;27.0070
P57=-95.9798 ;27.1792
P58=-95.8248 ;27.4435
P59=-95.6698 ;27.7079
P60=-95.5635 ;27.9835
P61=-95.4572 ;28.2590
P62=-95.3646 ;28.5380
P63=-95.2995 ;28.8484
P64=-95.2344 ;29.1587
P65=-95.2188 ;29.3427
P66=-95.2080 ;29.5144
P67=-95.2216 ;29.7414
P68=-95.2353 ;29.9684
P69=-95.2489 ;30.1954
P70=-95.2989 ;30.4309
P71=-95.3829 ;30.6596
P72=-95.4669 ;30.8883
P73=-95.5256 ;31.0075
P74=-95.7129 ;31.2676
P75=-95.9001 ;31.5276
P76=-96.0249 ;31.6339
P77=-96.1384 ;31.7240
P78=-96.3363 ;31.8093
P79=-96.5343 ;31.8947
P80=-96.8751 ;31.9616
P81=-97.1112 ;31.9634
P82=-97.3473 ;31.9651
P83=-97.5675 ;31.9537
P84=-97.7876 ;31.9423
P85=-98.1344 ;31.9379
P86=-98.3496 ;31.9589
P87=-98.5647 ;31.9799
P88=-98.8387 ;32.0677
P89=-99.1127 ;32.1555
P90=-99.3406 ;32.2571
P91=-99.5592 ;32.3562
P92=-99.7779 ;32.4553
P93=-99.9350 ;32.5119
P94=-100.1905;32.5827
P95=-100.4460;32.6535
P96=-100.6930;32.6806
P97=-100.9401;32.7077
P98=-101.0000;32.7069
P99=-101.0581;32.7061
P100=-101.2746;32.6799
P101=-101.4911;32.6536