

```
[FormatInfo]
format_ver=1
[GeoMain]
ntc_id=910100000
adm=USA
sat_name=USABSS-21
long_nom=-101.0000
n_diag=1
[COHeader]
beam_id=BB03
emi_rcp=E
polar_disc=C
reason=B
n_bore=1
n_cont=23
[B1]
gain=0.00
p=-81.8490;28.2570
[C1]
gain=-50.00
n_point=557
P1=-39.8985 ;71.7837
P2=-40.2940 ;71.7080
P3=-40.5000 ;71.6680
P4=-41.0000 ;71.5500
P5=-41.2680 ;71.5000
P6=-41.5000 ;71.4740
P7=-42.0000 ;71.4160
P8=-42.5000 ;71.3480
P9=-43.0000 ;71.2670
P10=-43.5000 ;71.1700
P11=-44.0000 ;71.0510
P12=-44.2410 ;71.0000
P13=-44.5000 ;70.9670
P14=-45.0000 ;70.9070
P15=-45.5000 ;70.8370
P16=-46.0000 ;70.7540
P17=-46.5000 ;70.6560
P18=-47.0000 ;70.5320
P19=-47.1340 ;70.5000
P20=-47.5000 ;70.4460
P21=-48.0000 ;70.3840
P22=-48.5000 ;70.3110
P23=-49.0000 ;70.2240
P24=-49.5000 ;70.1190
P25=-49.9750 ;70.0000
P26=-50.0000 ;69.9960
P27=-50.5000 ;69.9120
P28=-51.0000 ;69.8430
P29=-51.5000 ;69.7640
P30=-52.0000 ;69.6710
P31=-52.5000 ;69.5580
P32=-52.7330 ;69.5000
P33=-53.0000 ;69.4540
P34=-53.5000 ;69.3660
P35=-54.0000 ;69.2790
P36=-54.5000 ;69.1900
```

P37=-55.0000 ;69.0860
P38=-55.3600 ;69.0000
P39=-55.5000 ;68.9740
P40=-56.0000 ;68.8820
P41=-56.5000 ;68.7850
P42=-57.0000 ;68.6820
P43=-57.5000 ;68.5760
P44=-57.8260 ;68.5000
P45=-58.0000 ;68.4660
P46=-58.5000 ;68.3660
P47=-59.0000 ;68.2590
P48=-59.5000 ;68.1460
P49=-60.0000 ;68.0250
P50=-60.1020 ;68.0000
P51=-60.5000 ;67.9150
P52=-61.0000 ;67.8010
P53=-61.5000 ;67.6800
P54=-62.0000 ;67.5490
P55=-62.1820 ;67.5000
P56=-62.5000 ;67.4290
P57=-63.0000 ;67.3070
P58=-63.5000 ;67.1670
P59=-64.0000 ;67.0220
P60=-64.0730 ;67.0000
P61=-64.5000 ;66.9170
P62=-65.0000 ;66.8100
P63=-65.5000 ;66.6820
P64=-66.0000 ;66.5260
P65=-66.0750 ;66.5000
P66=-66.5000 ;66.4040
P67=-67.0000 ;66.2830
P68=-67.5000 ;66.1510
P69=-67.9980 ;66.0000
P70=-68.0000 ;65.9990
P71=-68.5000 ;65.8740
P72=-69.0000 ;65.7300
P73=-69.5000 ;65.5730
P74=-69.7200 ;65.5000
P75=-70.0000 ;65.4200
P76=-70.5000 ;65.2760
P77=-71.0000 ;65.1040
P78=-71.2680 ;65.0000
P79=-71.5000 ;64.9420
P80=-72.0000 ;64.8300
P81=-72.5000 ;64.6960
P82=-73.0000 ;64.5310
P83=-73.0870 ;64.5000
P84=-73.5000 ;64.3850
P85=-74.0000 ;64.2320
P86=-74.5000 ;64.0580
P87=-74.6570 ;64.0000
P88=-75.0000 ;63.8870
P89=-75.5000 ;63.7290
P90=-76.0000 ;63.5380
P91=-76.0890 ;63.5000
P92=-76.5000 ;63.3870
P93=-77.0000 ;63.2580

P94=-77.5000 ;63.1010
P95=-77.7870 ;63.0000
P96=-78.0000 ;62.9340
P97=-78.5000 ;62.7700
P98=-79.0000 ;62.5810
P99=-79.2020 ;62.5000
P100=-79.5000 ;62.4080
P101=-80.0000 ;62.2630
P102=-80.5000 ;62.0830
P103=-80.7090 ;62.0000
P104=-81.0000 ;61.9090
P105=-81.5000 ;61.7370
P106=-82.0000 ;61.5390
P107=-82.0940 ;61.5000
P108=-82.5000 ;61.3650
P109=-83.0000 ;61.1900
P110=-83.4360 ;61.0000
P111=-83.5000 ;60.9780
P112=-84.0000 ;60.8090
P113=-84.5000 ;60.6060
P114=-84.7380 ;60.5000
P115=-85.0000 ;60.4080
P116=-85.5000 ;60.2210
P117=-85.9530 ;60.0000
P118=-86.0000 ;59.9820
P119=-86.5000 ;59.7910
P120=-87.0000 ;59.5540
P121=-87.1080 ;59.5000
P122=-87.5000 ;59.3590
P123=-88.0000 ;59.1420
P124=-88.2760 ;59.0000
P125=-88.5000 ;58.8970
P126=-89.0000 ;58.6450
P127=-89.2570 ;58.5000
P128=-89.5000 ;58.4090
P129=-90.0000 ;58.1710
P130=-90.2920 ;58.0000
P131=-90.5000 ;57.8970
P132=-91.0000 ;57.6060
P133=-91.1580 ;57.5000
P134=-91.5000 ;57.3110
P135=-91.9440 ;57.0000
P136=-92.0000 ;56.9710
P137=-92.5000 ;56.6780
P138=-92.7470 ;56.5000
P139=-93.0000 ;56.3410
P140=-93.4280 ;56.0000
P141=-93.5000 ;55.9510
P142=-94.0000 ;55.5660
P143=-94.0790 ;55.5000
P144=-94.5000 ;55.2360
P145=-94.8000 ;55.0000
P146=-95.0000 ;54.8650
P147=-95.4330 ;54.5000
P148=-95.5000 ;54.4430
P149=-95.9820 ;54.0000
P150=-96.0000 ;53.9850

P151=-96.5000 ;53.5290
P152=-96.5300 ;53.5000
P153=-97.0000 ;53.0480
P154=-97.0470 ;53.0000
P155=-97.5000 ;52.5240
P156=-97.5220 ;52.5000
P157=-97.9900 ;52.0000
P158=-98.0000 ;51.9890
P159=-98.4560 ;51.5000
P160=-98.5000 ;51.4550
P161=-98.9250 ;51.0000
P162=-99.0000 ;50.9180
P163=-99.3860 ;50.5000
P164=-99.5000 ;50.3590
P165=-99.8110 ;50.0000
P166=-100.0000;49.7380
P167=-100.1940;49.5000
P168=-100.5000;49.0380
P169=-100.5300;49.0000
P170=-100.9280;48.5000
P171=-101.0000;48.3930
P172=-101.3150;48.0000
P173=-101.5000;47.7120
P174=-101.6630;47.5000
P175=-101.9780;47.0000
P176=-102.0000;46.9650
P177=-102.3440;46.5000
P178=-102.5000;46.2000
P179=-102.6390;46.0000
P180=-102.9200;45.5000
P181=-103.0000;45.3430
P182=-103.2250;45.0000
P183=-103.4670;44.5000
P184=-103.5000;44.4300
P185=-103.7860;44.0000
P186=-104.0000;43.5130
P187=-104.0080;43.5000
P188=-104.3190;43.0000
P189=-104.4920;42.5000
P190=-104.5000;42.4810
P191=-104.7630;42.0000
P192=-104.9480;41.5000
P193=-105.0000;41.3450
P194=-105.1850;41.0000
P195=-105.4040;40.5000
P196=-105.5000;40.1460
P197=-105.5710;40.0000
P198=-105.7820;39.5000
P199=-105.9310;39.0000
P200=-106.0000;38.7180
P201=-106.0930;38.5000
P202=-106.2850;38.0000
P203=-106.4120;37.5000
P204=-106.4930;37.0000
P205=-106.5000;36.9580
P206=-106.6520;36.5000
P207=-106.7830;36.0000

P208=-106.8800;35.5000
P209=-106.9390;35.0000
P210=-106.9760;34.5000
P211=-107.0000;34.0470
P212=-107.0070;34.0000
P213=-107.0660;33.5000
P214=-107.1000;33.0000
P215=-107.0970;32.5000
P216=-107.0670;32.0000
P217=-107.0250;31.5000
P218=-107.0000;31.2740
P219=-106.9900;31.0000
P220=-106.9660;30.5000
P221=-106.9400;30.0000
P222=-106.9130;29.5000
P223=-106.8840;29.0000
P224=-106.8480;28.5000
P225=-106.7920;28.0000
P226=-106.7420;27.5000
P227=-106.7070;27.0000
P228=-106.6690;26.5000
P229=-106.6170;26.0000
P230=-106.5540;25.5000
P231=-106.5000;25.1080
P232=-106.4940;25.0000
P233=-106.4630;24.5000
P234=-106.4130;24.0000
P235=-106.3380;23.5000
P236=-106.2370;23.0000
P237=-106.0950;22.5000
P238=-106.0000;22.2430
P239=-105.9590;22.0000
P240=-105.8520;21.5000
P241=-105.6440;21.0000
P242=-105.5000;20.7240
P243=-105.4480;20.5000
P244=-105.2640;20.0000
P245=-105.0000;19.5350
P246=-104.9870;19.5000
P247=-104.8360;19.0000
P248=-104.5490;18.5000
P249=-104.5000;18.4200
P250=-104.3560;18.0000
P251=-104.0730;17.5000
P252=-104.0000;17.3830
P253=-103.8680;17.0000
P254=-103.5710;16.5000
P255=-103.5000;16.3940
P256=-103.3130;16.0000
P257=-103.0000;15.5610
P258=-102.9640;15.5000
P259=-102.6880;15.0000
P260=-102.5000;14.7550
P261=-102.3260;14.5000
P262=-102.0000;14.0840
P263=-101.9320;14.0000
P264=-101.5390;13.5000

P265=-101.5000;13.4550
P266=-101.1490;13.0000
P267=-101.0000;12.8370
P268=-100.7130;12.5000
P269=-100.5000;12.2700
P270=-100.2340;12.0000
P271=-100.0000;11.7560
P272=-99.7380 ;11.5000
P273=-99.5000 ;11.2670
P274=-99.2270 ;11.0000
P275=-99.0000 ;10.7920
P276=-98.6630 ;10.5000
P277=-98.5000 ;10.3550
P278=-98.0230 ;10.0000
P279=-98.0000 ;9.9810
P280=-97.5000 ;9.6820
P281=-97.2880 ;10.0000
P282=-97.5000 ;10.1720
P283=-97.8600 ;10.5000
P284=-98.0000 ;10.6300
P285=-98.3980 ;11.0000
P286=-98.5000 ;11.1000
P287=-98.8750 ;11.5000
P288=-99.0000 ;11.6260
P289=-99.3330 ;12.0000
P290=-99.5000 ;12.1810
P291=-99.7900 ;12.5000
P292=-100.0000;12.7480
P293=-100.2150;13.0000
P294=-100.5000;13.3500
P295=-100.6090;13.5000
P296=-101.0000;13.9970
P297=-101.0030;14.0000
P298=-101.3090;14.5000
P299=-101.5000;14.7550
P300=-101.6590;15.0000
P301=-101.9800;15.5000
P302=-102.0000;15.5310
P303=-102.2290;16.0000
P304=-102.5000;16.4320
P305=-102.5320;16.5000
P306=-102.7310;17.0000
P307=-103.0000;17.4600
P308=-103.0210;17.5000
P309=-103.1660;18.0000
P310=-103.4180;18.5000
P311=-103.5000;18.6600
P312=-103.6090;19.0000
P313=-103.8190;19.5000
P314=-104.0000;19.8450
P315=-104.0410;20.0000
P316=-104.1870;20.5000
P317=-104.4090;21.0000
P318=-104.5000;21.2030
P319=-104.5750;21.5000
P320=-104.7080;22.0000
P321=-104.9060;22.5000

P322=-105.0000;22.7520
P323=-105.0320;23.0000
P324=-105.0800;23.5000
P325=-105.1710;24.0000
P326=-105.2570;24.5000
P327=-105.3300;25.0000
P328=-105.3940;25.5000
P329=-105.4550;26.0000
P330=-105.5000;26.4540
P331=-105.5020;26.5000
P332=-105.5140;27.0000
P333=-105.5230;27.5000
P334=-105.5270;28.0000
P335=-105.5290;28.5000
P336=-105.5280;29.0000
P337=-105.5270;29.5000
P338=-105.5300;30.0000
P339=-105.5360;30.5000
P340=-105.5380;31.0000
P341=-105.5390;31.5000
P342=-105.5430;32.0000
P343=-105.5480;32.5000
P344=-105.5470;33.0000
P345=-105.5380;33.5000
P346=-105.5240;34.0000
P347=-105.5050;34.5000
P348=-105.5000;34.5770
P349=-105.4390;35.0000
P350=-105.3490;35.5000
P351=-105.2520;36.0000
P352=-105.1570;36.5000
P353=-105.0810;37.0000
P354=-105.0120;37.5000
P355=-105.0000;37.5550
P356=-104.8380;38.0000
P357=-104.6640;38.5000
P358=-104.5340;39.0000
P359=-104.5000;39.1450
P360=-104.3520;39.5000
P361=-104.1670;40.0000
P362=-104.0280;40.5000
P363=-104.0000;40.5810
P364=-103.7810;41.0000
P365=-103.5660;41.5000
P366=-103.5000;41.6780
P367=-103.3180;42.0000
P368=-103.1050;42.5000
P369=-103.0000;42.7620
P370=-102.8580;43.0000
P371=-102.5860;43.5000
P372=-102.5000;43.6910
P373=-102.2970;44.0000
P374=-102.0300;44.5000
P375=-102.0000;44.5610
P376=-101.6880;45.0000
P377=-101.5000;45.3730
P378=-101.4100;45.5000

P379=-101.0930;46.0000
P380=-101.0000;46.1580
P381=-100.7440;46.5000
P382=-100.5000;46.9090
P383=-100.4290;47.0000
P384=-100.0410;47.5000
P385=-100.0000;47.5570
P386=-99.6190 ;48.0000
P387=-99.5000 ;48.1610
P388=-99.2030 ;48.5000
P389=-99.0000 ;48.7660
P390=-98.7920 ;49.0000
P391=-98.5000 ;49.3630
P392=-98.3760 ;49.5000
P393=-98.0000 ;49.9340
P394=-97.9380 ;50.0000
P395=-97.5000 ;50.4690
P396=-97.4690 ;50.5000
P397=-97.0000 ;50.9800
P398=-96.9790 ;51.0000
P399=-96.5000 ;51.4360
P400=-96.4280 ;51.5000
P401=-96.0000 ;51.8670
P402=-95.8480 ;52.0000
P403=-95.5000 ;52.2910
P404=-95.2590 ;52.5000
P405=-95.0000 ;52.7010
P406=-94.6400 ;53.0000
P407=-94.5000 ;53.1160
P408=-94.0330 ;53.5000
P409=-94.0000 ;53.5220
P410=-93.5000 ;53.8730
P411=-93.3260 ;54.0000
P412=-93.0000 ;54.1890
P413=-92.5570 ;54.5000
P414=-92.5000 ;54.5340
P415=-92.0000 ;54.8160
P416=-91.7160 ;55.0000
P417=-91.5000 ;55.1300
P418=-91.0000 ;55.4590
P419=-90.9380 ;55.5000
P420=-90.5000 ;55.7150
P421=-90.0180 ;56.0000
P422=-90.0000 ;56.0090
P423=-89.5000 ;56.2310
P424=-89.0300 ;56.5000
P425=-89.0000 ;56.5160
P426=-88.5000 ;56.7720
P427=-88.1080 ;57.0000
P428=-88.0000 ;57.0420
P429=-87.5000 ;57.2390
P430=-87.0000 ;57.4870
P431=-86.9740 ;57.5000
P432=-86.5000 ;57.6930
P433=-86.0000 ;57.9250
P434=-85.8500 ;58.0000
P435=-85.5000 ;58.1440

P436=-85.0000 ;58.3680
P437=-84.7220 ;58.5000
P438=-84.5000 ;58.5840
P439=-84.0000 ;58.7800
P440=-83.5220 ;59.0000
P441=-83.5000 ;59.0090
P442=-83.0000 ;59.2190
P443=-82.5000 ;59.4560
P444=-82.4080 ;59.5000
P445=-82.0000 ;59.6420
P446=-81.5000 ;59.8340
P447=-81.1170 ;60.0000
P448=-81.0000 ;60.0470
P449=-80.5000 ;60.2500
P450=-80.0000 ;60.4760
P451=-79.9460 ;60.5000
P452=-79.5000 ;60.6440
P453=-79.0000 ;60.8080
P454=-78.5110 ;61.0000
P455=-78.5000 ;61.0040
P456=-78.0000 ;61.1770
P457=-77.5000 ;61.3710
P458=-77.1780 ;61.5000
P459=-77.0000 ;61.5600
P460=-76.5000 ;61.7050
P461=-76.0000 ;61.8580
P462=-75.6060 ;62.0000
P463=-75.5000 ;62.0310
P464=-75.0000 ;62.1750
P465=-74.5000 ;62.3310
P466=-74.0010 ;62.5000
P467=-74.0000 ;62.5000
P468=-73.5000 ;62.6570
P469=-73.0000 ;62.7970
P470=-72.5000 ;62.9600
P471=-72.3900 ;63.0000
P472=-72.0000 ;63.0980
P473=-71.5000 ;63.2070
P474=-71.0000 ;63.3250
P475=-70.5000 ;63.4620
P476=-70.3700 ;63.5000
P477=-70.0000 ;63.5910
P478=-69.5000 ;63.7150
P479=-69.0000 ;63.8480
P480=-68.5000 ;63.9860
P481=-68.4470 ;64.0000
P482=-68.0000 ;64.1080
P483=-67.5000 ;64.2240
P484=-67.0000 ;64.3490
P485=-66.5000 ;64.4980
P486=-66.4940 ;64.5000
P487=-66.0000 ;64.5800
P488=-65.5000 ;64.6620
P489=-65.0000 ;64.7520
P490=-64.5000 ;64.8540
P491=-64.0000 ;64.9740
P492=-63.8950 ;65.0000

P493=-63.5000 ;65.0690
P494=-63.0000 ;65.1600
P495=-62.5000 ;65.2490
P496=-62.0000 ;65.3370
P497=-61.5000 ;65.4270
P498=-61.1450 ;65.5000
P499=-61.0000 ;65.5250
P500=-60.5000 ;65.6070
P501=-60.0000 ;65.6940
P502=-59.5000 ;65.7760
P503=-59.0000 ;65.8620
P504=-58.5000 ;65.9430
P505=-58.1570 ;66.0000
P506=-58.0000 ;66.0250
P507=-57.5000 ;66.1000
P508=-57.0000 ;66.1750
P509=-56.5000 ;66.2520
P510=-56.0000 ;66.3250
P511=-55.5000 ;66.4000
P512=-55.0000 ;66.4710
P513=-54.7960 ;66.5000
P514=-54.5000 ;66.5420
P515=-54.0000 ;66.6120
P516=-53.5000 ;66.6810
P517=-53.0000 ;66.7520
P518=-52.5000 ;66.8200
P519=-52.0000 ;66.8880
P520=-51.5000 ;66.9570
P521=-51.1710 ;67.0000
P522=-51.0000 ;67.0230
P523=-50.5000 ;67.0920
P524=-50.0000 ;67.1610
P525=-49.5000 ;67.2280
P526=-49.0000 ;67.2960
P527=-48.5000 ;67.3640
P528=-48.0000 ;67.4290
P529=-47.5000 ;67.4940
P530=-47.4590 ;67.5000
P531=-47.0000 ;67.5650
P532=-46.5000 ;67.6330
P533=-46.0000 ;67.7010
P534=-45.5000 ;67.7710
P535=-45.0000 ;67.8400
P536=-44.5000 ;67.9060
P537=-44.0000 ;67.9710
P538=-43.7970 ;68.0000
P539=-43.5000 ;68.0440
P540=-43.0000 ;68.1160
P541=-42.5000 ;68.1880
P542=-42.0000 ;68.2600
P543=-41.5000 ;68.3320
P544=-41.0000 ;68.4030
P545=-40.5000 ;68.4680
P546=-40.2830 ;68.5000
P547=-40.0000 ;68.5430
P548=-39.5000 ;68.6210
P549=-39.0000 ;68.6980

P550=-38.5000 ;68.7740
P551=-38.0000 ;68.8480
P552=-37.5000 ;68.9170
P553=-37.0000 ;68.9910
P554=-36.9460 ;69.0000
P555=-36.5000 ;69.0730
P556=-36.4710 ;69.0780
P557=-36.1040 ;69.1406

[C2]

gain=-50.00

n_point=509

P1=-44.5000 ;49.8920
P2=-44.5360 ;50.0000
P3=-44.7440 ;50.5000
P4=-44.9600 ;51.0000
P5=-45.0000 ;51.0960
P6=-45.2050 ;51.5000
P7=-45.5000 ;51.9890
P8=-45.5060 ;52.0000
P9=-45.7680 ;52.5000
P10=-46.0000 ;52.8360
P11=-46.1250 ;53.0000
P12=-46.4480 ;53.5000
P13=-46.5000 ;53.6020
P14=-46.6910 ;54.0000
P15=-46.9190 ;54.5000
P16=-47.0000 ;54.5820
P17=-47.3520 ;55.0000
P18=-47.5000 ;55.1190
P19=-48.0000 ;55.4520
P20=-48.0580 ;55.5000
P21=-48.5000 ;55.7390
P22=-49.0000 ;55.9510
P23=-49.0960 ;56.0000
P24=-49.5000 ;56.1550
P25=-50.0000 ;56.2920
P26=-50.5000 ;56.4240
P27=-50.7500 ;56.5000
P28=-51.0000 ;56.5640
P29=-51.5000 ;56.6670
P30=-52.0000 ;56.7260
P31=-52.5000 ;56.7820
P32=-53.0000 ;56.8580
P33=-53.5000 ;56.9350
P34=-54.0000 ;56.9720
P35=-54.5000 ;56.9860
P36=-54.8220 ;57.0000
P37=-55.0000 ;57.0140
P38=-55.5000 ;57.1070
P39=-56.0000 ;57.1770
P40=-56.5000 ;57.2250
P41=-57.0000 ;57.2700
P42=-57.5000 ;57.3110
P43=-58.0000 ;57.3430
P44=-58.5000 ;57.3700
P45=-59.0000 ;57.4090
P46=-59.5000 ;57.4680

P47=-59.7210 ;57.5000
P48=-60.0000 ;57.5270
P49=-60.5000 ;57.5610
P50=-61.0000 ;57.5830
P51=-61.5000 ;57.5840
P52=-62.0000 ;57.5790
P53=-62.5000 ;57.5760
P54=-63.0000 ;57.6010
P55=-63.5000 ;57.6360
P56=-64.0000 ;57.6560
P57=-64.5000 ;57.6630
P58=-65.0000 ;57.6590
P59=-65.5000 ;57.6530
P60=-66.0000 ;57.6360
P61=-66.5000 ;57.6090
P62=-67.0000 ;57.5630
P63=-67.5000 ;57.5030
P64=-67.5200 ;57.5000
P65=-68.0000 ;57.4510
P66=-68.5000 ;57.3940
P67=-69.0000 ;57.3300
P68=-69.5000 ;57.2610
P69=-70.0000 ;57.1840
P70=-70.5000 ;57.1000
P71=-70.9860 ;57.0000
P72=-71.0000 ;56.9960
P73=-71.5000 ;56.8670
P74=-72.0000 ;56.7650
P75=-72.5000 ;56.6650
P76=-73.0000 ;56.5510
P77=-73.1790 ;56.5000
P78=-73.5000 ;56.4250
P79=-74.0000 ;56.3400
P80=-74.5000 ;56.2530
P81=-75.0000 ;56.1500
P82=-75.5000 ;56.0160
P83=-75.5540 ;56.0000
P84=-76.0000 ;55.8540
P85=-76.5000 ;55.7240
P86=-77.0000 ;55.5910
P87=-77.2880 ;55.5000
P88=-77.5000 ;55.4300
P89=-78.0000 ;55.3210
P90=-78.5000 ;55.2220
P91=-79.0000 ;55.0900
P92=-79.2870 ;55.0000
P93=-79.5000 ;54.9030
P94=-80.0000 ;54.7530
P95=-80.5000 ;54.6260
P96=-80.9050 ;54.5000
P97=-81.0000 ;54.4760
P98=-81.5000 ;54.3510
P99=-82.0000 ;54.2080
P100=-82.5000 ;54.0280
P101=-82.5760 ;54.0000
P102=-83.0000 ;53.8600
P103=-83.5000 ;53.7290

P104=-84.0000 ;53.5520
P105=-84.1240 ;53.5000
P106=-84.5000 ;53.3520
P107=-85.0000 ;53.1830
P108=-85.4150 ;53.0000
P109=-85.5000 ;52.9740
P110=-86.0000 ;52.7980
P111=-86.5000 ;52.5560
P112=-86.6080 ;52.5000
P113=-87.0000 ;52.3680
P114=-87.5000 ;52.1530
P115=-87.7770 ;52.0000
P116=-88.0000 ;51.8960
P117=-88.5000 ;51.6840
P118=-88.8020 ;51.5000
P119=-89.0000 ;51.3850
P120=-89.5000 ;51.1260
P121=-89.6830 ;51.0000
P122=-90.0000 ;50.8120
P123=-90.4350 ;50.5000
P124=-90.5000 ;50.4650
P125=-91.0000 ;50.1670
P126=-91.2210 ;50.0000
P127=-91.5000 ;49.8410
P128=-91.9450 ;49.5000
P129=-92.0000 ;49.4550
P130=-92.5000 ;49.1180
P131=-92.6410 ;49.0000
P132=-93.0000 ;48.7440
P133=-93.2800 ;48.5000
P134=-93.5000 ;48.3190
P135=-93.8520 ;48.0000
P136=-94.0000 ;47.8630
P137=-94.3870 ;47.5000
P138=-94.5000 ;47.3890
P139=-94.9030 ;47.0000
P140=-95.0000 ;46.9040
P141=-95.4060 ;46.5000
P142=-95.5000 ;46.4060
P143=-95.8950 ;46.0000
P144=-96.0000 ;45.8910
P145=-96.3630 ;45.5000
P146=-96.5000 ;45.3500
P147=-96.8100 ;45.0000
P148=-97.0000 ;44.7780
P149=-97.2390 ;44.5000
P150=-97.5000 ;44.1680
P151=-97.6410 ;44.0000
P152=-97.9950 ;43.5000
P153=-98.0000 ;43.4930
P154=-98.3580 ;43.0000
P155=-98.5000 ;42.8030
P156=-98.7280 ;42.5000
P157=-99.0000 ;42.0330
P158=-99.0250 ;42.0000
P159=-99.3930 ;41.5000
P160=-99.5000 ;41.2910

P161=-99.7090 ;41.0000
P162=-99.9780 ;40.5000
P163=-100.0000;40.4570
P164=-100.2980;40.0000
P165=-100.5000;39.5610
P166=-100.5390;39.5000
P167=-100.7910;39.0000
P168=-100.9890;38.5000
P169=-101.0000;38.4790
P170=-101.2930;38.0000
P171=-101.4750;37.5000
P172=-101.5000;37.4350
P173=-101.7380;37.0000
P174=-101.8900;36.5000
P175=-102.0000;36.0770
P176=-102.0360;36.0000
P177=-102.2470;35.5000
P178=-102.3850;35.0000
P179=-102.4890;34.5000
P180=-102.5000;34.4390
P181=-102.6560;34.0000
P182=-102.7870;33.5000
P183=-102.8740;33.0000
P184=-102.9240;32.5000
P185=-102.9480;32.0000
P186=-102.9630;31.5000
P187=-102.9770;31.0000
P188=-102.9830;30.5000
P189=-102.9800;30.0000
P190=-102.9670;29.5000
P191=-102.9480;29.0000
P192=-102.9240;28.5000
P193=-102.8990;28.0000
P194=-102.8740;27.5000
P195=-102.8500;27.0000
P196=-102.8290;26.5000
P197=-102.8080;26.0000
P198=-102.7510;25.5000
P199=-102.6660;25.0000
P200=-102.5670;24.5000
P201=-102.5000;24.2080
P202=-102.4650;24.0000
P203=-102.4330;23.5000
P204=-102.4120;23.0000
P205=-102.2970;22.5000
P206=-102.1180;22.0000
P207=-102.0000;21.7200
P208=-101.9410;21.5000
P209=-101.8170;21.0000
P210=-101.5850;20.5000
P211=-101.5000;20.3590
P212=-101.3820;20.0000
P213=-101.0760;19.5000
P214=-101.0000;19.3850
P215=-100.8380;19.0000
P216=-100.5460;18.5000
P217=-100.5000;18.4340

P218=-100.2730;18.0000
P219=-100.0000;17.5830
P220=-99.9390 ;17.5000
P221=-99.6790 ;17.0000
P222=-99.5000 ;16.7640
P223=-99.2930 ;16.5000
P224=-99.0000 ;16.0480
P225=-98.9200 ;16.0000
P226=-98.5900 ;15.5000
P227=-98.5000 ;15.3910
P228=-98.1310 ;15.0000
P229=-98.0000 ;14.8560
P230=-97.7760 ;15.0000
P231=-97.9890 ;15.5000
P232=-98.0000 ;15.5140
P233=-98.3370 ;16.0000
P234=-98.5000 ;16.2540
P235=-98.6760 ;16.5000
P236=-98.9020 ;17.0000
P237=-99.0000 ;17.1570
P238=-99.1700 ;17.5000
P239=-99.4550 ;18.0000
P240=-99.5000 ;18.0720
P241=-99.6780 ;18.5000
P242=-99.9540 ;19.0000
P243=-100.0000;19.0760
P244=-100.1790;19.5000
P245=-100.4080;20.0000
P246=-100.5000;20.1580
P247=-100.6270;20.5000
P248=-100.8330;21.0000
P249=-101.0000;21.3380
P250=-101.0610;21.5000
P251=-101.1260;22.0000
P252=-101.2850;22.5000
P253=-101.4570;23.0000
P254=-101.5000;23.1560
P255=-101.5500;23.5000
P256=-101.6270;24.0000
P257=-101.6740;24.5000
P258=-101.6970;25.0000
P259=-101.7000;25.5000
P260=-101.7060;26.0000
P261=-101.7450;26.5000
P262=-101.7830;27.0000
P263=-101.8160;27.5000
P264=-101.8490;28.0000
P265=-101.8780;28.5000
P266=-101.9020;29.0000
P267=-101.9200;29.5000
P268=-101.9340;30.0000
P269=-101.9370;30.5000
P270=-101.9250;31.0000
P271=-101.8980;31.5000
P272=-101.8550;32.0000
P273=-101.8000;32.5000
P274=-101.7220;33.0000

P275=-101.6330;33.5000
P276=-101.5540;34.0000
P277=-101.5000;34.3850
P278=-101.4660;34.5000
P279=-101.2880;35.0000
P280=-101.1610;35.5000
P281=-101.0710;36.0000
P282=-101.0000;36.1720
P283=-100.8510;36.5000
P284=-100.6600;37.0000
P285=-100.5000;37.4960
P286=-100.4980;37.5000
P287=-100.2120;38.0000
P288=-100.0300;38.5000
P289=-100.0000;38.5580
P290=-99.7500 ;39.0000
P291=-99.5460 ;39.5000
P292=-99.5000 ;39.5730
P293=-99.2500 ;40.0000
P294=-99.0000 ;40.4900
P295=-98.9930 ;40.5000
P296=-98.6270 ;41.0000
P297=-98.5000 ;41.2280
P298=-98.2950 ;41.5000
P299=-98.0000 ;41.9910
P300=-97.9930 ;42.0000
P301=-97.6410 ;42.5000
P302=-97.5000 ;42.6910
P303=-97.2560 ;43.0000
P304=-97.0000 ;43.3200
P305=-96.8480 ;43.5000
P306=-96.5000 ;43.9420
P307=-96.4490 ;44.0000
P308=-96.0450 ;44.5000
P309=-96.0000 ;44.5480
P310=-95.5980 ;45.0000
P311=-95.5000 ;45.1020
P312=-95.1130 ;45.5000
P313=-95.0000 ;45.6110
P314=-94.5990 ;46.0000
P315=-94.5000 ;46.0930
P316=-94.0640 ;46.5000
P317=-94.0000 ;46.5600
P318=-93.5110 ;47.0000
P319=-93.5000 ;47.0110
P320=-93.0000 ;47.4060
P321=-92.8900 ;47.5000
P322=-92.5000 ;47.7990
P323=-92.2520 ;48.0000
P324=-92.0000 ;48.1910
P325=-91.5800 ;48.5000
P326=-91.5000 ;48.5600
P327=-91.0000 ;48.8870
P328=-90.8410 ;49.0000
P329=-90.5000 ;49.2190
P330=-90.0840 ;49.5000
P331=-90.0000 ;49.5420

P332=-89.5000 ;49.8370
P333=-89.2530 ;50.0000
P334=-89.0000 ;50.1170
P335=-88.5000 ;50.3930
P336=-88.3180 ;50.5000
P337=-88.0000 ;50.6440
P338=-87.5000 ;50.8690
P339=-87.2560 ;51.0000
P340=-87.0000 ;51.1360
P341=-86.5000 ;51.3240
P342=-86.1350 ;51.5000
P343=-86.0000 ;51.5720
P344=-85.5000 ;51.7800
P345=-85.0000 ;51.9970
P346=-84.9940 ;52.0000
P347=-84.5000 ;52.1650
P348=-84.0000 ;52.3540
P349=-83.6580 ;52.5000
P350=-83.5000 ;52.5730
P351=-83.0000 ;52.7280
P352=-82.5000 ;52.9000
P353=-82.2450 ;53.0000
P354=-82.0000 ;53.1240
P355=-81.5000 ;53.2940
P356=-81.0000 ;53.4500
P357=-80.8610 ;53.5000
P358=-80.5000 ;53.6050
P359=-80.0000 ;53.7490
P360=-79.5000 ;53.9120
P361=-79.2510 ;54.0000
P362=-79.0000 ;54.1180
P363=-78.5000 ;54.2440
P364=-78.0000 ;54.3520
P365=-77.5000 ;54.4840
P366=-77.4470 ;54.5000
P367=-77.0000 ;54.6540
P368=-76.5000 ;54.7810
P369=-76.0000 ;54.9030
P370=-75.6510 ;55.0000
P371=-75.5000 ;55.0510
P372=-75.0000 ;55.1530
P373=-74.5000 ;55.2210
P374=-74.0000 ;55.2980
P375=-73.5000 ;55.3860
P376=-73.0000 ;55.4880
P377=-72.9440 ;55.5000
P378=-72.5000 ;55.6010
P379=-72.0000 ;55.6820
P380=-71.5000 ;55.7470
P381=-71.0000 ;55.8140
P382=-70.5000 ;55.8830
P383=-70.0000 ;55.9460
P384=-69.5000 ;56.0000
P385=-69.4980 ;56.0000
P386=-69.0000 ;56.0580
P387=-68.5000 ;56.0990
P388=-68.0000 ;56.1300

P389=-67.5000 ;56.1520
P390=-67.0000 ;56.1590
P391=-66.5000 ;56.1540
P392=-66.0000 ;56.1400
P393=-65.5000 ;56.1370
P394=-65.0000 ;56.1340
P395=-64.5000 ;56.1350
P396=-64.0000 ;56.1290
P397=-63.5000 ;56.1070
P398=-63.0000 ;56.0860
P399=-62.5000 ;56.0550
P400=-62.0720 ;56.0000
P401=-62.0000 ;55.9910
P402=-61.5000 ;55.9350
P403=-61.0000 ;55.8860
P404=-60.5000 ;55.8450
P405=-60.0000 ;55.8210
P406=-59.5000 ;55.7990
P407=-59.0000 ;55.7610
P408=-58.5000 ;55.6850
P409=-58.0000 ;55.5950
P410=-57.5000 ;55.5510
P411=-57.0000 ;55.5210
P412=-56.8250 ;55.5000
P413=-56.5000 ;55.4320
P414=-56.0000 ;55.3120
P415=-55.5000 ;55.2180
P416=-55.0000 ;55.1200
P417=-54.5000 ;55.0240
P418=-54.4130 ;55.0000
P419=-54.0000 ;54.8560
P420=-53.5000 ;54.7160
P421=-53.0000 ;54.5650
P422=-52.8120 ;54.5000
P423=-52.5000 ;54.3640
P424=-52.0000 ;54.1580
P425=-51.6640 ;54.0000
P426=-51.5000 ;53.8950
P427=-51.0000 ;53.6140
P428=-50.8260 ;53.5000
P429=-50.5000 ;53.2060
P430=-50.2410 ;53.0000
P431=-50.0000 ;52.7500
P432=-49.8030 ;52.5000
P433=-49.5000 ;52.1110
P434=-49.4070 ;52.0000
P435=-49.0830 ;51.5000
P436=-49.0000 ;51.3630
P437=-48.7690 ;51.0000
P438=-48.5000 ;50.5780
P439=-48.4640 ;50.5000
P440=-48.2740 ;50.0000
P441=-48.0170 ;49.5000
P442=-48.0000 ;49.4600
P443=-47.8340 ;49.0000
P444=-47.7050 ;48.5000
P445=-47.6500 ;48.0000

P446=-47.6550 ;47.5000
P447=-47.6870 ;47.0000
P448=-47.7360 ;46.5000
P449=-47.8140 ;46.0000
P450=-47.9230 ;45.5000
P451=-48.0000 ;45.2350
P452=-48.0670 ;45.0000
P453=-48.2220 ;44.5000
P454=-48.3610 ;44.0000
P455=-48.4520 ;43.5000
P456=-48.5000 ;43.2690
P457=-48.5910 ;43.0000
P458=-48.7430 ;42.5000
P459=-48.8530 ;42.0000
P460=-48.9320 ;41.5000
P461=-49.0000 ;41.0830
P462=-49.0240 ;41.0000
P463=-49.1530 ;40.5000
P464=-49.2470 ;40.0000
P465=-49.3360 ;39.5000
P466=-49.4320 ;39.0000
P467=-49.5000 ;38.7800
P468=-49.5890 ;38.5000
P469=-49.6830 ;38.0000
P470=-49.7710 ;37.5000
P471=-49.7630 ;37.0000
P472=-49.5000 ;36.7380
P473=-49.0590 ;37.0000
P474=-49.0000 ;37.0280
P475=-48.5000 ;37.4330
P476=-48.4400 ;37.5000
P477=-48.0000 ;37.9740
P478=-47.9810 ;38.0000
P479=-47.6400 ;38.5000
P480=-47.5000 ;38.7250
P481=-47.3390 ;39.0000
P482=-47.1360 ;39.5000
P483=-47.0000 ;39.9370
P484=-46.9720 ;40.0000
P485=-46.8000 ;40.5000
P486=-46.6800 ;41.0000
P487=-46.5810 ;41.5000
P488=-46.5000 ;41.9760
P489=-46.4920 ;42.0000
P490=-46.3160 ;42.5000
P491=-46.1640 ;43.0000
P492=-46.0500 ;43.5000
P493=-46.0000 ;43.8490
P494=-45.9640 ;44.0000
P495=-45.8130 ;44.5000
P496=-45.5900 ;45.0000
P497=-45.5000 ;45.1790
P498=-45.3740 ;45.5000
P499=-45.2150 ;46.0000
P500=-45.0710 ;46.5000
P501=-45.0000 ;46.7250
P502=-44.8780 ;47.0000

P503=-44.7040 ;47.5000
P504=-44.5490 ;48.0000
P505=-44.5000 ;48.1790
P506=-44.4250 ;48.5000
P507=-44.3560 ;49.0000
P508=-44.3800 ;49.5000
P509=-44.5000 ;49.8920
[C3]
gain=-50.00
n_point=205
P1=-79.0000 ;48.5510
P2=-79.5000 ;48.5790
P3=-80.0000 ;48.5640
P4=-80.5000 ;48.5100
P5=-80.5440 ;48.5000
P6=-81.0000 ;48.2400
P7=-81.5000 ;48.1510
P8=-82.0000 ;48.0700
P9=-82.3640 ;48.0000
P10=-82.5000 ;47.9310
P11=-83.0000 ;47.8230
P12=-83.5000 ;47.7100
P13=-84.0000 ;47.5390
P14=-84.0910 ;47.5000
P15=-84.5000 ;47.3530
P16=-85.0000 ;47.2320
P17=-85.4830 ;47.0000
P18=-85.5000 ;46.9720
P19=-86.0000 ;46.7990
P20=-86.5000 ;46.5830
P21=-86.6390 ;46.5000
P22=-87.0000 ;46.2930
P23=-87.5000 ;46.0770
P24=-87.6170 ;46.0000
P25=-88.0000 ;45.7610
P26=-88.4610 ;45.5000
P27=-88.5000 ;45.4400
P28=-89.0000 ;45.1690
P29=-89.2350 ;45.0000
P30=-89.5000 ;44.7770
P31=-89.9370 ;44.5000
P32=-90.0000 ;44.4160
P33=-90.5000 ;44.0940
P34=-90.6140 ;44.0000
P35=-91.0000 ;43.6840
P36=-91.2210 ;43.5000
P37=-91.5000 ;43.2540
P38=-91.7920 ;43.0000
P39=-92.0000 ;42.8090
P40=-92.3330 ;42.5000
P41=-92.5000 ;42.3470
P42=-92.8500 ;42.0000
P43=-93.0000 ;41.8650
P44=-93.3540 ;41.5000
P45=-93.5000 ;41.3480
P46=-93.8310 ;41.0000
P47=-94.0000 ;40.8100

P48=-94.2760 ;40.5000
P49=-94.5000 ;40.2280
P50=-94.6900 ;40.0000
P51=-95.0000 ;39.6420
P52=-95.1160 ;39.5000
P53=-95.4520 ;39.0000
P54=-95.5000 ;38.9610
P55=-95.7400 ;38.5000
P56=-96.0000 ;38.2080
P57=-96.1400 ;38.0000
P58=-96.3420 ;37.5000
P59=-96.5000 ;37.3850
P60=-96.7360 ;37.0000
P61=-97.0000 ;36.5570
P62=-97.0390 ;36.5000
P63=-97.3340 ;36.0000
P64=-97.5000 ;35.6140
P65=-97.5700 ;35.5000
P66=-97.7840 ;35.0000
P67=-97.9620 ;34.5000
P68=-98.0000 ;34.4700
P69=-98.2070 ;34.0000
P70=-98.2850 ;33.5000
P71=-98.5000 ;33.0030
P72=-98.5020 ;33.0000
P73=-98.6650 ;32.5000
P74=-98.7720 ;32.0000
P75=-98.8670 ;31.5000
P76=-98.9430 ;31.0000
P77=-99.0000 ;30.6530
P78=-99.0320 ;30.5000
P79=-99.1120 ;30.0000
P80=-99.1550 ;29.5000
P81=-99.1650 ;29.0000
P82=-99.1510 ;28.5000
P83=-99.1330 ;28.0000
P84=-99.1110 ;27.5000
P85=-99.0600 ;27.0000
P86=-99.0000 ;26.6620
P87=-98.9570 ;26.5000
P88=-98.8800 ;26.0000
P89=-98.8680 ;25.5000
P90=-98.8980 ;25.0000
P91=-98.8390 ;24.5000
P92=-98.7160 ;24.0000
P93=-98.5610 ;23.5000
P94=-98.5000 ;23.3280
P95=-98.3770 ;23.0000
P96=-98.2910 ;22.5000
P97=-98.2940 ;22.0000
P98=-98.0380 ;21.5000
P99=-98.0000 ;21.4320
P100=-97.7690 ;21.0000
P101=-97.5930 ;20.5000
P102=-97.5000 ;20.3530
P103=-97.2680 ;20.0000
P104=-97.0000 ;19.5670

P105=-96.7650 ;20.0000
P106=-96.9990 ;20.5000
P107=-97.0000 ;20.5010
P108=-97.2640 ;21.0000
P109=-97.3450 ;21.5000
P110=-97.5000 ;21.8110
P111=-97.6010 ;22.0000
P112=-97.7350 ;22.5000
P113=-97.7730 ;23.0000
P114=-97.8180 ;23.5000
P115=-98.0000 ;23.9890
P116=-98.0110 ;24.0000
P117=-98.0830 ;24.5000
P118=-98.0930 ;25.0000
P119=-98.1810 ;25.5000
P120=-98.2480 ;26.0000
P121=-98.2790 ;26.5000
P122=-98.2760 ;27.0000
P123=-98.2740 ;27.5000
P124=-98.2950 ;28.0000
P125=-98.3150 ;28.5000
P126=-98.3300 ;29.0000
P127=-98.3220 ;29.5000
P128=-98.2890 ;30.0000
P129=-98.2410 ;30.5000
P130=-98.2050 ;31.0000
P131=-98.1850 ;31.5000
P132=-98.1420 ;32.0000
P133=-98.0000 ;32.3020
P134=-97.9330 ;32.5000
P135=-97.8180 ;33.0000
P136=-97.7560 ;33.5000
P137=-97.5840 ;34.0000
P138=-97.5000 ;34.1020
P139=-97.3360 ;34.5000
P140=-97.1690 ;35.0000
P141=-97.0000 ;35.2480
P142=-96.8550 ;35.5000
P143=-96.6550 ;36.0000
P144=-96.5000 ;36.2900
P145=-96.3700 ;36.5000
P146=-96.1820 ;37.0000
P147=-96.0000 ;37.2350
P148=-95.8480 ;37.5000
P149=-95.5370 ;38.0000
P150=-95.5000 ;38.0290
P151=-95.2810 ;38.5000
P152=-95.0000 ;38.8080
P153=-94.8540 ;39.0000
P154=-94.5000 ;39.4200
P155=-94.4320 ;39.5000
P156=-94.0910 ;40.0000
P157=-94.0000 ;40.0660
P158=-93.6610 ;40.5000
P159=-93.5000 ;40.6430
P160=-93.1790 ;41.0000
P161=-93.0000 ;41.1730

P162=-92.6840 ;41.5000
P163=-92.5000 ;41.7000
P164=-92.1870 ;42.0000
P165=-92.0000 ;42.2030
P166=-91.6630 ;42.5000
P167=-91.5000 ;42.6780
P168=-91.0860 ;43.0000
P169=-91.0000 ;43.1070
P170=-90.5000 ;43.4420
P171=-90.4240 ;43.5000
P172=-90.0000 ;43.8240
P173=-89.7430 ;44.0000
P174=-89.5000 ;44.2020
P175=-89.0000 ;44.4960
P176=-88.9940 ;44.5000
P177=-88.5000 ;44.8280
P178=-88.1960 ;45.0000
P179=-88.0000 ;45.1430
P180=-87.5000 ;45.4020
P181=-87.3140 ;45.5000
P182=-87.0000 ;45.6750
P183=-86.5000 ;45.9150
P184=-86.3240 ;46.0000
P185=-86.0000 ;46.1500
P186=-85.5000 ;46.3460
P187=-85.1640 ;46.5000
P188=-85.0000 ;46.6140
P189=-84.5000 ;46.7230
P190=-84.0000 ;46.9000
P191=-83.7630 ;47.0000
P192=-83.5000 ;47.1960
P193=-83.0000 ;47.2780
P194=-82.5000 ;47.3940
P195=-82.1820 ;47.5000
P196=-82.0000 ;47.7850
P197=-81.5000 ;47.8640
P198=-81.0000 ;47.9120
P199=-80.5000 ;47.9890
P200=-80.4540 ;48.0000
P201=-80.0000 ;48.3360
P202=-79.5000 ;48.4140
P203=-79.0000 ;48.4760
P204=-78.8170 ;48.5000
P205=-79.0000 ;48.5510
[C4]
gain=-50.00
n_point=181
P1=-57.5000 ;39.6390
P2=-57.5380 ;40.0000
P3=-57.6270 ;40.5000
P4=-57.7970 ;41.0000
P5=-58.0000 ;41.4370
P6=-58.0400 ;41.5000
P7=-58.2380 ;42.0000
P8=-58.4250 ;42.5000
P9=-58.5000 ;42.7010
P10=-58.6480 ;43.0000

P11=-58.8430 ;43.5000
P12=-59.0000 ;43.9490
P13=-59.0250 ;44.0000
P14=-59.2750 ;44.5000
P15=-59.4890 ;45.0000
P16=-59.5000 ;45.0190
P17=-59.8020 ;45.5000
P18=-60.0000 ;45.7550
P19=-60.2880 ;46.0000
P20=-60.5000 ;46.2080
P21=-60.8010 ;46.5000
P22=-61.0000 ;46.6270
P23=-61.5000 ;46.9470
P24=-61.5610 ;47.0000
P25=-62.0000 ;47.2730
P26=-62.4440 ;47.5000
P27=-62.5000 ;47.5300
P28=-63.0000 ;47.7560
P29=-63.5000 ;47.9580
P30=-63.5750 ;48.0000
P31=-64.0000 ;48.1850
P32=-64.5000 ;48.2830
P33=-64.8940 ;48.5000
P34=-65.0000 ;48.5420
P35=-65.5000 ;48.6920
P36=-66.0000 ;48.7780
P37=-66.3420 ;49.0000
P38=-66.5000 ;49.0450
P39=-67.0000 ;49.1270
P40=-67.5000 ;49.2680
P41=-68.0000 ;49.4640
P42=-68.3570 ;49.5000
P43=-68.5000 ;49.5130
P44=-69.0000 ;49.6130
P45=-69.5000 ;49.7430
P46=-70.0000 ;49.8150
P47=-70.5000 ;49.8440
P48=-71.0000 ;49.8520
P49=-71.5000 ;49.8270
P50=-72.0000 ;49.7850
P51=-72.5000 ;49.7310
P52=-73.0000 ;49.6740
P53=-73.5000 ;49.6200
P54=-74.0000 ;49.5710
P55=-74.5000 ;49.5220
P56=-74.7000 ;49.5000
P57=-75.0000 ;49.4130
P58=-75.5000 ;49.3500
P59=-76.0000 ;49.3150
P60=-76.5000 ;49.2850
P61=-77.0000 ;49.2260
P62=-77.5000 ;49.1550
P63=-78.0000 ;49.0670
P64=-78.3130 ;49.0000
P65=-78.0000 ;48.7820
P66=-77.5000 ;48.7420
P67=-77.0000 ;48.7430

P68=-76.5000 ;48.7610
P69=-76.0000 ;48.8080
P70=-75.5000 ;48.8530
P71=-75.0000 ;48.8980
P72=-74.5000 ;48.9400
P73=-74.0000 ;48.9760
P74=-73.5380 ;49.0000
P75=-73.5000 ;49.0120
P76=-73.0000 ;49.0580
P77=-72.5000 ;49.0380
P78=-72.0000 ;49.0010
P79=-71.9860 ;49.0000
P80=-71.5000 ;48.9880
P81=-71.0000 ;48.9980
P82=-70.8490 ;49.0000
P83=-70.5000 ;49.0030
P84=-70.4670 ;49.0000
P85=-70.0000 ;48.9400
P86=-69.5000 ;48.8020
P87=-69.0000 ;48.6910
P88=-68.5000 ;48.6090
P89=-68.0660 ;48.5000
P90=-68.0000 ;48.4770
P91=-67.5000 ;48.3120
P92=-67.0000 ;48.2260
P93=-66.5000 ;48.0970
P94=-66.3790 ;48.0000
P95=-66.0000 ;47.8690
P96=-65.5000 ;47.8390
P97=-65.0000 ;47.6640
P98=-64.7100 ;47.5000
P99=-64.5000 ;47.4460
P100=-64.0000 ;47.2650
P101=-63.5000 ;47.0160
P102=-63.4770 ;47.0000
P103=-63.0000 ;46.7020
P104=-62.6910 ;46.5000
P105=-62.5000 ;46.3810
P106=-62.0000 ;46.0110
P107=-61.9820 ;46.0000
P108=-61.5000 ;45.5610
P109=-61.4090 ;45.5000
P110=-61.0000 ;45.1130
P111=-60.8980 ;45.0000
P112=-60.5700 ;44.5000
P113=-60.5000 ;44.3820
P114=-60.1750 ;44.0000
P115=-60.0000 ;43.6560
P116=-59.9330 ;43.5000
P117=-59.7410 ;43.0000
P118=-59.5940 ;42.5000
P119=-59.5000 ;42.2220
P120=-59.4040 ;42.0000
P121=-59.2690 ;41.5000
P122=-59.1270 ;41.0000
P123=-59.0000 ;40.5620
P124=-58.9770 ;40.5000

P125=-58.8300 ;40.0000
P126=-58.6720 ;39.5000
P127=-58.6490 ;39.0000
P128=-58.6930 ;38.5000
P129=-58.5390 ;38.0000
P130=-58.5600 ;37.5000
P131=-58.6250 ;37.0000
P132=-58.8060 ;36.5000
P133=-58.7390 ;36.0000
P134=-58.8810 ;35.5000
P135=-58.9300 ;35.0000
P136=-59.0000 ;34.9230
P137=-59.2310 ;34.5000
P138=-59.1860 ;34.0000
P139=-59.3540 ;33.5000
P140=-59.4110 ;33.0000
P141=-59.5000 ;32.7210
P142=-59.5520 ;32.5000
P143=-59.6880 ;32.0000
P144=-59.7290 ;31.5000
P145=-59.8040 ;31.0000
P146=-59.9170 ;30.5000
P147=-60.0000 ;30.0180
P148=-60.0020 ;30.0000
P149=-60.1100 ;29.5000
P150=-60.0670 ;29.0000
P151=-60.0210 ;28.5000
P152=-60.0000 ;28.4590
P153=-59.9670 ;28.5000
P154=-59.6910 ;29.0000
P155=-59.5000 ;29.0930
P156=-59.3260 ;29.5000
P157=-59.1930 ;30.0000
P158=-59.0390 ;30.5000
P159=-59.0000 ;30.5760
P160=-58.8710 ;31.0000
P161=-58.7510 ;31.5000
P162=-58.6650 ;32.0000
P163=-58.5530 ;32.5000
P164=-58.5000 ;32.6590
P165=-58.3690 ;33.0000
P166=-58.3070 ;33.5000
P167=-58.1550 ;34.0000
P168=-58.0710 ;34.5000
P169=-58.0000 ;34.7400
P170=-57.8940 ;35.0000
P171=-57.8940 ;35.5000
P172=-57.6690 ;36.0000
P173=-57.6040 ;36.5000
P174=-57.5000 ;36.9470
P175=-57.4800 ;37.0000
P176=-57.3660 ;37.5000
P177=-57.4530 ;38.0000
P178=-57.3100 ;38.5000
P179=-57.3430 ;39.0000
P180=-57.4670 ;39.5000
P181=-57.5000 ;39.6390

[C5]

gain=-40.00

n_point=297

P1=-59.5000 ;37.2760
P2=-59.4920 ;37.0000
P3=-59.5000 ;36.9120
P4=-59.5540 ;36.5000
P5=-59.6440 ;36.0000
P6=-59.7270 ;35.5000
P7=-59.8170 ;35.0000
P8=-59.9460 ;34.5000
P9=-60.0000 ;34.2510
P10=-60.0790 ;34.0000
P11=-60.1980 ;33.5000
P12=-60.3650 ;33.0000
P13=-60.5000 ;32.5080
P14=-60.5030 ;32.5000
P15=-60.6660 ;32.0000
P16=-60.8500 ;31.5000
P17=-60.9950 ;31.0000
P18=-61.0000 ;30.9830
P19=-61.2000 ;30.5000
P20=-61.4080 ;30.0000
P21=-61.5000 ;29.7410
P22=-61.6090 ;29.5000
P23=-61.8680 ;29.0000
P24=-62.0000 ;28.7190
P25=-62.1220 ;28.5000
P26=-62.4320 ;28.0000
P27=-62.5000 ;27.8890
P28=-62.7680 ;27.5000
P29=-63.0000 ;27.1620
P30=-63.1270 ;27.0000
P31=-63.4910 ;26.5000
P32=-63.5000 ;26.4890
P33=-63.9290 ;26.0000
P34=-64.0000 ;25.9150
P35=-64.3690 ;25.5000
P36=-64.5000 ;25.3500
P37=-64.8180 ;25.0000
P38=-65.0000 ;24.7910
P39=-65.2710 ;24.5000
P40=-65.5000 ;24.2400
P41=-65.7260 ;24.0000
P42=-66.0000 ;23.7010
P43=-66.1870 ;23.5000
P44=-66.5000 ;23.1510
P45=-66.6450 ;23.0000
P46=-67.0000 ;22.5870
P47=-67.0800 ;22.5000
P48=-67.5000 ;22.0240
P49=-67.5220 ;22.0000
P50=-67.9860 ;21.5000
P51=-68.0000 ;21.4840
P52=-68.4680 ;21.0000
P53=-68.5000 ;20.9660
P54=-68.9640 ;20.5000

P55=-69.0000 ;20.4650
P56=-69.4960 ;20.0000
P57=-69.5000 ;19.9970
P58=-70.0000 ;19.5750
P59=-70.0900 ;19.5000
P60=-70.5000 ;19.1680
P61=-70.7060 ;19.0000
P62=-71.0000 ;18.7690
P63=-71.3360 ;18.5000
P64=-71.5000 ;18.3730
P65=-71.9710 ;18.0000
P66=-72.0000 ;17.9770
P67=-72.5000 ;17.5910
P68=-72.6040 ;17.5000
P69=-73.0000 ;17.1680
P70=-73.1780 ;17.0000
P71=-73.5000 ;16.7080
P72=-73.7080 ;16.5000
P73=-74.0000 ;16.2370
P74=-74.2490 ;16.0000
P75=-74.5000 ;15.7910
P76=-74.8390 ;15.5000
P77=-75.0000 ;15.3890
P78=-75.5000 ;15.0470
P79=-75.5660 ;15.0000
P80=-76.0000 ;14.7710
P81=-76.4930 ;14.5000
P82=-76.5000 ;14.4970
P83=-77.0000 ;14.3040
P84=-77.5000 ;14.1050
P85=-77.7630 ;14.0000
P86=-78.0000 ;13.9410
P87=-78.5000 ;13.8190
P88=-79.0000 ;13.6950
P89=-79.5000 ;13.5670
P90=-79.7570 ;13.5000
P91=-80.0000 ;13.4640
P92=-80.5000 ;13.3890
P93=-81.0000 ;13.3100
P94=-81.5000 ;13.2250
P95=-82.0000 ;13.1350
P96=-82.5000 ;13.0450
P97=-82.7600 ;13.0000
P98=-83.0000 ;12.9730
P99=-83.5000 ;12.9220
P100=-84.0000 ;12.8800
P101=-84.5000 ;12.8490
P102=-85.0000 ;12.8320
P103=-85.5000 ;12.8340
P104=-86.0000 ;12.8580
P105=-86.5000 ;12.9090
P106=-86.9540 ;13.0000
P107=-87.0000 ;13.0100
P108=-87.5000 ;13.1390
P109=-88.0000 ;13.2740
P110=-88.5000 ;13.4150
P111=-88.7110 ;13.5000

P112=-89.0000 ;13.6260
P113=-89.5000 ;13.8300
P114=-89.9310 ;14.0000
P115=-90.0000 ;14.0350
P116=-90.5000 ;14.2740
P117=-90.9880 ;14.5000
P118=-91.0000 ;14.5070
P119=-91.5000 ;14.7910
P120=-91.8600 ;15.0000
P121=-92.0000 ;15.0990
P122=-92.5000 ;15.4420
P123=-92.5730 ;15.5000
P124=-93.0000 ;15.8670
P125=-93.1380 ;16.0000
P126=-93.5000 ;16.3610
P127=-93.6240 ;16.5000
P128=-94.0000 ;16.9310
P129=-94.0550 ;17.0000
P130=-94.4350 ;17.5000
P131=-94.5000 ;17.5850
P132=-94.7840 ;18.0000
P133=-95.0000 ;18.2970
P134=-95.1170 ;18.5000
P135=-95.4640 ;19.0000
P136=-95.5000 ;19.0520
P137=-95.7480 ;19.5000
P138=-96.0000 ;19.8900
P139=-96.0530 ;20.0000
P140=-96.3070 ;20.5000
P141=-96.5000 ;20.8370
P142=-96.5650 ;21.0000
P143=-96.7630 ;21.5000
P144=-96.9810 ;22.0000
P145=-97.0000 ;22.0540
P146=-97.0880 ;22.5000
P147=-97.1970 ;23.0000
P148=-97.2970 ;23.5000
P149=-97.3860 ;24.0000
P150=-97.4600 ;24.5000
P151=-97.5000 ;24.7960
P152=-97.5120 ;25.0000
P153=-97.5320 ;25.5000
P154=-97.5450 ;26.0000
P155=-97.5560 ;26.5000
P156=-97.5700 ;27.0000
P157=-97.5840 ;27.5000
P158=-97.5930 ;28.0000
P159=-97.6000 ;28.5000
P160=-97.6090 ;29.0000
P161=-97.6080 ;29.5000
P162=-97.5910 ;30.0000
P163=-97.5610 ;30.5000
P164=-97.5260 ;31.0000
P165=-97.5000 ;31.3060
P166=-97.4690 ;31.5000
P167=-97.3580 ;32.0000
P168=-97.2370 ;32.5000

P169=-97.1170 ;33.0000
P170=-97.0010 ;33.5000
P171=-97.0000 ;33.5040
P172=-96.8040 ;34.0000
P173=-96.6190 ;34.5000
P174=-96.5000 ;34.8410
P175=-96.4230 ;35.0000
P176=-96.1810 ;35.5000
P177=-96.0000 ;35.9630
P178=-95.9790 ;36.0000
P179=-95.6820 ;36.5000
P180=-95.5000 ;36.8790
P181=-95.4190 ;37.0000
P182=-95.0980 ;37.5000
P183=-95.0000 ;37.6860
P184=-94.7770 ;38.0000
P185=-94.5000 ;38.4350
P186=-94.4510 ;38.5000
P187=-94.0610 ;39.0000
P188=-94.0000 ;39.0810
P189=-93.6440 ;39.5000
P190=-93.5000 ;39.6790
P191=-93.2160 ;40.0000
P192=-93.0000 ;40.2530
P193=-92.7700 ;40.5000
P194=-92.5000 ;40.7920
P195=-92.2960 ;41.0000
P196=-92.0000 ;41.2940
P197=-91.7860 ;41.5000
P198=-91.5000 ;41.7580
P199=-91.2350 ;42.0000
P200=-91.0000 ;42.1910
P201=-90.6390 ;42.5000
P202=-90.5000 ;42.6040
P203=-90.0130 ;43.0000
P204=-90.0000 ;43.0090
P205=-89.5000 ;43.3400
P206=-89.2810 ;43.5000
P207=-89.0000 ;43.6690
P208=-88.5230 ;44.0000
P209=-88.5000 ;44.0130
P210=-88.0000 ;44.2800
P211=-87.6520 ;44.5000
P212=-87.5000 ;44.5740
P213=-87.0000 ;44.8330
P214=-86.7090 ;45.0000
P215=-86.5000 ;45.0890
P216=-86.0000 ;45.3190
P217=-85.6460 ;45.5000
P218=-85.5000 ;45.5540
P219=-85.0000 ;45.7440
P220=-84.5000 ;45.9680
P221=-84.4260 ;46.0000
P222=-84.0000 ;46.1290
P223=-83.5000 ;46.2940
P224=-83.0000 ;46.4770
P225=-82.9360 ;46.5000

P226=-82.5000 ;46.6050
P227=-82.0000 ;46.7380
P228=-81.5000 ;46.8860
P229=-81.1350 ;47.0000
P230=-81.0000 ;47.0280
P231=-80.5000 ;47.1330
P232=-80.0000 ;47.2490
P233=-79.5000 ;47.3750
P234=-79.0250 ;47.5000
P235=-79.0000 ;47.5040
P236=-78.5000 ;47.5870
P237=-78.0000 ;47.6770
P238=-77.5000 ;47.7720
P239=-77.0000 ;47.8710
P240=-76.5000 ;47.9710
P241=-76.3460 ;48.0000
P242=-76.0000 ;48.0430
P243=-75.5000 ;48.0950
P244=-75.0000 ;48.1340
P245=-74.5000 ;48.1660
P246=-74.0000 ;48.1890
P247=-73.5000 ;48.2020
P248=-73.0000 ;48.2020
P249=-72.5000 ;48.1880
P250=-72.0000 ;48.1620
P251=-71.5000 ;48.1250
P252=-71.0000 ;48.0770
P253=-70.5000 ;48.0210
P254=-70.3400 ;48.0000
P255=-70.0000 ;47.9300
P256=-69.5000 ;47.8190
P257=-69.0000 ;47.7080
P258=-68.5000 ;47.6000
P259=-68.0860 ;47.5000
P260=-68.0000 ;47.4720
P261=-67.5000 ;47.2940
P262=-67.0000 ;47.1240
P263=-66.6140 ;47.0000
P264=-66.5000 ;46.9520
P265=-66.0000 ;46.7450
P266=-65.5000 ;46.5610
P267=-65.3320 ;46.5000
P268=-65.0000 ;46.3410
P269=-64.5000 ;46.1030
P270=-64.2770 ;46.0000
P271=-64.0000 ;45.8450
P272=-63.5000 ;45.5760
P273=-63.3610 ;45.5000
P274=-63.0000 ;45.2470
P275=-62.6720 ;45.0000
P276=-62.5000 ;44.8410
P277=-62.1790 ;44.5000
P278=-62.0000 ;44.2900
P279=-61.7890 ;44.0000
P280=-61.5000 ;43.5320
P281=-61.4830 ;43.5000
P282=-61.2340 ;43.0000

P283=-61.0000 ;42.5760
P284=-60.9650 ;42.5000
P285=-60.7740 ;42.0000
P286=-60.5540 ;41.5000
P287=-60.5000 ;41.3790
P288=-60.3640 ;41.0000
P289=-60.1580 ;40.5000
P290=-60.0000 ;40.0430
P291=-59.9890 ;40.0000
P292=-59.8560 ;39.5000
P293=-59.6900 ;39.0000
P294=-59.5860 ;38.5000
P295=-59.5360 ;38.0000
P296=-59.5100 ;37.5000
P297=-59.5000 ;37.2760

[C6]

gain=-40.00

n_point=407

P1=-64.5000 ;36.0710
P2=-64.5380 ;36.5000
P3=-64.5730 ;37.0000
P4=-64.6560 ;37.5000
P5=-64.8120 ;38.0000
P6=-65.0000 ;38.4630
P7=-65.0110 ;38.5000
P8=-65.2620 ;39.0000
P9=-65.5000 ;39.3580
P10=-65.5830 ;39.5000
P11=-65.9610 ;40.0000
P12=-66.0000 ;40.0410
P13=-66.4510 ;40.5000
P14=-66.5000 ;40.5440
P15=-67.0000 ;40.9660
P16=-67.0390 ;41.0000
P17=-67.5000 ;41.4410
P18=-67.5650 ;41.5000
P19=-68.0000 ;41.8750
P20=-68.1680 ;42.0000
P21=-68.5000 ;42.2670
P22=-68.8620 ;42.5000
P23=-69.0000 ;42.5980
P24=-69.5000 ;42.9000
P25=-69.7540 ;43.0000
P26=-70.0000 ;43.1320
P27=-70.5000 ;43.3630
P28=-70.9090 ;43.5000
P29=-71.0000 ;43.5420
P30=-71.5000 ;43.7440
P31=-72.0000 ;43.8810
P32=-72.5000 ;43.9680
P33=-72.7820 ;44.0000
P34=-73.0000 ;44.0480
P35=-73.5000 ;44.1320
P36=-74.0000 ;44.1900
P37=-74.5000 ;44.2240
P38=-75.0000 ;44.2380
P39=-75.5000 ;44.2350

P40=-76.0000 ;44.2200
P41=-76.5000 ;44.2100
P42=-77.0000 ;44.2030
P43=-77.5000 ;44.1840
P44=-78.0000 ;44.1530
P45=-78.5000 ;44.1090
P46=-79.0000 ;44.0520
P47=-79.3570 ;44.0000
P48=-79.5000 ;43.9900
P49=-80.0000 ;43.9480
P50=-80.5000 ;43.8890
P51=-81.0000 ;43.8080
P52=-81.5000 ;43.6960
P53=-82.0000 ;43.5450
P54=-82.1280 ;43.5000
P55=-82.5000 ;43.4330
P56=-83.0000 ;43.3080
P57=-83.5000 ;43.1190
P58=-83.7530 ;43.0000
P59=-84.0000 ;42.9340
P60=-84.5000 ;42.7600
P61=-84.9800 ;42.5000
P62=-85.0000 ;42.4920
P63=-85.5000 ;42.3120
P64=-86.0000 ;42.0090
P65=-86.0140 ;42.0000
P66=-86.5000 ;41.7870
P67=-86.9170 ;41.5000
P68=-87.0000 ;41.4550
P69=-87.5000 ;41.1660
P70=-87.7220 ;41.0000
P71=-88.0000 ;40.8370
P72=-88.4260 ;40.5000
P73=-88.5000 ;40.4500
P74=-89.0000 ;40.0660
P75=-89.0780 ;40.0000
P76=-89.5000 ;39.6810
P77=-89.7040 ;39.5000
P78=-90.0000 ;39.2530
P79=-90.2710 ;39.0000
P80=-90.5000 ;38.7980
P81=-90.8080 ;38.5000
P82=-91.0000 ;38.3140
P83=-91.3090 ;38.0000
P84=-91.5000 ;37.7920
P85=-91.7710 ;37.5000
P86=-92.0000 ;37.2190
P87=-92.1910 ;37.0000
P88=-92.5000 ;36.5700
P89=-92.5590 ;36.5000
P90=-92.9330 ;36.0000
P91=-93.0000 ;35.8990
P92=-93.3180 ;35.5000
P93=-93.5000 ;35.1570
P94=-93.6160 ;35.0000
P95=-93.9260 ;34.5000
P96=-94.0000 ;34.3440

P97=-94.2310 ;34.0000
P98=-94.4670 ;33.5000
P99=-94.5000 ;33.4140
P100=-94.7440 ;33.0000
P101=-94.9460 ;32.5000
P102=-95.0000 ;32.3180
P103=-95.1610 ;32.0000
P104=-95.3530 ;31.5000
P105=-95.4790 ;31.0000
P106=-95.5000 ;30.8910
P107=-95.6590 ;30.5000
P108=-95.7910 ;30.0000
P109=-95.8750 ;29.5000
P110=-95.9370 ;29.0000
P111=-95.9720 ;28.5000
P112=-95.9870 ;28.0000
P113=-95.9810 ;27.5000
P114=-95.9600 ;27.0000
P115=-95.9190 ;26.5000
P116=-95.8540 ;26.0000
P117=-95.7570 ;25.5000
P118=-95.6240 ;25.0000
P119=-95.5000 ;24.6410
P120=-95.4780 ;24.5000
P121=-95.3820 ;24.0000
P122=-95.2400 ;23.5000
P123=-95.0310 ;23.0000
P124=-95.0000 ;22.9320
P125=-94.8970 ;22.5000
P126=-94.6820 ;22.0000
P127=-94.5000 ;21.6770
P128=-94.4440 ;21.5000
P129=-94.1900 ;21.0000
P130=-94.0000 ;20.7430
P131=-93.8560 ;20.5000
P132=-93.5000 ;20.0570
P133=-93.4490 ;20.0000
P134=-93.0000 ;19.5200
P135=-92.9810 ;19.5000
P136=-92.5000 ;19.0410
P137=-92.4430 ;19.0000
P138=-92.0000 ;18.6200
P139=-91.8440 ;18.5000
P140=-91.5000 ;18.2370
P141=-91.1960 ;18.0000
P142=-91.0000 ;17.8500
P143=-90.5000 ;17.5700
P144=-90.3830 ;17.5000
P145=-90.0000 ;17.3430
P146=-89.7770 ;17.5000
P147=-90.0000 ;17.6430
P148=-90.2860 ;18.0000
P149=-90.5000 ;18.1820
P150=-90.8360 ;18.5000
P151=-91.0000 ;18.6490
P152=-91.3340 ;19.0000
P153=-91.5000 ;19.1680

P154=-91.8080 ;19.5000
P155=-92.0000 ;19.7210
P156=-92.2190 ;20.0000
P157=-92.5000 ;20.3580
P158=-92.5870 ;20.5000
P159=-92.8950 ;21.0000
P160=-93.0000 ;21.1650
P161=-93.1370 ;21.5000
P162=-93.3700 ;22.0000
P163=-93.5000 ;22.2700
P164=-93.5620 ;22.5000
P165=-93.6880 ;23.0000
P166=-93.8410 ;23.5000
P167=-94.0000 ;23.9740
P168=-94.0050 ;24.0000
P169=-94.0510 ;24.5000
P170=-94.1320 ;25.0000
P171=-94.2060 ;25.5000
P172=-94.2810 ;26.0000
P173=-94.3500 ;26.5000
P174=-94.4110 ;27.0000
P175=-94.4390 ;27.5000
P176=-94.4400 ;28.0000
P177=-94.4190 ;28.5000
P178=-94.3780 ;29.0000
P179=-94.3140 ;29.5000
P180=-94.2320 ;30.0000
P181=-94.1380 ;30.5000
P182=-94.0410 ;31.0000
P183=-94.0000 ;31.2050
P184=-93.8950 ;31.5000
P185=-93.7050 ;32.0000
P186=-93.5460 ;32.5000
P187=-93.5000 ;32.6400
P188=-93.3190 ;33.0000
P189=-93.0930 ;33.5000
P190=-93.0000 ;33.7110
P191=-92.8240 ;34.0000
P192=-92.5720 ;34.5000
P193=-92.5000 ;34.6280
P194=-92.2360 ;35.0000
P195=-92.0000 ;35.4040
P196=-91.9270 ;35.5000
P197=-91.5690 ;36.0000
P198=-91.5000 ;36.0880
P199=-91.1550 ;36.5000
P200=-91.0000 ;36.6840
P201=-90.7090 ;37.0000
P202=-90.5000 ;37.2240
P203=-90.2300 ;37.5000
P204=-90.0000 ;37.7290
P205=-89.7210 ;38.0000
P206=-89.5000 ;38.2020
P207=-89.1760 ;38.5000
P208=-89.0000 ;38.6460
P209=-88.5910 ;39.0000
P210=-88.5000 ;39.0720

P211=-88.0000 ;39.4400
P212=-87.9220 ;39.5000
P213=-87.5000 ;39.7580
P214=-87.1540 ;40.0000
P215=-87.0000 ;40.0940
P216=-86.5000 ;40.3700
P217=-86.2930 ;40.5000
P218=-86.0000 ;40.6400
P219=-85.5000 ;40.9010
P220=-85.3190 ;41.0000
P221=-85.0000 ;41.1190
P222=-84.5000 ;41.3280
P223=-84.1430 ;41.5000
P224=-84.0000 ;41.5480
P225=-83.5000 ;41.6860
P226=-83.0000 ;41.8630
P227=-82.6330 ;42.0000
P228=-82.5000 ;42.0350
P229=-82.0000 ;42.1310
P230=-81.5000 ;42.2380
P231=-81.0000 ;42.3570
P232=-80.5000 ;42.4780
P233=-80.3990 ;42.5000
P234=-80.0000 ;42.5620
P235=-79.5000 ;42.6210
P236=-79.0000 ;42.6710
P237=-78.5000 ;42.7150
P238=-78.0000 ;42.7520
P239=-77.5000 ;42.7790
P240=-77.0000 ;42.7850
P241=-76.5000 ;42.7770
P242=-76.0000 ;42.7560
P243=-75.5000 ;42.7200
P244=-75.0000 ;42.6710
P245=-74.5000 ;42.6120
P246=-74.0000 ;42.5490
P247=-73.5830 ;42.5000
P248=-73.5000 ;42.4780
P249=-73.0000 ;42.3200
P250=-72.5000 ;42.1640
P251=-72.0000 ;42.0400
P252=-71.8590 ;42.0000
P253=-71.5000 ;41.8220
P254=-71.0000 ;41.5550
P255=-70.8960 ;41.5000
P256=-70.5000 ;41.2320
P257=-70.1090 ;41.0000
P258=-70.0000 ;40.9190
P259=-69.5000 ;40.5590
P260=-69.4160 ;40.5000
P261=-69.0000 ;40.1670
P262=-68.7760 ;40.0000
P263=-68.5000 ;39.7450
P264=-68.2570 ;39.5000
P265=-68.0000 ;39.2280
P266=-67.8060 ;39.0000
P267=-67.5000 ;38.6420

P268=-67.4000 ;38.5000
P269=-67.0000 ;38.0140
P270=-66.9920 ;38.0000
P271=-66.7770 ;37.5000
P272=-66.5660 ;37.0000
P273=-66.5000 ;36.8640
P274=-66.3890 ;36.5000
P275=-66.2840 ;36.0000
P276=-66.2320 ;35.5000
P277=-66.1080 ;35.0000
P278=-66.0990 ;34.5000
P279=-66.0930 ;34.0000
P280=-66.0840 ;33.5000
P281=-66.1350 ;33.0000
P282=-66.1280 ;32.5000
P283=-66.2300 ;32.0000
P284=-66.2630 ;31.5000
P285=-66.3640 ;31.0000
P286=-66.4250 ;30.5000
P287=-66.5000 ;30.1330
P288=-66.5410 ;30.0000
P289=-66.7050 ;29.5000
P290=-66.8750 ;29.0000
P291=-67.0000 ;28.5400
P292=-67.0170 ;28.5000
P293=-67.2880 ;28.0000
P294=-67.4680 ;27.5000
P295=-67.5000 ;27.4410
P296=-67.7950 ;27.0000
P297=-68.0000 ;26.5750
P298=-68.0500 ;26.5000
P299=-68.3910 ;26.0000
P300=-68.5000 ;25.8230
P301=-68.7600 ;25.5000
P302=-69.0000 ;25.1350
P303=-69.1120 ;25.0000
P304=-69.4950 ;24.5000
P305=-69.5000 ;24.4940
P306=-69.9420 ;24.0000
P307=-70.0000 ;23.9320
P308=-70.4130 ;23.5000
P309=-70.5000 ;23.4010
P310=-70.8910 ;23.0000
P311=-71.0000 ;22.8870
P312=-71.3870 ;22.5000
P313=-71.5000 ;22.3840
P314=-71.8890 ;22.0000
P315=-72.0000 ;21.8910
P316=-72.4000 ;21.5000
P317=-72.5000 ;21.4050
P318=-72.9180 ;21.0000
P319=-73.0000 ;20.9250
P320=-73.4450 ;20.5000
P321=-73.5000 ;20.4500
P322=-73.9800 ;20.0000
P323=-74.0000 ;19.9820
P324=-74.5000 ;19.5480

P325=-74.5540 ;19.5000
P326=-75.0000 ;19.1410
P327=-75.1700 ;19.0000
P328=-75.5000 ;18.7500
P329=-75.8270 ;18.5000
P330=-76.0000 ;18.3640
P331=-76.5000 ;18.0150
P332=-76.5230 ;18.0000
P333=-77.0000 ;17.6580
P334=-77.2830 ;17.5000
P335=-77.5000 ;17.2900
P336=-78.0000 ;17.0670
P337=-78.1630 ;17.0000
P338=-78.0000 ;16.7550
P339=-77.5000 ;16.7200
P340=-77.0000 ;16.7940
P341=-76.5000 ;16.9350
P342=-76.3320 ;17.0000
P343=-76.0000 ;17.0940
P344=-75.5000 ;17.2540
P345=-75.0320 ;17.5000
P346=-75.0000 ;17.5130
P347=-74.5000 ;17.7290
P348=-74.1010 ;18.0000
P349=-74.0000 ;18.0520
P350=-73.5000 ;18.3820
P351=-73.3620 ;18.5000
P352=-73.0000 ;18.7760
P353=-72.7680 ;19.0000
P354=-72.5000 ;19.2180
P355=-72.2090 ;19.5000
P356=-72.0000 ;19.6970
P357=-71.7050 ;20.0000
P358=-71.5000 ;20.1880
P359=-71.1840 ;20.5000
P360=-71.0000 ;20.6780
P361=-70.6800 ;21.0000
P362=-70.5000 ;21.1710
P363=-70.1620 ;21.5000
P364=-70.0000 ;21.6650
P365=-69.6690 ;22.0000
P366=-69.5000 ;22.1690
P367=-69.1660 ;22.5000
P368=-69.0000 ;22.6840
P369=-68.6940 ;23.0000
P370=-68.5000 ;23.2310
P371=-68.2540 ;23.5000
P372=-68.0000 ;23.8420
P373=-67.8690 ;24.0000
P374=-67.5000 ;24.4940
P375=-67.4950 ;24.5000
P376=-67.0960 ;25.0000
P377=-67.0000 ;25.1850
P378=-66.7840 ;25.5000
P379=-66.5100 ;26.0000
P380=-66.5000 ;26.0230
P381=-66.2030 ;26.5000

P382=-66.0090 ;27.0000
P383=-66.0000 ;27.0240
P384=-65.7240 ;27.5000
P385=-65.5750 ;28.0000
P386=-65.5000 ;28.2420
P387=-65.3720 ;28.5000
P388=-65.2230 ;29.0000
P389=-65.0670 ;29.5000
P390=-65.0070 ;30.0000
P391=-65.0000 ;30.0350
P392=-64.8340 ;30.5000
P393=-64.7460 ;31.0000
P394=-64.6560 ;31.5000
P395=-64.5910 ;32.0000
P396=-64.5700 ;32.5000
P397=-64.5230 ;33.0000
P398=-64.5270 ;33.5000
P399=-64.5000 ;33.8540
P400=-64.4780 ;34.0000
P401=-64.4510 ;34.5000
P402=-64.5000 ;34.9450
P403=-64.5030 ;35.0000
P404=-64.5000 ;35.0700
P405=-64.4610 ;35.5000
P406=-64.4890 ;36.0000
P407=-64.5000 ;36.0710

[C7]

gain=-40.00

n_point=137

P1=-70.5000 ;32.5470
P2=-70.5710 ;33.0000
P3=-70.7040 ;33.5000
P4=-70.8120 ;34.0000
P5=-70.9800 ;34.5000
P6=-71.0000 ;34.5310
P7=-71.2440 ;35.0000
P8=-71.4840 ;35.5000
P9=-71.5000 ;35.5230
P10=-71.8120 ;36.0000
P11=-72.0000 ;36.2070
P12=-72.2280 ;36.5000
P13=-72.5000 ;36.7990
P14=-72.6830 ;37.0000
P15=-73.0000 ;37.2810
P16=-73.3470 ;37.5000
P17=-73.5000 ;37.6080
P18=-74.0000 ;37.8060
P19=-74.4510 ;38.0000
P20=-74.5000 ;38.0290
P21=-75.0000 ;38.3240
P22=-75.5000 ;38.4340
P23=-75.7330 ;38.5000
P24=-76.0000 ;38.6160
P25=-76.5000 ;38.7740
P26=-77.0000 ;38.7830
P27=-77.5000 ;38.7720
P28=-78.0000 ;38.8380

P29=-78.5000 ;38.8930
P30=-79.0000 ;38.9380
P31=-79.5000 ;38.9580
P32=-80.0000 ;38.9560
P33=-80.5000 ;38.9290
P34=-81.0000 ;38.8680
P35=-81.5000 ;38.7650
P36=-82.0000 ;38.6020
P37=-82.2490 ;38.5000
P38=-82.5000 ;38.4210
P39=-83.0000 ;38.3340
P40=-83.5000 ;38.1160
P41=-83.7070 ;38.0000
P42=-84.0000 ;37.8600
P43=-84.5000 ;37.6610
P44=-84.7510 ;37.5000
P45=-85.0000 ;37.2850
P46=-85.5000 ;37.0340
P47=-85.5490 ;37.0000
P48=-85.5000 ;36.8320
P49=-85.0000 ;36.8120
P50=-84.6090 ;37.0000
P51=-84.5000 ;37.1340
P52=-84.0000 ;37.2250
P53=-83.5000 ;37.4330
P54=-83.3560 ;37.5000
P55=-83.0000 ;37.6390
P56=-82.5000 ;37.7060
P57=-82.0000 ;37.8570
P58=-81.5540 ;38.0000
P59=-81.5000 ;38.0300
P60=-81.0000 ;38.0830
P61=-80.5000 ;38.0740
P62=-80.0000 ;38.0650
P63=-79.5000 ;38.0730
P64=-79.0000 ;38.0970
P65=-78.5000 ;38.1220
P66=-78.0000 ;38.1200
P67=-77.6070 ;38.0000
P68=-77.5000 ;37.9730
P69=-77.0000 ;37.7780
P70=-76.5000 ;37.7810
P71=-76.0000 ;37.6950
P72=-75.5000 ;37.5260
P73=-75.4590 ;37.5000
P74=-75.0000 ;37.2090
P75=-74.5000 ;37.0020
P76=-74.4970 ;37.0000
P77=-74.0000 ;36.6160
P78=-73.7230 ;36.5000
P79=-73.5000 ;36.3350
P80=-73.1850 ;36.0000
P81=-73.0000 ;35.8000
P82=-72.7600 ;35.5000
P83=-72.5000 ;35.1490
P84=-72.3940 ;35.0000
P85=-72.1410 ;34.5000

P86=-72.0000 ;34.2690
P87=-71.8860 ;34.0000
P88=-71.6880 ;33.5000
P89=-71.5000 ;33.0860
P90=-71.4720 ;33.0000
P91=-71.4050 ;32.5000
P92=-71.3180 ;32.0000
P93=-71.3210 ;31.5000
P94=-71.2720 ;31.0000
P95=-71.3340 ;30.5000
P96=-71.3780 ;30.0000
P97=-71.3780 ;29.5000
P98=-71.5000 ;29.1650
P99=-71.5370 ;29.0000
P100=-71.6580 ;28.5000
P101=-71.8330 ;28.0000
P102=-72.0000 ;27.5990
P103=-72.0460 ;27.5000
P104=-72.2170 ;27.0000
P105=-72.5000 ;26.6010
P106=-72.5660 ;26.5000
P107=-72.8220 ;26.0000
P108=-73.0000 ;25.7100
P109=-73.1460 ;25.5000
P110=-73.3890 ;25.0000
P111=-73.5000 ;24.8720
P112=-73.7200 ;24.5000
P113=-73.5000 ;24.2700
P114=-73.2990 ;24.5000
P115=-73.0000 ;24.7750
P116=-72.8170 ;25.0000
P117=-72.5000 ;25.3810
P118=-72.4090 ;25.5000
P119=-72.1180 ;26.0000
P120=-72.0000 ;26.2160
P121=-71.8290 ;26.5000
P122=-71.5940 ;27.0000
P123=-71.5000 ;27.0740
P124=-71.2510 ;27.5000
P125=-71.1490 ;28.0000
P126=-71.0000 ;28.2730
P127=-70.8630 ;28.5000
P128=-70.7230 ;29.0000
P129=-70.7090 ;29.5000
P130=-70.5520 ;30.0000
P131=-70.5000 ;30.3600
P132=-70.4610 ;30.5000
P133=-70.4300 ;31.0000
P134=-70.4320 ;31.5000
P135=-70.4660 ;32.0000
P136=-70.4860 ;32.5000
P137=-70.5000 ;32.5470
[C8]
gain=-30.00
n_point=147
P1=-72.0000 ;31.7540
P2=-71.9740 ;31.5000

P3=-71.9480 ;31.0000
P4=-71.9560 ;30.5000
P5=-71.9840 ;30.0000
P6=-72.0000 ;29.8520
P7=-72.0620 ;29.5000
P8=-72.1980 ;29.0000
P9=-72.3360 ;28.5000
P10=-72.4920 ;28.0000
P11=-72.5000 ;27.9740
P12=-72.7390 ;27.5000
P13=-72.9610 ;27.0000
P14=-73.0000 ;26.9190
P15=-73.2710 ;26.5000
P16=-73.5000 ;26.1180
P17=-73.5900 ;26.0000
P18=-73.9570 ;25.5000
P19=-74.0000 ;25.4400
P20=-74.3910 ;25.0000
P21=-74.5000 ;24.8700
P22=-74.8670 ;24.5000
P23=-75.0000 ;24.3640
P24=-75.4020 ;24.0000
P25=-75.5000 ;23.9120
P26=-75.9960 ;23.5000
P27=-76.0000 ;23.4970
P28=-76.5000 ;23.1560
P29=-76.7220 ;23.0000
P30=-77.0000 ;22.8240
P31=-77.4730 ;22.5000
P32=-77.5000 ;22.4830
P33=-78.0000 ;22.2150
P34=-78.2590 ;22.0000
P35=-78.5000 ;21.8660
P36=-78.9890 ;21.5000
P37=-79.0000 ;21.4940
P38=-79.5000 ;21.2000
P39=-79.7670 ;21.0000
P40=-80.0000 ;20.8850
P41=-80.5000 ;20.6290
P42=-80.7410 ;20.5000
P43=-81.0000 ;20.3960
P44=-81.5000 ;20.2170
P45=-82.0000 ;20.0450
P46=-82.1640 ;20.0000
P47=-82.5000 ;19.9260
P48=-83.0000 ;19.8510
P49=-83.5000 ;19.8120
P50=-84.0000 ;19.8020
P51=-84.5000 ;19.8270
P52=-85.0000 ;19.8870
P53=-85.4640 ;20.0000
P54=-85.5000 ;20.0090
P55=-86.0000 ;20.1590
P56=-86.5000 ;20.3320
P57=-86.8370 ;20.5000
P58=-87.0000 ;20.5880
P59=-87.5000 ;20.8920

P60=-87.6380 ;21.0000
P61=-88.0000 ;21.2910
P62=-88.2160 ;21.5000
P63=-88.5000 ;21.8020
P64=-88.6600 ;22.0000
P65=-89.0000 ;22.4450
P66=-89.0340 ;22.5000
P67=-89.3100 ;23.0000
P68=-89.5000 ;23.3510
P69=-89.5620 ;23.5000
P70=-89.7520 ;24.0000
P71=-89.9360 ;24.5000
P72=-90.0000 ;24.6950
P73=-90.0700 ;25.0000
P74=-90.1610 ;25.5000
P75=-90.2540 ;26.0000
P76=-90.3300 ;26.5000
P77=-90.3920 ;27.0000
P78=-90.4320 ;27.5000
P79=-90.4330 ;28.0000
P80=-90.3860 ;28.5000
P81=-90.3150 ;29.0000
P82=-90.2180 ;29.5000
P83=-90.1010 ;30.0000
P84=-90.0000 ;30.3960
P85=-89.9620 ;30.5000
P86=-89.7420 ;31.0000
P87=-89.5350 ;31.5000
P88=-89.5000 ;31.5770
P89=-89.2530 ;32.0000
P90=-89.0000 ;32.4570
P91=-88.9710 ;32.5000
P92=-88.6130 ;33.0000
P93=-88.5000 ;33.1570
P94=-88.2220 ;33.5000
P95=-88.0000 ;33.7580
P96=-87.7760 ;34.0000
P97=-87.5000 ;34.2840
P98=-87.2790 ;34.5000
P99=-87.0000 ;34.7530
P100=-86.7200 ;35.0000
P101=-86.5000 ;35.1660
P102=-86.0780 ;35.5000
P103=-86.0000 ;35.5490
P104=-85.5000 ;35.8590
P105=-85.2810 ;36.0000
P106=-85.0000 ;36.1390
P107=-84.5000 ;36.4140
P108=-84.3390 ;36.5000
P109=-84.0000 ;36.6300
P110=-83.5000 ;36.8380
P111=-83.1160 ;37.0000
P112=-83.0000 ;37.0320
P113=-82.5000 ;37.1560
P114=-82.0000 ;37.2790
P115=-81.5000 ;37.3900
P116=-81.0000 ;37.4790

P117=-80.8300 ;37.5000
P118=-80.5000 ;37.5230
P119=-80.0000 ;37.5400
P120=-79.5000 ;37.5400
P121=-79.0000 ;37.5230
P122=-78.6420 ;37.5000
P123=-78.5000 ;37.4840
P124=-78.0000 ;37.4010
P125=-77.5000 ;37.2970
P126=-77.0000 ;37.1790
P127=-76.5000 ;37.0510
P128=-76.3210 ;37.0000
P129=-76.0000 ;36.8540
P130=-75.5000 ;36.6260
P131=-75.2250 ;36.5000
P132=-75.0000 ;36.3620
P133=-74.5000 ;36.0560
P134=-74.4090 ;36.0000
P135=-74.0000 ;35.6490
P136=-73.8500 ;35.5000
P137=-73.5000 ;35.1270
P138=-73.4010 ;35.0000
P139=-73.0000 ;34.5010
P140=-72.9990 ;34.5000
P141=-72.7540 ;34.0000
P142=-72.5000 ;33.5510
P143=-72.4800 ;33.5000
P144=-72.3180 ;33.0000
P145=-72.1740 ;32.5000
P146=-72.0450 ;32.0000
P147=-72.0000 ;31.7540

[C9]

gain=-40.00

n_point=76

P1=-90.5000 ;24.0440
P2=-90.5865 ;24.2720
P3=-90.6730 ;24.5000
P4=-90.6920 ;24.7500
P5=-90.7110 ;25.0000
P6=-90.8110 ;25.2500
P7=-90.9110 ;25.5000
P8=-91.0000 ;25.7500
P9=-91.0780 ;26.0000
P10=-91.1075 ;26.2500
P11=-91.1370 ;26.5000
P12=-91.1325 ;26.7500
P13=-91.1280 ;27.0000
P14=-91.1305 ;27.2500
P15=-91.1330 ;27.5000
P16=-91.1410 ;27.7500
P17=-91.1490 ;28.0000
P18=-91.1530 ;28.2500
P19=-91.1570 ;28.5000
P20=-91.1445 ;28.7500
P21=-91.1320 ;29.0000
P22=-91.0660 ;29.2025
P23=-91.0000 ;29.4050

P24=-90.9760 ;29.5000
P25=-90.9220 ;29.7500
P26=-90.8680 ;30.0000
P27=-90.8340 ;30.2500
P28=-90.8000 ;30.5000
P29=-90.7735 ;30.7500
P30=-90.7470 ;31.0000
P31=-91.0000 ;31.0520
P32=-91.0290 ;31.0000
P33=-91.1200 ;30.7500
P34=-91.2110 ;30.5000
P35=-91.2980 ;30.2500
P36=-91.3850 ;30.0000
P37=-91.5000 ;29.8880
P38=-91.5790 ;29.6940
P39=-91.6580 ;29.5000
P40=-91.7225 ;29.2500
P41=-91.7870 ;29.0000
P42=-91.8335 ;28.7500
P43=-91.8800 ;28.5000
P44=-91.9160 ;28.2500
P45=-91.9520 ;28.0000
P46=-91.9680 ;27.7500
P47=-91.9840 ;27.5000
P48=-91.9825 ;27.2500
P49=-91.9810 ;27.0000
P50=-91.9580 ;26.7500
P51=-91.9350 ;26.5000
P52=-91.9150 ;26.2500
P53=-91.8950 ;26.0000
P54=-91.8920 ;25.7500
P55=-91.8890 ;25.5000
P56=-91.7840 ;25.2500
P57=-91.6790 ;25.0000
P58=-91.5895 ;24.8345
P59=-91.5000 ;24.6690
P60=-91.4200 ;24.5000
P61=-91.3600 ;24.2500
P62=-91.3000 ;24.0000
P63=-91.1500 ;23.7730
P64=-91.0000 ;23.5460
P65=-90.9270 ;23.5000
P66=-90.8320 ;23.3333
P67=-90.7370 ;23.1667
P68=-90.6420 ;23.0000
P69=-90.5000 ;22.8040
P70=-90.3620 ;22.9020
P71=-90.2240 ;23.0000
P72=-90.2615 ;23.2500
P73=-90.2990 ;23.5000
P74=-90.3890 ;23.7500
P75=-90.4790 ;24.0000
P76=-90.5000 ;24.0440
[C10]
gain=-30.00
n_point=78
P1=-80.5000 ;34.5210

P2=-80.6250 ;34.5205
P3=-80.7500 ;34.5200
P4=-80.8750 ;34.5195
P5=-81.0000 ;34.5190
P6=-81.1090 ;34.5000
P7=-81.2393 ;34.4757
P8=-81.3697 ;34.4513
P9=-81.5000 ;34.4270
P10=-81.6250 ;34.4173
P11=-81.7500 ;34.4075
P12=-81.8750 ;34.3978
P13=-82.0000 ;34.3880
P14=-82.1250 ;34.3623
P15=-82.2500 ;34.3365
P16=-82.3750 ;34.3107
P17=-82.5000 ;34.2850
P18=-82.6250 ;34.2295
P19=-82.7500 ;34.1740
P20=-82.8750 ;34.1185
P21=-83.0000 ;34.0630
P22=-83.1010 ;34.0000
P23=-83.2007 ;33.9462
P24=-83.3005 ;33.8925
P25=-83.4003 ;33.8388
P26=-83.5000 ;33.7850
P27=-83.6250 ;33.7155
P28=-83.7500 ;33.6460
P29=-83.8750 ;33.5765
P30=-84.0000 ;33.5070
P31=-84.0100 ;33.5000
P32=-84.1080 ;33.4072
P33=-84.2060 ;33.3144
P34=-84.3040 ;33.2216
P35=-84.4020 ;33.1288
P36=-84.5000 ;33.0360
P37=-84.5490 ;33.0000
P38=-84.5000 ;32.9700
P39=-84.3750 ;32.9752
P40=-84.2500 ;32.9805
P41=-84.1250 ;32.9857
P42=-84.0000 ;32.9910
P43=-83.9800 ;33.0000
P44=-83.8600 ;33.0615
P45=-83.7400 ;33.1230
P46=-83.6200 ;33.1845
P47=-83.5000 ;33.2460
P48=-83.3750 ;33.2570
P49=-83.2500 ;33.2680
P50=-83.1250 ;33.2790
P51=-83.0000 ;33.2900
P52=-82.8852 ;33.3425
P53=-82.7705 ;33.3950
P54=-82.6558 ;33.4475
P55=-82.5410 ;33.5000
P56=-82.5000 ;33.5460
P57=-82.3750 ;33.5835
P58=-82.2500 ;33.6210

P59=-82.1250 ;33.6585
P60=-82.0000 ;33.6960
P61=-81.8750 ;33.7265
P62=-81.7500 ;33.7570
P63=-81.6250 ;33.7875
P64=-81.5000 ;33.8180
P65=-81.3750 ;33.8555
P66=-81.2500 ;33.8930
P67=-81.1250 ;33.9305
P68=-81.0000 ;33.9680
P69=-80.8540 ;34.0000
P70=-80.7832 ;34.0876
P71=-80.7124 ;34.1752
P72=-80.6416 ;34.2628
P73=-80.5708 ;34.3504
P74=-80.5000 ;34.4380
P75=-80.4185 ;34.4690
P76=-80.3370 ;34.5000
P77=-80.4185 ;34.5105
P78=-80.5000 ;34.5210
[C11]
gain=-30.00
n_point=74
P1=-75.5000 ;32.6190
P2=-75.5750 ;32.7142
P3=-75.6500 ;32.8095
P4=-75.7250 ;32.9048
P5=-75.8000 ;33.0000
P6=-75.9000 ;33.0990
P7=-76.0000 ;33.1980
P8=-76.1250 ;33.2673
P9=-76.2500 ;33.3365
P10=-76.3750 ;33.4058
P11=-76.5000 ;33.4750
P12=-76.5460 ;33.5000
P13=-76.6973 ;33.5683
P14=-76.8487 ;33.6367
P15=-77.0000 ;33.7050
P16=-77.1017 ;33.6367
P17=-77.2033 ;33.5683
P18=-77.3050 ;33.5000
P19=-77.2033 ;33.4080
P20=-77.1017 ;33.3160
P21=-77.0000 ;33.2240
P22=-76.9260 ;33.1120
P23=-76.8520 ;33.0000
P24=-76.7793 ;32.8750
P25=-76.7065 ;32.7500
P26=-76.6337 ;32.6250
P27=-76.5610 ;32.5000
P28=-76.5000 ;32.4120
P29=-76.4543 ;32.2747
P30=-76.4087 ;32.1373
P31=-76.3630 ;32.0000
P32=-76.3060 ;31.8750
P33=-76.2490 ;31.7500
P34=-76.1920 ;31.6250

P35=-76.1350 ;31.5000
P36=-76.0675 ;31.3640
P37=-76.0000 ;31.2280
P38=-75.9480 ;31.1140
P39=-75.8960 ;31.0000
P40=-75.8372 ;30.8750
P41=-75.7785 ;30.7500
P42=-75.7197 ;30.6250
P43=-75.6610 ;30.5000
P44=-75.6457 ;30.3750
P45=-75.6305 ;30.2500
P46=-75.6152 ;30.1250
P47=-75.6000 ;30.0000
P48=-75.5667 ;29.8737
P49=-75.5333 ;29.7473
P50=-75.5000 ;29.6210
P51=-75.4093 ;29.7473
P52=-75.3187 ;29.8737
P53=-75.2280 ;30.0000
P54=-75.1947 ;30.1250
P55=-75.1615 ;30.2500
P56=-75.1283 ;30.3750
P57=-75.0950 ;30.5000
P58=-75.0760 ;30.6250
P59=-75.0570 ;30.7500
P60=-75.0380 ;30.8750
P61=-75.0190 ;31.0000
P62=-75.0283 ;31.1250
P63=-75.0375 ;31.2500
P64=-75.0468 ;31.3750
P65=-75.0560 ;31.5000
P66=-75.0730 ;31.6250
P67=-75.0900 ;31.7500
P68=-75.1070 ;31.8750
P69=-75.1240 ;32.0000
P70=-75.1973 ;32.1250
P71=-75.2705 ;32.2500
P72=-75.3438 ;32.3750
P73=-75.4170 ;32.5000
P74=-75.5000 ;32.6190
[C12]
gain=-30.00
n_point=78
P1=-76.5000 ;25.9990
P2=-76.6000 ;25.9052
P3=-76.7000 ;25.8114
P4=-76.8000 ;25.7176
P5=-76.9000 ;25.6238
P6=-77.0000 ;25.5300
P7=-77.0220 ;25.5000
P8=-77.1176 ;25.4070
P9=-77.2132 ;25.3140
P10=-77.3088 ;25.2210
P11=-77.4044 ;25.1280
P12=-77.5000 ;25.0350
P13=-77.5320 ;25.0000
P14=-77.6490 ;24.8997

P15=-77.7660 ;24.7995
P16=-77.8830 ;24.6992
P17=-78.0000 ;24.5990
P18=-78.1070 ;24.5000
P19=-78.2380 ;24.4013
P20=-78.3690 ;24.3027
P21=-78.5000 ;24.2040
P22=-78.6200 ;24.1020
P23=-78.7400 ;24.0000
P24=-78.8267 ;23.9247
P25=-78.9133 ;23.8493
P26=-79.0000 ;23.7740
P27=-79.1250 ;23.6827
P28=-79.2500 ;23.5913
P29=-79.3750 ;23.5000
P30=-79.4375 ;23.4160
P31=-79.5000 ;23.3320
P32=-79.6247 ;23.2490
P33=-79.7495 ;23.1660
P34=-79.8743 ;23.0830
P35=-79.9990 ;23.0000
P36=-79.8992 ;22.9054
P37=-79.7994 ;22.8108
P38=-79.6996 ;22.7162
P39=-79.5998 ;22.6216
P40=-79.5000 ;22.5270
P41=-79.3333 ;22.5463
P42=-79.1667 ;22.5657
P43=-79.0000 ;22.5850
P44=-78.8750 ;22.6345
P45=-78.7500 ;22.6840
P46=-78.6250 ;22.7335
P47=-78.5000 ;22.7830
P48=-78.4160 ;22.8553
P49=-78.3320 ;22.9277
P50=-78.2480 ;23.0000
P51=-78.1240 ;23.0645
P52=-78.0000 ;23.1290
P53=-77.9060 ;23.2218
P54=-77.8120 ;23.3145
P55=-77.7180 ;23.4072
P56=-77.6240 ;23.5000
P57=-77.5620 ;23.5730
P58=-77.5000 ;23.6460
P59=-77.4050 ;23.7640
P60=-77.3100 ;23.8820
P61=-77.2150 ;24.0000
P62=-77.1433 ;24.1333
P63=-77.0717 ;24.2667
P64=-77.0000 ;24.4000
P65=-76.9360 ;24.5000
P66=-76.8703 ;24.6250
P67=-76.8045 ;24.7500
P68=-76.7387 ;24.8750
P69=-76.6730 ;25.0000
P70=-76.6298 ;25.1150
P71=-76.5865 ;25.2300

P72=-76.5432 ;25.3450
P73=-76.5000 ;25.4600
P74=-76.4810 ;25.5000
P75=-76.4857 ;25.6248
P76=-76.4905 ;25.7495
P77=-76.4952 ;25.8743
P78=-76.5000 ;25.9990
[C13]
gain=-30.00
n_point=76
P1=-88.0000 ;28.8870
P2=-88.0625 ;28.7903
P3=-88.1250 ;28.6935
P4=-88.1875 ;28.5968
P5=-88.2500 ;28.5000
P6=-88.3333 ;28.4250
P7=-88.4167 ;28.3500
P8=-88.5000 ;28.2750
P9=-88.5513 ;28.1833
P10=-88.6027 ;28.0917
P11=-88.6540 ;28.0000
P12=-88.6872 ;27.9000
P13=-88.7204 ;27.8000
P14=-88.7536 ;27.7000
P15=-88.7868 ;27.6000
P16=-88.8200 ;27.5000
P17=-88.8366 ;27.4000
P18=-88.8532 ;27.3000
P19=-88.8698 ;27.2000
P20=-88.8864 ;27.1000
P21=-88.9030 ;27.0000
P22=-88.8930 ;26.9000
P23=-88.8830 ;26.8000
P24=-88.8730 ;26.7000
P25=-88.8630 ;26.6000
P26=-88.8530 ;26.5000
P27=-88.8128 ;26.4000
P28=-88.7726 ;26.3000
P29=-88.7324 ;26.2000
P30=-88.6922 ;26.1000
P31=-88.6520 ;26.0000
P32=-88.6013 ;25.9317
P33=-88.5507 ;25.8633
P34=-88.5000 ;25.7950
P35=-88.4157 ;25.7212
P36=-88.3315 ;25.6475
P37=-88.2473 ;25.5738
P38=-88.1630 ;25.5000
P39=-88.0815 ;25.4320
P40=-88.0000 ;25.3640
P41=-87.9505 ;25.4320
P42=-87.9010 ;25.5000
P43=-87.8714 ;25.6000
P44=-87.8418 ;25.7000
P45=-87.8122 ;25.8000
P46=-87.7826 ;25.9000
P47=-87.7530 ;26.0000

P48=-87.7526 ;26.1000
P49=-87.7522 ;26.2000
P50=-87.7518 ;26.3000
P51=-87.7514 ;26.4000
P52=-87.7510 ;26.5000
P53=-87.7590 ;26.6000
P54=-87.7670 ;26.7000
P55=-87.7750 ;26.8000
P56=-87.7830 ;26.9000
P57=-87.7910 ;27.0000
P58=-87.8016 ;27.1000
P59=-87.8122 ;27.2000
P60=-87.8228 ;27.3000
P61=-87.8334 ;27.4000
P62=-87.8440 ;27.5000
P63=-87.8538 ;27.6000
P64=-87.8636 ;27.7000
P65=-87.8734 ;27.8000
P66=-87.8832 ;27.9000
P67=-87.8930 ;28.0000
P68=-87.9002 ;28.1000
P69=-87.9074 ;28.2000
P70=-87.9146 ;28.3000
P71=-87.9218 ;28.4000
P72=-87.9290 ;28.5000
P73=-87.9468 ;28.5968
P74=-87.9645 ;28.6935
P75=-87.9822 ;28.7903
P76=-88.0000 ;28.8870

[C14]

gain=-20.00

n_point=115

P1=-76.5000 ;30.8240
P2=-76.4180 ;30.5000
P3=-76.3835 ;30.2500
P4=-76.3490 ;30.0000
P5=-76.3290 ;29.7500
P6=-76.3090 ;29.5000
P7=-76.3190 ;29.2500
P8=-76.3290 ;29.0000
P9=-76.3615 ;28.7500
P10=-76.3940 ;28.5000
P11=-76.4445 ;28.2500
P12=-76.4950 ;28.0000
P13=-76.5000 ;27.9840
P14=-76.5875 ;27.7420
P15=-76.6750 ;27.5000
P16=-76.7810 ;27.2500
P17=-76.8870 ;27.0000
P18=-77.0000 ;26.7770
P19=-77.1610 ;26.5000
P20=-77.3160 ;26.2500
P21=-77.4710 ;26.0000
P22=-77.5000 ;25.9600
P23=-77.6885 ;25.7300
P24=-77.8770 ;25.5000
P25=-78.0000 ;25.3590

P26=-78.3440 ;25.0000
P27=-78.5000 ;24.8610
P28=-78.7080 ;24.6805
P29=-78.9160 ;24.5000
P30=-79.0000 ;24.4360
P31=-79.2500 ;24.2565
P32=-79.5000 ;24.0770
P33=-79.6190 ;24.0000
P34=-80.0000 ;23.7890
P35=-80.2500 ;23.6555
P36=-80.5000 ;23.5220
P37=-80.5500 ;23.5000
P38=-81.0000 ;23.3170
P39=-81.2500 ;23.2295
P40=-81.5000 ;23.1420
P41=-82.0000 ;23.0100
P42=-82.0550 ;23.0000
P43=-82.5000 ;22.8930
P44=-83.0000 ;22.8290
P45=-83.5000 ;22.8120
P46=-84.0000 ;22.8620
P47=-84.4230 ;23.0000
P48=-84.5000 ;23.0170
P49=-84.7500 ;23.1080
P50=-85.0000 ;23.1990
P51=-85.3810 ;23.5000
P52=-85.5000 ;23.5740
P53=-85.7265 ;23.7870
P54=-85.9530 ;24.0000
P55=-86.0000 ;24.0440
P56=-86.1770 ;24.2720
P57=-86.3540 ;24.5000
P58=-86.5000 ;24.7000
P59=-86.6670 ;25.0000
P60=-86.7860 ;25.2500
P61=-86.9050 ;25.5000
P62=-87.0000 ;25.7280
P63=-87.0800 ;26.0000
P64=-87.1345 ;26.2500
P65=-87.1890 ;26.5000
P66=-87.2230 ;26.7500
P67=-87.2570 ;27.0000
P68=-87.2690 ;27.2500
P69=-87.2810 ;27.5000
P70=-87.2630 ;27.7500
P71=-87.2450 ;28.0000
P72=-87.2065 ;28.2500
P73=-87.1680 ;28.5000
P74=-87.1055 ;28.7500
P75=-87.0430 ;29.0000
P76=-87.0000 ;29.1250
P77=-86.8400 ;29.5000
P78=-86.7130 ;29.7500
P79=-86.5860 ;30.0000
P80=-86.5000 ;30.1360
P81=-86.2460 ;30.5000
P82=-86.0000 ;30.8040

P83=-85.8270 ;31.0000
P84=-85.5000 ;31.3140
P85=-85.2930 ;31.5000
P86=-85.0000 ;31.7250
P87=-84.6370 ;32.0000
P88=-84.5000 ;32.0820
P89=-84.2500 ;32.2325
P90=-84.0000 ;32.3830
P91=-83.8040 ;32.5000
P92=-83.5000 ;32.6230
P93=-83.0000 ;32.8420
P94=-82.6330 ;33.0000
P95=-82.5000 ;33.0360
P96=-82.0000 ;33.1650
P97=-81.5000 ;33.2870
P98=-81.0000 ;33.3800
P99=-80.5000 ;33.4340
P100=-80.0000 ;33.4350
P101=-79.5000 ;33.3860
P102=-79.0000 ;33.2800
P103=-78.5000 ;33.1120
P104=-78.2600 ;33.0000
P105=-78.0000 ;32.8460
P106=-77.7705 ;32.6730
P107=-77.5410 ;32.5000
P108=-77.5000 ;32.4640
P109=-77.2915 ;32.2320
P110=-77.0830 ;32.0000
P111=-77.0000 ;31.8820
P112=-76.7890 ;31.5000
P113=-76.6760 ;31.2500
P114=-76.5630 ;31.0000
P115=-76.5000 ;30.8240
[C15]
gain=-10.00
n_point=108
P1=-78.0000 ;30.7790
P2=-77.8550 ;30.5000
P3=-77.7750 ;30.2500
P4=-77.6950 ;30.0000
P5=-77.6470 ;29.7500
P6=-77.5990 ;29.5000
P7=-77.5980 ;29.2500
P8=-77.5970 ;29.0000
P9=-77.6245 ;28.7500
P10=-77.6520 ;28.5000
P11=-77.7100 ;28.2500
P12=-77.7680 ;28.0000
P13=-77.8540 ;27.7500
P14=-77.9400 ;27.5000
P15=-78.0000 ;27.3640
P16=-78.0930 ;27.1820
P17=-78.1860 ;27.0000
P18=-78.3385 ;26.7500
P19=-78.4910 ;26.5000
P20=-78.5000 ;26.4880
P21=-78.6970 ;26.2440

P22=-78.8940 ;26.0000
P23=-79.0000 ;25.8870
P24=-79.2015 ;25.6935
P25=-79.4030 ;25.5000
P26=-79.5000 ;25.4190
P27=-79.7500 ;25.2325
P28=-80.0000 ;25.0460
P29=-80.0720 ;25.0000
P30=-80.2860 ;24.8830
P31=-80.5000 ;24.7660
P32=-80.7500 ;24.6495
P33=-81.0000 ;24.5330
P34=-81.0910 ;24.5000
P35=-81.2955 ;24.4390
P36=-81.5000 ;24.3780
P37=-81.7500 ;24.3265
P38=-82.0000 ;24.2750
P39=-82.2500 ;24.2515
P40=-82.5000 ;24.2280
P41=-82.7500 ;24.2325
P42=-83.0000 ;24.2370
P43=-83.2500 ;24.2745
P44=-83.5000 ;24.3120
P45=-83.7500 ;24.3805
P46=-84.0000 ;24.4490
P47=-84.1210 ;24.5000
P48=-84.3105 ;24.5985
P49=-84.5000 ;24.6970
P50=-84.7225 ;24.8485
P51=-84.9450 ;25.0000
P52=-85.0000 ;25.0470
P53=-85.2160 ;25.2735
P54=-85.4320 ;25.5000
P55=-85.5000 ;25.5930
P56=-85.6180 ;25.7965
P57=-85.7360 ;26.0000
P58=-85.8450 ;26.2500
P59=-85.9540 ;26.5000
P60=-86.0000 ;26.6850
P61=-86.0610 ;27.0000
P62=-86.0790 ;27.2500
P63=-86.0970 ;27.5000
P64=-86.0805 ;27.7500
P65=-86.0640 ;28.0000
P66=-86.0320 ;28.1865
P67=-86.0000 ;28.3730
P68=-85.9730 ;28.5000
P69=-85.8765 ;28.7500
P70=-85.7800 ;29.0000
P71=-85.6630 ;29.2500
P72=-85.5460 ;29.5000
P73=-85.5000 ;29.5750
P74=-85.3510 ;29.7875
P75=-85.2020 ;30.0000
P76=-85.0000 ;30.2480
P77=-84.7670 ;30.5000
P78=-84.5000 ;30.7560

P79=-84.2120 ;31.0000
P80=-84.0000 ;31.1520
P81=-83.7500 ;31.3145
P82=-83.5000 ;31.4770
P83=-83.4590 ;31.5000
P84=-83.2295 ;31.6090
P85=-83.0000 ;31.7180
P86=-82.7500 ;31.8220
P87=-82.5000 ;31.9260
P88=-82.2720 ;32.0000
P89=-82.0000 ;32.0740
P90=-81.7500 ;32.1205
P91=-81.5000 ;32.1670
P92=-81.2500 ;32.1910
P93=-81.0000 ;32.2150
P94=-80.7500 ;32.2130
P95=-80.5000 ;32.2110
P96=-80.2500 ;32.1780
P97=-80.0000 ;32.1450
P98=-79.7500 ;32.0820
P99=-79.5000 ;32.0190
P100=-79.4500 ;32.0000
P101=-79.2250 ;31.8875
P102=-79.0000 ;31.7750
P103=-78.7995 ;31.6375
P104=-78.5990 ;31.5000
P105=-78.5000 ;31.4120
P106=-78.3235 ;31.2060
P107=-78.1470 ;31.0000
P108=-78.0000 ;30.7790
[C16]
gain=-6.00
n_point=95
P1=-78.5000 ;29.3170
P2=-78.4840 ;29.1585
P3=-78.4680 ;29.0000
P4=-78.4815 ;28.7500
P5=-78.4950 ;28.5000
P6=-78.5000 ;28.4780
P7=-78.5570 ;28.2390
P8=-78.6140 ;28.0000
P9=-78.7120 ;27.7500
P10=-78.8100 ;27.5000
P11=-78.9050 ;27.3110
P12=-79.0000 ;27.1220
P13=-79.0710 ;27.0000
P14=-79.1953 ;26.8333
P15=-79.3197 ;26.6667
P16=-79.4440 ;26.5000
P17=-79.5000 ;26.4370
P18=-79.6487 ;26.2913
P19=-79.7973 ;26.1457
P20=-79.9460 ;26.0000
P21=-80.0000 ;25.9550
P22=-80.2500 ;25.7800
P23=-80.5000 ;25.6050
P24=-80.6800 ;25.5000

P25=-80.8400 ;25.4220
P26=-81.0000 ;25.3440
P27=-81.2500 ;25.2525
P28=-81.5000 ;25.1610
P29=-81.7500 ;25.1035
P30=-82.0000 ;25.0460
P31=-82.2375 ;25.0230
P32=-82.4750 ;25.0000
P33=-82.5000 ;24.9980
P34=-82.5300 ;25.0000
P35=-82.7650 ;25.0200
P36=-83.0000 ;25.0400
P37=-83.2500 ;25.1015
P38=-83.5000 ;25.1630
P39=-83.7500 ;25.2735
P40=-84.0000 ;25.3840
P41=-84.1870 ;25.5000
P42=-84.3435 ;25.6305
P43=-84.5000 ;25.7610
P44=-84.6085 ;25.8805
P45=-84.7170 ;26.0000
P46=-84.8585 ;26.2105
P47=-85.0000 ;26.4210
P48=-85.0410 ;26.5000
P49=-85.1190 ;26.7500
P50=-85.1970 ;27.0000
P51=-85.2325 ;27.2500
P52=-85.2680 ;27.5000
P53=-85.2530 ;27.7500
P54=-85.2380 ;28.0000
P55=-85.1860 ;28.2500
P56=-85.1340 ;28.5000
P57=-85.0670 ;28.6765
P58=-85.0000 ;28.8530
P59=-84.9340 ;29.0000
P60=-84.7855 ;29.2500
P61=-84.6370 ;29.5000
P62=-84.5000 ;29.6820
P63=-84.3625 ;29.8410
P64=-84.2250 ;30.0000
P65=-84.0000 ;30.2160
P66=-83.8295 ;30.3580
P67=-83.6590 ;30.5000
P68=-83.5000 ;30.6140
P69=-83.2500 ;30.7640
P70=-83.0000 ;30.9140
P71=-82.8190 ;31.0000
P72=-82.6595 ;31.0640
P73=-82.5000 ;31.1280
P74=-82.2500 ;31.2035
P75=-82.0000 ;31.2790
P76=-81.7500 ;31.3265
P77=-81.5000 ;31.3740
P78=-81.2500 ;31.3875
P79=-81.0000 ;31.4010
P80=-80.7500 ;31.3750
P81=-80.5000 ;31.3490

P82=-80.2500 ;31.2790
P83=-80.0000 ;31.2090
P84=-79.7815 ;31.1045
P85=-79.5630 ;31.0000
P86=-79.5000 ;30.9610
P87=-79.3333 ;30.8147
P88=-79.1667 ;30.6683
P89=-79.0000 ;30.5220
P90=-78.9810 ;30.5000
P91=-78.8355 ;30.2500
P92=-78.6900 ;30.0000
P93=-78.6065 ;29.7500
P94=-78.5230 ;29.5000
P95=-78.5000 ;29.3170

[C17]

gain=-4.00

n_point=90

P1=-79.5000 ;30.0720
P2=-79.4440 ;30.0000
P3=-79.3597 ;29.8333
P4=-79.2753 ;29.6667
P5=-79.1910 ;29.5000
P6=-79.1547 ;29.3333
P7=-79.1183 ;29.1667
P8=-79.0820 ;29.0000
P9=-79.0857 ;28.8333
P10=-79.0893 ;28.6667
P11=-79.0930 ;28.5000
P12=-79.1270 ;28.3333
P13=-79.1610 ;28.1667
P14=-79.1950 ;28.0000
P15=-79.2620 ;27.8333
P16=-79.3290 ;27.6667
P17=-79.3960 ;27.5000
P18=-79.5000 ;27.3130
P19=-79.6025 ;27.1565
P20=-79.7050 ;27.0000
P21=-79.8525 ;26.8240
P22=-80.0000 ;26.6480
P23=-80.1490 ;26.5000
P24=-80.3245 ;26.3555
P25=-80.5000 ;26.2110
P26=-80.6595 ;26.1055
P27=-80.8190 ;26.0000
P28=-81.0000 ;25.9000
P29=-81.1667 ;25.8330
P30=-81.3333 ;25.7660
P31=-81.5000 ;25.6990
P32=-81.7500 ;25.6350
P33=-82.0000 ;25.5710
P34=-82.2500 ;25.5530
P35=-82.5000 ;25.5350
P36=-82.7500 ;25.5670
P37=-83.0000 ;25.5990
P38=-83.1667 ;25.6583
P39=-83.3333 ;25.7177
P40=-83.5000 ;25.7770

P41=-83.6905 ;25.8885
P42=-83.8810 ;26.0000
P43=-84.0000 ;26.0940
P44=-84.1183 ;26.2293
P45=-84.2367 ;26.3647
P46=-84.3550 ;26.5000
P47=-84.4275 ;26.6330
P48=-84.5000 ;26.7660
P49=-84.5480 ;26.8830
P50=-84.5960 ;27.0000
P51=-84.6287 ;27.1667
P52=-84.6613 ;27.3333
P53=-84.6940 ;27.5000
P54=-84.6877 ;27.6667
P55=-84.6813 ;27.8333
P56=-84.6750 ;28.0000
P57=-84.6393 ;28.1667
P58=-84.6037 ;28.3333
P59=-84.5680 ;28.5000
P60=-84.5000 ;28.6680
P61=-84.4185 ;28.8340
P62=-84.3370 ;29.0000
P63=-84.2263 ;29.1667
P64=-84.1157 ;29.3333
P65=-84.0050 ;29.5000
P66=-84.0000 ;29.5060
P67=-83.8340 ;29.6707
P68=-83.6680 ;29.8353
P69=-83.5020 ;30.0000
P70=-83.5000 ;30.0010
P71=-83.3333 ;30.1103
P72=-83.1667 ;30.2197
P73=-83.0000 ;30.3290
P74=-82.8380 ;30.4145
P75=-82.6760 ;30.5000
P76=-82.5000 ;30.5790
P77=-82.2500 ;30.6565
P78=-82.0000 ;30.7340
P79=-81.7500 ;30.7745
P80=-81.5000 ;30.8150
P81=-81.2500 ;30.8150
P82=-81.0000 ;30.8150
P83=-80.7500 ;30.7680
P84=-80.5000 ;30.7210
P85=-80.2500 ;30.6185
P86=-80.0000 ;30.5160
P87=-79.9750 ;30.5000
P88=-79.8167 ;30.3573
P89=-79.6583 ;30.2147
P90=-79.5000 ;30.0720
[C18]
gain=-2.00
n_point=84
P1=-80.0000 ;29.1440
P2=-79.9420 ;29.0000
P3=-79.9273 ;28.8333
P4=-79.9127 ;28.6667

P5=-79.8980 ;28.5000
P6=-79.9260 ;28.3333
P7=-79.9540 ;28.1667
P8=-79.9820 ;28.0000
P9=-80.0000 ;27.9560
P10=-80.0773 ;27.8040
P11=-80.1547 ;27.6520
P12=-80.2320 ;27.5000
P13=-80.3213 ;27.3790
P14=-80.4107 ;27.2580
P15=-80.5000 ;27.1370
P16=-80.5635 ;27.0685
P17=-80.6270 ;27.0000
P18=-80.7513 ;26.9013
P19=-80.8757 ;26.8027
P20=-81.0000 ;26.7040
P21=-81.1150 ;26.6360
P22=-81.2300 ;26.5680
P23=-81.3450 ;26.5000
P24=-81.5000 ;26.4290
P25=-81.6667 ;26.3890
P26=-81.8333 ;26.3490
P27=-82.0000 ;26.3090
P28=-82.1667 ;26.3050
P29=-82.3333 ;26.3010
P30=-82.5000 ;26.2970
P31=-82.6667 ;26.3343
P32=-82.8333 ;26.3717
P33=-83.0000 ;26.4090
P34=-83.0895 ;26.4545
P35=-83.1790 ;26.5000
P36=-83.2860 ;26.5847
P37=-83.3930 ;26.6693
P38=-83.5000 ;26.7540
P39=-83.5955 ;26.8770
P40=-83.6910 ;27.0000
P41=-83.7420 ;27.1250
P42=-83.7930 ;27.2500
P43=-83.8440 ;27.3750
P44=-83.8950 ;27.5000
P45=-83.8997 ;27.6667
P46=-83.9043 ;27.8333
P47=-83.9090 ;28.0000
P48=-83.8633 ;28.1667
P49=-83.8177 ;28.3333
P50=-83.7720 ;28.5000
P51=-83.7060 ;28.6250
P52=-83.6400 ;28.7500
P53=-83.5740 ;28.8750
P54=-83.5080 ;29.0000
P55=-83.5000 ;29.0100
P56=-83.3808 ;29.1325
P57=-83.2615 ;29.2550
P58=-83.1423 ;29.3775
P59=-83.0230 ;29.5000
P60=-83.0000 ;29.5190
P61=-82.8750 ;29.5920

P62=-82.7500 ;29.6650
P63=-82.6250 ;29.7380
P64=-82.5000 ;29.8110
P65=-82.3397 ;29.8740
P66=-82.1793 ;29.9370
P67=-82.0190 ;30.0000
P68=-82.0000 ;30.0060
P69=-81.8333 ;30.0257
P70=-81.6667 ;30.0453
P71=-81.5000 ;30.0650
P72=-81.3333 ;30.0487
P73=-81.1667 ;30.0323
P74=-81.0000 ;30.0160
P75=-80.9520 ;30.0000
P76=-80.8013 ;29.9243
P77=-80.6507 ;29.8487
P78=-80.5000 ;29.7730
P79=-80.4023 ;29.6820
P80=-80.3047 ;29.5910
P81=-80.2070 ;29.5000
P82=-80.1380 ;29.3813
P83=-80.0690 ;29.2627
P84=-80.0000 ;29.1440
[C19]
gain=-50.00
n_point=145
P1=-59.5000 ;26.3460
P2=-59.9990 ;26.0000
P3=-60.0000 ;25.9990
P4=-60.3040 ;25.5000
P5=-60.5000 ;25.3420
P6=-60.7330 ;25.0000
P7=-61.0000 ;24.6760
P8=-61.1300 ;24.5000
P9=-61.5000 ;24.0790
P10=-61.5580 ;24.0000
P11=-61.9640 ;23.5000
P12=-62.0000 ;23.4710
P13=-62.4120 ;23.0000
P14=-62.5000 ;22.9150
P15=-62.8560 ;22.5000
P16=-63.0000 ;22.3610
P17=-63.3280 ;22.0000
P18=-63.5000 ;21.8400
P19=-63.8070 ;21.5000
P20=-64.0000 ;21.3070
P21=-64.2780 ;21.0000
P22=-64.5000 ;20.7870
P23=-64.7700 ;20.5000
P24=-65.0000 ;20.2890
P25=-65.2850 ;20.0000
P26=-65.5000 ;19.8020
P27=-65.8000 ;19.5000
P28=-66.0000 ;19.3220
P29=-66.3340 ;19.0000
P30=-66.5000 ;18.8650
P31=-66.8900 ;18.5000

P32=-67.0000 ;18.4090
P33=-67.4450 ;18.0000
P34=-67.5000 ;17.9630
P35=-68.0000 ;17.5320
P36=-68.0370 ;17.5000
P37=-68.5000 ;17.1670
P38=-68.6970 ;17.0000
P39=-69.0000 ;16.8190
P40=-69.3810 ;16.5000
P41=-69.5000 ;16.4210
P42=-69.9920 ;16.0000
P43=-70.0000 ;15.9940
P44=-70.5000 ;15.7100
P45=-70.7650 ;15.5000
P46=-71.0000 ;15.3560
P47=-71.4530 ;15.0000
P48=-71.5000 ;14.9680
P49=-72.0000 ;14.7170
P50=-72.3320 ;14.5000
P51=-72.5000 ;14.4070
P52=-73.0000 ;14.1700
P53=-73.3180 ;14.0000
P54=-73.5000 ;13.9310
P55=-74.0000 ;13.7850
P56=-74.5000 ;13.6310
P57=-75.0000 ;13.5120
P58=-75.0910 ;13.5000
P59=-75.5000 ;13.4730
P60=-76.0000 ;13.4430
P61=-76.5000 ;13.4010
P62=-77.0000 ;13.3540
P63=-77.5000 ;13.2890
P64=-78.0000 ;13.1900
P65=-78.5000 ;13.0690
P66=-78.7730 ;13.0000
P67=-79.0000 ;12.9120
P68=-79.5000 ;12.7660
P69=-80.0000 ;12.6510
P70=-80.5000 ;12.5600
P71=-80.8660 ;12.5000
P72=-80.5000 ;12.4320
P73=-80.0000 ;12.3470
P74=-79.5000 ;12.2600
P75=-79.0000 ;12.1720
P76=-78.5000 ;12.0840
P77=-78.0210 ;12.0000
P78=-78.0000 ;11.9910
P79=-77.5000 ;11.8170
P80=-77.0000 ;11.7740
P81=-76.5000 ;11.8240
P82=-76.0000 ;11.9600
P83=-75.8960 ;12.0000
P84=-75.5000 ;12.0830
P85=-75.0000 ;12.2480
P86=-74.5000 ;12.4810
P87=-74.4630 ;12.5000
P88=-74.0000 ;12.6700

P89=-73.5000 ;12.8760
P90=-73.2720 ;13.0000
P91=-73.0000 ;13.1240
P92=-72.5000 ;13.3550
P93=-72.2700 ;13.5000
P94=-72.0000 ;13.6210
P95=-71.5000 ;13.8990
P96=-71.3570 ;14.0000
P97=-71.0000 ;14.1920
P98=-70.5910 ;14.5000
P99=-70.5000 ;14.5520
P100=-70.0000 ;14.8850
P101=-69.8530 ;15.0000
P102=-69.5000 ;15.1790
P103=-69.1130 ;15.5000
P104=-69.0000 ;15.5730
P105=-68.5100 ;16.0000
P106=-68.5000 ;16.0110
P107=-68.0000 ;16.3330
P108=-67.8020 ;16.5000
P109=-67.5000 ;16.7220
P110=-67.1810 ;17.0000
P111=-67.0000 ;17.1160
P112=-66.5630 ;17.5000
P113=-66.5000 ;17.5600
P114=-66.0140 ;18.0000
P115=-66.0000 ;18.0130
P116=-65.5000 ;18.4390
P117=-65.4310 ;18.5000
P118=-65.0000 ;18.9000
P119=-64.8930 ;19.0000
P120=-64.5000 ;19.3880
P121=-64.3830 ;19.5000
P122=-64.0000 ;19.8910
P123=-63.8910 ;20.0000
P124=-63.5000 ;20.4120
P125=-63.4100 ;20.5000
P126=-63.0000 ;20.9580
P127=-62.9590 ;21.0000
P128=-62.5380 ;21.5000
P129=-62.5000 ;21.5530
P130=-62.1200 ;22.0000
P131=-62.0000 ;22.1440
P132=-61.7000 ;22.5000
P133=-61.5000 ;22.7490
P134=-61.2950 ;23.0000
P135=-61.0000 ;23.3960
P136=-60.9130 ;23.5000
P137=-60.5090 ;24.0000
P138=-60.5000 ;24.0180
P139=-60.2600 ;24.5000
P140=-60.0000 ;24.8160
P141=-59.8770 ;25.0000
P142=-59.7110 ;25.5000
P143=-59.5000 ;25.7730
P144=-59.3980 ;26.0000
P145=-59.5000 ;26.3460

[C20]

gain=-50.00

n_point=71

P1=-81.0000 ;9.5780
P2=-81.1000 ;9.5692
P3=-81.2000 ;9.5604
P4=-81.3000 ;9.5516
P5=-81.4000 ;9.5428
P6=-81.5000 ;9.5340
P7=-81.5630 ;9.5170
P8=-81.6260 ;9.5000
P9=-81.7195 ;9.4800
P10=-81.8130 ;9.4600
P11=-81.9065 ;9.4400
P12=-82.0000 ;9.4200
P13=-82.1000 ;9.4018
P14=-82.2000 ;9.3836
P15=-82.3000 ;9.3654
P16=-82.4000 ;9.3472
P17=-82.5000 ;9.3290
P18=-82.6000 ;9.3078
P19=-82.7000 ;9.2866
P20=-82.8000 ;9.2654
P21=-82.9000 ;9.2442
P22=-83.0000 ;9.2230
P23=-83.1000 ;9.1984
P24=-83.2000 ;9.1738
P25=-83.3000 ;9.1492
P26=-83.4000 ;9.1246
P27=-83.5000 ;9.1000
P28=-83.5894 ;9.0800
P29=-83.6788 ;9.0600
P30=-83.7682 ;9.0400
P31=-83.8576 ;9.0200
P32=-83.9470 ;9.0000
P33=-83.8576 ;8.9632
P34=-83.7682 ;8.9264
P35=-83.6788 ;8.8896
P36=-83.5894 ;8.8528
P37=-83.5000 ;8.8160
P38=-83.4000 ;8.7908
P39=-83.3000 ;8.7656
P40=-83.2000 ;8.7404
P41=-83.1000 ;8.7152
P42=-83.0000 ;8.6900
P43=-82.9000 ;8.6796
P44=-82.8000 ;8.6692
P45=-82.7000 ;8.6588
P46=-82.6000 ;8.6484
P47=-82.5000 ;8.6380
P48=-82.4000 ;8.6384
P49=-82.3000 ;8.6388
P50=-82.2000 ;8.6392
P51=-82.1000 ;8.6396
P52=-82.0000 ;8.6400
P53=-81.9000 ;8.6568
P54=-81.8000 ;8.6736

P55=-81.7000 ;8.6904
P56=-81.6000 ;8.7072
P57=-81.5000 ;8.7240
P58=-81.4000 ;8.7702
P59=-81.3000 ;8.8164
P60=-81.2000 ;8.8626
P61=-81.1000 ;8.9088
P62=-81.0000 ;8.9550
P63=-80.9230 ;9.0000
P64=-80.8726 ;9.1000
P65=-80.8222 ;9.2000
P66=-80.7718 ;9.3000
P67=-80.7214 ;9.4000
P68=-80.6710 ;9.5000
P69=-80.7807 ;9.5260
P70=-80.8903 ;9.5520
P71=-81.0000 ;9.5780
[C21]
gain=-50.00
n_point=80
P1=-78.5000 ;7.5510
P2=-78.7500 ;7.5815
P3=-79.0000 ;7.6120
P4=-79.2500 ;7.5740
P5=-79.5000 ;7.5360
P6=-79.5930 ;7.5000
P7=-79.7965 ;7.4650
P8=-80.0000 ;7.4300
P9=-80.2500 ;7.3450
P10=-80.5000 ;7.2600
P11=-80.7050 ;7.1300
P12=-80.9100 ;7.0000
P13=-81.0000 ;6.9630
P14=-81.2500 ;6.8750
P15=-81.5000 ;6.7870
P16=-81.7490 ;6.6435
P17=-81.9980 ;6.5000
P18=-82.0000 ;6.4990
P19=-82.2500 ;6.4495
P20=-82.5000 ;6.4000
P21=-82.7500 ;6.3235
P22=-83.0000 ;6.2470
P23=-83.2500 ;6.1760
P24=-83.5000 ;6.1050
P25=-83.7225 ;6.0525
P26=-83.9450 ;6.0000
P27=-84.0000 ;5.9830
P28=-84.2500 ;5.9365
P29=-84.5000 ;5.8900
P30=-84.7500 ;5.8575
P31=-85.0000 ;5.8250
P32=-85.2500 ;5.7985
P33=-85.5000 ;5.7720
P34=-85.7500 ;5.7465
P35=-86.0000 ;5.7210
P36=-86.2500 ;5.6820
P37=-86.5000 ;5.6430

P38=-86.6635 ;5.5715
P39=-86.8270 ;5.5000
P40=-86.6635 ;5.4745
P41=-86.5000 ;5.4490
P42=-86.2500 ;5.4130
P43=-86.0000 ;5.3770
P44=-85.7500 ;5.3420
P45=-85.5000 ;5.3070
P46=-85.2500 ;5.2735
P47=-85.0000 ;5.2400
P48=-84.7500 ;5.2115
P49=-84.5000 ;5.1830
P50=-84.2500 ;5.1655
P51=-84.0000 ;5.1480
P52=-83.7500 ;5.1420
P53=-83.5000 ;5.1360
P54=-83.2500 ;5.1445
P55=-83.0000 ;5.1530
P56=-82.7500 ;5.2165
P57=-82.5000 ;5.2800
P58=-82.2655 ;5.3900
P59=-82.0310 ;5.5000
P60=-82.0000 ;5.5050
P61=-81.7500 ;5.5750
P62=-81.5000 ;5.6450
P63=-81.2500 ;5.7725
P64=-81.0000 ;5.9000
P65=-80.8330 ;6.0000
P66=-80.6665 ;6.0390
P67=-80.5000 ;6.0780
P68=-80.2500 ;6.1925
P69=-80.0000 ;6.3070
P70=-79.8350 ;6.4035
P71=-79.6700 ;6.5000
P72=-79.5000 ;6.5990
P73=-79.2500 ;6.7230
P74=-79.0000 ;6.8470
P75=-78.8655 ;6.9235
P76=-78.7310 ;7.0000
P77=-78.6155 ;7.1965
P78=-78.5000 ;7.3930
P79=-78.3680 ;7.5000
P80=-78.5000 ;7.5510

[C22]

gain=-8.00

n_point=97

P1=-83.3865 ;31.1113
P2=-83.5803 ;30.9879
P3=-83.7742 ;30.8645
P4=-83.9398 ;30.7356
P5=-84.1054 ;30.6067
P6=-84.2591 ;30.4680
P7=-84.4129 ;30.3292
P8=-84.6346 ;30.0960
P9=-84.7952 ;29.8964
P10=-84.9557 ;29.6969
P11=-85.0920 ;29.4765

P12=-85.2282 ;29.2562
P13=-85.3333 ;29.0501
P14=-85.3802 ;28.9481
P15=-85.4587 ;28.7458
P16=-85.5372 ;28.5434
P17=-85.5908 ;28.2899
P18=-85.6444 ;28.0363
P19=-85.6516 ;27.9857
P20=-85.6561 ;27.9333
P21=-85.6584 ;27.7131
P22=-85.6608 ;27.4929
P23=-85.6631 ;27.2727
P24=-85.6217 ;26.9701
P25=-85.6108 ;26.9060
P26=-85.5860 ;26.7926
P27=-85.4718 ;26.4916
P28=-85.3576 ;26.1906
P29=-85.2373 ;25.9995
P30=-85.1171 ;25.8085
P31=-84.9045 ;25.5659
P32=-84.6719 ;25.3364
P33=-84.4840 ;25.2026
P34=-84.2961 ;25.0687
P35=-83.9870 ;24.9269
P36=-83.6779 ;24.7851
P37=-83.5608 ;24.7545
P38=-83.4883 ;24.7355
P39=-83.2187 ;24.7068
P40=-82.9490 ;24.6780
P41=-82.6794 ;24.6493
P42=-82.4098 ;24.6206
P43=-82.0910 ;24.6746
P44=-81.7722 ;24.7287
P45=-81.4534 ;24.7828
P46=-81.2197 ;24.8593
P47=-80.9326 ;24.9823
P48=-80.6456 ;25.1053
P49=-80.3907 ;25.2437
P50=-80.1819 ;25.3840
P51=-79.9730 ;25.5244
P52=-79.9103 ;25.5699
P53=-79.6731 ;25.7756
P54=-79.4359 ;25.9812
P55=-79.3304 ;26.0835
P56=-79.1196 ;26.3329
P57=-78.9089 ;26.5824
P58=-78.8046 ;26.7233
P59=-78.6993 ;26.8949
P60=-78.5941 ;27.0665
P61=-78.4894 ;27.2748
P62=-78.3848 ;27.4831
P63=-78.3316 ;27.6150
P64=-78.2588 ;27.8145
P65=-78.1789 ;28.1053
P66=-78.0990 ;28.3961
P67=-78.0601 ;28.6639
P68=-78.0389 ;28.9137

P69=-78.0552 ;29.1504
P70=-78.0715 ;29.3871
P71=-78.0878 ;29.6238
P72=-78.1127 ;29.7338
P73=-78.1259 ;29.7855
P74=-78.1637 ;29.9087
P75=-78.2908 ;30.2088
P76=-78.4178 ;30.5090
P77=-78.5302 ;30.6718
P78=-78.6426 ;30.8347
P79=-78.7724 ;30.9659
P80=-78.9023 ;31.0972
P81=-79.1502 ;31.2942
P82=-79.3732 ;31.4164
P83=-79.5961 ;31.5387
P84=-79.9418 ;31.6627
P85=-80.2970 ;31.7505
P86=-80.5680 ;31.7840
P87=-80.8862 ;31.7886
P88=-81.2044 ;31.7931
P89=-81.5171 ;31.7646
P90=-81.7802 ;31.7139
P91=-82.0433 ;31.6632
P92=-82.1915 ;31.6210
P93=-82.4897 ;31.5143
P94=-82.7879 ;31.4077
P95=-83.0355 ;31.2983
P96=-83.2110 ;31.2048
P97=-83.3865 ;31.1113

[C23]

gain=-15.00

n_point=111

P1=-83.2248 ;32.1786
P2=-83.4486 ;32.0758
P3=-83.6725 ;31.9730
P4=-83.9547 ;31.8004
P5=-84.1748 ;31.6591
P6=-84.3950 ;31.5178
P7=-84.6107 ;31.3501
P8=-84.8264 ;31.1825
P9=-85.0436 ;30.9904
P10=-85.2993 ;30.7416
P11=-85.4566 ;30.5631
P12=-85.6139 ;30.3845
P13=-85.7948 ;30.1480
P14=-85.9452 ;29.9195
P15=-86.0957 ;29.6910
P16=-86.1995 ;29.4803
P17=-86.3769 ;29.0934
P18=-86.4564 ;28.8789
P19=-86.5442 ;28.5122
P20=-86.6320 ;28.1454
P21=-86.6515 ;28.0252
P22=-86.6622 ;27.9117
P23=-86.6656 ;27.5152
P24=-86.6690 ;27.1188
P25=-86.6505 ;26.9456

P26=-86.6151 ;26.6864
P27=-86.5662 ;26.4648
P28=-86.5173 ;26.2432
P29=-86.3697 ;25.8560
P30=-86.1998 ;25.5038
P31=-86.0351 ;25.2398
P32=-85.8705 ;24.9758
P33=-85.7712 ;24.8574
P34=-85.6828 ;24.7530
P35=-85.4545 ;24.5306
P36=-85.2261 ;24.3081
P37=-85.0096 ;24.1506
P38=-84.7930 ;23.9930
P39=-84.5706 ;23.8524
P40=-84.1983 ;23.7293
P41=-83.8260 ;23.6062
P42=-83.6986 ;23.5764
P43=-83.6405 ;23.5694
P44=-83.2702 ;23.5640
P45=-82.8998 ;23.5587
P46=-82.5295 ;23.5533
P47=-82.2154 ;23.6152
P48=-81.9013 ;23.6771
P49=-81.5872 ;23.7390
P50=-81.3327 ;23.8146
P51=-81.0424 ;23.9210
P52=-80.7520 ;24.0273
P53=-80.6469 ;24.0749
P54=-80.3796 ;24.2134
P55=-80.1124 ;24.3520
P56=-80.0030 ;24.4122
P57=-79.8492 ;24.4985
P58=-79.5866 ;24.6850
P59=-79.3241 ;24.8714
P60=-79.0779 ;25.0821
P61=-78.8318 ;25.2927
P62=-78.7104 ;25.4080
P63=-78.6190 ;25.5001
P64=-78.4193 ;25.7272
P65=-78.2196 ;25.9543
P66=-78.1659 ;26.0204
P67=-77.9910 ;26.2696
P68=-77.8161 ;26.5188
P69=-77.6931 ;26.7195
P70=-77.5293 ;27.0432
P71=-77.3654 ;27.3668
P72=-77.3054 ;27.5192
P73=-77.2747 ;27.5995
P74=-77.1951 ;27.8845
P75=-77.1155 ;28.1694
P76=-77.0359 ;28.4543
P77=-77.0136 ;28.5968
P78=-76.9973 ;28.7331
P79=-76.9881 ;29.0314
P80=-76.9790 ;29.3298
P81=-76.9699 ;29.6281
P82=-76.9723 ;29.6785

P83=-76.9822 ;29.7562
P84=-77.0560 ;30.1239
P85=-77.1297 ;30.4916
P86=-77.2153 ;30.7389
P87=-77.3261 ;30.9693
P88=-77.4368 ;31.1998
P89=-77.6427 ;31.4786
P90=-77.8486 ;31.7574
P91=-77.8921 ;31.8068
P92=-77.9350 ;31.8554
P93=-78.2199 ;32.0805
P94=-78.5049 ;32.3055
P95=-78.7225 ;32.4184
P96=-78.9402 ;32.5312
P97=-79.3265 ;32.6620
P98=-79.5679 ;32.7155
P99=-79.8094 ;32.7691
P100=-80.1253 ;32.8047
P101=-80.4330 ;32.8199
P102=-80.7088 ;32.8084
P103=-80.9847 ;32.7970
P104=-81.3672 ;32.7466
P105=-81.6714 ;32.6845
P106=-81.9756 ;32.6224
P107=-82.0620 ;32.6011
P108=-82.3533 ;32.5144
P109=-82.6446 ;32.4278
P110=-82.8603 ;32.3363
P111=-83.2248 ;32.1786