S2422

SAT-STA-20120720-00119

Date & Time Filed: Jul 20 2012 4:50:07:576PM

File Number: SAT-STA-20120720-00119

IB2012001728

Intelsat License LLC Galaxy 12

Callsign:

File # SAT-STA-20120720-00119 **GRANTED*** International Bureau *with conditions

Call Sign <u>52422</u> Grant Date <u>08/02/12</u>

(or other identifier)

period of Term Dates 60 days

Approved by OMB 3060-0678

From 07/27/12

Approved:

Chief, Satellite Policy Branch

FEDERAL COMMUNICATIONS COMMISSION APPLICATION FOR SPACE STATION SPECIAL TEMPORARY AUTHORITY

FOR OFFICIAL USE ONLY

APPLICANT INFORMATION

Enter a description of this application to identify it on the main menu:

Request for Further Extension of Special Temporary Authority to Operate Galaxy 12, Call Sign S2422

1. Applicant

Name:

Intelsat License LLC

Phone Number:

202-944-7848

DBA Name:

Fax Number:

202-944-7870

Street:

c/o Intelsat Corporation

E-Mail:

susan.crandall@intelsat.com

-3006

3400 International Drive, N.W.

City:

Washington

State:

DC

Country:

USA

Zipcode:

20008

Attention:

Susan H Crandall


Intelsat License LLC IBFS File No. SAT-STA-20120720-00119 Call Sign S2422

The application of Intelsat License LLC (Intelsat) for special temporary authority, IBFS File No. SAT-STA-20120720-00119, is granted. Accordingly, Intelsat is authorized for a period of 60 days, commencing July 27, 2012, to continue Telemetry, Tracking, and Command (TT&C) operations with the Galaxy 12 space station (Call Sign S2422) to maintain Galaxy 12 at the 129.0° W.L. orbital location using the following center frequencies: 4198 MHz (space-to-Earth), 4199.875 MHz (space-to-Earth), and 6424.5 MHz (Earth-to-space). Additionally, Intelsat is granted authority to continue to provide Fixed-Satellite Service while located at the 129.0° W.L. orbital location on a temporary basis using the 3700-4200 MHz (space-to-Earth) and 5925-6425 MHz (Earth-to-space) frequency bands. Operations under this authorization must be in accordance with the terms and conditions contained in Intelsat's application and the Federal Communications Commission's rules not waived herein, and are subject to the following conditions:

- 1. All operations of Galaxy 12 at the 129.0° W.L. orbital location shall be on an unprotected and non-harmful interference basis, *i.e.*, Intelsat shall not cause harmful interference to, and shall not claim protection from interference caused to it by, any other lawfully operating station.
- 2. In the event of any harmful interference during Galaxy 12 's operation at the 129.0° W.L. orbital location, Intelsat shall cease operations immediately upon notification of such interference, and shall inform the Commission, in writing, immediately of such an event.
- 3. Intelsat shall operate Galaxy 12 at the 129.0° W.L. orbital location in accordance with any existing coordination agreements for this location.
- 4. While at the 129.0° W.L orbital location, Intelsat shall maintain the Galaxy 12 space station with an east/west longitudinal station-keeping tolerance of +/- 0.05 degrees.
- 5. Intelsat shall comply with the power levels specified in Section 25.212 of the Commission's rules, unless it coordinates any operations using power levels exceeding the levels in Section 25.212 with all potentially affected adjacent satellites within 6 degrees orbital separation off the 129.0° W. L. orbital location. Intelsat shall inform the Commission of the power levels it has coordinated. In addition, Intelsat must inform all affected earth station operators that Section 25.220 of the Commission's rules applies to operations that exceed the power levels specified in Section 25.212. In no event shall the uplink input power spectral density level of Galaxy 12's digital carriers exceed -38.7 dBW/Hz into the antenna and the downlink EIRP density of such carriers exceed -30.6 dBW/Hz.
- 6. Any action taken or expense incurred as a result of operations pursuant to this special temporary authority is solely at Intelsat's own risk.
- 7. Grant of this authorization is without prejudice to any determination that the Commission may make regarding Intelsat's pending application to modify the authorization of the Galaxy 12 space station in order to re-locate it to the 129.0° W.L. orbital location (IBFS File No. File No. SAT-MOD-20111011-00197).
- 8. Grant of this authorization does not constitute "specific authority" pursuant to 25.161(c) of the Commission's rules.

Intelsat License LLC IBFS File No. SAT-STA-20120720-00119 Call Sign S2422

- 9. This grant of special temporary authority is without prejudice (1) to any decision with respect to any replacement expectancy at the 129.0° W.L. orbital location, or (2) any action on the Petition for Specific Authority Under Section 25.161(c) filed by Intelsat North America LLC on June 28, 2010, to retain authority to use C- and Ku-band frequencies at the 129.0° E.L. orbital location (SAT-MSC-20100628-00160).
- 10. This action is issued pursuant to Section 0.261 of the Commission's rules on delegated authority, 47 C.F.R. § 0.261, and is effective immediately.



2. Contact	-								
	Name:	Susan H. Crandall	Phone Nu	ımber:	202-94	202-944-7848			
	Company:	Intelsat Corporation	Fax Num	ber:	202-94	202-944-7870 susan.crandall@intelsat.com			
	Street:	3400 International Drive, N.W.	E-Mail:		susan.cr				
	City:	Washington	State:		DC				
	Country:	USA	Zipcode:		20008	-3006			
	Attention:	Susan H. Crandall	Relations	hip:	Legal C				
(If your application is related to an application filed with the Commission, enter either the file number or the IB Submission ID of the related application. Please enter only one.) 3. Reference File Number SATMOD2011101100197 or Submission ID									
If Yes.	, complete and	with this application? I attach FCC Form 159. If No, ind y Noncommercial educational		for fee exempti	on (see 47 C.F.R.Se	ction 1.1114).			
O Other	(please explair	1):							
4b. Fee Cl	assification	CRY - Space Station (Geostationary	у)						
5. Type Re	equest								
O Chang	ge Station Loc	eation	Date	O Othe	r				
6. Temporary Orbit Location				7. Requested Extended Expiration Date 2012–07–26 00:00:00.0					

8. Description (If the complete description	n does not appear in this bo	ox, please go to the end of	the form to view it in its entirety.)						
Intelsat License LLC herein requests a 60-day extension, through September 22, 2012, of the Special Temporary Authority previously granted Intelsat to drift Galaxy 12 (call sign S2422) from 132.9 W.L. to 129.0 W.L. and begin operating at 129.0 W.L. Intelsat has a pending application for permanent authority to operate Galaxy 12 at 129.0 W.L. in the C-									
9. By checking Yes, the undersigned certifito a denial of Federal benefits that includes 21 U.S.C. Section 862, because of a convict 1.2002(b) for the meaning of "party to	FCC benefits pursuant to strion for possession or distr	Section 5301 of the Anti–I ibution of a controlled sub	Drug Act of 1988,	O No					
10. Name of Person Signing Susan H. Crandall		11. Title of Person Signing Asst. General Counsel, Intelsat Corporation							
12. Please supply any need attachments.									
Attachment 1: STA Request	Attachment 2:		Attachment 3:						
(U.S. Code, Title 18, S	Section 1001), AND/OR RI	EVOCATION OF ANY ST	Y FINE AND / OR IMPRISONMENTATION AUTHORIZATION Code, Title 47, Section 503).	NT					

FCC NOTICE REQUIRED BY THE PAPERWORK REDUCTION ACT

The public reporting for this collection of information is estimated to average 2 hours per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the required data, and completing and reviewing the collection of information. If you have any comments on this burden estimate, or how we can improve the collection and reduce the burden it causes you, please write to the Federal Communications Commission, AMD-PERM, Paperwork Reduction Project (3060–0678), Washington, DC 20554. We will also accept your comments regarding the Paperwork Reduction Act aspects of this collection via the Internet if you send them to PRA@fcc.gov. PLEASE DO NOT SEND COMPLETED FORMS TO THIS ADDRESS.

Remember – You are not required to respond to a collection of information sponsored by the Federal government, and the government may not conduct or sponsor this collection, unless it displays a currently valid OMB control number or if we fail to provide you with this notice. This collection has been assigned an OMB control number of 3060–0678.

THE FOREGOING NOTICE IS REQUIRED BY THE PAPERWORK REDUCTION ACT OF 1995, PUBLIC LAW 104–13, OCTOBER 1, 1995, 44 U.S.C. SECTION 3507.

8. Description

Intelsat License LLC herein requests a 60-day extension, through September 22, 2012, of the Special Temporary Authority previously granted Intelsat to drift Galaxy 12 (call sign S2422) from 132.9 W.L. to 129.0 W.L. and begin operating at 129.0 W.L. Intelsat has a pending application for permanent authority to operate Galaxy 12 at 129.0 W.L. in the C-band.



Ms. Marlene H. Dortch Secretary Federal Communications Commission 445 12th Street, S.W. Washington, DC 20554

Re: Request for Further Extension of Special Temporary Authority to

Operate Galaxy 12 Call Sign S2422

Dear Ms. Dortch:

Intelsat License LLC ("Intelsat") herein requests a 60-day further extension -through September 24, 2012 -- of the Special Temporary Authority ("STA")¹
previously granted Intelsat to drift Galaxy 12 (call sign S2422) from 132.9°
W.L. to 129.0° W.L. and begin operating at 129.0° W.L.² Intelsat has a
pending application for permanent authority to operate Galaxy 12 at 129.0°
W.L. in the C-band.³

Galaxy 12 is currently operating at 129.0° W.L. utilizing the following frequencies.

The specific TT&C frequencies are as follows:

Uplink:

6424.5 MHz (RHCP), (H)

¹ Intelsat has filed this STA request, an FCC Form 159 and an \$860.00 filing fee electronically via the International Bureau's Filing System.

² See Policy Branch Information; Actions Taken, Report No. SAT-00873, File No. SAT-STA-20120521-00086 (June 8, 2012) (Public Notice); Policy Branch Information Actions Taken; Report No. SAT-00861, File No. SAT-STA-20120323-00060 (Apr. 20, 2012) (Public Notice); Policy Branch Information; Actions Taken, Report No. SAT-00844, File No. SAT-STA-20120124-00009 (Feb. 10, 2012) (Public Notice); Policy Branch Information; Actions Taken, Report No. SAT-00838, File No. SAT-STA-20111227-00252 (Jan. 20, 2012) (Public Notice); Policy Branch Information; Actions Taken, Report No. SAT-00826, File No. SAT-STA-20111118-00223 (Dec. 2, 2011) (Public Notice).

³ See Policy Branch Information; Policy Branch Information; Satellite Space Applications Accepted for Filing, Report No. SAT-00824, File No. SAT-MOD-20111011-00197 (Nov. 18, 2011) (Public Notice).

Ms. Marlene H. Dortch July 20, 2012 Page 2

Downlink:

4198 MHz (LHCP), (V) 4199.875 MHZ (LHCP), (V)

The specific communications frequencies are as follows:

3700-4200 MHz (space-to-Earth) 5925-6425 MHz (Earth-to-space)

Intelsat requests that the waiver of Section 25.283(c) of the Commission's rules continue to apply at the 129.0° W.L. orbital location.⁴

Grant of this STA further extension request is in the public interest because it will allow Intelsat to continue operating Galaxy 12 at 129.0° W.L. while the Commission completes its consideration of the pending application for permanent authority. Intelsat understands and accepts that a grant of this STA further extension would not prejudge the Commission's determination of Intelsat's request to operate Galaxy 12 at 129.0° W.L. on a permanent basis, and that operation pursuant to this STA is at Intelsat's risk.

Grant of this STA further extension request will not result in increased risk of harmful interference. Intelsat will continue to operate Galaxy 12 in conformance with its coordination agreements related to the 129.0° W.L. location.

Intelsat has assessed and limited the probability of the space station becoming a source of debris as a result of collision with large debris or other operational space stations. Galaxy 12 is not located at the same orbital location as another satellite or at an orbital location that has an overlapping station-keeping volume with another satellite. Further, Intelsat is not aware of any other FCC licensed system, or any other system applied for and under consideration by the FCC, having an overlapping station-keeping volume with Galaxy 12 at 129.0° W.L. Finally, Intelsat is not aware of any system with an overlapping station-keeping volume with Galaxy 12 at 129.0° W.L. that is the subject of an ITU filing and that is either in orbit or progressing towards launch.

⁴ 47 C.F.R. § 25.283(c). *See Policy Branch Information; Actions Taken*, Report No. SAT-00730, File Nos. SAT-MOD-20100120-00013 and SAT-AMD-20100514-00102 (Oct. 22, 2010) (Public Notice).

Ms. Marlene H. Dortch July 20, 2012 Page 3

For the reasons set forth herein, Intelsat respectfully requests that the Commission expeditiously grant this extension request.

Sincerely,

Susan H. Crandall

Assistant General Counsel

Intelsat Corporation

cc: Stephen Duall Jay Whaley