

MessageFrom: a larson [alarson@larsonusa.com]
Sent: Thursday, June 03, 2004 12:17 PM
To: Towanda Bryant
Subject: RE: VERESTAR, INC. SES-LIC-20040528-00741, E040249

Hello Ms. Bryant,

Thanks for the opportunity to fix the errors on VERESTAR, INC. SES-LIC-20040528-00741, E040249.

Please correct the following:

Site No. 1, Site ID: 1

14000 - 14500 MHz.
 East Elevation Angle to 17.0
 West Elevation Angle to: 31.3
11700 - 12200 MHz.
 East Elevation Angle to 17.0
 West Elevation Angle to 31.3

Site ID:1 AntennaID:1

14000 - 14500 MHz.
 Emission Designator: 400KF1D
 Max. Power Density towards horizon: -14.3 dBW - (calculated @ 17 degrees elevation)

11700 - 12200 MHz.
 Emission Designator: 400KF1D

Please let me know if you need anything else.

Thanks,

Arthur Larson
VP Engineering
Larson Associates USA, Inc.
(972) 612-1373
alarson@larsonusa.com

-----Original Message-----

From: Towanda Bryant [mailto:Towanda.Bryant@fcc.gov]
Sent: Thursday, June 03, 2004 10:20 AM
To: alarson@larsonusa.com
Subject: RE: VERESTAR, INC. SES-LIC-20040528-00741, E040249

TNX. t.

-----Original Message-----

From: a larson [mailto:alarson@larsonusa.com]
Sent: Thursday, June 03, 2004 11:17 AM
To: Towanda Bryant

Subject: RE: VERESTAR, INC. SES-LIC-20040528-00741, E040249

Hi Ms Bryant,

I received the fax and will fix the errors today.

Thanks!

Arthur

-----Original Message-----

From: Towanda Bryant [mailto:Towanda.Bryant@fcc.gov]

Sent: Wednesday, June 02, 2004 2:04 PM

To: alarson@larsonusa.com

Subject: VERESTAR, INC. SES-LIC-20040528-00741, E040249

Good Afternoon, I have found some errors on your application, I have faxed you an autogrant check sheet, please look over and email me the changes.

Tnx. T.