

Towanda Bryant

From: Hunter, Daryl [daryl.hunter@viasat.com]
Sent: Tuesday, November 13, 2012 3:33 PM
To: Towanda Bryant
Subject: RE: SES-MOD-20121107-00993, E050033
Attachments: PGP.sig

The defective emission designators should be: 400KG7W, not 400G7W, and 52M1G7W, not 52MG7D

Thanks and regards,

Daryl

Daryl T. Hunter, P.E.
Director, Regulatory Affairs
ViaSat, Inc.
6155 El Camino Real
Carlsbad, CA 92009
Email: daryl.hunter@viasat.com
Phone: 760-476-2583
Fax: 760-929-3934
ViaSat Brings Your Network to Life
PGP User

From: Towanda Bryant [<mailto:Towanda.Bryant@fcc.gov>]
Sent: Tuesday, November 13, 2012 12:12 PM
To: Hunter, Daryl
Subject: SES-MOD-20121107-00993, E050033

Please check the emissions 400G7W and 52MG7D on new antenna, coming up unknown.

Tnx. T.