



beyond frontiers

June 2, 2020

By Electronic Filing

Ms. Marlene H. Dortch
Secretary
Federal Communications Commission
445 12th Street, S.W.
Washington, DC 20554

Re: SES Americom, Inc., Modification of FCC license File No. SES-MOD-20200305-00221 (Call Sign# E890531)

Dear Ms. Dortch,

SES Americom, Inc., pursuant to Section 1.65 of the Commission's rules, 47 C.F.R. § 1.65, hereby updates the record with respect to the above-referred request for the operating authority/blanket license for VSATs.

As per the new requirements/forms when the license modification is filed, the information-E38 (Total input power at the antenna flange) and E40 (Total EIRP of all carriers) pertaining to the terminals that are part of the original license are to be provided. So, the information for the antenna Ids 1 to 5 as specified in the original license is provided in the table below:

Table with 4 columns: Site ID, E28 Antenna ID, E38 Total Input Power at the antenna flange (Watts), E40 Total EIRP for all carriers (dBW). Rows show data for Site ID 1 with Antenna IDs 1 through 5.

The missing information pertaining to the terminals that are to be added to the license for which the modification is filed is given in the table below:

Table with 7 columns: E28 (Ant. Id), E43/44 (Freq. Bands) MHz, E45 T/R mode, E46 Ant. Pol (H/V), E47 Emission desig., E48 Max. EIRP /Carrier (dBW), E49 Max. EIRP densi. /carrier (dBW/4kHz). Rows show data for various antenna IDs and frequencies.



beyond frontiers

7	14000-14500	T	H/V	4M02G7W	64.9	34.9
7	14000-14500	T	H/V	8M04G7W	64.9	31.9
7	14000-14500	T	H/V	12M7G7W	64.9	29.9
7	11700-12200	R	H/V	100KG7W	-	-
7	11700-12200	R	H/V	36M0G7W	-	-

Please address any questions regarding this matter to the undersigned.

Yours Sincerely,

/s/ George Varkey

George Varkey
Senior Engineer, Ground Systems
SES Americom, Inc.

Email:George.varkey@ses.com

Tel:+1 609 987 4327