

CALL SIGN E000635
EXHIBIT A
RENEWAL APPLICATION

In assessing the license information for the earth station authorized under call sign E000635, GCI identified a discrepancy in the positioning coordinates reflected at the time of initial licensing and the coordinates measured using geopositioning tools available 10 years later. The difference modestly exceeds the one second measure allowable under a minor modification (2.40 seconds), and thus, a major modification is required. GCI is in the process of securing the required frequency coordination to file the major modification, but in the meantime is filing the instant renewal so as not to allow the license to expire.

GCI will file the application for major modification to correct the location immediately upon completion of the frequency coordination process. Moreover, given the remote location of the earth station and its continued operation in the current location since initial licensing, no harmful interference is anticipated.