

From: [Baum, Kimberly](#)
To: [Manner, Jennifer](#); [Jae Lim](#)
Subject: RE: SES-RWL-20191121-01536; Call Sign: E940460
Date: Tuesday, December 10, 2019 1:58:39 PM

Hi Jae,

If possible, we would like to replace the point of contacts with the replacement satellites at those slots, as follows:

AMC-9 (S2434)@85W → replace with AMC-2 and AMC-16

Galaxy XI@91W → replace with Galaxy 17

Intelsat Americas 5 @97W → replace with Galaxy 19

[SATMEX-5@116.8W](#) → replace with Eutelsat 117WA

Best,
Kim

From: Manner, Jennifer
Sent: Thursday, December 5, 2019 11:59 AM
To: Jae Lim <Jae.Lim@fcc.gov>
Cc: Baum, Kimberly <Kimberly.Baum@echostar.com>
Subject: RE: SES-RWL-20191121-01536; Call Sign: E940460

Thank you for your note. Kim Baum will get back to you shortly.

With our thanks,
JAM

From: Jae Lim <Jae.Lim@fcc.gov>
Sent: Thursday, December 5, 2019 9:20 AM
To: Manner, Jennifer <Jennifer.Manner@echostar.com>
Subject: SES-RWL-20191121-01536; Call Sign: E940460

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hi Jennifer Manner,

The following satellites (PntComm) are either no longer there or replaced.
Please verify your PntComm's.

AMC-9 (S2434)@85W
Galaxy XI@91W
Intelsat Americas 5 @97W

SATMEX-5@116.8W

Thanks.

Jae Lim
FCC/IB
1-202-418-2899