
Approved by OMB 3060-0678

## APPLICATION FOR EARTH STATION SPECIAL TEMPORARY AUTHORITY

APPLICANT INFORMATIONEnter a description of this application to identify it on the main menu: STA for E000284 to communicate with the Inmarsat 4F2 satellite

1

Name:	Telenor Satellite, Inc.	Phone Number:	301-838-7860
DBA Name:		Fax Number:	301-838-7752
Street:	1101 Wootton Parkway	E-Mail:	keith.fagan@telenor-usa.com
	10th Floor		
City:	Rockville	State:	MD
<b>Country:</b>	USA	Zipcode:	20852 -1064
Attention:	Mr Keith H Fagan		



### **Telenor Satellite Inc.**

# IBFS File Nos. SES-STA-20051216-01756, SES-STA-20051216-01757, SES-STA-20051216-01758, SES-STA-20051216-01759; SES-STA-20060118-00055; SES-STA-20060118-00056; SES-STA-20060118-00057; SES-STA-20060118-00058; SES-STA-20060119-00064

The request of Telenor Satellite, Inc. (Telenor) for special temporary authority (STA) IS GRANTED. Accordingly, Telenor is authorized from January 19, 2006 to March 19, 2006 to continue operations on the Inmarsat 4F2 satellite using hub earth stations and mobile earth terminals (METs) previously authorized under call signs KA312, WB36, WA28, KA313, E000280, E000282, E000283, E000284, and E000285 to communicate with the Inmarsat 3F4 satellite in accordance with the terms, conditions, and technical specifications set forth in the Commission's rules and this document.

- 1. Neither the aggregate uplink EIRP densities in the direction of any other L-band satellite serving the United States, nor the downlink EIRP densities at any geographical point within the United States, shall be increased as a result of continuance on the Inmarsat 4F2 satellite of operations previously authorized on the Inmarsat 3F4 satellite.
- 2. Operations on the Inmarsat 4F2 satellite shall be on an unprotected basis. Telenor shall not claim protection from, and is required to accept interference from, other lawfully operating satellites or radiocommunication systems.
- 3. No later than February 17, 2006 a report must be submitted addressing whether, given the increased capacity of the Inmarsat 4F2 satellite relative to the Inmarsat 3F4 satellite, there would be any discontinuance of, or degradation of the reliability of, existing operations should access to the "loaned" spectrum be terminated. In the event that the report asserts that such discontinuation or degradation may occur, the report must include a detailed, quantitative explanation of the basis of this assertion. Any such explanation must also include a list of the end-users, including any U.S. government end-users, using METs that may operate in the "loaned" spectrum under this STA, a point of contact (name and telephone number) for each such end-user, and the number of METs associated with each such end-user. Any such explanation, to the extent that it claims that termination of operations on the "loaned" spectrum would degrade service on other frequencies, must include a list of the potentially affected end-users, including any U.S. government end-users, using METs operating under this STA, a point of contact (name and telephone number) for each such enduser, and the number of METs associated with each such end-user. Should the U.S. government users not authorize disclosure of frequencies or services used on the "loaned" spectrum, the report must include a point of contact (name and telephone number) for the associated end-user who can verify the government's use. For purposes of this condition, "loaned" spectrum is defined as those bandwidth segments that were loaned to Inmarsat by MSV and MSV Canada, either as part of the Revised 1999 Spectrum Sharing Arrangement (October 4, 1999), or later as bilateral arrangements between Inmarsat and MSV and Inmarsat and MSV Canada.
- 4. Any action taken or expense incurred as a result of operations pursuant to this special temporary authority is solely at Telenor's own risk.
- 5. The grant of this STA is not based on a finding that Inmarsat's L-band operations are consistent with operation on a non-interference basis.
- 6. The grant of this STA is without prejudice to any future determination that the Commission may make as to whether Inmarsat's L-band operations are consistent with operation on a non-interference basis.
- 7. This STA may be terminated or modified at the International Bureau's discretion, without a hearing, if conditions warrant.

### **Telenor Satellite Inc.**

# IBFS File Nos. SES-STA-20051216-01756, SES-STA-20051216-01757, SES-STA-20051216-01758, SES-STA-20051216-01759; SES-STA-20060118-00055; SES-STA-20060118-00056; SES-STA-20060118-00057; SES-STA-20060118-00058; SES-STA-20060119-00064

- 8. Telenor must notify its customers in writing no later than February 17, 2006 that operations on the Inmarsat 4F2 satellite are pursuant to a 60-day grant of special temporary authority that may be terminated or modified at any time.
- Authority granted in this STA is without prejudice to the disposition of the underlying modification applications in IBFS File Nos. SES-MFS-20051202-01665, SES-MFS-20051122-01614, SES-MFS-20051122-01615, SES-MFS-20051122-01616, SES-MFS-20051122-01617, SES-MFS-20051122-01618, SES-MFS-20051123-01626, SES-MFS-20051123-01627, SES-MFS-20051123-01629, SES-MFS-20051123-01630, SES-MFS-20051207-01709, SES-MFS-20060118-00050, SES-MFS-20060118-00051, SES-MFS-20060118-00052, and SES-MFS-20060118-00053.
- 10. Authority granted in this STA is without prejudice to possible enforcement action in connection with any prior unauthorized operation of Inmarsat-C terminals.
- 11. This grant is issued pursuant to Section 0.261 of the Commission's rules on delegated authority, 47 C.F.R. § 0.261, and is effective immediately.
- 12. Telenor is afforded thirty days from the date of release of this action to decline this special temporary authorization as conditioned. Failure to respond within this period will constitute formal acceptance of the special temporary authorization as conditioned.

. 1

2. Contact				
Name:	Telenor Satellite, Inc.	Phone Number:	301-838-7860	
Company:		Fax Number:	301-838-7752	
Street:	1101 Wootton Parkway	E-Mail:	keith.fagan@telenor-usa.com	
	10th Floor			
City:	Rockville	State:	MD	
Country:	USA	Zipcode:	20852 -1064	
Attention:	Mr Keith H Fagan	<b>Relationship:</b>		
<ul> <li>If Yes, complete and</li> <li>Governmental Entit</li> <li>Other(please explain</li> </ul>	y O Noncommercial educati		on (see 47 C.F.R.Section 1.1114).	
4b. Fee Classification	CGB – Mobile Satellite Earth S	tations		
5. Type Request				
Use Prior to Grant O Change Station Location O Other				
6. Requested Use Prior I 01/20/2006	Date			
7. CityVarious		8. Latitude (dd mm ss.s h)	0 0 0.0	

9. State	10. Longitude (dd mm ss.s h) 0 0 0.0
11. Please supply any need attachments.	
Attachment 1: Need Attachment Attachment 2	2: Attachment 3:
12. Description. (If the complete description does not appea	r in this box, please go to the end of the form to view it in its entirety.)
	ority to allow up to 1000 Inmarsat C half-duplex s the Inmarsat 4F2 satellite at 52.75 degrees W.L. ermanent authorization shortly.
13. By checking Yes, the undersigned certifies that neither appropriate subject to a denial of Federal benefits that includes FCC bene of 1988, 21 U.S.C. Section 862, because of a conviction for p See 47 CFR 1.2002(b) for the meaning of "party to the	fits pursuant to Section 5301 of the Anti-Drug Act possession or distribution of a controlled substance.
14. Name of Person Signing Keith H. Fagan	15. Title of Person Signing Senior Counsel
(U.S. Code, Title 18, Section 1001), AND	IS FORM ARE PUNISHABLE BY FINE AND / OR IMPRISONMENT D/OR REVOCATION OF ANY STATION AUTHORIZATION , AND/OR FORFEITURE (U.S. Code, Title 47, Section 503).

### FCC NOTICE REQUIRED BY THE PAPERWORK REDUCTION ACT

The public reporting for this collection of information is estimated to average 2 hours per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the required data, and completing and reviewing the collection of information. If you have any comments on this burden estimate, or how we can improve the collection and reduce the burden it causes you, please write to the Federal Communications Commission, AMD-PERM, Paperwork Reduction Project (3060-0678), Washington, DC 20554. We will also accept your comments regarding the Paperwork Reduction Act aspects of this collection via the Internet if you send them to jboley@fcc.gov. PLEASE DO NOT SEND COMPLETED FORMS TO THIS ADDRESS.

Remember – You are not required to respond to a collection of information sponsored by the Federal government, and the government may not conduct or sponsor this collection, unless it displays a currently valid OMB control number or if we fail to provide you with this notice. This collection has been assigned an OMB control number of 3060–0678.

THE FOREGOING NOTICE IS REQUIRED BY THE PAPERWORK REDUCTION ACT OF 1995, PUBLIC LAW 104–13, OCTOBER 1, 1995, 44 U.S.C. SECTION 3507.

#### TELENOR SATELLITE, INC.

#### **REQUEST FOR SPECIAL TEMPORARY AUTHORITY**

Telenor Satellite, Inc. ("Telenor") requests special temporary authority to allow the mobile earth terminals ("METs") with call signs E000280, E000282, E000283, E000284 and E000285 to communicate with the Inmarsat 4F2 satellite at 52.75° W.L. beginning on or about January 19, 2006, when Inmarsat is scheduled to migrate existing and evolved ("E&E") services from the Inmarsat 3F4 satellite currently located at 54° W.L. Each of those METs is currently licensed to operate with Inmarsat 3F4 (among other satellites), and Telenor has modification applications pending for each of those METs to allow communications with Inmarsat 4F2. However, those applications cannot be granted before the service migration date. Accordingly, an STA is needed to assure continuity of service for Telenor's many customers who now receive service on the Inmarsat 3F4.

Inmarsat has informed Telenor that it is critical to transition E&E services to the Inmarsat 4F2 as soon as possible because the Inmarsat 3F4 satellite needs to be moved to 142° W.L., where it will replace a second generation Inmarsat satellite that is running out of fuel and will be decommissioned shortly. An untimely migration of E&E services from Inmarsat 3F4 to Inmarsat 4F2 would jeopardize the continuity of the essential services currently being provided by the second generation satellite at the 142° W.L. orbital location.

The services to be transitioned from Inmarsat 3F4 to Inmarsat 4F2 include Inmarsat B, Inmarsat C, Inmarsat Mini-M and Aero Mini-M, GAN, Aero-H and H+, Aero-I, and Swift. As shown below, and as stated in the attached declaration by Bo Norton, Telenor's Director of Channel Sales, The Americas, each of those services is used by Telenor's customers to meet critical telecommunications needs via the Inmarsat satellite at the 54°/52.75° W.L. orbital location.

Inmarsat B is used by the U.S. Navy and U.S. Coast Guard, as well as commercial shipping companies, to support communications to and from ships at sea. Inmarsat B terminals are also deployed by the U.S. State Department at American embassies worldwide, and these terminals are also used by the Department of Homeland Security and the National Guard.

Inmarsat C supports GMDSS, the Global Marine Distress and Safety System. It also aids in tracking fishing fleets in U.S. territorial waters and commercial shipping approaching the U.S. coastline.

Mini-M, Aero Mini-M and GAN services are used by every branch of the U.S. military in support of training and deployment to Iraq, Afghanistan and around the world. These services are also used by the State Department, DHS and the National Guard, as well as by news organizations covering events in Iraq, Afghanistan and elsewhere.

Aero-I service is used by the Air Mobility Command, the Air Force component of the United States Transportation Command. Aero-H and H+ services, as well as Swift services, are used aboard U.S. Presidential aircraft, including Air Force One, both by government officials and by journalists covering the President. Aero-H and Swift services are also used by the 89<sup>th</sup> Air Wing to support the Administration, Congress and flag officers of the different services. In addition, these services are used to support the U.S. military's Commanders in Chief (CinCs), and other classified airborne assets.

Disruption of any of these services would be costly, and in many cases service interruption would have an adverse effect on vital national interests. Accordingly, grant of this STA will serve the public interest, convenience and necessity.

Moreover, grant of this STA will not prejudice any interested party. The services that Telenor currently provides over Inmarsat 3F4 can and will be provided over Inmarsat 4F2 without adversely affecting the interference environment that exists today with respect to other operating L-Band spacecraft. Specifically, (i) the EIRP spectral density of the proposed carriers on Inmarsat 4F2 will be no greater than the EIRP spectral density of the same services provided today over Inmarsat 3F4, (ii) the out-of-band emissions from those Inmarsat 4F2 carriers will not exceed the limits of §25.202(f) (1), (2) and (3), and (iii) no greater protection from interference into the Inmarsat 4F2 spacecraft or the Telenor mobile earth terminals, beyond the level of protection that exists today, is sought. In sum, during the term of this STA, these services can and will be provided on Inmarsat 4F2 within the technical envelope pursuant to which these services are currently provided on Inmarsat 3F4.

For all these reasons, Telenor respectfully requests the Bureau to grant this STA for a period beginning on January 19, 2006 and ending after sixty days, or whenever the Bureau takes action on Telenor's underlying applications.

Ļ