

July 13, 2016

Ms. Marlene H. Dortch Secretary Federal Communications Commission 445 12th Street, S.W. Washington, D.C. 20554

> Re: Request for Further Extension of Special Temporary Authority Hagerstown, Maryland Earth Station KA258

Dear Ms. Dortch:

Intelsat License LLC ("Intelsat") herein requests an additional 30 days, beginning July 27, 2016, of the Special Temporary Authority ("STA")¹ previously granted Intelsat to use its Hagerstown, Maryland Kuband earth station—call sign KA258—to provide launch and early orbit phase ("LEOP") services² for Intelsat 31; telemetry, tracking, and command ("TT&C") during in-orbit testing ("IOT") at 132.0° W.L; and TT&C during the drift of Intelsat 31 to its final location of 95.05° W.L.³ Intelsat 31 was launched on June 9, 2016. The LEOP period is completed; IOT and drift are expected to last approximately three and two weeks, respectively.

The Intelsat 31 operations will continue to be performed using the following frequencies: 13998.50 MHz, and 14006.0 MHz in the uplink (LHCP, H); and 11194.25 MHz, 11195.5 MHz, 11196.25 MHz, and 11196.75 MHz in the downlink (RHCP, V). The operations will be coordinated with all operators of satellites that use the same frequency bands and are in the LEOP path, the drift path, or are potentially affected by these operations at the IOT location.⁴ The TT&C operations at 95.05° W.L. will be consistent with Intelsat's coordination agreements for the nominal 95° W.L. location. All operators of potentially affected satellites will be provided with an emergency phone number where the licensee can be reached in the event that harmful interference occurs.

The 24x7 contact information for the Intelsat 31 mission is as follows:

Ph.: (703) 559-7701 – East Coast Operations Center (primary) (310) 525-5591 – West Coast Operations Center (back-up)

¹ Intelsat has filed its STA request, an FCC Form 159, a \$195.00 filing fee, and this supporting letter electronically via the International Bureau's Filing System ("IBFS").

² See Satellite Communications Services Information; Actions Taken, Report No. SES-01864, File No. SES-20160622-00567 (June 29, 2016) (Public Notice); Satellite Communications Services Information; Actions Taken, Report No. SES-015751856, File No. SES-STA-20160503-00388 (June 1, 2016) (Public Notice).

³ See Policy Branch Information; Actions Taken, Report No. SAT-01052, File No. SAT-LOA-20140410-00038 (November 7, 2014) (Public Notice). At 95.05° W.L., Intelsat 31 will be co-located with Intelsat 30 (S2887) and Galaxy 3C (S2381).

Ms. Marlene H. Dortch July 13, 2016 Page 2

Request to speak with Harry Burnham or Kevin Bell.

In further support of this further extension request, incorporates by reference Exhibit A of its initial STA request which contains technical information that demonstrates that the operation of the earth station will be compatible with its electromagnetic environment and will not cause harmful interference into any lawfully operating terrestrial facility, or into Federal systems operating in the 13.75 -14.00 GHz band. In the extremely unlikely event that harmful interference should occur due to transmissions to or from its earth station, Intelsat will take all reasonable steps to eliminate the interference.

Grant of this STA further extension request will allow Intelsat to safely complete the testing and drift of the Intelsat 31 satellite. This, in turn, will help ensure continuity of service at the 95.05° W.L. orbital location and thereby promotes the public interest.

Please direct any questions regarding this STA request to the undersigned at (703) 559-6949.

Respectfully submitted,

Cynthia J. Sudy

1

Cynthia J. Grady Regulatory Counsel Intelsat Corporation

cc: Paul Blais