

Applicant: Intelsat License LLC, as debtor-in-possession  
Call Sign: KA275  
File No.: SES-STA-20200706-00714  
Special Temporary Authority (“STA”)

Intelsat License LLC is granted STA, for 30 days, commencing July 28, 2020, to operate its fixed-satellite C-band earth station located in Hagerstown, MD to provide launch and early orbit phase (“LEOP”) services for and conduct In-Orbit Testing (“IOT”) of Galaxy 30 (Call Sign S3016) and drift the satellite to its final orbital location 125.0° W. Galaxy 30 is expected to launch on July 28, 2020. The LEOP operations will be performed at the following frequencies: 6421.75 MHz and 6424.25 MHz (Earth-to-space), and 4197.5 MHz and 4198.5 MHz (space-to-Earth) under the following conditions:

1. Operations, shall not cause harmful interference to, and shall not claim protection from, interference caused to it by any other lawfully operating station and it shall cease transmission(s) immediately upon notice of such interference.
2. In the event of any harmful interference under this grant of STA, Intelsat License LLC must cease operations immediately upon notification of such interference, and must inform the Commission, in writing, immediately of such an event.
3. The LEOP operations must be coordinated with all operators of satellites that use the same frequency bands and are in the LEOP path. All operators of satellites in that path will be provided with an emergency phone number where the licensee can be reached in the event that harmful interference occurs.
4. Currently the 24x7 contact information for the Galaxy 30 satellite LEOP mission is as follows: Ph.: (703) 559-7701 - East Coast Operations Center (primary); (310) 525-5591 - West Coast Operations Center (back-up). Request to speak with Harry Burnham or Kevin Bell.
5. Grant of this authorization is without prejudice to any determination that the Commission may make regarding pending or future Intelsat License LLC applications.
6. Any action taken or expense incurred as a result of operations pursuant to this STA is solely at Intelsat License LLC’s risk.

This action is issued pursuant to Section 0.261 of the Commission’s rules on delegated authority, 47 C.F.R. §0.261, and is effective immediately.