5. Time of Occupancy (Dwell Time)

5.1 Ant1

5.1.1 Test Result

Condition	Antenna	Packet Type	Pulse Time(ms)	Hops	Dwell Time(ms)	Limit(s)	Result
NVNT	ANT1	1-DH1	0.384	318.00	122.112	0.40	Pass
NVNT	ANT1	1-DH3	1.641	151.00	247.791	0.40	Pass
NVNT	ANT1	1-DH5	2.889	118.00	340.902	0.40	Pass

BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

5.1.2 Test Graph

Dwell_Time_(Hopping)_NVNT_ANT1_1-DH1_2441_One_Burst_Time

Dwell_Time_(Hopping)_NVNT_ANT1_1-DH1_2441_Accumulated


BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

Dwell_Time_(Hopping)_NVNT_ANT1_1-DH3_2441_One_Burst_Time

Dwell_Time_(Hopping)_NVNT_ANT1_1-DH3_2441_Accumulated


BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

Dwell_Time_(Hopping)_NVNT_ANT1_1-DH5_2441_One_Burst_Time

Dwell_Time_(Hopping)_NVNT_ANT1_1-DH5_2441_Accumulated


BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

6. Unwanted Emissions In Non-restricted Frequency Bands

6.1 Test Graph

1_Reference_Level_NVNT_ANT1_1-DH1_2402



2_Spurious_Emissions_NVNT_ANT1_1-DH1_2402



BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

1_Reference_Level_NVNT_ANT1_1-DH1_2441

2_Spurious_Emissions_NVNT_ANT1_1-DH1_2441



1_Reference_Level_NVNT_ANT1_1-DH1_2480

2_Spurious_Emissions_NVNT_ANT1_1-DH1_2480



BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

1_Reference_Level_NVNT_ANT1_2-DH1_2402

2_Spurious_Emissions_NVNT_ANT1_2-DH1_2402



BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

1_Reference_Level_NVNT_ANT1_2-DH1_2441

2_Spurious_Emissions_NVNT_ANT1_2-DH1_2441



BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

1_Reference_Level_NVNT_ANT1_2-DH1_2480

2_Spurious_Emissions_NVNT_ANT1_2-DH1_2480



BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

1_Reference_Level_NVNT_ANT1_3-DH1_2402

2_Spurious_Emissions_NVNT_ANT1_3-DH1_2402



1_Reference_Level_NVNT_ANT1_3-DH1_2441

2_Spurious_Emissions_NVNT_ANT1_3-DH1_2441



BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

1_Reference_Level_NVNT_ANT1_3-DH1_2480

2_Spurious_Emissions_NVNT_ANT1_3-DH1_2480



BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

GFSK No-hopping Band edge-left side



GFSK Hopping Band edge-left side



BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

GFSK No-hopping Band edge-right side



GFSK Hopping Band edge-right side



BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

π/4-DQPSK No-hopping Band edge-left side



π/4-DQPSK Hopping Band edge-left side



BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

π/4-DQPSK No-hopping Band edge-right side



π/4-DQPSK Hopping Band edge-right side



BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

8-DPSK No-hopping Band edge-left side



8-DPSK Hopping Band edge-left side



BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

8-DPSK No-hopping Band edge-right side



8-DPSK Hopping Band edge-right side



BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

BTF Testing Lab (Shenzhen) Co., Ltd.

F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China

www.btf-lab.com

-- END OF REPORT --

BTF Testing Lab (Shenzhen) Co., Ltd.
F101, 201 and 301, Building 1, Block 2, Tantou Industrial Park, Tantou Community, Songgang Street, Bao'an District, Shenzhen, China