

To: Richard Roberts  
E-Mail: richard.roberts@avitechtechnologies.com  
From: Hung Le  
Date: July 15, 2019

Subject: Request for Info - File # 0480-EX-CN-2019

---

Message:

Your response is inaccurate. Please correct the emission designator. Emission bandwidth or necessary bandwidth (300 MHz) must be smaller than or equal to the frequency band requested (9.6-9.65 GHz). Modulation signals should not be X letter, F2N is valid for modulation signal (pulse and data).

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of July 15, 2019 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 49504