

To: Jeff Rummel
E-Mail: rummelj@arentfox.com
From: Leann Nguyen
Date: August 26, 2021

Subject: Request for Info - File # 0173-EX-CM-2021

Message:

Please verify the following information

- The bandwidth of emission designator has exceeded the frequency bands. Please make a correction.
- Any changes/updated coordinates (latitude/longitude) is required to submit as a new antenna. All the NGs that was approved from the previous files has been messed up. Please add new antennas for new coordinates on the application.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of August 26, 2021 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 64242