

Exhibit 1

This modification application is being filed to modify the records associated with Station WE2XBT as follows:

- Modify the Stop Buzzer information at Special Condition 5 to delete Rick Ball:
 - (5) The designated point-of-contact to terminate transmissions if interference occurs is Mr. Sean Hallinan (603) 361-5959, ~~Rick Ball at (603) 318-6913~~ or BAE Systems Emergency Services Center at (603) 885-3842.
- Pursuant to Section 5.77(b) of the Commission's rules, permanently modify the Commission's records for the equipment associated with Station WE2XBT as follows:
 - o Transmitting Equipment:
 - Modify : For HP – HP8753A: Change quantity to “1.”
 - Add: Keysight; Model 5071C; Quantity 1
 - o Additional Signal Amplification:
 - Add: Mini-Circuits; TVA 11-422; 10-4200 MHz; Power Output: 1W;
 - Quantity: 2
 - o Delete Directional Antenna Information – No directional antennas currently being used

Other than the above changes, the data submitted at Exhibit 1 to the application under File No. 0038-EX-ML-2008 remains valid.

No changes are requested to area of operations/frequencies/power levels/emissions.