

Federal Communications Commission
Washington, D.C. 20554

Office of Engineering and Technology Electromagnetic Compatibility Division

March 15, 2005

Philip L. Verveer, Esq. Jennifer D. McCarthy, Esq. Kasey A. Chappelle, Esq. Willkie Farr & Gallagher LLP 1875 K Street, NW Washington, DC 20006

Re:

General Dynamics SATCOM Technologies, Inc.

Call Sign WC9XAP

File No. 0640-EX-ST-2004 (Granted November 24, 2004)

Dear Counsel:

As you are aware, on November 24, 2004, we granted the above-referenced application that you filed on behalf of General Dynamics SATCOM Technologies, Inc. Special Condition (3) of the authorization for Experimental Radio Service Station WC9XAP states (italics and bolding added):

Prior to commencement of operation with Intelsat 707 at 53 degrees WL pursuant to this experimental license, General Dynamics SATCOM Technologies, Inc. shall obtain a certification from Intelsat that Intelsat has notified all satellite operators with cofrequency operations within 6 degrees longitude of the Intelsat 707 satellite, generally describing the experimental operations authorized herein, including the term thereof, and providing a point of contact for the purpose of resolving any complaints of interference. General Dynamics SATCOM Technologies, Inc. shall obtain a similar certification from Intelsat if, during the term of this experimental license, a new or different satellite operator commences co-frequency operations within 6 degrees longitude of the Intelsat 707 satellite. If the point of contact receives a complaint of harmful interference, the party receiving the complaint (if not General Dynamics SATCOM Technologies, Inc.) will notify General Dynamics SATCOM Technologies, Inc., and General Dynamics SATCOM Technologies, Inc. shall immediately cease such operations or adjust such operations to avoid harmful interference. General Dynamics SATCOM Technologies, Inc. will submit a copy of Intelsat's certification(s) to the Commission for incorporation into the record of this file.

The Commission's file for Station WC9XAP does not contain a copy of the Intelsat certification(s) that General Dynamics SATCOM Technologies, Inc. has been required to submit to the Commission. Failure to comply with all the conditions of the authorization, including the condition that requires the obtaining and filing of necessary certifications, is a violation of the Commission's rules and could result in enforcement action.

Accordingly, we request that General Dynamics SATCOM Technologies, Inc. file these certification(s) with the Commission within ten (10) days from the date of this letter. Along with the certification(s), General Dynamics SATCOM Technologies, Inc. must state whether or not it has been notified of any complaints of harmful interference and, if it has been so notified, must state what actions it has taken to resolve such complaints. Finally, if the licensee has failed to meet any of these conditions, it must disclose this to the Commission and explain the reasons for such failure and the steps it has taken to remedy the failure.

Sincerely,

Ira Keltz

Dra Leff

Chief,

Electromagnetic Compatibility Division

cc: Mr. Timothy M. Shroyer