

660 Barnstable Road Hyannis, MA 02601 800-CAPE-AIR www.capeair.com

5/25/2021

Hello Mr. Lee,

In response to your request dated 5/21/2021 I would like to provide the justification for the experimental license we have applied for at our 1601 Aviation Place, Billings, MT 59101 location. Hyannis Air Service, D.B.A. Cape Air is an airline operator where we have approximately 100 aircraft in our fleet and our regional maintenance base for aircraft repairs in Montana is located at this address. During the course of regular business, we have a need to update, troubleshoot and repair our aircraft GPS while they are undergoing maintenance inside our hangar and the GPS signal is often very weak or non-existent inside the hangar especially when the exterior doors are shut. Since we are unable to properly troubleshoot these GPS devices inside the hangar, we are requesting an experimental license so that we can re-radiate a GPS signal indoors within our maintenance space.

Sincerely,

Brett Stone

Manager of Network Operations

brett.stone@capeair.com